DRAFT

Phase I Environmental Site Assessment Report
Security Square Mall
6901 Security Blvd, Baltimore MD, 21224
Baltimore County Owned Parcels

Prepared for

Baltimore County Department of Planning
105 West Chesapeake Avenue
Towson, MD 21204

Prepared by

EA Engineering, Science, Technology, Inc., PBC
225 Schilling Circle, Suite 400
Hunt Valley, Maryland 21031
410-584-7000

EA Project No. 16424-04
1 October 2025

This page intentionally left blank

TABLE OF CONTENTS

Page

LIST OF TABLES v
LIST OF FIGURES (Provided in Appendix A) v
LIST OF APPENDIXES vi
LIST OF ACRONYMS AND ABBREVIATIONS vii
EXECUTIVE SUMMARY 1

1. INTRODUCTION 1-1

1.1 LOCATION AND LEGAL DESCRIPTION 1-1
1.2 PURPOSE 1-2
1.3 DETAILED SCOPE OF SERVICES 1-2
1.4 LIMITING CONDITIONS, DELETIONS, AND DEVIATIONS 1-4
1.5 LIMITATIONS AND EXCEPTIONS 1-4
1.6 SIGNIFICANT ASSUMPTIONS 1-4
1.7 SPECIAL TERMS AND CONDITIONS 1-5
1.8 USER RELIANCE 1-5

2. USER PROVIDED INFORMATION 2-1

2.1 REASON FOR PERFORMING THE PHASE I ESA 2-1
2.2 USER PROVIDED INFORMATION 2-1

2.2.1 Environmental Liens 2-1
2.2.2 Activity and Use Limitations 2-1
2.2.3 Specialized Knowledge or Experience 2-1
2.2.4 Relationship of Purchase Price to Fair Market Value 2-1
2.2.5 Commonly Known or Reasonably Ascertainable Information 2-1
2.2.6 Obvious Indicators of Contamination 2-2
2.2.7 Other User Provided Documentation 2-2

3. SITE RECONNAISSANCE 3-1

3.1 METHODOLOGY AND LIMITING CONDITIONS 3-1
3.2 SITE AND VICINITY GENERAL CHARACTERISTICS 3-1
3.3 CURRENT USE OF THE PROPERTY 3-1
3.4 DESCRIPTION OF ON-SITE STRUCTURES, ROADS, AND IMPROVEMENT 3-2

3.4.1 Parcel A 3-2
3.4.2 Parcel C 3-2
3.4.3 Parcel D 3-2
3.4.4 Parcel E 3-2
3.4.5 Former Macy's 3-2

3.4.6 Former Sears 3-2

3.5 INTERIOR AND EXTERIOR OBSERVATIONS 3-3

3.5.1 Parcel A 3-3
3.5.2 Parcel C 3-4
3.5.3 Parcel D 3-5
3.5.4 Parcel E 3-6
3.5.5 Former Macy's 3-7
3.5.6 Former Sears 3-8

3.6 PAST USES OF SUBJECT PROPERTY 3-10
3.7 CURRENT USE OF ADJOINING PROPERTIES 3-11
3.8 PAST USES OF ADJOINING PROPERTIES 3-11

4. RECORDS REVIEW 4-1

4.1 PHYSICAL SETTING SOURCES 4-1

4.1.1 Topography 4-1
4.1.2 Soils 4-1
4.1.3 Geology 4-1

4.2 RECORD SOURCES 4-1

4.2.1 Standard Federal, State, and Tribal Environmental Record Sources 4-2
4.2.2 Additional Federal, State, Tribal, and Local Environmental Record Sources 4-5
4.2.3 Vapor Encroachment 4-6

4.3 STATE REGULATORY ENVIRONMENTAL DEPARTMENT RECORDS 4-7
4.4 LOCAL REGULATORY ENVIRONMENTAL DEPARTMENT RECORDS 4-9
4.5 FIRE DEPARTMENT RECORDS 4-10
4.6 BUILDING DEPARTMENT RECORDS 4-10
4.7 HISTORICAL USE INFORMATION 4-10

4.7.1 U.S. Geological Survey Topographic Maps 4-10
4.7.2 Aerial Photographs 4-11
4.7.3 Fire Insurance Maps 4-13
4.7.4 Local Street Directories 4-13

4.7.4.1 Subject Property City Directory Review 4-13
4.7.4.2 Adjacent Property City Directory Review 4-13

4.7.5 Property Tax Files 4-14
4.7.6 Recorded Land Title Records 4-14
4.7.7 Zoning/Land Use Records 4-14

4.7.8 Prior Environmental Reports 4-14
4.7.9 Other 4-14

5. INTERVIEWS 5-15

5.1 KEY SITE MANAGER 5-15
5.2 OPERATOR/OCCUPANT 5-15
5.3 STATE AND/OR LOCAL GOVERNMENT OFFICIALS 5-15
5.4 ADDITIONAL INTERVIEWS 5-15

6. FINDINGS AND OPINIONS 6-1

6.1 *DE MINIMIS* CONDITIONS 6-1
6.2 HISTORICAL RECOGNIZED ENVIRONMENTAL CONDITIONS 6-1
6.3 CONTROLLED RECOGNIZED ENVIRONMENTAL CONDITIONS 6-1
6.4 RECOGNIZED ENVIRONMENTAL CONDITIONS 6-1
6.5 DATA GAPS 6-4

7. CONCLUSIONS 7-1
8. NON-SCOPE SERVICES 8-1
9. STATEMENT AND SIGNATURE OF THE ENVIRONMENTAL PROFESSIONAL(S) 9-1
10. REFERENCES 10-1

LIST OF TABLES

Table ES-1. Phase I ESA Component Dates

Table 3-1. Subject Property Tenants

Table 3-2. Description of On-Site Structures, Roads, and Improvements

Table 3-3. Interior Observations

Table 3-4. Exterior Observations

Table 4-1. Topographic Map Review

Table 4-2. Aerial Photograph Review

Table 4-3. Fire Insurance Map Review

Table 4-4. Subject Property City Directory Review

Table 4-5. Adjacent Property City Directory Review

Table 4-6. Land Title Records Review

Table 6-1. Data Gaps

LIST OF FIGURES (Provided in Appendix A)

Figure 1. Subject Property Location Map

Figure 2. Subject Property Tax Map

Figure 3-1. Full Subject Property Site Features

Figure 3-2. Former Macy's Site Features

Figure 3-3. Former Sears Site Features

Figure 3-4. Former Sears Auto Service Center Site Features

LIST OF APPENDIXES

Appendix A. Figures

Appendix B. Supporting Documentation

Appendix C. Photographic Log

Appendix D. Environmental Records Search

Appendix E. Regulatory Agency Records Documentation

Appendix F: Historical Research Documentation
F.1. Topographic Maps
F.2. Aerial Photographs
F.3. Fire Insurance Maps
F.4. Local Street Directories
F.5. Property Tax Files

Appendix G. Resumes

LIST OF ACRONYMS AND ABBREVIATIONS

ºF	Degrees Fahrenheit
AAI	All Appropriate Inquiries
amsl	Above mean sea level
AST	Aboveground Storage Tank
ASTM	ASTM International
AUL	Activity and use limitation
BCDEPS	Baltimore County Department of Environmental Protection and Sustainability
CERCLA	Comprehensive Environmental Response, Compensation, and Liability Act
COC	Contaminant of concern
COPC	Contaminant of potential concern
CREC	Controlled recognized environmental condition
DOQQ	Digital Orthophoto Quarter Quads
EA	EA Engineering, Science, and Technology, Inc., PBC
EDR	Environmental Data Resources, Inc.
ESA	Environmental Site Assessment
FOIA	Freedom of Information Act
ft	Foot (feet)
ft^2	Square foot (feet)
HREC	Historical recognized environmental condition
LNAPL	Light non-aqueous phase liquid
NAIP	National Aerial Imagery Program
NFRAP	No Further Remedial Action Planned (Delisted CERCLA Site)
NHAP	National Historical Aerial Photography
No.	Number
NPL	National Priorities List
NRCS	Natural Resource Conservation Service
PCB	Polychlorinated biphenyl
PFAS	Per- and polyfluoroalkyl substances
PIA	Public Information Act
RCRA	Resource Conservation and Recovery Act
REC	Recognized environmental condition
RPD	Real Property Database

LIST OF ACRONYMS AND ABBREVIATIONS (continued)

SDAT	State Department of Assessment and Taxation
USDA	U.S. Department of Agriculture
USGS	U.S. Geological Survey
UST	Underground storage tank

This page intentionally left blank

EXECUTIVE SUMMARY

EA Engineering, Science, and Technology, Inc., PBC (EA) performed a Phase I Environmental Site Assessment (ESA) of the Baltimore County owned parcels associated with the Security Square Mall located at 6901 Security Boulevard, Baltimore, MD 21244. This Phase I ESA was performed in accordance with the requirements of ASTM International (ASTM) E1527-21 Standard Practice for ESAs: Phase I ESA Process.

Review of information from the Maryland State Department of Assessment and Taxation (SDAT) Real Property Database (RPD) identified Subject Property legal descriptions for the Baltimore County owned parcels. In addition, the ALTA Commitment for Title Insurance provided by Baltimore County provides additional designations for the parcels. This report uses the property designations from the Title Commitment documentation, the SDAT files, and the former uses of the parcels to differentiate the parcels. A total of 7 subdivided parcels (collectively referred to herein as the Subject Property) are included in the assessment and are described as follows (under 6 descriptions):

1) "Parcel A", name derived from the title commitment documentation, currently in use as a parking lot, is described as follows:

   - Tax map 0094, Parcel 0355, Subdivision 0000, Security Boulevard, 1.2687 acres.

2) "Parcel C", name derived from the title commitment documentation, currently in use as a parking lot, is described as follows:

   - Tax map 0094, Parcel 0351, Subdivision 0000, 1803 Rolling Road, 3.2207 acres.

3) "Parcel D", name derived from the title commitment documentation, currently in use as a parking lot and containing a green space with a stormwater retention pond, is described as follows:

   - Tax map 0094, Parcel 0350, Subdivision 8114, 6973 Security Boulevard, 1.5520 acres.

4) "Parcel E", name derived from SDAT documentation, currently in use as a parking lot, is described as follows:

   - Tax map 0094, Parcel 0476, Subdivision 0000, 6901 Security Boulevard, 11.4100 acres.

   - Tax map 0094, Parcel 0476, Subdivision 0166, 6901 Security Boulevard, 4.6200 acres.

5) "Former Macy's", name derived from its former use, currently a vacant retail building, is described as follows:

   - Tax map 0094, Parcel 0350, Subdivision 9187, 6901 Security Boulevard, 2.9500 acres.

6) "Former Sears", name derived from its former use, currently a vacant retail building and its surrounding parking area, is described as follows:

- Tax map 0094, Parcel 0350, Subdivision 0000, Security Boulevard, 18.0000 acres.

The Subject Property consists of approximately 43 acres of land and is currently comprised of the retail spaces of former mall tenants and surrounding surface parking lots.

The Subject Property has historically been mostly undeveloped land since at least 1894, until it was developed into a shopping mall in the early 1970s. Since then, several tenants have been present on the Subject Property including Sears, Macy's, and Hecht's. The buildings on the Subject Property are currently vacant.

This Phase I ESA did not identify any evidence of controlled RECs recognized environmental conditions (CRECs) or historical RECs recognized environmental conditions (HRECs) in connection with the Subject Property.

This Phase I ESA identified the following RECs in connection with the Subject Property:

Former Macy's

- Leaking emergency generator fuel tank – An emergency generator was observed in the mezzanine level of the Former Macy's. The day tank attached to the generator was actively leaking diesel fuel into a floor drain located beneath the fuel tank. The discharge point of the floor drain is unknown. The presence of the active oil leak constitutes a REC for the Subject Property.

- Leaking elevator control units – Two leaking elevator control units were observed during the site reconnaissance. Oil was actively leaking from units contained in both the customer elevator and utility elevator control rooms. The presence of active oil leaks constitutes a REC for the Subject Property.

- Missing monitoring wells – Documents provided by MDE reference monitoring well installations in the vicinity of a former UST, although these were not located in later inspections of the area. Improperly abandoned wells can act as a pathway for contaminants to reach groundwater, constituting a REC for the Subject Property.

Former Sears

- Leaking electrical transformer – A leaking electrical transformer was observed during the site reconnaissance. The side of the unit and the ground below the unit were visibly stained, and an oil odor was noticeable in the transformer room. The oil leak appeared to be active and constitutes a REC for the Subject Property.

- Leaking elevator control unit leaks – Two leaking elevator control units were observed during the site reconnaissance. Oil was actively leaking from units contained in both the customer elevator and utility elevator control rooms. The presence of active oil leaks constitutes a REC for the Subject Property.

- Oil-water Separator – Evidence of an underground oil-water separator associated with the Former Sear's Auto Service Center was observed outside the service center door during the site reconnaissance. The current condition of the separator is unknown and the historic operation of the separator represents a potential pathway for hazardous substances or petroleum products to be released into the environment, constituting a REC for the Subject Property.

- Acid Neutralization Pit - An underground Acid Neutralization Pit associated with the Former Sear's Auto Service Center was observed outside the Battery Storage Room door during the site reconnaissance. The current condition of the pit is unknown and the historic operation of the pit represents a potential pathway for hazardous substances to be released to the environment, constituting a REC for the Subject Property.

- Sand trap – A sand trap and five floor drains were observed in the floor of the Former Sear's Auto Service Center garage area during the site reconnaissance. The current condition of the trap and drains is unknown and the former use of the drainage system represents a potential pathway for hazardous substances or petroleum products to be released to the environment, constituting a REC for the Subject Property.

- Floor staining – The floor of the Former Sear's Auto Service Center garage was observed to be stained from historical operations. A floor area of severely stained concrete and pitting was observed near the southern entrance door to the garage. Due to the unknown nature of the staining and the potential to leach into the concrete and subsurface, the floor staining constitutes a REC for the Subject Property.

- USTs – Architectural Plans dated 1971 were reviewed for the former Sears Auto Service Center was observed during the site reconnaissance showing the installation of six 5,000-gallon gasoline USTs. In addition, records contained in the EDR Report as well as provided by Baltimore County indicate that six 5,000-gallon gasoline USTs were removed in 1986. Aerial photographs show that a concrete pad in the suspected location of the USTs was replaced with asphalt between 1982 and 1988. No additional information regarding the removal of these USTs was provided by MDE. The potential of environmental impact cannot be ruled out, constituting a REC for the Subject Property.

- Sears Gas Station – A review of historical documents revealed the former presence of a gas station in the parking lot that operated for approximately twenty years. A letter within a report provided by MDE dated 1993 references the possible removal of three 5,000-gallon USTs outside of the Former Sears Auto Service Center; however, no other documentation regarding these USTs was identified during the assessment. Three manholes and an intact concrete pad in the location of the former Auto center gas station

were observed during the site reconnaissance, which would indicate that USTs in this area are still present. However, the status of the USTs could not be confirmed. The possibility of the presence of USTs and potential environmental impact cannot be ruled out, constituting a REC for the Subject Property.

- Hydraulic systems – Evidence of multiple hydraulic systems was observed in the garage of the Former Sears Auto Service Center. A review of historical documents observed in the mechanical room during the site reconnaissance depicted thirteen single-acting and five double-acting hydraulic systems installed in the building. Visual evidence that several systems remain in place was also observed during the site reconnaissance. The status and condition of the systems beneath the concrete floor is unknown. Additional systems may be hidden from view due to the current use of the garage as storage for Baltimore County. Hydraulic systems may contain hazardous substances and/or petroleum products, and the potential for a system leak constitutes a REC for the Subject Property.

- Waste Oil UST – According to a report provided by BCDEPS, a 550-gallon steel UST containing waste oil was removed in 1993. The report indicates perforations were observed on the tank and the surrounding soil was contaminated. It is unknown if the contaminated soil has been addressed. The potential presence of contaminated soil constitutes a REC for the Subject Property.

Table ES-1 provides the dates on which the following ASTM E1527-21 Standard Practice for ESAs: Phase ESA Process components were performed.

Table ES-1. Phase I ESA Component Dates

Component	Date(s) Performed / Comments
Interview with Owner	8/5/2025
Interview with Operator – N/A	N/A -Subject Property is currently vacant
Interview with Occupant – N/A	N/A – Subject Property is currently vacant
Searches for Recorded Environmental Cleanup Liens (a User Responsibility)	User responsibility
Visual Inspection of the Subject Property and Adjoining Properties	8/7/2025
Records Review – Reviews of Federal, Tribal, State, and Local Government Records – Regulatory Database Report	7/23/2025
Records Review – Public of Information Act (PIA) request submitted to Maryland Department of the Environment	8/11/2025
Records Review – Public Information Act (PIA) request submitted to Baltimore County Fire Department	7/23/2025
Records Review – Public Information Act (PIA) request submitted to Baltimore County Department of Health	7/23/2025
Declaration by the Environmental Professional	October 1, 2025

1. INTRODUCTION

1.1 LOCATION AND LEGAL DESCRIPTION

EA Engineering, Science, and Technology, Inc., PBC (EA) performed a Phase I Environmental Site Assessment (ESA) of the Security Square Mall Baltimore County Owned Parcels located at 6901 Security Boulevard, Baltimore, MD 21244 (Subject Property). The Subject Property consists of approximately 43 acres of land. This Phase I ESA was performed in accordance with the requirements of ASTM International (ASTM) E1527-21 Standard Practice for ESA: Phase I ESA.

Review of information from the Maryland State Department of Assessment and Taxation (SDAT) Real Property Database (RPD) identified the legal descriptions for the following parcels comprising the Subject Property; these parcels have been given names in this report which are derived from the title commitment documentation, the SDAT files, and the former uses of the parcels.

1) "Parcel A", name derived from the title commitment documentation, currently in use as a parking lot, is described as follows:

    - Tax map 0094, Parcel 0355, Subdivision 0000, Security Boulevard, 1.2687 acres.

2) "Parcel C", name derived from the title commitment documentation, currently in use as a parking lot, is described as follows:

    - Tax map 0094, Parcel 0351, Subdivision 0000, 1803 Rolling Road, 3.2207 acres.

3) "Parcel D", name derived from the title commitment documentation, currently in use as a parking lot and containing a green space with a stormwater retention pond, is described as follows:

    - Tax map 0094, Parcel 0350, Subdivision 8114, 6973 Security Boulevard, 1.5520 acres.

4) "Parcel E", name derived from SDAT documentation, currently in use as a parking lot, is described as follows:

    - Tax map 0094, Parcel 0476, Subdivision 0000, 6901 Security Boulevard, 11.4100 acres.

    - Tax map 0094, Parcel 0476, Subdivision 0166, 6901 Security Boulevard, 4.6200 acres.

5) "Former Macy's", name derived from its former use, currently a vacant retail building, is described as follows:

    - Tax map 0094, Parcel 0350, Subdivision 9187, 6901 Security Boulevard, 2.9500 acres.

6) "Former Sears", name derived from its former use, currently a vacant retail building and its surrounding parking area, is described as follows:

    - Tax map 0094, Parcel 0350, Subdivision 0000, Security Boulevard, 18.0000 acres.

The Subject Property is located in a commercial area of Baltimore County, Maryland. The Subject Property location, as depicted on a U.S. Geological Survey Topographic (USGS) Map, is shown on Figure 1 (Appendix A). The boundaries of the Subject Property, as depicted on the current tax map, are shown on Figure 2 (Appendix A).

1.2 PURPOSE

The purpose of a Phase I ESA is to identify, to the extent feasible pursuant to the process prescribed in ASTM E1527-21 Standard Practice for ESAs: Phase I ESA Process, recognized environmental conditions (RECs), controlled RECs (CRECs), historical RECs (HRECs), and *de minimis* conditions in connection with the Subject Property.

An REC is defined by ASTM as: (1) the presence of hazardous substances or petroleum products in, on, or at the property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on, or at the property due to a release or likely release to the environment; or (3) the presence of hazardous substances or petroleum products in, on, or at the property under conditions that pose a material threat of a future release to the environment.

A CREC is defined by ASTM as an REC affecting the property that has been addressed to the satisfaction of the applicable regulatory authority or authorities with hazardous substances or petroleum products allowed to remain in place subject to implementation of required controls (e.g., activity and use limitations [AULs] or other property use limitations).

An HREC is defined by ASTM as a previous release of hazardous substances or petroleum products affecting the property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the property to any controls (e.g., AULs or other property use limitations). An HREC is not an REC.

A *de minimis* condition is defined by ASTM as a condition related to a release that generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. A condition determined to be a *de minimis* condition is not an REC nor a CREC.

The ASTM E1527-21 practice constitutes All Appropriate Inquiries (AAIs) for the purpose of Landowner Liability Protections, under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA).

1.3 DETAILED SCOPE OF SERVICES

EA prepared this Phase I ESA in accordance with Baltimore County PO 10027320.

This report reflects the observations, information, and data collected by EA during the period of July 23, 2025 through September 16, 2025.

This Phase I ESA was performed in accordance with ASTM E1527-21 (Standard Practice for ESAs: Phase I ESA Process) and consists of a review of current and historic activities and conditions at the Subject Property and surrounding properties, including a non-intrusive visual inspection of the Subject Property; review of local, state, and federal regulatory database records; review of available historic records; and a survey of adjacent land uses.

This Phase I ESA does not address the following ASTM non-scope considerations:

- Asbestos-containing building materials unrelated to releases into the environment
- Biological agents
- Cultural and historic resources
- Ecological resources
- Endangered species
- Health and safety
- Indoor air quality unrelated to releases of hazardous substances or petroleum products into the environment
- Industrial hygiene
- Lead-based paint unrelated to releases into the environment
- Lead in drinking water
- Mold or microbial growth conditions
- Polychlorinated biphenyl (PCB)-containing building materials (for example, interior fluorescent light ballasts, paint, and caulk)
- Naturally occurring radon
- Regulatory compliance
- Substances not defined as hazardous substances (including some substances sometimes generally referred to as emerging contaminants such as per- and polyfluoroalkyl

Substances [PFAS]) unless or until such substances are classified as a CERCLA hazardous substance

- Wetlands.

In addition, this Phase I ESA does not include sampling or chemical analysis of soil, sediment, groundwater, or surface water or an intensive examination of facility hazards (compliance audit).

1.4 LIMITING CONDITIONS, DELETIONS, AND DEVIATIONS

No limiting conditions deletions, or deviations apply to this assessment.

1.5 LIMITATIONS AND EXCEPTIONS

EA does not warrant that there are no toxic or hazardous materials or contamination, nor does EA accept any liability if such are found at some future time or could have been found if sampling or additional studies were conducted. EA does not assume responsibility for other environmental issues that may be associated with this Subject Property.

In view of the rapidly changing status of environmental laws, regulations, and guidelines, EA cannot be responsible for changes in laws, regulations, or guidelines that occur after the study has been completed and that may affect the Subject Property.

This report was prepared for Baltimore County Department of Planning by EA and is based in part on third-party information not within the control of Baltimore County Department of Planning or EA. While it is believed that the third-party information contained herein will be reliable under the conditions and subject to the limitations set forth herein, neither Baltimore County Department of Planning nor EA guarantee the accuracy thereof.

1.6 SIGNIFICANT ASSUMPTIONS

In expressing the opinions stated in this report, EA has exercised the degree of skill and care ordinarily exercised by a reasonable prudent Environmental Professional in the same community and in the same timeframe given the same or similar facts and circumstances. EA assumes that the client, as set forth in the contractual agreement, is also the User as defined by ASTM E1527-21. Documentation and data provided by the User, designated representatives thereof, or other interested third parties, or from the public domain, and referred to in the preparation of this assessment, were used and referenced. Consequently, EA assumes no responsibility or liability for the accuracy of such documentation or data.

The independent conclusions in this report represent EA's professional judgment based on information and data available to EA during the course of this assignment. The factual information regarding operations, conditions, and test data provided by the User or their representative are assumed to be correct and complete. The conclusions presented are based on the data provided and reviewed, observations, and conditions that existed on the date of the on-site visit.

1.7 SPECIAL TERMS AND CONDITIONS

No special terms and conditions apply to this assessment.

1.8 USER RELIANCE

This report is exclusively for the use and benefit of the client as shown on the cover page of this report. This report is not for the use or benefit of, nor may it be relied upon by, any other person or entity without the advance written consent of EA.

2. USER PROVIDED INFORMATION

An Environmental User Questionnaire based on the ASTM E1527-21 Phase I ESA Standard User Questionnaire (Appendix X.3) was submitted to Mr. Stephen Lafferty, Director of Planning for Baltimore County Department of Planning, for the purpose of requesting information in the following sections. Mr. Lafferty, who has been associated with the Subject Property for three years, completed the questionnaire and returned it to EA. A copy of the completed questionnaire is included in Appendix B.

2.1 REASON FOR PERFORMING THE PHASE I ESA

According to Mr. Lafferty, this Phase I ESA has been performed to establish an understanding of environmental conditions prior to redevelopment.

2.2 USER PROVIDED INFORMATION

2.2.1 Environmental Liens

Mr. Lafferty indicated that, to the best of his knowledge, he is not aware of any environmental liens against the Subject Property that are filed or recorded under federal, tribal, state, or local law.

2.2.2 Activity and Use Limitations

Mr. Lafferty indicated that, to the best of his knowledge, he is not aware of any AULs, such as engineering controls, land use restrictions or institutional controls, that are in place at the Subject Property and/or have been filed or recorded against the Subject Property under federal, tribal, state or local law.

2.2.3 Specialized Knowledge or Experience

Mr. Lafferty indicated that he does not have any specialized knowledge or experience related to the operations conducted on the Subject Property or nearby properties.

2.2.4 Relationship of Purchase Price to Fair Market Value

Mr. Lafferty indicated that he is unsure whether the purchase price paid for the Subject Property reflects the fair market value of the property.

2.2.5 Commonly Known or Reasonably Ascertainable Information

Mr. Lafferty indicated that he had knowledge of the past uses of the Subject Property. However, the User did not specify what those were.

2.2.6 Obvious Indicators of Contamination

Mr. Lafferty indicated that, to the best of his knowledge, he is not aware of the presence or likely presence of contamination at the Subject Property.

2.2.7 Other User Provided Documentation

No additional information was provided by the User as part of this Phase I ESA.

This page intentionally left blank

3. SITE RECONNAISSANCE

3.1 METHODOLOGY AND LIMITING CONDITIONS

EA conducted a site reconnaissance of the Subject Property that consisted of a walk-through observation of the on-site areas and interviews with representatives of the Subject Property owner. EA also conducted a site reconnaissance of the adjoining properties and surrounding area that consisted of observations from public thoroughfares adjacent to or traveled on the way to the Subject Property, and from the boundaries of the Subject Property. A photographic log is included in Appendix C.

Site reconnaissance activities and/or interviews were conducted on 7 August 2025 by Mr. James Hulbert and Mr. Mitchell Richards of EA. During the site reconnaissance, EA was accompanied by Mr. John Picco with the Baltimore County. EA interviewed Mr. Picco during the site reconnaissance, and details of the interview are included in Section 5.1.

Weather conditions at the time of the assessment were partly cloudy, with temperatures in the high 70s degrees Fahrenheit (ºF) and light winds.

Areas accessed during the site reconnaissance included the following interior and exterior areas:

- Parcel A, exterior
- Parcel C, exterior
- Parcel D, exterior
- Parcel E, exterior
- Former Macy's, interior and exterior
- Former Sears, interior and exterior

Additional areas accessed included the Subject Property boundaries.

No areas of the Subject Property were inaccessible.

3.2 SITE AND VICINITY GENERAL CHARACTERISTICS

The Subject Property is located in an urban area of Baltimore County, Maryland, and is located within surrounding property actively used as a shopping mall.

3.3 CURRENT USE OF THE PROPERTY

The Subject Property currently consists of several parking lots, two vacant structures, and a green space. Parcel A, Parcel C, and Parcel E are currently in use as parking lots. Parcel D is currently in use as a green space, with a stormwater retention pond located in the northern portion of the parcel. The Former Macy's is a vacant two-story department store, with an adjacent outdoor spaces including a fenced-in area for utilities. The Former Sear's is a vacant two-story department store, with adjacent outdoor spaces and the surrounding parking area.

3.4 DESCRIPTION OF ON-SITE STRUCTURES, ROADS, AND IMPROVEMENT

Site features are depicted on Figure 3 (Appendix A). Table 3-2 provides a summary of the on-site structures, roads, and improvements. Electric and natural gas service is provided to the Subject Property by Baltimore Gas and Electric. Water and sewer services are available from Baltimore County.

3.4.1 Parcel A

The parcel contains an asphalt parking lot with high mast lighting.

3.4.2 Parcel C

The parcel contains an asphalt parking lot with high mast lighting and stormwater drains.

3.4.3 Parcel D

The parcel contains an asphalt parking lot with high mast lighting, a green space including a stormwater retention pond, and a stormwater drain.

3.4.4 Parcel E

The parcel contains an asphalt parking lot with high mast lighting and stormwater drains.

3.4.5 Former Macy's

The site features on this parcel are depicted on Figure 3 (Appendix A). Table 3-1 provides a summary of the on-site structures and improvements. No roads are located within this parcel.

Table 3-1. Description of Structures and Improvements – Former Macy's

Improvement	Description
Number of Structures	1
Number of Stories	2 - with mechanical mezzanine level
Construction Year	1970s
Number of Tenant Units	0
Exterior Areas	Fenced utility area

3.4.6 Former Sears

The site features on this parcel are depicted on Figure 3 (Appendix A). Table 3-2 provides a summary of the on-site structures, roads/paved areas, and improvements.

Table 3-2. Description of Structures, Roads, and Improvements – Former Sears

Improvement	Description
Number of Structures	1
Number of Stories	2- with mechanical mezzanine level
Construction Year	1970s

Table 3-2. Description of Structures, Roads, and Improvements – Former Sears

Improvement	Description
Number of Tenant Units	0
Exterior Areas	Fenced utility area and parking lot with stormwater drains. Remaining elements of the Sears Auto Care Center were observed including the former gas station pad, oil/water separator and the acid neutralization pit.

3.5 INTERIOR AND EXTERIOR OBSERVATIONS

3.5.1 Parcel A

No structures are present on Parcel A; therefore, interior observations are not applicable to this parcel.

Table 3-3 documents the exterior observations made within this parcel.

Table 3-3. Exterior Observations – Parcel A

Component	Observed? (Y/N)	Comments
Hazardous substances and petroleum products in connection with identified uses	N	
Storage tanks	N	
Strong, pungent, or noxious odors and their sources	N	
Standing surface water and pools or sumps containing liquids likely to be hazardous substances or petroleum products	N	
Drums, totes, and intermediate bulk containers	N	
Hazardous substance and petroleum product containers not in connection with identified uses	N	
Unidentified substance containers	N	
PCB-containing items	N	
Heating/cooling	N	
Pits, ponds, or lagoons	N	
Stained soil or pavement	Y	Minor staining on the asphalt paved areas typical of small fluid leaks from motor vehicles
Stressed vegetation (from something other than insufficient water)	N	
Solid waste	Y	Scattered municipal waste in parking lot
Water/wastewater—wastewater or other liquid (including stormwater) discharged from or to the subject property	N	
Wells (including dry wells, irrigation wells, injection wells, monitoring wells, abandoned wells, or other wells)	N	
Septic systems or cesspools	N	

Notes:
N = No
Y = Yes

3.5.2 Parcel C

No structures are present on Parcel C; therefore, interior observations are not applicable to this parcel.

Table 3-4 documents the exterior observations made within this parcel.

Table 3-4. Exterior Observations – Parcel C

Component	Observed? (Y/N)	Comments
Hazardous substances and petroleum products in connection with identified uses	N	
Storage tanks	N	
Strong, pungent, or noxious odors and their sources	N	
Standing surface water and pools or sumps containing liquids likely to be hazardous substances or petroleum products	N	
Drums, totes, and intermediate bulk containers	N	
Hazardous substance and petroleum product containers not in connection with identified uses	N	
Unidentified substance containers	N	
PCB-containing items	N	
Heating/cooling	N	
Pits, ponds, or lagoons	N	
Stained soil or pavement	Y	Minor staining on the asphalt paved areas typical of small fluid leaks from motor vehicles
Stressed vegetation (from something other than insufficient water)	N	
solid waste	Y	Scattered municipal waste in parking lot
Water/wastewater—wastewater or other liquid (including stormwater) discharged from or to the subject property	Y	Stormwater drains
Wells (including dry wells, irrigation wells, injection wells, monitoring wells, abandoned wells, or other wells)	N	
Septic systems or cesspools	N	

Notes:
N = No
Y = Yes

3.5.3 Parcel D

No structures are present on Parcel D; therefore, interior observations are not applicable to this parcel.

Table 3-5 documents the exterior observations made within this parcel.

Table 3-5. Exterior Observations – Parcel D

Component	Observed? (Y/N)	Comments
Hazardous substances and petroleum products in connection with identified uses	N	
Storage tanks	N	
Strong, pungent, or noxious odors and their sources	N	
Standing surface water and pools or sumps containing liquids likely to be hazardous substances or petroleum products	N	
Drums, totes, and intermediate bulk containers	N	
Hazardous substance and petroleum product containers not in connection with identified uses	N	
Unidentified substance containers	N	
PCB-containing items		
Heating/cooling	N	
Pits, ponds, or lagoons	Y	Stormwater retention pond
Stained soil or pavement	Y	Minor staining on the asphalt paved areas typical of small fluid leaks from motor vehicles.
Stressed vegetation (from something other than insufficient water)	N	
solid waste	Y	Scattered municipal waste in parking lot
Water/wastewater—wastewater or other liquid (including stormwater) discharged from or to the subject property	Y	Stormwater drain
Wells (including dry wells, irrigation wells, injection wells, monitoring wells, abandoned wells, or other wells)	N	
Septic systems or cesspools	N	

Notes:
N = No
Y = Yes

3.5.4 Parcel E

No structures are present on Parcel E; therefore, interior observations are not applicable to this parcel.

Table 3-6 documents the exterior observations made within this parcel.

Table 3-6. Exterior Observations – Parcel E

Component	Observed? (Y/N)	Comments
Hazardous substances and petroleum products in connection with identified uses	N	
Storage tanks	N	
Strong, pungent, or noxious odors and their sources	N	
Standing surface water and pools or sumps containing liquids likely to be hazardous substances or petroleum products	N	
Drums, totes, and intermediate bulk containers	N	
Hazardous substance and petroleum product containers not in connection with identified uses	N	
Unidentified substance containers	N	
PCB-containing items		
Heating/cooling	N	
Pits, ponds, or lagoons	N	
Stained soil or pavement	Y	Minor staining on the asphalt paved areas typical of small fluid leaks from motor vehicles
Stressed vegetation (from something other than insufficient water)	N	
solid waste	Y	Scattered municipal waste in parking lot
Water/wastewater—wastewater or other liquid (including stormwater) discharged from or to the subject property	Y	Stormwater drains
Wells (including dry wells, irrigation wells, injection wells, monitoring wells, abandoned wells, or other wells)	N	
Septic systems or cesspools	N	

Notes:
N = No
Y = Yes

3.5.5 Former Macy's

Table 3-7 documents the interior observations made within this parcel.

Table 3-7. Interior Observations – Former Macy's

Component	Observed? (Y/N)	Comments
Hazardous Substances and Petroleum Products In Connection With Identified Uses	Y	Routine janitorial and maintenance supplies (e.g., paint, gasoline) in retail-size containers (5-gallons and less) in the mechanical room and elevator room
Storage Tanks	Y	Leaking day tank (diesel fuel) connected to emergency generator in mechanical room Exterior 500-gallon AST provides diesel fuel source for emergency generator
Strong, Pungent, or Noxious Odors and Their Sources	Y	Strong oil smells in the elevator and mechanical rooms from observed leaks
Standing surface water and pools or sumps containing liquids likely to be hazardous substances or petroleum products	N	
Drums, totes, and intermediate bulk containers	Y	Waste oil bucket in elevator room
Hazardous substance and petroleum product containers not in connection with identified uses	N	
Unidentified substance containers	N	
PCB-containing items	N	
Pits, ponds, or lagoons	N	
Heating/cooling	Y	Electric heating and cooling
Stains or corrosion on floors, walls, or ceilings (except for staining from water)	Y	Minor staining throughout building
Drains and sumps	Y	Floor drain under emergency generator oil tank, with active leak observed entering floor drain
Solid waste	Y	Scattered remnant municipal waste observed in some areas
Water/wastewater—wastewater or other liquid (including stormwater) discharged from or to the subject property	N	
Other	Y	Dry type transformers Oil leaking from equipment in elevator control room

Notes:
N = No
Y = Yes

Table 3-8 documents the exterior observations made within this parcel.

Table 3-8. Exterior Observations – Former Macy's

Component	Observed? (Y/N)	Comments
Hazardous substances and petroleum products in connection with identified uses	N	
Storage tanks	Y	Exterior 500 gallon AST provides diesel fuel source for emergency generator
..Strong, pungent, or noxious odors and their sources	N	
Standing surface water and pools or sumps containing liquids likely to be hazardous substances or petroleum products	N	
Drums, totes, and intermediate bulk containers	N	
Hazardous substance and petroleum product containers not in connection with identified uses	N	
Unidentified substance containers	N	
PCB-containing items		
Heating/cooling	N	
Pits, ponds, or lagoons	N	
Stained soil or pavement	N	
Stressed vegetation (from something other than insufficient water)	N	
solid waste	Y	Municipal waste scattered around perimeter of building
Water/wastewater—wastewater or other liquid (including stormwater) discharged from or to the subject property	N	
Wells (including dry wells, irrigation wells, injection wells, monitoring wells, abandoned wells, or other wells)	N	
Septic systems or cesspools	N	

Notes:
N = No
Y = Yes

3.5.6 Former Sears

Table 3-9 documents the interior observations made within this parcel.

Table 3-9. Interior Observations – Former Sears

Component	Observed? (Y/N)	Comments
Hazardous Substances and Petroleum Products In Connection With Identified Uses	Y	Routine janitorial and maintenance supplies (e.g., paint, gasoline) in retail-size containers (5-gallons and less) in the mechanical room
Storage Tanks	N	

Table 3-9. Interior Observations – Former Sears

Component	Observed? (Y/N)	Comments
Strong, Pungent, or Noxious Odors and Their Sources	Y	Several areas with strong oil smells, including the elevator control rooms and garage, from oil leaks and past use
Standing surface water and pools or sumps containing liquids likely to be hazardous substances or petroleum products	Y	Sand trap with visible liquid in garage
Drums, totes, and intermediate bulk containers	Y	Filled drum of universal tractor fluid in customer elevator control room
Hazardous substance and petroleum product containers not in connection with identified uses	N	
Unidentified substance containers	N	
PCB-containing items	N	
Pits, ponds, or lagoons	N	
Heating/cooling	Y	Natural gas heating, electric cooling
Stains or corrosion on floors, walls, or ceilings (except for staining from water)	Y	Staining throughout former Sears Auto Service Center space Pitted concrete from suspected spill or leak in garage Significant staining from detergent spill in garage
Drains and sumps	Y	Multiple floor drains in bathroom facilities, multiple floor drains in garage including a sand trap
Solid waste	Y	Municipal trash scattered in some areas
Water/wastewater—wastewater or other liquid (including stormwater) discharged from or to the subject property	Y	
Other	Y	The remnants of multiple hydraulic lift systems were observed in the garage. Architectural plans indicated up to 12 single-acting and 5 double-acting hydraulic systems have been installed on site. Unobserved systems may have been hidden due to the current use of the garage as storage for Baltimore County.

Notes:
N = No
Y = Yes

Table 3-10 documents the exterior observations within this parcel.

Table 3-10. Exterior Observations – Former Sears

Component	Observed? (Y/N)	Comments
Hazardous substances and petroleum products in connection with identified uses	N	
Storage tanks	Y	Surface features indicative of three USTs were observed in the area of the former gas station including three manholes on a concrete pad. Surface features indicative of an oil-water separator and associated UST were observed beneath metal access door outside of garage
Strong, pungent, or noxious odors and their sources	Y	Oil smell near leaking transformer
Standing surface water and pools or sumps containing liquids likely to be hazardous substances or petroleum products	N	
Drums, totes, and intermediate bulk containers	N	
Hazardous substance and petroleum product containers not in connection with identified uses	N	
Unidentified substance containers	N	
PCB-containing items	Y	Leaking electrical transformer in exterior utility area
Heating/cooling	N	
Pits, ponds, or lagoons	N	
Stained soil or pavement	Y	Minor staining on the asphalt paved areas typical of small fluid leaks from motor vehicles.
Stressed vegetation (from something other than insufficient water)	N	
solid waste	Y	Municipal waste scattered in parking lot.
Water/wastewater—wastewater or other liquid (including stormwater) discharged from or to the subject property	Y	Stormwater drains in parking lot. Acid neutralization pit located near the battery storage room.
Wells (including dry wells, irrigation wells, injection wells, monitoring wells, abandoned wells, or other wells)	N	
Septic systems or cesspools	N	

Notes:
N = No
Y = Yes

3.6 PAST USES OF SUBJECT PROPERTY

The following evidence of past uses of the Subject Property with respect to the likely past use, treatment, storage, disposal, and/or generation of hazardous substances or petroleum products was observed during the site reconnaissance:

- A concrete pad was observed in the former Sears parking lot believed to have been the location of a former gas station. Three manholes remain in the concrete pad.

- Three vent pipes and evidence of a fourth vent pipe were observed outside the Former Sears Auto Service Center, near the suspected location of the former waste oil UST and oil-water separator. The former locations of six suspected vent pipe support brackets were observed on exterior wall of the building, south of the location of the oil-water separator, likely associated with the six historic USTs located in the same area.

3.7 CURRENT USE OF ADJOINING PROPERTIES

The parcels of the Subject Property are non-contiguous and are adjoined and surrounded by portions of the wider mall complex (considered offsite for this assessment), including parking areas and the main mall building. In addition, the following offsite properties/areas adjoin the Subject Property:

- North – A fast food restaurant and Security Boulevard followed by a commercial area and an Exxon gas station
- Northwest – Weis grocery store and gas station
- East – Interstate 695, Baltimore Beltway
- South – Maryland Route 70
- Southeast – An automotive repair center (Crash Champions Collision Repair)
- West – A shopping center and Rolling Road followed by Tuscany Woods Apartments

3.8 PAST USES OF ADJOINING PROPERTIES

The following evidence of past uses of the adjoining properties with respect to the likely past use, treatment, storage, disposal, and/or generation of hazardous substances or petroleum products was observed during the site reconnaissance:

- An automotive repair center, Crash Champions Collision Repair, is located to the southeast of the mall complex. Based on the review of historical sources, the automotive repair center has operated at this property since at least 2017.
- Two gas stations, Exxon and Weis Gas n' Go, are located to the north of the Subject Property. Based on the review of historical sources, these gas stations have operated at these locations since at least 2012 and 2017 respectively.

4. RECORDS REVIEW

4.1 PHYSICAL SETTING SOURCES

4.1.1 Topography

The Subject Property is located on the USGS Ellicott City and Baltimore West 7.5-minute topographic quadrangle maps, dated 2019, as shown on Figure 1 in Appendix A. The elevation of the Subject Property is relatively flat at approximately 380 ft amsl.

The nearest surface water feature shown on the topographic maps is Dead Run located 1,600 ft north of the Subject Property. This surface water feature flows in a general east direction.

Observations during the site reconnaissance generally identified that the Subject Property topography mimics the topography as shown on the topographic maps.

4.1.2 Soils

Review of soil information available online from the U.S. Department of Agriculture (USDA) identified that the Subject Property is located in an area consisting of one soil type:

- **Urban land, 0 to 8 percent slopes**. General soil characteristics include:

  — Typical profile: Not specified
  — Drainage class: Not specified
  — Depth to water table: Not specified
  — Available water capacity: Not specified

4.1.3 Geology

Review of the Geologic Map of the Ellicott City Quadrangle, prepared by Crowley and Reinhardt, and dated 1980, identified that the Subject Property is underlain by Hollofield Layered Ultramafite which consists of:

- Ultramafic and mafic rocks interlayed on a scale varying from centimeters to tens of meters. Chiefly actinofels and actinoschist with subordinate amphibolite and very subordinate serpentinite.

4.2 RECORD SOURCES

An Environmental Data Resources, Inc. (EDR) Radius Map™ Report with Geocheck® was obtained from EDR to fulfill the requirements pertaining to standard environmental record sources. Explanations of the content of the databases are provided directly within the EDR Radius Map™ Report with Geocheck® in Appendix D.

4.2.1 Standard Federal, State, and Tribal Environmental Record Sources

The following standard federal, state, and tribal environmental record sources were reviewed as part of this Phase I ESA:

- Lists of Federal National Priorities List (NPL) (Superfund) sites
- Lists of Federal Delisted NPL sites
- Lists of Federal sites subject to CERCLA removals and CERCLA orders
- Lists of Federal CERCLA sites with Further Remedial Action Planned (NFRAP)
- Lists of Federal Resource Conservation and Conservation Act (RCRA) facilities undergoing Corrective Action
- Lists of Federal RCRA Treatment, Storage, and/or Disposal (TSD) facilities
- Lists of Federal RCRA generators
- Federal institutional control/engineering control registries
- Federal Emergency Response Notification System (ERNS) list
- Lists of state- and tribal "Superfund" equivalent sites
- Lists of state- and tribal hazardous waste facilities
- Lists of state and tribal landfills and solid waste disposal facilities
- Lists of state and tribal leaking storage tanks
- Lists of state and tribal registered storage tanks
- State and tribal institutional control/engineering control registries
- Lists of state and tribal voluntary cleanup sites
- Lists of state and tribal Brownfield sites.

Review of the EDR Radius Map™ Report indicates the Subject Property is listed in the RCRA, OCP Cases, and ERNS databases. Information contained in the Radius Map™ report indicates that the Former Sears was listed as a RCRA Small Quantity Generator (SQG) for ignitable waste, corrosive waste, and mercury. No notices of violation have been reported for this listing. The Former Macy's is currently listed as a RCRA NonGen, indicating that hazardous waste (ignitable waste) was previously generated at that location but is not currently being generated. No notices of violation have been reported for this listing.

The location of the Former Macy's appears twice in the OCP database, one case which was opened in September 2003 and closed in February 2006 for Hecht's, which occupied the building before Macy's, and a second which was opened in October 2012 and closed in May 2013. No releases were reported with either case. A search of the facility on the OCP database revealed the presence of two 300-gallon diesel USTs, one which was installed in 1979 with no listed closure date, and one which was installed in 1999 and closed in 2012. Both tanks are listed as removed from ground.

The former Sears appears once in the OCP database, for a case which was opened in December 1993 and closed in March 1995. The listing does not identify whether or not a release or cleanup occurred. A search of the facility on the OCP database revealed the presence of one 550-gallon waste oil UST which was installed in 1972 and closed in 1995. The tank is listed as removed from ground.

The following adjoining properties were listed on the standard federal, state, and local environmental records sources:

- *Town & Country Rolling Road Apartments,* which are located between 200 and 900 ft to the west and downgradient of the Subject Property, are identified in the OCP database under facility ID 10514. Twelve OCP cases are associated with this facility with the following addresses:

    - *7145 Rolling Bend Road,*
    - *7142 Rolling Bend Road,*
    - 7139 *Rolling Bend Road*
    - *7132 Rolling Bend Road*
    - *7127 Rolling Bend Road*
    - *7115 Rolling Bend Road*
    - *7108 Rolling Bend Road*
    - *7105 Rolling Bend Road*
    - *9 West Bend Court*
    - *8 West Bend Court*
    - *4 East Bend Court*
    - *3 East Bend Court*

    Information contained in the EDR Radius Map™ Report indicates that all but one of the cases were opened in May 1994, with the remaining case opened in June 1993. The majority of the cases were closed between March and June of 1995, with one closed in December 1995 and one closed in May 1997. A release is reported for all but two of the cases. No cleanups are listed with any of the cases. The status of all cases is closed.

    A subsequent search of the facility ID in the OCP UST database revealed twelve heating oil USTs, all of which are listed as being installed in 1968 and removed in 1994.

The operation of USTs at this site and the associated releases are not anticipated to have negatively impacted the environmental integrity of the Subject Property, based on distance and the closed status of the cases, and a review of regulatory files for the site is not deemed warranted.

- *Exxon Service Station, 1601 Belmont Avenue* which is located approximately 250 ft to the north and downgradient of the Subject Property, is identified in the OCP database. Information contained in the EDR Radius Map™ Report indicates that an OCP case was opened in October 2005 and closed in September 2009. A release and clean up were listed for this case. The status of the case is closed. A search of the facility on the OCP database revealed the presence of nine USTs. Five of the USTs were installed in 1982 and were closed by the end of 2007; they are listed as removed from the ground. The remaining four tanks were installed in October 2007 and are listed as currently in use.

  This site is not anticipated to have negatively impacted the environmental integrity of the Subject Property, based on distance from the Subject Property, topographic position relative to the Subject Property, and the closed status of the OCP case, and a review of regulatory files for the site is not deemed warranted.

- *Weis Gas N' Go, 7005 Security Boulevard* which is located adjacent to the north and downgradient of the Subject Property, is identified in the OCP database. Information contained in the EDR Radius Map™ Report indicates that an OCP case was opened in May 2015 and subsequently closed in August 2016. No release or clean up was listed for this case. The status of the case is closed. A search of the facility on the OCP database revealed the presence of two USTs which were installed in May 2015 and are listed as currently in use.

  This site is not anticipated to have negatively impacted the environmental integrity of the Subject Property, due to the lack of reported release and the closed status of the OCP case, and a review of regulatory files for the site is not deemed warranted.

- *J.C. Penny Co., 6901 Security Boulevard,* which was part of the wider Security Square mall complex that is not owned by Baltimore County, is identified in the OCP database. Information contained in the EDR Radius Map™ Report indicates that an OCP case was open April 1993. No release or clean up were listed for this case. The status of the case is closed with no listed closure date. A search of the facility on the OCP database revealed one 10,000-gallon heating oil UST that was installed in 1975 and removed in 1993.

  This site is not anticipated to have negatively impacted the environmental integrity of the Subject Property due to the lack of reported release and closed status of the OCP case, and a review of regulatory files for the site is not deemed warranted.

- *SS Self Storage LLC*, *6901 Security Boulevard,* which is part of the wider Security Square mall complex that is not owned by Baltimore County, is identified in the OCP database. Information contained in the EDR Radius Map™ Report indicates that an OCP case was

opened in March 2023 and subsequently closed in June 2023. No release or clean up was reported with this case. The status of the case is closed. A search of the facility on the OCP database revealed one 550-gallon used oil UST that was removed in March 2023.

This site is not anticipated to have negatively impacted the environmental integrity of the Subject Property due to the lack of reported release and closed status of the OCP case, and a review of regulatory files for the site is not deemed warranted.

- *Firestone Security Mall*, *6901 Security Boulevard,* which is part of the wider Security Square mall complex that is not owned by Baltimore County, is identified in the OCP database. Information contained in the EDR Radius Map™ Report indicates that an OCP case was opened in February 1994 and subsequently closed in July 1994. No release or clean up was reported with this case. The status of the case is closed. A search of the facility on the OCP database revealed two former USTs, one 6,000-gallon

  This site is not anticipated to have negatively impacted the environmental integrity of the Subject Property due to the lack of reported release and closed status of the OCP case, and a review of regulatory files for the site is not deemed warranted.

The remaining sites listed in the EDR Radius Map™ Report as included on the standard environmental records sources are not anticipated to have negatively impacted the environmental integrity of the Subject Property based on various factors such as distance from the Subject Property, topographic relations, estimated direction of groundwater flow, and/or regulatory status, and a review of regulatory files for the sites is deemed not warranted.

4.2.2 Additional Federal, State, Tribal, and Local Environmental Record Sources

A complete listing and a description of all databases associated with the additional environmental record sources is provided directly within the appended EDR Radius Map™ Report.

Review of the EDR Radius Map™ Report indicates the Subject Property is not listed on the additional federal, state, and local environmental record sources.

The following adjoining properties were listed on the additional federal, state, and local environmental records sources:

- *Michael's Tailor & Dry Cleaning*, *6901 Security Boulevard,* which is part of the wider Security Square mall complex that is not owned by Baltimore County, is listed on the EDR historic cleaners database. No evidence of a release was found in the EDR report, therefore this site is not anticipated to have negatively impacted the environmental integrity of the Subject Property.

- *Care Cleaners*, *7005 Security Boulevard,* which is to the north and adjacent to the Subject Property, is listed on the EDR historic cleaners database. No evidence of a

release was found in the EDR report, therefore this site is not anticipated to have negatively impacted the environmental integrity of the Subject Property.

The remaining sites listed in the EDR Radius Map™ Report as included on the standard environmental records sources are not anticipated to have negatively impacted the environmental integrity of the Subject Property based on various factors such as distance from the Subject Property, topographic relations, estimated direction of groundwater flow, and/or regulatory status, and a review of regulatory files for the sites is deemed not warranted.

EA also reviewed orphan/unmappable sites included in the EDR Radius Map™ Report in an effort to determine if any were located within the ASTM required search distances for the additional federal, state, tribal, and local environmental record sources. One orphan/unmappable sites was identified within the specified distances searched in accordance with the ASTM E1527-21 Phase I ESA Standard; this site is not anticipated to have negatively impacted the environmental integrity of the Subject Property based on the lack of reported releases or other indications of environmental impairment. A review of regulatory files for the site is deemed not warranted.

4.2.3 Vapor Encroachment

A vapor encroachment assessment was conducted ss part of this Phase I ESA. The EDR database findings discussed in Sections 4.2.1 and 4.2.2 are used, in conjunction with other available information, to assess whether a given facility/site has the potential to impact the Subject Property via vapor encroachment. The vapor encroachment screening process includes a review of the proximity of a source of chemicals of concern[1] (COCs), and the subset of COCs referred to as petroleum COCs, to the boundary of the Subject Property.

The appropriate distances of concern (ADOCs) noted below, which were applied as part of this screening exercise, are those established by the ASTM E2600 standard in conjunction with related industry guidance. The ADOCs assume that no information is known regarding the length or width of the contaminant plume. Note that ADOCs differ based on the hydrogeologic/ topographic position relative to the Subject Property and contaminants identified at a particular site. Additionally, ADOCs can be expanded or reduced at the discretion of the Environmental Professional with documented justification.

- Upgradient Sites—1,760 ft (1/3 miles) for non-petroleum hydrocarbon COC sites, and 528 ft (1/10 miles) for sites with petroleum hydrocarbon COC sites.

- Crossgradient Sites—365 ft for non-petroleum hydrocarbon COC sites, 165 ft for sites with petroleum hydrocarbon COCs where light non-aqueous phase liquid (LNAPL) or free product exists, and 95 ft where only dissolved petroleum hydrocarbons are present.

[1] COCs are chemicals with volatile or semivolatile properties, and petroleum COCs are those listed in Table X6.1 of the Standard Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transactions (E2600), such as benzene, xylene, etc. These compounds are segregated from COCs due to their ability to readily biodegrade to carbon dioxide or water by soil microbes in aerated environments.

- Downgradient Sites—100 ft for COC contaminated sites and sites where LNAPL or free product is presumed, and 30 ft when dissolved-phase petroleum hydrocarbons are presumed.

The following vapor encroachment concern(s) were identified:

- The Subject Property prior use as an automotive repair facility and gas station with unresolved UST listings presents a vapor intrusion concern.

4.3 STATE REGULATORY ENVIRONMENTAL DEPARTMENT RECORDS

EA submitted Public Information Act (PIA) requests to the Maryland Department of the Environment (MDE) for information regarding petroleum/hazardous materials storage and/or releases of petroleum products or hazardous materials or other environmental issues at the Subject Property. On 3 September 2025, MDE provided EA with a number of files related to the Subject Property and surrounding parcels. A discussion of the MDE files is provided as follows, grouped by relevant Subject Property parcel.

Former Sears

MDE files on the parcel designated as "Former Sears" were dated from 1987 to 1995, and were related to the presence of USTs formerly on the parcel. A "Notification for Underground Storage Tanks" dated to 1987 confirmed the presence of a 550-gallon waste oil UST. The UST was listed as 15 years old in 1987, which correlates with the installation date of 1972 found in the EDR report. An "Underground Storage Tank Removal and Closure" report dated 29 December 1993 and prepared by Groundwater Technology Inc. (GTI) also correlates with the removal date found in the EDR report. According to the GTI report, four soil samples were collected during the removal of the 550-gallon waste oil UST on 1 December 1993. An analysis of these samples by GTEL Environmental Laboratories, Inc. identified detectable concentrations of Toluene, Ethylbenzene, Xylenes, and Total Recoverable Petroleum Hydrocarbons (TRPH) above the lab's reporting limits. Of these, TRPH was found in the highest concentrations, ranging from 360 mg/kg to 6,200 mg/kg. These results are consistent with a "Tank Removal/Abandonment" document provided by the Baltimore County Department of Environmental Protection and Sustainability (BCDEPS) dated 1 December 1993, which identified contaminated soil, petroleum odors, perforations in the UST, and a PID reading of 64.3 ppm at the UST pad (refer to Section 4.4). On 11 April 1994, GTI sent a letter to MDE containing a Soil Assessment Work Plan to further evaluate the environmental impact of leaking waste oil from the 550-gallon UST; however, no documentation of further environmental investigation or remediation being completed was provided to EA by MDE or any other source. Therefore, the possibility of residual contamination from the 550-gallon waste oil UST cannot be ruled out and constitutes a REC for the Subject Property.

A letter to MDE from GTI dated 13 October 1993 states that in addition to the 550-gallon UST removal activities were to include three 5,000-gallon USTs containing gasoline. This letter appears to have been included in GTI's 29 December 1993 report for the removal activities, but no reference to the removal of 5,000-gallon gasoline USTs appears anywhere else in this report or in any other documents provided by MDE. Similarly, no reference to these USTs were found in the OCP's facility and case search databases. A single document provided by BCDEPS dated 1986 refers to the removal of six 5,000-gallon gasoline USTs at the Subject Property; however, it is believed that this information is unrelated, as discussed in Section 4.4.

Evidence provided in the EDR report, including local directories and aerial photographs, shows that a gas station was formerly present in the vicinity of the Former Sears Auto Service Center. In addition, during the site reconnaissance, EA observed a concrete pad with three manholes in the suspected location of the former gas station. The lack of available documentation regarding the three 5,000-gallon USTs referenced in the GTI report indicates the likely presence of USTs and potential environmental impact cannot be ruled out, constituting a REC for the Subject Property.

Former Macy's

MDE files on the parcel designated as "Former Macy's" were dated from 1986 to 2013. "Notification for Underground Storage Tanks" documents from 1986 and 1998 indicate the presence of a 250-gallon steel UST installed in 1979 that may have contained kerosene in 1986 and diesel in 1998. It should be noted that later documentation lists this UST as being either 250- or 300-gallons in capacity; however, it is consistently stated that the UST was installed in 1979, was composed of steel, and contained diesel for an emergency generator when it was removed in 1999. This information is corroborated by two letters and a Bill of Lading from Tri County Industries, Inc. (TCI) dated 1999. Later documentation lists this UST as removed from the ground; however, MDE notes in a letter dated 1 January 2004 that "no case file or Tank Removal Form exists." Based on available information provided by MDE and EDR, it can be assumed that this UST was removed in February 1999 when a new UST containing diesel for an emergency generator was installed in its place. A letter of transmittal dated 12 April 1999 from TCI states that an official from MDE inspected the removal of the tank and ordered soil samples, and "no contamination above regulated limits was detected. The soils did have a slight petroleum odor". A certificate of analysis from February 1999 confirms that two samples were analyzed for Total Petroleum Hydrocarbons, one of which was reported as less than the laboratory's reporting limit of 10 mg/kg, and one which was reported as 19 mg/kg. It is unknown if the samples were tested for any other analytes.

A Notification for Underground Storage Tanks from 1999 lists the presence of a composite 300-gallon diesel UST which was installed the same year. This UST was described as being 250-gallons in capacity in at least one other document provided by MDE; however, it is believed that this information was erroneous. Based on available inspection reports, this tank was in place

until 2012 when it was removed. An Underground Storage Tank Closure Report prepared by HP Environmental, Inc (HPE) was sent to MDE on 27 November 2012 which describes the removal efforts and includes photographs of the removal as well as a laboratory report for the analysis of soil samples taken during the event. The report did not find evidence that a release had occurred.

The 12 April 1999 Letter of Transmittal from TCI also describes the installation of the above-referenced UST, in which it states that monitoring pipes/wells were installed in the UST tank field. This information contrasts with later documents, including routine inspections carried out by MDE between 2003 and 2012, which mark the absence of monitoring pipes/wells. However, in a letter dated 23 March 2004 from TCI, forwarded to MDE on 24 March 2004, it is stated that "two (2) monitoring wells were found in opposing corners of the tank field" after removing mulch from the area. A later MDE inspection in 2009 suggests that monitoring pipes/wells may be hidden by mulch/soil. Improperly abandoned monitoring wells can act as a pathway for contaminants to reach groundwater, constituting a REC for the Subject Property.

Documents provided by MDE can be found in Appendix E.

4.4 LOCAL REGULATORY ENVIRONMENTAL DEPARTMENT RECORDS

EA submitted Public Information Act (PIA) requests to the Baltimore County Department of Environmental Protection and Sustainability (BCDEPS) for information regarding petroleum/hazardous materials storage and/or releases of petroleum products or hazardous materials or other environmental issues at the Subject Property. On 26 August 2025, BCDEPS provided EA with a number of files related to the Subject Property and surrounding parcels. A discussion of the BCDEPS files for the Subject Property is provided as follows.

Former Sears

A UST removal document from 1993 corroborates the removal of a 550-gallon waste oil UST that same year and the presence of possible contamination, as discussed in Section 4.3. The document identified contaminated soil, petroleum odors, perforations in the UST, and a PID reading of 64.3 ppm at the UST pad. It is unknown if this contamination has been addressed, constituting a REC for the Subject Property.

A UST removal document dated 21 May 1986 describes a tank removal that took place at "the Sears Auto Shop, 6901 Security Blvd" that involved six 5,000-gallon gasoline USTs. A site plan dated to 1971 found during site reconnaissance showed the planned installation of six 5,000-gallon USTs outside of the Former Sears Auto Service Center (refer to Figure 3-4). Aerial photographs provided by EDR showed that a concrete pad was present in the location indicated by this document; this pad appears to have been replaced with asphalt between 1982 and 1988, corroborating a possible removal date of 1986. No other documentation confirming the removal of these USTs was found in any other source provided to EA. The lack of available

documentation indicates the likely presence of USTs and potential environmental impact cannot be ruled out, constituting a REC for the Subject Property.

Documents provided by BCDEPS can be found in Appendix E.

4.5 FIRE DEPARTMENT RECORDS

EA submitted a PIA request to the Baltimore County Fire Department for information regarding petroleum/hazardous materials storage and/or releases of petroleum products or hazardous materials or other environmental issues at the Subject Property.

EA received a response letter dated 24 July 2025 indicating that no records were found pursuant to the PIA request.

Documentation of the PIA request and response is presented in Appendix E.

4.6 BUILDING DEPARTMENT RECORDS

EA reviewed online Baltimore County Building Department information on Baltimore County's MyNeighborhood pertaining to the Subject Property, which identified the tax information including tax maps presented in Appendix F.5.

4.7 HISTORICAL USE INFORMATION

Based upon interviews and a review of historical information summarized in the following sections, the Subject Property consisted primarily of undeveloped land and agricultural land throughout its history dating back to at least 1894, until Security Square Mall was constructed in the early 1970s. Since construction of the mall, several businesses have been present on the Subject Property, including Sears, Macy's, Hetch's, a gas station and an auto service center.

The following sections are presented for the purpose of compiling historical information on the activities that occurred on the Subject Property.

4.7.1 U.S. Geological Survey Topographic Maps

Historical topographic maps were obtained from EDR as part of this Phase I ESA. Copies of the topographic maps are presented in Appendix F.1. The results of this review are included in Table 4-1.

Table 4-1. Topographic Map Review

Date	Source	Subject Property	Adjacent and Surrounding Properties
1894	USGS	The Subject Property appears to be undeveloped except for a road running through the northwest corner.	The adjacent and surrounding properties appear to be sparsely developed with a few roads, with a single building depicted within a quarter mile of the Subject Property to the southwest.

Date	Source	Subject Property	Adjacent and Surrounding Properties
1904, 1906	USGS	The Subject Property appears similar to the map from 1894.	Additional buildings are depicted in the area surrounding the Subject Property; the overall configuration of roads appears similar to the 1894 map.
1908	USGS	The Subject Property appears similar to the maps from 1904 and 1906.	Additional buildings are depicted in the area surrounding the Subject Property; the overall configuration of roads appears similar to the prior maps.
1944	USGS	Two buildings are now depicted adjacent to the road running through the northwest corner of the Subject Property. The Subject Property is mostly shaded green, indicating a lack of development.	Additional buildings and roads are depicted in the area surrounding the Subject Property. The towns of Woodlawn and Catonsville are now depicted to the northeast and southeast, respectively.
1953	USGS	The Subject Property appears similar to the map from 1944.	The adjacent and surrounding properties appear similar to the map from 1944, except for expanding urban development.
1966	USGS	The Subject Property appears similar to the map from 1953.	Major highways appear to be under development to the south and east of the Subject Property.
1974	USGS	Security Square Mall is now depicted.	The highways adjacent to the Subject Property appears to have been completed. More urbanization was observed in all directions from the Subject Property.
2014	USGS	The Subject Property appears similar to the map from 1974 except for map formatting changes which no longer show the primary mall structure.	The areas around the Subject Property now appear to have been fully urbanized.
2016	USGS	The Subject Property appears similar to the map from 2014.	The adjacent and surrounding properties appear similar to the map from 2014.
2019	USGS	The Subject Property appears similar to the map from 2016.	The adjacent and surrounding properties appear similar to the map from 2016.

Notes: Several maps were included in the EDR report which contained only a portion of the Subject Property. Summaries of these maps were excluded from the table above; however, the maps can be found in Appendix F.1.

4.7.2 Aerial Photographs

Aerial photographs were obtained from EDR as part of this Phase I ESA. Copies of the aerial photographs are presented in Appendix F.2. Observations made from the review of the aerial photographs are presented in Table 4-2.

Table 4-2. Aerial Photograph Review

Date	Source	Subject Property	Adjacent and Surrounding Properties
1938	USDA	The Subject Property appears to be mostly undeveloped, except for some farmland and a road running through the northwest corner.	The surrounding area appears to be mostly undeveloped, except for scattered farmland and a few roads and buildings.
1943	USDA	The Subject Property appears similar to the map from 1938.	The adjacent and surrounding properties appear similar to the map from 1938.

Date	Source	Subject Property	Adjacent and Surrounding Properties
1952	USDA	The Subject Property appears similar to the map from 1943, except for the removal of a line of trees, possibly for the installation of utilities.	The adjacent and surrounding properties appear similar to the map from 1943.
1957	USDA	The Subject Property appears similar to the map from 1952.	The adjacent and surrounding properties appear similar to the map from 1952.
1964	USGS	The Subject Property appears similar to the map from 1957.	Highways are now under construction to the immediate south and east of the Subject Property. More urban development appears in the surrounding area.
1971	USDA	Security Square Mall appears to be under construction.	The highways now appear to have been completed. Urban development continues to appear in the surrounding area.
1979	USDA	Security Square Mall appears to have been completed. The Former Sears gas station canopy is present, as well as a concrete pad adjacent to the northeast corner of the Former Sears Auto Service Center.	The adjacent and surrounding properties appear similar to the map from 1971, except for continued urban development.
1982	NHAP	The Subject Property appears similar to the map from 1979. The concrete pad adjacent to the auto service center appears to have been resurfaced with asphalt.	The adjacent and surrounding properties appear similar to the map from 1979, except for continued urban development.
1988	NAPP	The Subject Property appears similar to the map from 1982.	The adjacent and surrounding properties appear similar to the map from 1982, except for continued urban development.
1994	USGS/ DOQQ	The Subject Property appears similar to the map from 1988.	The adjacent and surrounding properties appear similar to the map from 1988, except for continued urban development.
2007	USDA/ NAIP	The Subject Property appears similar to the map from 1994. The Former Sears gas station canopy is no longer present.	The adjacent and surrounding properties appear similar to the map from 1994, except for continued urban development.
2011	USDA/ NAIP	The Subject Property appears similar to the map from 2007.	The adjacent and surrounding properties appear similar to the map from 2007.
2015	USDA/ NAIP	The Subject Property appears similar to the map from 2011.	The adjacent and surrounding properties appear similar to the map from 2011.
2018	USDA/ NAIP	The Subject Property appears similar to the map from 2015.	The adjacent and surrounding properties appear similar to the map from 2015.
2023	USDA/ NAIP	The Subject Property appears similar to the map from 2018.	The adjacent and surrounding properties appear similar to the map from 2018.

Notes:
DOQQ = Digital Orthophoto Quarter Quads
NAIP = National Aerial Imagery Program
NHAP = National Historical Aerial Photography

4.7.3 Fire Insurance Maps

EA engaged EDR to conduct a search for historical fire insurance maps for the Subject Property. EDR confirmed that no Sanborn fire insurance map coverage exists for the area of the Subject Property in the EDR fire insurance map holdings. Documentation of the search performed by EDR on 23 July 2025 is presented in Appendix F.3.

4.7.4 Local Street Directories

A City Directory Report was provided by EDR which included local street directories dating back to 1986. A copy of the EDR City Directory Report is included in Appendix F.4.

4.7.4.1 Subject Property City Directory Review

Review of the city directory listings identified the following, as presented in Table 4-4.

Table 4-4. Subject Property City Directory Review

Year	Source	Listing(s)
2010	Cole Information	6901 Security Blvd: Sears Auto Center
2022	EDR Digital Archive	6901 Security Blvd: Sears Auto Center

Notes: Numerous businesses located within Security Square Mall were listed on the directory; only those businesses of potential environmental concern are listed in the table.

4.7.4.2 Adjacent Property City Directory Review

Review of the city directory listings identified the following, as presented in Table 4-5.

Table 4-5. Adjacent Property City Directory Review

Year	Source	Listing(s)
2000	Cole Information	6901 Security Blvd: American Tire and Service Co; Firestone Tire & Service Center
2005	Cole Information	6901 Security Blvd: Firestone Master Care Car Service
2010	Cole Information	6901 Security Blvd: Grand Auto Body
2014	Cole Information	6901 Security Blvd: 695 Auto Body; Muns Auto Repair Center Inc
2017	Cole Information	7005 Security Blvd: Weis Gas N Go 6901 Security Blvd: 695 Auto Body Shop; Grand Auto Body; Muns Auto Repair Center Inc
2022	EDR Digital Archive	7005 Security Blvd: Weis Gas N Go

Notes: Numerous businesses located within Security Square Mall were listed on the directory; only those businesses of potential environmental concern are listed in the table.

4.7.5 Property Tax Files

Limited historical information pertaining to the parcels that comprise the Subject Property was obtained online from the SDAT RPD. Review of information from SDAT RPD identified the Subject Property is currently owned by Baltimore County. A copy of the SDAT RPD sheets is presented in Appendix F.5.

4.7.6 Recorded Land Title Records

No chain-of-title report for the Subject Property was provided by the User for review as part of this Phase I ESA. However, in order to fulfill the requirements of the ASTM E1527-21 Phase I ESA Standard, a formal review of title and judicial records for environmental liens and AULs associated with the Subject Property would be required of the User.

4.7.7 Zoning/Land Use Records

Review of online zoning and land use information available from Baltimore County's online GIS service "My Neighborhood" identified that the Subject Property is currently zoned "Business Major". A copy of the zoning map is included in Appendix F.5.

4.7.8 Prior Environmental Reports

EA was not provided with any previously conducted environmental assessment reports by the User as part of this investigation.

4.7.9 Other

Architectural plans developed by Allan B. Mitchell and Associates Architects, Pittsburgh PA dated 1971 for the Sear Automotive Care Center were provided to EA for review. The plans included construction plans for the installation of six 5,000-gallon gasoline USTs outside the former Sears Auto Service Center. A concrete pad can be seen in the location indicated by the plans in aerial photographs from the 1970's and 80's, suggesting that the installation was completed as planned. The planning documents also provided EA with the locations of numerous hydraulic systems throughout the former Sears Auto Service Center. The remnants of many of these systems were identified during site reconnaissance; it is presumed that the unobserved systems were obscured due to the facility's current use as storage for Baltimore County. Details for the oil/water separator, sand trap/floor drain system and acid neutralization pit were also included on the plans.

A scan of one of the plans was used as the basis for Figure 3-4. Additional photos of the plans taken during site reconnaissance are included in Appendix C.

5. INTERVIEWS

5.1 KEY SITE MANAGER

EA interviewed Mr. John Picco of the Baltimore County Department of Planning during the site reconnaissance. Mr. Picco has been associated with the Subject Property for approximately two years and is familiar with the HVAC systems at the Former Macy's and Former Sears. He provided access to mechanical spaces, emergency generators, electric and communication rooms, and fenced exterior areas containing utilities. Mr. Picco reported that the Former Sears location is used by Baltimore County for storage of various equipment and supplies. He noted a location of detergent leaking from a pallet of stored product in the garage of the Former Sears. He also noted the stained condition of the outdoor transformer at the Former Sears. He was unfamiliar with the operations of the Former Sears Auto Service Center but was able to provide access to the space. Mr. Picco also provided access to the building plans for the Former Macy's and Former Sears which were reviewed by EA and pertinent sections photographed for documentation.

5.2 OPERATOR/OCCUPANT

The Subject Property is currently vacant and is used for storage by Baltimore County; therefore, no operators or occupants were interviewed.

5.3 STATE AND/OR LOCAL GOVERNMENT OFFICIALS

EA submitted PIA requests to the agencies included in Sections 4.3, 4.4, 4.5, and 4.6. Information pertaining to those requests for information is included in those sections.

5.4 ADDITIONAL INTERVIEWS

No other interviews were conducted for this assessment.

6. FINDINGS AND OPINIONS

The findings and opinions presented below identify *de minimis* conditions, HRECs, CRECs, and RECs.

6.1 *DE MINIMIS* CONDITIONS

The findings noted below are not considered RECs, but are rather considered a *de minimis* conditions:

Minor staining was observed on the asphalt paved areas typical of small leaks from vehicles.

Minor staining was observed inside the Former Sears and Former Macy's throughout the structures, especially in the mechanical rooms.

Based on the results of this Phase I ESA, including the results of the site reconnaissance, interviews, and records review, EA is of the opinion that the identified *de minimis* conditions generally does not present a threat to human health or the environment and generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies.

6.2 HISTORICAL RECOGNIZED ENVIRONMENTAL CONDITIONS

No HRECs were identified.

6.3 CONTROLLED RECOGNIZED ENVIRONMENTAL CONDITIONS

No CRECs were identified.

6.4 RECOGNIZED ENVIRONMENTAL CONDITIONS

The following RECs were identified:

Parcel A

- No RECs were identified.

Parcel C

- No RECs were identified.

Parcel D

- No RECs were identified.

Parcel E

- No RECs were identified.

Former Macy's

- Leaking emergency generator fuel tank – An emergency generator was observed in the mezzanine level of the Former Macy's. The day tank attached to the generator was actively leaking diesel fuel into a floor drain located beneath the fuel tank. The discharge point of the floor drain is unknown. The presence of the active oil leak constitutes a REC for the Subject Property.

- Leaking elevator control units – Two leaking elevator control units were observed during the site reconnaissance. Oil was actively leaking from units contained in both the customer elevator and utility elevator control rooms. The presence of active oil leaks constitutes a REC for the Subject Property.

- Missing monitoring wells – Documents provided by MDE reference monitoring well installations in the vicinity of a former UST, although these were not located in later inspections of the area. Improperly abandoned wells can act as a pathway for contaminants to reach groundwater, constituting a REC for the Subject Property.

Former Sears

- Leaking electrical transformer – A leaking electrical transformer was observed during the site reconnaissance. The side of the unit and the ground below the unit were visibly stained, and an oil odor was noticeable in the transformer room. The oil leak appeared to be active and constitutes a REC for the Subject Property.

- Leaking elevator control unit leaks – Two leaking elevator control units were observed during the site reconnaissance. Oil was actively leaking from units contained in both the customer elevator and utility elevator control rooms. The presence of active oil leaks constitutes a REC for the Subject Property.

- Oil-water Separator – Evidence of an underground oil-water separator associated with the Former Sear's Auto Service Center was observed outside the service center door during the site reconnaissance. The current condition of the separator is unknown and the historic operation of the separator represents a potential pathway for hazardous substances or petroleum products to be released into the environment, constituting a REC for the Subject Property.

- Acid Neutralization Pit - An underground Acid Neutralization Pit associated with the Former Sear's Auto Service Center was observed outside the Battery Storage Room door during the site reconnaissance. The current condition of the pit is unknown and the

historic operation of the pit represents a potential pathway for hazardous substances to be released to the environment, constituting a REC for the Subject Property.

- Sand trap – A sand trap and five floor drains were observed in the floor of the Former Sear's Auto Service Center garage area during the site reconnaissance. The current condition of the trap and drains is unknown and the former use of the drainage system represents a potential pathway for hazardous substances or petroleum products to be released to the environment, constituting a REC for the Subject Property.

- Floor staining – The floor of the Former Sear's Auto Service Center garage was observed to be stained from historical operations. A floor area of severely stained concrete and pitting was observed near the southern entrance door to the garage. Due to the unknown nature of the staining and the potential to leach into the concrete and subsurface, the floor staining constitutes a REC for the Subject Property.

- USTs – Architectural Plans dated 1971 were reviewed for the former Sears Auto Service Center was observed during the site reconnaissance showing the installation of six 5,000-gallon gasoline USTs. In addition, records contained in the EDR Report as well as provided by Baltimore County indicate that six 5,000-gallon gasoline USTs were removed in 1986. Aerial photographs show that a concrete pad in the suspected location of the USTs was replaced with asphalt between 1982 and 1988. No additional information regarding the removal of these USTs was provided by MDE. The potential of environmental impact cannot be ruled out, constituting a REC for the Subject Property.

- Sears Gas Station – A review of historical documents revealed the former presence of a gas station in the parking lot that operated for approximately twenty years. A letter within a report provided by MDE dated 1993 references the possible removal of three 5,000-gallon USTs outside of the Former Sears Auto Service Center; however, no other documentation regarding these USTs was identified during the assessment. Three manholes and an intact concrete pad in the location of the former Auto center gas station were observed during the site reconnaissance, which would indicate that USTs in this area are still present. However, the status of the USTs could not be confirmed. The possibility of the presence of USTs and potential environmental impact cannot be ruled out, constituting a REC for the Subject Property.

- Hydraulic systems – Evidence of multiple hydraulic systems was observed in the garage of the Former Sears Auto Service Center. A review of historical documents observed in the mechanical room during the site reconnaissance depicted thirteen single-acting and five double-acting hydraulic systems installed in the building. Visual evidence that several systems remain in place was also observed during the site reconnaissance. The status and condition of the systems beneath the concrete floor is unknown. Additional systems may be hidden from view due to the current use of the garage as storage for Baltimore County. Hydraulic systems may contain hazardous substances and/or petroleum products, and the potential for a system leak constitutes a REC for the Subject Property.

- Waste Oil UST – According to a report provided by BCDEPS, a 550-gallon steel UST containing waste oil was removed in 1993. The report indicates perforations were observed on the tank and the surrounding soil was contaminated. It is unknown if the contaminated soil has been addressed. The potential presence of contaminated soil constitutes a REC for the Subject Property.

Based on the results of this Phase I ESA, including the results of the site reconnaissance, interviews, and records review, EA is of the opinion that there is a potential that the identified RECs have impacted the environmental integrity of the Subject Property and further investigation is required to address them.

6.5 DATA GAPS

No data gaps were identified.

This page intentionally left blank

7. CONCLUSIONS

We have performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM Practice E1527-21 of 6901 Security Boulevard, Baltimore County Owned Parcels, the Subject Property. Any exceptions to, or deletions from, this practice are described in Section 1.4 of this report. This assessment has revealed the following recognized environmental conditions, controlled recognized environmental conditions, and/or significant data gaps in connection with the Subject Property:

Former Macy's

- Leaking emergency generator fuel tank – An emergency generator was observed in the mezzanine level of the Former Macy's. The day tank attached to the generator was actively leaking diesel fuel into a floor drain located beneath the fuel tank. The discharge point of the floor drain is unknown. The presence of the active oil leak constitutes a REC for the Subject Property.

- Leaking elevator control units – Two leaking elevator control units were observed during the site reconnaissance. Oil was actively leaking from units contained in both the customer elevator and utility elevator control rooms. The presence of active oil leaks constitutes a REC for the Subject Property.

- Missing monitoring wells – Documents provided by MDE reference monitoring well installations in the vicinity of a former UST, although these were not located in later inspections of the area. Improperly abandoned wells can act as a pathway for contaminants to reach groundwater, constituting a REC for the Subject Property.

Former Sears

- Leaking electrical transformer – A leaking electrical transformer was observed during the site reconnaissance. The side of the unit and the ground below the unit were visibly stained, and an oil odor was noticeable in the transformer room. The oil leak appeared to be active and constitutes a REC for the Subject Property.

- Leaking elevator control unit leaks – Two leaking elevator control units were observed during the site reconnaissance. Oil was actively leaking from units contained in both the customer elevator and utility elevator control rooms. The presence of active oil leaks constitutes a REC for the Subject Property.

- Oil-water Separator – Evidence of an underground oil-water separator associated with the Former Sear's Auto Service Center was observed outside the service center door during the site reconnaissance. The current condition of the separator is unknown and the historic operation of the separator represents a potential pathway for hazardous substances or petroleum products to be released into the environment, constituting a REC for the Subject Property.

- Acid Neutralization Pit - An underground Acid Neutralization Pit associated with the Former Sear's Auto Service Center was observed outside the Battery Storage Room door during the site reconnaissance. The current condition of the pit is unknown and the historic operation of the pit represents a potential pathway for hazardous substances to be released to the environment, constituting a REC for the Subject Property.

- Sand trap – A sand trap and five floor drains were observed in the floor of the Former Sear's Auto Service Center garage area during the site reconnaissance. The current condition of the trap and drains is unknown and the former use of the drainage system represents a potential pathway for hazardous substances or petroleum products to be released to the environment, constituting a REC for the Subject Property.

- Floor staining – The floor of the Former Sear's Auto Service Center garage was observed to be stained from historical operations. A floor area of severely stained concrete and pitting was observed near the southern entrance door to the garage. Due to the unknown nature of the staining and the potential to leach into the concrete and subsurface, the floor staining constitutes a REC for the Subject Property.

- USTs – Architectural Plans dated 1971 were reviewed for the former Sears Auto Service Center was observed during the site reconnaissance showing the installation of six 5,000-gallon gasoline USTs. In addition, records contained in the EDR Report as well as provided by Baltimore County indicate that six 5,000-gallon gasoline USTs were removed in 1986. Aerial photographs show that a concrete pad in the suspected location of the USTs was replaced with asphalt between 1982 and 1988. No additional information regarding the removal of these USTs was provided by MDE. The potential of environmental impact cannot be ruled out, constituting a REC for the Subject Property.

- Sears Gas Station – A review of historical documents revealed the former presence of a gas station in the parking lot that operated for approximately twenty years. A letter within a report provided by MDE dated 1993 references the possible removal of three 5,000-gallon USTs outside of the Former Sears Auto Service Center; however, no other documentation regarding these USTs was identified during the assessment. Three manholes and an intact concrete pad in the location of the former Auto center gas station were observed during the site reconnaissance, which would indicate that USTs in this area are still present. However, the status of the USTs could not be confirmed. The possibility of the presence of USTs and potential environmental impact cannot be ruled out, constituting a REC for the Subject Property.

- Hydraulic systems – Evidence of multiple hydraulic systems was observed in the garage of the Former Sears Auto Service Center. A review of historical documents observed in the mechanical room during the site reconnaissance depicted thirteen single-acting and five double-acting hydraulic systems installed in the building. Visual evidence that several systems remain in place was also observed during the site reconnaissance. The status and condition of the systems beneath the concrete floor is unknown. Additional

systems may be hidden from view due to the current use of the garage as storage for Baltimore County. Hydraulic systems may contain hazardous substances and/or petroleum products, and the potential for a system leak constitutes a REC for the Subject Property.

- Waste Oil UST – According to a report provided by BCDEPS, a 550-gallon steel UST containing waste oil was removed in 1993. The report indicates perforations were observed on the tank and the surrounding soil was contaminated. It is unknown if the contaminated soil has been addressed. The potential presence of contaminated soil constitutes a REC for the Subject Property.

This page intentionally left blank

8. NON-SCOPE SERVICES

No non-scope considerations or additional services were requested or included in this Phase I ESA.

This page intentionally left blank

9. STATEMENT AND SIGNATURE OF THE ENVIRONMENTAL PROFESSIONAL(S)

I declare that, to the best of my professional knowledge and belief, I meet the definition of Environmental Professional as defined in § 312.10 of 40 C.F.R. § 312. I have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the Subject Property. I have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 C.F.R. Part 312."



Jim Hulbert 1 October 2025
Project Manager

Resumes for personnel assigned to this project: Mr. Hulbert, Project Manager; Mr. Mitchell Richards, Project Engineer, are presented in Appendix G.

This page intentionally left blank

10. REFERENCES

The following sources of information were consulted as a part of this Phase I ESA.

ASTM International (ASTM) E1527-21 Standard Practices for Environmental Site Assessments: Phase I Environmental Site Assessment Process.

———. E2600-15 Standard Guide for Vapor Encroachment Screening on Property Involved In Real Estate Transactions.

EA Engineering, Science, and Technology, Inc., PBC (EA). 2025. Site reconnaissance by Mr. James Hulbert and Mr. Mitchell Richards. 7 August.

Environmental Data Resources, Inc (EDR). 2025. EDR Radius Map™ Report with Geocheck®, Inquiry Number 8056060; Aerial Photographs dated: 1938, 1943, 1952, 1957, 1964, 1971, 1979, 1982, 1988, 1994, 2007, 2011, 2015, 2018 and 2023; Historical United States Geological Survey Topographic Quadrangles dated: 1890, 1892, 1894, 1899, 1904, 1906, 1908, 1943, 1944, 1946, 1953, 1966, 1974, 1982, 2014, 2016, and 2019; Certified No Sanborn Coverage Report; City Directory Abstract; City Directories dated 1961, 1966, 1971, 1976, 1981, 1986, 1991, 2000, 2005, 2010, 2014, 2017, and 2022.

Maryland Department of Assessment and Taxation website. (WEB ADDRESS).

U.S. Geological Survey (USGS). 2019. 7.5-Minute Ellicott City Topographic Quadrangle Map.

U.S. Geological Survey (USGS). 2019. 7.5-Minute Baltimore West Topographic Quadrangle Map.

This page intentionally left blank

Appendix A

Figures



Reference: US Geological Survey Baltimore West and Ellicott City 7.5-Minute Quadrangle Topographic Maps, dated 2019 obtained from EDR, Inc. ®

6901 Security Boulevard
Baltimore, MD 21244

Figure 1

Subject Property Location Map

EA Engineering, Science, and Technology, Inc., PBC
225 Schilling Circle, Suite 400
Hunt Valley, Maryland 21031

Scale:

Not to Scale

EA Project No.
16424-04



Reference: Baltimore County Circuit Court – Plat Book EHK, Jr. 44, p. 105. Dated 6/27/1979.

6901 Security Boulevard
Baltimore, MD 21244

Figure 2

Subject Property
Tax Map

®EA Engineering, Science, and Technology, Inc., PBC
225 Schilling Circle, Suite 400
Hunt Valley, Maryland 21031

Scale:

Not to Scale

EA Project No.
16424-04



Legend

Stormwater retention pond

Electric utilities

Storm drainage

Diesel AST

Reference: USDA/NAIP, Flight Year 2023

6901 Security Square Boulevard:
Baltimore, MD 21244

Figure 3-1
Full Subject Property
Site Features

EA Engineering, Science, and Technology, Inc., PBC
225 Schilling Circle, Suite 400
Hunt Valley, Maryland 21031

Scale:
1:4000

EA Project
No. 16424-04

Legend

Diesel AST

Electrical Transformer

Elevator control room - leak

Emergency Generator (top floor) – leak

Reference: Google Maps, Map Date 2025

6901 Security Square Boulevard:
Baltimore, MD 21244

Figure 3-2
Former Macy's
Site Features

® EA Engineering, Science, and Technology, Inc., PBC
225 Schilling Circle, Suite 400
Hunt Valley, Maryland 21031

Scale:
1:870

EA Project
No. 16424-04



Legend

Electrical transformer – staining

Elevator control room - leak

See location notes

Suspect vent pipes

A.N.P. – Acid Neutralization Pit

Reference: Google Earth

6901 Security Square Boulevard:
Baltimore, MD 21244

Figure 3-3
Former Sears
Site Features

EA Engineering, Science, and Technology, Inc., PBC
225 Schilling Circle, Suite 400
Hunt Valley, Maryland 21031

Scale:
1:1400

EA Project
No. 16424-04



Legend

Approximate Auto Service Center Boundary

Hydraulic systems, single and double

Detergent spill

Concrete stain

Floor drains

Sand trap

See location notes

A.N.P. – Acid Neutralization Pit

Suspect UST vents

Reference: Allan B. Mitchell and Associates Architects, 1971
(Planning document discovered during site reconnaissance)

**6901 Security Square Boulevard:
Baltimore, MD 21244**

**Figure 3-4
Former Sears Auto Service Center
Site Features**

**® EA Engineering, Science, and Technology, Inc., PBC
225 Schilling Circle, Suite 400
Hunt Valley, Maryland 21031**

**Scale:
1:380**

**EA Project
No. 16424-04**

This page intentionally left blank

Appendix B

Supporting Documentation

EA Engineering, Science, and Technology, Inc., PBC

225 Schilling Circle, Suite 400,
Hunt Valley, MD 21031
410-584-7000
www.eaest.com

PHASE I ENVIRONMENTAL SITE ASSESSMENT
PRE-SURVEY QUESTIONNAIRE

EA has been retained to conduct a Phase I Environmental Site Assessment (ESA) of the property located at/referred to Security Square Mall - Baltimore County Parcels.

The Phase I ESA is being performed in accordance with ASTM International E1527-21 Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process. To ensure complete success of the Phase I ESA, and in accordance with the Scope of Work for this assessment, we request that you complete this questionnaire prior to the date of our site visit and return/email it to jhulbert@eaest.com.

Date: August 3, 2025

Name and title of person completing questionnaire: Stephen Lafferty, Director of Planning

Company: Baltimore County Government

Phone Number: 410-887-3215 **Length of association with property (years/month):** 3 years

Please check the following appropriate box(es) for association with property:

Property Owner: ☐ **Report User:** ☑ **Other:** ☑ **If other, please explain:** County representative

Directions: Please answer all questions to the best of your knowledge and in good faith. Mark the column corresponding to the appropriate response ("Y" = Yes; "N"= No; "U/NR" = Unknown/No Response). Additional details necessary to explain any Y or U/NR responses should be provided in the "Comment(s)" column.

	Question:	Response			Comment(s):
		Y	N	U/NR	
1.	Are you aware of any pending, threatened, or past litigation relevant to hazardous substances or petroleum products in, on, at, or from the property?	☐	☑	☐	
2.	Are you aware of any threatened, or past administrative proceedings relevant to hazardous substances or petroleum products in, on, at, or from the property?	☐	☑	☐	
3.	Are you aware of any notices from any governmental entity regarding any possible violation of environmental laws or possible liability relating to hazardous substances or petroleum products?	☐	☑	☐	
4.	Did a search of land title records (or judicial records where appropriate) identify any environmental liens that are filed or recorded against the property under federal, tribal, state, or local law?	☐	☑	☐	See attached title commitment
5.	Did a search of land title records (or judicial records where appropriate) identify any Activity and Use Limitations (AULs), such as engineering controls, land use restrictions or institutional controls that are in place at the property and/or have been filed or recorded against the property under federal, tribal, state or local law?	☐	☑	☐	See attached title commitment
6.	Do you have any specialized knowledge or experience related to the subject property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the subject property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business?	☐	☑	☐	

EA Engineering, Science, and Technology, Inc., PBC

225 Schilling Circle, Suite 400,
Hunt Valley, MD 21031
410-584-7000
www.eaest.com

Question:			Response Y	Response N	Response U/NR	Comment(s):
7.	Does the purchase price being paid for this subject property reasonably reflect the fair market value of the property? If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the property?		☐	☐	☑	
8.	Are you aware of commonly known or reasonably ascertainable information about the property that would help the environmental professional to identify conditions indicative of releases or threatened releases? For example,		☐	☐	☐	
	8a.	Do you know the past uses of the property?	☑	☐	☐	
	8b.	Do you know of specific chemicals that are present or once were present at the property?	☐	☑	☐	
	8c.	Do you know of spills or other chemical releases that have taken place at the property?	☐	☑	☐	
	8d.	Do you know of any environmental cleanups that have taken place at the property?	☐	☑	☐	
9.	Based on your knowledge and experience related to the property, are there any obvious indicators that point to the presence or likely presence of releases at the property?		☐	☑	☐	

In addition to the above, are you aware of any of the following documents? Yes ☐ No ☑
If yes, please provide copies prior to our site visit (or to our site visit personnel on the date of the onsite assessment).

1. Environmental site assessment and environmental site investigation reports (i.e., Phase I ESA, Phase II ESA, soil/groundwater testing, tank testing results, radon, lead paint, or asbestos testing, etc.).
2. Environmental compliance audit reports.
3. Environmental permits (for example, solid waste disposal permits, hazardous waste disposal permits, wastewater permits, NPDES permits, underground injection permits, air permits).
4. Registrations for underground storage tanks (USTs) and aboveground storage tanks (ASTs).
5. Safety data sheets.
6. Community right-to-know plan.
7. Safety plans, preparedness and prevention plans, spill prevention, countermeasure, and control plans, facility response plans, etc.
8. Reports regarding hydrogeological conditions on the property and surrounding area.
9. Reports regarding any self-directed or other cleanup activities conducted at the property.
10. Notices or other correspondence from any government agency relating to past or current violations of environmental laws with respect to the subject property or relating to environmental liens encumbering the property.
11. Hazardous waste generator notices or reports.
12. Geotechnical studies.
13. Risk assessments.
14. Recorded AULs.

Other information:

Parcel B - Not BC Owned, listed on title commitment
Parcel A - BC owned, listed on title commitment
Parcel D - BC Owned, listed on title commitment
Parcel C - BC Owned, listed on title commitment
Parcel E - BC Owned, not listed on title commitment, name listed on SDAT
Former Macy's - BC Owned, not listed on title commitment
Former Sears - BC owned, not listed on title commitment
Security Blvd
Belmont Ave
Rolling Rd
N Rolling Rd
West Bend Ct
Fairbrook Rd
Rolling Bend Rd
East Bend Ct
Johnnycake Rd
King William Dr
695
70
2100000047
1800004599
1800011835
1700014294
0108005580
0108005581
1800011832
1800004598
1800011833
2200028601
0105990010
1600009904
2500003341
2500003343
1900001399
1600003470
1700014291
2500019000
2500008667
1900001398
1800010199
0119271780
1700014290
2500018334
1800010198
1900010713
0113402450
1800010197
0119271830
2500020705
M00940476000
1600008512
0118100320
1600013170
1600010179
2500018342
2100007478
0120661520
1800004845
2000011457
2000011462
0119751373
2000011458
2500003392


Security Blvd
Belmont Ave
Security Blvd
MACY'S
BC
BALTIMORE COUNTY
Fairbrook Rd
CV
N Rolling Rd
CITYVIEW COMMERCIAL (CV)
HELMSMAN PROPERTIES
East Bend Ct
SET THE CAPTIVES FREE
BLUE OCEAN
695
70
Johnnycake Rd

SITE PLAN • SANITARY SEWER

BALTIMORE BELTWAY

RAMP "E"

RAMP "O"

RAMP "M"

S-E-C-U-R-I-T-Y BOULEVARD

SEARS

WOOLWORTH

PENNEY T.B.A.

J.C. PENNEY

J.C. PENNEY PARCEL = 11.9996 AC.

GENERATOR BLDG.

CONC.

HECHT'S

GCC CINEMA · 8

HUTZLERS

HUTZLERS PARCEL = 16.0262 AC.

MAY TRACT LEASED PARCEL 'B' 1.2697 AC.

MAY TRACT LEASED PARCEL 'C' 4.531± AC.

MAY TRACT LEASED PARCEL 'D' 3.190 AC.

MAY TRACT LEASED PARCEL 'E' 2.0559 AC.

NOT PART OF SITE

RETENTION POND

ELECTRIC EASEMENT

40' GAS EASEMENT

NEW PYLON SIGN

NEW CINEMA SIGN

NEW MALL PYLON SIGN

ROLLINS ROAD

FAIRBROOK ROAD

INTERSTATE 70

LEGEND

— 8"S — SANITARY SEWER

● SANITARY SEWER MANHOLE

N

Scale : 1"=80'

SU-2	SHEET NO. 84102	PRELIM / 1st SUB / CHANGES	ISSUE DATE / REVISIONS

QSS, INC.
ARCHITECTS/ENGINEERS/CONSTRUCTION MANAGERS
6305 DEEP CREEK DRIVE - PROSPECT, KENTUCKY - 40059 502-228-3537
5963 ELLENVIEW AVENUE - WOODLAND HILLS, CA. - 91367 818-992-6732
1285 SIDNEY STREET - NAUVOO, ILLINOIS - 62358 217-453-2445

SECURITY SQUARE MALL
6901 SECURITY BOULEVARD
BALTIMORE COUNTY, MARYLAND

PROPERTY MANAGEMENT CORPORATION
875 NORTH MICHIGAN AVENUE
CHICAGO, ILLINOIS 60611



SITE PLAN · STORM WATER

SHEET	SU-3
OF SHEETS	
JOB NO.	84102
PRELIM	
1st SUB	
CHANGES	
ISSUE DATE	
REVISIONS	

QSS, INC.
ARCHITECTS/ENGINEERS/CONSTRUCTION MANAGERS
6305 DEEP CREEK DRIVE - PROSPECT, KENTUCKY - 40059 502-228-3537
5963 ELLENVIEW AVENUE - WOODLAND HILLS, CA. - 91367 818-992-6732
1285 SIDNEY STREET - NAUVOO, ILLINOIS - 62358 217-453-2445

SECURITY SQUARE MALL
6901 SECURITY BOULEVARD
BALTIMORE COUNTY, MARYLAND

PROPERTY MANAGEMENT CORPORATION
875 NORTH MICHIGAN AVENUE
CHICAGO, ILLINOIS 60611

INTERSTATE 70

GCC CINEMA - 8

PENNEY T.B.A.

J. C. PENNEY PARCEL = 11.9996 AC.

J.C. PENNEY

HUTZLERS

HUTZLERS PARCEL = 16.0226 AC.

WOOLWORTH

SEARS

A.S.C.

SEARS PARCEL = 18.6061 AC.

HECHT'S

MAY TRACT LEASED PARCEL 'B' 1.2687 AC.

MAY TRACT LEASED PARCEL 'C' 4.5312 AC.

MAY TRACT LEASE PARCEL 'D' 3.190 AC.

DEVELOPER PARCEL 'A' 2.0569 AC.

NOT PART OF SITE

BALTIMORE BELTWAY

RAMP "E"

RAMP "M"

RAMP "O"

ROLLING ROAD

FAIRBROOK ROAD

SECURITY BOULEVARD

NEW CINEMA SIGN

NEW MALL PYLON SIGN

NEW SECURITY SQUARE PYLON SIGN

RETENTION POND

40' GAS EASEMENT

GENERATOR BLDG.

TEL. EQUIP. RM.

RELOCATE TRANS. TRA.

RESTAURANT

CONC. "A"

CONC. "B"

CONC. "E"

MANHOLE NO. 1

ELECTRIC EASEMENT

50' TELEPHONE EASEMENT

SEARS A.S.C. PYLON SIGN

PENNEY FREE STANDING GAS PRICE PYLON SIGN

CALDORA OUTDOOR SALES AREAS

SEALANT FULL H.

54" DUCTS

4"-4" DUCTS

4"-6" DUCTS

HOOKS 10 & 10 (18)

HOOKS 10

HOOKS 48

T1A T2 T3 T4 T5 T6 T7 T8 T9 T10 T10A T11 T12

SYMBOL LIST

- TRANSFORMER PAD MTD.
- PRIMARY SWITCHGEAR PAD MTD.
- PRIMARY ELECT. CABLE (UNDERGROUND)
- TRANSFORMER ENCLOSURE
- TELEPHONE EQUIP. ROOM
- TELEPHONE MANHOLE
- UNDERGROUND TEL. DUCT (SIZE AS NOTED)



N

Scale : 1"=80'

SITE PLAN • PRIMARY ELECT. & TEL. DISTR.

PROPERTY OF QSS, INC.

SECURITY SQUARE MALL
6901 SECURITY BOULEVARD
BALTIMORE COUNTY, MARYLAND

QSS, INC.
ARCHITECTS/ENGINEERS/CONSTRUCTION MANAGERS
6305 DEEP CREEK DRIVE - PROSPECT, KENTUCKY - 40059 502-228-3537
5963 ELLENVIEW AVENUE - WOODLAND HILLS, CA. - 91367 818-992-5732
1285 SIDNEY STREET - MAUVOO, ILLINOIS - 62358 217-453-2445

REVISIONS

ISSUE DATE

PRELIM 11/16/84
1st SUB
CHANGES

SHEET 84102

SE-1

OF SHEETS



SECURITY SQUARE MALL
6901 SECURITY BOULEVARD
BALTIMORE COUNTY, MARYLAND

PROPERTY MANAGEMENT CORPORATION
875 NORTH MICHIGAN AVENUE
CHICAGO, ILLINOIS 60611

QSS, INC.
ARCHITECTS/ENGINEERS/CONSTRUCTION MANAGERS
6305 DEEP CREEK DRIVE - PROSPECT, KENTUCKY - 40059 502-228-3537
5963 ELLENVIEW AVENUE - WOODLAND HILLS, CA. - 91367 818-902-6732
1285 SIDNEY STREET - NAPOO, ILLINOIS - 62359 217-453-2445

REVISIONS

ISSUE DATE

PRELIM.
1st SUB.
CHANGES

SHEET 3
84102

SU·1
OF SHEETS

SITE PLAN · WATER SUPPLY

SITE PLAN • GAS DISTRIBUTION

BALTIMORE BELTWAY

RAMP "E"

RAMP "O"

RAMP "M"

SECURITY BOULEVARD

INTERSTATE 70

SEARS

A.S.C.

WOOLWORTH

J.C. PENNEY

PENNEY T.B.A.

J.C. PENNEY PARCEL = 11.9996 AC.

GENERATOR BLDG.

HECHT'S

GCC CINEMA - 8

HUTZLERS

HUTZLERS PARCEL = 6.6202 AC.

SEARS PARCEL = 18.0521 AC.

MAY TRACT (LEASED) PARCEL 'B' 1.2087 AC.

MAY TRACT LEASED PARCEL 'C' 4.5912 AC.

MAY TRACT LEASED PARCEL 'D' 3.790 AC.

DEVELOPABLE PARCEL 2.0589 AC.

NOT PART OF SITE

NEW PYLON SIGN

NEW MALL PYLON SIGN

NEW CINEMA SIGN

PROBABLE LOCATION OF GAS LINES TO HUTZLERS. SIZE UNKNOWN.

RETENTION POND

BANK

FAIRBROOK ROAD

ROLLING ROAD

LEGEND

— 6"G — GAS LINE

N

Scale : 1"=80'

SHEET OF SHEETS: SU-4	ISSUE DATE: PRELIM. / 1st SUB. / CHANGES	REVISIONS	**QSS, INC.** ARCHITECTS/ENGINEERS/CONSTRUCTION MANAGERS 6305 DEEP CREEK DRIVE - PROSPECT, KENTUCKY - 40059 502-228-3537 5963 ELLENVIEW AVENUE - WOODLAND HILLS, CA. - 91367 818-992-6732 1285 SIDNEY STREET - NAUVOO, ILLINOIS - 62358 217-453-2445	**SECURITY SQUARE MALL** **6901 SECURITY BOULEVARD** **BALTIMORE COUNTY, MARYLAND**	PROPERTY MANAGEMENT CORPORATION 875 NORTH MICHIGAN AVENUE CHICAGO, ILLINOIS 60611

SHEET 84102.

ALTA COMMITMENT FOR TITLE INSURANCE

issued by:

CHICAGO TITLE INSURANCE COMPANY

Commitment Number:

202400732MD
Revision 2

Maryland Code, Insurance Article §22-104. This Document Constitutes A Statement Of The Terms And Conditions On Which A Title Insurer Is Willing To Issue A Policy Of Title Insurance If The Title Insurer Accepts The Premium For The Policy. It Is Not A Representation As To The State Of Title And Does Not Constitute An Abstract Of Title

NOTICE

IMPORTANT - READ CAREFULLY: THIS COMMITMENT IS AN OFFER TO ISSUE ONE OR MORE TITLE INSURANCE POLICIES. ALL CLAIMS OR REMEDIES SOUGHT AGAINST THE COMPANY INVOLVING THE CONTENT OF THIS COMMITMENT OR THE POLICY MUST BE BASED SOLELY IN CONTRACT.

THIS COMMITMENT IS NOT AN ABSTRACT OF TITLE, REPORT OF THE CONDITION OF TITLE, LEGAL OPINION, OPINION OF TITLE, OR OTHER REPRESENTATION OF THE STATUS OF TITLE. THE PROCEDURES USED BY THE COMPANY TO DETERMINE INSURABILITY OF THE TITLE, INCLUDING ANY SEARCH AND EXAMINATION, ARE PROPRIETARY TO THE COMPANY, WERE PERFORMED SOLELY FOR THE BENEFIT OF THE COMPANY, AND CREATE NO EXTRACONTRACTUAL LIABILITY TO ANY PERSON, INCLUDING A PROPOSED INSURED.

THE COMPANY'S OBLIGATION UNDER THIS COMMITMENT IS TO ISSUE A POLICY TO A PROPOSED INSURED IDENTIFIED IN SCHEDULE A IN ACCORDANCE WITH THE TERMS AND PROVISIONS OF THIS COMMITMENT. THE COMPANY HAS NO LIABILITY OR OBLIGATION INVOLVING THE CONTENT OF THIS COMMITMENT TO ANY OTHER PERSON.

COMMITMENT TO ISSUE POLICY

Subject to the Notice; Schedule B, Part I-Requirements; Schedule B, Part II-Exceptions; and the Commitment Conditions, Chicago Title Insurance Company, a Florida corporation (the "Company"), commits to issue the Policy according to the terms and provisions of this Commitment. This Commitment is effective as of the Commitment Date shown in Schedule A for each Policy described in Schedule A, only when the Company has entered in Schedule A both the specified dollar amount as the Proposed Amount of Insurance and the name of the Proposed Insured.

If all of the Schedule B, Part I-Requirements have not been met within one hundred eighty (180) days after the Commitment Date, this Commitment terminates and the Company's liability and obligation end.

Chicago Title Insurance Company

By:

Michael J. Nolan, President

Countersigned By:

Dianne E. Boyle

Dianne Boyle
Authorized Officer or Agent

Attest:

Marjorie Nemzura

Marjorie Nemzura, Secretary

This page is only a part of a 2021 ALTA® Commitment for Title Insurance issued by Chicago Title Insurance Company. This Commitment is not valid without the Notice; the Commitment to Issue Policy; the Commitment Conditions; Schedule A; Schedule B, Part I-Requirements; Schedule B, Part II-Exceptions; and a counter-signature by the Company or its issuing agent that may be in electronic form.

Copyright American Land Title Association. All rights reserved.

The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association.

AMERICAN LAND TITLE ASSOCIATION

Transaction Identification Data, for which the Company assumes no liability as set forth in Commitment Condition 5.e.:

ISSUING OFFICE:	FOR SETTLEMENT INQUIRIES, CONTACT:
Title Officer: Dianne Boyle Chicago Title Insurance Company 1901 Pennsylvania Ave., NW, Suite 201 Washington, DC 20006 Phone: 202-263-4745 Email: BoyleD@CTT.com	Escrow Officer: Stephanie Perez Valencia CTIC 23929 Valencia Boulevard, Suite 304 Valencia, CA 91355 Email: Stephanie.Perez@ctt.com Escrow No.: 210444-57

Order Number: 202400732MD

Prepared For: Valencia CTIC, Ref. No.: 210444-57

SCHEDULE A

1. Commitment Date: October 24, 2024 at 08:00 AM
   Court Records Date: October 11, 2024 at 08:00 AM

2. Policy to be issued:

   (a) ALTA Owner's Policy 2021 w-MD Mod
   Proposed Insured: Baltimore County, Maryland, a body politic and corporate and a political subdivision of the State of Maryland
   Proposed Amount of Insurance: $6,500,000.00
   The estate or interest to be insured: Fee Simple

3. The estate or interest in the Land at the Commitment Date is:

   Fee Simple

4. The Title is, at the Commitment Date, vested in:

   Macy's Retail Holdings, LLC, an Ohio limited liability company, formerly known as Associated Dry Goods Corporation, by virtue of a Deed and Agreement, dated February 10, 1989 and recorded February 17, 1989 in Liber 8107 at folio 160. (Parcels A, B, C and D).

5. The Land is described as follows:

   SEE EXHIBIT "A" ATTACHED HERETO AND MADE A PART HEREOF

Maryland Code, Insurance Article §22-104. This Document Constitutes A Statement Of The Terms And Conditions On Which A Title Insurer Is Willing To Issue A Policy Of Title Insurance If The Title Insurer Accepts The Premium For The Policy. It Is Not A Representation As To The State Of Title And Does Not Constitute An Abstract Of Title

END OF SCHEDULE A

Copyright American Land Title Association. All rights reserved.

The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association.

EXHIBIT "A"

Legal Description

All of that certain lot or parcel, together with all improvements located thereon, situate and lying in the County of Baltimore,Maryland, and being more particularly described as follows:

Parcel A

Beginning for the first at the point of intersection of the south right-of-way line of Security Boulevard and the west right-of-way line of existing Belmont Avenue, as shown on State Roads Commission of Maryland Plat No. 28381, opposite station 29 + 03.40 along the base line of right-of-way of said Belmont Avenue, said point also being the principal point and place of beginning of the following description:

Thence S 42° 29, 18" W a distance of 78.40 feet to a point; thence S 62° 00' 00" W a distance of 307.52 feet to a point; thence 70.69 feet along an arc to the right having a radius of 45.00 feet and a chord of 63.64 feet bearing N 73° 00' 00" W; thence 29.67 feet along an arc to the right having a radius of 56.00 feet and a chord of 29.33 feet bearing N 12° 49' 09" W; thence N 02° 21' 42" E a distance of 77.78 feet to a point; thence 142.70 feet along an arc to the right having a radius of 120.00 feet and a chord of 134.44 feet bearing N 36° 25' 46" E, said point also being on the south right-of-way line of Security Boulevard; thence in an easterly direction along said right-of-way line 307.060feet along an arc to the right having a radius of 4518.66 feet and a chord of 307.00 feet bearing S 84° 18' 20.2" E; thence continuing along said right-of-way S 82° 21' 32" E a distance of 3.35 feet to the point of beginning.

Parcel B

Beginning for the second at the point of intersection of the south right-of-way line of Security Boulevard and the west right-of-way sine of existing Belmont Avenue, as shown on State Roads Commission of Maryland Plat No. 28381, opposite station 29 + 03.40 along the base line of right-of-way of said Belmont Avenue; thence S 42° 29' 18" W a distance of 78.40 feet to a point; thence S 62° 00' 00" W a distance of 477.52 feet to the principal point and place of beginning of the following description:

Thence S 62° 00' 00" W a distance of 339.19 feet to a point; thence 70.69 feet along an arc to the right having a radius of 45.00 feet and a chord of 63.64 feet bearing N 73° 00' 00" W; thence N 28° 00' 00" W a distance of 288.30 feet to a point; thence 63.10 feet along an arc to the right having a radius of 141.00 feet and a chord of 62.57 feet bearing N 15° 10' 50" W; thence N 02° 21' 39" W a distance of 26.21 feet to a point; thence 139.16 feet along an arc to the right having a radius of 120.00 feet and a chord of 131.49 feet bearing N 30° 51' 39" E, said point also being on the south right-of-way line of Security Boulevard; thence N 87° 38' 21" E along said right-of-way line a distance of 130.11 feet to a point; thence continuing along said right-of-way line 309.11 feet along an arc to the right having a radius of 4518.66 feet and a chord of 309.05 feet bearing N 89° 35' 56" E; thence 40.87 feet along an arc to the right having a radius of 45.00 feet and a chord of 39.48 feet bearing S 23° 39' 31" E; thence S 02° 21' 42" W a distance of 154.55 feet to a point; thence 72.07 feet along an arc to the left having a radius of 136.00 feet and a chord of 71.23 feet bearing S 12° 49' 09" E; thence 70:69 feet along an arc to the right having a radius of 45.00 feet and a chord of 63.64 feet bearing S 17° 00' 00" W, said point also being the point of beginning.

Being part of the lot of ground which by Deed dated January 13, 1977 and recorded among the Land Records of Baltimore County in Liber E.H.K., Jr. No. 5812, folio 765 was granted and 14 conveyed by Zanvyl Krieger unto Beltway Properties.

Parcel C

Beginning for the third at the point of intersection of the south right-of-way line of Security Boulevard and the west right-of-way line of existing Belmont Avenue, as shown on State Roads Commission of Maryland Plat No. 28381, opposite Station 29 + 03.40 along the base line of right-of-way of said Belmont Avenue; thence South 42° 29' 18" West a distance of 78.40 feet to a point; thence South 62° 00' 00" West a distance of 986.71 feet to the principal point and place of

Copyright American Land Title Association. All rights reserved.

The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association.

beginning of the following description:

Thence South 62° 00' 00" West a distance of 161.93 feet to a point; thence South 32° 00' 00" West a distance of 109.60 feet to a point; thence South 07° 00' 00" West a distance of 13.38 feet to a point; thence 44.54 feet along an arc to the right having a radius of 45.00 feet and a chord of 42.74 feet bearing South 78° 38' 44" West; thence North 73° 00' 00" West a distance of 189.68 feet to a point; thence 132.86 feet along an arc to the left having a radius of 184.00 feet and a chord of 130.00 feet bearing South 86° 18' 49" West; thence 50.68 feet along an arc to the right having a radius of 45.00 feet and a chord of 48.04 feet beating North 82° 06' 32" West to a point on the easterly right-of-way line of Rolling Road; thence along the easterly right-of-way line of Rolling Road a distance of 82.00 feet along an arc to the right having a radius of 2235.83 feet and a chord of 82.00 feet bearing North 21° 47' 36" West; thence North 62° 00' 00" East a distance of 633.12 feet to a point; thence South 28° 00' 00" East a distance of 198.81 feet to a point; thence 70.69 feet along an arc to the right having a radius of 45.00 feet and a chord of 63.64 feet bearing South 17° 00' 00" West to the principal point and place of beginning.

TOGETHER WITH the non-exclusive easements for vehicular ingress and egress established in a Deed by and between Beltway Properties and Hechinger Company dated September 15, 1981 and recorded in Liber E.H.K., Jr. No. 6328, folio 707.

Parcel D

Lot 3, Parcel D, Security Square Shopping Center, containing 67,593 square feet or 1.552 acres, more or less, as shown on a plat entitled "Resubdivision of Parcel D, Security Square Shopping Center" recorded in Plat Book JLE 80, page 114 among the Land Records of Baltimore County, Maryland.

Copyright American Land Title Association. All rights reserved.

The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association.

SCHEDULE B, PART I - Requirements

All of the following Requirements must be met:

1. The Proposed Insured must notify the Company in writing of the name of any party not referred to in this Commitment who will obtain an interest in the Land or who will make a loan on the Land. The Company may then make additional Requirements or Exceptions.

2. Pay the agreed amount for the estate or interest to be insured.

3. Pay the premiums, fees, and charges for the Policy to the Company.

4. Documents satisfactory to the Company that convey the Title or create the Mortgage to be insured, or both, must be properly authorized, executed, delivered, and recorded in the Public Records.

   a. Deed from the current owner to the Proposed Insured.
   b. Deed of Trust from the Proposed Insured, securing indebtedness and obligations in favor of the Proposed Insured Lender.

   Note: Withholding requirement pursuant to Section 10-912 of the Tax-General Article of the Annotated Code of Maryland (the "Withholding Law"):

   (a) If the seller claims full or partial exemption from the tax, the applicable form below must be submitted with the deed for recordation:
      (i) Certification of Exemption from Withholding Upon Disposition of Maryland Real Estate Affidavit of Residence or Principal Residence; or
      (ii) Certificate of Full or Partial Exemption from Comptroller's Office (NOTE: Comptroller's Office requires that an Application for Certificate of full or partial exemption be filed a minimum of 21 days before the settlement date);
   (b) If the seller does not qualify for full exemption from withholding, the withholding tax must be paid to the Clerk of the Circuit Court at the time the deed is presented to record. Form MW 506 NRS must be completed and presented with the tax payment to the Clerk.

   Note: In the event of the transfer of the land, receipt of a current lien certificate for each subject tax parcel that is unexpired at the time of recordation of the deed of transfer; and payment of all outstanding taxes, assessments and other public charges that are shown as due and payable thereon. The Company must be advised of the scheduled closing date at least ten (10) business days in advance to order any required lien certificate(s). Scheduled closings may be delayed if this requirement is not met.

   Localities Requiring Lien Certificates: Anne Arundel County (optional), City of Annapolis, *Baltimore County*, *Baltimore City*, *Carroll County*, *Charles County*, *Frederick County*, *City of Frederick*, *Harford County and Howard County*

   Note: Payment of all applicable transfer and recordation tax is required. The Office of the Recorder of Deeds will assess the following charges in connection with transfers submitted for recordation, unless an exemption can be established: Tax Rates

   Note: Certification is required on instruments conveying an interest in real property, such certification being to the effect that the instrument has been prepared by or under the supervision of an attorney or under the supervision of

Copyright American Land Title Association. All rights reserved.

The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association.

SCHEDULE B, PART I - Requirements
(continued)

one of the parties to the instrument and the certification must be signed by such attorney or officer of one of the party entities.

Note: Any remote notarization of document must be pre-approved by the Company. Please contact this office prior to engaging a remote notary.

5. All real property taxes and assessments, general and special, must be paid through the fiscal year ending June 30, 2025. (Note: Taxes are assessed in advance on a fiscal year running from July 1 through June 30.)

The 2024-2025 Real Property Taxes were paid in the amount of $61,592.63. (Account 01-1800010198)

The 2024-2025 Real Property Taxes were paid in the amount of $13,506.53. (Account 01-1900001398)

The 2024-2025 Real Property Taxes were paid in the amount of $4,612.87. (Account 01-1700014297)

The 2024-2025 Real Property Taxes were paid in the amount of $9,319.76. (Account 01-2500019068)

Note: Notwithstanding the fact that Real Estate Taxes are not delinquent until October 1, should the transaction addressed by this Commitment involve the recordation of a Deed and such Deed is to be recorded subsequent to June 30, the real estate taxes associated with the following tax year must be paid, as required by the Clerk of the Court.

6. Evidence must be submitted of both the determination and payment of all other taxes, assessments, bonds and charges now due, and which may become due prior to the effective date of the policy anticipated by this Commitment. These taxes, assessments, bonds and charges include, but are not limited to State Tax, County Tax, Town Tax, Solid Waste Fee, water charges, or other sanitary sewer service charges, public or private, through and including the effective date of said policy.

7. A plat or survey must be submitted which has been made in accordance with "Minimum Standard Detail Requirements for ALTA/NSPS Land Title Surveys" jointly established and adopted by ALTA and NSPS effective as of February 23, 2021, and which meets the accuracy requirements of the appropriate classification of cadastral survey. Matters disclosed by the survey that in the Company's judgment constitute defects in title to the property will be shown as exceptions to coverage under the proposed policy, replacing the survey exception in the Standard Exceptions currently shown on this Commitment in Schedule B, Part II.

8. The following must be duly released of record, or the same will appear as exception(s) to coverage under the policy anticipated by this Commitment:

A. ~~Case Filed in the District Court for Baltimore County Civil Division, filed July 3, 2019 as Case No. D-08-CV-19-020599.~~ INTENTIONALLY DELETED

9. With regard to **Macy's Retail Holdings, LLC, a Ohio limited liability company** (the "LLC"), the following is required:

a. a full and complete copy of the LLC's Articles of Organization, and any amendment(s) thereto;
b. a current Good Standing Certificate issued by the Secretary of State (or equivalent) from the LLC's

Copyright American Land Title Association. All rights reserved.

The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association.

SCHEDULE B, PART I - Requirements
(continued)

jurisdiction of formation;
c. a current Certificate of Registration from the State of Maryland (foreign LLC only);
d. an Affidavit of Members accurately identifying the current membership of the LLC; and
e. a full and complete copy of the Operating Agreement governing the authority of any or all of the members of the LLC to act on behalf of the LLC.

Note: This Commitment is subject to such additional exceptions as may appear upon review of said documentation.

10. All current owners of the property must execute and deliver to the Company an owner affidavit which in the Company's judgment are sufficient in both form and content to identify:

a. rights or claims of parties in possession not shown by the public records;
b. easements, or claims of easements, not shown by the public records; or
c. the occurrence of any event which could give rise to any lien, or right to a lien, for services, labor, or material furnished, imposed by law and not shown by the public records.

Matters disclosed by the affidavits which in the Company's judgment constitute defects in title to the property will be shown as exceptions to coverage under the proposed policy, replacing the Standard Exceptions currently shown on this Commitment in Schedule B, Part II.

11. The actual value of the estate or interest to be insured must be disclosed to the Company, and subject to approval by the Company, entered as the amount of the policy to be issued. Until the amount of the policy to be issued shall be determined, and entered as aforesaid, it is agreed that as between the Company, the applicant for this Commitment, and every person relying on this Commitment, the Company cannot be required to approve any such evaluation in excess of $100,000.00 and the total liability of the Company on account of this Commitment shall not exceed said amount.

12. Note: Please be aware that due to the conflict between federal and state laws concerning the cultivation, distribution,manufacture or sale of marijuana, the Company is not able to close or insure any transaction involving Land that is associated with these activities.

13. The following endorsements may be attached to the final owner's and/or loan policy as applicable, subject to compliance with the requirements listed parenthetically, and additional underwriting requirements and premium, if applicable:

a. ALTA 3 Zoning (unimproved land) or ALTA 3.1 Zoning (improved land) [owner and loan] or ALTA 3.2 (receipt of acceptable zoning report);
b.. ALTA 4.1 Condominium Endorsement (applies only to condominium units insured in Schedule A; requires review of condominium documents and verification of payment of any current or past due condominium assessments);
c. ALTA 6-06 Variable Rate or ALTA 6.2-06 Negative Amortization [loan only] (review of loan documents);
d. ALTA 8.1 Environmental [Residential property only] or ALTA 8.2-06 Commercial Environmental (none);
e. ALTA 9, (loan only) ALTA 9.1 (owners), ALTA 9.2 (owners), ALTA 9.3-06 [loan only] ALTA 9.6 (Loan only) ALTA 9.9-06 (Owner only) (receipt of acceptable ALTA/NSPS survey and review of documents);

This page is only a part of a 2021 ALTA® Commitment for Title Insurance issued by Chicago Title Insurance Company. This Commitment is not valid without the Notice; the Commitment to Issue Policy; the Commitment Conditions; Schedule A; Schedule B, Part I-Requirements; Schedule B, Part II-Exceptions; and a counter-signature by the Company or its issuing agent that may be in electronic form.

Copyright American Land Title Association. All rights reserved.

The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association.

SCHEDULE B, PART I - Requirements
(continued)

f. ALTA 9.7 (Land Under Development – Loan only), ALTA 9.8 (Land Under Development – Owner's only) (receipt of acceptable ALTA/NSPS survey and approved plans and specs);
g. ALTA 10 Assignment [loan only with no date-down] or ALTA 10.1 Assignment and Date Down [loan only] (review of mortgage assignment document and title update if ALTA 10.1);
h. ALTA 11 Mortgage Modification [loan only] (review of modification documents and update of title);
i. ALTA 12-06 Aggregation – Loan Only (none);
j. ALTA 13-06 Leasehold [owner] or ALTA 13.1-06 [loan] (review of insured lease);
k. ALTA 14.1 Future Advance [loan only] (review of loan documents and state law to determine appropriate form);
l. ALTA 15-06 Non-Imputation (Full Equity) or ALTA 15.1-06 (Additional Equity) or ALTA 15.2-06 (Partial Equity) [owner only] (receipt of satisfactory affidavit and indemnity from existing and/or exiting entity(ies) with respect to knowledge of off-record matters);
m. ALTA 16-06 Mezzanine [owner only] (review of pledge agreements and execution of endorsement by insured owner and mezzanine lender);
n. ALTA 17-06 (access and entry) or ALTA 17.1-06 (indirect access and entry) [owner or loan] (receipt of current ALTA/NSPS survey showing access on a labeled public way, or via vested rights over a private way or easement to a public way);
o. ALTA 17.2-06 Utility Access [owner of loan] (receipt of current ALTA/NSPS survey showing access points for all listed utilities located either in a public way adjacent to the property, or within an easement appurtenant to the property);
p. ALTA 18-06 Single Tax Parcel or ALTA 18.1-06 Multiple Tax Parcel [owner and loan] (evidence that each parcel of land described in Schedule A is separately assessed for real estate taxation purposes);
q. ALTA 19-06 Contiguity (Multiple Lots) or ALTA 19.1-06 (Single Lot) (receipt of ALTA/NSPS survey showing the referenced parcels as contiguous to each other with no gores, gaps or overlays);
r. ALTA 20-06 First Loss [lender only] (review of structure of transaction – multi-site only)
s. ALTA 22-06 Location (formerly Street Address) [owner and loan] (receipt of ALTA/NSPS survey depicting the improvements on the property and the address of those improvements; verification of address with the local taxing authority);
t. ALTA 24-06 Doing Business [loan only] (none);
u. ALTA 25-06 Same as Survey or ALTA 25.1-06 Portion of Same as Survey [owner and loan] (receipt of ALTA/NSPS survey depicting the same land described in Schedule A hereof);
v. ALTA 26 Subdivision [owner or loan] (satisfactory evidence that the land described in Schedule A is in compliance with local and state subdivision laws);
w. ALTA 27 Usury [loan only) (review of loan documents and state law regarding usury);
x. ALTA 28-06 Easement – Damage or Enforced Removal [owner or loan] or ALTA 28.1 (review of easements and current ALTA/NSPS survey showing location of all easements and improvements located on the property);
y. ALTA 37-06 Assignment of Leases and Rents (Loan Only) (recordation of an Assignment of Leases and Rents);
z. ALTA 38-06 Mortgage Tax (Loan only) (none); and
aa. Pending Disbursement [loan only] (review of construction loan documents – additional requirements may be imposed including a mechanic's lien affidavit and indemnity).

END OF SCHEDULE B, PART I

This page is only a part of a 2021 ALTA® Commitment for Title Insurance issued by Chicago Title Insurance Company. This Commitment is not valid without the Notice; the Commitment to Issue Policy; the Commitment Conditions; Schedule A; Schedule B, Part I-Requirements; Schedule B, Part II-Exceptions; and a counter-signature by the Company or its issuing agent that may be in electronic form.

Copyright American Land Title Association. All rights reserved.

The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association.

SCHEDULE B, PART II - Exceptions

Some historical land records contain Discriminatory Covenants that are illegal and unenforceable by law. This Commitment and the Policy treat any Discriminatory Covenant in a document referenced in Schedule B as if each Discriminatory Covenant is redacted, repudiated, removed, and not republished or recirculated. Only the remaining provisions of the document will be excepted from coverage.

The Policy will not insure against loss or damage resulting from the terms and conditions of any lease or easement identified in Schedule A, and will include the following Exceptions unless cleared to the satisfaction of the Company:

Any defect, lien, encumbrance, adverse claim, or other matter that appears for the first time in the Public Records or is created, attaches, or is disclosed between the Commitment Date and the date on which all of the Schedule B, Part I—Requirements are met.

STANDARD EXCEPTIONS

a. Rights or claims of parties in possession not shown by the Public Records.

b. Easements, or claims of easements, not shown by the Public Records.

c. Any lien, or right to a lien, for services, labor, or material heretofore or hereafter furnished, imposed by law and not shown by the Public Records.

d. Any encumbrance, violation, variation, adverse circumstance, boundary line overlap, or encroachment (including an encroachment of an improvement across the boundary lines of the Land) that would have been disclosed by an accurate and complete land title survey of the Land.

NOTE: Upon receipt of a satisfactory owner's affidavit and the ALTA/NSPS Survey the Standard Exceptions will not be appear in the final policy, or will be modified as required based on the facts disclosed in the affidavit and/or survey.

SPECIAL EXCEPTIONS

1. Taxes and other public charges, including assessments by any State, County, Municipality, Metropolitan District or Commission payable on an annual basis subsequent to the fiscal year ending June 30, 2025, a lien not yet due and payable. This policy does not insure against the balance of any public charges, including assessments by any State, County, Municipality, Metropolitan District or Commission, payable on an annual basis subsequent to the fiscal year ending June 30, 2025. This policy insures against neither possible future tax levies nor possible public charges, as defined above, that have not been levied or assessed as of Date of Policy.

2. Rights of parties entitled to possession, as tenants only, under unrecorded leases.

3. Water charges, sanitary sewer service charges and solid waste charges arising in connection with the Land subsequent to the original Date of Policy, a lien not yet due and payable.

Copyright American Land Title Association. All rights reserved.

The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association.

SCHEDULE B, PART II - Exceptions
(continued)

The following exceptions affect Tract I:

4. Terms, provisions, conditions and easements as set forth in that certain Construction, Operation and Reciprocal Easement Agreement by and between Sears, Roebuck and Co., Hochschild, Kohn & Co., Incorporated and Security Square, Inc., dated April 7, 1971 and recorded among the Land Records of Baltimore County in Liber 5178 at folio 250; as affected by First Agreement Modifying Construction, Operation and Reciprocal Easement Agreement by and between Sears, Roebuck & Co., Hochschild, Kohn & Co., Incorporated and Security Square, Inc., dated September 14, 1971 and recorded among the aforesaid Land Records in Liber 5226 at folio 988; as further affected by Second Agreement Modifying Construction, Operation and Reciprocal Easement Agreement by Sears, Roebuck and Co., Hochschild Kohn & Co., Incorporated, J.C. Penney Properties, Inc. and Security Square Associates, dated June 25, 1973 and recorded among the aforesaid Land Records in Liber 5370 at folio 538; as further affected by Third Agreement Modifying and Supplementing Construction, Operation and Reciprocal Easement Agreement by Sears, Roebuck and Co., Supermarkets General Corporation, JC Penney Properties, Inc., The May Department Stores Company, and Security Square Associates, dated August 1, 1979 and recorded among the aforesaid Land Records in Liber 6102 at folio 121; as amended by Amendment to Third Agreement Modifying and Supplementing Construction, Operation and Reciprocal Easement Agreement by Sears, Roebuck and Co., J.C. Penney Properties, Inc., The May Department Stores Company, Hutzler Brothers Co. and Security Square Associates, dated September 4, 1986 and recorded among the aforesaid Land Records in Liber 9533 at folio 123; as assigned by Assignment and Assumption of Rights Under Construction, Operation and Reciprocal Easement Agreement by and between Hutzlers Brothers Company and Security Square Associates, dated November 1, 1987 and recorded among the aforesaid Land Records in Liber 7724 at folio 654; as further assigned by Assignment and Assumption of Construction, Operation and Reciprocal Easement Agreement by and between Security Square Associates and Montgomery Ward & Co., Incorporated, dated December 21, 1990 and recorded among the aforesaid Land Records in Liber 8681 at folio 606; as further amended by Second Amendment to Third Agreement Modifying and Supplementing Construction, Operation and Reciprocal Easement Agreement by and between Sears, Roebuck and Co., J.C. Penney Properties, Inc., The May Department Stores Company, Montgomery Ward & Co., Incorporated and Security Square Associates, dated December 30, 1992 and recorded among the aforesaid Land Records in Liber 9533 at folio 139.

The following exceptions affect Parcels A, B and C:

5. All matters as shown on Plat entitled, “Plat Showing Right of Way to Be Acquired From Edgar A. Kalb and Estella M. Kalb, Wife”, recorded in Plat Book JWB No. 14 at folio 125.

6. All matters as shown on Plat entitled, “Revision of Parcel ‘G’ Plat 2 – Security Square Shopping Center”, recorded in Plat Book EHK Jr. No. 47 at folio 72.

7. Terms, provisions, conditions and easements as set forth in that certain Deed recorded in Liber 1782 at folio 346.

8. Terms, provisions, conditions and easements as set forth in that certain Agreement recorded in Liber 3470 at folio 392.

9. Easements granted to Baltimore Gas and Electric Company, recorded in Liber 4446 at folio 626.

This page is only a part of a 2021 ALTA® Commitment for Title Insurance issued by Chicago Title Insurance Company. This Commitment is not valid without the Notice; the Commitment to Issue Policy; the Commitment Conditions; Schedule A; Schedule B, Part I-Requirements; Schedule B, Part II-Exceptions; and a counter-signature by the Company or its issuing agent that may be in electronic form.

Copyright American Land Title Association. All rights reserved.

The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association.

SCHEDULE B, PART II - Exceptions
(continued)

10. Terms, provisions, conditions and easements as set forth in that certain Declaration of Restrictions recorded in Liber 5178 at folio 231.

11. Terms, provisions, conditions and easements as set forth in that certain Construction, Operation and Reciprocal Easement Agreement by and between Sears, Roebuck and Co., Hochschild, Kohn & Co., Incorporated and Security Square, Inc., dated April 7, 1971 and recorded among the Land Records of Baltimore County in Liber 5178 at folio 250; as affected by First Agreement Modifying Construction, Operation and Reciprocal Easement Agreement by and between Sears, Roebuck & Co., Hochschild, Kohn & Co., Incorporated and Security Square, Inc., dated September 14, 1971 and recorded among the aforesaid Land Records in Liber 5226 at folio 988; as further affected by Second Agreement Modifying Construction, Operation and Reciprocal Easement Agreement by Sears, Roebuck and Co., Hochschild Kohn & Co., Incorporated, J.C. Penney Properties, Inc. and Security Square Associates, dated June 25, 1973 and recorded among the aforesaid Land Records in Liber 5370 at folio 538.

12. Ten Foot (10') Drainage and Utility Easement to Baltimore County as set forth in Deed and Agreement recorded in Liber 5413 at folio 502, as shown on Plat Book OTG No. 35 at folio 141 and Plat Book EHK Jr., No. 44 at folio 105 (Affects Parcel B).

13. Terms, provisions, conditions and easements set forth in that certain Agreement, recorded in Liber 5876 at folio 662.

14. Variable Wdith Access Easement as set forth in deeds recorded in Liber 6142 at folio 523 and Liber 6142 at folio 526, as shown on Plat Book EHK Jr. No. 47 at folio 72. (Affects Parcel C).

15. Terms, provisions, conditions and easements set forth in that certain Agreement, recorded in Liber 5886 at folio 4.

16. Ten Foot (10') wide drainage and utility easement to Baltimore County as set forth in Deed and Agreement recorded in Liber 5977 at folio 194, as shown on Plat Book EHK Jr., No. 44 at folio 105 and Plat Book EHK Jr., No. 47 at folio 72 (Affects Parcels B and C).

17. Variable width acess easement set forth in a deed recorded in Liber 6328 at folio 707, as shown on Plat Book EHK Jr., No. 47 at folio 72 (affects Parcel C).

18. Telecommunications easement to Chesapeake and Potomac Telephone Company of Maryland as set forth in instrument recorded in Liber 8931 at folio 608 (affects Parcel A).

19. Forty Foot (40') wide right of way for the construction, operation and maintenance of two underground gas mains in the easement area shown crossing Parcel B, as set forth in Deed at Liber 1776 at folio 523 and shown on Plat Book OTG No. 35 at folio 141 and Plat Book EHK Jr., No. 44 at folio 105.

20. Terms, provisions, conditions, easements, restrictions and covenants set forth in that certain Declaration of Covenants, Easements and Restrictions by Macy's Retail Holdings, LLC recorded in Liber 47157 at folio 166, as amended by Amended and Restated Declaration of Covenants, Easements and Restrictions recorded in Liber 48330 at folio 202.(Affects ALL Parcels)

This page is only a part of a 2021 ALTA® Commitment for Title Insurance issued by Chicago Title Insurance Company. This Commitment is not valid without the Notice; the Commitment to Issue Policy; the Commitment Conditions; Schedule A; Schedule B, Part I-Requirements; Schedule B, Part II-Exceptions; and a counter-signature by the Company or its issuing agent that may be in electronic form.

Copyright American Land Title Association. All rights reserved.

The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association.

SCHEDULE B, PART II - Exceptions
(continued)

The following exceptions affect Parcel D:

21. Terms, provisions, conditions and easements as set forth in that certain Deed recorded in Liber 1782 at folio 346.

22. Terms, provisions, conditions and easements as set forth in that certain Agreement recorded in Liber 3470 at folio 392.

23. Terms, provisions, conditions and easements set forth in that certain Deed recorded in Liber 3548 at folio 648.

24. Easements granted to Baltimore Gas and Electric Company, recorded in Liber 4446 at folio 626.

25. Terms, provisions, conditions and easements set forth in that certain Deed and Agreement recorded in Liber 4687 at folio 159.

26. Terms, provisions, conditions and easements set forth in that certain Deed recorded in Liber 5068 at folio 707.

27. Terms, provisions, conditions and easements set forth in that certain Deed recorded in Liber 5114 at folio 200.

28. Terms, provisions, conditions and easements set forth in that certain Deed in Liber 5126 at folio 242.

29. All matters shown on the plat recorded in Plat Book 35, page 141.

30. Terms, provisions, conditions and easements set forth in that certain Deed recorded in Liber 5172 at folio 741.

31. Term, provisions, conditions and easements set forth in that certain Deed and Agreement recorded in Liber 5178 at folio 199.

32. Terms, provisions, conditions and easements set forth in that certain Confirmatory Deed and Agreement recorded in Liber 5228 at folio 723.

33. Terms, provisions, conditions and easements set forth in that certain Agreement, recorded in Liber 5876 at folio 662.

34. Terms, provisions, conditions and easements set forth in that certain Agreement, recorded in Liber 5886 at folio 4.

35. Terms, provisions, conditions and easements set forth in that certain Deed and Agreement recorded in Liber 5977 at folio 194.

36. Terms, provisions, conditions and easements set forth in that certain Declaration recorded in Liber 6210 at folio 562.

This page is only a part of a 2021 ALTA® Commitment for Title Insurance issued by Chicago Title Insurance Company. This Commitment is not valid without the Notice; the Commitment to Issue Policy; the Commitment Conditions; Schedule A; Schedule B, Part I-Requirements; Schedule B, Part II-Exceptions; and a counter-signature by the Company or its issuing agent that may be in electronic form.

Copyright American Land Title Association. All rights reserved.

The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association.

SCHEDULE B, PART II - Exceptions
(continued)

37. Terms, provisions, conditions and easements set forth in that certain Deed recorded in Liber 6328 at folio 707.

38. Easement granted to The Chesapeake and Potomac Telephone Company of Maryland recorded in Liber 8931 at folio 608.

39. All matters shown on the plat recorded in Plat Book 80, page 114.

END OF SCHEDULE B, PART II

This page is only a part of a 2021 ALTA® Commitment for Title Insurance issued by Chicago Title Insurance Company. This Commitment is not valid without the Notice; the Commitment to Issue Policy; the Commitment Conditions; Schedule A; Schedule B, Part I-Requirements; Schedule B, Part II-Exceptions; and a counter-signature by the Company or its issuing agent that may be in electronic form.

Copyright American Land Title Association. All rights reserved.

The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association.

COMMITMENT CONDITIONS

1. DEFINITIONS

a. "Discriminatory Covenant": Any covenant, condition, restriction, or limitation that is unenforceable under applicable law because it illegally discriminates against a class of individuals based on personal characteristics such as race, color, religion, sex, sexual orientation, gender identity, familial status, disability, national origin, or other legally protected class.

b. "Knowledge" or "Known": Actual knowledge or actual notice, but not constructive notice imparted by the Public Records.

c. "Land": The land described in Item 5 of Schedule A and improvements located on that land that by State law constitute real property. The term "Land" does not include any property beyond that described in Schedule A, nor any right, title, interest, estate, or easement in any abutting street, road, avenue, alley, lane, right-of-way, body of water, or waterway, but does not modify or limit the extent that a right of access to and from the Land is to be insured by the Policy.

d. "Mortgage": A mortgage, deed of trust, trust deed, security deed, or other real property security instrument, including one evidenced by electronic means authorized by law.

e. "Policy": Each contract of title insurance, in a form adopted by the American Land Title Association, issued or to be issued by the Company pursuant to this Commitment.

f. "Proposed Amount of Insurance": Each dollar amount specified in Schedule A as the Proposed Amount of Insurance of each Policy to be issued pursuant to this Commitment.

g. "Proposed Insured": Each person identified in Schedule A as the Proposed Insured of each Policy to be issued pursuant to this Commitment.

h. "Public Records": The recording or filing system established under State statutes in effect at the Commitment Date under which a document must be recorded or filed to impart constructive notice of matters relating to the Title to a purchaser for value without Knowledge. The term "Public Records" does not include any other recording or filing system, including any pertaining to environmental remediation or protection, planning, permitting, zoning, licensing, building, health, public safety, or national security matters.

i. "State": The state or commonwealth of the United States within whose exterior boundaries the Land is located. The term "State" also includes the District of Columbia, the Commonwealth of Puerto Rico, the U.S. Virgin Islands, and Guam.

j. "Title": The estate or interest in the Land identified in Item 3 of Schedule A.

2. If all of the Schedule B, Part I-Requirements have not been met within the time period specified in the Commitment to Issue Policy, this Commitment terminates and the Company's liability and obligation end.

3. The Company's liability and obligation is limited by and this Commitment is not valid without:

a. the Notice;

b. the Commitment to Issue Policy;

c. the Commitment Conditions;

d. Schedule A;

e. Schedule B, Part I-Requirements;

f. Schedule B, Part II-Exceptions; and

g. a counter-signature by the Company or its issuing agent that may be in electronic form.

4. COMPANY'S RIGHT TO AMEND

The Company may amend this Commitment at any time. If the Company amends this Commitment to add a defect, lien, encumbrance, adverse claim, or other matter recorded in the Public Records prior to the Commitment Date, any liability of the Company is limited by Commitment Condition 5. The Company is not liable for any other amendment to this Commitment.

5. LIMITATIONS OF LIABILITY

a. The Company's liability under Commitment Condition 4 is limited to the Proposed Insured's actual expense incurred in the interval between the Company's delivery to the Proposed Insured of the Commitment and the delivery of the amended Commitment, resulting from the Proposed Insured's good faith reliance to:

i. comply with the Schedule B, Part I-Requirements;

ii. eliminate, with the Company's written consent, any Schedule B, Part II-Exceptions; or

iii. acquire the Title or create the Mortgage covered by this Commitment.

b. The Company is not liable under Commitment Condition 5.a. if the Proposed Insured requested the amendment or had Knowledge of the matter and did not notify the Company about it in writing.

c. The Company is only liable under Commitment Condition 4 if the Proposed Insured would not have incurred the expense had the Commitment included the added matter when the Commitment was first delivered to the Proposed Insured.

d. The Company's liability does not exceed the lesser of the Proposed Insured's actual expense incurred in good faith and described in Commitment Condition 5.a. or the Proposed Amount of Insurance.

This page is only a part of a 2021 ALTA® Commitment for Title Insurance issued by Chicago Title Insurance Company. This Commitment is not valid without the Notice; the Commitment to Issue Policy; the Commitment Conditions; Schedule A; Schedule B, Part I-Requirements; Schedule B, Part II-Exceptions; and a counter-signature by the Company or its issuing agent that may be in electronic form.

Copyright American Land Title Association. All rights reserved.

The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association.

AMERICAN LAND TITLE ASSOCIATION

(continued)

e. The Company is not liable for the content of the Transaction Identification Data, if any.

f. The Company is not obligated to issue the Policy referred to in this Commitment unless all of the Schedule B, Part I-Requirements have been met to the satisfaction of the Company.

g. The Company's liability is further limited by the terms and provisions of the Policy to be issued to the Proposed Insured.

6. LIABILITY OF THE COMPANY MUST BE BASED ON THIS COMMITMENT; CHOICE OF LAW AND CHOICE OF FORUM

a. Only a Proposed Insured identified in Schedule A, and no other person, may make a claim under this Commitment.

b. Any claim must be based in contract under the State law of the State where the Land is located and is restricted to the terms and provisions of this Commitment. Any litigation or other proceeding brought by the Proposed Insured against the Company must be filed only in a State or federal court having jurisdiction.

c. This Commitment, as last revised, is the exclusive and entire agreement between the parties with respect to the subject matter of this Commitment and supersedes all prior commitment negotiations, representations, and proposals of any kind, whether written or oral, express or implied, relating to the subject matter of this Commitment.

d. The deletion or modification of any Schedule B, Part II-Exception does not constitute an agreement or obligation to provide coverage beyond the terms and provisions of this Commitment or the Policy.

e. Any amendment or endorsement to this Commitment must be in writing and authenticated by a person authorized by the Company.

f. When the Policy is issued, all liability and obligation under this Commitment will end and the Company's only liability will be under the Policy.

7. IF THIS COMMITMENT IS ISSUED BY AN ISSUING AGENT

The issuing agent is the Company's agent only for the limited purpose of issuing title insurance commitments and policies. The issuing agent is not the Company's agent for closing, settlement, escrow, or any other purpose.

8. PRO-FORMA POLICY

The Company may provide, at the request of a Proposed Insured, a pro-forma policy illustrating the coverage that the Company may provide. A pro-forma policy neither reflects the status of Title at the time that the pro-forma policy is delivered to a Proposed Insured, nor is it a commitment to insure.

9. CLAIMS PROCEDURES

This Commitment incorporates by reference all Conditions for making a claim in the Policy to be issued to the Proposed Insured. Commitment Condition 9 does not modify the limitations of liability in Commitment Conditions 5 and 6.

10. CLASS ACTION

ALL CLAIMS AND DISPUTES ARISING OUT OF OR RELATING TO THIS COMMITMENT, INCLUDING ANY SERVICE OR OTHER MATTER IN CONNECTION WITH ISSUING THIS COMMITMENT, ANY BREACH OF A COMMITMENT PROVISION, OR ANY OTHER CLAIM OR DISPUTE ARISING OUT OF OR RELATING TO THE TRANSACTION GIVING RISE TO THIS COMMITMENT, MUST BE BROUGHT IN AN INDIVIDUAL CAPACITY. NO PARTY MAY SERVE AS PLAINTIFF, CLASS MEMBER, OR PARTICIPANT IN ANY CLASS OR REPRESENTATIVE PROCEEDING. ANY POLICY ISSUED PURSUANT TO THIS COMMITMENT WILL CONTAIN A CLASS ACTION CONDITION.

11. ARBITRATION – INTENTIONALLY DELETED

END OF CONDITIONS

This page is only a part of a 2021 ALTA® Commitment for Title Insurance issued by Chicago Title Insurance Company. This Commitment is not valid without the Notice; the Commitment to Issue Policy; the Commitment Conditions; Schedule A; Schedule B, Part I-Requirements; Schedule B, Part II-Exceptions; and a counter-signature by the Company or its issuing agent that may be in electronic form.

Copyright American Land Title Association. All rights reserved.

The use of this Form (or any derivative thereof) is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association.

This page intentionally left blank

Appendix C

Photographic Log

Photo 1: Former Macy's front view

Photo 2: Sales floor (typical)

Photo 3: Air compressor

Photo 4: Paint Mixer

Photo 5: Fire suppression system

Photo 6: Air handling unit

Photo 7: Cardboard baler

Photo 8: Waste oil bucket in customer elevator control room

Photo 9: Paint cans in customer elevator control room

Photo 10: Oil leak in customer elevator control room

Photo 11: Floor staining in electrical room

Photo 12: Dry transformer (typical)

Photo 13: Dry transformer

Photo 14: Dry transformer

Photo 15: Dry transformer

Photo 16: Dry transformer

Photo 17: Dry transformer

Photo 18: Hazardous waste collection area (vacant)

Photo 19: Mechanical room, floor drain visible



Photo 20: Oil leaking from tank of emergency generator into floor drain, mechanical room

Photo 21: Roof air conditioning unit



Photo 22: Top floor AC piping

Photo 23: Outdoor utilities area overview

Photo 24: Electric transformer in outdoor utility area

Photo 25: Above ground storage tank in outdoor utility area for emergency generator, assumed diesel fuel



Photo 26: AST label

Photo 1: Parcel A

Photo 2: Utility box Parcel A

Photo 3: Parcel C

Photo 4: Parcel C storm drain (typical)

Photo 5: Parcel D

Photo 6: Parcel D stormwater retention pond

Photo 7: Parcel D storm drain

Photo 8: Parcel E

Photo 9: Parcel E, remnant pipes in parking lot

Photo 10: Parcel E, stormwater manhole (typical)

Photo 11: Parcel E, stormwater drain (typical)

Photo 12: Parcel E, electrical utilities

Photo 13: North adjoining properties, Exxon station and Security Boulevard

Photo 14: Northwest adjoining properties, Weis market and gas station

Photo 15: West adjoining properties, Tuscany woods apartments and Rolling Road

Photo 16: View of Interstate 70 to the South

Photo 17: View of on-ramp to Interstate 695 from Security Boulevard to the east

Photo 18: Collision repair center located to the southeast of the Security Square mall complex

Photo 1: Former Sears front view

Photo 2: Outdoor utility area—electrical transformer and switch box

Photo 3: Leaking oil from electrical transformer in outdoor utility area

Photo 4: Sales floor (typical)

Photo 5: Oil leak in customer elevator control room

Photo 6: Oil drum located in customer elevator control room,

Photo 7: Oil leak in utility elevator control room

Photo 8: Garage overview

Photo 9: Hydraulic system remnants in garage

Photo 10: Stained concrete in garage

Photo 11: Detergent spill in garage

Photo 12: Floor drain in garage (typical)

Photo 13: Sand trap in garage

Photo 14: Floor drain in men's bathroom

Photo 15: Floor drain in locker room



Photo 16: Floor drain second floor mechanical room

Photo 17: Floor staining second floor mechanical room

Photo 18: Floor drain in second floor mechanical room

Photo 19: Fire suppression system

Photo 20: Air compressor pads with stains and floor drain

Photo 21: Former Sears parking lot overview

Photo 22: Former Sears lot gas station location



Photo 23: Broken vents outside former auto shop

Photo 24: Suspect UST location and oil water separator outside former auto shop

Photo 25: Oil water separator

Photo 26: Acid neutralization pit

Photo 27: Former Sears lot sewer manhole

Photo 28: Electric utilities in former Sears lot



Photo 29: Planning documents overview



Photo 30: Sears auto service center in planning documents



Photo 31: Acid neutralization pit in planning documents



Photo 32: Hydraulic systems in planning documents



Photo 33: Waste oil tank and sand trap in planning documents



Photo 34: 5,000-gallon Gasoline USTs location in planning documents

This page intentionally left blank

Appendix D

Environmental Records Search

Security Square Mall
6901 Security Boulevard
Windsor Mill, MD 21244

Inquiry Number: 8056060.2s
July 24, 2025

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	260
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-9
Physical Setting Source Map Findings	A-10
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA) INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2025 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527 - 21), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E2247 - 16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E1528 - 22) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

6901 SECURITY BOULEVARD
WINDSOR MILL, MD 21244

COORDINATES

Latitude (North):	39.3106540 - 39° 18' 38.35''
Longitude (West):	76.7502290 - 76° 45' 0.82''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	349101.0
UTM Y (Meters):	4352503.0
Elevation:	459 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	14434506 BALTIMORE WEST, MD
Version Date:	2019
West Map:	14403185 ELLICOTT CITY, MD
Version Date:	2019

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20230525
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
6901 SECURITY BOULEVARD
WINDSOR MILL, MD 21244

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	SEARS STORE #1634	6901 SECURITY BLVD	RCRA-SQG, E MANIFEST		TP
A2	GRAND AUTO BODY & CA	6901 SECURITY BLVD	FINDS, ECHO		TP
A3	BULL ON THE BEACH	6901 SECURITY BOULEV	US AIRS, FINDS, ECHO		TP
A4	J C PENNEY CO	6901 SECURITY BLVD	MD OCPCASES		TP
A5	BOB'S BIG BOY	6901 SECURITY BLVD	FINDS, ECHO		TP
A6	BRIDGESTONE/FIRESTON	6901 SECURITY BLVD.	UST FINDER		TP
A7	SECURITY WARDS LLC	6901 SECURITY BLVD	MD MANIFEST		TP
A8	MICHAELS TAILOR & DR	6901 SECURITY BLVD	EDR Hist Cleaner		TP
A9	SS SELF STORAGE LLC	6901 SECURITY BLVD	MD UST, MD Financial Assurance		TP
A10	TANNER ENTERPRISES	6901 SECURITY BLVD.	FINDS		TP
A11	MACYS SECURITY SQUAR	6901 SECURITY BLVD	ECHO		TP
A12	SEARS STORE #1634	6901 SECURITY BLVD.	US AIRS, FINDS		TP
A13	J.C. PENNEY CO. INC.	6901 SECURITY BLVD	US AIRS		TP
A14	CRASH CHAMPIONS - WI	6901 SECURITY BLVD	US AIRS, FINDS, ECHO		TP
A15		6901 SECURITY BLVD	ERNS		TP
A16	MACY'S STORE #159	6901 SECURITY BLVD	MD MANIFEST		TP
A17	SEARS, ROEBUCK AND C	6901 SECURITY BLVD.	MD UST, MD Financial Assurance		TP
A18	SEOUL PLAZA (FMR FIR	6901 SECURITY BLVD S	MD OCPCASES		TP
A19	J. C. PENNY PROPERTI	6901 SECURITY BLVD	MD HIST UST		TP
A20	MONTGOMERY WARD CO	6901 SECURITY SQUARE	RCRA-VSQG, E MANIFEST		TP
A21	FIRESTONE SECURITY M	6901 SECURITY BLVD	MD OCPCASES		TP
A22	SEARS 1634	6901 SECURITY BLVD	PA MANIFEST		TP
A23	SET THE CAPTIVES FRE	6901 SECURITY BLVD,	MD ASBESTOS		TP
A24	HECHT'S	6901 SECURITY BLVD	MD OCPCASES		TP
A25	SEARS, ROEBUCK AND C	6901 SECURITY BLVD.	UST FINDER		TP
A26	SIGNATURE COLLISION	6901 SECURITY BLVD #	RCRA-VSQG, E MANIFEST		TP
A27	FIRESTONE MASTERCARE	6901 SECURITY BLVD	MD HIST UST		TP
A28	SS SELF STORAGE LLC	6901 SECURITY BLVD	MD OCPCASES		TP
A29	SEARS #1634	6901 SECURITY SQ BLV	MD MANIFEST		TP
A30	J.C. PENNEY CO. INC.	6901 SECURITY BLVD	FINDS, ECHO		TP
A31	SEARS STORE #1634	6901 SECURITY BLVD	MD OCPCASES, MD ASBESTOS		TP
A32	SECURITY MALL	6901 SECURITY BLVD	MD HIST UST		TP
A33	GRAND AUTO BODY	6901 SECURITY BOULEV	US AIRS		TP
A34	MACY'S SECURITY SQUA	6901 SECURITY BLVD.	UST FINDER		TP
A35	MACY'S SECURITY SQUA	6901 SECURITY BLVD.	MD UST, MD Financial Assurance		TP
A36	MACYS SECURITY SQUAR	6901 SECURITY BLVD.	ECHO, E MANIFEST		TP
A37	SEARS UNIT #1634	6901 SECURITY SQUARE	MD ASBESTOS		TP
A38	BURLINGTON	6901 SECURITY BOULEV	E MANIFEST		TP
A39	SEARS ROEBUCK - SECU	6901 SECURITY BOULEV	FINDS		TP

MAPPED SITES SUMMARY

Target Property Address:
6901 SECURITY BOULEVARD
WINDSOR MILL, MD 21244

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A40	SEARS ROEBUCK & COMP	6901 SECURITY BLVD	MD HIST UST		TP
A41	MACYS SECURITY SQUAR	6901 SECURITY BLVD	RCRA NonGen / NLR		TP
A42	SEARS	6901 SECURITY SQ BLV	E MANIFEST		TP
A43	MACY'S	6901 SECURITY BLVD	MD OCPCASES		TP
A44	JC PENNEY CO.	6901 SECURITY BLVD	MD UST, MD Financial Assurance		TP
A45	BRIDGESTONE/FIRESTON	6901 SECURITY BLVD.	MD UST, MD Financial Assurance		TP
B46	CARE CLEANERS	7005 SECURITY BOULEV	MD DRYCLEANERS, MD NPDES	Lower	1 ft.
B47	WEIS GAS N' GO	7005 SECURITY BLVD	MD OCPCASES	Lower	1 ft.
B48	CARE CLEANERS	7005 SECURITY BOULEV	RCRA NonGen / NLR, FINDS, ECHO	Lower	1 ft.
B49	WEIS GAS N' GO #229	7005 SECURITY BLVD.	UST FINDER	Lower	1 ft.
B50	CARE CLEANERS	7005 SECURITY BLVD	EDR Hist Cleaner	Lower	1 ft.
B51	WEIS MARKET	7005 SECURITY BLVD	E MANIFEST	Lower	1 ft.
B52	WEIS GAS N' GO #229	7005 SECURITY BLVD.	MD UST, MD Financial Assurance	Lower	1 ft.
B53	MACYS INC	6975 SECURITY BLVD	PA MANIFEST	Lower	2, 0.000,
B54	FIRESTONE	6921 SECURITY BLVD	MD OCPCASES	Lower	3, 0.001,
55	HOUSEHOLD BANK	1700 ROLLING RD	MD OCPCASES	Higher	63, 0.012, SW
B56	RUPERT LILY-DRIVER	SECURITY BLVD & BELM	MD OCPCASES	Lower	66, 0.013, North
C57	DIAMOND CLEANERS	1732 N. ROLLING ROAD	MD MANIFEST	Lower	78, 0.015, SW
C58	DIAMOND CLEANERS	1732 NORTH ROLLING R	MD DRYCLEANERS	Lower	78, 0.015, SW
C59	DIAMOND CLEANERS INC	1732 N ROLLING RD	EDR Hist Cleaner	Lower	78, 0.015, SW
C60	DIAMOND CLEANERS	1732 N ROLLING RD	RCRA-VSQG, FINDS, ECHO, RI MANIFEST	Lower	78, 0.015, SW
D61	TOWN & COUNTRY - ROL	7106 ROLLING BEND RD	MD HIST UST	Higher	167, 0.032, West
D62	STREET SPILL	7106 ROLLING BEND RD	MD OCPCASES, MD LEAD	Higher	167, 0.032, West
D63	TOWN & COUNTRY ROLLI	7108 ROLLING BEND RD	MD OCPCASES	Higher	168, 0.032, West
D64	TOWN & COUNTRY ROLLI	7105 ROLLING BEND RD	MD OCPCASES	Higher	182, 0.034, West
E65	SECURITY STATION	1700 TO 1750 NORTH R	MD INST CONTROL	Higher	232, 0.044, WSW
E66	SECURITY STATION	1700 TO 1750 NORTH R	MD LRP	Higher	232, 0.044, WSW
F67	EXXON SERVICE STATIO	1601 BELMONT AVE	UST FINDER, UST FINDER RELEASE	Lower	252, 0.048, North
F68	27733 SECURITY SQUAR	1601 BELMONT AVENUE	MD OCPCASES, MD UST, MD Financial Assurance	Lower	252, 0.048, North
F69	SECURITY SQUARE MALL	1601 BELMONT AVE	EDR Hist Auto	Lower	252, 0.048, North
F70	EXXON #27733	1601 BELMONT AVE	MD OCPCASES	Lower	252, 0.048, North
F71	EXXON SERVICE STATIO	1601 BELMONT AVE	MD OCPCASES	Lower	252, 0.048, North
F72	EXXON R\S #27733	1601 BELMONT AVE	MD HIST UST	Lower	254, 0.048, North
F73	LSR MOTOR FUELS INC	1604 BELMONT AVE	EDR Hist Auto	Lower	293, 0.055, North
G74	MAY AMBULANCE	1811 N ROLLING RD	MD OCPCASES	Higher	329, 0.062, WNW
H75	TOWN & COUNTRY ROLLI	9 W BEND CT	MD OCPCASES	Higher	411, 0.078, West
I76	KOONS FORD OF BALTIM	6970 SECURITY BLVD	MD HIST UST	Lower	430, 0.081, NNW
I77	KOONS FORD, BALTIMOR	6970 SECURITY BLVD	MD OCPCASES, MD UST, MD Financial Assurance	Lower	430, 0.081, NNW
I78	KOONS FORD	6970 SECURITY BLVD	RCRA NonGen / NLR, US AIRS, FINDS, ECHO	Lower	430, 0.081, NNW

MAPPED SITES SUMMARY

Target Property Address:
6901 SECURITY BOULEVARD
WINDSOR MILL, MD 21244

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
I79	KOONS FORD, BALTIMOR	6970 SECURITY BLVD	UST FINDER	Lower	430, 0.081, NNW
H80	TOWN & COUNTRY ROLLI	8 W BEND CT	MD OCPCASES	Higher	452, 0.086, West
G81	MOBIL	1900 N ROLLING RD	MD OCPCASES	Lower	465, 0.088, WNW
G82	SECURITY SUNOCO	1900 N ROLLING RD	MD OCPCASES	Lower	465, 0.088, WNW
G83	FJ SONS ENTERPRISES	1900 N ROLLING RD	EDR Hist Auto	Lower	465, 0.088, WNW
G84	SECURITY SUNOCO	1900 N. ROLLING ROAD	UST FINDER	Lower	465, 0.088, WNW
G85	MOBIL	1900 N ROLLING RD	MD OCPCASES	Lower	465, 0.088, WNW
G86	CMF 2134	1900 N. ROLLING ROAD	MD UST, MD Financial Assurance	Lower	465, 0.088, WNW
J87	TOWN & COUNTRY ROLLI	7115 ROLLING BEND RD	MD OCPCASES	Higher	468, 0.089, West
88	GRACE GAS AND TRANSP	7000 SECURITY BLVD	EDR Hist Auto	Lower	483, 0.091, NW
K89	NATIONAL COATINGS &	2040-R LORD BALTIMOR	MD MANIFEST	Lower	494, 0.094, NNW
K90	NATIONAL COATINGS -	2040-R LORD BALTIMOR	RCRA-VSQG, NJ MANIFEST	Lower	494, 0.094, NNW
L91	TOWN & COUNTRY ROLLI	4 E BEND CT	MD OCPCASES	Higher	497, 0.094, WSW
92	SHA BRIDGE 0313300	I-695 RAMP (7) OVER	RCRA-LQG, FINDS, ECHO	Lower	509, 0.096, NW
L93	TOWN & COUNTRY ROLLI	3 E BEND CT	MD OCPCASES	Higher	526, 0.100, WSW
J94	TOWN & COUNTRY ROLLI	7132 ROLLING BEND RD	MD OCPCASES	Higher	549, 0.104, WSW
95	RAMADA HOTEL	1701 BELMONT AVE	MD OCPCASES	Lower	592, 0.112, NNE
J96	TOWN & COUNTRY ROLLI	7142 ROLLING BEND RD	MD OCPCASES	Higher	644, 0.122, WSW
K97	PJS LLC COMMERCIAL P	2015 LORD BALTIMORE	MD OCPCASES	Lower	648, 0.123, NNW
K98	PJS LLC COMMERCIAL P	2015 LORD BALTIMORE	UST FINDER RELEASE	Lower	648, 0.123, NNW
L99	TOWN & COUNTRY ROLLI	7127 ROLLING BEND RD	MD OCPCASES	Higher	691, 0.131, WSW
K100	MERRITT CORPORATION	2066 LORD BALTIMORE	UST FINDER	Lower	706, 0.134, NNW
K101	MERRITT CORPORATION	2066 LORD BALTIMORE	MD OCPCASES, MD UST, MD Financial Assurance	Lower	706, 0.134, NNW
M102	TOWN & COUNTRY ROLLI	7139 ROLLING BEND RD	MD OCPCASES	Higher	825, 0.156, WSW
M103	TOWN & COUNTRY ROLLI	7145 ROLLING BEND RD	MD OCPCASES	Higher	890, 0.169, WSW
N104	CHADWICK CLEANERS	7133 SECURITY BOULEV	MD DRYCLEANERS	Lower	1027, 0.195, WNW
O105	SECURITY BLVD SITE	1718 K. BELMONT AVE.	SEMS-ARCHIVE	Lower	1037, 0.196, NNE
O106	SECURITY BLVD SITE	1718 K BELMONT AVE	MD SHWS	Lower	1037, 0.196, NNE
N107	CHADWICK CLEANERS	7133 SECURITY BLVD	RCRA NonGen / NLR, FINDS, ECHO	Lower	1039, 0.197, WNW
N108	KAISER PERMANENTE -	7141 SECURITY BLVD	RCRA-SQG, E MANIFEST	Lower	1045, 0.198, WNW
N109	RITE AID #02209	7153 SECURITY BLVD	MD MANIFEST	Lower	1072, 0.203, WNW
N110	RITE AID # 2209	7153 SECURITY BOULEV	PA MANIFEST	Lower	1072, 0.203, WNW
N111	DBA RITE AID # 2209	7153 SECURITY BLVD	RCRA NonGen / NLR, FINDS, ECHO, E MANIFEST	Lower	1072, 0.203, WNW
P112	MIL SPEC PAINTING IN	1720 BELMONT AVE STE	E MANIFEST	Lower	1080, 0.205, NE
P113	SECURITY BOULEVARD S	1718 BELMONT AVENUE	MD LRP	Lower	1080, 0.205, NE
P114	MIL-SPEC PAINTING IN	1720 BELMONT AVE	RCRA-SQG, E MANIFEST, NJ MANIFEST	Lower	1080, 0.205, NE
P115	MIL-SPEC PAINTING	1720 BELMONT AVE	MD PFAS	Lower	1080, 0.205, NE
P116	MIL-SPEC PAINTING IN	1720 BELMONT AVE	PFAS ECHO	Lower	1080, 0.205, NE
P117	MIL SPEC PAINTING IN	1720 BELMONT AVE STE	MD MANIFEST	Lower	1080, 0.205, NE

MAPPED SITES SUMMARY

Target Property Address:
6901 SECURITY BOULEVARD
WINDSOR MILL, MD 21244

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
P118	MIL SPEC PAINTING IN	1720 1720 BELMONT AV	E MANIFEST	Lower	1080, 0.205, NE
P119	SECURITY ANNEX	1711 BELMONT AVENUE	UST FINDER, UST FINDER RELEASE	Lower	1196, 0.227, NE
P120	MD STATE POLICE SECU	1711 BELMONT AVE	MD OCPCASES	Lower	1196, 0.227, NE
P121	MD STATE POLICE ANNE	1711 BELMONT AVE	MD OCPCASES	Lower	1196, 0.227, NE
P122	MD STATE POLICE SECU	1711 BELMONT AVE	MD OCPCASES	Lower	1196, 0.227, NE
123	CHADWICK CLEANERS	7137 SECURITY BOULEV	MD LRP	Higher	1199, 0.227, West
N124	CHADWICK SHELL #517	7175 SECURITY BOULEV	MD UST, MD Financial Assurance	Lower	1215, 0.230, WNW
N125	CHADWICK SHELL #517	7175 SECURITY BOULEV	UST FINDER, UST FINDER RELEASE	Lower	1215, 0.230, WNW
N126	CHADWICK STORE #517	7175 SECURITY BLVD	MD OCPCASES	Lower	1215, 0.230, WNW
127	DENNIS MENDOZA PROPE	1700 HILL DR	MD OCPCASES	Lower	1332, 0.252, NNE
128	ALIKHAN RESIDENCE	6627 JOHNNYCAKE RD	MD OCPCASES	Lower	1413, 0.268, SSE
Q129	WESTVIEW PARK NOA	1505 N. ROLLING ROAD	SEMS-ARCHIVE	Lower	1459, 0.276, SSW
Q130	WESTVIEW PARK NOA SI	1505 NORTH ROLLING R	MD LRP	Lower	1459, 0.276, SSW
R131	AMOCO	6698 SECURITY BOULEV	MD HIST LUST	Lower	1611, 0.305, East
R132	AMOCO #1221	6698 SECURITY BLVD	MD OCPCASES	Lower	1709, 0.324, ENE
R133	SECURITY BP	6698 SECURITY BOULEV	UST FINDER, UST FINDER RELEASE	Lower	1709, 0.324, ENE
S134	RAHILL PROPERTY	1720 WHITEHEAD RD	MD OCPCASES	Lower	1733, 0.328, NE
T135	KOREAN UNITED CHURCH	1501 N ROLLING RD	UST FINDER RELEASE	Higher	1763, 0.334, SSW
T136	NEW LIFE PRESBYTERIA	1501 N ROLLING RD	UST FINDER RELEASE	Higher	1763, 0.334, SSW
T137	KOREAN UNITED CHURCH	1501 N.ROLLING RD	MD OCPCASES, US AIRS, FINDS, ECHO	Higher	1763, 0.334, SSW
S138	MAC MACHINE	1719 WHITEHEAD RD	MD OCPCASES	Lower	1876, 0.355, NE
139	RESIDENTIAL PROPERTY	6666 SECURITY BLVD	MD OCPCASES	Lower	1910, 0.362, East
U140	BEVERAGE CAPITOL COR	1620 WHITEHEAD RD	MD OCPCASES	Lower	1958, 0.371, East
U141	BEVERAGE CAPITAL COR	1620 WHITEHEAD COURT	UST FINDER, UST FINDER RELEASE	Lower	1958, 0.371, East
V142	TOWN & COUNTRY GARDE	1609 BLUFFDALE RD	MD OCPCASES	Higher	2007, 0.380, WSW
143	CENTER FOR MEDICADE	7500 SECURITY BLVD	MD OCPCASES	Lower	2011, 0.381, WNW
144	MATTHEWS PROPERTY	6701 EDWARDS AVE	MD OCPCASES	Lower	2027, 0.384, NNE
V145	TOWN & COUNTRY GARDE	1621 BLUFFDALE RD	MD OCPCASES	Higher	2039, 0.386, WSW
W146	FOX CHEVROLET	6633 SECURITY BLVD.	UST FINDER, UST FINDER RELEASE	Lower	2251, 0.426, East
W147	FOX CHEVROLET	6633 SECURITY BLVD	MD OCPCASES	Lower	2251, 0.426, East
W148	TCG MANAGEMENT INC	6640 SECURITY BLVD	MD OCPCASES	Lower	2417, 0.458, East
149	LITTLE SLIPPER DAY C	2112 N ROLLING RD	MD OCPCASES	Lower	2454, 0.465, NW
W150	MEADOWS PARK SHOPPIN	6606-6658 SECURITY B	MD INST CONTROL, MD VCP, MD LRP	Lower	2454, 0.465, East
151	AUTONATION LOCATION	6611 SECURITY BLVD	MD OCPCASES, MD UST, MD Financial Assurance	Lower	2615, 0.495, East

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 8 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
SEARS STORE #1634 6901 SECURITY BLVD WINDSOR MILL, MD 21244	RCRA-SQG EPA ID:: MDR000015511 E MANIFEST	MDR000015511
GRAND AUTO BODY & CA 6901 SECURITY BLVD BALTIMORE), MD 21244	FINDS Registry ID:: 110022379399 ECHO Registry ID: 110022379399	N/A
BULL ON THE BEACH 6901 SECURITY BOULEV WOODLAWN, MD 21207	US AIRS Database: US AIRS MINOR, Date of Government Version: 10/12/2016 EPA plant ID:: 110001778791 FINDS Registry ID:: 110001778791 ECHO Registry ID: 110001778791	N/A
J C PENNEY CO 6901 SECURITY BLVD WINDSOR MILL, MD 21244	MD OCPCASES Facility Status: CLOSED Facility Id: 93-2242BA2	N/A
BOB'S BIG BOY 6901 SECURITY BLVD BALTIMORE, MD 21207	FINDS Registry ID:: 110002339880 ECHO Registry ID: 110002339880	N/A
BRIDGESTONE/FIRESTON 6901 SECURITY BLVD. BALTIMORE, MD 21244	UST FINDER	N/A
SECURITY WARDS LLC 6901 SECURITY BLVD BALTIMORE, MD 21244	MD MANIFEST	N/A
MICHAELS TAILOR & DR 6901 SECURITY BLVD BALTIMORE, MD 21244	EDR Hist Cleaner	N/A
SS SELF STORAGE LLC 6901 SECURITY BLVD WINDSOR MILL, MD 21244	MD UST	N/A

EXECUTIVE SUMMARY

	Facility Id: 21208 Tank Status: Permanently Out Of Use MD Financial Assurance Database: FIN ASSURANCE 2, Date of Government Version: 04/01/2025 Facility Id: 21208	
TANNER ENTERPRISES 6901 SECURITY BLVD. BALTIMORE, MD 21244	FINDS Registry ID:: 110019905389	N/A
MACYS SECURITY SQUAR 6901 SECURITY BLVD WINDSOR MILL, MD 21244	ECHO	N/A
SEARS STORE #1634 6901 SECURITY BLVD. BALTIMORE, MD 21207	US AIRS Database: US AIRS MINOR, Date of Government Version: 10/12/2016 EPA plant ID:: 110022380644 FINDS Registry ID:: 110022380644	N/A
J.C. PENNEY CO. INC. 6901 SECURITY BLVD CATONSVILLE, MD 21207	US AIRS Database: US AIRS MINOR, Date of Government Version: 10/12/2016 EPA plant ID:: 110002021035	N/A
CRASH CHAMPIONS - WI 6901 SECURITY BLVD BALTIMORE, MD 21207	US AIRS Database: US AIRS MINOR, Date of Government Version: 10/12/2016 EPA plant ID:: 110001261438 FINDS Registry ID:: 110003532730 Registry ID:: 110001261438 ECHO Registry ID: 110003532730 Registry ID: 110001261438	N/A
6901 SECURITY BLVD 6901 SECURITY BLVD WINDSOR MILL, MD	ERNS NRC Report #: 1134542 Incident Date Time: 2015-11-25 12:00:00	N/A
MACY'S STORE #159 6901 SECURITY BLVD BALTIMORE, MD 21244	MD MANIFEST	N/A
SEARS, ROEBUCK AND C 6901 SECURITY BLVD. BALTIMORE, MD 21244	MD UST	N/A

	Facility Id: 14022 Tank Status: Permanently Out of Use MD Financial Assurance Database: FIN ASSURANCE 2, Date of Government Version: 04/01/2025 Facility Id: 14022	
SEOUL PLAZA (FMR FIR 6901 SECURITY BLVD S BALTIMORE, MD 21207	MD OCPCASES Date Closed: 12/30/2015 Facility Status: CLOSED Facility Id: 15-0515BA	N/A
J. C. PENNY PROPERTI 6901 SECURITY BLVD GWYNN OAK, MD 21207	MD HIST UST Facility Id: 3003747 Tank Status: REMOVED	N/A
MONTGOMERY WARD CO 6901 SECURITY SQUARE BALTIMORE, MD 21207	RCRA-VSQG EPA ID:: MDD985408335 E MANIFEST	MDD985408335
FIRESTONE SECURITY M 6901 SECURITY BLVD BALTIMORE, MD 21244	MD OCPCASES Date Closed: 07/12/1994 Facility Status: CLOSED Facility Id: 94-2145BA2	N/A
SEARS 1634 6901 SECURITY BLVD BALTIMORE, MD 21244	PA MANIFEST Generator EPA Id: MDR000015511 Generator EPA Id: MDR000516369	N/A
SET THE CAPTIVES FRE 6901 SECURITY BLVD, BALTIMORE, MD 21207	MD ASBESTOS	N/A
HECHT'S 6901 SECURITY BLVD BALTIMORE, MD 21207	MD OCPCASES Date Closed: 02/15/2006 Facility Status: CLOSED Facility Id: 04-0455BA1	N/A
SEARS, ROEBUCK AND C 6901 SECURITY BLVD. BALTIMORE, MD 21244	UST FINDER	N/A

EXECUTIVE SUMMARY

SIGNATURE COLLISION 6901 SECURITY BLVD # BALTIMORE, MD 21244	RCRA-VSQG EPA ID:: MDD150022150 E MANIFEST	MDD150022150
FIRESTONE MASTERCARE 6901 SECURITY BLVD GWYNN OAK, MD 21207	MD HIST UST Facility Id: 3003990 Tank Status: REMOVED Tank Status: CURRENTL	N/A
SS SELF STORAGE LLC 6901 SECURITY BLVD WINDSOR MILL, MD 21244	MD OCPCASES Date Closed: 06/20/2023 Facility Status: CLOSED Facility Id: 23-0411BA	N/A
SEARS #1634 6901 SECURITY SQ BLV BALTIMORE-WEST, MD 21244	MD MANIFEST	N/A
J.C. PENNEY CO. INC. 6901 SECURITY BLVD WINDSOR MILL, MD 21244	FINDS Registry ID:: 110002021035 ECHO Registry ID: 110002021035	N/A
SEARS STORE #1634 6901 SECURITY BLVD BALTIMORE, MD 21244	MD OCPCASES Date Closed: 03/28/1995 Facility Status: CLOSED Facility Id: 94-1624BA2 MD ASBESTOS	N/A
SECURITY MALL 6901 SECURITY BLVD GWYNN OAK, MD 21207	MD HIST UST Facility Id: 3001797 Tank Status: CURRENTL	N/A
GRAND AUTO BODY 6901 SECURITY BOULEV WINDSOR MILL, MD 21244	US AIRS Database: US AIRS MINOR, Date of Government Version: 10/12/2016	N/A
MACY'S SECURITY SQUA 6901 SECURITY BLVD. BALTIMORE, MD 21207	UST FINDER	N/A
MACY'S SECURITY SQUA 6901 SECURITY BLVD. BALTIMORE, MD 21207	MD UST	N/A

	Facility Id: 6267 Tank Status: Permanently Out Of Use	
	MD Financial Assurance Database: FIN ASSURANCE 2, Date of Government Version: 04/01/2025 Facility Id: 6267	
MACYS SECURITY SQUAR 6901 SECURITY BLVD. BALTIMORE, MD 21244	ECHO Registry ID: 110022380644	N/A
	E MANIFEST	
SEARS UNIT #1634 6901 SECURITY SQUARE BALTIMORE, MD 21244	MD ASBESTOS	N/A
BURLINGTON 6901 SECURITY BOULEV BALTIMORE, MD 21244	E MANIFEST	N/A
SEARS ROEBUCK - SECU 6901 SECURITY BOULEV WOODLAWN, MD 21207	FINDS Registry ID:: 110019858732	N/A
SEARS ROEBUCK & COMP 6901 SECURITY BLVD GWYNN OAK, MD 21207	MD HIST UST Facility Id: 3013156 Tank Status: REMOVED	N/A
MACYS SECURITY SQUAR 6901 SECURITY BLVD WINDSOR MILL, MD 21244	RCRA NonGen / NLR EPA ID:: MDR000516369	MDR000516369
SEARS 6901 SECURITY SQ BLV BALTIMORE-WEST, MD 21244	E MANIFEST	N/A
MACY'S 6901 SECURITY BLVD BALTIMORE, MD 21207	MD OCPCASES Date Closed: 05/02/2013 Facility Status: CLOSED Facility Id: 13-0249BA	N/A
JC PENNEY CO. 6901 SECURITY BLVD BALTIMORE, MD 21207	MD UST Facility Id: 16393	N/A

Tank Status: Permanently Out of Use

MD Financial Assurance
Database: FIN ASSURANCE 2, Date of Government Version: 04/01/2025
Facility Id: 16393

BRIDGESTONE/FIRESTON
6901 SECURITY BLVD.
BALTIMORE, MD 21244

MD UST N/A
Facility Id: 5743
Tank Status: Permanently Out Of Use

MD Financial Assurance
Database: FIN ASSURANCE 2, Date of Government Version: 04/01/2025
Facility Id: 5743

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Lists of Federal Delisted NPL sites

Delisted NPL ---------- National Priority List Deletions

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS ---------- Corrective Action Report

Lists of Federal RCRA TSD facilities

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROLS ---------- Institutional Controls Sites List

EXECUTIVE SUMMARY

Lists of state and tribal landfills and solid waste disposal facilities

MD SWF/LF ---- Permitted Solid Waste Disposal Facilities

Lists of state and tribal leaking storage tanks

INDIAN LUST ---- Leaking Underground Storage Tanks on Indian Land

Lists of state and tribal registered storage tanks

FEMA UST ---- Underground Storage Tank Listing
MD AST ---- Permitted Aboveground Storage Tanks
INDIAN UST ---- Underground Storage Tanks on Indian Land

State and tribal institutional control / engineering control registries

MD ENG CONTROLS ---- Engineering Controls Site listing

Lists of state and tribal voluntary cleanup sites

INDIAN VCP ---- Voluntary Cleanup Priority Listing

Lists of state and tribal brownfield sites

MD BROWNFIELDS ---- Eligible Brownfields Properties

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ---- A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

MD SWRCY ---- Recycling Directory
INDIAN ODI ---- Report on the Status of Open Dumps on Indian Lands
ODI ---- Open Dump Inventory
DEBRIS REGION 9 ---- Torres Martinez Reservation Illegal Dump Site Locations
IHS OPEN DUMPS ---- Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ---- Delisted National Clandestine Laboratory Register
US CDL ---- National Clandestine Laboratory Register

Local Land Records

LIENS 2 ---- CERCLA Lien Information

Records of Emergency Release Reports

HMIRS ---- Hazardous Materials Information Reporting System
MD SPILLS 90 ---- SPILLS 90 data from FirstSearch

Other Ascertainable Records

FUDS	Formerly Used Defense Sites
DOD	Department of Defense Sites
SCRD DRYCLEANERS	State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR	Financial Assurance Information
EPA WATCH LIST	EPA WATCH LIST
2020 COR ACTION	2020 Corrective Action Program List
TSCA	Toxic Substances Control Act
TRIS	Toxic Chemical Release Inventory System
SSTS	Section 7 Tracking Systems
ROD	Records Of Decision
RMP	Risk Management Plans
RAATS	RCRA Administrative Action Tracking System
PRP	Potentially Responsible Parties
PADS	PCB Activity Database System
ICIS	Integrated Compliance Information System
FTTS	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS	Material Licensing Tracking System
COAL ASH DOE	Steam-Electric Plant Operation Data
COAL ASH EPA	Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER	PCB Transformer Registration Database
RADINFO	Radiation Information Database
HIST FTTS	FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS	Incident and Accident Data
CONSENT	Superfund (CERCLA) Consent Decrees
INDIAN RESERV	Indian Reservations
FUSRAP	Formerly Utilized Sites Remedial Action Program
UMTRA	Uranium Mill Tailings Sites
LEAD SMELTERS	Lead Smelter Sites
US MINES	Mines Master Index File
MINES MRDS	Mineral Resources Data System
ABANDONED MINES	Abandoned Mines
DOCKET HWC	Hazardous Waste Compliance Docket Listing
UXO	Unexploded Ordnance Sites
FUELS PROGRAM	EPA Fuels Program Registered Listing
PFAS NPL	Superfund Sites with PFAS Detections Information
PFAS FEDERAL SITES	Federal Sites PFAS Information
PFAS TRIS	List of PFAS Added to the TRI
PFAS TSCA	PFAS Manufacture and Imports Information
PFAS RCRA MANIFEST	PFAS Transfers Identified In the RCRA Database Listing
PFAS ATSDR	PFAS Contamination Site Location Listing
PFAS WQP	Ambient Environmental Sampling for PFAS
PFAS PROJECT	NORTHEASTERN UNIVERSITY PFAS PROJECT
PFAS NPDES	Clean Water Act Discharge Monitoring Information
PFAS ECHO FIRE TRAIN	Facilities in Industries that May Be Handling PFAS Listing
PFAS PT 139 AIRPORT	All Certified Part 139 Airports PFAS Information Listing
AQUEOUS FOAM NRC	Aqueous Foam Related Incidents Listing
BIOSOLIDS	ICIS-NPDES Biosolids Facility Data
MD AIRS	Permit and Facility Information Listing
MD COAL ASH	Coal Ash Disposal Site Listing
MD UIC	Underground Injection Wells Database

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP	EDR Proprietary Manufactured Gas Plants

EXECUTIVE SUMMARY

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

MD RGA HWS..... Recovered Government Archive State Hazardous Waste Facilities List
MD RGA LF..... Recovered Government Archive Solid Waste Facilities List
MD RGA LUST..... Recovered Government Archive Leaking Underground Storage Tank

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 06/26/2025 has revealed that there are 2 SEMS-ARCHIVE sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
SECURITY BLVD SITE Site ID: 0300346 EPA Id: MDD981035405	1718 K. BELMONT AVE.	NNE 1/8 - 1/4 (0.196 mi.)	O105	150
WESTVIEW PARK NOA	1505 N. ROLLING ROAD	SSW 1/4 - 1/2 (0.276 mi.)	Q129	238

EXECUTIVE SUMMARY

Lists of Federal RCRA generators

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 06/02/2025 has revealed that there is 1 RCRA-LQG site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
SHA BRIDGE 0313300 EPA ID:: MDR000527067	***I-695 RAMP (7) OVER***	***NW 0 - 1/8 (0.096 mi.)***	***92***	***139***

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 06/02/2025 has revealed that there are 2 RCRA-SQG sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
KAISER PERMANENTE - EPA ID:: MDR000526244	***7141 SECURITY BLVD***	***WNW 1/8 - 1/4 (0.198 mi.)***	***N108***	***156***
MIL-SPEC PAINTING IN EPA ID:: MDR000006262	***1720 BELMONT AVE***	***NE 1/8 - 1/4 (0.205 mi.)***	***P114***	***199***

RCRA-VSQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-VSQG list, as provided by EDR, and dated 06/02/2025 has revealed that there are 2 RCRA-VSQG sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
DIAMOND CLEANERS EPA ID:: MDR000005900	***1732 N ROLLING RD***	***SW 0 - 1/8 (0.015 mi.)***	***C60***	***97***
NATIONAL COATINGS - EPA ID:: MDR000523045	***2040-R LORD BALTIMOR***	***NNW 0 - 1/8 (0.094 mi.)***	***K90***	***132***

Lists of state- and tribal hazardous waste facilities

MD SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of the Environment's Notice of Potential Hazardous Waste Sites list.

A review of the MD SHWS list, as provided by EDR, and dated 10/01/2009 has revealed that there is 1 MD SHWS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
SECURITY BLVD SITE Facility Id: (MD-188) Facility Status: No Further Remedial Action	1718 K BELMONT AVE	NNE 1/8 - 1/4 (0.196 mi.)	O106	151

Lists of state and tribal leaking storage tanks

MD OCPCASES: Cases monitored by the Oil Control Program.

A review of the MD OCPCASES list, as provided by EDR, and dated 01/02/2025 has revealed that there are 48 MD OCPCASES sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HOUSEHOLD BANK Date Closed: 11/07/1986 Facility Status: CLOSED Facility Id: 7-0763BA2	1700 ROLLING RD	SW 0 - 1/8 (0.012 mi.)	55	93
STREET SPILL Date Closed: 05/13/2004 Facility Status: CLOSED Facility Id: 04-1717BA1	***7106 ROLLING BEND RD***	***W 0 - 1/8 (0.032 mi.)***	***D62***	***103***
TOWN & COUNTRY ROLLI Date Closed: 06/01/1995 Facility Status: CLOSED Facility Id: 94-2893BA2	7108 ROLLING BEND RD	W 0 - 1/8 (0.032 mi.)	D63	104
TOWN & COUNTRY ROLLI Date Closed: 05/31/1995 Facility Status: CLOSED Facility Id: 94-2894BA2	7105 ROLLING BEND RD	W 0 - 1/8 (0.034 mi.)	D64	104
MAY AMBULANCE Date Closed: 12/27/1987 Facility Status: CLOSED Facility Id: 7-2090BA	1811 N ROLLING RD	WNW 0 - 1/8 (0.062 mi.)	G74	117
TOWN & COUNTRY ROLLI Date Closed: 06/01/1995 Facility Status: CLOSED Facility Id: 94-2904BA2	9 W BEND CT	W 0 - 1/8 (0.078 mi.)	H75	117
TOWN & COUNTRY ROLLI	8 W BEND CT	W 0 - 1/8 (0.086 mi.)	H80	126

Date Closed: 06/01/1995 Facility Status: CLOSED Facility Id: 94-2903BA2				
TOWN & COUNTRY ROLLI Date Closed: 03/31/1995 Facility Status: CLOSED Facility Id: 94-2895BA2	7115 ROLLING BEND RD	W 0 - 1/8 (0.089 mi.)	J87	131
TOWN & COUNTRY ROLLI Date Closed: 05/31/1995 Facility Status: CLOSED Facility Id: 94-2898BA2	4 E BEND CT	WSW 0 - 1/8 (0.094 mi.)	L91	138
TOWN & COUNTRY ROLLI Date Closed: 05/31/1995 Facility Status: CLOSED Facility Id: 94-2897BA2	3 E BEND CT	WSW 0 - 1/8 (0.100 mi.)	L93	142
TOWN & COUNTRY ROLLI Date Closed: 05/31/1995 Facility Status: CLOSED Facility Id: 94-2896BA2	7132 ROLLING BEND RD	WSW 0 - 1/8 (0.104 mi.)	J94	143
TOWN & COUNTRY ROLLI Date Closed: 05/31/1995 Facility Status: CLOSED Facility Id: 94-2902BA2	7142 ROLLING BEND RD	WSW 0 - 1/8 (0.122 mi.)	J96	144
TOWN & COUNTRY ROLLI Date Closed: 05/31/1997 Facility Status: CLOSED Facility Id: 94-2899BA2	7127 ROLLING BEND RD	WSW 1/8 - 1/4 (0.131 mi.)	L99	145
TOWN & COUNTRY ROLLI Date Closed: 12/31/1995 Facility Status: CLOSED Facility Id: 94-2900BA2	7139 ROLLING BEND RD	WSW 1/8 - 1/4 (0.156 mi.)	M102	148
TOWN & COUNTRY ROLLI Date Closed: 05/31/1995 Facility Status: CLOSED Facility Id: 94-2901BA2	7145 ROLLING BEND RD	WSW 1/8 - 1/4 (0.169 mi.)	M103	149
KOREAN UNITED CHURCH Date Closed: 01/03/2017 Date Closed: 12/27/2005 Facility Status: CLOSED Facility Id: 16-0378BA Facility Id: 92-2214BA1	***1501 N.ROLLING RD***	***SSW 1/4 - 1/2 (0.334 mi.)***	***T137***	***247***
TOWN & COUNTRY GARDE Date Closed: 05/31/1995 Facility Status: CLOSED Facility Id: 94-2879BA2	1609 BLUFFDALE RD	WSW 1/4 - 1/2 (0.380 mi.)	V142	251
TOWN & COUNTRY GARDE Date Closed: 06/01/1995 Facility Status: CLOSED Facility Id: 94-2820BA2	1621 BLUFFDALE RD	WSW 1/4 - 1/2 (0.386 mi.)	V145	252

Lower Elevation	Address	Direction / Distance	Map ID	Page
WEIS GAS N' GO	7005 SECURITY BLVD	0 - 1/8 (0.000 mi.)	B47	84

Date Closed: 08/05/2016 Facility Status: CLOSED Facility Id: 15-0686BA				
FIRESTONE Date Closed: 12/19/1994 Facility Status: CLOSED Facility Id: 95-1429BA2	6921 SECURITY BLVD	0 - 1/8 (0.001 mi.)	B54	93
RUPERT LILY-DRIVER Date Closed: 01/25/1996 Facility Status: CLOSED Facility Id: 96-1410BA2	SECURITY BLVD & BELM	N 0 - 1/8 (0.013 mi.)	B56	94
27733 SECURITY SQUAR Date Closed: 08/21/1995 Date Closed: 09/19/2008 Date Closed: 03/19/2008 Facility Status: CLOSED Facility Id: 96-0349BA2 Facility Id: 06-0286BA1 Facility Id: 08-0168BA	***1601 BELMONT AVENUE***	***N 0 - 1/8 (0.048 mi.)***	***F68***	***111***
EXXON #27733 Facility Status: CLOSED Facility Id: 94-1884BA2	1601 BELMONT AVE	N 0 - 1/8 (0.048 mi.)	F70	115
EXXON SERVICE STATIO Date Closed: 11/02/2000 Facility Status: CLOSED Facility Id: 00-2099BA1	1601 BELMONT AVE	N 0 - 1/8 (0.048 mi.)	F71	115
KOONS FORD, BALTIMOR Date Closed: 04/06/1995 Facility Status: CLOSED Facility Id: 92-2234BA2 Facility Id: 92-2236BA2 Facility Id: 92-2237BA2	***6970 SECURITY BLVD***	***NNW 0 - 1/8 (0.081 mi.)***	***I77***	***118***
MOBIL Date Closed: 07/02/1996 Facility Status: CLOSED Facility Id: 97-0019BA2	1900 N ROLLING RD	WNW 0 - 1/8 (0.088 mi.)	G81	126
SECURITY SUNOCO Date Closed: 02/04/2011 Facility Status: CLOSED Facility Id: 10-0300BA	1900 N ROLLING RD	WNW 0 - 1/8 (0.088 mi.)	G82	126
MOBIL Date Closed: 05/10/2005 Facility Status: CLOSED Facility Id: 04-0715BA1	1900 N ROLLING RD	WNW 0 - 1/8 (0.088 mi.)	G85	129
RAMADA HOTEL Date Closed: 11/01/1994 Facility Status: CLOSED Facility Id: 90-2404BA2	1701 BELMONT AVE	NNE 0 - 1/8 (0.112 mi.)	95	143
PJS LLC COMMERCIAL P Date Closed: 07/18/2017 Facility Status: CLOSED	2015 LORD BALTIMORE	NNW 0 - 1/8 (0.123 mi.)	K97	144

Facility Id: 17-0730BA				
MERRITT CORPORATION Date Closed: 03/25/1992 Facility Status: CLOSED Facility Id: 92-0295BA2	***2066 LORD BALTIMORE***	***NNW 1/8 - 1/4 (0.134 mi.)***	***K101***	***147***
MD STATE POLICE SECU Date Closed: 08/21/1998 Facility Status: CLOSED Facility Id: 98-1962BA2	1711 BELMONT AVE	NE 1/8 - 1/4 (0.227 mi.)	P120	231
MD STATE POLICE ANNE Date Closed: 09/16/1994 Facility Status: CLOSED Facility Id: 93-0762BA2	1711 BELMONT AVE	NE 1/8 - 1/4 (0.227 mi.)	P121	232
MD STATE POLICE SECU Date Closed: 06/03/2013 Facility Status: CLOSED Facility Id: 10-0438BA	1711 BELMONT AVE	NE 1/8 - 1/4 (0.227 mi.)	P122	232
CHADWICK STORE #517 Date Closed: 01/11/2006 Facility Status: CLOSED Facility Id: 06-0027BA2	7175 SECURITY BLVD	WNW 1/8 - 1/4 (0.230 mi.)	N126	237
DENNIS MENDOZA PROPE Date Closed: 05/13/2004 Facility Status: CLOSED Facility Id: 02-1388BA1	1700 HILL DR	NNE 1/4 - 1/2 (0.252 mi.)	127	237
ALIKHAN RESIDENCE Date Closed: 04/28/2004 Facility Status: CLOSED Facility Id: 03-1984BA1	6627 JOHNNYCAKE RD	SSE 1/4 - 1/2 (0.268 mi.)	128	238
AMOCO #1221 Date Closed: 09/16/1997 Facility Status: CLOSED Facility Id: 92-1107BA2	6698 SECURITY BLVD	ENE 1/4 - 1/2 (0.324 mi.)	R132	241
RAHILL PROPERTY Date Closed: 10/12/1999 Facility Status: CLOSED Facility Id: 99-2858BA2	1720 WHITEHEAD RD	NE 1/4 - 1/2 (0.328 mi.)	S134	245
MAC MACHINE Date Closed: 10/10/1989 Facility Status: CLOSED Facility Id: 90-0434BA2	1719 WHITEHEAD RD	NE 1/4 - 1/2 (0.355 mi.)	S138	248
RESIDENTIAL PROPERTY Date Closed: 02/14/1995 Facility Status: CLOSED Facility Id: 95-1859BA2	6666 SECURITY BLVD	E 1/4 - 1/2 (0.362 mi.)	139	248
BEVERAGE CAPITOL COR Date Closed: 03/03/1999 Facility Status: CLOSED Facility Id: 99-1154BA2	1620 WHITEHEAD RD	E 1/4 - 1/2 (0.371 mi.)	U140	249
CENTER FOR MEDICADE	7500 SECURITY BLVD	WNW 1/4 - 1/2 (0.381 mi.)	143	251

Facility Status: OPEN Facility Id: 05-1221BA				
MATTHEWS PROPERTY Date Closed: 09/19/1995 Facility Status: CLOSED Facility Id: 96-0544BA2	6701 EDWARDS AVE	NNE 1/4 - 1/2 (0.384 mi.)	144	251
FOX CHEVROLET Date Closed: 07/06/2009 Facility Status: CLOSED Facility Id: 09-0496BA	6633 SECURITY BLVD	E 1/4 - 1/2 (0.426 mi.)	W147	255
TCG MANAGEMENT INC Date Closed: 07/15/1991 Facility Status: CLOSED Facility Id: 91-2687BA	6640 SECURITY BLVD	E 1/4 - 1/2 (0.458 mi.)	W148	255
LITTLE SLIPPER DAY C Date Closed: 12/22/1993 Facility Status: CLOSED Facility Id: 90-2351BA2	2112 N ROLLING RD	NW 1/4 - 1/2 (0.465 mi.)	149	256
AUTONATION LOCATION Date Closed: 01/03/2018 Facility Status: CLOSED Facility Id: 17-0667BA	***6611 SECURITY BLVD***	***E 1/4 - 1/2 (0.495 mi.)***	***151***	***258***

MD HIST LUST: In 1999, the Department of the Environment stopped adding new sites to its Recovery Sites Database. Current leaking underground storage tank information maybe found in underground storage tank information maybe found in the OCPCASES database.

A review of the MD HIST LUST list, as provided by EDR, and dated 03/01/1999 has revealed that there is 1 MD HIST LUST site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
AMOCO Open Or Closed: CLOSED Case Number: 92-1107BA	6698 SECURITY BOULEV	E 1/4 - 1/2 (0.305 mi.)	R131	241

Lists of state and tribal registered storage tanks

MD UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of the Environment's Listing of Underground Storage Tanks Reported in Maryland.

A review of the MD UST list, as provided by EDR, and dated 04/01/2025 has revealed that there are 6 MD UST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
WEIS GAS N' GO #229 Facility Id: 20550 Tank Status: Currently In Use	***7005 SECURITY BLVD.***	***0 - 1/8 (0.000 mi.)***	***B52***	***91***
27733 SECURITY SQUAR	***1601 BELMONT AVENUE***	***N 0 - 1/8 (0.048 mi.)***	***F68***	***111***

Facility Id: 6865
Tank Status: Permanently Out Of Use
Tank Status: Currently In Use

KOONS FORD, BALTIMOR	***6970 SECURITY BLVD***	***NNW 0 - 1/8 (0.081 mi.)***	***I77***	***118***
Facility Id: 13221 Tank Status: Permanently Out of Use				
CMF 2134	***1900 N. ROLLING ROAD***	***WNW 0 - 1/8 (0.088 mi.)***	***G86***	***129***
Facility Id: 5444 Tank Status: Currently In Use Tank Status: Permanently Out Of Use				
MERRITT CORPORATION	***2066 LORD BALTIMORE***	***NNW 1/8 - 1/4 (0.134 mi.)***	***K101***	***147***
Facility Id: 8234 Tank Status: Permanently Out of Use				
CHADWICK SHELL #517	***7175 SECURITY BOULEV***	***WNW 1/8 - 1/4 (0.230 mi.)***	***N124***	***233***
Facility Id: 7047 Tank Status: Permanently Out of Use				

State and tribal institutional control / engineering control registries

MD INST CONTROL: Sites included in the Voluntary Cleanup Program Applicants/Participants listing that have Deed Restrictions.

A review of the MD INST CONTROL list, as provided by EDR, and dated 09/23/2024 has revealed that there are 2 MD INST CONTROL sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SECURITY STATION	1700 TO 1750 NORTH R	WSW 0 - 1/8 (0.044 mi.)	E65	105

Lower Elevation	Address	Direction / Distance	Map ID	Page
MEADOWS PARK SHOPPIN	***6606-6658 SECURITY B***	***E 1/4 - 1/2 (0.465 mi.)***	***W150***	***256***

Lists of state and tribal voluntary cleanup sites

MD VCP: The Voluntary Cleanup Program, administrated by the Dept. of the Environment, streamlines the environmental cleanup process for sites, usually industrial or commercial properties that are contaminated, or perceived to be contaminated, by hazardous substances. Developers and lenders are provided with certain limitations on liability and particpants in the program are provided certainty in the process by knowing exactly what will be required.

A review of the MD VCP list, as provided by EDR, and dated 09/23/2024 has revealed that there is 1 MD VCP site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
MEADOWS PARK SHOPPIN	***6606-6658 SECURITY B***	***E 1/4 - 1/2 (0.465 mi.)***	***W150***	***256***

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Registered Storage Tanks

MD HIST UST: Historical UST Registered Database.

A review of the MD HIST UST list, as provided by EDR, and dated 11/21/1996 has revealed that there are 3 MD HIST UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
TOWN & COUNTRY - ROL Facility Id: 6014691 Tank Status: PERM. OU	7106 ROLLING BEND RD	W 0 - 1/8 (0.032 mi.)	D61	101

Lower Elevation	Address	Direction / Distance	Map ID	Page
EXXON R\S #27733 Facility Id: 3003702 Tank Status: CURRENTL Tank Status: REMOVED	1601 BELMONT AVE	N 0 - 1/8 (0.048 mi.)	F72	116
KOONS FORD OF BALTIM Facility Id: 3003195 Tank Status: REMOVED Tank Status: EXEMPT Tank Status: CURRENTL	6970 SECURITY BLVD	NNW 0 - 1/8 (0.081 mi.)	I76	117

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 06/02/2025 has revealed that there are 4 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CARE CLEANERS EPA ID:: MDR000001776	***7005 SECURITY BOULEV***	***0 - 1/8 (0.000 mi.)***	***B48***	***85***
KOONS FORD EPA ID:: MDD054912373	***6970 SECURITY BLVD***	***NNW 0 - 1/8 (0.081 mi.)***	***I78***	***120***
CHADWICK CLEANERS EPA ID:: MDD054913975	***7133 SECURITY BLVD***	***WNW 1/8 - 1/4 (0.197 mi.)***	***N107***	***151***
DBA RITE AID # 2209 EPA ID:: MDR000526131	***7153 SECURITY BLVD***	***WNW 1/8 - 1/4 (0.203 mi.)***	***N111***	***174***

EXECUTIVE SUMMARY

PFAS ECHO: Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

A review of the PFAS ECHO list, as provided by EDR, and dated 03/24/2025 has revealed that there is 1 PFAS ECHO site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
MIL-SPEC PAINTING IN	1720 BELMONT AVE	NE 1/8 - 1/4 (0.205 mi.)	P116	223

UST FINDER: EPA developed UST Finder, a web map application containing a comprehensive, state-sourced national map of underground storage tank (UST) and leaking UST (LUST) data. It provides the attributes and locations of active and closed USTs, UST facilities, and LUST sites from states and from Tribal lands and US territories . UST Finder contains information about proximity of UST facilities and LUST sites to: surface and groundwater public drinking water protection areas; estimated number of private domestic wells and number of people living nearby; and flooding and wildfires.

A review of the UST FINDER list, as provided by EDR, and dated 06/08/2023 has revealed that there are 7 UST FINDER sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
WEIS GAS N' GO #229	7005 SECURITY BLVD.	0 - 1/8 (0.000 mi.)	B49	88
EXXON SERVICE STATIO	***1601 BELMONT AVE***	***N 0 - 1/8 (0.048 mi.)***	***F67***	***107***
KOONS FORD, BALTIMOR	6970 SECURITY BLVD	NNW 0 - 1/8 (0.081 mi.)	I79	125
SECURITY SUNOCO	1900 N. ROLLING ROAD	WNW 0 - 1/8 (0.088 mi.)	G84	127
MERRITT CORPORATION	2066 LORD BALTIMORE	NNW 1/8 - 1/4 (0.134 mi.)	K100	146
SECURITY ANNEX	***1711 BELMONT AVENUE***	***NE 1/8 - 1/4 (0.227 mi.)***	***P119***	***229***
CHADWICK SHELL #517	***7175 SECURITY BOULEV***	***WNW 1/8 - 1/4 (0.230 mi.)***	***N125***	***235***

UST FINDER RELEASE: US EPA's UST Finder data is a national composite of leaking underground storage tanks. This data contains information about, and locations of, leaking underground storage tanks. Data was collected from state sources and standardized into a national profile by EPA's Office of Underground Storage Tanks, Office of Research and Development, and the Association of State and Territorial Solid Waste Management Officials.

A review of the UST FINDER RELEASE list, as provided by EDR, and dated 06/08/2023 has revealed that there are 9 UST FINDER RELEASE sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
KOREAN UNITED CHURCH	1501 N ROLLING RD	SSW 1/4 - 1/2 (0.334 mi.)	T135	245
NEW LIFE PRESBYTERIA	1501 N ROLLING RD	SSW 1/4 - 1/2 (0.334 mi.)	T136	246

Lower Elevation	Address	Direction / Distance	Map ID	Page
EXXON SERVICE STATIO	***1601 BELMONT AVE***	***N 0 - 1/8 (0.048 mi.)***	***F67***	***107***
PJS LLC COMMERCIAL P	2015 LORD BALTIMORE	NNW 0 - 1/8 (0.123 mi.)	K98	145
SECURITY ANNEX	***1711 BELMONT AVENUE***	***NE 1/8 - 1/4 (0.227 mi.)***	***P119***	***229***
CHADWICK SHELL #517	***7175 SECURITY BOULEV***	***WNW 1/8 - 1/4 (0.230 mi.)***	***N125***	***235***
SECURITY BP	***6698 SECURITY BOULEV***	***ENE 1/4 - 1/2 (0.324 mi.)***	***R133***	***242***
BEVERAGE CAPITAL COR	***1620 WHITEHEAD COURT***	***E 1/4 - 1/2 (0.371 mi.)***	***U141***	***249***
FOX CHEVROLET	***6633 SECURITY BLVD.***	***E 1/4 - 1/2 (0.426 mi.)***	***W146***	***252***

E MANIFEST: EPA established a national system for tracking hazardous waste shipments electronically. This system, known as ?e-Manifest,? will modernize the nation?s cradle-to-grave hazardous waste tracking process while saving valuable time, resources, and dollars for industry and states.

A review of the E MANIFEST list, as provided by EDR, and dated 02/17/2025 has revealed that there are 6 E MANIFEST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
WEIS MARKET	7005 SECURITY BLVD	0 - 1/8 (0.000 mi.)	B51	89
KAISER PERMANENTE - DBA RITE AID # 2209	***7141 SECURITY BLVD 7153 SECURITY BLVD***	***WNW 1/8 - 1/4 (0.198 mi.) WNW 1/8 - 1/4 (0.203 mi.)***	***N108 N111***	***156 174***
MIL SPEC PAINTING IN	1720 BELMONT AVE STE	NE 1/8 - 1/4 (0.205 mi.)	P112	189
MIL-SPEC PAINTING IN	***1720 BELMONT AVE***	***NE 1/8 - 1/4 (0.205 mi.)***	***P114***	***199***
MIL SPEC PAINTING IN	1720 1720 BELMONT AV	NE 1/8 - 1/4 (0.205 mi.)	P118	228

MD PFAS: The list includes potential sources of PFAS. This may include different manufacturing facilities, landfills, wastewater treatment plants, electroplating facilities, etc. Sites on this were identified by their NASIC codes as industries that may use or produce PFAS. This list also includes sites known to the Land Restoration.

A review of the MD PFAS list, as provided by EDR, and dated 03/03/2025 has revealed that there is 1 MD PFAS site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
MIL-SPEC PAINTING	1720 BELMONT AVE	NE 1/8 - 1/4 (0.205 mi.)	P115	222

MD DRYCLEANERS: A listing of registered drycleaning facilities.

A review of the MD DRYCLEANERS list, as provided by EDR, and dated 01/02/2025 has revealed that there are 3 MD DRYCLEANERS sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CARE CLEANERS Facility Status: I Facility Id: 005-2451	***7005 SECURITY BOULEV***	***0 - 1/8 (0.000 mi.)***	***B46***	***83***
DIAMOND CLEANERS Facility Status: A Facility Id: 005-2809	1732 NORTH ROLLING R	SW 0 - 1/8 (0.015 mi.)	C58	96
CHADWICK CLEANERS Facility Status: I Facility Id: 005-1078	7133 SECURITY BOULEV	WNW 1/8 - 1/4 (0.195 mi.)	N104	149

MD LRP: A listing of Land Restoration Program sites. Site types included in the database are: Voluntary Cleanup Program, National Priority List, Brownfields, Site Assessment, Formerly Used Defense Site, State Master List, Non Master List, Groundwater Investigation and Federal Facility.

A review of the MD LRP list, as provided by EDR, and dated 12/11/2024 has revealed that there are 5 MD LRP sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SECURITY STATION	1700 TO 1750 NORTH R	WSW 0 - 1/8 (0.044 mi.)	E66	106

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CHADWICK CLEANERS	7137 SECURITY BOULEV	W 1/8 - 1/4 (0.227 mi.)	123	232

Lower Elevation	Address	Direction / Distance	Map ID	Page
SECURITY BOULEVARD S	1718 BELMONT AVENUE	NE 1/8 - 1/4 (0.205 mi.)	P113	198
WESTVIEW PARK NOA SI	1505 NORTH ROLLING R	SSW 1/4 - 1/2 (0.276 mi.)	Q130	240
MEADOWS PARK SHOPPIN	***6606-6658 SECURITY B***	***E 1/4 - 1/2 (0.465 mi.)***	***W150***	***256***

MD MANIFEST: Hazardous waste manifest information for the state of Maryland. Maryland regulations require the generator to submit a copy of the manifest to the Maryland Department of the Environment.

A review of the MD MANIFEST list, as provided by EDR, and dated 06/30/2018 has revealed that there are 4 MD MANIFEST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
DIAMOND CLEANERS	1732 N. ROLLING ROAD	SW 0 - 1/8 (0.015 mi.)	C57	94
NATIONAL COATINGS &	2040-R LORD BALTIMOR	NNW 0 - 1/8 (0.094 mi.)	K89	132
RITE AID #02209	7153 SECURITY BLVD	WNW 1/8 - 1/4 (0.203 mi.)	N109	168
MIL SPEC PAINTING IN	1720 BELMONT AVE STE	NE 1/8 - 1/4 (0.205 mi.)	P117	225

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2018 has revealed that there are 2 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
NATIONAL COATINGS - EPA Id: MDR000523045	***2040-R LORD BALTIMOR***	***NNW 0 - 1/8 (0.094 mi.)***	***K90***	***132***
MIL-SPEC PAINTING IN EPA Id: MDR000006262	***1720 BELMONT AVE***	***NE 1/8 - 1/4 (0.205 mi.)***	***P114***	***199***

RI MANIFEST: Hazardous waste manifest information

A review of the RI MANIFEST list, as provided by EDR, and dated 12/31/2020 has revealed that there is 1 RI MANIFEST site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
DIAMOND CLEANERS EPA Id: MDR000005900 Manifest Document Number: 010013607JJK	***1732 N ROLLING RD***	***SW 0 - 1/8 (0.015 mi.)***	***C60***	***97***

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, and dated 06/30/2018 has revealed that there are 2 PA MANIFEST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
MACYS INC Generator EPA Id: MDP000016969	6975 SECURITY BLVD	0 - 1/8 (0.000 mi.)	B53	92
RITE AID # 2209 Generator EPA Id: MDR000526131	7153 SECURITY BOULEV	WNW 1/8 - 1/4 (0.203 mi.)	N110	171

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 4 EDR Hist Auto sites within approximately 0.125 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
SECURITY SQUARE MALL	1601 BELMONT AVE	N 0 - 1/8 (0.048 mi.)	F69	114
LSR MOTOR FUELS INC	1604 BELMONT AVE	N 0 - 1/8 (0.055 mi.)	F73	116
FJ SONS ENTERPRISES	1900 N ROLLING RD	WNW 0 - 1/8 (0.088 mi.)	G83	127
GRACE GAS AND TRANSP	7000 SECURITY BLVD	NW 0 - 1/8 (0.091 mi.)	88	131

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there are 2 EDR Hist Cleaner sites within approximately 0.125 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CARE CLEANERS	7005 SECURITY BLVD	0 - 1/8 (0.000 mi.)	B50	89
DIAMOND CLEANERS INC	1732 N ROLLING RD	SW 0 - 1/8 (0.015 mi.)	C59	96

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 12 records.

Site Name	Database(s)
DOGWOOD CLEANERS	US AIRS, MD DRYCLEANERS
ROLLING ROAD CLEANERS	MD DRYCLEANERS
C & P C & P TELEPHONE / WOODLAWN C	MD OCPCASES
C & P COIN CENTER	MD OCPCASES
C&P TELEPHONE COIN CENTER	MD OCPCASES
VERIZON COIN CENTER	MD OCPCASES
MONTGOMERY WARD	MD OCPCASES
BG&E/CNR	MD OCPCASES
PATTERSON RESIDENCE	MD OCPCASES
HELLMAN RESIDENCE	MD OCPCASES
RECON-WAGMAN	MD OCPCASES
BG&E MEADOWS SUBSTATION	MD OCPCASES

OVERVIEW MAP - 8056060.2S



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

National Priority List Sites

Dept. Defense Sites

0 1/4 1/2 1 Miles

Indian Reservations BIA

Power transmission lines

Pipelines

Special Flood Hazard Area (1%)

0.2% Annual Chance Flood Hazard

National Wetland Inventory

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Security Square Mall	CLIENT:	EA Engineering Science & Tech.
ADDRESS:	6901 Security Boulevard Windsor Mill MD 21244	CONTACT:	Mitchell Richards
		INQUIRY #:	8056060.2s
LAT/LONG:	39.310654 / 76.750229	DATE:	July 24, 2025 2:46 pm

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 8056060.2S



0 1/8 1/4 1/2 Miles

- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- Pipelines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Security Square Mall	CLIENT:	EA Engineering Science & Tech.
ADDRESS:	6901 Security Boulevard Windsor Mill MD 21244	CONTACT:	Mitchell Richards
LAT/LONG:	39.310654 / 76.750229	INQUIRY #:	8056060.2s
		DATE:	July 24, 2025 2:50 pm

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Lists of Federal NPL (Superfund) sites								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Lists of Federal Delisted NPL sites								
Delisted NPL	1.000		0	0	0	0	NR	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Lists of Federal CERCLA sites with NFRAP								
SEMS-ARCHIVE	0.500		0	1	1	NR	NR	2
Lists of Federal RCRA facilities undergoing Corrective Action								
CORRACTS	1.000		0	0	0	0	NR	0
Lists of Federal RCRA TSD facilities								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA generators								
RCRA-LQG	0.250		1	0	NR	NR	NR	1
RCRA-SQG	0.250	1	0	2	NR	NR	NR	3
RCRA-VSQG	0.250	2	2	0	NR	NR	NR	4
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	TP	1	NR	NR	NR	NR	NR	1
Lists of state- and tribal hazardous waste facilities								
MD SHWS	1.000		0	1	0	0	NR	1
Lists of state and tribal landfills and solid waste disposal facilities								
MD SWF/LF	0.500		0	0	0	NR	NR	0
Lists of state and tribal leaking storage tanks								
INDIAN LUST	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
MD OCPCASES	0.500	7	24	8	16	NR	NR	55
MD HIST LUST	0.500		0	0	1	NR	NR	1
Lists of state and tribal registered storage tanks								
FEMA UST	0.250		0	0	NR	NR	NR	0
MD UST	0.250	5	4	2	NR	NR	NR	11
MD AST	0.250		0	0	NR	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
MD ENG CONTROLS	0.500		0	0	0	NR	NR	0
MD INST CONTROL	0.500		1	0	1	NR	NR	2
Lists of state and tribal voluntary cleanup sites								
MD VCP	0.500		0	0	1	NR	NR	1
INDIAN VCP	0.500		0	0	0	NR	NR	0
Lists of state and tribal brownfield sites								
MD BROWNFIELDS	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
MD SWRCY	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
US CDL	TP		NR	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
MD HIST UST	0.250	4	3	0	NR	NR	NR	7
Local Land Records								
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
MD SPILLS 90	TP		NR	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250	1	2	2	NR	NR	NR	5

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP	5	NR	NR	NR	NR	NR	5
US MINES	0.250		0	0	NR	NR	NR	0
MINES MRDS	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	TP	8	NR	NR	NR	NR	NR	8
DOCKET HWC	TP		NR	NR	NR	NR	NR	0
ECHO	TP	7	NR	NR	NR	NR	NR	7
UXO	1.000		0	0	0	0	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
PFAS NPL	0.250		0	0	NR	NR	NR	0
PFAS FEDERAL SITES	0.250		0	0	NR	NR	NR	0
PFAS TRIS	0.250		0	0	NR	NR	NR	0
PFAS TSCA	0.250		0	0	NR	NR	NR	0
PFAS RCRA MANIFEST	0.250		0	0	NR	NR	NR	0
PFAS ATSDR	0.250		0	0	NR	NR	NR	0
PFAS WQP	0.250		0	0	NR	NR	NR	0
PFAS PROJECT	0.250		0	0	NR	NR	NR	0
PFAS NPDES	0.250		0	0	NR	NR	NR	0
PFAS ECHO	0.250		0	1	NR	NR	NR	1
PFAS ECHO FIRE TRAIN	0.250		0	0	NR	NR	NR	0
PFAS PT 139 AIRPORT	0.250		0	0	NR	NR	NR	0
AQUEOUS FOAM NRC	0.250		0	0	NR	NR	NR	0
BIOSOLIDS	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
UST FINDER	0.250	3	4	3	NR	NR	NR	10
UST FINDER RELEASE	0.500		2	2	5	NR	NR	9
E MANIFEST	0.250	6	1	5	NR	NR	NR	12
MD PFAS	0.250		0	1	NR	NR	NR	1
MD AIRS	TP		NR	NR	NR	NR	NR	0
MD ASBESTOS	TP	3	NR	NR	NR	NR	NR	3
MD COAL ASH	0.500		0	0	0	NR	NR	0
MD DRYCLEANERS	0.250		2	1	NR	NR	NR	3
MD Financial Assurance	TP	5	NR	NR	NR	NR	NR	5
MD LEAD	TP		NR	NR	NR	NR	NR	0
MD LRP	0.500		1	2	2	NR	NR	5
MD MANIFEST	0.250	3	2	2	NR	NR	NR	7
NJ MANIFEST	0.250		1	1	NR	NR	NR	2
RI MANIFEST	0.250		1	0	NR	NR	NR	1
PA MANIFEST	0.250	1	1	1	NR	NR	NR	3
MD NPDES	TP		NR	NR	NR	NR	NR	0
MD UIC	TP		NR	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	0	0	NR	0
EDR Hist Auto	0.125		4	NR	NR	NR	NR	4
EDR Hist Cleaner	0.125	1	2	NR	NR	NR	NR	3
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
MD RGA HWS	TP		NR	NR	NR	NR	NR	0
MD RGA LF	TP		NR	NR	NR	NR	NR	0
MD RGA LUST	TP		NR	NR	NR	NR	NR	0
- Totals --		63	58	35	27	0	0	183

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1 **SEARS STORE #1634** **RCRA-SQG** **1001214375**
Target **6901 SECURITY BLVD** **E MANIFEST** **MDR000015511**
Property **WINDSOR MILL, MD 21244**

Site 1 of 45 in cluster A

Actual: 459 ft.

RCRA Listings:

Date Form Received by Agency:	20180730
Handler Name:	Sears Store #1634
Handler Address:	6901 Security Blvd
Handler City,State,Zip:	WINDSOR MILL, MD 21244
EPA ID:	MDR000015511
Contact Name:	JAMES TUNNEY
Contact Address:	3333 BEVERLY RD, B5-348A
Contact City,State,Zip:	HOFFMAN ESTATES, IL 60179
Contact Telephone:	845-286-3667
Contact Fax:	Not reported
Contact Email:	JAMES.TUNNEY@SEARSHC.COM
Contact Title:	MANAGER
EPA Region:	03
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	3333 BEVERLY RD, B5-348A
Mailing City,State,Zip:	HOFFMAN ESTATES, IL 60179
Owner Name:	Sears Roebuck And Company
Owner Type:	Private
Operator Name:	Ann Manherz
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

SEARS STORE #1634 (Continued) **1001214375**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20190222
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D009
Waste Description:	Mercury

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: ANN MANHERZ	
Legal Status:	Private
Date Became Current:	20171201
Date Ended Current:	Not reported
Owner/Operator Address:	6901 SECURITY SQUARE BLVD
Owner/Operator City,State,Zip:	BALTIMORE, MD 21244
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: SEARS ROEBUCK AND CO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3333 BEVERLY RD
Owner/Operator City,State,Zip:	HOFFMAN ESTATES, IL 60179
Owner/Operator Telephone:	847-286-2500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: SEARS ROEBUCK AND COMPANY	
Legal Status:	Private
Date Became Current:	19730207

SEARS STORE #1634 (Continued) **1001214375**

Date Ended Current:	Not reported
Owner/Operator Address:	3333 BEVERLY RD, B5-348A
Owner/Operator City,State,Zip:	HOFFMAN ESTATES, IL 60179
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19971024
Handler Name: SEARS 1634	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20180730
Handler Name: SEARS STORE #1634	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	452210
NAICS Description:	Department Stores

Has the Facility Received Notices of Violations:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported

SEARS STORE #1634 (Continued) **1001214375**

Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20230713
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	PSA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

E MANIFEST:

Manifest Tracking Number:	025755049JJK
Last Updated Date:	20230717
Shipped Date:	20230622
Received Date:	20230710
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDR000015511
Generator Name:	Crash Champions
Generator Location Street Number:	Not reported
Generator Location Street 1:	6901 SECURITY BLVD #200
Generator Location Street 2:	Not reported
Generator Location City:	WINDSOR MILL
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	6901 SECURITY BLVD #200
Generator Mail Street 2:	Not reported

SEARS STORE #1634 (Continued) **1001214375**

Generator Mail City:	WINDSOR MILL
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	ALD070513767
Designated Facility Name:	Giant Resource Recovery- Attalla, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1229 VALLEY DRIVE
Designated Facility Mail City:	ATTALLA
Designated Facility Mail Zip:	35954
Designated Facility Mail State:	AL
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	1229 VALLEY DRIVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ATTALLA
Designated Facility Location Zip:	35954
Designated Facility Location State:	AL
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	025755049JJK
Transporter Line Number:	1
Transporter EPA ID:	GAR000061564
Transporter Name:	Mcf Environmental Services

Manifest Tracking Number:	025755049JJK
Transporter Line Number:	2
Transporter EPA ID:	GAR000061564
Transporter Name:	Mcf Environmental Services

Waste Line:

Manifest Tracking Number:	025755049JJK
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN1263
U.S. DOT Description:	Un1263, Waste Paint Related Material, 3, Pgii
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	55
Quantity Unit of Measure Code:	G
Quantity Unit of Measure Description:	Gallons
Waste Quantity, in Tons:	0.2293578
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.2293578
Waste Quantity, in Kilograms:	208.03441
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	208.03441
Management Method Code:	H061
Management Method Description:	FUEL BLENDING
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N

SEARS STORE #1634 (Continued) **1001214375**

Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D001, F003, F005
Quantity Haz Kg:	208.03441
Quantity Haz Tons:	0.2293578
Quantity Non Haz Kg:	Not reported
Quantity Non Haz Tons:	Not reported
State Waste Codes:	Not reported

A2 Target Property **GRAND AUTO BODY & CARE**
6901 SECURITY BLVD
BALTIMORE), MD 21244

FINDS **1018325249**
ECHO **N/A**

Site 2 of 45 in cluster A

Actual: 459 ft.

FINDS:
Registry ID: 110022379399

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Maryland's Resource Conservation and Recovery Act (RCRA) database houses data related to hazardous waste.
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018325249
Registry ID:	110022379399

DFR URL:

Name:	GRAND AUTO BODY & CARE
Address:	6901 Security Blvd
City,State,Zip:	BALTIMORE), MD 21244

A3
Target
Property

BULL ON THE BEACH
6901 SECURITY BOULEVARD
WOODLAWN, MD 21207

US AIRS
FINDS
ECHO

1004521309
N/A

Site 3 of 45 in cluster A

Actual:
459 ft.

US AIRS MINOR:

Envid:	1004521309
Region Code:	03
Programmatic ID:	AIR MD0000002400501978
Facility Registry ID:	110001778791
D and B Number:	Not reported
Primary SIC Code:	5812
NAICS Code:	722211
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

FINDS:

Registry ID: 110001778791

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.
The Maryland Permanent Emission (MD-PEMIS) database houses data related to air emissions.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004521309
Registry ID:	110001778791

DFR URL:

Name:	BULL ON THE BEACH
Address:	6901 Security Boulevard
City,State,Zip:	WOODLAWN, MD 21207

A4
Target
Property

J C PENNEY CO
6901 SECURITY BLVD
WINDSOR MILL, MD 21244

MD OCPCASES

S121712783
N/A

Site 4 of 45 in cluster A

Actual:
459 ft.

OCPCASES:

Name:	J C PENNEY CO
Address:	6901 SECURITY BLVD
City,State,Zip:	WINDSOR MILL, MD 21244
Facility ID:	93-2242BA2
Facility Status/Code:	CLOSED/

J C PENNEY CO (Continued) **S121712783**

Date Open: 04/22/1993
Date Closed: Not reported
Release: Not reported
Cleanup: Not reported
Registration Number: 16393

A5 Target Property **BOB'S BIG BOY** **FINDS 1004522945**
6901 SECURITY BLVD **ECHO N/A**
BALTIMORE, MD 21207

Site 5 of 45 in cluster A

Actual: 459 ft.

FINDS:
Registry ID: 110002339880

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004522945
Registry ID: 110002339880

DFR URL:
Name: BOB'S BIG BOY
Address: 6901 Security Blvd
City,State,Zip: BALTIMORE, MD 21207

A6 Target Property **BRIDGESTONE/FIRESTONE** **UST FINDER 1028411858**
6901 SECURITY BLVD. **N/A**
BALTIMORE, MD 21244

Site 6 of 45 in cluster A

Actual: 459 ft.

UST FINDER:
Object ID: 638189
Facility ID: MD5743
Name: BRIDGESTONE/FIRESTONE
Address: 6901 SECURITY BLVD.
City,State,Zip: BALTIMORE, MD 21244
Address Match Type: PointAddress
Open USTs: 0
Closed USTs: 2
TOS USTs: 0
Population 1500ft: 253
Private Wells 1500ft: 2

BRIDGESTONE/FIRESTONE (Continued) **1028411858**

Within 100yr Floodplain:	No
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	3
Tribe:	Not reported
Coordinate Source:	Geocode
X Coord:	-76.75049444
Y Coord:	39.3128395200001
Latitude:	39.31283952
Longitude:	-76.75049444

UST FINDER:

Object ID:	688691
Facility ID:	MD5743
Tank ID:	MD5743_1
Tank Status:	Closed
Installation Date:	1995/01/01 15:59:59+00
Removal Date:	2015/08/12 15:59:59+00
Tank Capacity:	6000
Substances:	Heating Oil
Tank Wall Type:	Single

Object ID:	712755
Facility ID:	MD5743
Tank ID:	MD5743_2
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	1994/02/15 15:59:59+00
Tank Capacity:	550
Substances:	Used Oil
Tank Wall Type:	Single

A7 **SECURITY WARDS LLC** **MD MANIFEST** **S121869905**
Target **6901 SECURITY BLVD** **N/A**
Property **BALTIMORE, MD 21244**

Site 7 of 45 in cluster A

Actual:
459 ft.

MD MANIFEST:

EPAID:	MDD985408335
Name:	SECURITY WARDS LLC
Address:	6901 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244
Manifest Number:	010128182JJK
Transporter 1:	CLEAN VENTURE, INC
Transporter 2:	Not reported

SECURITY WARDS LLC (Continued) **S121869905**

Generator Certifier: DIANNA MAERERS
Date Shipped Out: 10/28/2015
Destination Facility Certifier: DAVE S
Date Arrived at Destingation Facility: 10/29/2015
Quantity: 7800
Unit: K

EPAID: MDD985408335
Name: SECURITY WARDS LLC
Address: 6901 SECURITY BLVD
City,State,Zip: BALTIMORE, MD 21244
Manifest Number: 010128186JJK
Transporter 1: FREEHOLD CARTAGE, INC
Transporter 2: Not reported
Generator Certifier: DAVID E KEENE
Date Shipped Out: 10/28/2015
Destination Facility Certifier: CHARLES DEWITT
Date Arrived at Destingation Facility: 10/29/2015
Quantity: 18688
Unit: K

EPAID: MDD985408335
Name: SECURITY WARDS LLC
Address: 6901 SECURITY BLVD
City,State,Zip: BALTIMORE, MD 21244
Manifest Number: 013338211JJK
Transporter 1: CLEAN VENTURE INC
Transporter 2: Not reported
Generator Certifier: DIANNA MAERERS
Date Shipped Out: 05/18/2015
Destination Facility Certifier: DAN SHELTON
Date Arrived at Destingation Facility: 05/20/2015
Quantity: 11736
Unit: KILOGRAMS

A8 **MICHAELS TAILOR & DRY CLEANING** **EDR Hist Cleaner** **1018568442**
Target Property **6901 SECURITY BLVD** **N/A**
BALTIMORE, MD 21244

Site 8 of 45 in cluster A

Actual: 459 ft.

EDR Hist Cleaner

Year:	Name:	Type:
1992	ROBINSON & LEWIS COMPANY INC	Drycleaning Plants, Except Rugs, NEC

A9 **SS SELF STORAGE LLC** **MD UST** **U004373351**
Target Property **6901 SECURITY BLVD** **MD Financial Assurance** **N/A**
WINDSOR MILL, MD 21244

Site 9 of 45 in cluster A

Actual: 459 ft.

UST:
Facility Id: 21208
Oper Name: Not reported
Form Name: Dave Thompson

SS SELF STORAGE LLC (Continued) **U004373351**

Form Title: Owner's Rep
Form Date: 03/09/2023
Owner Id: 15802

Owner:
Owner Name: SS Self Storage LLC
Owner Address: 1340 Smith Ave Suite 200
Owner City: Baltimore
Owner State: MD
Owner Zip: 21209
Owner Phone: (443) 838-7277
Owner Contact: Peter Garver

Tanks:
Tank ID: 1
Tank Status: Permanently Out Of Use
Tank Capacity: Not reported
Substance Description: Used Oil
Tank Compartment: False
Compartment Compartment: A
Date Installed: Not reported
Tank Material Desc: Fiberglass Reinforced Plastic
Pipe Material Desc: Fiberglass Reinforced Plastic

MD Financial Assurance 2:
Name: SS SELF STORAGE LLC
Address: 6901 SECURITY BLVD
City,State,Zip: WINDSOR MILL, MD 21244
Region: 2
Facility ID: 21208
Self Insured: False
Insurance: False
Risk Retention Group: False
Guarantee: False
Surety Bonds: False
Letter of Credit: False
State Fund: False
Other Finance: False
Finacnce Comments: Not reported
FR Not Listed: False

A10
Target Property

TANNER ENTERPRISES
6901 SECURITY BLVD.
BALTIMORE, MD 21244

FINDS **1007827754**
N/A

Site 10 of 45 in cluster A

Actual: 459 ft.

FINDS:
Registry ID: 110019905389

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Maryland Department of the Environment (MDE) Environmental Permits Service Center (MD-EPSC) promotes multi-media pollution prevention and provides permit assistance to business and industries.

TANNER ENTERPRISES (Continued) **1007827754**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

A11 **MACYS SECURITY SQUARE** **ECHO** **1031817108**
Target **6901 SECURITY BLVD** **N/A**
Property **WINDSOR MILL, MD 21244**

Site 11 of 45 in cluster A

Actual: **459 ft.**

ECHO:
Envid: 1031817108
Registry ID: Not reported

DFR URL:
Name: MACYS SECURITY SQUARE
Address: 6901 Security Blvd
City,State,Zip: WINDSOR MILL, MD 21244

A12 **SEARS STORE #1634** **US AIRS** **1008383096**
Target **6901 SECURITY BLVD.** **FINDS** **N/A**
Property **BALTIMORE, MD 21207**

Site 12 of 45 in cluster A

Actual: **459 ft.**

US AIRS MINOR:
Envid: 1008383096
Region Code: 03
Programmatic ID: AIR MD0000002400500910
Facility Registry ID: 110022380644
D and B Number: Not reported
Primary SIC Code: 5311
NAICS Code: 452990
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 03
Programmatic ID: AIR MD0000002400500910
Facility Registry ID: 110022380644
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1989-05-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

FINDS:
Registry ID: 110022380644

Click Here for FRS Facility Detail Report:

SEARS STORE #1634 (Continued) **1008383096**

Environmental Interest/Information System:
Maryland's Resource Conservation and Recovery Act (RCRA) database houses data related to hazardous waste.
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

A13 **J.C. PENNEY CO. INC.** **US AIRS** **1004520807**
Target **6901 SECURITY BLVD** **N/A**
Property **CATONSVILLE, MD 21207**

Site 13 of 45 in cluster A

Actual:
459 ft.

US AIRS MINOR:

Envid:	1004520807
Region Code:	03
Programmatic ID:	AIR MD0000002400501871
Facility Registry ID:	110002339880
D and B Number:	Not reported
Primary SIC Code:	5812
NAICS Code:	722211
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	03
Programmatic ID:	AIR MD0000002400501871
Facility Registry ID:	110002339880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1989-01-27 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	03
Programmatic ID:	AIR MD0000002400501871
Facility Registry ID:	110002339880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

J.C. PENNEY CO. INC. (Continued) **1004520807**

Activity Date: 1992-10-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Envid: 1004520807
Region Code: 03
Programmatic ID: AIR MD0000002400501169
Facility Registry ID: 110002021035
D and B Number: Not reported
Primary SIC Code: 5311
NAICS Code: 452111
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 03
Programmatic ID: AIR MD0000002400501169
Facility Registry ID: 110002021035
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1988-12-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR MD0000002400501169
Facility Registry ID: 110002021035
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1989-07-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

A14 **CRASH CHAMPIONS - WINDSOR MILL 211** **US AIRS** **1000222667**
Target **6901 SECURITY BLVD** **FINDS** **N/A**
Property **BALTIMORE, MD 21207** **ECHO**

Site 14 of 45 in cluster A

Actual: 459 ft.

US AIRS MINOR:
Envid: 1000222667
Region Code: 03
Programmatic ID: AIR MD0000002400501629
Facility Registry ID: 110001261438
D and B Number: Not reported
Primary SIC Code: 5531

CRASH CHAMPIONS - WINDSOR MILL 211 (Continued) **1000222667**

NAICS Code: 811121
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

FINDS:
Registry ID: 110003532730

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.
Registry ID: 110001261438

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000222667
Registry ID: 110003532730

DFR URL:
Name: MONTGOMERY WARD CO
Address: 6901 Security Square
City,State,Zip: BALTIMORE, MD 21207

Envid: 1000222667
Registry ID: 110001261438

DFR URL:
Name: CRASH CHAMPIONS - WINDSOR MILL 211
Address: 6901 Security Blvd
City,State,Zip: BALTIMORE, MD 21207

A15 **ERNS** **2015134542**
Target Property **6901 SECURITY BLVD** **N/A**
WINDSOR MILL, MD

Site 15 of 45 in cluster A

Actual: 459 ft.

Incident Commons:

NRC Report #:	1134542
Description of Incident:	CALLER STATED THAT INDIVIDUALS WORKING AT THE BUSINESS HAS BEEN WITNESSED DUMPING ANTI-FREEZE DOWN BATHROOM SINKS.
Type of Incident:	FIXED
Incident Cause:	DUMPING
Incident Date Time:	2015-11-25 12:00:00
Incident DTG:	DISCOVERED
Incident Location:	Not reported
Loaction Address:	6901 SECURITY BLVD
Location Street 1:	Not reported
Location Street 2:	Not reported
Location Nearest City:	WINDSOR MILL
Location State:	MD
Location County:	BALTIMORE
Location Zip:	Not reported
Distance From City:	Not reported
Distance Units:	Not reported
Direction From City:	Not reported
Lat Deg:	Not reported
Lat Min:	Not reported
Lat Sec:	Not reported
Lat Quad:	Not reported
Long Deg:	Not reported
Long Min:	Not reported
Long Sec:	Not reported
Long Quad:	Not reported
Location Section:	Not reported
Location Township:	Not reported
Location range:	Not reported
Potential Range:	N

Incidents:

Year:	2015
NRC Report #:	1134542
Aircraft Type:	Not reported
Aircraft Model:	Not reported
Aircraft ID:	Not reported
Aircraft Fuel Capacity:	Not reported
Aircraft Fuel Capacity Units:	Not reported
Aircraft Fuel on Board:	Not reported
Aircraft Fuel on Board Units:	Not reported
Aircraft Spot Number:	Not reported
Aircraft Hanger:	Not reported
Aircraft Runway Number:	Not reported
Road Mile Marker:	Not reported
Building ID:	Not reported
Type of Fixed Object:	OTHER
Power Generating Facility:	U
Generating Capacity:	Not reported
Type of Fuel:	Not reported
NPDES:	Not reported
NPDES Compliance:	U
Pipeline Type:	Not reported

(Continued) **2015134542**

DOT Regulated:	U
Pipeline Above Ground:	ABOVE
Exposed Underwater:	N
Pipeline Covered:	U
Railroad Hotline:	Not reported
Grade Crossing:	U
Location Subdivision:	Not reported
Railroad Milepost:	Not reported
Type Vehicle Involved:	Not reported
Crossing Device Type:	Not reported
Device Operational:	U
DOT Crossing Number:	Not reported
Brake Failure:	U
Description of Tank:	Not reported
Tank Above Ground:	ABOVE
Transportable Container:	U
Tank Regulated:	U
Tank Regulated By:	Not reported
Tank ID:	Not reported
Capacity of Tank:	Not reported
Capacity of Tank Units:	Not reported
Actual Amount:	Not reported
Actual Amount Units:	Not reported
Platform Rig Name:	Not reported
Platform Letter:	Not reported
Location Area ID:	Not reported
Location Block ID:	Not reported
OCSG Number:	Not reported
OCSP Number:	Not reported
State Lease Number:	Not reported
Pier Dock Number:	Not reported
Berth Slip Number:	Not reported
Continuous Release Type:	Not reported
Initial Continuous Release No:	Not reported
Continuous Release Permit:	Not reported
Allision:	U
Type of Structure:	Not reported
Structure Name:	Not reported
Structure Operational:	U
Airbag Deployed:	U
Date Tiem Normal Service:	Not reported
Service Disruption Time:	Not reported
Service Disruption Units:	Not reported
Transit Bus Flag:	Not reported
CR Begin Date:	Not reported
CR End Date:	Not reported
CR Change Date:	Not reported
FBI Contact:	Not reported
FBI Contact Date Time:	Not reported
Sub Part C Testing Req:	XXX
Conductor Testing:	Not reported
Engineer Testing:	Not reported
Trainman Testing:	Not reported
Yard Foreman Testing:	Not reported
RCL Operator Testing:	Not reported
Brakeman Testing:	Not reported
Train Dispatcher Testing:	Not reported

(Continued) **2015134542**

Signalman Testing:	Not reported
Other Employee Testing:	Not reported
Unknown Testing:	Not reported
Passenger Handling:	Not reported
Passenger Route:	XXX
Passenger Delay:	XXX

Incident Details:

Year:	2015
NRC Report #:	1134542
Fire Involved:	N
Fire Extinguished:	U
Any Evacuations:	N
Number Evacuated:	Not reported
Who Evacuated:	Not reported
Radius of Evacuation:	Not reported
Any Injuries:	N
Number Injured:	Not reported
Number Hospitalized:	Not reported
Any Fatalities:	N
Number Fatalities:	Not reported
Any Damages:	N
Damage Amount:	Not reported
Air Corridor Closed:	N
Air Corridor Desc:	Not reported
Air Closure Time:	Not reported
Waterway Closed:	N
Waterway Desc:	Not reported
Waterway Closure Time:	Not reported
Road Closed:	N
Road Desc:	Not reported
Road Closure Time:	Not reported
Closure Direction:	Not reported
Major Artery:	N
Track Closed:	N
Track Desc:	Not reported
Track Closure Time:	Not reported
Media Interest:	UNKNOWN
Medium Desc:	WATER
Additional Medium Info:	SINK
Body of Water:	SINK
Tributary of:	SEWER SYSTEM
Release Secured:	U
Estimated Duration of Release:	Not reported
Release rate:	Not reported
Desc Remedial Action:	NONE
State Agency on Scene:	Not reported
State Agency Report Number:	Not reported
Other Agency Notified:	Not reported
Weather Conditions:	UNKNOWN
Air Temperature:	Not reported
Wind Speed:	Not reported
Wind Direction:	Not reported
Water Supply Contaminated:	U
Sheen Size:	Not reported
Sheen Color:	Not reported
Direction of Sheen Travel:	Not reported

(Continued) **2015134542**

Sheen Odor Description:	Not reported
Wave Condition:	Not reported
Current Speed:	Not reported
Current Direction:	Not reported
Water Temperature:	Not reported
Track Close Dir:	Not reported
Empl Fatality:	Not reported
Pass Fatality:	Not reported
Community Impact:	Not reported
Wind Speed Unit:	Not reported
Employee Injuries:	Not reported
Passenger Injuries:	Not reported
Occupant Fatality:	Not reported
Current Speed Unit:	Not reported
Road Closure Units:	Not reported
Track CLosure Units:	Not reported
Sheen Size Units:	Not reported
Additional Info:	Not reported
State Agency Notified:	Not reported
Federal Agency Notified:	Not reported
nearest River Mile Marker:	Not reported
Sheen Size Length:	Not reported
Sheen Size Length Units:	Not reported
Sheen Size Width:	Not reported
Sheen Size Width Units:	Not reported
Offshore:	N
Duration Unit:	Not reported
Release Rate Unit:	Not reported
Release Rate Rate:	Not reported
Passengers Transferred:	NO

Calls:

Year:	2015
NRC Report #:	1134542
Site ID:	20151134542
Date Time Received:	2015-11-30 10:32:53
Date Time Complete:	2015-11-30 10:36:29
Call Type:	INC
Responsible Company:	NORTH AMERICA TRADE SCHOOLS
Responsible Org Type:	UNKNOWN
Responsible City:	WINDSOR MILL
Responsible State:	MD
Responsible Zip:	Not reported
On Behalf:	Not reported
Source:	TELEPHONE

Material Involved:

Year:	2015
NRC Report #:	1134542
Chris Code:	EGL
Case Number:	000107-21-1
UN Number:	Not reported
Amount of Material:	0
Unit of Measure:	UNKNOWN AMOUNT
Name of Material:	ETHYLENE GLYCOL
If Reached Water:	YES

(Continued) **2015134542**

Amount in Water: 0
Unit of Measure Reach Water: UNKNOWN AMOUNT

A16 **MACY'S STORE #159** **MD MANIFEST** **S121871513**
Target **6901 SECURITY BLVD** **N/A**
Property **BALTIMORE, MD 21244**

Site 16 of 45 in cluster A

Actual: **459 ft.**

MD MANIFEST:

EPAID:	MDR000516369
Name:	MACY'S STORE #159
Address:	6901 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244
Manifest Number:	008783634FLE
Transporter 1:	CLEAN HARBORS ENVIRONMENTAL SERVICES, INC.
Transporter 2:	SJ TRANSPORTATION CO., INC.
Generator Certifier:	PATRICIA ROLAND
Date Shipped Out:	07/21/2015
Destination Facility Certifier:	LINDA GOODWIN
Date Arrived at Destingation Facility:	07/15/2015
Quantity:	150
Unit:	POUNDS

EPAID:	MDR000516369
Name:	MACY'S STORE #159
Address:	6901 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244
Manifest Number:	008845409FLE
Transporter 1:	CLEAN HARBORS ENVIRONMENTAL SERVICES INC
Transporter 2:	S J TRANSPORATION CO INC
Generator Certifier:	TERREL MORCLAUNT
Date Shipped Out:	04/24/2015
Destination Facility Certifier:	LINDA GOODWIN
Date Arrived at Destingation Facility:	05/19/2015
Quantity:	180
Unit:	POUNDS

EPAID:	MDR000516369
Name:	MACY'S STORE #159
Address:	6901 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244
Manifest Number:	009065479FLE
Transporter 1:	CLEAN HARBORS ENV SERVICE, INC.
Transporter 2:	Not reported
Generator Certifier:	ANGELA DEVAUX
Date Shipped Out:	04/01/2016
Destination Facility Certifier:	DANA TUCKER
Date Arrived at Destingation Facility:	04/13/2016
Quantity:	200
Unit:	Pounds

EPAID:	MDR000516369
Name:	MACY'S STORE #159
Address:	6901 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244
Manifest Number:	009044266FLE

MACY'S STORE #159 (Continued) **S121871513**

Transporter 1:	CLEAN HARBORS ENVIRONMENTAL SERV, INC
Transporter 2:	Not reported
Generator Certifier:	LILITH SODEN
Date Shipped Out:	02/12/2016
Destination Facility Certifier:	CHARLEEKA THOMPSON
Date Arrived at Destingation Facility:	02/23/2016
Quantity:	200
Unit:	Pounds

EPAID:	MDR000516369
Name:	MACY'S STORE #159
Address:	6901 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244
Manifest Number:	008578844FLE
Transporter 1:	REPUBLIC ENVIRONMENTAL SYS (TRANS GROUP)
Transporter 2:	Not reported
Generator Certifier:	DENISE LUCAS
Date Shipped Out:	09/01/2016
Destination Facility Certifier:	JEAN SAALMAN
Date Arrived at Destingation Facility:	09/13/2016
Quantity:	133
Unit:	Pounds

EPAID:	MDR000516369
Name:	MACY'S STORE #159
Address:	6901 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244
Manifest Number:	008498817FLE
Transporter 1:	REPUBLIC ENV SYS (TRANS GP)
Transporter 2:	Not reported
Generator Certifier:	ANGELA DEVAUX
Date Shipped Out:	12/29/2016
Destination Facility Certifier:	JEAN SAALMAN
Date Arrived at Destingation Facility:	01/06/2017
Quantity:	23
Unit:	Pounds

EPAID:	MDR000516369
Name:	MACY'S STORE #159
Address:	6901 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244
Manifest Number:	009624880FLE
Transporter 1:	CLEAN HARBORS ENVIRONMENTAL SVC, INC
Transporter 2:	SJ TRANSPORTATION CO., INC.
Generator Certifier:	LOGAN SMITH
Date Shipped Out:	05/27/2016
Destination Facility Certifier:	LINDA GOODWIN
Date Arrived at Destingation Facility:	06/27/2016
Quantity:	200
Unit:	Pounds

A17 **SEARS, ROEBUCK AND CO. INC.** **MD UST** **U004445601**
Target **6901 SECURITY BLVD.** **MD Financial Assurance** **N/A**
Property **BALTIMORE, MD 21244**

Site 17 of 45 in cluster A

Actual:
459 ft.

UST:

Facility Id:	14022
Oper Name:	John V. Long
Form Name:	John V. Long
Form Title:	Loss Prevention Manager
Form Date:	06/05/1995
Owner Id:	8945

Owner:

Owner Name:	Sears,Roebuck And Co., Inc.
Owner Address:	6901 Security Blvd.
Owner City:	Baltimore
Owner State:	MD
Owner Zip:	21244
Owner Phone:	(410) 281-2255
Owner Contact:	John V. Long

Tanks:

Tank ID:	1
Tank Status:	**Permanently Out of Use**
Tank Capacity:	550
Substance Description:	Used Oil
Tank Compartment:	False
Compartment Compartment:	A
Date Installed:	01/01/1972
Tank Material Desc:	Asphalt Coated or Bare Steel
Pipe Material Desc:	Bare or Galvanized Steel

MD Financial Assurance 2:

Name:	SEARS, ROEBUCK AND CO. INC.
Address:	6901 SECURITY BLVD.
City,State,Zip:	BALTIMORE, MD 21244
Region:	2
Facility ID:	14022
Self Insured:	False
Insurance:	False
Risk Retention Group:	False
Guarantee:	False
Surety Bonds:	False
Letter of Credit:	False
State Fund:	False
Other Finance:	False
Finacnce Comments:	Not reported
FR Not Listed:	False

A18 **SEOUL PLAZA (FMR FIRESTONE)** **MD OCPCASES** **S117975914**
Target **6901 SECURITY BLVD STE 2000** **N/A**
Property **BALTIMORE, MD 21207**

Site 18 of 45 in cluster A

Actual: **459 ft.**

OCPCASES:

Name:	SEOUL PLAZA (FMR FIRESTONE)
Address:	6901 SECURITY BLVD STE 2000
City,State,Zip:	BALTIMORE, MD 21207
Facility ID:	15-0515BA
Facility Status/Code:	CLOSED/Tank Closure - Commercial Heating Oil
Date Open:	03/10/2015
Date Closed:	12/30/2015
Release:	YES
Cleanup:	NO
Registration Number:	5743

A19 **J. C. PENNY PROPERTIES, INC.** **MD HIST UST** **S104630391**
Target **6901 SECURITY BLVD** **N/A**
Property **GWYNN OAK, MD 21207**

Site 19 of 45 in cluster A

Actual: **459 ft.**

Historical UST:

Facility ID:	3003747
Tank ID:	001
Age:	20
Capacity:	10,000
Tank Status:	Removed
Product:	Heating Oil

A20 **MONTGOMERY WARD CO** **RCRA-VSQG** **1004719749**
Target **6901 SECURITY SQUARE** **E MANIFEST** **MDD985408335**
Property **BALTIMORE, MD 21207**

Site 20 of 45 in cluster A

Actual: **459 ft.**

RCRA Listings:

Date Form Received by Agency:	19920317
Handler Name:	Montgomery Ward Co
Handler Address:	6901 Security Square
Handler City,State,Zip:	BALTIMORE, MD 21207
EPA ID:	MDD985408335
Contact Name:	ROBERT EGAN
Contact Address:	6901 SECURITY SQUARE
Contact City,State,Zip:	BALTIMORE, MD 21207
Contact Telephone:	301-265-9459
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	03
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities

MONTGOMERY WARD CO (Continued) **1004719749**

State District Owner:		Not reported
State District:		Not reported
Mailing Address:		6901 SECURITY SQUARE
Mailing City,State,Zip:		BALTIMORE, MD 21207
Owner Name:	Montgomery Ward Co	
Owner Type:		Private
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20180130
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D006
Waste Description:	Cadmium

MONTGOMERY WARD CO (Continued) **1004719749**

Waste Code: D007
Waste Description: Chromium

Waste Code: D018
Waste Description: Benzene

Waste Code: D039
Waste Description: Tetrachloroethylene

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: MONTGOMERY WARD CO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 6901 SECURITY SQUARE
Owner/Operator City,State,Zip: BALTIMORE, MD 21207
Owner/Operator Telephone: 301-265-9459
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19920317
Handler Name: MONTGOMERY WARD CO
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E MANIFEST:
Manifest Tracking Number: 017960403FLE
Last Updated Date: 20221121
Shipped Date: 20221107
Received Date: 20221110
Manifest Status: Corrected
Submission Type: DataImage5Copy

MONTGOMERY WARD CO (Continued) **1004719749**

Origin Type:	Service
Generator EPA ID:	MDD985408335
Generator Name:	Security Wards Llc
Generator Location Street Number:	Not reported
Generator Location Street 1:	6901 SECURITY BLVD
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1212 YORK ROAD
Generator Mail Street 2:	Not reported
Generator Mail City:	LUTHERVILLE
Generator Mail Zip:	21093
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	MID048090633
Designated Facility Name:	Wayne Disposal, Inc. Site #2 Landfill
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	49350 N I-94 SERVICE DRIVE
Designated Facility Mail City:	BELLEVILLE
Designated Facility Mail Zip:	48111
Designated Facility Mail State:	MI
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	49350 N I-94 SERVICE DRIVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	BELLEVILLE
Designated Facility Location Zip:	48111
Designated Facility Location State:	MI
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	017960404FLE
Last Updated Date:	20221109
Shipped Date:	20221026
Received Date:	20221027
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDD985408335
Generator Name:	Security Wards Llc
Generator Location Street Number:	Not reported
Generator Location Street 1:	6901 SECURITY BLVD
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1212 YORK ROAD
Generator Mail Street 2:	Not reported
Generator Mail City:	LUTHERVILLE
Generator Mail Zip:	21093
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	MID048090633

MONTGOMERY WARD CO (Continued) **1004719749**

Designated Facility Name:	Wayne Disposal, Inc. Site #2 Landfill
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	49350 N I-94 SERVICE DRIVE
Designated Facility Mail City:	BELLEVILLE
Designated Facility Mail Zip:	48111
Designated Facility Mail State:	MI
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	49350 N I-94 SERVICE DRIVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	BELLEVILLE
Designated Facility Location Zip:	48111
Designated Facility Location State:	MI
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

PCB Information:

Manifest Tracking Number:	017960404FLE
Waste Line Number:	1
Article or Container ID:	Not reported
Bulk Identity:	PCB Solid
Date of Removal:	20221011
Load Type:	BulkWaste
Load Type Description:	Bulk Waste
Waste Type:	Not reported
Weight:	5972.727

Transporter:

Manifest Tracking Number:	017960404FLE
Transporter Line Number:	1
Transporter EPA ID:	NJD980647028
Transporter Name:	Jrp Waste Oil Service, Inc

Waste Line:

Manifest Tracking Number:	017960404FLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN3432
U.S. DOT Description:	Rq, Un3432, Polychlorinated Biphenyls, Solid, 9, Pgii, Pcb, Erg#171
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	CM
Container Type Description:	Metal boxes, cartons, cases (including roll offs)
Waste Quantity:	5973
Quantity Unit of Measure Code:	K
Quantity Unit of Measure Description:	Kilograms
Waste Quantity, in Tons:	6.5852284
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	6.5852284
Waste Quantity, in Kilograms:	5973
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	5973
Management Method Code:	H132
Management Method Description:	LANDFILL (WITH PRIOR TREATMENT AND/OR STABILIZATION)
Waste Residue Indicator:	N

MONTGOMERY WARD CO (Continued) **1004719749**

Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not reported
Quantity Haz Kg:	0
Quantity Haz Tons:	0
Quantity Non Haz Kg:	5973
Quantity Non Haz Tons:	6.5852284
State Waste Codes:	Not reported

A21 **FIRESTONE SECURITY MALL** **MD OCPCASES** **S121712803**
Target **6901 SECURITY BLVD** **N/A**
Property **BALTIMORE, MD 21244**

Site 21 of 45 in cluster A

Actual:
459 ft.

OCPCASES:

Name:	FIRESTONE SECURITY MALL
Address:	6901 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244
Facility ID:	94-2145BA2
Facility Status/Code:	CLOSED/
Date Open:	02/15/1994
Date Closed:	07/12/1994
Release:	Not reported
Cleanup:	Not reported
Registration Number:	16393

Name:	FIRESTONE SECURITY MALL
Address:	6901 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244
Facility ID:	94-2145BA2
Facility Status/Code:	CLOSED/
Date Open:	02/15/1994
Date Closed:	07/12/1994
Release:	Not reported
Cleanup:	Not reported
Registration Number:	16393

A22 **SEARS 1634** **PA MANIFEST** **S110048928**
Target **6901 SECURITY BLVD** **N/A**
Property **BALTIMORE, MD 21244**

Site 22 of 45 in cluster A

Actual:
459 ft.

PA MANIFEST:

Name:	SEARS 1634
Address:	6901 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244
Year:	2015
Manifest Number:	007324553FLE
Manifest Type:	T
Generator EPA ID:	MDR000015511
Generator Date:	06/30/2015
Mailing Address:	Not reported
Contact Name:	Not reported
Contact Phone:	410-281-2211
TSD EPA ID:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	4
Container Type:	CF
Waste Quantity:	168
Unit:	P
Handling Code:	Not reported
TSP EPA ID:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	007324553FLE
Manifest Type:	T
Generator EPA ID:	MDR000015511
Generator Date:	06/30/2015
Mailing Address:	Not reported
Contact Name:	Not reported
Contact Phone:	410-281-2211
TSD EPA ID:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D001
Container Number:	1
Container Type:	CF
Waste Quantity:	15
Unit:	P
Handling Code:	Not reported

SEARS 1634 (Continued) **S110048928**

TSP EPA ID: PAD085690592
Date TSP Sig: Not reported

Year: 2008
Manifest Number: 002036143FLE
Manifest Type: T
Generator EPA ID: MDR000015511
Generator Date: 10/10/2008
Mailing Address: Not reported
Contact Name: Not reported
Contact Phone: 410-281-2211
TSD EPA ID: PAD067098822
TSD Date: Not reported
TSD Facility Name: CYCLE CHEM INC
TSD Facility Address: 550 INDUSTRIAL DRIVE
TSD Facility City: LEWISBERRY
TSD Facility State: PA
Facility Telephone: Not reported
Page Number: 1
Line Number: 1
Waste Number: D016
Container Number: 1
Container Type: DF
Waste Quantity: 25
Unit: P
Handling Code: Not reported
TSP EPA ID: Not reported
Date TSP Sig: Not reported

Year: 2008
Manifest Number: 002036143FLE
Manifest Type: T
Generator EPA ID: MDR000015511
Generator Date: 10/10/2008
Mailing Address: Not reported
Contact Name: Not reported
Contact Phone: 410-281-2211
TSD EPA ID: PAD067098822
TSD Date: Not reported
TSD Facility Name: CYCLE CHEM INC
TSD Facility Address: 550 INDUSTRIAL DRIVE
TSD Facility City: LEWISBERRY
TSD Facility State: PA
Facility Telephone: Not reported
Page Number: 1
Line Number: 2
Waste Number: D001
Container Number: 1
Container Type: DF
Waste Quantity: 75
Unit: P
Handling Code: Not reported
TSP EPA ID: Not reported
Date TSP Sig: Not reported

Year: 2008
Manifest Number: 002036143FLE

SEARS 1634 (Continued) **S110048928**

Manifest Type:	T
Generator EPA ID:	MDR000015511
Generator Date:	10/10/2008
Mailing Address:	Not reported
Contact Name:	Not reported
Contact Phone:	410-281-2211
TSD EPA ID:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	3
Waste Number:	D001
Container Number:	1
Container Type:	DF
Waste Quantity:	200
Unit:	P
Handling Code:	Not reported
TSP EPA ID:	Not reported
Date TSP Sig:	Not reported
Year:	2008
Manifest Number:	002036143FLE
Manifest Type:	T
Generator EPA ID:	MDR000015511
Generator Date:	10/10/2008
Mailing Address:	Not reported
Contact Name:	Not reported
Contact Phone:	410-281-2211
TSD EPA ID:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	4
Waste Number:	U121
Container Number:	3
Container Type:	DM
Waste Quantity:	400
Unit:	P
Handling Code:	Not reported
TSP EPA ID:	Not reported
Date TSP Sig:	Not reported
Year:	2009
Manifest Number:	002036320FLE
Manifest Type:	T
Generator EPA ID:	MDR000015511
Generator Date:	05/19/2009
Mailing Address:	Not reported
Contact Name:	Not reported

SEARS 1634 (Continued) **S110048928**

Contact Phone:	410-281-2211
TSD EPA ID:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	DM
Waste Quantity:	50
Unit:	P
Handling Code:	Not reported
TSP EPA ID:	Not reported
Date TSP Sig:	Not reported

Year:	2009
Manifest Number:	002036320FLE
Manifest Type:	T
Generator EPA ID:	MDR000015511
Generator Date:	05/19/2009
Mailing Address:	Not reported
Contact Name:	Not reported
Contact Phone:	410-281-2211
TSD EPA ID:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D002
Container Number:	1
Container Type:	DF
Waste Quantity:	50
Unit:	P
Handling Code:	Not reported
TSP EPA ID:	Not reported
Date TSP Sig:	Not reported

Year:	2009
Manifest Number:	002036320FLE
Manifest Type:	T
Generator EPA ID:	MDR000015511
Generator Date:	05/19/2009
Mailing Address:	Not reported
Contact Name:	Not reported
Contact Phone:	410-281-2211
TSD EPA ID:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE

SEARS 1634 (Continued) **S110048928**

TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	3
Waste Number:	D002
Container Number:	1
Container Type:	DF
Waste Quantity:	50
Unit:	P
Handling Code:	Not reported
TSP EPA ID:	Not reported
Date TSP Sig:	Not reported
Year:	2009
Manifest Number:	002036320FLE
Manifest Type:	T
Generator EPA ID:	MDR000015511
Generator Date:	05/19/2009
Mailing Address:	Not reported
Contact Name:	Not reported
Contact Phone:	410-281-2211
TSD EPA ID:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	4
Waste Number:	D001
Container Number:	1
Container Type:	DF
Waste Quantity:	100
Unit:	P
Handling Code:	Not reported
TSP EPA ID:	Not reported
Date TSP Sig:	Not reported
Year:	2005
Manifest Number:	PAG126388
Manifest Type:	T
Generator EPA ID:	MDR000015511
Generator Date:	03/22/2005
Mailing Address:	3333 BEVERLY RD D824EV
Contact Name:	Not reported
Contact Phone:	410-281-2211
TSD EPA ID:	PAD067098822
TSD Date:	04/11/2005
TSD Facility Name:	CYCLE CHEM
TSD Facility Address:	550 INDUSTRIAL DR
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1

SEARS 1634 (Continued) **S110048928**

Waste Number:	D001
Container Number:	2
Container Type:	DM
Waste Quantity:	100
Unit:	G
Handling Code:	Not reported
TSP EPA ID:	NYD980761191
Date TSP Sig:	03/22/2005

Click this hyperlink while viewing on your computer to access
15 additional PA MANIFEST: record(s) in the EDR Site Report.

A23 **SET THE CAPTIVES FREE OUTREACH CENTER** **MD ASBESTOS** **S131451887**
Target **6901 SECURITY BLVD, SECURITY SQUARE MALL, ANCHOR STORE** **N/A**
Property **BALTIMORE, MD 21207**

Site 23 of 45 in cluster A

Actual:
459 ft.

ASBESTOS:

Name:	SET THE CAPTIVES FREE OUTREACH CENTER
Address:	6901 SECURITY BLVD, SECURITY SQUARE MALL, ANCHOR STORE
City,State,Zip:	BALTIMORE, MD 21207
Year:	2023
Removal/Encapsulation/Demolition Start Date:	07/17/2023
Removal/Encapsulation/Demolition End Date:	08/07/2023
Days of the week worked:	From Mon - Sat
Volume off facility Component (Cat I) not removed:	0 Cubic Yards
Volume off facility Component (Cat I) not removed:	0 Cubic Yards
Volume off facility Component (Cat II) not removed:	0 Cubic Yards
Hours worked in a day:	1800-0200
Original or resubmit:	Not reported
Number of floors in building:	Not reported
Pipe Cat I not removed:	0 Linear Feet
Pipe Cat II not removed:	0 Linear Feet
Type of Building:	Not reported
Contractor name:	BELLZ & BELLZ
Length of project:	Not reported
Type of project from notification form:	D-N Demolition (NESHAP)
Volume off facility component Cat I non friable removed:	0 Cubic Yards
Pipes Cat I non friable removed:	0 Linear Feet
Surface area Cat I non friable removed:	0 Square Feet
Volume off facility component, Cat II non friable removed:	0 Cubic Yards
Pipe Cat II non friable removed:	0 Linear Feet
Surface area Cat II non friable removed:	0 Square Feet
Volume of facility component RACM removed:	0 Cubic Yards
Pipes RACM removed:	0 Linear Feet
Surface area RACM removed:	9000 Square Feet
Surface area Cat I not removed:	0 Square Feet
Surface area Cat II not removed:	0 Square Feet
Site description (found in Section II of the notification):	2nd Floor
Owner of the site:	Not reported
Landfill asbestos will be sent to:	Not reported
Transporter of the waste:	Not reported
Facility off components units:	Not reported
Pipes unit of measure:	Linear Feet
Surface area unit of measure:	Square Feet
Received Date:	Not reported
Owner name:	Not reported

SET THE CAPTIVES FREE OUTREACH CENTER (Continued) **S131451887**

Owner contact:	Not reported
Owner street address:	Not reported
Owner street address 2:	Not reported
Owner city:	Not reported
Owner state:	Not reported
Owner zip code:	Not reported
ID number:	Not reported
Contractor:	m21-24-684
Notification:	5252
Asbestos Present:	Asbestos is Present
Submitted Date:	2023-06-29 00:00:00
Creation Date:	2023-07-28 00:00:00
Created By:	WGabriel
MDE Date:	2023-07-28 00:00:00
Comments:	Mastic
Number Of Workers:	4
Project Supervisor:	Garpue Barchue
Project Contact:	Adebayo Bello
Project Contact Phone:	4103439997
Last Updated By:	WGabriel
Last Updated On:	2023-07-28 00:00:00

A24 **HECHT'S** **MD OCPCASES** **S121712361**
Target Property **6901 SECURITY BLVD** **N/A**
BALTIMORE, MD 21207

Site 24 of 45 in cluster A

Actual: 459 ft.

OCPCASES:

Name:	HECHT'S
Address:	6901 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21207
Facility ID:	04-0455BA1
Facility Status/Code:	CLOSED/Compliance Inspections (C3, 4, 4A, 5, 9, 10, 11)
Date Open:	09/03/2003
Date Closed:	02/15/2006
Release:	NO
Cleanup:	NO
Registration Number:	6267

A25 **SEARS, ROEBUCK AND CO. INC.** **UST FINDER** **1028405173**
Target Property **6901 SECURITY BLVD.** **N/A**
BALTIMORE, MD 21244

Site 25 of 45 in cluster A

Actual: 459 ft.

UST FINDER:

Object ID:	638191
Facility ID:	MD14022
Name:	SEARS, ROEBUCK AND CO. INC.
Address:	6901 SECURITY BLVD.
City,State,Zip:	BALTIMORE, MD 21244
Address Match Type:	PointAddress
Open USTs:	0
Closed USTs:	1
TOS USTs:	0

SEARS, ROEBUCK AND CO. INC. (Continued) **1028405173**

Population 1500ft:	253
Private Wells 1500ft:	2
Within 100yr Floodplain:	No
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	3
Tribe:	Not reported
Coordinate Source:	Geocode
X Coord:	-76.75049444
Y Coord:	39.3128395200001
Latitude:	39.31283952
Longitude:	-76.75049444

UST FINDER:

Object ID:	709787
Facility ID:	MD14022
Tank ID:	MD14022_1
Tank Status:	Closed
Installation Date:	1972/01/01 16:00:00+00
Removal Date:	1995/03/28 15:59:59+00
Tank Capacity:	550
Substances:	Used Oil
Tank Wall Type:	Single

A26 **SIGNATURE COLLISION** **RCRA-VSQG** **1027472421**
Target **6901 SECURITY BLVD #2000** **E MANIFEST** **MDD150022150**
Property **BALTIMORE, MD 21244**

Site 26 of 45 in cluster A

Actual: 459 ft.

RCRA Listings:

Date Form Received by Agency:	20221102
Handler Name:	Crash Champions - Windsor Mill 211
Handler Address:	Security Blvd - Ste 2000
Handler City,State,Zip:	WINDSOR MILL, MD 21244
EPA ID:	MDD150022150
Contact Name:	MATTHEW EBERT
Contact Address:	OAKMONT LANE, SUITE 400
Contact City,State,Zip:	WESTMONT, IL 60559
Contact Telephone:	708-631-0403
Contact Fax:	Not reported
Contact Email:	COMPLIANCE@CRASHCHAMPIONS.COM
Contact Title:	CEO
EPA Region:	03
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator

SIGNATURE COLLISION (Continued) **1027472421**

Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		OAKMONT LANE, SUITE 400
Mailing City,State,Zip:		WESTMONT, IL 60559
Owner Name:	Crash Champions, Llc	
Owner Type:		Private
Operator Name:	Crash Champions, Llc	
Operator Type:		Tribal
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20221118
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

SIGNATURE COLLISION (Continued) **1027472421**

Waste Code: D039
Waste Description: Tetrachloroethylene

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CRASH CHAMPIONS, LLC
Legal Status: Private
Date Became Current: 20210731
Date Ended Current: Not reported
Owner/Operator Address: 601 OAKMONT LANE, SUITE 400
Owner/Operator City,State,Zip: WESTMONT, IL 60559
Owner/Operator Telephone: 708-906-6458
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: COMPLIANCE@CRASHCHAMPIONS.COM

Owner/Operator Indicator: Operator
Owner/Operator Name: ZIMMERMAN
Legal Status: Private
Date Became Current: 19870401
Date Ended Current: 20030301
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: FIRESTONE TIRE & RUBBER CO INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: OWNERSTREET
Owner/Operator City,State,Zip: OWNERCITY, AK 99999
Owner/Operator Telephone: 215-555-1212

SIGNATURE COLLISION (Continued) **1027472421**

Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CRASH CHAMPIONS, LLC	
Legal Status:	Tribal
Date Became Current:	20210731
Date Ended Current:	Not reported
Owner/Operator Address:	601 OAKMONT LANE, SUITE 400
Owner/Operator City,State,Zip:	WESTMONT, IL 60559
Owner/Operator Telephone:	708-906-6458
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	COMPLIANCE@CRASHCHAMPIONS.COM
Owner/Operator Indicator:	Owner
Owner/Operator Name: STEVE CHOI	
Legal Status:	Private
Date Became Current:	20030301
Date Ended Current:	Not reported
Owner/Operator Address:	6901 SECURITY BLVD
Owner/Operator City,State,Zip:	BALTIMORE, MD 21244
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: CHONG ZK LEE	
Legal Status:	Private
Date Became Current:	20050501
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: OPERNAME	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	OPERSTREET
Owner/Operator City,State,Zip:	OPERCITY, AK 99999
Owner/Operator Telephone:	215-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: FIRESTONE TIRE & RUBBER CO INC	
Legal Status:	Private
Date Became Current:	19870401
Date Ended Current:	20030301

SIGNATURE COLLISION (Continued) **1027472421**

Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19870401
Handler Name: FIRESTONE TIRES INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20050526
Handler Name: GRAND AUTO BODY & CARE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20221102
Handler Name: CRASH CHAMPIONS - WINDSOR MILL 211
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 811121
NAICS Description: Automotive Body, Paint, And Interior Repair And Maintenance

Facility Has Received Notices of Violations:
Violations: No Violations Found

SIGNATURE COLLISION (Continued) **1027472421**

Evaluation Action Summary:
Evaluations: No Evaluations Found

E MANIFEST:

Manifest Tracking Number:	013814060FLE
Last Updated Date:	20191108
Shipped Date:	20191011
Received Date:	20191011
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDD150022150
Generator Name:	Signature Collision
Generator Location Street Number:	Not reported
Generator Location Street 1:	6901 SECURITY BLVD #2000
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	6901 SECURITY BLVD #2000
Generator Mail Street 2:	Not reported
Generator Mail City:	BALTIMORE
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD067098822
Designated Facility Name:	Cycle Chem, Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	550 INDUSTRIAL DRIVE
Designated Facility Mail City:	LEWISBERRY
Designated Facility Mail Zip:	17339
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	550 INDUSTRIAL DRIVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	LEWISBERRY
Designated Facility Location Zip:	17339
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	013814060FLE
Transporter Line Number:	1
Transporter EPA ID:	MDR000509283
Transporter Name:	Biomedical Waste Services

Waste Line:

Manifest Tracking Number:	013814060FLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y

SIGNATURE COLLISION (Continued) **1027472421**

U.S. DOT ID Number:	UN1263
U.S. DOT Description:	Un1263, Waste Paint Related Material, 3 , Ii
Non-Hazardous Waste Description:	Not reported
Number of Containers:	3
Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	165
Quantity Unit of Measure Code:	G
Quantity Unit of Measure Description:	Gallons
Waste Quantity, in Tons:	0.6880734
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.6880734
Waste Quantity, in Kilograms:	624.1032
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	624.1032
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D001, D035
Quantity Haz Kg:	624.1032
Quantity Haz Tons:	0.6880734
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	Not reported

Manifest Tracking Number:	013814060FLE
Waste Line Number:	2
U.S. DOT Hazardous Indicator:	N
U.S. DOT ID Number:	Not reported
U.S. DOT Description:	Not reported
Non-Hazardous Waste Description:	Non Regulated Material
Number of Containers:	7
Container Type Code:	DF
Container Type Description:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	500
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.25
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.25
Waste Quantity, in Kilograms:	226.7575
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	226.7575
Management Method Code:	Not reported

SIGNATURE COLLISION (Continued) **1027472421**

Management Method Description:	Not reported
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not reported
Quantity Haz Kg:	0
Quantity Haz Tons:	0
Quantity Non Haz Kg:	226.7575
Quantity Non Haz Tons:	0.25
State Waste Codes:	Not reported

A27 **FIRESTONE MASTERCARE** **MD HIST UST** **S104630561**
Target **6901 SECURITY BLVD** **N/A**
Property **GWYNN OAK, MD 21207**

Site 27 of 45 in cluster A

Actual: **459 ft.**

Historical UST:

Facility ID:	3003990
Tank ID:	001
Age:	20
Capacity:	550
Tank Status:	Removed
Product:	Used Oil

Facility ID:	3003990
Tank ID:	002
Age:	20
Capacity:	6,000
Tank Status:	Currently in use
Product:	Heating Oil

A28 **SS SELF STORAGE LLC** **MD OCPCASES** **S130272443**
Target **6901 SECURITY BLVD** **N/A**
Property **WINDSOR MILL, MD 21244**

Site 28 of 45 in cluster A

Actual: **459 ft.**

OCPCASES:

Name:	SS SELF STORAGE LLC
Address:	6901 SECURITY BLVD
City,State,Zip:	WINDSOR MILL, MD 21244
Facility ID:	23-0411BA
Facility Status/Code:	CLOSED/Tank Closure - Motor/Lube Oil
Date Open:	03/09/2023

SS SELF STORAGE LLC (Continued) **S130272443**

Date Closed: 06/20/2023
Release: NO
Cleanup: NO
Registration Number: 21208

A29 **SEARS #1634** **MD MANIFEST** **S121870942**
Target **6901 SECURITY SQ BLVD** **N/A**
Property **BALTIMORE-WEST, MD 21244**

Site 29 of 45 in cluster A

Actual:
459 ft.

MD MANIFEST:

EPAID:	MDR000015511
Name:	SEARS #1634
Address:	6901 SECURITY SQ BLVD
City,State,Zip:	BALTIMORE-WEST, MD 21244
Manifest Number:	011454013FLE
Transporter 1:	REPUBLIC ENVIRONMENTAL SYSTEMS (TRANS GROUP) LLC
Transporter 2:	Not reported
Generator Certifier:	ANN MANHERT
Date Shipped Out:	05/22/2018
Destination Facility Certifier:	JEAN SAALMAN
Date Arrived at Destingation Facility:	06/05/2018
Quantity:	52
Unit:	Pounds

EPAID:	MDR000015511
Name:	SEARS #1634
Address:	6901 SECURITY SQ BLVD
City,State,Zip:	BALTIMORE-WEST, MD 21244
Manifest Number:	007324553FLE
Transporter 1:	STERICYCLE SPECIALTY WASTE SOLUTIONS INC
Transporter 2:	REPUBLIC ENV SYS (TRANS GROUP) LLC
Generator Certifier:	LAQUANDA HANLEY
Date Shipped Out:	06/30/2015
Destination Facility Certifier:	MALVOR
Date Arrived at Destingation Facility:	07/09/2015
Quantity:	8
Unit:	POUND

EPAID:	MDR000015511
Name:	SEARS #1634
Address:	6901 SECURITY SQ BLVD
City,State,Zip:	BALTIMORE-WEST, MD 21244
Manifest Number:	008590628FLE
Transporter 1:	STERICYCLE SPECIALTY WASTE SOLUTIONS,INC.
Transporter 2:	REPUBLIC ENV SYSTEMS (PA) LLC
Generator Certifier:	GLENN MARLEY
Date Shipped Out:	12/15/2015
Destination Facility Certifier:	JEAN SAALMAN
Date Arrived at Destingation Facility:	12/28/2015
Quantity:	17
Unit:	POUNDS

EPAID:	MDR000015511
Name:	SEARS #1634
Address:	6901 SECURITY SQ BLVD
City,State,Zip:	BALTIMORE-WEST, MD 21244

SEARS #1634 (Continued) **S121870942**

Manifest Number:	010102426FLE
Transporter 1:	REPUBLIC ENV SYS (TRANS GROUP) LLC
Transporter 2:	Not reported
Generator Certifier:	P. THOMPSON
Date Shipped Out:	05/30/2017
Destination Facility Certifier:	JEAN SAALMAN
Date Arrived at Destingation Facility:	06/07/2017
Quantity:	759
Unit:	Pounds

EPAID:	MDR000015511
Name:	SEARS #1634
Address:	6901 SECURITY SQ BLVD
City,State,Zip:	BALTIMORE-WEST, MD 21244
Manifest Number:	010102426FLE
Transporter 1:	REPUBLIC ENV SYS (TRANS GROUP) LLC
Transporter 2:	Not reported
Generator Certifier:	P. THOMPSON
Date Shipped Out:	05/30/2017
Destination Facility Certifier:	JEAN SAALMAN
Date Arrived at Destingation Facility:	06/07/2017
Quantity:	148
Unit:	Pounds

EPAID:	MDR000015511
Name:	SEARS #1634
Address:	6901 SECURITY SQ BLVD
City,State,Zip:	BALTIMORE-WEST, MD 21244
Manifest Number:	010056798FLE
Transporter 1:	REPUBLIC ENV SYS (TRANS GROUP) LLC
Transporter 2:	Not reported
Generator Certifier:	ANN MANHERZ
Date Shipped Out:	11/30/2017
Destination Facility Certifier:	JEAN SAALMAN
Date Arrived at Destingation Facility:	12/07/2017
Quantity:	9
Unit:	Pounds

A30 **J.C. PENNEY CO. INC.** **FINDS** **1016183728**
Target **6901 SECURITY BLVD** **ECHO** **N/A**
Property **WINDSOR MILL, MD 21244**

Site 30 of 45 in cluster A

Actual:
459 ft.

FINDS:
Registry ID: 110002021035

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.

J.C. PENNEY CO. INC. (Continued) **1016183728**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016183728
Registry ID: 110002021035

DFR URL:
Name: J.C. PENNEY CO. INC.
Address: 6901 Security Blvd
City,State,Zip: WINDSOR MILL, MD 21244

A31 SEARS STORE #1634 **MD OCPCASES S121712798**
Target 6901 SECURITY BLVD **MD ASBESTOS N/A**
Property BALTIMORE, MD 21244

Site 31 of 45 in cluster A

Actual: 459 ft.

OCPCASES:
Name: SEARS STORE #1634
Address: 6901 SECURITY BLVD
City,State,Zip: BALTIMORE, MD 21244
Facility ID: 94-1624BA2
Facility Status/Code: CLOSED/
Date Open: 12/01/1993
Date Closed: 03/28/1995
Release: Not reported
Cleanup: Not reported
Registration Number: 14022

Name: SEARS STORE #1634
Address: 6901 SECURITY BLVD
City,State,Zip: BALTIMORE, MD 21244
Facility ID: 94-1624BA2
Facility Status/Code: CLOSED/
Date Open: 12/01/1993
Date Closed: 03/28/1995
Release: Not reported
Cleanup: Not reported
Registration Number: 14022

ASBESTOS:
Name: SECURITY SQUARE MALL, ANCHOR STORE
Address: 6901 SECURITY BLVD
City,State,Zip: BALTIMORE, MD 21207-
Year: 2019
Removal/Encapsulation/Demolition Start Date: 03/23/2019
Removal/Encapsulation/Demolition End Date: 03/24/2019
Days of the week worked: SAT-SUN
Volume off facility Component (Cat I) not removed: 0 Cubic Yards
Volume off facility Component (Cat I) not removed: 0 Cubic Yards
Volume off facility Component (Cat II) not removed: 0 Cubic Yards
Hours worked in a day: 0800-170
Original or resubmit: O Origina
Number of floors in building: 2
Pipe Cat I not removed: 0 Linear Feet
Pipe Cat II not removed: 0 Linear Feet

SEARS STORE #1634 (Continued) **S121712798**

Type of Building:	Commercial
Contractor name:	The Environmental Group, Inc
Length of project:	Not reported
Type of project from notification form:	R-N Renovation (NESHAP)
Volume off facility component Cat I non friable removed:	0 Cubic Yards
Pipes Cat I non friable removed:	0 Linear Feet
Surface area Cat I non friable removed:	0 Square Feet
Volume off facility component, Cat II non friable removed:	0 Cubic Yards
Pipe Cat II non friable removed:	0 Linear Feet
Surface area Cat II non friable removed:	0 Square Feet
Volume of facility component RACM removed:	0 Cubic Yards
Pipes RACM removed:	0 Linear Feet
Surface area RACM removed:	1690 Square Feet
Surface area Cat I not removed:	0 Square Feet
Surface area Cat II not removed:	0 Square Feet
Site description (found in Section II of the notification):	escalator Agency Partner, offi
Owner of the site:	True
Landfill asbestos will be sent to:	True
Transporter of the waste:	True
Facility off components units:	Not reported
Pipes unit of measure:	Linear Feet
Surface area unit of measure:	Square Feet Square Feet
Received Date:	03/11/2019
Owner name:	Set the Captives Free Outreach
Owner contact:	Penn-Jones
Owner street address:	7200 Rutherford RD Suite 140
Owner street address 2:	Not reported
Owner city:	Baltimore
Owner state:	MD
Owner zip code:	21244-
ID number:	190465
Contractor:	Not reported
Notification:	Not reported
Asbestos Present:	Not reported
Submitted Date:	Not reported
Creation Date:	Not reported
Created By:	Not reported
MDE Date:	Not reported
Comments:	Not reported
Number Of Workers:	Not reported
Project Supervisor:	Not reported
Project Contact:	Not reported
Project Contact Phone:	Not reported
Last Updated By:	Not reported
Last Updated On:	Not reported

A32 **SECURITY MALL** **MD HIST UST** **S104629396**
Target **6901 SECURITY BLVD** **N/A**
Property **GWYNN OAK, MD 21207**

Site 32 of 45 in cluster A

Actual:
459 ft.

Historical UST:

Facility ID:	3001797
Tank ID:	001
Age:	17
Capacity:	250
Tank Status:	Currently in use

SECURITY MALL (Continued) **S104629396**

Product: Kerosene

A33 **GRAND AUTO BODY** **US AIRS** **1016941317**
Target **6901 SECURITY BOULEVARD #2000E** **N/A**
Property **WINDSOR MILL, MD 21244**

Site 33 of 45 in cluster A

Actual:
459 ft.

US AIRS MINOR:

Envid:	1016941317
Region Code:	03
Programmatic ID:	AIR MD0000002400502557
Facility Registry ID:	110022379399
D and B Number:	Not reported
Primary SIC Code:	7532
NAICS Code:	811121
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	03
Programmatic ID:	AIR MD0000002400502557
Facility Registry ID:	110022379399
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2014-06-25 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	03
Programmatic ID:	AIR MD0000002400502557
Facility Registry ID:	110022379399
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2014-06-25 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

A34 **MACY'S SECURITY SQUARE MALL** **UST FINDER** **1028412182**
Target **6901 SECURITY BLVD.** **N/A**
Property **BALTIMORE, MD 21207**

Site 34 of 45 in cluster A

Actual:
459 ft.

UST FINDER:

Object ID:	638190
Facility ID:	MD6267
Name:	MACY'S SECURITY SQUARE MALL
Address:	6901 SECURITY BLVD.
City,State,Zip:	BALTIMORE, MD 21207
Address Match Type:	PointAddress
Open USTs:	0
Closed USTs:	2
TOS USTs:	0
Population 1500ft:	253
Private Wells 1500ft:	2
Within 100yr Floodplain:	No
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	3
Tribe:	Not reported
Coordinate Source:	Geocode
X Coord:	-76.75049444
Y Coord:	39.3128395200001
Latitude:	39.31283952
Longitude:	-76.75049444

UST FINDER:

Object ID:	739150
Facility ID:	MD6267
Tank ID:	MD6267_1
Tank Status:	Closed
Installation Date:	1979/05/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	300
Substances:	Diesel
Tank Wall Type:	Single

Object ID:	689794
Facility ID:	MD6267
Tank ID:	MD6267_2
Tank Status:	Closed
Installation Date:	1999/02/17 15:59:59+00
Removal Date:	2012/10/26 15:59:59+00
Tank Capacity:	300
Substances:	Diesel
Tank Wall Type:	Single

A35 **MACY'S SECURITY SQUARE MALL** **MD UST** **U004445751**
Target **6901 SECURITY BLVD.** **MD Financial Assurance** **N/A**
Property **BALTIMORE, MD 21207**

Site 35 of 45 in cluster A

Actual:
459 ft.

UST:

Facility Id:	6267
Oper Name:	Robert Kozul
Form Name:	Mark Bruce
Form Title:	Owner's Rep
Form Date:	10/26/2012
Owner Id:	13222

Owner:

Owner Name:	Macy's Inc.
Owner Address:	7 West 7th Street
Owner City:	Cincinnati
Owner State:	OH
Owner Zip:	45202
Owner Phone:	(513) 562-6702
Owner Contact:	Melissa Hoffman

Tanks:

Tank ID:	1
Tank Status:	**Permanently Out Of Use**
Tank Capacity:	300
Substance Description:	Diesel
Tank Compartment:	False
Compartment Compartment:	A
Date Installed:	05/01/1979
Tank Material Desc:	Asphalt Coated or Bare Steel
Pipe Material Desc:	Bare or Galvanized Steel

Tank ID:	2
Tank Status:	**Permanently Out Of Use**
Tank Capacity:	300
Substance Description:	Diesel
Tank Compartment:	False
Compartment Compartment:	A
Date Installed:	02/17/1999
Tank Material Desc:	Cathodically Protected Steel (Coating w/CP - Galvanic)
Pipe Material Desc:	Copper sleeved in plastic

MD Financial Assurance 2:

Name:	MACY'S SECURITY SQUARE MALL
Address:	6901 SECURITY BLVD.
City,State,Zip:	BALTIMORE, MD 21207
Region:	2
Facility ID:	6267
Self Insured:	True
Insurance:	False
Risk Retention Group:	False
Guarantee:	False
Surety Bonds:	False
Letter of Credit:	False
State Fund:	False
Other Finance:	False

MACY'S SECURITY SQUARE MALL (Continued) **U004445751**

Finacnce Comments: Period of Coverage: 5/15/12 - 5/15/13 (sd)
FR Not Listed: False

A36 Target Property **MACYS SECURITY SQUARE 710159**
6901 SECURITY BLVD.
BALTIMORE, MD 21244

ECHO **1026010568**
E MANIFEST **N/A**

Site 36 of 45 in cluster A

Actual: 459 ft.

ECHO:
Envid: 1026010568
Registry ID: 110022380644

DFR URL:
Name: SEARS STORE #1634
Address: 6901 Security Blvd.
City,State,Zip: BALTIMORE, MD 21207

E MANIFEST:
Manifest Tracking Number: 012322768FLE
Last Updated Date: 20191229
Shipped Date: 20191216
Received Date: 20191217
Manifest Status: Signed
Submission Type: DataImage5Copy
Origin Type: Service
Generator EPA ID: Not reported
Generator Name: Macys Security Square 710159
Generator Location Street Number: Not reported
Generator Location Street 1: 6901 SECURITY BLVD.
Generator Location Street 2: Not reported
Generator Location City: BALTIMORE
Generator Location State: MD
Generator Location Zip: 21244
Generator Mail Street Number: Not reported
Generator Mail Street 1: ATTN: RECEIVING TEAM LEAD
Generator Mail Street 2: 6901 SECURITY BLVD.
Generator Mail City: BALTIMORE
Generator Mail Zip: 21244
Generator Mail State: MD
Generator Contact Company Name: Not reported
Designated Facility EPA ID: PAD010154045
Designated Facility Name: Envirite Of Pennsylvania Inc
Designated Facility Mail Street Number: Not reported
Designated Facility Mail Street 1: Not reported
Designated Facility Mail Street 2: 730 VOGELSONG RD
Designated Facility Mail City: YORK
Designated Facility Mail Zip: 17404-6707
Designated Facility Mail State: PA
Designated Facility Location Street Number: Not reported
Designated Facility Location Street 1: 730 VOGELSONG RD
Designated Facility Location Street 2: Not reported
Designated Facility Location City: YORK
Designated Facility Location Zip: 17404-6707
Designated Facility Location State: PA
Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N

MACYS SECURITY SQUARE 710159 (Continued) **1026010568**

Rejection Indicator:	N
Manifest Tracking Number:	012322768FLE
Last Updated Date:	20191229
Shipped Date:	20191216
Received Date:	20191217
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	Not reported
Generator Name:	Macys Security Square 710159
Generator Location Street Number:	Not reported
Generator Location Street 1:	6901 SECURITY BLVD.
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	ATTN: RECEIVING TEAM LEAD
Generator Mail Street 2:	6901 SECURITY BLVD.
Generator Mail City:	BALTIMORE
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD010154045
Designated Facility Name:	Envirite Of Pennsylvania Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	730 VOGELSONG RD
Designated Facility Mail City:	YORK
Designated Facility Mail Zip:	17404-6707
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	730 VOGELSONG RD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	YORK
Designated Facility Location Zip:	17404-6707
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	023021179JJK
Last Updated Date:	20220217
Shipped Date:	20220208
Received Date:	20220210
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDR000516369
Generator Name:	Macys Security Square 710159
Generator Location Street Number:	Not reported
Generator Location Street 1:	6901 SECURITY BLVD.
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244

MACYS SECURITY SQUARE 710159 (Continued) **1026010568**

Generator Mail Street Number:	Not reported
Generator Mail Street 1:	ATTN: RECEIVING TEAM LEAD
Generator Mail Street 2:	6901 SECURITY BLVD.
Generator Mail City:	BALTIMORE
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD010154045
Designated Facility Name:	Envirite Of Pennsylvania, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	730 VOGELSONG ROAD
Designated Facility Mail City:	YORK
Designated Facility Mail Zip:	17404
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	730 VOGELSONG ROAD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	YORK
Designated Facility Location Zip:	17404
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	023021179JJK
Last Updated Date:	20220217
Shipped Date:	20220208
Received Date:	20220210
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDR000516369
Generator Name:	Macys Security Square 710159
Generator Location Street Number:	Not reported
Generator Location Street 1:	6901 SECURITY BLVD.
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	ATTN: RECEIVING TEAM LEAD
Generator Mail Street 2:	6901 SECURITY BLVD.
Generator Mail City:	BALTIMORE
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD010154045
Designated Facility Name:	Envirite Of Pennsylvania, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	730 VOGELSONG ROAD
Designated Facility Mail City:	YORK
Designated Facility Mail Zip:	17404
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	730 VOGELSONG ROAD

MACYS SECURITY SQUARE 710159 (Continued) **1026010568**

Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	YORK
Designated Facility Location Zip:	17404
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	014843835FLE
Last Updated Date:	20201023
Shipped Date:	20201013
Received Date:	20201014
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	Not reported
Generator Name:	Macys Security Square 710159
Generator Location Street Number:	Not reported
Generator Location Street 1:	6901 SECURITY BLVD.
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	ATTN: RECEIVING TEAM LEAD
Generator Mail Street 2:	6901 SECURITY BLVD.
Generator Mail City:	BALTIMORE
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD010154045
Designated Facility Name:	Envirite Of Pennsylvania Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	730 VOGELSONG RD
Designated Facility Mail City:	YORK
Designated Facility Mail Zip:	17404-6707
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	730 VOGELSONG RD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	YORK
Designated Facility Location Zip:	17404-6707
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	014843835FLE
Last Updated Date:	20201023
Shipped Date:	20201013
Received Date:	20201014
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	Not reported
Generator Name:	Macys Security Square 710159

MACYS SECURITY SQUARE 710159 (Continued) **1026010568**

Generator Location Street Number:	Not reported
Generator Location Street 1:	6901 SECURITY BLVD.
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	ATTN: RECEIVING TEAM LEAD
Generator Mail Street 2:	6901 SECURITY BLVD.
Generator Mail City:	BALTIMORE
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD010154045
Designated Facility Name:	Envirite Of Pennsylvania Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	730 VOGELSONG RD
Designated Facility Mail City:	YORK
Designated Facility Mail Zip:	17404-6707
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	730 VOGELSONG RD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	YORK
Designated Facility Location Zip:	17404-6707
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	023534710JJK
Last Updated Date:	20240326
Shipped Date:	20211209
Received Date:	20211209
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDR000516369
Generator Name:	Macys Security Square 710159
Generator Location Street Number:	Not reported
Generator Location Street 1:	6901 SECURITY BLVD.
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	ATTN: RECEIVING TEAM LEAD
Generator Mail Street 2:	6901 SECURITY BLVD.
Generator Mail City:	BALTIMORE
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD010154045
Designated Facility Name:	Envirite Of Pennsylvania, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported

MACYS SECURITY SQUARE 710159 (Continued) **1026010568**

Designated Facility Mail Street 2:	730 VOGELSONG ROAD
Designated Facility Mail City:	YORK
Designated Facility Mail Zip:	17404
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	730 VOGELSONG ROAD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	YORK
Designated Facility Location Zip:	17404
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	023534710JJK
Last Updated Date:	20240326
Shipped Date:	20211209
Received Date:	20211209
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDR000516369
Generator Name:	Macys Security Square 710159
Generator Location Street Number:	Not reported
Generator Location Street 1:	6901 SECURITY BLVD.
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	ATTN: RECEIVING TEAM LEAD
Generator Mail Street 2:	6901 SECURITY BLVD.
Generator Mail City:	BALTIMORE
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD010154045
Designated Facility Name:	Envirite Of Pennsylvania, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	730 VOGELSONG ROAD
Designated Facility Mail City:	YORK
Designated Facility Mail Zip:	17404
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	730 VOGELSONG ROAD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	YORK
Designated Facility Location Zip:	17404
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	012317419FLE
Last Updated Date:	20191007
Shipped Date:	20190220

MACYS SECURITY SQUARE 710159 (Continued) **1026010568**

Received Date:	20190220
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	Not reported
Generator Name:	Macys Security Square 710159
Generator Location Street Number:	Not reported
Generator Location Street 1:	6901 SECURITY BLVD.
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	ATTN: RECEIVING TEAM LEAD
Generator Mail Street 2:	6901 SECURITY BLVD.
Generator Mail City:	BALTIMORE
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD010154045
Designated Facility Name:	Envirite Of Pennsylvania Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	730 VOGELSONG RD
Designated Facility Mail City:	YORK
Designated Facility Mail Zip:	17404-6707
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	730 VOGELSONG RD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	YORK
Designated Facility Location Zip:	17404-6707
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	012317419FLE
Last Updated Date:	20191007
Shipped Date:	20190220
Received Date:	20190220
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	Not reported
Generator Name:	Macys Security Square 710159
Generator Location Street Number:	Not reported
Generator Location Street 1:	6901 SECURITY BLVD.
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	ATTN: RECEIVING TEAM LEAD
Generator Mail Street 2:	6901 SECURITY BLVD.
Generator Mail City:	BALTIMORE
Generator Mail Zip:	21244

MACYS SECURITY SQUARE 710159 (Continued) **1026010568**

Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD010154045
Designated Facility Name:	Envirite Of Pennsylvania Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	730 VOGELSONG RD
Designated Facility Mail City:	YORK
Designated Facility Mail Zip:	17404-6707
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	730 VOGELSONG RD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	YORK
Designated Facility Location Zip:	17404-6707
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	025479510JJK
Last Updated Date:	20231002
Shipped Date:	20230911
Received Date:	20230914
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDR000516369
Generator Name:	Macys Security Square 710159
Generator Location Street Number:	Not reported
Generator Location Street 1:	6901 SECURITY BLVD.
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	ATTN: RECEIVING TEAM LEAD
Generator Mail Street 2:	6901 SECURITY BLVD.
Generator Mail City:	BALTIMORE
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD010154045
Designated Facility Name:	Envirite Of Pennsylvania, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	730 VOGELSONG ROAD
Designated Facility Mail City:	YORK
Designated Facility Mail Zip:	17404
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	730 VOGELSONG ROAD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	YORK
Designated Facility Location Zip:	17404
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported

MACYS SECURITY SQUARE 710159 (Continued) **1026010568**

Manifest Residue Indicator: N
Rejection Indicator: N

Transporter:
Manifest Tracking Number: 025479510JJK
Transporter Line Number: 1
Transporter EPA ID: MAD084814136
Transporter Name: Eq Northeast, Inc.

Waste Line:
Manifest Tracking Number: 025479510JJK
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: UN1263
U.S. DOT Description: Rq, Un1263, Waste Paint Related Material, 3, Pgii, (Rq:D001), Erg#128
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: DF
Container Type Description: Fiberboard or plastic drums, barrels, kegs
Waste Quantity: 11
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.0055
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.0055
Waste Quantity, in Kilograms: 4.988665
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 4.988665
Management Method Code: H141
Management Method Description: STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y
Federal Waste Codes: D001
Quantity Haz Kg: 4.988665
Quantity Haz Tons: 0.0055
Quantity Non Haz Kg: Not reported
Quantity Non Haz Tons: Not reported
State Waste Codes: Not reported

Manifest Tracking Number: 025479510JJK
Waste Line Number: 2
U.S. DOT Hazardous Indicator: N
U.S. DOT ID Number: Not reported
U.S. DOT Description: Not reported

MACYS SECURITY SQUARE 710159 (Continued) **1026010568**

Non-Hazardous Waste Description:	Non Hazardous Liquid
Number of Containers:	1
Container Type Code:	DF
Container Type Description:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	41
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.0205
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.0205
Waste Quantity, in Kilograms:	18.594116
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	18.594116
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not reported
Quantity Haz Kg:	Not reported
Quantity Haz Tons:	Not reported
Quantity Non Haz Kg:	18.594116
Quantity Non Haz Tons:	0.0205
State Waste Codes:	Not reported

Click this hyperlink while viewing on your computer to access
24 additional US EManifest: record(s) in the EDR Site Report.

A37 **SEARS UNIT #1634** **MD ASBESTOS** **S121458036**
Target **6901 SECURITY SQUARE BLVD.** **N/A**
Property **BALTIMORE, MD 21244**

Site 37 of 45 in cluster A

Actual:
459 ft.

ASBESTOS:

Name:	SEARS UNIT #1634
Address:	6901 SECURITY SQUARE BLVD.
City,State,Zip:	BALTIMORE, MD 21244-
Year:	2017
Removal/Encapsulation/Demolition Start Date:	03/10/2017
Removal/Encapsulation/Demolition End Date:	03/10/2017
Days of the week worked:	M-F
Volume off facility Component (Cat I) not removed:	0 Cubic Yards
Volume off facility Component (Cat I) not removed:	0 Cubic Yards
Volume off facility Component (Cat II) not removed:	0 Cubic Yards
Hours worked in a day:	1000-160
Original or resubmit:	O Origina

SEARS UNIT #1634 (Continued) **S121458036**

Number of floors in building:	2
Pipe Cat I not removed:	0 Linear Feet
Pipe Cat II not removed:	0 Linear Feet
Type of Building:	Commercial
Contractor name:	Bristol Environmental Inc
Length of project:	Not reported
Type of project from notification form:	R-S Renovation (State)
Volume off facility component Cat I non friable removed:	0 Cubic Yards
Pipes Cat I non friable removed:	0 Linear Feet
Surface area Cat I non friable removed:	0 Square Feet
Volume off facility component, Cat II non friable removed:	0 Cubic Yards
Pipe Cat II non friable removed:	0 Linear Feet
Surface area Cat II non friable removed:	0 Square Feet
Volume of facility component RACM removed:	0 Cubic Yards
Pipes RACM removed:	1 Linear Feet
Surface area RACM removed:	0 Square Feet
Surface area Cat I not removed:	0 Square Feet
Surface area Cat II not removed:	0 Square Feet
Site description (found in Section II of the notification):	2nd floor
Owner of the site:	TRUE
Landfill asbestos will be sent to:	TRUE
Transporter of the waste:	TRUE
Facility off components units:	Not reported
Pipes unit of measure:	Linear Feet Linear Feet
Surface area unit of measure:	Square Feet
Received Date:	03/13/2017
Owner name:	Sears Holdings Corp.
Owner contact:	Jacobs
Owner street address:	3333 Beverly Drive
Owner street address 2:	Not reported
Owner city:	Hoffman Estates
Owner state:	IL
Owner zip code:	60179-
ID number:	170577
Contractor:	Not reported
Notification:	Not reported
Asbestos Present:	Not reported
Submitted Date:	Not reported
Creation Date:	Not reported
Created By:	Not reported
MDE Date:	Not reported
Comments:	Not reported
Number Of Workers:	Not reported
Project Supervisor:	Not reported
Project Contact:	Not reported
Project Contact Phone:	Not reported
Last Updated By:	Not reported
Last Updated On:	Not reported

A38 **BURLINGTON** **E MANIFEST** **1027805979**
Target **6901 SECURITY BOULEVARD** **N/A**
Property **BALTIMORE, MD 21244**

Site 38 of 45 in cluster A

Actual:
459 ft.

E MANIFEST:

Manifest Tracking Number:	012455084FLE
Last Updated Date:	20190418
Shipped Date:	20190328
Received Date:	20190403
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Burlington
Generator Location Street Number:	Not reported
Generator Location Street 1:	6901 SECURITY BOULEVARD
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	6901 Security Boulevard
Generator Mail Street 2:	Not reported
Generator Mail City:	Baltimore
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 Sandstone Drive
Designated Facility Mail City:	Hatfield
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	200894856CLE
Last Updated Date:	20240912
Shipped Date:	20240808
Received Date:	20240830
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Burlington
Generator Location Street Number:	Not reported
Generator Location Street 1:	6901 SECURITY BOULEVARD
Generator Location Street 2:	Not reported

BURLINGTON (Continued) **1027805979**

Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	6901 SECURITY BOULEVARD
Generator Mail Street 2:	Not reported
Generator Mail City:	BALTIMORE
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys (Pa) Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 SANDSTONE DRIVE
Designated Facility Mail City:	HATFIELD
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 SANDSTONE DRIVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	HATFIELD
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	010055414FLE
Last Updated Date:	20181107
Shipped Date:	20181011
Received Date:	20181025
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Burlington
Generator Location Street Number:	Not reported
Generator Location Street 1:	6901 SECURITY BOULEVARD
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	4287 Route 130 South
Generator Mail Street 2:	Not reported
Generator Mail City:	Edgewater Park
Generator Mail Zip:	08010
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 Sandstone Drive
Designated Facility Mail City:	Hatfield
Designated Facility Mail Zip:	19440

BURLINGTON (Continued) **1027805979**

Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	200958846CLE
Last Updated Date:	20241118
Shipped Date:	20241009
Received Date:	20241017
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Burlington
Generator Location Street Number:	Not reported
Generator Location Street 1:	6901 SECURITY BOULEVARD
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	6901 SECURITY BOULEVARD
Generator Mail Street 2:	Not reported
Generator Mail City:	BALTIMORE
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys (Pa) Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 SANDSTONE DRIVE
Designated Facility Mail City:	HATFIELD
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 SANDSTONE DRIVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	HATFIELD
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	200958846CLE
Transporter Line Number:	1
Transporter EPA ID:	PAD982661381
Transporter Name:	Republic Env Sys (Trans Group), Llc

BURLINGTON (Continued) **1027805979**

Waste Line:

Manifest Tracking Number:	200958846CLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN1950
U.S. DOT Description:	Un1950, Waste Aerosols, 2.1,Rq(D001=100lbs)
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	BA
Container Type Description:	Burlap, cloth, paper, or plastic bags
Waste Quantity:	7
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.0035
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.0035
Waste Quantity, in Kilograms:	3.17461
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	3.174605
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D001
Quantity Haz Kg:	3.174605
Quantity Haz Tons:	0.0035
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	Not reported

Manifest Tracking Number:	200958846CLE
Waste Line Number:	2
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN1993
U.S. DOT Description:	Un1993, Waste Flammable Liquids, N.O.S. (Petroleum Distillates, Ethyl Alcohol), 3, Pg-Ii
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	CF
Container Type Description:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	16
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.008
Acute Waste Quantity, in Tons:	0

BURLINGTON (Continued) **1027805979**

Non-Acute Waste Quantity, in Tons:	0.008
Waste Quantity, in Kilograms:	7.25624
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	7.25624
Management Method Code:	H061
Management Method Description:	FUEL BLENDING
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D001
Quantity Haz Kg:	7.25624
Quantity Haz Tons:	0.008
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	Not reported
Manifest Tracking Number:	200958846CLE
Waste Line Number:	3
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN3266
U.S. DOT Description:	Un3266, Waste Corrosive Liquid, Basic, Inorganic, N.O.S. (Potassium Hydroxide, Sodium Hypochlorite), 8, Pg-Ii
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	CF
Container Type Description:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	4
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.002
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.002
Waste Quantity, in Kilograms:	1.81406
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	1.81406
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported

BURLINGTON (Continued) **1027805979**

Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D002
Quantity Haz Kg:	1.81406
Quantity Haz Tons:	0.002
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	Not reported
Manifest Tracking Number:	200958846CLE
Waste Line Number:	4
U.S. DOT Hazardous Indicator:	N
U.S. DOT ID Number:	Not reported
U.S. DOT Description:	Not reported
Non-Hazardous Waste Description:	Material Not Regulated By D.O.T. (Washington State Dangerous Waste Only, Toxic) (Water Based Cleaners, Latex Paint)
Number of Containers:	1
Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	113
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.0565
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.0565
Waste Quantity, in Kilograms:	51.2472
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	51.247195
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not reported
Quantity Haz Kg:	0
Quantity Haz Tons:	0
Quantity Non Haz Kg:	51.247195
Quantity Non Haz Tons:	0.0565
State Waste Codes:	Not reported

A39
Target
Property

SEARS ROEBUCK - SECURITY SQUARE
6901 SECURITY BOULEVARD
WOODLAWN, MD 21207

FINDS **1007823170**
N/A

Site 39 of 45 in cluster A

Actual:
459 ft.

FINDS:
Registry ID: 110019858732

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Maryland Permanent Emission (MD-PEMIS) database houses data related to air emissions.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

A40
Target
Property

SEARS ROEBUCK & COMPANY
6901 SECURITY BLVD
GWYNN OAK, MD 21207

MD HIST UST **S104634671**
N/A

Site 40 of 45 in cluster A

Actual:
459 ft.

Historical UST:
Facility ID: 3013156
Tank ID: 001
Age: 23
Capacity: 550
Tank Status: Removed
Product: Used Oil

A41
Target
Property

MACYS SECURITY SQUARE
6901 SECURITY BLVD
WINDSOR MILL, MD 21244

RCRA NonGen / NLR **1031784882**
MDR000516369

Site 41 of 45 in cluster A

Actual:
459 ft.

RCRA Listings:

Date Form Received by Agency:	20250411
Handler Name:	Macys Security Square
Handler Address:	6901 Security Blvd
Handler City,State,Zip:	WINDSOR MILL, MD 21244
EPA ID:	MDR000516369
Contact Name:	MONICA NG
Contact Address:	237 WOODBRIDGE CENTER DR
Contact City,State,Zip:	WOODBRIDGE, NJ 07095
Contact Telephone:	732-439-7300
Contact Fax:	Not reported
Contact Email:	MONICA.Y.NG@MACYS.COM
Contact Title:	DISTRICT FACILITY MNGR
EPA Region:	03
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported

MACYS SECURITY SQUARE (Continued) **1031784882**

Mailing Address:		237 WOODBRIDGE CENTER DR
Mailing City,State,Zip:		WOODBRIDGE, NJ 07095
Owner Name:	Macys	
Owner Type:		Private
Operator Name:	Macys	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20250505
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: MACYS	
Legal Status:	Private

MACYS SECURITY SQUARE (Continued) **1031784882**

Date Became Current:	19790815
Date Ended Current:	Not reported
Owner/Operator Address:	151 W 34TH ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10001-2101
Owner/Operator Telephone:	732-439-7300
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	ENVIRONMENTAL@MACYS.COM
Owner/Operator Indicator:	Operator
Owner/Operator Name: MACYS	
Legal Status:	Private
Date Became Current:	19790815
Date Ended Current:	Not reported
Owner/Operator Address:	151 W 34TH ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10001-2101
Owner/Operator Telephone:	732-439-7300
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	ENVIRONMENTAL@MACYS.COM
Owner/Operator Indicator:	Owner
Owner/Operator Name: MACYS	
Legal Status:	Private
Date Became Current:	19790815
Date Ended Current:	Not reported
Owner/Operator Address:	151 W 34TH ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10001-2101
Owner/Operator Telephone:	732-439-7300
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	ENVIRONMENTAL@MACYS.COM
Owner/Operator Indicator:	Operator
Owner/Operator Name: MACY'S EAST #159	
Legal Status:	Private
Date Became Current:	20061026
Date Ended Current:	Not reported
Owner/Operator Address:	6901 SECURITY BLVD
Owner/Operator City,State,Zip:	BALTIMORE, MD 21244
Owner/Operator Telephone:	410-944-8040
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: MACYS	
Legal Status:	Private
Date Became Current:	19790815
Date Ended Current:	Not reported
Owner/Operator Address:	151 W 34TH ST
Owner/Operator City,State,Zip:	NEW YORK, NY 10001-2101
Owner/Operator Telephone:	732-439-7300
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	ENVIRONMENTAL@MACYS.COM

MACYS SECURITY SQUARE (Continued) **1031784882**

Historic Generators:

Receive Date:		20250411
Handler Name:	MACYS SECURITY SQUARE	
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		Not reported
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		Yes
Non Storage Recycler Activity:		No
Electronic Manifest Broker:		No

Receive Date:		20061016
Handler Name:	MACY'S EAST #159	
Federal Waste Generator Description:		Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner:		Not reported
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20250226
Handler Name:	MACYS SECURITY SQUARE	
Federal Waste Generator Description:		Small Quantity Generator
State District Owner:		Not reported
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		No
Electronic Manifest Broker:		No

List of NAICS Codes and Descriptions:

NAICS Code:	45211
NAICS Description:	Department Stores

NAICS Code:	45511
NAICS Description:	Department Stores

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

A42 **SEARS** **E MANIFEST** **1031592653**
Target **6901 SECURITY SQ BLVD** **N/A**
Property **BALTIMORE-WEST, MD 21244**

Site 42 of 45 in cluster A

Actual:
459 ft.

E MANIFEST:

Manifest Tracking Number:	013392105FLE
Last Updated Date:	20200109
Shipped Date:	20191112
Received Date:	20191126
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDR000015511
Generator Name:	Sears
Generator Location Street Number:	Not reported
Generator Location Street 1:	6901 SECURITY SQ BLVD
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE-WEST
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	6901 Security Sq Blvd
Generator Mail Street 2:	Not reported
Generator Mail City:	Baltimore-West
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 Sandstone Drive
Designated Facility Mail City:	Hatfield
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	012452549FLE
Last Updated Date:	20200107
Shipped Date:	20190808
Received Date:	20190816
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDR000015511
Generator Name:	Sears
Generator Location Street Number:	Not reported
Generator Location Street 1:	6901 SECURITY SQ BLVD
Generator Location Street 2:	Not reported

SEARS (Continued) **1031592653**

Generator Location City:	BALTIMORE-WEST
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	6901 Security Sq Blvd
Generator Mail Street 2:	Not reported
Generator Mail City:	Baltimore-West
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 Sandstone Drive
Designated Facility Mail City:	Hatfield
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	012452549FLE
Transporter Line Number:	1
Transporter EPA ID:	PAD982661381
Transporter Name:	Republic Environmental Systems Transportation Group Llc
Manifest Tracking Number:	012452549FLE
Transporter Line Number:	2
Transporter EPA ID:	PAD982661381
Transporter Name:	Republic Environmental Systems Transportation Group Llc

Waste Line:

Manifest Tracking Number:	012452549FLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	N
U.S. DOT ID Number:	Not reported
U.S. DOT Description:	Not reported
Non-Hazardous Waste Description:	Non-Hazardous, Non-Regulated Liquids & Solids
Number of Containers:	1
Container Type Code:	BA
Container Type Description:	Burlap, cloth, paper, or plastic bags
Waste Quantity:	8
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.004
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.004
Waste Quantity, in Kilograms:	3.6281202

SEARS (Continued) **1031592653**

Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	3.6281202
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not reported
Quantity Haz Kg:	0
Quantity Haz Tons:	0
Quantity Non Haz Kg:	3.6281202
Quantity Non Haz Tons:	0.004
State Waste Codes:	Not reported

A43 **MACY'S** **MD OCPCASES** **S121712469**
Target **6901 SECURITY BLVD** **N/A**
Property **BALTIMORE, MD 21207**

Site 43 of 45 in cluster A

Actual: **459 ft.**

OCPCASES:

Name:	MACY'S
Address:	6901 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21207
Facility ID:	13-0249BA
Facility Status/Code:	CLOSED/Tank Closure - Motor/Lube Oil
Date Open:	10/26/2012
Date Closed:	05/02/2013
Release:	NO
Cleanup:	NO
Registration Number:	6267

A44 **JC PENNEY CO.** **MD UST** **U004445634**
Target **6901 SECURITY BLVD** **MD Financial Assurance** **N/A**
Property **BALTIMORE, MD 21207**

Site 44 of 45 in cluster A

Actual: **459 ft.**

UST:

Facility Id:	16393
Oper Name:	Randy Chambers
Form Name:	Dewayne R. Brown
Form Title:	District Maint. Rep
Form Date:	07/20/1993
Owner Id:	10912

JC PENNEY CO. (Continued) **U004445634**

Owner:
- Owner Name: JC Penny Co.
- Owner Address: 6901 Security Blvd
- Owner City: Baltimore
- Owner State: MD
- Owner Zip: 21207
- Owner Phone: (410) 298-8100
- Owner Contact: Randy Chambers

Tanks:
- Tank ID: 1
- **Tank Status: Permanently Out of Use**
- Tank Capacity: 10000
- Substance Description: Heating Oil
- Tank Compartment: False
- Compartment Compartment: A
- Date Installed: 07/01/1975
- Tank Material Desc: Fiberglass Reinforced Plastic
- Pipe Material Desc: Not Listed

MD Financial Assurance 2:
- Name: JC PENNEY CO.
- Address: 6901 SECURITY BLVD
- City,State,Zip: BALTIMORE, MD 21207
- Region: 2
- Facility ID: 16393
- Self Insured: False
- Insurance: False
- Risk Retention Group: False
- Guarantee: False
- Surety Bonds: False
- Letter of Credit: False
- State Fund: False
- Other Finance: False
- Finacnce Comments: Not reported
- FR Not Listed: False

A45 **BRIDGESTONE/FIRESTONE** **MD UST** **U004445739**
Target Property **6901 SECURITY BLVD.** **MD Financial Assurance** **N/A**
BALTIMORE, MD 21244

Site 45 of 45 in cluster A

Actual: 459 ft.

UST:
- Facility Id: 5743
- Oper Name: Randy Chambers
- Form Name: Mark Harris
- Form Title: Owner's Rep
- Form Date: 08/12/2015
- Owner Id: 14833

Owner:
- Owner Name: Blue Ocean Realty
- Owner Address: 6609 Reisterstown Rd
- Owner City: Baltimore
- Owner State: MD

BRIDGESTONE/FIRESTONE (Continued) **U004445739**

Owner Zip: 21215
Owner Phone: (443) 278-9302
Owner Contact: Jonathan Ehrenfeld

Tanks:
Tank ID: 1
Tank Status: Permanently Out Of Use
Tank Capacity: 6000
Substance Description: Heating Oil
Tank Compartment: False
Compartment Compartment: A
Date Installed: 01/01/1995
Tank Material Desc: Fiberglass Reinforced Plastic
Pipe Material Desc: Copper

Tank ID: 2
Tank Status: Permanently Out Of Use
Tank Capacity: 550
Substance Description: Used Oil
Tank Compartment: False
Compartment Compartment: A
Date Installed: Not reported
Tank Material Desc: Asphalt Coated or Bare Steel
Pipe Material Desc: Bare or Galvanized Steel

MD Financial Assurance 2:
Name: BRIDGESTONE/FIRESTONE
Address: 6901 SECURITY BLVD.
City,State,Zip: BALTIMORE, MD 21244
Region: 2
Facility ID: 5743
Self Insured: True
Insurance: False
Risk Retention Group: False
Guarantee: False
Surety Bonds: False
Letter of Credit: False
State Fund: False
Other Finance: False
Finacnce Comments: Not reported
FR Not Listed: False

B46 **CARE CLEANERS** **MD DRYCLEANERS S106489031**
7005 SECURITY BOULEVARD **MD NPDES N/A**
< 1/8 **WOODLAWN, MD 21244**
1 ft.

Site 1 of 10 in cluster B

Relative: Lower
Actual: 443 ft.

Drycleaners:
Name: CARE CLEANERS
Address: 7005 SECURITY BOULEVARD
City,State,Zip: WOODLAWN, MD 21244
Facility ID: 005-2451
SIC Code: 7216
Fstatus Decode: Inactive
Facility Status: Inactive

CARE CLEANERS (Continued) **S106489031**

NPDES:

Name:	Weis Gas N Go #229
Address:	7005 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244
Facility Status:	Not reported
Bay Trib Number:	Not reported
Watershed:	Not reported
Permit Type:	Not reported
Description:	Not reported
Sic Number:	Not reported
Permit Number:	Not reported
Npdes Number:	Not reported
App Description:	Not reported
Latitude/Longitude:	Not reported
Last Issued:	Not reported
Expiration Date:	Not reported
Owner Name:	Not reported
Owner Address:	Not reported
Owner Address 2:	Not reported
Owner City:	Not reported
Owner State:	Not reported
Owner Zip:	Not reported
Received:	Received_March2015
Comments:	Application received for Gp for (1) Motor Vehicle Refinishing Autobody
AI ID:	Not reported
Address 2:	Not reported
SIC Description:	Not reported
SIC Code2:	Not reported
SIC Description 2:	Not reported
SIC Code 3:	Not reported
SIC Description 3:	Not reported
Status Date:	Not reported
State Number:	Not reported
Approval Issued Date:	Not reported
Effective End Date:	Not reported

B47 **WEIS GAS N' GO** **MD OCPCASES** **S118504989**
7005 SECURITY BLVD **N/A**
< 1/8 **BALTIMORE, MD 21244**
1 ft.

Site 2 of 10 in cluster B

Relative: Lower
Actual: 443 ft.

OCPCASES:

Name:	WEIS GAS N' GO
Address:	7005 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244
Facility ID:	15-0686BA
Facility Status/Code:	CLOSED/New Installation - Motor/Lube Oil
Date Open:	05/21/2015
Date Closed:	08/05/2016
Release:	NO
Cleanup:	NO
Registration Number:	20550

B48 **CARE CLEANERS** **RCRA NonGen / NLR** **1004720153**
7005 SECURITY BOULEVARD **FINDS** **MDR000001776**
< 1/8 **BALTIMORE, MD 21244** **ECHO**
1 ft.

Site 3 of 10 in cluster B

Relative: **Lower**
Actual: **443 ft.**

RCRA Listings:

Date Form Received by Agency:		19950327
Handler Name:		Hechinger #66
Handler Address:		7005 Security Blvd
Handler City,State,Zip:		BALTIMORE, MD 21207
EPA ID:		MDR000001776
Contact Name:		DEBBIE FOX
Contact Address:		1801 MC CORMICK DR
Contact City,State,Zip:		LANDOVER, MD 20785
Contact Telephone:		301-925-3496
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		03
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		1801 MC CORMICK DR
Mailing City,State,Zip:		LANDOVER, MD 20785
Owner Name:	Hechinger	
Owner Type:		Private
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No

CARE CLEANERS (Continued) **1004720153**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140421
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D003
Waste Description:	Reactive Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: HECHINGER	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1801 MC CORMICK DR
Owner/Operator City,State,Zip:	LANDOVER, MD 20785
Owner/Operator Telephone:	301-925-3496
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19950327
Handler Name: HECHINGER #66	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

CARE CLEANERS (Continued) **1004720153**

NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110003539369

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.
Registry ID: 110006838093

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Maryland's Resource Conservation and Recovery Act (RCRA) database houses data related to hazardous waste.
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.
The Maryland Permanent Emission (MD-PEMIS) database houses data related to air emissions.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004720153
Registry ID: 110006838093

DFR URL:
Name: CARE CLEANERS
Address: 7005 Security Boulevard
City,State,Zip: BALTIMORE, MD 21244

Envid: 1004720153
Registry ID: 110003539369

DFR URL:
Name: HECHINGER #66
Address: 7005 Security Blvd

CARE CLEANERS (Continued) **1004720153**

City,State,Zip: BALTIMORE, MD 21207

B49 **WEIS GAS N' GO #229** **UST FINDER** **1028409306**
7005 SECURITY BLVD. **N/A**
< 1/8 **WINDSOR MILL, MD 21244**
1 ft.

Site 4 of 10 in cluster B

Relative: **Lower**
Actual: **443 ft.**

UST FINDER:

Object ID:	642817
Facility ID:	MD20550
Name:	WEIS GAS N' GO #229
Address:	7005 SECURITY BLVD.
City,State,Zip:	WINDSOR MILL, MD 21244
Address Match Type:	StreetAddress
Open USTs:	2
Closed USTs:	0
TOS USTs:	0
Population 1500ft:	588
Private Wells 1500ft:	4
Within 100yr Floodplain:	No
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	3
Tribe:	Not reported
Coordinate Source:	Geocode
X Coord:	-76.75252729
Y Coord:	39.3127559800001
Latitude:	39.31275598
Longitude:	-76.75252729

UST FINDER:

Object ID:	727719
Facility ID:	MD20550
Tank ID:	MD20550_1
Tank Status:	Open
Installation Date:	2015/05/21 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	Not reported
Substances:	Gasohol
Tank Wall Type:	Double

Object ID:	727720
Facility ID:	MD20550
Tank ID:	MD20550_2
Tank Status:	Open
Installation Date:	2015/05/21 15:59:59+00

WEIS GAS N' GO #229 (Continued) **1028409306**

Removal Date:	Not reported
Tank Capacity:	5000
Substances:	Gasohol
Tank Wall Type:	Double

B50 **CARE CLEANERS** **EDR Hist Cleaner** **1019948871**
7005 SECURITY BLVD **N/A**
< 1/8 **BALTIMORE, MD 21244**
1 ft.

Site 5 of 10 in cluster B

Relative: EDR Hist Cleaner
Lower

Actual: **443 ft.**

Year:	Name:	Type:
2004	CARE CLEANERS	Drycleaning Plants, Except Rugs
2005	CARE CLEANERS	Drycleaning Plants, Except Rugs
2006	CARE CLEANERS	Drycleaning Plants, Except Rugs
2007	CARE CLEANERS	Drycleaning Plants, Except Rugs
2010	CARE CLEANERS	Drycleaning Plants, Except Rugs

B51 **WEIS MARKET** **E MANIFEST** **1031665789**
7005 SECURITY BLVD **N/A**
< 1/8 **WINDSOR MILL, MD 21244**
1 ft.

Site 6 of 10 in cluster B

Relative: E MANIFEST:
Lower

Actual: **443 ft.**

Manifest Tracking Number:	026931716JJK
Last Updated Date:	20240906
Shipped Date:	20240724
Received Date:	20240725
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	Not reported
Generator Name:	Weis Market
Generator Location Street Number:	Not reported
Generator Location Street 1:	7005 SECURITY BLVD
Generator Location Street 2:	Not reported
Generator Location City:	WINDSOR MILL
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	7005 SECURITY BLVD
Generator Mail Street 2:	Not reported
Generator Mail City:	WINDSOR MILL
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD067098822
Designated Facility Name:	Cycle Chem, Inc.
Designated Facility Mail Street Number:	550
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	INDUSTRIAL DRIVE
Designated Facility Mail City:	LEWISBERRY

WEIS MARKET (Continued) **1031665789**

Designated Facility Mail Zip:	17339
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	550
Designated Facility Location Street 1:	INDUSTRIAL DRIVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	LEWISBERRY
Designated Facility Location Zip:	17339
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	026931716JJK
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Acv Environmental Services Inc.

Waste Line:

Manifest Tracking Number:	026931716JJK
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN1203
U.S. DOT Description:	Un1203, Waste, Gasoline, 3, Pgii, Erg#128
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	650
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.325
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.325
Waste Quantity, in Kilograms:	294.78475
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	294.78475
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D001, D018
Quantity Haz Kg:	294.78475
Quantity Haz Tons:	0.325

WEIS MARKET (Continued) **1031665789**

Quantity Non Haz Kg: 0
Quantity Non Haz Tons: 0
State Waste Codes: Not reported

B52 **WEIS GAS N' GO #229** **MD UST** **U004248606**
7005 SECURITY BLVD. **MD Financial Assurance** **N/A**
< 1/8 **WINDSOR MILL, MD 21244**
1 ft.

Site 7 of 10 in cluster B

Relative: Lower
Actual: 443 ft.

UST:
Facility Id: 20550
Oper Name: John T. Lerch
Form Name: Madelynn Barton
Form Title: Gas Attendant
Form Date: 02/18/2022
Owner Id: 10554

Owner:
Owner Name: Weis Markets, Inc.
Owner Address: PO Box 471
Owner City: Sunbury
Owner State: PA
Owner Zip: 17801
Owner Phone: (570) 274-7010
Owner Contact: John T. Lerch

Tanks:
Tank ID: 1
Tank Status: **Currently In Use**
Tank Capacity: Not reported
Substance Description: Gasohol
Tank Compartment: False
Compartment Compartment: A
Date Installed: 05/21/2015
Tank Material Desc: Composite (Steel w/ FRP)
Pipe Material Desc: Flexible Plastic

Tank ID: 2
Tank Status: **Currently In Use**
Tank Capacity: 5000
Substance Description: Gasohol
Tank Compartment: True
Compartment Compartment: B
Date Installed: 05/21/2015
Tank Material Desc: Composite (Steel w/ FRP)
Pipe Material Desc: Flexible Plastic

Tank ID: 2
Tank Status: **Currently In Use**
Tank Capacity: 10000
Substance Description: Gasohol
Tank Compartment: True
Compartment Compartment: A
Date Installed: 05/21/2015
Tank Material Desc: Composite (Steel w/ FRP)
Pipe Material Desc: Fiberglass Reinforced Plastic

WEIS GAS N' GO #229 (Continued) **U004248606**

MD Financial Assurance 2:

Name:	WEIS GAS N' GO #229
Address:	7005 SECURITY BLVD.
City,State,Zip:	WINDSOR MILL, MD 21244
Region:	2
Facility ID:	20550
Self Insured:	False
Insurance:	True
Risk Retention Group:	False
Guarantee:	False
Surety Bonds:	False
Letter of Credit:	False
State Fund:	False
Other Finance:	False
Finacnce Comments:	Policy # G24552329 010 Insurer: Illinois Union Ins. Co. Policy Period: 4/1/2021 - 4/1/2022 (cel)
FR Not Listed:	False

B53 **MACYS INC** **PA MANIFEST** **S111770927**
6975 SECURITY BLVD **N/A**
< 1/8 **BALTIMORE, MD 21244**
0.000 mi.
2 ft. **Site 8 of 10 in cluster B**

Relative: PA MANIFEST:
Lower

Actual: Name:	MACYS INC
445 ft. Address:	6975 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244
Year:	2010
Manifest Number:	003528495FLE
Manifest Type:	T
Generator EPA ID:	MDP000016969
Generator Date:	07/02/2010
Mailing Address:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA ID:	PAD085690592
TSD Date:	Not reported
TSD Facility Name:	REPUBLIC ENVIRONMENTAL SYSTEMS OF PA INC
TSD Facility Address:	2869 SANDSTONE DRIVE
TSD Facility City:	HATFIELD
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	NONE
Container Number:	1
Container Type:	CF
Waste Quantity:	50
Unit:	P
Handling Code:	Not reported
TSP EPA ID:	Not reported
Date TSP Sig:	Not reported
Year:	2010
Manifest Number:	003528495FLE
Manifest Type:	T

MACYS INC (Continued) **S111770927**

Generator EPA ID:	MDP000016969
Generator Date:	07/02/2010
Mailing Address:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA ID:	PAD085690592
TSD Date:	Not reported
TSD Facility Name:	REPUBLIC ENVIRONMENTAL SYSTEMS OF PA INC
TSD Facility Address:	2869 SANDSTONE DRIVE
TSD Facility City:	HATFIELD
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D001
Container Number:	1
Container Type:	CF
Waste Quantity:	50
Unit:	P
Handling Code:	Not reported
TSP EPA ID:	Not reported
Date TSP Sig:	Not reported

B54 **FIRESTONE** **MD OCPCASES** **S104606165**
6921 SECURITY BLVD **N/A**
< 1/8 **WOODLAWN, MD 21244**
0.001 mi.
3 ft. **Site 9 of 10 in cluster B**

Relative: **Lower**
Actual: **445 ft.**

OCPCASES:

Name:	FIRESTONE
Address:	6921 SECURITY BLVD
City,State,Zip:	WOODLAWN, MD 21244
Facility ID:	95-1429BA2
Facility Status/Code:	CLOSED/Transfer Accident Motor/Lube Oil
Date Open:	12/13/1994
Date Closed:	12/19/1994
Release:	Not reported
Cleanup:	Not reported
Registration Number:	Not reported

---

55 **HOUSEHOLD BANK** **MD OCPCASES** **S108471605**
SW **1700 ROLLING RD** **N/A**
< 1/8 **WOODLAWN, MD 21244**
0.012 mi.
63 ft.

Relative: **Higher**
Actual: **467 ft.**

OCPCASES:

Name:	HOUSEHOLD BANK
Address:	1700 ROLLING RD
City,State,Zip:	WOODLAWN, MD 21244
Facility ID:	7-0763BA2
Facility Status/Code:	CLOSED/
Date Open:	10/24/1986
Date Closed:	11/07/1986
Release:	Not reported

HOUSEHOLD BANK (Continued) **S108471605**

Cleanup: Not reported
Registration Number: Not reported

B56 **RUPERT LILY-DRIVER** **MD OCPCASES** **S104598929**
North **SECURITY BLVD & BELMONT AVE** **N/A**
< 1/8 **WOODLAWN, MD 21244**
0.013 mi.
66 ft. **Site 10 of 10 in cluster B**

Relative: OCPCASES:
Lower
Name: RUPERT LILY-DRIVER
Actual: Address: SECURITY BLVD & BELMONT AVE
445 ft. City,State,Zip: WOODLAWN, MD 21244
Facility ID: 96-1410BA2
Facility Status/Code: CLOSED/Tank Truck Driver Attendance - Motor /Lube Oil
Date Open: 01/25/1996
Date Closed: 01/25/1996
Release: Not reported
Cleanup: Not reported
Registration Number: Not reported

C57 **DIAMOND CLEANERS** **MD MANIFEST** **S121870825**
SW **1732 N. ROLLING ROAD** **N/A**
< 1/8 **BALTIMORE, MD 21244**
0.015 mi.
78 ft. **Site 1 of 4 in cluster C**

Relative: MD MANIFEST:
Lower
EPAID: MDR000005900
Actual: Name: DIAMOND CLEANERS
454 ft. Address: 1732 N. ROLLING ROAD
City,State,Zip: BALTIMORE, MD 21244
Manifest Number: 015263767JJK
Transporter 1: MCF SYSTEMS ATLANTA, INC.
Transporter 2: MCF ENVIRONMENTAL SERVICES, INC.
Generator Certifier: SUNG IM HAN
Date Shipped Out: 03/01/2016
Destination Facility Certifier: GASHTASEB GHOLIPOUR
Date Arrived at Destingation Facility: 03/18/2016
Quantity: 150
Unit: Pounds

EPAID: MDR000005900
Name: DIAMOND CLEANERS
Address: 1732 N. ROLLING ROAD
City,State,Zip: BALTIMORE, MD 21244
Manifest Number: 015213880JJK
Transporter 1: MCF SYSTEMS ATLANTA INC
Transporter 2: MCF ENVIRONMENTAL SERVICES INC
Generator Certifier: SUNG IM HAN
Date Shipped Out: 12/03/2015
Destination Facility Certifier: GASHTASEB GHOLIPOUR
Date Arrived at Destingation Facility: 12/11/2015
Quantity: 150
Unit: POUNDS

DIAMOND CLEANERS (Continued) **S121870825**

EPAID: MDR000005900
Name: DIAMOND CLEANERS
Address: 1732 N. ROLLING ROAD
City,State,Zip: BALTIMORE, MD 21244
Manifest Number: 015214237JJK
Transporter 1: MCF SYSTEMS ATLANTA, INC.
Transporter 2: MCF ENVIRONMENTAL SERVICES, INC.
Generator Certifier: SUNG LM HAM
Date Shipped Out: 01/20/2016
Destination Facility Certifier: GASHTASEB GHOLIPOUR
Date Arrived at Destingation Facility: 02/01/2016
Quantity: 150
Unit: Pounds

EPAID: MDR000005900
Name: DIAMOND CLEANERS
Address: 1732 N. ROLLING ROAD
City,State,Zip: BALTIMORE, MD 21244
Manifest Number: 015445379JJK
Transporter 1: MCF SYSTEMS ATLANTA, INC.
Transporter 2: MCF ENVIRONMENTAL SERVICES, INC.
Generator Certifier: SUNG IM HAN
Date Shipped Out: 05/24/2016
Destination Facility Certifier: BAHRAM NAJAFI
Date Arrived at Destingation Facility: 06/03/2016
Quantity: 150
Unit: Pounds

EPAID: MDR000005900
Name: DIAMOND CLEANERS
Address: 1732 N. ROLLING ROAD
City,State,Zip: BALTIMORE, MD 21244
Manifest Number: 013702561JJK
Transporter 1: MCF SYSTEMS ATLANTA, INC.
Transporter 2: MCF ENVIRONMENTAL SERVICES, INC.
Generator Certifier: SUNG HAN
Date Shipped Out: 03/03/2015
Destination Facility Certifier: MARK CASSABON
Date Arrived at Destingation Facility: 03/11/2015
Quantity: 150
Unit: POUNDS

EPAID: MDR000005900
Name: DIAMOND CLEANERS
Address: 1732 N. ROLLING ROAD
City,State,Zip: BALTIMORE, MD 21244
Manifest Number: 014074597JJK
Transporter 1: MCF SYSTEMS ATLANTA INC
Transporter 2: MCF ENVIRONMENTAL SERVICES INC
Generator Certifier: SUNG IM HAN
Date Shipped Out: 05/27/2015
Destination Facility Certifier: JAMES P. CARNEY
Date Arrived at Destingation Facility: 06/03/2015
Quantity: 150
Unit: POUNDS

EPAID: MDR000005900

DIAMOND CLEANERS (Continued) **S121870825**

Name:	DIAMOND CLEANERS
Address:	1732 N. ROLLING ROAD
City,State,Zip:	BALTIMORE, MD 21244
Manifest Number:	014330525JJK
Transporter 1:	MCF SYSTEMS ATLANTA INC
Transporter 2:	MCF ENVIRONMENTAL SERVICES INC
Generator Certifier:	SUNG IM HAN
Date Shipped Out:	04/14/2015
Destination Facility Certifier:	MARK CASSABON
Date Arrived at Destingation Facility:	04/22/2015
Quantity:	150
Unit:	POUNDS

EPAID:	MDR000005900
Name:	DIAMOND CLEANERS
Address:	1732 N. ROLLING ROAD
City,State,Zip:	BALTIMORE, MD 21244
Manifest Number:	014419843JJK
Transporter 1:	MCF SYSTEMS ATLANTIC, INC
Transporter 2:	MCF ENVIRONMENTAL SERVICES INC
Generator Certifier:	SUNG IM HAN
Date Shipped Out:	08/25/2015
Destination Facility Certifier:	Not reported
Date Arrived at Destingation Facility:	Not reported
Quantity:	150
Unit:	P

C58 **DIAMOND CLEANERS** **MD DRYCLEANERS** **S117068266**
SW **1732 NORTH ROLLING ROAD** **N/A**
< 1/8 **WINDSOR MILL, MD 21244**
0.015 mi.
78 ft. **Site 2 of 4 in cluster C**

Relative: Drycleaners:
Lower

Name:	DIAMOND CLEANERS
Address:	1732 NORTH ROLLING ROAD
City,State,Zip:	WINDSOR MILL, MD 21244
Facility ID:	005-2809
SIC Code:	7216
Fstatus Decode:	Active
Facility Status:	Active

Actual:
454 ft.

C59 **DIAMOND CLEANERS INC** **EDR Hist Cleaner** **1019972473**
SW **1732 N ROLLING RD** **N/A**
< 1/8 **BALTIMORE, MD 21244**
0.015 mi.
78 ft. **Site 3 of 4 in cluster C**

Relative: EDR Hist Cleaner
Lower

Actual:
454 ft.

Year:	Name:	Type:
1993	DIAMOND CLEANERS	Drycleaning Plants, Except Rugs
1994	DIAMOND CLEANERS INC	Drycleaning Plants, Except Rugs
1995	DIAMOND CLEANERS INC	Drycleaning Plants, Except Rugs
1996	DIAMOND CLEANERS INC	Drycleaning Plants, Except Rugs
1997	DIAMOND CLEANERS INC	Drycleaning Plants, Except Rugs

DIAMOND CLEANERS INC (Continued) **1019972473**

1998	DIAMOND CLEANERS INC	Drycleaning Plants, Except Rugs
1999	DIAMOND CLEANERS INC	Drycleaning Plants, Except Rugs
2000	DIAMOND CLEANERS INC	Drycleaning Plants, Except Rugs
2001	DIAMOND CLEANERS INC	Drycleaning Plants, Except Rugs
2002	DIAMOND CLEANERS INC	Drycleaning Plants, Except Rugs
2003	DIAMOND CLEANERS INC	Drycleaning Plants, Except Rugs
2004	DIAMOND CLEANERS INC	Drycleaning Plants, Except Rugs
2005	DIAMOND CLEANERS INC	Drycleaning Plants, Except Rugs
2006	DIAMOND CLEANERS INC	Drycleaning Plants, Except Rugs
2007	DIAMOND CLEANERS INC	Drycleaning Plants, Except Rugs
2008	DIAMOND CLEANERS INC	Drycleaning Plants, Except Rugs
2009	DIAMOND CLEANERS INC	Drycleaning Plants, Except Rugs
2010	DIAMOND CLEANERS INC	Drycleaning Plants, Except Rugs
2011	DIAMOND CLEANERS INC	Drycleaning Plants, Except Rugs
2012	DIAMOND CLEANERS INC	Drycleaning Plants, Except Rugs
2013	DIAMOND CLEANERS INC	Drycleaning Plants, Except Rugs
2014	DIAMOND CLEANERS INC	Drycleaning Plants, Except Rugs

C60 **DIAMOND CLEANERS** **RCRA-VSQG** **1004720430**
SW **1732 N ROLLING RD** **FINDS** **MDR000005900**
< 1/8 **BALTIMORE, MD 21244** **ECHO**
0.015 mi. **RI MANIFEST**
78 ft. **Site 4 of 4 in cluster C**

Relative: **Lower**
Actual: **454 ft.**

RCRA Listings:

Date Form Received by Agency:		19950921
Handler Name:		Diamond Cleaners
Handler Address:		1732 N Rolling Rd
Handler City,State,Zip:		BALTIMORE, MD 21244
EPA ID:		MDR000005900
Contact Name:		SUNG HAN
Contact Address:		1732 N ROLLING RD
Contact City,State,Zip:		BALTIMORE, MD 21244
Contact Telephone:		410-265-1133
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		03
Land Type:		Private
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		1732 N ROLLING RD
Mailing City,State,Zip:		BALTIMORE, MD 21244
Owner Name:	Sung Han	
Owner Type:		Private
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No

DIAMOND CLEANERS (Continued) **1004720430**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20180130
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: SUNG HAN	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1732 N ROLLING RD
Owner/Operator City,State,Zip:	BALTIMORE, MD 21244

DIAMOND CLEANERS (Continued) **1004720430**

Owner/Operator Telephone: 410-265-1133
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19950921
Handler Name: DIAMOND CLEANERS
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 81232
NAICS Description: Drycleaning And Laundry Services (Except Coin-Operated)

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110003541178

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Maryland's Resource Conservation and Recovery Act (RCRA) database houses data related to hazardous waste.
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.
MD-TEMPO is Maryland's central repository for all facility data and includes permits, compliance, enforcement activities information needed to ensure the quality of Maryland's air, water, and land resources.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many

DIAMOND CLEANERS (Continued) **1004720430**

types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004720430
Registry ID:	110003541178
DFR URL:	
Name:	DIAMOND CLEANERS
Address:	1732 N Rolling Rd
City,State,Zip:	BALTIMORE, MD 21244

RI MANIFEST:

Name:	DIAMOND CLEANERS
Address:	1732 N ROLLING RD
City,State,Zip:	BALTIMORE, MD 21244
EPA Id:	MDR000005900
GEN Cert Date:	11/13/2012
Manifest Document Number:	010013607JJK
Waste Description:	TETRACHLOROETHYLENE
TSDF Id:	RID084802842
TSDF Name:	SAFETY KLEEN
Qty:	150
WT/Vol Units:	P
TSDF Date:	11/16/2012
Transporter 2 Id:	NJD071629976
Item Number:	1
Transporter 2 Name:	11/16/2012
Transporter Name 2:	MCF SYSTEMS ATLANTA INC
Transporter EPAID:	GAR000060905
Transporter Receipt Date:	11/13/2012
Number Of Containers:	1
Container Type:	DF
Waste Code1:	D039
Waste Code2:	F002
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Fee Exempt Code:	Not reported
Comment:	Not reported
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
Quarter:	Not reported
Transporter Contact Name:	Not reported
Transporter Contact Email:	Not reported
Filing Date:	Not reported
Total Fee:	Not reported
Billing Name:	Not reported
Paid Date:	Not reported
Paid Time:	Not reported
Facility Receipt Date:	Not reported
Fee:	Not reported

DIAMOND CLEANERS (Continued) **1004720430**

Manifest Created Date:	Not reported
Manifest Updated Date:	Not reported

RI MANIFEST:

Transporter Receipt Date:	11/13/2012
Number Of Containers:	1
Container Type:	DF
Waste Code1:	D039
Waste Code2:	F002
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	MDR000005900
Manifest Docket Number:	010013607JJK
Quarter:	Not reported
Waste Description:	TETRACHLOROETHYLENE
Transporter Contact Name:	Not reported
Quantity:	150
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	MCF SYSTEMS ATLANTA INC
Billing Name:	Not reported
Transporter EPA ID:	GAR000060905
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	11/13/2012
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	11/16/2012
Manifest Created Date:	Not reported
TSDF Receipt Date:	11/16/2012
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported

D61 **TOWN & COUNTRY - ROLLING ROAD** **MD HIST UST** **S104641393**
West **7106 ROLLING BEND RD APT D** **N/A**
< 1/8 **GWYNN OAK, MD 21244**
0.032 mi.
167 ft. **Site 1 of 4 in cluster D**

Relative: **Higher**

Actual: **469 ft.**

Historical UST:

Facility ID:	6014691
Tank ID:	001
Age:	28
Capacity:	1000
Tank Status:	Permanently out of use

TOWN & COUNTRY - ROLLING ROAD (Continued) **S104641393**

Product: Heating Oil

Facility ID: 6014691
Tank ID: 002
Age: 28
Capacity: 1000
Tank Status: Permanently out of use
Product: Heating Oil

Facility ID: 6014691
Tank ID: 003
Age: 28
Capacity: 1000
Tank Status: Permanently out of use
Product: Heating Oil

Facility ID: 6014691
Tank ID: 004
Age: 28
Capacity: 1000
Tank Status: Permanently out of use
Product: Heating Oil

Facility ID: 6014691
Tank ID: 005
Age: 28
Capacity: 1000
Tank Status: Permanently out of use
Product: Heating Oil

Facility ID: 6014691
Tank ID: 006
Age: 28
Capacity: 1000
Tank Status: Permanently out of use
Product: Heating Oil

Facility ID: 6014691
Tank ID: 007
Age: 28
Capacity: 1000
Tank Status: Permanently out of use
Product: Heating Oil

Facility ID: 6014691
Tank ID: 008
Age: 28
Capacity: 1000
Tank Status: Permanently out of use
Product: Heating Oil

Facility ID: 6014691
Tank ID: 009
Age: 28
Capacity: 1000
Tank Status: Permanently out of use
Product: Heating Oil

TOWN & COUNTRY - ROLLING ROAD (Continued) **S104641393**

Facility ID: 6014691
Tank ID: 010
Age: 28
Capacity: 1000
Tank Status: Permanently out of use
Product: Heating Oil

Facility ID: 6014691
Tank ID: 011
Age: 28
Capacity: 1000
Tank Status: Permanently out of use
Product: Heating Oil

Facility ID: 6014691
Tank ID: 012
Age: 28
Capacity: 1000
Tank Status: Permanently out of use
Product: Heating Oil

D62 **STREET SPILL** **MD OCPCASES** **S106464039**
West **7106 ROLLING BEND RD** **MD LEAD** **N/A**
< 1/8 **BALTIMORE, MD 21244**
0.032 mi.
167 ft. **Site 2 of 4 in cluster D**

Relative:
Higher

Actual:
469 ft.

OCPCASES:
Name: STREET SPILL
Address: 7106 ROLLING BEND RD
City,State,Zip: BALTIMORE, MD 21244
Facility ID: 04-1717BA1
Facility Status/Code: CLOSED/Vehicle Accident
Date Open: 04/19/2004
Date Closed: 05/13/2004
Release: YES
Cleanup: YES
Registration Number: Not reported

MD LEAD:
Name: Not reported
Address: 7106 ROLLING BEND ROAD
City,State,Zip: BALTIMORE, MD 21244
Facility ID: 040113402450
Cert Number: 762673
Unit ID: Not reported
Inspection Date: 09/01/2016
Limit Date: Not reported
Invalid: Not reported
Company No: 4531
Company Name: CONNOR Environmental Srvcs & Engineering Assessments
ReInspection Date: / /
Option: Full Lead Free
Inspection Category: Lead Free
Pass/Fail: P
Inspector Number: 15450
Inspector Name: Orsulak Joseph Edward

STREET SPILL (Continued) **S106464039**

Property Number:	040113402450
Owner Number:	Not reported
Inspection Type:	Not reported
Total Applies:	Not reported
Invalidated Date:	Not reported
Inspection Expiration Date:	Not reported
SP Expiration Date:	Not reported

D63 **TOWN & COUNTRY ROLLING ROAD APTS** **MD OCPCASES** **S104604469**
West **7108 ROLLING BEND RD** **N/A**
< 1/8 **WOODLAWN, MD 21244**
0.032 mi.
168 ft. **Site 3 of 4 in cluster D**

Relative: OCPCASES:
Higher

Actual:
469 ft.

Name:	TOWN & COUNTRY ROLLING ROAD APTS
Address:	7108 ROLLING BEND RD
City,State,Zip:	WOODLAWN, MD 21244
Facility ID:	94-2893BA2
Facility Status/Code:	CLOSED/
Date Open:	05/09/1994
Date Closed:	06/01/1995
Release:	Not reported
Cleanup:	Not reported
Registration Number:	10514

Name:	TOWN & COUNTRY ROLLING ROAD APTS
Address:	7108 ROLLING BEND RD
City,State,Zip:	WOODLAWN, MD 21244
Facility ID:	94-2893BA2
Facility Status/Code:	CLOSED/
Date Open:	05/09/1994
Date Closed:	06/01/1995
Release:	Not reported
Cleanup:	Not reported
Registration Number:	10514

D64 **TOWN & COUNTRY ROLLING ROAD APTS** **MD OCPCASES** **S104604470**
West **7105 ROLLING BEND RD** **N/A**
< 1/8 **WOODLAWN, MD 21244**
0.034 mi.
182 ft. **Site 4 of 4 in cluster D**

Relative: OCPCASES:
Higher

Actual:
468 ft.

Name:	TOWN & COUNTRY ROLLING ROAD APTS
Address:	7105 ROLLING BEND RD
City,State,Zip:	WOODLAWN, MD 21244
Facility ID:	94-2894BA2
Facility Status/Code:	CLOSED/Soil Contamination - Residential Heating Oil
Date Open:	05/09/1994
Date Closed:	05/31/1995
Release:	YES
Cleanup:	Not reported
Registration Number:	10514

Name:	TOWN & COUNTRY ROLLING ROAD APTS

TOWN & COUNTRY ROLLING ROAD APTS (Continued) **S104604470**

Address:	7105 ROLLING BEND RD
City,State,Zip:	WOODLAWN, MD 21244
Facility ID:	94-2894BA2
Facility Status/Code:	CLOSED/Soil Contamination - Residential Heating Oil
Date Open:	05/09/1994
Date Closed:	05/31/1995
Release:	YES
Cleanup:	Not reported
Registration Number:	10514

E65 **SECURITY STATION** **MD INST CONTROL** **S126252208**
WSW **1700 TO 1750 NORTH ROLLING ROAD** **N/A**
< 1/8 **WINDSOR MILL, MD 21244**
0.044 mi.
232 ft. **Site 1 of 2 in cluster E**

Relative: **Higher**

Actual: **459 ft.**

INST CONTROL:

Name:	SECURITY STATION
Address:	1700 TO 1750 NORTH ROLLING ROAD
City,State,Zip:	WINDSOR MILL, MD 21244
Site Alias:	Diamond Cleaners; Security Station Shopping Center
App Name:	Security Station Investors, LLC
Type Name:	EC Only
Low Freq Recreational:	False
Medium Freq Recreational:	False
High Freq Recrreation:	False
Other Rest:	False
Other Rest Notes:	At least 60 days prior to occupancy change of 1732 tenant space to a non-dry cleaner operation, the owner shall notify MDE and provide indoor air sample results.
Shape Length:	0
Shape Area:	0
Property Account Id:	0118100320, 1600008512, 0111000172, 0119270030, 1600013170
Issue Date:	03/10/2020
Covenant:	True
Date Covenant Recorded:	Not reported
Residential Land Use Unrestricted:	False
Residential Land Use Restricted:	False
Recreational Land Use Unrestricted:	Not reported
Recreational Land Use Restricted:	Not reported
Commercial Land Use Unrestricted:	False
Commercial Land Use Restricted:	True
Industrial Land Use Unrestricted:	False
Industrial Land Use Restricted:	False
Groundwater(GW) Use Restriction?:	True
GW Encountered During Excavation Rqmnts?:	False
Continued GW Remediation?:	False
Long Term Monitoring For GW?:	False
Excavation Notification Restriction?:	False
Vapor Barrier Required?:	False
Vapor System Required?:	False
Long Term Monitoring Of Indoor Air?:	False
Active Dry Cleaner Restrictions?:	True
Paving Maintenance Required?:	False
Future Construction Testing Required?:	False
Slab Maintenance Required?:	False
Excavated Material Disposal Requirement?:	False
BMI Number:	MD1665

SECURITY STATION (Continued) **S126252208**

Archive:	True
Acres:	Not reported
Count Acres Toward Total:	False

E66
WSW
< 1/8
0.044 mi.
232 ft.

SECURITY STATION **MD LRP** **S126252219**
1700 TO 1750 NORTH ROLLING ROAD **N/A**
WINDSOR MILL, MD 21244

Site 2 of 2 in cluster E

Relative:
Higher

Actual:
459 ft.

MD LRP:

Name:	SECURITY STATION
Address:	1700 To 1750 North Rolling Road
City,State,Zip:	WINDSOR MILL, MD 21244
Factsheet URL:	Fact Sheet Not Available.
Voluntary Cleanup Program:	No
Brownfield Assesment Complete:	No
NPL:	No
Federal Facility:	No
Alias:	Diamond Cleaners; Security Station Shopping Center
Groundwater:	No
Assessment On-Going:	No
Remediation On-Going:	No
Withdrawn:	No
GW Chlorinated:	No
GW Petroleum:	No
GW Metals:	No
GW Pesticides:	No
GW PCB:	No
GW PAH:	No
Soil Chlorinated:	Yes
Soil Metals:	No
Soil Pesticides:	No
Soil PCB:	No
Soil PAH:	No
Soil Petroleum:	No
Sediment Chlorinated:	No
Sediment Petroleum:	No
Sediment Metals:	No
Sediment Pesticides:	No
Sediment PCB:	No
Sediment PAH:	No
SW Chlorinated:	No
SW Petroleum:	No
SW Metals:	No
SW Pesticides:	No
SW PCB:	No
SW PAH:	No
Site Assessment:	No
Tax Map Number:	94
File Available:	Yes
BMI Number:	MD1665
Archived:	Yes
Table Site ID:	1874
Parcel Number:	289, 289, 182, 1
Block:	Not reported
Lot Number:	Not reported
Tax ID:	0118100320, 1600008512, 01110001

SECURITY STATION (Continued) **S126252219**

Det Issued:	Yes
Enfor congo:	No
CHS Oversig:	Yes
EPAID:	Not reported
Regulatory:	Not reported
FY Open:	2014
FY_Closed:	2020

F67 **EXXON SERVICE STATION** **UST FINDER** **1028412614**
North **1601 BELMONT AVE** **UST FINDER RELEASE** **N/A**
< 1/8 **BALTIMORE, MD 21244**
0.048 mi.
252 ft. **Site 1 of 7 in cluster F**

Relative: **Lower**
Actual: **441 ft.**

UST FINDER:

Object ID:	644108
Facility ID:	MD6865
Name:	27733 SECURITY SQUARE MALL EXXON
Address:	1601 BELMONT AVENUE
City,State,Zip:	BALTIMORE, MD 21207
Address Match Type:	PointAddress
Open USTs:	4
Closed USTs:	5
TOS USTs:	0
Population 1500ft:	226
Private Wells 1500ft:	2
Within 100yr Floodplain:	No
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	3
Tribe:	Not reported
Coordinate Source:	Geocode
X Coord:	-76.7498518799999
Y Coord:	39.3138103200001
Latitude:	39.31381032
Longitude:	-76.74985188

UST FINDER:

Object ID:	708925
Facility ID:	MD6865
Tank ID:	MD6865_5
Tank Status:	Closed
Installation Date:	1982/01/01 16:00:00+00
Removal Date:	1995/08/21 15:59:59+00
Tank Capacity:	1000
Substances:	Used Oil
Tank Wall Type:	Single

EXXON SERVICE STATION (Continued) **1028412614**

Object ID:	692242
Facility ID:	MD6865
Tank ID:	MD6865_1
Tank Status:	Closed
Installation Date:	1982/01/01 16:00:00+00
Removal Date:	2007/09/17 15:59:59+00
Tank Capacity:	8000
Substances:	Gasoline
Tank Wall Type:	Single

Object ID:	692243
Facility ID:	MD6865
Tank ID:	MD6865_2
Tank Status:	Closed
Installation Date:	1982/01/01 16:00:00+00
Removal Date:	2007/09/17 15:59:59+00
Tank Capacity:	10000
Substances:	Gasoline
Tank Wall Type:	Single

Object ID:	692244
Facility ID:	MD6865
Tank ID:	MD6865_3
Tank Status:	Closed
Installation Date:	1982/01/01 16:00:00+00
Removal Date:	2007/09/17 15:59:59+00
Tank Capacity:	10000
Substances:	Gasoline
Tank Wall Type:	Single

Object ID:	692245
Facility ID:	MD6865
Tank ID:	MD6865_4
Tank Status:	Closed
Installation Date:	1982/01/01 16:00:00+00
Removal Date:	2007/09/17 15:59:59+00
Tank Capacity:	6000
Substances:	Diesel
Tank Wall Type:	Single

Object ID:	728383
Facility ID:	MD6865
Tank ID:	MD6865_6
Tank Status:	Open
Installation Date:	2007/10/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	10000
Substances:	Gasohol
Tank Wall Type:	Double

Object ID:	728384
Facility ID:	MD6865
Tank ID:	MD6865_7
Tank Status:	Open
Installation Date:	2007/10/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	10000

EXXON SERVICE STATION (Continued) **1028412614**

Substances:	Gasohol
Tank Wall Type:	Double
Object ID:	728385
Facility ID:	MD6865
Tank ID:	MD6865_8
Tank Status:	Open
Installation Date:	2007/10/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	8000
Substances:	Gasohol
Tank Wall Type:	Double
Object ID:	728386
Facility ID:	MD6865
Tank ID:	MD6865_9
Tank Status:	Open
Installation Date:	2007/10/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	8000
Substances:	Diesel
Tank Wall Type:	Double

UST FINDER RELEASE:

Object ID:	196075
Facility ID:	MD6865
Lust ID:	MD00-2099BA1
Name:	EXXON SERVICE STATION
Address:	1601 BELMONT AVE
City,State,Zip:	BALTIMORE, MD 21244
Address Match Type:	PointAddress
Reported Date:	2000/03/23 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	227
Domestic Wells within 1500ft:	2
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	3
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	Geocode

EXXON SERVICE STATION (Continued) **1028412614**

X Coord:	-76.7498518799999
Y Coord:	39.3138103200001
Latitude:	39.31381032
Longitude:	-76.7498518799999
Object ID:	196076
Facility ID:	MD6865
Lust ID:	MD06-0286BA1
Name:	EXXON SERVICE STATION #27733
Address:	1601 BELMONT AVE
City,State,Zip:	BALTIMORE, MD 21244
Address Match Type:	PointAddress
Reported Date:	2005/10/04 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	227
Domestic Wells within 1500ft:	2
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	3
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	Geocode
X Coord:	-76.7498518799999
Y Coord:	39.3138103200001
Latitude:	39.31381032
Longitude:	-76.7498518799999
Object ID:	196077
Facility ID:	MD6865
Lust ID:	MD08-0168BA
Name:	EXXON #27733
Address:	1601 BELMONT AVE
City,State,Zip:	BALTIMORE, MD 21244
Address Match Type:	PointAddress
Reported Date:	2007/09/17 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	227
Domestic Wells within 1500ft:	2
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported

EXXON SERVICE STATION (Continued) **1028412614**

SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	3
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	Geocode
X Coord:	-76.7498518799999
Y Coord:	39.3138103200001
Latitude:	39.31381032
Longitude:	-76.7498518799999

F68 **27733 SECURITY SQUARE MALL EXXON** **MD OCPCASES** **U003753476**
North **1601 BELMONT AVENUE** **MD UST** **N/A**
< 1/8 **BALTIMORE, MD 21244** **MD Financial Assurance**
0.048 mi.
252 ft. **Site 2 of 7 in cluster F**

Relative: **Lower**

Actual: **441 ft.**

OCPCASES:

Name:	EXXON #27733
Address:	1601 BELMONT AVE
City,State,Zip:	BALTIMORE, MD 21244
Facility ID:	96-0349BA2
Facility Status/Code:	CLOSED/Tank Closure - Motor/Lube Oil
Date Open:	08/21/1995
Date Closed:	08/21/1995
Release:	Not reported
Cleanup:	Not reported
Registration Number:	6865

Name:	EXXON SERVICE STATION #27733
Address:	1601 BELMONT AVE
City,State,Zip:	BALTIMORE, MD 21244
Facility ID:	06-0286BA1
Facility Status/Code:	CLOSED/Well/GW Contamination - Motor/Lube Oil
Date Open:	10/04/2005
Date Closed:	09/19/2008
Release:	YES
Cleanup:	YES
Registration Number:	6865

Name:	EXXON #27733
Address:	1601 BELMONT AVE
City,State,Zip:	BALTIMORE, MD 21244
Facility ID:	08-0168BA
Facility Status/Code:	CLOSED/Tank Closure - Motor/Lube Oil
Date Open:	09/17/2007
Date Closed:	03/19/2008

27733 SECURITY SQUARE MALL EXXON (Continued) **U003753476**

Release: YES
Cleanup: YES
Registration Number: 6865

UST:
Facility Id: 6865
Oper Name: Prabhjot Likhari
Form Name: Kathleen McCaney
Form Title: Compliance Coordinator
Form Date: 09/26/2024
Owner Id: 15251

Owner:
Owner Name: Sunoco, LLC
Owner Address: c/o OWL Services 1815 Gallagher Rd
Owner City: Plymouth Meeting
Owner State: PA
Owner Zip: 19462
Owner Phone: (610) 276-5988
Owner Contact: Kathleen McCaney

Tanks:
Tank ID: 1
Tank Status: **Permanently Out Of Use**
Tank Capacity: 8000
Substance Description: Gasoline
Tank Compartment: False
Compartment Compartment: A
Date Installed: 01/01/1982
Tank Material Desc: Fiberglass Reinforced Plastic
Pipe Material Desc: Fiberglass Reinforced Plastic

Tank ID: 2
Tank Status: **Permanently Out Of Use**
Tank Capacity: 10000
Substance Description: Gasoline
Tank Compartment: False
Compartment Compartment: A
Date Installed: 01/01/1982
Tank Material Desc: Fiberglass Reinforced Plastic
Pipe Material Desc: Fiberglass Reinforced Plastic

Tank ID: 3
Tank Status: **Permanently Out Of Use**
Tank Capacity: 10000
Substance Description: Gasoline
Tank Compartment: False
Compartment Compartment: A
Date Installed: 01/01/1982
Tank Material Desc: Fiberglass Reinforced Plastic
Pipe Material Desc: Fiberglass Reinforced Plastic

Tank ID: 4
Tank Status: **Permanently Out Of Use**
Tank Capacity: 6000
Substance Description: Diesel
Tank Compartment: False

27733 SECURITY SQUARE MALL EXXON (Continued) **U003753476**

Compartment Compartment: A
Date Installed: 01/01/1982
Tank Material Desc: Fiberglass Reinforced Plastic
Pipe Material Desc: Fiberglass Reinforced Plastic

Tank ID: 5
Tank Status: **Permanently Out Of Use**
Tank Capacity: 1000
Substance Description: Used Oil
Tank Compartment: False
Compartment Compartment: A
Date Installed: 01/01/1982
Tank Material Desc: Fiberglass Reinforced Plastic
Pipe Material Desc: Fiberglass Reinforced Plastic

Tank ID: 6
Tank Status: **Currently In Use**
Tank Capacity: 10000
Substance Description: Gasohol
Tank Compartment: False
Compartment Compartment: A
Date Installed: 10/01/2007
Tank Material Desc: Fiberglass Reinforced Plastic
Pipe Material Desc: Fiberglass Reinforced Plastic

Tank ID: 7
Tank Status: **Currently In Use**
Tank Capacity: 10000
Substance Description: Gasohol
Tank Compartment: False
Compartment Compartment: A
Date Installed: 10/01/2007
Tank Material Desc: Fiberglass Reinforced Plastic
Pipe Material Desc: Fiberglass Reinforced Plastic

Tank ID: 8
Tank Status: **Currently In Use**
Tank Capacity: 8000
Substance Description: Gasohol
Tank Compartment: False
Compartment Compartment: A
Date Installed: 10/01/2007
Tank Material Desc: Fiberglass Reinforced Plastic
Pipe Material Desc: Fiberglass Reinforced Plastic

Tank ID: 9
Tank Status: **Currently In Use**
Tank Capacity: 8000
Substance Description: Diesel
Tank Compartment: False
Compartment Compartment: A
Date Installed: 10/01/2007
Tank Material Desc: Fiberglass Reinforced Plastic
Pipe Material Desc: Fiberglass Reinforced Plastic

27733 SECURITY SQUARE MALL EXXON (Continued) **U003753476**

MD Financial Assurance 2:

Name:	27733 SECURITY SQUARE MALL EXXON
Address:	1601 BELMONT AVENUE
City,State,Zip:	BALTIMORE, MD 21244
Region:	2
Facility ID:	6865
Self Insured:	False
Insurance:	True
Risk Retention Group:	False
Guarantee:	False
Surety Bonds:	False
Letter of Credit:	False
State Fund:	False
Other Finance:	False
Finacnce Comments:	Policy Number: MWZZ 301298 23 Period of Coverage: 9/15/2023 - 9/15/2024 Insurer: Old Republic Insurance Company Annual Submission Complete - Email received 3/19/24. https://drive.google.com/drive/u/0/folders/1HrgCe7dKFP2VkGY-MK4w1e3RKcPBT91Q
FR Not Listed:	False

F69 **SECURITY SQUARE MALL EXXON** **EDR Hist Auto** **1021548405**
North **1601 BELMONT AVE** **N/A**
< 1/8 **BALTIMORE, MD 21244**
0.048 mi.
252 ft. **Site 3 of 7 in cluster F**

Relative: EDR Hist Auto
Lower

Actual: **441 ft.**

Year:	Name:	Type:
1992	ELDERSBURG EXXON SERVICE STATI	Gasoline Service Stations
1993	ELDERSBURG EXXON SERVICE STATI	Gasoline Service Stations
1994	SECURITY SQUARE MALL EXXON	Gasoline Service Stations
1998	SECURITY SQUARE MALL EXXON	Gasoline Service Stations
1999	SECURITY SQUARE MALL EXXON	Gasoline Service Stations
1999	LSR MOTOR FUELS INC	Convenience Stores
2000	SECURITY SQUARE MALL EXXON	Gasoline Service Stations
2000	L S R MOTOR FUELS INC	Convenience Stores
2001	SECURITY SQUARE MALL EXXON	Gasoline Service Stations
2001	L S R MOTOR FUELS INC	Convenience Stores
2002	SECURITY SQUARE MALL EXXON	Gasoline Service Stations
2002	L S R MOTOR FUELS INC	Convenience Stores
2003	SECURITY SQUARE MALL EXXON	Gasoline Service Stations
2003	L S R MOTOR FUELS INC	Convenience Stores
2004	L S R MOTOR FUELS INC	Convenience Stores
2004	SECURITY SQUARE MALL EXXON	Gasoline Service Stations
2005	L S R MOTOR FUELS INC	Gasoline Service Stations, NEC
2005	SECURITY SQUARE MALL EXXON	Gasoline Service Stations, NEC
2006	L S R MOTOR FUELS INC	Gasoline Service Stations, NEC
2006	SECURITY SQUARE MALL EXXON	Gasoline Service Stations, NEC
2007	SECURITY SQUARE MALL EXXON	Gasoline Service Stations, NEC
2007	L S R MOTOR FUELS INC	Gasoline Service Stations, NEC
2008	L S R MOTOR FUELS INC	Gasoline Service Stations, NEC
2008	SECURITY SQUARE MALL EXXON	Gasoline Service Stations, NEC
2009	SECURITY SQUARE MALL EXXON	Gasoline Service Stations, NEC
2009	L S R MOTOR FUELS INC	Gasoline Service Stations, NEC
2010	SECURITY SQUARE MALL EXXON	Gasoline Service Stations, NEC

SECURITY SQUARE MALL EXXON (Continued) **1021548405**

2010	L S R MOTOR FUELS INC	Gasoline Service Stations, NEC
2011	L S R MOTOR FUELS INC	Gasoline Service Stations, NEC
2011	SECURITY SQUARE MALL EXXON	Gasoline Service Stations, NEC
2012	L S R MOTOR FUELS INC	Gasoline Service Stations, NEC
2012	SECURITY SQUARE MALL EXXON	Gasoline Service Stations, NEC
2013	L S R MOTOR FUELS INC	Gasoline Service Stations, NEC
2013	SECURITY SQUARE MALL EXXON	Gasoline Service Stations, NEC
2014	SECURITY SQUARE MALL EXXON	Gasoline Service Stations, NEC
2014	L S R MOTOR FUELS INC	Gasoline Service Stations, NEC

F70 **EXXON #27733** **MD OCPCASES** **S120842602**
North **1601 BELMONT AVE** **N/A**
< 1/8 **BALTIMORE, MD 21244**
0.048 mi.
252 ft. **Site 4 of 7 in cluster F**

Relative: **Lower**
Actual: **441 ft.**

OCPCASES:

Name:	EXXON #27733
Address:	1601 BELMONT AVE
City,State,Zip:	BALTIMORE, MD 21244
Facility ID:	94-1884BA2
Facility Status/Code:	CLOSED/
Date Open:	01/10/1994
Date Closed:	Not reported
Release:	Not reported
Cleanup:	Not reported
Registration Number:	6865

Name:	EXXON #27733
Address:	1601 BELMONT AVE
City,State,Zip:	BALTIMORE, MD 21244
Facility ID:	94-1884BA2
Facility Status/Code:	CLOSED/
Date Open:	01/10/1994
Date Closed:	Not reported
Release:	Not reported
Cleanup:	Not reported
Registration Number:	6865

F71 **EXXON SERVICE STATION** **MD OCPCASES** **S120841572**
North **1601 BELMONT AVE** **N/A**
< 1/8 **BALTIMORE, MD 21244**
0.048 mi.
252 ft. **Site 5 of 7 in cluster F**

Relative: **Lower**
Actual: **441 ft.**

OCPCASES:

Name:	EXXON SERVICE STATION
Address:	1601 BELMONT AVE
City,State,Zip:	BALTIMORE, MD 21244
Facility ID:	00-2099BA1
Facility Status/Code:	CLOSED/Retrofit/Repair - Motor/Lube Oil
Date Open:	03/23/2000
Date Closed:	11/02/2000
Release:	YES
Cleanup:	YES
Registration Number:	6865

F72
North
< 1/8
0.048 mi.
254 ft.

EXXON R\\S #27733
1601 BELMONT AVE
GWYNN OAK, MD 21207

Site 6 of 7 in cluster F

MD HIST UST **S104630354**
N/A

Relative:
Lower

Actual:
441 ft.

Historical UST:

Facility ID:	3003702
Tank ID:	001
Age:	13
Capacity:	8,000
Tank Status:	Currently in use
Product:	Gasoline

Facility ID:	3003702
Tank ID:	002
Age:	13
Capacity:	10,000
Tank Status:	Currently in use
Product:	Gasoline

Facility ID:	3003702
Tank ID:	003
Age:	13
Capacity:	6,000
Tank Status:	Currently in use
Product:	Gasoline

Facility ID:	3003702
Tank ID:	004
Age:	13
Capacity:	10,000
Tank Status:	Currently in use
Product:	Diesel

Facility ID:	3003702
Tank ID:	005
Age:	Not reported
Capacity:	1,000
Tank Status:	Removed
Product:	Used Oil

F73
North
< 1/8
0.055 mi.
293 ft.

LSR MOTOR FUELS INC
1604 BELMONT AVE
BALTIMORE, MD 21244

Site 7 of 7 in cluster F

EDR Hist Auto **1020871765**
N/A

Relative:
Lower

Actual:
438 ft.

EDR Hist Auto

Year:	Name:	Type:
1997	LSR MOTOR FUELS INC	Convenience Stores
1998	LSR MOTOR FUELS INC	Convenience Stores

G74 **MAY AMBULANCE** **MD OCPCASES** **S117658910**
WNW **1811 N ROLLING RD** **N/A**
< 1/8 **WOODLAWN, MD 21244**
0.062 mi.
329 ft. **Site 1 of 7 in cluster G**

Relative: OCPCASES:
Higher

Actual:
465 ft.

Name:	MAY AMBULANCE
Address:	1811 N ROLLING RD
City,State,Zip:	WOODLAWN, MD 21244
Facility ID:	7-2090BA
Facility Status/Code:	CLOSED/
Date Open:	04/18/1987
Date Closed:	12/27/1987
Release:	Not reported
Cleanup:	Not reported
Registration Number:	Not reported

H75 **TOWN & COUNTRY ROLLING ROAD APTS** **MD OCPCASES** **S104604480**
West **9 W BEND CT** **N/A**
< 1/8 **WOODLAWN, MD 21244**
0.078 mi.
411 ft. **Site 1 of 2 in cluster H**

Relative: OCPCASES:
Higher

Actual:
465 ft.

Name:	TOWN & COUNTRY ROLLING ROAD APTS
Address:	9 W BEND CT
City,State,Zip:	WOODLAWN, MD 21244
Facility ID:	94-2904BA2
Facility Status/Code:	CLOSED/Soil Contamination - Residential Heating Oil
Date Open:	05/09/1994
Date Closed:	06/01/1995
Release:	YES
Cleanup:	Not reported
Registration Number:	10514

Name:	TOWN & COUNTRY ROLLING ROAD APTS
Address:	9 W BEND CT
City,State,Zip:	WOODLAWN, MD 21244
Facility ID:	94-2904BA2
Facility Status/Code:	CLOSED/Soil Contamination - Residential Heating Oil
Date Open:	05/09/1994
Date Closed:	06/01/1995
Release:	YES
Cleanup:	Not reported
Registration Number:	10514

I76 **KOONS FORD OF BALTIMORE** **MD HIST UST** **S104630014**
NNW **6970 SECURITY BLVD** **N/A**
< 1/8 **GWYNN OAK, MD 21244**
0.081 mi.
430 ft. **Site 1 of 4 in cluster I**

Relative: Historical UST:
Lower

Actual:
446 ft.

Facility ID:	3003195
Tank ID:	001
Age:	16
Capacity:	8,000

KOONS FORD OF BALTIMORE (Continued) **S104630014**

Tank Status: Removed
Product: Gasoline

Facility ID: 3003195
Tank ID: 002
Age: 16
Capacity: 550
Tank Status: Not Regulated
Product: Other

Facility ID: 3003195
Tank ID: 003
Age: 17
Capacity: 2,000
Tank Status: Currently in use
Product: Used Oil

I77 **KOONS FORD, BALTIMORE** **MD OCPCASES** **U003836223**
NNW **6970 SECURITY BLVD** **MD UST** **N/A**
< 1/8 **WOODLAWN, MD 21244** **MD Financial Assurance**
0.081 mi.
430 ft. **Site 2 of 4 in cluster I**

Relative: OCPCASES:
Lower
Name: KOONS FORD
Actual: Address: 6970 SECURITY BLVD
446 ft. City,State,Zip: WINDSOR MILL, MD 21244
Facility ID: 92-2234BA2
Facility Status/Code: CLOSED/
Date Open: 04/22/1992
Date Closed: 04/06/1995
Release: Not reported
Cleanup: Not reported
Registration Number: 13221

Name: RICHARD STINE
Address: 6970 SECURITY BLVD
City,State,Zip: WINDSOR MILL, MD 21244
Facility ID: 92-2236BA2
Facility Status/Code: CLOSED/
Date Open: 04/22/1992
Date Closed: Not reported
Release: Not reported
Cleanup: Not reported
Registration Number: Not reported

Name: CHARLES THOMAS
Address: 6970 SECURITY BLVD
City,State,Zip: WINDSOR MILL, MD 21244
Facility ID: 92-2237BA2
Facility Status/Code: CLOSED/
Date Open: 04/22/1992
Date Closed: Not reported
Release: Not reported
Cleanup: Not reported
Registration Number: Not reported

KOONS FORD, BALTIMORE (Continued) **U003836223**

UST:

Facility Id:	13221
Oper Name:	Ralph Mastantuono
Form Name:	David Robinson
Form Title:	Maintenance Manager
Form Date:	05/07/1997
Owner Id:	8388

Owner:

Owner Name:	Koons Ford, Baltimore
Owner Address:	6970 Security Blvd
Owner City:	Woodlawn
Owner State:	MD
Owner Zip:	21244
Owner Phone:	(410) 298-3800
Owner Contact:	David Robinson

Tanks:

Tank ID:	1
Tank Status:	**Permanently Out of Use**
Tank Capacity:	10000
Substance Description:	Gasoline
Tank Compartment:	False
Compartment Compartment:	A
Date Installed:	01/01/1979
Tank Material Desc:	Asphalt Coated or Bare Steel
Pipe Material Desc:	Bare or Galvanized Steel

Tank ID:	2
Tank Status:	**Permanently Out of Use**
Tank Capacity:	2000
Substance Description:	Other
Tank Compartment:	False
Compartment Compartment:	A
Date Installed:	01/01/1979
Tank Material Desc:	Asphalt Coated or Bare Steel
Pipe Material Desc:	Bare or Galvanized Steel

MD Financial Assurance 2:

Name:	KOONS FORD, BALTIMORE
Address:	6970 SECURITY BLVD
City,State,Zip:	WOODLAWN, MD 21244
Region:	2
Facility ID:	13221
Self Insured:	False
Insurance:	False
Risk Retention Group:	False
Guarantee:	False
Surety Bonds:	False
Letter of Credit:	False
State Fund:	False
Other Finance:	False
Finacnce Comments:	Not reported
FR Not Listed:	False

I78 **KOONS FORD** **RCRA NonGen / NLR** **1000302434**
NNW **6970 SECURITY BLVD** **US AIRS** **MDD054912373**
< 1/8 **BALTIMORE, MD 21207** **FINDS**
0.081 mi. **ECHO**
430 ft. **Site 3 of 4 in cluster I**

Relative: **Lower**
Actual: **446 ft.**

RCRA Listings:

Date Form Received by Agency:		20250515
Handler Name:		Koons Ford Of Baltimore, Inc
Handler Address:		6970 Security Blvd
Handler City,State,Zip:		BALTIMORE, MD 21244
EPA ID:		MDD054912373
Contact Name:		SLAVO GLADIS
Contact Address:		6970 SECURITY BLVD
Contact City,State,Zip:		BALTIMORE, MD 21244
Contact Telephone:		410-984-5517
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		03
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		6970 SECURITY BLVD
Mailing City,State,Zip:		BALTIMORE, MD 21244
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No

KOONS FORD (Continued) **1000302434**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20250515
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D035
Waste Description:	Methyl Ethyl Ketone
Waste Code:	D039
Waste Description:	Tetrachloroethylene
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F005
Waste Description:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: KOONS FORD OF BALT, INC	
Legal Status:	Private
Date Became Current:	20050921
Date Ended Current:	Not reported
Owner/Operator Address:	6970 SECURITY BLVD
Owner/Operator City,State,Zip:	BALTIMORE, MD 21244

KOONS FORD (Continued) **1000302434**

Owner/Operator Telephone: 410-984-5517
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: OPERNAME
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: OPERSTREET
Owner/Operator City,State,Zip: OPERCITY, AK 99999
Owner/Operator Telephone: 215-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: JAMES KOONS
Legal Status: Private
Date Became Current: 19850121
Date Ended Current: Not reported
Owner/Operator Address: 2000 CHAIN BRIDGE ROAD
Owner/Operator City,State,Zip: VIENNA, VA 22182
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: JIM KOONS PARTNERSHIP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 6701 ROCKLEDGE DR
Owner/Operator City,State,Zip: BETHESDA, MD 20817
Owner/Operator Telephone: 301-571-8140
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20250515
Handler Name: KOONS FORD OF BALTIMORE, INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19830218
Handler Name: KOONS FORD OF BALTIMORE

KOONS FORD (Continued) **1000302434**

Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20080403
Handler Name:	KOONS FORD OF BALTIMORE, INC
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	811111
NAICS Description:	General Automotive Repair

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

US AIRS MINOR:

Envid:	1000302434
Region Code:	03
Programmatic ID:	AIR MD0000002400501408
Facility Registry ID:	110001773340
D and B Number:	Not reported
Primary SIC Code:	5511
NAICS Code:	441110
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	03
Programmatic ID:	AIR MD0000002400501408
Facility Registry ID:	110001773340
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2012-07-19 00:00:00

KOONS FORD (Continued) **1000302434**

Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	03
Programmatic ID:	AIR MD0000002400501408
Facility Registry ID:	110001773340
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2012-07-19 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

FINDS:
Registry ID: 110001773340

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
Maryland's Resource Conservation and Recovery Act (RCRA) database houses data related to hazardous waste.
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.
The Maryland Permanent Emission (MD-PEMIS) database houses data related to air emissions.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000302434
Registry ID:	110001773340

DFR URL:

Name:	KOONS FORD
Address:	6970 Security Blvd
City,State,Zip:	BALTIMORE, MD 21207

I79 **KOONS FORD, BALTIMORE** **UST FINDER** **1028404590**
NNW **6970 SECURITY BLVD** **N/A**
< 1/8 **WOODLAWN, MD 21244**
0.081 mi.
430 ft. **Site 4 of 4 in cluster I**

Relative:
Lower

Actual:
446 ft.

UST FINDER:

Object ID:	638203
Facility ID:	MD13221
Name:	KOONS FORD, BALTIMORE
Address:	6970 SECURITY BLVD
City,State,Zip:	WOODLAWN, MD 21244
Address Match Type:	PointAddress
Open USTs:	0
Closed USTs:	1
TOS USTs:	0
Population 1500ft:	313
Private Wells 1500ft:	2
Within 100yr Floodplain:	No
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	3
Tribe:	Not reported
Coordinate Source:	Geocode
X Coord:	-76.7510308
Y Coord:	39.3130534800001
Latitude:	39.31305348
Longitude:	-76.7510308

UST FINDER:

Object ID:	716921
Facility ID:	MD13221
Tank ID:	MD13221_1
Tank Status:	Closed
Installation Date:	1979/01/01 16:00:00+00
Removal Date:	1992/04/22 15:59:59+00
Tank Capacity:	10000
Substances:	Gasoline
Tank Wall Type:	Single

H80 **TOWN & COUNTRY ROLLING ROAD APTS** **MD OCPCASES** **S104604479**
West **8 W BEND CT** **N/A**
< 1/8 **WOODLAWN, MD 21244**
0.086 mi.
452 ft. **Site 2 of 2 in cluster H**

Relative: OCPCASES:
Higher

Actual:
464 ft.

Name:	TOWN & COUNTRY ROLLING ROAD APTS
Address:	8 W BEND CT
City,State,Zip:	WOODLAWN, MD 21244
Facility ID:	94-2903BA2
Facility Status/Code:	CLOSED/
Date Open:	05/10/1994
Date Closed:	06/01/1995
Release:	Not reported
Cleanup:	Not reported
Registration Number:	10514

Name:	TOWN & COUNTRY ROLLING ROAD APTS
Address:	8 W BEND CT
City,State,Zip:	WOODLAWN, MD 21244
Facility ID:	94-2903BA2
Facility Status/Code:	CLOSED/
Date Open:	05/10/1994
Date Closed:	06/01/1995
Release:	Not reported
Cleanup:	Not reported
Registration Number:	10514

G81 **MOBIL** **MD OCPCASES** **S120842710**
WNW **1900 N ROLLING RD** **N/A**
< 1/8 **BALTIMORE, MD 21244**
0.088 mi.
465 ft. **Site 2 of 7 in cluster G**

Relative: OCPCASES:
Lower

Actual:
451 ft.

Name:	MOBIL
Address:	1900 N ROLLING RD
City,State,Zip:	BALTIMORE, MD 21244
Facility ID:	97-0019BA2
Facility Status/Code:	CLOSED/Tank Closure - Commercial Heating Oil
Date Open:	07/02/1996
Date Closed:	07/02/1996
Release:	Not reported
Cleanup:	Not reported
Registration Number:	5444

G82 **SECURITY SUNOCO** **MD OCPCASES** **S107176575**
WNW **1900 N ROLLING RD** **N/A**
< 1/8 **BALTIMORE, MD 21244**
0.088 mi.
465 ft. **Site 3 of 7 in cluster G**

Relative: OCPCASES:
Lower

Actual:
451 ft.

Name:	SECURITY SUNOCO
Address:	1900 N ROLLING RD
City,State,Zip:	BALTIMORE, MD 21244
Facility ID:	10-0300BA

SECURITY SUNOCO (Continued) **S107176575**

Facility Status/Code: CLOSED/C-16
Date Open: 11/24/2009
Date Closed: 02/04/2011
Release: NO
Cleanup: NO
Registration Number: 5444

G83 **FJ SONS ENTERPRISES INC** **EDR Hist Auto** **1021762325**
WNW **1900 N ROLLING RD** **N/A**
< 1/8 **BALTIMORE, MD 21244**
0.088 mi.
465 ft. **Site 4 of 7 in cluster G**

Relative: EDR Hist Auto
Lower

Actual: **451 ft.**

Year:	Name:	Type:
2002	FJ SONS ENTERPRISES INC	Gasoline Service Stations
2003	FJ SONS ENTERPRISES INC	Gasoline Service Stations
2004	FJ SONS ENTERPRISES INC	Gasoline Service Stations
2005	FJ SONS ENTERPRISES INC	Gasoline Service Stations
2006	FJ SONS ENTERPRISES INC	Gasoline Service Stations
2007	FJ SONS ENTERPRISES INC	Gasoline Service Stations
2008	FJ SONS ENTERPRISES INC	Gasoline Service Stations
2009	SECURITY SUNOCO LLC	Gasoline Service Stations
2010	SECURITY SUNOCO LLC	Gasoline Service Stations
2011	SECURITY SUNOCO LLC	Gasoline Service Stations
2012	SECURITY SUNOCO LLC	Gasoline Service Stations
2013	SECURITY SUNOCO LLC	Gasoline Service Stations
2014	SECURITY SUNOCO LLC	Gasoline Service Stations

G84 **SECURITY SUNOCO** **UST FINDER** **1028411672**
WNW **1900 N. ROLLING ROAD** **N/A**
< 1/8 **BALTIMORE, MD 21244**
0.088 mi.
465 ft. **Site 5 of 7 in cluster G**

Relative: UST FINDER:
Lower

Actual: **451 ft.**

Object ID:	644103
Facility ID:	MD5444
Name:	SECURITY SUNOCO
Address:	1900 N. ROLLING ROAD
City,State,Zip:	BALTIMORE, MD 21244
Address Match Type:	StreetAddress
Open USTs:	4
Closed USTs:	1
TOS USTs:	0
Population 1500ft:	1125
Private Wells 1500ft:	7
Within 100yr Floodplain:	No
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No

SECURITY SUNOCO (Continued) **1028411672**

WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	3
Tribe:	Not reported
Coordinate Source:	Geocode
X Coord:	-76.75479863
Y Coord:	39.3119528400001
Latitude:	39.31195284
Longitude:	-76.75479863

UST FINDER:

Object ID:	707078
Facility ID:	MD5444
Tank ID:	MD5444_5
Tank Status:	Closed
Installation Date:	1988/01/01 16:00:00+00
Removal Date:	1996/07/02 15:59:59+00
Tank Capacity:	1000
Substances:	Heating Oil
Tank Wall Type:	Single

Object ID:	733156
Facility ID:	MD5444
Tank ID:	MD5444_4
Tank Status:	Open
Installation Date:	1988/04/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	10000
Substances:	Diesel
Tank Wall Type:	Single

Object ID:	733157
Facility ID:	MD5444
Tank ID:	MD5444_3
Tank Status:	Open
Installation Date:	1988/04/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	10000
Substances:	Gasohol
Tank Wall Type:	Single

Object ID:	733158
Facility ID:	MD5444
Tank ID:	MD5444_2
Tank Status:	Open
Installation Date:	1988/04/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	10000
Substances:	Gasohol
Tank Wall Type:	Single

Object ID:	733159
Facility ID:	MD5444
Tank ID:	MD5444_1

SECURITY SUNOCO (Continued) **1028411672**

Tank Status:	Open
Installation Date:	1988/04/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	10000
Substances:	Gasohol
Tank Wall Type:	Single

G85 **MOBIL** **MD OCPCASES** **S113767737**
WNW **1900 N ROLLING RD** **N/A**
< 1/8 **BALTIMORE, MD 21244**
0.088 mi.
465 ft. **Site 6 of 7 in cluster G**

Relative:
Lower

Actual:
451 ft.

OCPCASES:

Name:	MOBIL
Address:	1900 N ROLLING RD
City,State,Zip:	BALTIMORE, MD 21244
Facility ID:	04-0715BA1
Facility Status/Code:	CLOSED/Vehicle Accident
Date Open:	10/16/2003
Date Closed:	05/10/2005
Release:	YES
Cleanup:	YES
Registration Number:	5444

G86 **CMF 2134** **MD UST** **U003752772**
WNW **1900 N. ROLLING ROAD** **MD Financial Assurance** **N/A**
< 1/8 **BALTIMORE, MD 21244**
0.088 mi.
465 ft. **Site 7 of 7 in cluster G**

Relative:
Lower

Actual:
451 ft.

UST:

Facility Id:	5444
Oper Name:	Abdul Jabbar
Form Name:	Herb Meade
Form Title:	Environmental Director
Form Date:	11/04/2021
Owner Id:	54

Owner:

Owner Name:	Carroll Independent Fuel, LLC
Owner Address:	18 Loveton Circle
Owner City:	Sparks
Owner State:	MD
Owner Zip:	21152
Owner Phone:	(410) 261-5450
Owner Contact:	Herb Meade

Tanks:

Tank ID:	1
Tank Status:	**Currently In Use**
Tank Capacity:	10000
Substance Description:	Gasohol
Tank Compartment:	False
Compartment Compartment:	A

CMF 2134 (Continued) **U003752772**

Date Installed:	04/01/1988
Tank Material Desc:	Fiberglass Reinforced Plastic
Pipe Material Desc:	Fiberglass Reinforced Plastic
Tank ID:	2
Tank Status:	**Currently In Use**
Tank Capacity:	10000
Substance Description:	Gasohol
Tank Compartment:	False
Compartment Compartment:	A
Date Installed:	04/01/1988
Tank Material Desc:	Fiberglass Reinforced Plastic
Pipe Material Desc:	Fiberglass Reinforced Plastic
Tank ID:	3
Tank Status:	**Currently In Use**
Tank Capacity:	10000
Substance Description:	Gasohol
Tank Compartment:	False
Compartment Compartment:	A
Date Installed:	04/01/1988
Tank Material Desc:	Fiberglass Reinforced Plastic
Pipe Material Desc:	Fiberglass Reinforced Plastic
Tank ID:	4
Tank Status:	**Currently In Use**
Tank Capacity:	10000
Substance Description:	Diesel
Tank Compartment:	False
Compartment Compartment:	A
Date Installed:	04/01/1988
Tank Material Desc:	Fiberglass Reinforced Plastic
Pipe Material Desc:	Fiberglass Reinforced Plastic
Tank ID:	5
Tank Status:	**Permanently Out Of Use**
Tank Capacity:	1000
Substance Description:	Heating Oil
Tank Compartment:	False
Compartment Compartment:	A
Date Installed:	01/01/1988
Tank Material Desc:	Fiberglass Reinforced Plastic
Pipe Material Desc:	Fiberglass Reinforced Plastic

MD Financial Assurance 2:

Name:	CMF 2134
Address:	1900 N. ROLLING ROAD
City,State,Zip:	BALTIMORE, MD 21244
Region:	2
Facility ID:	5444
Self Insured:	False
Insurance:	True
Risk Retention Group:	False
Guarantee:	False
Surety Bonds:	False
Letter of Credit:	False

CMF 2134 (Continued) **U003752772**

State Fund: False
Other Finance: False
Finacnce Comments: Policy # 002655601 Insurer: Ironshore Specialty Ins. Co. Policy Period: 02/16/2021 - 02/16/2022 (cel)
FR Not Listed: False

J87 **TOWN & COUNTRY ROLLING ROAD APTS** **MD OCPCASES** **S104604471**
West **7115 ROLLING BEND RD** **N/A**
< 1/8 **WOODLAWN, MD 21244**
0.089 mi.
468 ft. **Site 1 of 3 in cluster J**

Relative: **Higher**
Actual: **482 ft.**

OCPCASES:
Name: TOWN & COUNTRY ROLLING ROAD APTS
Address: 7115 ROLLING BEND RD
City,State,Zip: WOODLAWN, MD 21244
Facility ID: 94-2895BA2
Facility Status/Code: CLOSED/Soil Contamination - Residential Heating Oil
Date Open: 05/09/1994
Date Closed: 03/31/1995
Release: YES
Cleanup: Not reported
Registration Number: 10514

Name: TOWN & COUNTRY ROLLING ROAD APTS
Address: 7115 ROLLING BEND RD
City,State,Zip: WOODLAWN, MD 21244
Facility ID: 94-2895BA2
Facility Status/Code: CLOSED/Soil Contamination - Residential Heating Oil
Date Open: 05/09/1994
Date Closed: 03/31/1995
Release: YES
Cleanup: Not reported
Registration Number: 10514

---

88 **GRACE GAS AND TRANSPORT MGT CO** **EDR Hist Auto** **1020522229**
NW **7000 SECURITY BLVD** **N/A**
< 1/8 **WINDSOR MILL, MD 21244**
0.091 mi.
483 ft.

Relative: **Lower**
Actual: **451 ft.**

EDR Hist Auto

Year:	Name:	Type:
2011	GRACE GAS AND TRANSPORT MGT CO	Gasoline Service Stations, NEC
2012	GRACE GAS AND TRANSPORT MGT CO	Gasoline Service Stations, NEC
2013	GRACE GAS AND TRANSPORT MGT CO	Gasoline Service Stations, NEC
2014	GRACE GAS AND TRANSPORT MGT CO	Gasoline Service Stations, NEC

K89 **NATIONAL COATINGS & SUPPLIES** **MD MANIFEST** **S121871672**
NNW **2040-R LORD BALTIMORE DR.** **N/A**
< 1/8 **WINDSOR MILL, MD 21244**
0.094 mi.
494 ft. **Site 1 of 6 in cluster K**

Relative: MD MANIFEST:
Lower

Actual: EPAID: MDR000523045
447 ft. Name: NATIONAL COATINGS & SUPPLIES
Address: 2040-R LORD BALTIMORE DR.
City,State,Zip: WINDSOR MILL, MD 21244
Manifest Number: 005318690SKS
Transporter 1: SAFETY-KLEEN SYSTEMS, INC.
Transporter 2: CLEAN HARBORS ENVIRONMENTAL SERVICE
Generator Certifier: CHARLES MORGAN
Date Shipped Out: 05/13/2016
Destination Facility Certifier: SAMANTHA CALHOUN
Date Arrived at Destingation Facility: 06/10/2016
Quantity: 200
Unit: Pounds

K90 **NATIONAL COATINGS - SUPPLIES** **RCRA-VSQG** **1012179847**
NNW **2040-R LORD BALTIMORE DR** **NJ MANIFEST** **MDR000523045**
< 1/8 **WINDSOR MILL, MD 21244**
0.094 mi.
494 ft. **Site 2 of 6 in cluster K**

Relative: RCRA Listings:
Lower

Actual: Date Form Received by Agency: 20131223
447 ft. Handler Name: National Coatings - Supplies
Handler Address: 2040-R Lord Baltimore Dr
Handler City,State,Zip: WINDSOR MILL, MD 21244
EPA ID: MDR000523045
Contact Name: CHARLIE MORGAN
Contact Address: 2040-R LORD BALTIMORE DR
Contact City,State,Zip: BALTIMORE, MD 21244
Contact Telephone: 410-944-3003
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: MANAGER
EPA Region: 03
Land Type: Private
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Handler Activities
State District Owner: Not reported
State District: Not reported
Mailing Address: 2040-R LORD BALTIMORE DR
Mailing City,State,Zip: WINDSOR MILL, MD 21244
Owner Name: National Coatings - Supplies
Owner Type: Private
Operator Name: National Coatings - Supplies
Operator Type: Private
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility Activity: No

NATIONAL COATINGS - SUPPLIES (Continued) **1012179847**

Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20151218
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D005
Waste Description:	Barium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D035
Waste Description:	Methyl Ethyl Ketone
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent

NATIONAL COATINGS - SUPPLIES (Continued) **1012179847**

Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator: Operator
Owner/Operator Name: SUPERIOR AUTO PAINTS INC
Legal Status: Private
Date Became Current: 20040301
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NATIONAL COATINGS - SUPPLIES
Legal Status: Private
Date Became Current: 20131004
Date Ended Current: Not reported
Owner/Operator Address: 4900 FALLS OF NEUSE, STE 150
Owner/Operator City,State,Zip: RALEIGH, NC 27609
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MERRITT PROPERTIES LLC
Legal Status: Private
Date Became Current: 20040301
Date Ended Current: Not reported
Owner/Operator Address: 2066 LORD BALTIMORE DR
Owner/Operator City,State,Zip: BALTIMORE, MD 21244
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SUPERIOR AUTO PAINTS INC
Legal Status: Private

NATIONAL COATINGS - SUPPLIES (Continued) **1012179847**

Date Became Current: 20040301
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MERRITT PROPERTIES LLC
Legal Status: Private
Date Became Current: 20040301
Date Ended Current: Not reported
Owner/Operator Address: 2066 LORD BALTIMORE DR
Owner/Operator City,State,Zip: BALTIMORE, MD 21244
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NATIONAL COATINGS - SUPPLIES
Legal Status: Private
Date Became Current: 20131004
Date Ended Current: Not reported
Owner/Operator Address: 4900 FALLS OF NEUSE, STE 150
Owner/Operator City,State,Zip: RALEIGH, NC 27609
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20130916
Handler Name: SUPERIOR AUTO PAINTS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090709
Handler Name: SUPERIOR AUTO PAINTS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No

NATIONAL COATINGS - SUPPLIES (Continued) **1012179847**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20131223
Handler Name: NATIONAL COATINGS - SUPPLIES
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 42295
NAICS Description: Paint, Varnish, And Supplies Wholesalers

NAICS Code: 441310
NAICS Description: Automotive Parts And Accessories Stores

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported

NATIONAL COATINGS - SUPPLIES (Continued) **1012179847**

SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20130916
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	MDANE
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

NJ MANIFEST:

EPA ID:	MDR000523045
Name:	NATIONAL COATINGS - SUPPLIES
Address:	2040 LORD BALTIMORE DR
City,State,Zip:	BALTIMORE, MD 21244
County:	Not reported
Mailing Address:	LORD BALTIMORE DR
Mailing City,State,Zip:	BALTIMORE, MD 21244
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	TOM HOCHHEISER
Comments:	Not reported
SIC Code:	Not reported
County:	MD005
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	MDR000523045
Manifest Number:	001997154SKS
Date Shipped:	08/03/2009
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported

NATIONAL COATINGS - SUPPLIES (Continued) **1012179847**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/03/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/10/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H061
Quantity:	1500
Unit:	P

L91 **TOWN & COUNTRY ROLLING ROAD APTS** **MD OCPCASES** **S104604474**
WSW **4 E BEND CT** **N/A**
< 1/8 **WOODLAWN, MD 21244**
0.094 mi.
497 ft. **Site 1 of 3 in cluster L**

Relative:
Higher

Actual:
467 ft.

OCPCASES:

Name:	TOWN & COUNTRY ROLLING ROAD APTS
Address:	4 E BEND CT
City,State,Zip:	WOODLAWN, MD 21244
Facility ID:	94-2898BA2
Facility Status/Code:	CLOSED/Soil Contamination - Residential Heating Oil
Date Open:	05/09/1994
Date Closed:	05/31/1995
Release:	YES
Cleanup:	Not reported
Registration Number:	10514
Name:	TOWN & COUNTRY ROLLING ROAD APTS
Address:	4 E BEND CT

TOWN & COUNTRY ROLLING ROAD APTS (Continued) **S104604474**

City,State,Zip:	WOODLAWN, MD 21244
Facility ID:	94-2898BA2
Facility Status/Code:	CLOSED/Soil Contamination - Residential Heating Oil
Date Open:	05/09/1994
Date Closed:	05/31/1995
Release:	YES
Cleanup:	Not reported
Registration Number:	10514

92
NW
< 1/8
0.096 mi.
509 ft.

SHA BRIDGE 0313300
I-695 RAMP (7) OVER MD 122
WINDSOR MILL, MD 21244

RCRA-LQG **1018275706**
FINDS **MDR000527067**
ECHO

Relative:
Lower

Actual:
456 ft.

RCRA Listings:

Date Form Received by Agency:	20180212
Handler Name:	Sha Bridge 0313300
Handler Address:	I-695 Ramp (7) Over Md 122
Handler City,State,Zip:	WINDSOR MILL, MD 21244
EPA ID:	MDR000527067
Contact Name:	ROD S THORNTON
Contact Address:	N. CALVERT ST -MAILSTOP C-203
Contact City,State,Zip:	BALTIMORE, MD 21202
Contact Telephone:	410-545-8388
Contact Fax:	410-209-5047
Contact Email:	RTHORNTON@SHA.STATE.MD.US
Contact Title:	DEPUTY DIRECTOR, OFFICE OF STRUCTURES
EPA Region:	03
Land Type:	State
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	N. CALVERT ST - MAILSTOP C-203
Mailing City,State,Zip:	BALTIMORE, MD 21202
Owner Name:	Maryland State Highway Administration
Owner Type:	State
Operator Name:	Reglas Painting
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported

SHA BRIDGE 0313300 (Continued) **1018275706**

Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181003
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years

Year:	2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	MARYLAND STATE HIGHWAY ADMINISTRATION -
Legal Status:	State
Date Became Current:	19610101
Date Ended Current:	Not reported
Owner/Operator Address:	707 N CALVERT ST, MS C-203
Owner/Operator City,State,Zip:	BALTIMORE, MD 21202
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	REGLAS PAINTING
Legal Status:	Private
Date Became Current:	20151210
Date Ended Current:	Not reported
Owner/Operator Address:	4128 NORTH POINT RD
Owner/Operator City,State,Zip:	DUNDALK, MD 21222
Owner/Operator Telephone:	410-477-8024

SHA BRIDGE 0313300 (Continued) **1018275706**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: 410-477-4384
Owner/Operator Email: TREGLAS@AOL.COM

Owner/Operator Indicator: Operator
Owner/Operator Name: REGLAS PAINTING COMPANY, INC
Legal Status: Private
Date Became Current: 20151210
Date Ended Current: Not reported
Owner/Operator Address: 4128 NORTH POINT RD
Owner/Operator City,State,Zip: DUNDALK, MD 21222
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MARYLAND STATE HIGHWAY ADMINISTRATION
Legal Status: State
Date Became Current: 19610101
Date Ended Current: Not reported
Owner/Operator Address: 707 N.CALVERT ST, MAILSTOP C-203
Owner/Operator City,State,Zip: BALTIMORE, MD 21202
Owner/Operator Telephone: 410-545-8388
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: 410-209-5047
Owner/Operator Email: RTHORNTON@SHA.STATE.MD.US

Historic Generators:
Receive Date: 20180212
Handler Name: SHA BRIDGE 0313300
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20160202
Handler Name: SHA BRIDGE 0313300
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:

SHA BRIDGE 0313300 (Continued) **1018275706**

NAICS Code: 926120
NAICS Description: Regulation And Administration Of Transportation Programs

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067417094

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
All generators and treatment, storage, and disposal (TSD) facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years. The data collected is used to create the National Biennial Resource Conservation and Recovery Act (RCRA) Hazardous Waste Report. This data is processed within the RCRA Information (RCRAInfo) database
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018275706
Registry ID: 110067417094

DFR URL:
Name: SHA BRIDGE 0313300
Address: I-695 Ramp (7) Over Md 122
City,State,Zip: WINDSOR MILL, MD 21244

L93 **TOWN & COUNTRY ROLLING ROAD APTS** **MD OCPCASES** **S104604473**
WSW **3 E BEND CT** **N/A**
< 1/8 **WOODLAWN, MD 21244**
0.100 mi.
526 ft. **Site 2 of 3 in cluster L**

Relative:
Higher

Actual:
465 ft.

OCPCASES:
Name: TOWN & COUNTRY ROLLING ROAD APTS
Address: 3 E BEND CT
City,State,Zip: WOODLAWN, MD 21244
Facility ID: 94-2897BA2
Facility Status/Code: CLOSED/Soil Contamination - Residential Heating Oil
Date Open: 05/09/1994
Date Closed: 05/31/1995
Release: YES
Cleanup: Not reported

TOWN & COUNTRY ROLLING ROAD APTS (Continued) **S104604473**

Registration Number: 10514

Name: TOWN & COUNTRY ROLLING ROAD APTS
Address: 3 E BEND CT
City,State,Zip: WOODLAWN, MD 21244
Facility ID: 94-2897BA2
Facility Status/Code: CLOSED/Soil Contamination - Residential Heating Oil
Date Open: 05/09/1994
Date Closed: 05/31/1995
Release: YES
Cleanup: Not reported
Registration Number: 10514

J94 **TOWN & COUNTRY ROLLING ROAD APTS** **MD OCPCASES** **S104604472**
WSW **7132 ROLLING BEND RD** **N/A**
< 1/8 **WOODLAWN, MD 21244**
0.104 mi.
549 ft. **Site 2 of 3 in cluster J**

Relative: OCPCASES:
Higher
Name: TOWN & COUNTRY ROLLING ROAD APTS
Actual: Address: 7132 ROLLING BEND RD
479 ft. City,State,Zip: WOODLAWN, MD 21244
Facility ID: 94-2896BA2
Facility Status/Code: CLOSED/Soil Contamination - Residential Heating Oil
Date Open: 05/09/1994
Date Closed: 05/31/1995
Release: YES
Cleanup: Not reported
Registration Number: 10514

Name: TOWN & COUNTRY ROLLING ROAD APTS
Address: 7132 ROLLING BEND RD
City,State,Zip: WOODLAWN, MD 21244
Facility ID: 94-2896BA2
Facility Status/Code: CLOSED/Soil Contamination - Residential Heating Oil
Date Open: 05/09/1994
Date Closed: 05/31/1995
Release: YES
Cleanup: Not reported
Registration Number: 10514

---

95 **RAMADA HOTEL** **MD OCPCASES** **S121712706**
NNE **1701 BELMONT AVE** **N/A**
< 1/8 **WOODLAWN, MD 21244**
0.112 mi.
592 ft.

Relative: OCPCASES:
Lower
Name: RAMADA HOTEL
Actual: Address: 1701 BELMONT AVE
427 ft. City,State,Zip: WOODLAWN, MD 21244
Facility ID: 90-2404BA2
Facility Status/Code: CLOSED/
Date Open: 05/24/1990
Date Closed: 11/01/1994

RAMADA HOTEL (Continued) **S121712706**

Release: Not reported
Cleanup: Not reported
Registration Number: 18154

J96
WSW
< 1/8
0.122 mi.
644 ft.

TOWN & COUNTRY ROLLING ROAD APTS **MD OCPCASES** **S104604478**
7142 ROLLING BEND RD **N/A**
WOODLAWN, MD 21244

Site 3 of 3 in cluster J

Relative: Higher
Actual: 470 ft.

OCPCASES:
Name: TOWN & COUNTRY ROLLING ROAD APTS
Address: 7142 ROLLING BEND RD
City,State,Zip: WOODLAWN, MD 21244
Facility ID: 94-2902BA2
Facility Status/Code: CLOSED/Soil Contamination - Residential Heating Oil
Date Open: 05/10/1994
Date Closed: 05/31/1995
Release: YES
Cleanup: Not reported
Registration Number: 10514

Name: TOWN & COUNTRY ROLLING ROAD APTS
Address: 7142 ROLLING BEND RD
City,State,Zip: WOODLAWN, MD 21244
Facility ID: 94-2902BA2
Facility Status/Code: CLOSED/Soil Contamination - Residential Heating Oil
Date Open: 05/10/1994
Date Closed: 05/31/1995
Release: YES
Cleanup: Not reported
Registration Number: 10514

K97
NNW
< 1/8
0.123 mi.
648 ft.

PJS LLC COMMERCIAL PROPERTY **MD OCPCASES** **S121131069**
2015 LORD BALTIMORE DR **N/A**
WINDSOR MILL, MD 20772

Site 3 of 6 in cluster K

Relative: Lower
Actual: 434 ft.

OCPCASES:
Name: PJS LLC COMMERCIAL PROPERTY
Address: 2015 LORD BALTIMORE DR
City,State,Zip: WINDSOR MILL, MD 20772
Facility ID: 17-0730BA
Facility Status/Code: CLOSED/Soil Contamination - Motor/Lube Oil
Date Open: 06/23/2017
Date Closed: 07/18/2017
Release: YES
Cleanup: YES
Registration Number: Not reported

K98 **PJS LLC COMMERCIAL PROPERTY** **UST FINDER RELEASE** **1029092081**
NNW **2015 LORD BALTIMORE DR** **N/A**
< 1/8 **WINDSOR MILL, MD 20772**
0.123 mi.
648 ft. **Site 4 of 6 in cluster K**

Relative: **Lower**
Actual: **434 ft.**

UST FINDER RELEASE:

Object ID:	188630
Facility ID:	Not reported
Lust ID:	MD17-0730BA
Name:	PJS LLC COMMERCIAL PROPERTY
Address:	2015 LORD BALTIMORE DR
City,State,Zip:	WINDSOR MILL, MD 20772
Address Match Type:	PointAddress
Reported Date:	2017/06/23 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	475
Domestic Wells within 1500ft:	2
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	3
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	Geocode
X Coord:	-76.75241446
Y Coord:	39.3147540000001
Latitude:	39.314754
Longitude:	-76.7524144599999

L99 **TOWN & COUNTRY ROLLING ROAD APTS** **MD OCPCASES** **S104604475**
WSW **7127 ROLLING BEND RD** **N/A**
1/8-1/4 **WOODLAWN, MD 21244**
0.131 mi.
691 ft. **Site 3 of 3 in cluster L**

Relative: **Higher**
Actual: **466 ft.**

OCPCASES:

Name:	TOWN & COUNTRY ROLLING ROAD APTS
Address:	7127 ROLLING BEND RD
City,State,Zip:	WOODLAWN, MD 21244
Facility ID:	94-2899BA2
Facility Status/Code:	CLOSED/Soil Contamination - Residential Heating Oil
Date Open:	05/09/1994
Date Closed:	05/31/1997
Release:	YES
Cleanup:	Not reported

TOWN & COUNTRY ROLLING ROAD APTS (Continued) **S104604475**

Registration Number: 10514

Name: TOWN & COUNTRY ROLLING ROAD APTS
Address: 7127 ROLLING BEND RD
City,State,Zip: WOODLAWN, MD 21244
Facility ID: 94-2899BA2
Facility Status/Code: CLOSED/Soil Contamination - Residential Heating Oil
Date Open: 05/09/1994
Date Closed: 05/31/1997
Release: YES
Cleanup: Not reported
Registration Number: 10514

K100 **MERRITT CORPORATION II** **UST FINDER** **1028413625**
NNW **2066 LORD BALTIMORE DRIVE** **N/A**
1/8-1/4 **BALTIMORE, MD 21244**
0.134 mi.
706 ft. **Site 5 of 6 in cluster K**

Relative: **Lower**

Actual: **441 ft.**

UST FINDER:
Object ID: 638259
Facility ID: MD8234
Name: MERRITT CORPORATION II
Address: 2066 LORD BALTIMORE DRIVE
City,State,Zip: BALTIMORE, MD 21244
Address Match Type: PointAddress
Open USTs: 0
Closed USTs: 2
TOS USTs: 0
Population 1500ft: 547
Private Wells 1500ft: 2
Within 100yr Floodplain: No
Land Use: Developed, Medium Intensity
Within SPA: No
SPA PWS Facility ID: Not reported
SPA Water Type: Not reported
SPA Facility Type: Not reported
SPA HUC12: Not reported
Within WHPA: No
WHPA PWS Facility ID: Not reported
WHPA Water Type: Not reported
WHPA Facility Type: Not reported
WHPA HUC12: Not reported
Facility Status: Closed UST(s)
Date of Last Inspection: Not reported
EPA Region: 3
Tribe: Not reported
Coordinate Source: Geocode
X Coord: -76.7523872
Y Coord: 39.31533276
Latitude: 39.31533276
Longitude: -76.7523872

UST FINDER:
Object ID: 706492
Facility ID: MD8234
Tank ID: MD8234_1
Tank Status: Closed

MERRITT CORPORATION II (Continued) **1028413625**

Installation Date:	1982/01/01 16:00:00+00
Removal Date:	1996/10/17 15:59:59+00
Tank Capacity:	2000
Substances:	Diesel
Tank Wall Type:	Single
Object ID:	718814
Facility ID:	MD8234
Tank ID:	MD8234_2
Tank Status:	Closed
Installation Date:	1979/01/01 16:00:00+00
Removal Date:	1991/07/25 15:59:59+00
Tank Capacity:	10000
Substances:	Gasoline
Tank Wall Type:	Single

K101 **MERRITT CORPORATION II** **MD OCPCASES** **U003754123**
NNW **2066 LORD BALTIMORE DRIVE** **MD UST** **N/A**
1/8-1/4 **BALTIMORE, MD 21244** **MD Financial Assurance**
0.134 mi.
706 ft. **Site 6 of 6 in cluster K**

Relative: **Lower**

Actual: **441 ft.**

OCPCASES:

Name:	MERRIT MGMT
Address:	2066 LORD BALTIMORE DR
City,State,Zip:	WINDSOR MILL, MD 21244
Facility ID:	92-0295BA2
Facility Status/Code:	CLOSED/Tank Test Failure - Motor/Lube Oil
Date Open:	07/25/1991
Date Closed:	03/25/1992
Release:	YES
Cleanup:	Not reported
Registration Number:	8234

UST:

Facility Id:	8234
Oper Name:	Josie Kaminski
Form Name:	Josie Kaminski
Form Title:	Property Manager
Form Date:	05/29/1997
Owner Id:	991

Owner:

Owner Name:	Merritt Properties LLC
Owner Address:	2066 Lord Baltimore Drive
Owner City:	Baltimore
Owner State:	MD
Owner Zip:	21244
Owner Phone:	(410) 298-2600
Owner Contact:	Mrs. Josie Kaminski

Tanks:

Tank ID:	1
Tank Status:	**Permanently Out of Use**
Tank Capacity:	2000
Substance Description:	Diesel

MERRITT CORPORATION II (Continued) **U003754123**

Tank Compartment:	False
Compartment Compartment:	A
Date Installed:	01/01/1982
Tank Material Desc:	Asphalt Coated or Bare Steel
Pipe Material Desc:	Bare or Galvanized Steel

Tank ID:	2
Tank Status:	**Permanently Out of Use**
Tank Capacity:	10000
Substance Description:	Gasoline
Tank Compartment:	False
Compartment Compartment:	A
Date Installed:	01/01/1979
Tank Material Desc:	Asphalt Coated or Bare Steel
Pipe Material Desc:	Bare or Galvanized Steel

MD Financial Assurance 2:

Name:	MERRITT CORPORATION II
Address:	2066 LORD BALTIMORE DRIVE
City,State,Zip:	BALTIMORE, MD 21244
Region:	2
Facility ID:	8234
Self Insured:	False
Insurance:	False
Risk Retention Group:	False
Guarantee:	False
Surety Bonds:	False
Letter of Credit:	False
State Fund:	False
Other Finance:	False
Finacnce Comments:	Not reported
FR Not Listed:	False

M102 **TOWN & COUNTRY ROLLING ROAD APTS** **MD OCPCASES** **S104604476**
WSW **7139 ROLLING BEND RD** **N/A**
1/8-1/4 **WOODLAWN, MD 21244**
0.156 mi.
825 ft. **Site 1 of 2 in cluster M**

Relative:
Higher

Actual:
474 ft.

OCPCASES:

Name:	TOWN & COUNTRY ROLLING ROAD APTS
Address:	7139 ROLLING BEND RD
City,State,Zip:	WOODLAWN, MD 21244
Facility ID:	94-2900BA2
Facility Status/Code:	CLOSED/Soil Contamination - Residential Heating Oil
Date Open:	06/30/1993
Date Closed:	12/31/1995
Release:	YES
Cleanup:	Not reported
Registration Number:	10514

Name:	TOWN & COUNTRY ROLLING ROAD APTS
Address:	7139 ROLLING BEND RD
City,State,Zip:	WOODLAWN, MD 21244
Facility ID:	94-2900BA2
Facility Status/Code:	CLOSED/Soil Contamination - Residential Heating Oil

TOWN & COUNTRY ROLLING ROAD APTS (Continued) **S104604476**

Date Open: 06/30/1993
Date Closed: 12/31/1995
Release: YES
Cleanup: Not reported
Registration Number: 10514

M103 **TOWN & COUNTRY ROLLING ROAD APTS** **MD OCPCASES** **S104604477**
WSW **7145 ROLLING BEND RD** **N/A**
1/8-1/4 **WOODLAWN, MD 21244**
0.169 mi.
890 ft. **Site 2 of 2 in cluster M**

Relative: **Higher**
Actual: **479 ft.**

OCPCASES:
Name: TOWN & COUNTRY ROLLING ROAD APTS
Address: 7145 ROLLING BEND RD
City,State,Zip: WOODLAWN, MD 21244
Facility ID: 94-2901BA2
Facility Status/Code: CLOSED/Soil Contamination - Residential Heating Oil
Date Open: 05/10/1994
Date Closed: 05/31/1995
Release: YES
Cleanup: Not reported
Registration Number: 10514

Name: TOWN & COUNTRY ROLLING ROAD APTS
Address: 7145 ROLLING BEND RD
City,State,Zip: WOODLAWN, MD 21244
Facility ID: 94-2901BA2
Facility Status/Code: CLOSED/Soil Contamination - Residential Heating Oil
Date Open: 05/10/1994
Date Closed: 05/31/1995
Release: YES
Cleanup: Not reported
Registration Number: 10514

N104 **CHADWICK CLEANERS** **MD DRYCLEANERS** **S110089675**
WNW **7133 SECURITY BOULEVARD** **N/A**
1/8-1/4 **WOODLAWN, MD 21244**
0.195 mi.
1027 ft. **Site 1 of 9 in cluster N**

Relative: **Lower**
Actual: **439 ft.**

Drycleaners:
Name: CHADWICK CLEANERS
Address: 7133 SECURITY BOULEVARD
City,State,Zip: WOODLAWN, MD 21244
Facility ID: 005-1078
SIC Code: 7216
Fstatus Decode: Inactive
Facility Status: Inactive

O105 **SECURITY BLVD SITE** **SEMS-ARCHIVE** **1003864765**
NNE **1718 K. BELMONT AVE.** **MDD981035405**
1/8-1/4 **WOODLAWN, MD 21207**
0.196 mi.
1037 ft. **Site 1 of 2 in cluster O**

Relative:
Lower

Actual:
417 ft.

SEMS Archive:

Site ID:	0300346
EPA ID:	MDD981035405
Name:	SECURITY BLVD SITE
Address:	1718 K. BELMONT AVE.
Address 2:	Not reported
City,State,Zip:	WOODLAWN, MD 21207
Cong District:	02
FIPS Code:	24005
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	03
Site ID:	0300346
EPA ID:	MDD981035405
Site Name:	SECURITY BLVD SITE
NPL:	N
FF:	N
OU:	00
Action Code:	RV
Action Name:	RMVL
SEQ:	1
Start Date:	1984-09-26 05:00:00
Finish Date:	1985-04-07 06:00:00
Qual:	C
Current Action Lead:	EPA Perf

Region:	03
Site ID:	0300346
EPA ID:	MDD981035405
Site Name:	SECURITY BLVD SITE
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	1987-10-20 04:00:00
Finish Date:	1987-10-20 04:00:00
Qual:	N
Current Action Lead:	St Perf

Region:	03
Site ID:	0300346
EPA ID:	MDD981035405
Site Name:	SECURITY BLVD SITE
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1

SECURITY BLVD SITE (Continued) **1003864765**

Start Date:	1985-02-01 06:00:00
Finish Date:	1985-02-01 06:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	03
Site ID:	0300346
EPA ID:	MDD981035405
Site Name:	SECURITY BLVD SITE
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1996-01-23 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

O106 **SECURITY BLVD SITE** **MD SHWS** **1000427176**
NNE **1718 K BELMONT AVE** **N/A**
1/8-1/4 **BALTIMORE, MD 21207**
0.196 mi.
1037 ft. **Site 2 of 2 in cluster O**

Relative: **Lower**
Actual: **417 ft.**

SHWS:

Facility ID:	(MD-188)
Alias Name:	NONE
Status:	**No Further Remedial Action**
Facility Type:	State Master List

N107 **CHADWICK CLEANERS** **RCRA NonGen / NLR** **1000193440**
WNW **7133 SECURITY BLVD** **FINDS** **MDD054913975**
1/8-1/4 **BALTIMORE, MD 21207** **ECHO**
0.197 mi.
1039 ft. **Site 2 of 9 in cluster N**

Relative: **Lower**
Actual: **440 ft.**

RCRA Listings:

Date Form Received by Agency:	20250514
Handler Name:	Chadwick Cleaners
Handler Address:	7133 Security Blvd
Handler City,State,Zip:	BALTIMORE, MD 21207
EPA ID:	MDD054913975
Contact Name:	TERRY BARBERIS
Contact Address:	7133 SECURITY BLVD
Contact City,State,Zip:	BALTIMORE, MD 21207
Contact Telephone:	301-944-5800
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	03
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported

CHADWICK CLEANERS (Continued) **1000193440**

Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		7133 SECURITY BLVD
Mailing City,State,Zip:		BALTIMORE, MD 21207
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20250514
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane,

CHADWICK CLEANERS (Continued) **1000193440**

Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: OPERNAME	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	OPERSTREET
Owner/Operator City,State,Zip:	OPERCITY, AK 99999
Owner/Operator Telephone:	215-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: BARBERIS, TERRY	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	OWNERSTREET
Owner/Operator City,State,Zip:	OWNERCITY, AK 99999
Owner/Operator Telephone:	215-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20250514
Handler Name: CHADWICK CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	19880426
Handler Name: CHADWICK CLEANERS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

CHADWICK CLEANERS (Continued) **1000193440**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20000223
Handler Name: CHADWICK CLEANERS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 81232
NAICS Description: Drycleaning And Laundry Services (Except Coin-Operated)

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported

CHADWICK CLEANERS (Continued) **1000193440**

Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20001128
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110003511584

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000193440
Registry ID:	110003511584

DFR URL:

Name:	CHADWICK CLEANERS
Address:	7133 Security Blvd
City,State,Zip:	BALTIMORE, MD 21207

N108 **KAISER PERMANENTE - ROCKVILLE MD** **RCRA-SQG** **1031487398**
WNW **7141 SECURITY BLVD** **E MANIFEST** **MDR000526244**
1/8-1/4 **BALTIMORE, MD 21244**
0.198 mi.
1045 ft. **Site 3 of 9 in cluster N**

Relative: **Lower**

Actual: **438 ft.**

RCRA Listings:

Date Form Received by Agency:	20241014
Handler Name:	Kaiser Permanente Mas - Woodlawn Mob
Handler Address:	Security Blvd
Handler City,State,Zip:	WINDSOR MILL, MD 21244
EPA ID:	MDR000526244
Contact Name:	DAVID H WELSH, III
Contact Address:	SECURITY BLVD
Contact City,State,Zip:	WINDSOR MILL, MD 21244
Contact Telephone:	202-515-6742
Contact Fax:	Not reported
Contact Email:	DAVID.H.WELSH-III@KP.ORG
Contact Title:	EHS SPECIALIST
EPA Region:	03
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities, State-specific Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	SECURITY BLVD
Mailing City,State,Zip:	WINDSOR MILL, MD 21244
Owner Name:	Kaiser Permanente Foundation Of The Mid-Atlantic States, Inc
Owner Type:	Private
Operator Name:	Kaiser Permanente Foundation Of The Mid-Atlantic States, Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	Y--
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

KAISER PERMANENTE - ROCKVILLE MD (Continued) **1031487398**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20250319
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D005
Waste Description:	Barium
Waste Code:	D011
Waste Description:	Silver
Waste Code:	LABP
Waste Description:	Lab Pack

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	KAISER PERMANENTE FOUNDATION OF THE MID-ATLANTIC STATES, INC
Legal Status:	Private
Date Became Current:	20241001
Date Ended Current:	Not reported
Owner/Operator Address:	4000 GARDEN CITY DRIVE
Owner/Operator City,State,Zip:	HYATTSVILLE, MD 20785
Owner/Operator Telephone:	202-515-6742
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	DAVID.H.WELSH-III@KP.ORG
Owner/Operator Indicator:	Owner
Owner/Operator Name:	KAISER PERMANENTE FOUNDATION OF THE MID-ATLANTIC STATES, INC
Legal Status:	Private
Date Became Current:	20241001
Date Ended Current:	Not reported
Owner/Operator Address:	4000 GARDEN CITY DRIVE
Owner/Operator City,State,Zip:	HYATTSVILLE, MD 20785
Owner/Operator Telephone:	202-515-6742
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

KAISER PERMANENTE - ROCKVILLE MD (Continued) **1031487398**

Owner/Operator Email: DAVID.H.WELSH-III@KP.ORG

Historic Generators:
Receive Date: 20241014
Handler Name: KAISER PERMANENTE MAS - WOODLAWN MOB
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 621112
NAICS Description: Offices Of Physicians, Mental Health Specialists

NAICS Code: 621491
NAICS Description: Hmo Medical Centers

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E MANIFEST:
Manifest Tracking Number: 018057358FLE
Last Updated Date: 20241120
Shipped Date: 20241022
Received Date: 20241112
Manifest Status: Signed
Submission Type: DataImage5Copy
Origin Type: Service
Generator EPA ID: CESQGXXXXXX
Generator Name: Kaiser Permanente - Rockville Md
Generator Location Street Number: Not reported
Generator Location Street 1: 7141 SECURITY BLVD
Generator Location Street 2: WOODLAWN MEDICAL CENTER
Generator Location City: BALTIMORE
Generator Location State: MD
Generator Location Zip: 21244
Generator Mail Street Number: Not reported
Generator Mail Street 1: 2101 E JEFFERSON ST
Generator Mail Street 2: Not reported
Generator Mail City: ROCKVILLE
Generator Mail Zip: 20852
Generator Mail State: MD
Generator Contact Company Name: Not reported
Designated Facility EPA ID: OHD048415665
Designated Facility Name: Ross Incineration Services, Inc.

KAISER PERMANENTE - ROCKVILLE MD (Continued) **1031487398**

Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	36790 GILES RD
Designated Facility Mail Street 2:	ROSS INCINERATION SERVICES, IN
Designated Facility Mail City:	GRAFTON
Designated Facility Mail Zip:	44044
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	36790 GILES RD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	GRAFTON
Designated Facility Location Zip:	44044
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	018057360FLE
Last Updated Date:	20241120
Shipped Date:	20241022
Received Date:	20241112
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQGXXXXXXX
Generator Name:	Kaiser Permanente - Rockville Md
Generator Location Street Number:	Not reported
Generator Location Street 1:	7141 SECURITY BLVD
Generator Location Street 2:	WOODLAWN MEDICAL CENTER
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2101 E JEFFERSON ST
Generator Mail Street 2:	Not reported
Generator Mail City:	ROCKVILLE
Generator Mail Zip:	20852
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD048415665
Designated Facility Name:	Ross Incineration Services, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	36790 GILES RD
Designated Facility Mail Street 2:	ROSS INCINERATION SERVICES, IN
Designated Facility Mail City:	GRAFTON
Designated Facility Mail Zip:	44044
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	36790 GILES RD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	GRAFTON
Designated Facility Location Zip:	44044
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	018059782FLE

KAISER PERMANENTE - ROCKVILLE MD (Continued) **1031487398**

Last Updated Date:	20240717
Shipped Date:	20240618
Received Date:	20240706
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQGXXXXXXX
Generator Name:	Kaiser Permanente - Rockville Md
Generator Location Street Number:	Not reported
Generator Location Street 1:	7141 SECURITY BLVD
Generator Location Street 2:	WOODLAWN MEDICAL CENTER
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2101 E JEFFERSON ST
Generator Mail Street 2:	Not reported
Generator Mail City:	ROCKVILLE
Generator Mail Zip:	20852
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD048415665
Designated Facility Name:	Ross Incineration Services, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	36790 GILES RD
Designated Facility Mail Street 2:	ROSS INCINERATION SERVICES, IN
Designated Facility Mail City:	GRAFTON
Designated Facility Mail Zip:	44044
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	36790 GILES RD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	GRAFTON
Designated Facility Location Zip:	44044
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	018059783FLE
Last Updated Date:	20240717
Shipped Date:	20240618
Received Date:	20240706
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQGXXXXXXX
Generator Name:	Kaiser Permanente - Rockville Md
Generator Location Street Number:	Not reported
Generator Location Street 1:	7141 SECURITY BLVD
Generator Location Street 2:	WOODLAWN MEDICAL CENTER
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2101 E JEFFERSON ST
Generator Mail Street 2:	Not reported

KAISER PERMANENTE - ROCKVILLE MD (Continued) **1031487398**

Generator Mail City:	ROCKVILLE
Generator Mail Zip:	20852
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD048415665
Designated Facility Name:	Ross Incineration Services, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	36790 GILES RD
Designated Facility Mail Street 2:	ROSS INCINERATION SERVICES, IN
Designated Facility Mail City:	GRAFTON
Designated Facility Mail Zip:	44044
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	36790 GILES RD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	GRAFTON
Designated Facility Location Zip:	44044
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	018060303FLE
Last Updated Date:	20240919
Shipped Date:	20240827
Received Date:	20240914
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQGXXXXXXX
Generator Name:	Kaiser Permanente - Rockville Md
Generator Location Street Number:	Not reported
Generator Location Street 1:	7141 SECURITY BLVD
Generator Location Street 2:	WOODLAWN MEDICAL CENTER
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2101 E JEFFERSON ST
Generator Mail Street 2:	Not reported
Generator Mail City:	ROCKVILLE
Generator Mail Zip:	20852
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD048415665
Designated Facility Name:	Ross Incineration Services, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	36790 GILES RD
Designated Facility Mail Street 2:	ROSS INCINERATION SERVICES, IN
Designated Facility Mail City:	GRAFTON
Designated Facility Mail Zip:	44044
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	36790 GILES RD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	GRAFTON
Designated Facility Location Zip:	44044

KAISER PERMANENTE - ROCKVILLE MD (Continued) **1031487398**

Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	018060304FLE
Last Updated Date:	20240919
Shipped Date:	20240827
Received Date:	20240914
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQGXXXXXXX
Generator Name:	Kaiser Permanente - Rockville Md
Generator Location Street Number:	Not reported
Generator Location Street 1:	7141 SECURITY BLVD
Generator Location Street 2:	WOODLAWN MEDICAL CENTER
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2101 E JEFFERSON ST
Generator Mail Street 2:	Not reported
Generator Mail City:	ROCKVILLE
Generator Mail Zip:	20852
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD048415665
Designated Facility Name:	Ross Incineration Services, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	36790 GILES RD
Designated Facility Mail Street 2:	ROSS INCINERATION SERVICES, IN
Designated Facility Mail City:	GRAFTON
Designated Facility Mail Zip:	44044
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	36790 GILES RD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	GRAFTON
Designated Facility Location Zip:	44044
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	011494877FLE
Last Updated Date:	20180924
Shipped Date:	20180828
Received Date:	20180913
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Kaiser Permanente
Generator Location Street Number:	Not reported
Generator Location Street 1:	7141 SECURITY BLVD
Generator Location Street 2:	Not reported

KAISER PERMANENTE - ROCKVILLE MD (Continued) **1031487398**

Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	7141 SECURITY BLVD
Generator Mail Street 2:	Not reported
Generator Mail City:	BALTIMORE
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD048415665
Designated Facility Name:	Ross Incineration Services Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	36790 GILES RD
Designated Facility Mail City:	GRAFTON
Designated Facility Mail Zip:	44044-9586
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	36790 GILES RD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	GRAFTON
Designated Facility Location Zip:	44044
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	011494877FLE
Last Updated Date:	20180924
Shipped Date:	20180828
Received Date:	20180913
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Kaiser Permanente
Generator Location Street Number:	Not reported
Generator Location Street 1:	7141 SECURITY BLVD
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	7141 SECURITY BLVD
Generator Mail Street 2:	Not reported
Generator Mail City:	BALTIMORE
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD048415665
Designated Facility Name:	Ross Incineration Services Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	36790 GILES RD
Designated Facility Mail City:	GRAFTON
Designated Facility Mail Zip:	44044-9586

KAISER PERMANENTE - ROCKVILLE MD (Continued) **1031487398**

Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	36790 GILES RD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	GRAFTON
Designated Facility Location Zip:	44044
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	012021444FLE
Last Updated Date:	20200629
Shipped Date:	20200527
Received Date:	20200607
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQGXXXXXXX
Generator Name:	Kaiser Permanente
Generator Location Street Number:	Not reported
Generator Location Street 1:	7141 SECURITY BLVD
Generator Location Street 2:	WOODLAWN MEDICAL CENTER
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2101 E JEFFERSON STREET
Generator Mail Street 2:	Not reported
Generator Mail City:	ROCKVILLE
Generator Mail Zip:	20852
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD048415665
Designated Facility Name:	Ross Incineration Services Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	36790 GILES RD
Designated Facility Mail City:	GRAFTON
Designated Facility Mail Zip:	44044
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	36790 GILES RD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	GRAFTON
Designated Facility Location Zip:	44044
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	012021444FLE
Last Updated Date:	20200629
Shipped Date:	20200527
Received Date:	20200607
Manifest Status:	Signed
Submission Type:	DataImage5Copy

KAISER PERMANENTE - ROCKVILLE MD (Continued) **1031487398**

Origin Type:	Service
Generator EPA ID:	CESQGXXXXXXX
Generator Name:	Kaiser Permanente
Generator Location Street Number:	Not reported
Generator Location Street 1:	7141 SECURITY BLVD
Generator Location Street 2:	WOODLAWN MEDICAL CENTER
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2101 E JEFFERSON STREET
Generator Mail Street 2:	Not reported
Generator Mail City:	ROCKVILLE
Generator Mail Zip:	20852
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD048415665
Designated Facility Name:	Ross Incineration Services Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	36790 GILES RD
Designated Facility Mail City:	GRAFTON
Designated Facility Mail Zip:	44044
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	36790 GILES RD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	GRAFTON
Designated Facility Location Zip:	44044
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	012021722FLE
Last Updated Date:	20201222
Shipped Date:	20201120
Received Date:	20201205
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQGXXXXXXX
Generator Name:	Kaiser Permanente
Generator Location Street Number:	Not reported
Generator Location Street 1:	7141 SECURITY BLVD
Generator Location Street 2:	WOODLAWN MEDICAL CENTER
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2101 E JEFFERSON STREET
Generator Mail Street 2:	Not reported
Generator Mail City:	ROCKVILLE
Generator Mail Zip:	20852
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD048415665

KAISER PERMANENTE - ROCKVILLE MD (Continued) **1031487398**

Designated Facility Name:	Ross Incineration Services Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	36790 GILES RD
Designated Facility Mail Street 2:	ROSS INCINERATION SERVICES, IN
Designated Facility Mail City:	GRAFTON
Designated Facility Mail Zip:	44044
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	36790 GILES RD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	GRAFTON
Designated Facility Location Zip:	44044
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	012021722FLE
Transporter Line Number:	1
Transporter EPA ID:	MAC300016672
Transporter Name:	Triumvirate Environmental, Inc

Manifest Tracking Number:	012021722FLE
Transporter Line Number:	2
Transporter EPA ID:	OHD980614374
Transporter Name:	Ross Transportation Services,

Waste Line:

Manifest Tracking Number:	012021722FLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN1493
U.S. DOT Description:	Un1493, Waste Silver Nitrate 5.1, Ii Rq:(D011)
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	DF
Container Type Description:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	5
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.0025
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.0025
Waste Quantity, in Kilograms:	2.267575
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	2.267575
Management Method Code:	H040
Management Method Description:	INCINERATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported

KAISER PERMANENTE - ROCKVILLE MD (Continued) **1031487398**

Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D001, D011
Quantity Haz Kg:	2.267575
Quantity Haz Tons:	0.0025
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	Not reported
Manifest Tracking Number:	012021722FLE
Waste Line Number:	2
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3077
U.S. DOT Description:	Na3077, Hazardous Waste, Solid, N.O.S. (Cresol, Mitomycin) 9, Iii
Non-Hazardous Waste Description:	Not reported
Number of Containers:	12
Container Type Code:	DF
Container Type Description:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	195
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.0975
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.0975
Waste Quantity, in Kilograms:	88.435425
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	88.435425
Management Method Code:	H040
Management Method Description:	INCINERATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D001, D005, D007, D010, D013, D024, U010, U035, U059, U089, U129, U132, U150, U200, U201, U204, U205, U236
Quantity Haz Kg:	88.435425
Quantity Haz Tons:	0.0975
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	Not reported

KAISER PERMANENTE - ROCKVILLE MD (Continued) **1031487398**

Click this hyperlink while viewing on your computer to access
26 additional US EManifest: record(s) in the EDR Site Report.

N109 **RITE AID #02209** **MD MANIFEST** **S121872072**
WNW **7153 SECURITY BLVD** **N/A**
1/8-1/4 **BALTIMORE, MD 21244**
0.203 mi.
1072 ft. **Site 4 of 9 in cluster N**

Relative:
Lower

Actual:
437 ft.

MD MANIFEST:

EPAID:	MDR000526131
Name:	RITE AID #02209
Address:	7153 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244-1811
Manifest Number:	016477632JJK
Transporter 1:	EQ NORTHEAST, INC
Transporter 2:	Not reported
Generator Certifier:	BRANDY BRANDFORD
Date Shipped Out:	12/12/2016
Destination Facility Certifier:	SHANE BIESE
Date Arrived at Destingation Facility:	12/16/2016
Quantity:	9
Unit:	Pounds

EPAID:	MDR000526131
Name:	RITE AID #02209
Address:	7153 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244-1811
Manifest Number:	016107214JJK
Transporter 1:	EQ NORTHEAST, INC.
Transporter 2:	Not reported
Generator Certifier:	MAGDALINE CHRISTIAN
Date Shipped Out:	04/05/2017
Destination Facility Certifier:	SHANE BIESE
Date Arrived at Destingation Facility:	04/07/2017
Quantity:	24
Unit:	Pounds

EPAID:	MDR000526131
Name:	RITE AID #02209
Address:	7153 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244-1811
Manifest Number:	016107839JJK
Transporter 1:	EQ NORTHEAST INC
Transporter 2:	Not reported
Generator Certifier:	KALEEN DEAN
Date Shipped Out:	11/07/2017
Destination Facility Certifier:	STEFANIEANA MHERSH
Date Arrived at Destingation Facility:	11/10/2017
Quantity:	6
Unit:	Pounds

EPAID:	MDR000526131
Name:	RITE AID #02209
Address:	7153 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244-1811
Manifest Number:	011690713FLE
Transporter 1:	CLEAN HARBORS ENVIRONMENTAL SERVICES

RITE AID #02209 (Continued) **S121872072**

Transporter 2:	ROBBIE D WOOD INC
Generator Certifier:	BRANDY BRANDFORD
Date Shipped Out:	03/07/2018
Destination Facility Certifier:	GINA CHAMBERS
Date Arrived at Destingation Facility:	03/21/2018
Quantity:	1
Unit:	Pounds

EPAID:	MDR000526131
Name:	RITE AID #02209
Address:	7153 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244-1811
Manifest Number:	015661496JJK
Transporter 1:	EQ NORTHEAST, INC.
Transporter 2:	Not reported
Generator Certifier:	INA FLAGER
Date Shipped Out:	08/30/2016
Destination Facility Certifier:	STEFANIEANA M HERSH
Date Arrived at Destingation Facility:	09/01/2016
Quantity:	21
Unit:	Pounds

EPAID:	MDR000526131
Name:	RITE AID #02209
Address:	7153 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244-1811
Manifest Number:	015530689JJK
Transporter 1:	EQ NORTHEAST, INC.
Transporter 2:	Not reported
Generator Certifier:	INA FLAGER
Date Shipped Out:	01/21/2016
Destination Facility Certifier:	STEFAMEANA M. LOWER
Date Arrived at Destingation Facility:	01/22/2016
Quantity:	22
Unit:	Pounds

EPAID:	MDR000526131
Name:	RITE AID #02209
Address:	7153 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244-1811
Manifest Number:	015662447JJK
Transporter 1:	EQ NORTHEAST, INC
Transporter 2:	Not reported
Generator Certifier:	INA FLAGER
Date Shipped Out:	05/12/2016
Destination Facility Certifier:	STEFANIEANA M. LOWER
Date Arrived at Destingation Facility:	05/12/2016
Quantity:	12
Unit:	Pounds

EPAID:	MDR000526131
Name:	RITE AID #02209
Address:	7153 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244-1811
Manifest Number:	013598377JJK
Transporter 1:	EQ NORTHEAST, INC.
Transporter 2:	Not reported

RITE AID #02209 (Continued) **S121872072**

Generator Certifier:	TINA FLAGER
Date Shipped Out:	08/14/2015
Destination Facility Certifier:	STEFANIEANA VAUGHT
Date Arrived at Destingation Facility:	08/14/2015
Quantity:	31
Unit:	POUNDS

EPAID:	MDR000526131
Name:	RITE AID #02209
Address:	7153 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244-1811
Manifest Number:	013598418JJK
Transporter 1:	EQ NORTHEAST INC
Transporter 2:	Not reported
Generator Certifier:	BRANDY BRANDFORD
Date Shipped Out:	10/29/2015
Destination Facility Certifier:	STEFANIEANA M. VAUGHT
Date Arrived at Destingation Facility:	10/30/2015
Quantity:	27
Unit:	POUNDS

EPAID:	MDR000526131
Name:	RITE AID #02209
Address:	7153 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244-1811
Manifest Number:	013600232JJK
Transporter 1:	EQ NORTHEAST INC
Transporter 2:	Not reported
Generator Certifier:	MAGELALIA CHASTIAN
Date Shipped Out:	05/21/2015
Destination Facility Certifier:	STEFANIEANA M. VAUGHT
Date Arrived at Destingation Facility:	05/22/2015
Quantity:	12
Unit:	POUNDS

EPAID:	MDR000526131
Name:	RITE AID #02209
Address:	7153 SECURITY BLVD
City,State,Zip:	BALTIMORE, MD 21244-1811
Manifest Number:	01362049JJK
Transporter 1:	EQ NORTHEAST INC
Transporter 2:	Not reported
Generator Certifier:	JASON MICHAEL
Date Shipped Out:	02/23/2015
Destination Facility Certifier:	STEFANIEANA M VAUGHT
Date Arrived at Destingation Facility:	02/27/2015
Quantity:	18
Unit:	POUNDS

Click this hyperlink while viewing on your computer to access
3 additional MD_MANIFEST: record(s) in the EDR Site Report.

N110 **RITE AID # 2209** **PA MANIFEST** **S118070310**
WNW **7153 SECURITY BOULEVARD** **N/A**
1/8-1/4 **BALTIMORE, MD 21244**
0.203 mi.
1072 ft. **Site 5 of 9 in cluster N**

Relative:
Lower

Actual:
437 ft.

PA MANIFEST:

Name:	RITE AID # 2209
Address:	7153 SECURITY BOULEVARD
City,State,Zip:	BALTIMORE, MD 21244
Year:	2014
Manifest Number:	012147762JJK
Manifest Type:	T
Generator EPA ID:	MDR000526131
Generator Date:	01/09/2014
Mailing Address:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA ID:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Envirite of Pennsylvania Inc
TSD Facility Address:	730 Vogelsong Rd
TSD Facility City:	York
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D035
Container Number:	1
Container Type:	DF
Waste Quantity:	1
Unit:	P
Handling Code:	Not reported
TSP EPA ID:	PAD010154045
Date TSP Sig:	Not reported
Year:	2014
Manifest Number:	012147762JJK
Manifest Type:	T
Generator EPA ID:	MDR000526131
Generator Date:	01/09/2014
Mailing Address:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA ID:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Envirite of Pennsylvania Inc
TSD Facility Address:	730 Vogelsong Rd
TSD Facility City:	York
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	DF
Waste Quantity:	1
Unit:	P
Handling Code:	Not reported

RITE AID # 2209 (Continued) **S118070310**

TSP EPA ID:	PAD010154045
Date TSP Sig:	Not reported
Year:	2014
Manifest Number:	012147762JJK
Manifest Type:	T
Generator EPA ID:	MDR000526131
Generator Date:	01/09/2014
Mailing Address:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA ID:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Envirite of Pennsylvania Inc
TSD Facility Address:	730 Vogelsong Rd
TSD Facility City:	York
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	U002
Container Number:	1
Container Type:	DM
Waste Quantity:	2
Unit:	P
Handling Code:	Not reported
TSP EPA ID:	PAD010154045
Date TSP Sig:	Not reported
Year:	2014
Manifest Number:	012147762JJK
Manifest Type:	T
Generator EPA ID:	MDR000526131
Generator Date:	01/09/2014
Mailing Address:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA ID:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Envirite of Pennsylvania Inc
TSD Facility Address:	730 Vogelsong Rd
TSD Facility City:	York
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D035
Container Number:	1
Container Type:	DM
Waste Quantity:	2
Unit:	P
Handling Code:	Not reported
TSP EPA ID:	PAD010154045
Date TSP Sig:	Not reported
Year:	2014
Manifest Number:	012147762JJK

RITE AID # 2209 (Continued) **S118070310**

Manifest Type:	T
Generator EPA ID:	MDR000526131
Generator Date:	01/09/2014
Mailing Address:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA ID:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Envirite of Pennsylvania Inc
TSD Facility Address:	730 Vogelsong Rd
TSD Facility City:	York
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D018
Container Number:	1
Container Type:	DM
Waste Quantity:	2
Unit:	P
Handling Code:	Not reported
TSP EPA ID:	PAD010154045
Date TSP Sig:	Not reported
Year:	2014
Manifest Number:	012147762JJK
Manifest Type:	T
Generator EPA ID:	MDR000526131
Generator Date:	01/09/2014
Mailing Address:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA ID:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Envirite of Pennsylvania Inc
TSD Facility Address:	730 Vogelsong Rd
TSD Facility City:	York
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D001
Container Number:	1
Container Type:	DM
Waste Quantity:	2
Unit:	P
Handling Code:	Not reported
TSP EPA ID:	PAD010154045
Date TSP Sig:	Not reported
Year:	2014
Manifest Number:	012147762JJK
Manifest Type:	T
Generator EPA ID:	MDR000526131
Generator Date:	01/09/2014
Mailing Address:	Not reported
Contact Name:	Not reported

RITE AID # 2209 (Continued) **S118070310**

Contact Phone:	Not reported
TSD EPA ID:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Envirite of Pennsylvania Inc
TSD Facility Address:	730 Vogelsong Rd
TSD Facility City:	York
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	3
Waste Number:	P001
Container Number:	1
Container Type:	DF
Waste Quantity:	1
Unit:	P
Handling Code:	Not reported
TSP EPA ID:	PAD010154045
Date TSP Sig:	Not reported

N111 **DBA RITE AID # 2209** **RCRA NonGen / NLR** **1016141928**
WNW **7153 SECURITY BLVD** **FINDS** **MDR000526131**
1/8-1/4 **BALTIMORE, MD 21244** **ECHO**
0.203 mi. **E MANIFEST**
1072 ft. **Site 6 of 9 in cluster N**

Relative: **Lower**
Actual: **437 ft.**

RCRA Listings:

Date Form Received by Agency:		20180807
Handler Name:		Dba Rite Aid # 2209
Handler Address:		7153 Security Blvd
Handler City,State,Zip:		BALTIMORE, MD 21244
EPA ID:		MDR000526131
Contact Name:		KIM DASCOLI
Contact Address:		104 WILMOT RD, MS 1434
Contact City,State,Zip:		DEERFIELD, IL 60015
Contact Telephone:		847-315-2602
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		COMPLIANCE OFFICER
EPA Region:		03
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		300 WILMOT ROAD MS#3301
Mailing City,State,Zip:		DEERFIELD, IL 60015
Owner Name:	Chadwick Manor, Llc	
Owner Type:		Private
Operator Name:	Walgreens	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No

DBA RITE AID # 2209 (Continued) **1016141928**

Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20180810
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D005
Waste Description:	Barium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D009
Waste Description:	Mercury
Waste Code:	D010
Waste Description:	Selenium
Waste Code:	D011

DBA RITE AID # 2209 (Continued) **1016141928**

Waste Description:	Silver
Waste Code:	D013
Waste Description:	Lindane (1,2,3,4,5,6-Hexa-Chlorocyclohexane, Gamma Isomer)
Waste Code:	D016
Waste Description:	2,4-D (2,4-Dichlorophenoxyacetic Acid)
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	D024
Waste Description:	M-Cresol
Waste Code:	D026
Waste Description:	Cresol
Waste Code:	D027
Waste Description:	1,4-Dichlorobenzene
Waste Code:	D035
Waste Description:	Methyl Ethyl Ketone
Waste Code:	P001
Waste Description:	2h-1-Benzopyran-2-One, 4-Hydroxy-3-(3-Oxo-1-Phenylbutyl)-, & Salts, When Present At Concentrations Greater Than 0.3% (Or) Warfarin, & Salts, When Present At Concentrations Greater Than 0.3%
Waste Code:	P042
Waste Description:	1,2-Benzenediol, 4-[1-Hydroxy-2-(Methylamino)Ethyl]-, (R)- (Or) Epinephrine
Waste Code:	P072
Waste Description:	Alpha-Naphthylthiourea (Or) Thiourea, 1-Naphthalenyl-
Waste Code:	P075
Waste Description:	Nicotine, & Salts (Or) Pyridine, 3-(1-Methyl-2-Pyrrolidinyl)-,(S)-, & Salts
Waste Code:	U002
Waste Description:	2-Propanone (I) (Or) Acetone (I)
Waste Code:	U035
Waste Description:	Benzenebutanoic Acid, 4-[Bis(2-Chloroethyl)Amino]- (Or) Chlorambucil
Waste Code:	U044
Waste Description:	Chloroform (Or) Methane, Trichloro-
Waste Code:	U058
Waste Description:	2h-1,3,2-Oxazaphosphorin-2-Amine, N,N-Bis(2-Chloroethyl)Tetrahydro-, 2-Oxide (Or) Cyclophosphamide
Waste Code:	U072
Waste Description:	Benzene, 1,4-Dichloro- (Or) P-Dichlorobenzene
Waste Code:	U122
Waste Description:	Formaldehyde

DBA RITE AID # 2209 (Continued) **1016141928**

Waste Code: U129
Waste Description: Cyclohexane, 1,2,3,4,5,6-Hexachloro-, (1alpha, 2alpha, 3beta, 4alpha, 5alpha, 6beta)- (Or) Lindane

Waste Code: U154
Waste Description: Methanol (I) (Or) Methyl Alcohol (I)

Waste Code: U165
Waste Description: Naphthalene

Waste Code: U172
Waste Description: 1-Butanamine, N-Butyl-N-Nitroso- (Or) N-Nitrosodi-N-Butylamine

Waste Code: U205
Waste Description: Selenium Sulfide (Or) Selenium Sulfide Ses2 (R,T)

Waste Code: U211
Waste Description: Carbon Tetrachloride (Or) Methane, Tetrachloro-

Waste Code: U240
Waste Description: 2,4-D, Salts & Esters (Or) Acetic Acid, (2,4-Dichlorophenoxy)-, Salts & Esters (Or) Dichlorophenoxyacetic Acid 2,4-D

Waste Code: U279
Waste Description: U279

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: RITE AID OF MARYLAND, INC
Legal Status: Private
Date Became Current: 19870306
Date Ended Current: Not reported
Owner/Operator Address: 30 HUNTER LANE
Owner/Operator City,State,Zip: CAMP HILL, PA 17011
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CHADWICK MANOR, LLC
Legal Status: Private
Date Became Current: 19701001
Date Ended Current: Not reported
Owner/Operator Address: C/O DAVID S BROWN
Owner/Operator City,State,Zip: OWINGS MILLS, MD 21244
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CHADWICK MANOR, LLC
Legal Status: Private
Date Became Current: 19701001
Date Ended Current: Not reported
Owner/Operator Address: C/O DAVID S BROWN

DBA RITE AID # 2209 (Continued) **1016141928**

Owner/Operator City,State,Zip: OWINGS MILLS, MD 21244
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: WALGREENS
Legal Status: Private
Date Became Current: 20180302
Date Ended Current: Not reported
Owner/Operator Address: 200 WILMOT RD
Owner/Operator City,State,Zip: DEERFIELD, IL 60015
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CHADWICK MANOR LLC
Legal Status: Private
Date Became Current: 19701001
Date Ended Current: Not reported
Owner/Operator Address: 100 PAINTERS MILL RD STE 900
Owner/Operator City,State,Zip: OWINGS MILLS, MD 21117
Owner/Operator Telephone: 410-363-3434
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CHADWICK MANOR, LLC
Legal Status: Private
Date Became Current: 19701001
Date Ended Current: Not reported
Owner/Operator Address: C/O DAVID S BROWN
Owner/Operator City,State,Zip: OWINGS MILLS, MD 21244
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: RITE AID OF MARYLAND, INC
Legal Status: County
Date Became Current: 19870306
Date Ended Current: Not reported
Owner/Operator Address: 30 HUNTER LANE
Owner/Operator City,State,Zip: CAMP HILL, PA 17011
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: RITE AID OF MARYLAND, INC
Legal Status: Private

DBA RITE AID # 2209 (Continued) **1016141928**

Date Became Current:	19870306
Date Ended Current:	Not reported
Owner/Operator Address:	30 HUNTER LANE
Owner/Operator City,State,Zip:	CAMP HILL, PA 17011
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: RITE AID OF MARYLAND, INC	
Legal Status:	Private
Date Became Current:	19870306
Date Ended Current:	Not reported
Owner/Operator Address:	30 HUNTER LANE
Owner/Operator City,State,Zip:	CAMP HILL, PA 17011
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: WALGREENS	
Legal Status:	Private
Date Became Current:	20180302
Date Ended Current:	Not reported
Owner/Operator Address:	200 WILMOT RD
Owner/Operator City,State,Zip:	DEERFIELD, IL 60015
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: RITE AID CORPORATION	
Legal Status:	County
Date Became Current:	19870306
Date Ended Current:	Not reported
Owner/Operator Address:	30 HUNTER LANE
Owner/Operator City,State,Zip:	CAMP HILL, PA 17011
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CHADWICK MANOR, LLC	
Legal Status:	Private
Date Became Current:	19701001
Date Ended Current:	Not reported
Owner/Operator Address:	C/O DAVID S BROWN
Owner/Operator City,State,Zip:	OWINGS MILLS, MD 21244
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

DBA RITE AID # 2209 (Continued) **1016141928**

Historic Generators:

Receive Date:		20130129
Handler Name:	RITE AID # 2209	
Federal Waste Generator Description:		Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner:		Not reported
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20150319
Handler Name:	RITE AID # 2209	
Federal Waste Generator Description:		Large Quantity Generator
State District Owner:		Not reported
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20151116
Handler Name:	RITE AID # 2209	
Federal Waste Generator Description:		Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner:		Not reported
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20150904
Handler Name:	RITE AID # 2209	
Federal Waste Generator Description:		Large Quantity Generator
State District Owner:		Not reported
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20180117
Handler Name:	DBA RITE AID # 2209	

DBA RITE AID # 2209 (Continued) **1016141928**

Federal Waste Generator Description:	Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20180807
Handler Name:	DBA RITE AID # 2209
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	446110
NAICS Description:	Pharmacies And Drug Stores

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FINDS:

Registry ID: 110055449260

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016141928
Registry ID:	110055449260

DBA RITE AID # 2209 (Continued) **1016141928**

DFR URL:
Name: DBA RITE AID # 2209
Address: 7153 Security Blvd
City,State,Zip: BALTIMORE, MD 21244

E MANIFEST:

Manifest Tracking Number:	011852374FLE
Last Updated Date:	20180926
Shipped Date:	20180717
Received Date:	20180808
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDR000526131
Generator Name:	Dba Rite Aid 2209
Generator Location Street Number:	Not reported
Generator Location Street 1:	7153 SECURITY BLVD
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	7153 Security Blvd
Generator Mail Street 2:	Not reported
Generator Mail City:	Baltimore
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NCD000648451
Designated Facility Name:	Clean Harbors Reidsville Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	208 Watlington Industrial Drive
Designated Facility Mail City:	Reidsville
Designated Facility Mail Zip:	27320
Designated Facility Mail State:	NC
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	208 Watlington Industrial Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Reidsville
Designated Facility Location Zip:	27320
Designated Facility Location State:	NC
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	011852374FLE
Transporter Line Number:	1
Transporter EPA ID:	MAD039322250
Transporter Name:	Clean Harbors Environmental Services, Inc.
Manifest Tracking Number:	011852374FLE
Transporter Line Number:	2
Transporter EPA ID:	NJD986607380

DBA RITE AID # 2209 (Continued) **1016141928**

Transporter Name: Maumee Express Incorporated

Manifest Tracking Number: 011852374FLE
Transporter Line Number: 3
Transporter EPA ID: NJD986607380
Transporter Name: Maumee Express Incorporated

Waste Line:
Manifest Tracking Number: 011852374FLE
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: UN1950
U.S. DOT Description: Un1950, Waste Aerosols, Flammable, (Acetone, Methyl Ethyl Ketone), 2.1, None
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: DF
Container Type Description: Fiberboard or plastic drums, barrels, kegs
Waste Quantity: 2
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.001
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.001
Waste Quantity, in Kilograms: 0.90703005
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 0.90703005
Management Method Code: H141
Management Method Description: STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y
Federal Waste Codes: D001, D035
Quantity Haz Kg: 0.90703005
Quantity Haz Tons: 0.001
Quantity Non Haz Kg: 0
Quantity Non Haz Tons: 0
State Waste Codes: Not reported

Manifest Tracking Number: 011852374FLE
Waste Line Number: 2
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: UN1978
U.S. DOT Description: Un1978, Propane, 2.1, None
Non-Hazardous Waste Description: Not reported
Number of Containers: 1

DBA RITE AID # 2209 (Continued) **1016141928**

Container Type Code:	DF
Container Type Description:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	2
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.001
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.001
Waste Quantity, in Kilograms:	0.90703005
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	0.90703005
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not reported
Quantity Haz Kg:	0
Quantity Haz Tons:	0
Quantity Non Haz Kg:	0.90703005
Quantity Non Haz Tons:	0.001
State Waste Codes:	Not reported

Manifest Tracking Number:	011852374FLE
Waste Line Number:	3
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN1993
U.S. DOT Description:	Un1993, Waste Flammable Liquids, N.O.S. (Alcohol, Acetone), 3, Pg Ii
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	DF
Container Type Description:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	6
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.003
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.003
Waste Quantity, in Kilograms:	2.72109
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	2.72109
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N

DBA RITE AID # 2209 (Continued) **1016141928**

Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D001, D005, D007, D011, D018, D035, U002, U154
Quantity Haz Kg:	2.72109
Quantity Haz Tons:	0.003
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	Not reported
Manifest Tracking Number:	011852374FLE
Waste Line Number:	4
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN3139
U.S. DOT Description:	Un3139, Waste Oxidizing Liquid, N.O.S (Calcium Hypochlorite), 5.1, Pg Ii
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	DF
Container Type Description:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	9
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.0045
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.0045
Waste Quantity, in Kilograms:	4.081635
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	4.081635
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D001
Quantity Haz Kg:	4.081635
Quantity Haz Tons:	0.0045
Quantity Non Haz Kg:	0

DBA RITE AID # 2209 (Continued) **1016141928**

Quantity Non Haz Tons: 0
State Waste Codes: Not reported

Manifest Tracking Number: 011852374FLE
Waste Line Number: 5
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: UN2810
U.S. DOT Description: Un2810, Waste Toxic Liquids, Organic, N.O.S (2,4-D, Phenol), 6.1, Pg Ii
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: DF
Container Type Description: Fiberboard or plastic drums, barrels, kegs
Waste Quantity: 1
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.0005
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.0005
Waste Quantity, in Kilograms: 0.45351502
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 0.45351502
Management Method Code: H141
Management Method Description: STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y
Federal Waste Codes: D004, D005, D007, D010, D011, D016, D019, D022, D024, D026, U035, U044, U058, U072, U129, U150, U188, U200, U201, U211, U279
Quantity Haz Kg: 0.45351502
Quantity Haz Tons: 0.0005
Quantity Non Haz Kg: 0
Quantity Non Haz Tons: 0
State Waste Codes: Not reported

Manifest Tracking Number: 011852374FLE
Waste Line Number: 6
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: UN3077
U.S. DOT Description: Un3077, Environmentally Hazardous Substances, Solid, N.O.S. (Mercury), 9, Pg Iii, Universal Waste Mercury Lamps
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: DF
Container Type Description: Fiberboard or plastic drums, barrels, kegs
Waste Quantity: 2

DBA RITE AID # 2209 (Continued) **1016141928**

Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.001
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.001
Waste Quantity, in Kilograms:	0.90703005
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	0.90703005
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not reported
Quantity Haz Kg:	0
Quantity Haz Tons:	0
Quantity Non Haz Kg:	0.90703005
Quantity Non Haz Tons:	0.001
State Waste Codes:	Not reported

Manifest Tracking Number:	011852374FLE
Waste Line Number:	7
U.S. DOT Hazardous Indicator:	N
U.S. DOT ID Number:	Not reported
U.S. DOT Description:	Not reported
Non-Hazardous Waste Description:	N/A, Non Dot Regulated Material (Soaps And Lotions), N/A, None
Number of Containers:	2
Container Type Code:	CF
Container Type Description:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	170
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.085
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.085
Waste Quantity, in Kilograms:	77.09756
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	77.09756
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported

DBA RITE AID # 2209 (Continued) **1016141928**

Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not reported
Quantity Haz Kg:	0
Quantity Haz Tons:	0
Quantity Non Haz Kg:	77.09756
Quantity Non Haz Tons:	0.085
State Waste Codes:	Not reported
Manifest Tracking Number:	011852374FLE
Waste Line Number:	8
U.S. DOT Hazardous Indicator:	N
U.S. DOT ID Number:	Not reported
U.S. DOT Description:	Not reported
Non-Hazardous Waste Description:	None, Batteries, Dry, Sealed, N.O.S. (Alkaline Dry Cell Batteries,Nicad Batteries), N/A, None
Number of Containers:	1
Container Type Code:	DF
Container Type Description:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	3
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.0015
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.0015
Waste Quantity, in Kilograms:	1.360545
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	1.360545
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not reported
Quantity Haz Kg:	0
Quantity Haz Tons:	0
Quantity Non Haz Kg:	1.360545
Quantity Non Haz Tons:	0.0015
State Waste Codes:	Not reported

DBA RITE AID # 2209 (Continued) **1016141928**

Manifest Tracking Number:	011852374FLE
Waste Line Number:	9
U.S. DOT Hazardous Indicator:	N
U.S. DOT ID Number:	Not reported
U.S. DOT Description:	Not reported
Non-Hazardous Waste Description:	None, Non D.O.T. Regulated (Electronics Universal Waste), N/A, None
Number of Containers:	1
Container Type Code:	DF
Container Type Description:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	13
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.0065
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.0065
Waste Quantity, in Kilograms:	5.895695
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	5.895695
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not reported
Quantity Haz Kg:	0
Quantity Haz Tons:	0
Quantity Non Haz Kg:	5.895695
Quantity Non Haz Tons:	0.0065
State Waste Codes:	Not reported

P112 **MIL SPEC PAINTING INC** **E MANIFEST** **1031592641**
NE **1720 BELMONT AVE STE G** **N/A**
1/8-1/4 **BALTIMORE, MD 21244**
0.205 mi.
1080 ft. **Site 1 of 11 in cluster P**

Relative: E MANIFEST:
Lower

Actual: Manifest Tracking Number:	008498645SKS
405 ft. Last Updated Date:	20221001
Shipped Date:	20220816
Received Date:	20220901
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDR000006262
Generator Name:	Mil Spec Painting Inc
Generator Location Street Number:	Not reported

MIL SPEC PAINTING INC (Continued) **1031592641**

Generator Location Street 1:	1720 BELMONT AVE STE G
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1720 Belmont Ave Ste G
Generator Mail Street 2:	Not reported
Generator Mail City:	Baltimore
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	MIL Spec Painting Inc
Designated Facility EPA ID:	OHD000816629
Designated Facility Name:	Spring Grove Resource Recovery Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	4879 Spring Grove Avenue
Designated Facility Mail City:	Cincinnati
Designated Facility Mail Zip:	45232
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	4879 Spring Grove Avenue
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Cincinnati
Designated Facility Location Zip:	45232
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	008498646SKS
Last Updated Date:	20221010
Shipped Date:	20220816
Received Date:	20220920
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDR000006262
Generator Name:	Mil Spec Painting Inc
Generator Location Street Number:	Not reported
Generator Location Street 1:	1720 BELMONT AVE STE G
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1720 Belmont Ave Ste G
Generator Mail Street 2:	Not reported
Generator Mail City:	Baltimore
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	MIL Spec Painting Inc
Designated Facility EPA ID:	KYD053348108
Designated Facility Name:	Safety-Kleen Systems, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	3700 LaGrange Road

MIL SPEC PAINTING INC (Continued) **1031592641**

Designated Facility Mail City:	Smithfield
Designated Facility Mail Zip:	40068
Designated Facility Mail State:	KY
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	3700 LaGrange Road
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Smithfield
Designated Facility Location Zip:	40068
Designated Facility Location State:	KY
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	008498713SKS
Last Updated Date:	20221026
Shipped Date:	20220907
Received Date:	20221003
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDR000006262
Generator Name:	Mil Spec Painting Inc
Generator Location Street Number:	Not reported
Generator Location Street 1:	1720 BELMONT AVE STE G
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1720 Belmont Ave Ste G
Generator Mail Street 2:	Not reported
Generator Mail City:	Baltimore
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	MIL Spec Painting Inc
Designated Facility EPA ID:	ARD069748192
Designated Facility Name:	Clean Harbors El Dorado Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	309 American Circle
Designated Facility Mail City:	El Dorado
Designated Facility Mail Zip:	71730
Designated Facility Mail State:	AR
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	309 American Circle
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	El Dorado
Designated Facility Location Zip:	71730
Designated Facility Location State:	AR
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	008498823SKS
Last Updated Date:	20230116
Shipped Date:	20221202
Received Date:	20221227

MIL SPEC PAINTING INC (Continued) **1031592641**

Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDR000006262
Generator Name:	Mil Spec Painting Inc
Generator Location Street Number:	Not reported
Generator Location Street 1:	1720 BELMONT AVE STE G
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1720 Belmont Ave Ste G
Generator Mail Street 2:	Not reported
Generator Mail City:	Baltimore
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	MIL Spec Painting Inc
Designated Facility EPA ID:	ILD980613913
Designated Facility Name:	Safety-Kleen Systems, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	633 East 138th Street
Designated Facility Mail City:	Dolton
Designated Facility Mail Zip:	60419
Designated Facility Mail State:	IL
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	633 East 138th Street
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Dolton
Designated Facility Location Zip:	60419
Designated Facility Location State:	IL
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	006854401SKS
Last Updated Date:	20190513
Shipped Date:	20190329
Received Date:	20190416
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDR000006262
Generator Name:	Mil Spec Painting Inc
Generator Location Street Number:	Not reported
Generator Location Street 1:	1720 BELMONT AVE STE G
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1720 Belmont Ave Ste G
Generator Mail Street 2:	Not reported
Generator Mail City:	Baltimore
Generator Mail Zip:	21244
Generator Mail State:	MD

MIL SPEC PAINTING INC (Continued) **1031592641**

Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	ILD980613913
Designated Facility Name:	Safety-Kleen Systems, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	633 East 138th Street
Designated Facility Mail City:	Dolton
Designated Facility Mail Zip:	60419
Designated Facility Mail State:	IL
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	633 East 138th Street
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Dolton
Designated Facility Location Zip:	60419
Designated Facility Location State:	IL
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	008101055SKS
Last Updated Date:	20220804
Shipped Date:	20220701
Received Date:	20220715
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDR000006262
Generator Name:	Mil Spec Painting Inc
Generator Location Street Number:	Not reported
Generator Location Street 1:	1720 BELMONT AVE STE G
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1720 Belmont Ave Ste G
Generator Mail Street 2:	Not reported
Generator Mail City:	Baltimore
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	MIL Spec Painting Inc
Designated Facility EPA ID:	ILD980613913
Designated Facility Name:	Safety-Kleen Systems, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	633 East 138th Street
Designated Facility Mail City:	Dolton
Designated Facility Mail Zip:	60419
Designated Facility Mail State:	IL
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	633 East 138th Street
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Dolton
Designated Facility Location Zip:	60419
Designated Facility Location State:	IL
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N

MIL SPEC PAINTING INC (Continued) **1031592641**

Rejection Indicator:	N
Manifest Tracking Number:	008101106SKS
Last Updated Date:	20220308
Shipped Date:	20220127
Received Date:	20220210
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDR000006262
Generator Name:	Mil Spec Painting Inc
Generator Location Street Number:	Not reported
Generator Location Street 1:	1720 BELMONT AVE STE G
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1720 Belmont Ave Ste G
Generator Mail Street 2:	Not reported
Generator Mail City:	Baltimore
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	MIL Spec Painting Inc
Designated Facility EPA ID:	KYD053348108
Designated Facility Name:	Safety-Kleen Systems, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	3700 LaGrange Road
Designated Facility Mail City:	Smithfield
Designated Facility Mail Zip:	40068
Designated Facility Mail State:	KY
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	3700 LaGrange Road
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Smithfield
Designated Facility Location Zip:	40068
Designated Facility Location State:	KY
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	007882949SKS
Last Updated Date:	20230807
Shipped Date:	20230620
Received Date:	20230717
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDR000006262
Generator Name:	Mil Spec Painting Inc
Generator Location Street Number:	Not reported
Generator Location Street 1:	1720 BELMONT AVE STE G
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244

MIL SPEC PAINTING INC (Continued) **1031592641**

Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1720 Belmont Ave Ste G
Generator Mail Street 2:	Not reported
Generator Mail City:	Baltimore
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	MIL Spec Painting Inc
Designated Facility EPA ID:	ILD980613913
Designated Facility Name:	Safety-Kleen Systems, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	633 East 138th Street
Designated Facility Mail City:	Dolton
Designated Facility Mail Zip:	60419
Designated Facility Mail State:	IL
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	633 East 138th Street
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Dolton
Designated Facility Location Zip:	60419
Designated Facility Location State:	IL
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	009165600SKS
Last Updated Date:	20241216
Shipped Date:	20241004
Received Date:	20241023
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDR000006262
Generator Name:	Mil Spec Painting Inc
Generator Location Street Number:	1720
Generator Location Street 1:	1720 BELMONT AVE STE G
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	1720
Generator Mail Street 1:	BELMONT AVE STE G
Generator Mail Street 2:	Not reported
Generator Mail City:	BALTIMORE
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	MIL SPEC PAINTING INC
Designated Facility EPA ID:	NJD002182897
Designated Facility Name:	Safety-Kleen Systems, Inc.
Designated Facility Mail Street Number:	1200
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	SYLVAN STREET
Designated Facility Mail City:	LINDEN
Designated Facility Mail Zip:	07036
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	1200
Designated Facility Location Street 1:	SYLVAN STREET

MIL SPEC PAINTING INC (Continued) **1031592641**

Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	LINDEN
Designated Facility Location Zip:	07036
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	009165609SKS
Last Updated Date:	20241203
Shipped Date:	20241022
Received Date:	20241107
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDR000006262
Generator Name:	Mil Spec Painting Inc
Generator Location Street Number:	1720
Generator Location Street 1:	1720 BELMONT AVE STE G
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	1720
Generator Mail Street 1:	BELMONT AVE STE G
Generator Mail Street 2:	Not reported
Generator Mail City:	BALTIMORE
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	MIL SPEC PAINTING INC
Designated Facility EPA ID:	NJD002182897
Designated Facility Name:	Safety-Kleen Systems, Inc.
Designated Facility Mail Street Number:	1200
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	SYLVAN STREET
Designated Facility Mail City:	LINDEN
Designated Facility Mail Zip:	07036
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	1200
Designated Facility Location Street 1:	SYLVAN STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	LINDEN
Designated Facility Location Zip:	07036
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	008615843SKS
Last Updated Date:	20230705
Shipped Date:	20230517
Received Date:	20230614
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDR000006262
Generator Name:	Mil Spec Painting Inc

MIL SPEC PAINTING INC (Continued) **1031592641**

Generator Location Street Number:	Not reported
Generator Location Street 1:	1720 BELMONT AVE STE G
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1720 Belmont Ave Ste G
Generator Mail Street 2:	Not reported
Generator Mail City:	Baltimore
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	MIL Spec Painting Inc
Designated Facility EPA ID:	ILD980613913
Designated Facility Name:	Safety-Kleen Systems, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	633 East 138th Street
Designated Facility Mail City:	Dolton
Designated Facility Mail Zip:	60419
Designated Facility Mail State:	IL
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	633 East 138th Street
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Dolton
Designated Facility Location Zip:	60419
Designated Facility Location State:	IL
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	006815525SKS
Transporter Line Number:	1
Transporter EPA ID:	TXR000081205
Transporter Name:	Safety-Kleen Systems, Inc.
Manifest Tracking Number:	006815525SKS
Transporter Line Number:	2
Transporter EPA ID:	MAD039322250
Transporter Name:	Clean Harbors Environmental Services, Inc.
Manifest Tracking Number:	006815525SKS
Transporter Line Number:	3
Transporter EPA ID:	MAD039322250
Transporter Name:	Clean Harbors Environmental Services, Inc.

Waste Line:

Manifest Tracking Number:	006815525SKS
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN1263
U.S. DOT Description:	Un1263, Waste Un1263 Waste Paint Related Material,3, Pg Ii, (Erg#128)(F003,D001,D018,D035,D039,D040), 3, Pg Ii
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1

MIL SPEC PAINTING INC (Continued) **1031592641**

Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	10
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.005
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.005
Waste Quantity, in Kilograms:	4.53515
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	4.53515
Management Method Code:	H020
Management Method Description:	SOLVENTS RECOVERY
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D001, D018, D035, D039, D040, F003
Quantity Haz Kg:	4.53515
Quantity Haz Tons:	0.005
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	Not reported

Click this hyperlink while viewing on your computer to access
31 additional US EManifest: record(s) in the EDR Site Report.

P113 **SECURITY BOULEVARD SITE** **MD LRP** **S110090358**
NE **1718 BELMONT AVENUE** **N/A**
1/8-1/4 **BALTIMORE, MD 21244**
0.205 mi.
1080 ft. **Site 2 of 11 in cluster P**

Relative:
Lower

Actual:
405 ft.

MD LRP:

Name:	SECURITY BOULEVARD SITE
Address:	1718 Belmont Avenue
City,State,Zip:	BALTIMORE, MD 21244

Factsheet URL:

Voluntary Cleanup Program:	No
Brownfield Assesment Complete:	No
NPL:	No
Federal Facility:	No
Alias:	Not reported
Groundwater:	No
Assessment On-Going:	No
Remediation On-Going:	No
Withdrawn:	No

SECURITY BOULEVARD SITE (Continued) **S110090358**

GW Chlorinated:	No
GW Petroleum:	No
GW Metals:	No
GW Pesticides:	No
GW PCB:	No
GW PAH:	No
Soil Chlorinated:	No
Soil Metals:	No
Soil Pesticides:	No
Soil PCB:	No
Soil PAH:	No
Soil Petroleum:	No
Sediment Chlorinated:	No
Sediment Petroleum:	No
Sediment Metals:	No
Sediment Pesticides:	No
Sediment PCB:	No
Sediment PAH:	No
SW Chlorinated:	No
SW Petroleum:	No
SW Metals:	No
SW Pesticides:	No
SW PCB:	No
SW PAH:	No
Site Assessment:	Yes
Tax Map Number:	Not reported
File Available:	Yes
BMI Number:	MD0188
Archived:	Yes
Table Site ID:	442
Parcel Number:	Not reported
Block:	Not reported
Lot Number:	Not reported
Tax ID:	Not reported
Det Issued:	No
Enfor congo:	No
CHS Oversig:	Yes
EPAID:	MDD981035405
Regulatory:	Not reported
FY Open:	Not reported
FY_Closed:	2012

P114 **MIL-SPEC PAINTING INC** **RCRA-SQG** **1011844006**
NE **1720 BELMONT AVE** **E MANIFEST** **MDR000006262**
1/8-1/4 **WINDSOR MILL, MD 21244** **NJ MANIFEST**
0.205 mi.
1080 ft. **Site 3 of 11 in cluster P**

Relative: **Lower**
Actual: **405 ft.**

RCRA Listings:

Date Form Received by Agency:	20240216
Handler Name:	Mil-Spec Painting Inc
Handler Address:	Belmont Ave
Handler City,State,Zip:	WINDSOR MILL, MD 21244
EPA ID:	MDR000006262
Contact Name:	EMILY CARTER
Contact Address:	BELMONT AVE, STE G
Contact City,State,Zip:	WINDSOR MILL, MD 21244
Contact Telephone:	410-265-1019

MIL-SPEC PAINTING INC (Continued) **1011844006**

Contact Fax:		Not reported
Contact Email:		INFO@MILSPECPAINTING.COM
Contact Title:		CFO
EPA Region:		03
Land Type:		Private
Federal Waste Generator Description:		Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		2023
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		BELMONT AVE
Mailing City,State,Zip:		WINDSOR MILL, MD 21244
Owner Name:	Investors Management Co	
Owner Type:		Private
Operator Name:	Mil-Spec Painting Inc	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20240922
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No

MIL-SPEC PAINTING INC (Continued) **1011844006**

Sub-Part P Indicator: No

Biennial: List of Years
Year: 2023

Click Here for Biennial Reporting System Data:
Year: 2021

Click Here for Biennial Reporting System Data:
Year: 2019

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: D005
Waste Description: Barium

Waste Code: D006
Waste Description: Cadmium

Waste Code: D007
Waste Description: Chromium

Waste Code: D008
Waste Description: Lead

Waste Code: D018
Waste Description: Benzene

Waste Code: D035
Waste Description: Methyl Ethyl Ketone

Waste Code: D036
Waste Description: Nitrobenzene

Waste Code: D039
Waste Description: Tetrachloroethylene

Waste Code: D040
Waste Description: Trichloroethylene

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still

MIL-SPEC PAINTING INC (Continued) **1011844006**

Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: INVESTORS MANAGEMENT CO	
Legal Status:	Private
Date Became Current:	19790105
Date Ended Current:	Not reported
Owner/Operator Address:	2528 MARYLAND AVE
Owner/Operator City,State,Zip:	BALTIMORE, MD 21218
Owner/Operator Telephone:	410-235-1220
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	INFO@INVESTORSMGMT.COM

Owner/Operator Indicator:	Owner
Owner/Operator Name: RAYMOND MAHAFFEY	
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	15 PERRY RIDGE CT
Owner/Operator City,State,Zip:	BALTIMORE, MD 21237
Owner/Operator Telephone:	410-882-8658
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: MIL-SPEC PAINTING, INC	
Legal Status:	Private
Date Became Current:	19960101
Date Ended Current:	Not reported
Owner/Operator Address:	1720 G BELMONT AVE
Owner/Operator City,State,Zip:	BALTIMORE, MD 21244
Owner/Operator Telephone:	410-265-1019
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: INVESTORS MANAGEMENT CO., INC.	
Legal Status:	Private
Date Became Current:	20220208
Date Ended Current:	Not reported
Owner/Operator Address:	2528 MARYLAND AVE
Owner/Operator City,State,Zip:	BALTIMORE, MD 21218
Owner/Operator Telephone:	410-235-7188

MIL-SPEC PAINTING INC (Continued) **1011844006**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: INFO2@INVESTORSMGMT.COM

Owner/Operator Indicator: Owner
Owner/Operator Name: RAYMOND MAHAFFEY
Legal Status: Municipal
Date Became Current: 20010101
Date Ended Current: Not reported
Owner/Operator Address: 15 PERRY RIDGE CT
Owner/Operator City,State,Zip: BALTIMORE, MD 21237
Owner/Operator Telephone: 410-882-8658
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSUMER MGT SERVICES
Legal Status: Private
Date Became Current: 19950831
Date Ended Current: Not reported
Owner/Operator Address: P O BOX 13063
Owner/Operator City,State,Zip: BALTIMORE, MD 21203
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSUMER MANAGEMENT SERVICES
Legal Status: County
Date Became Current: 19790105
Date Ended Current: Not reported
Owner/Operator Address: 2500 MARYLAND AVE
Owner/Operator City,State,Zip: BALTIMORE, MD 21218
Owner/Operator Telephone: 410-235-0202
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: INFO@INVESTORSMGMT.COM

Owner/Operator Indicator: Operator
Owner/Operator Name: MIL-SPEC PAINTING, INC
Legal Status: Private
Date Became Current: 19960101
Date Ended Current: Not reported
Owner/Operator Address: 1720 G BELMONT AVE
Owner/Operator City,State,Zip: BALTIMORE, MD 21244
Owner/Operator Telephone: 410-265-1019
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSUMER MANAGEMENT SERVICES
Legal Status: County
Date Became Current: 19790105
Date Ended Current: Not reported

MIL-SPEC PAINTING INC (Continued) **1011844006**

Owner/Operator Address: 2500 MARYLAND AVE
Owner/Operator City,State,Zip: BALTIMORE, MD 21218
Owner/Operator Telephone: 410-235-0202
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: INFO@INVESTORSMGMT.COM

Owner/Operator Indicator: Operator
Owner/Operator Name: MIL-SPEC PAINTING INC
Legal Status: Private
Date Became Current: 19950831
Date Ended Current: Not reported
Owner/Operator Address: 1720 BELMONT AVE, STE G
Owner/Operator City,State,Zip: WINDSOR MILL, MD 21244
Owner/Operator Telephone: 410-265-1019
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: INFO@MILSPECPAINTING.COM

Owner/Operator Indicator: Operator
Owner/Operator Name: MIL-SPEC PAINTING INC
Legal Status: Private
Date Became Current: 19950831
Date Ended Current: Not reported
Owner/Operator Address: 1720 BELMONT AVE, STE G
Owner/Operator City,State,Zip: WINDSOR MILL, MD 21244
Owner/Operator Telephone: 410-265-1019
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: INFO@MILSPECPAINTING.COM

Owner/Operator Indicator: Operator
Owner/Operator Name: MIL-SPEC PAINTING INC
Legal Status: Private
Date Became Current: 19950831
Date Ended Current: Not reported
Owner/Operator Address: 1720 BELMONT AVE, STE G
Owner/Operator City,State,Zip: WINDSOR MILL, MD 21244
Owner/Operator Telephone: 410-265-1019
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: INFO@MILSPECPAINTING.COM

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSUMER MGT SERVICES
Legal Status: Private
Date Became Current: 19950831
Date Ended Current: Not reported
Owner/Operator Address: P O BOX13063
Owner/Operator City,State,Zip: BALTIMORE, MD 21203
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSUMER MANAGEMENT SERVICES

MIL-SPEC PAINTING INC (Continued) **1011844006**

Legal Status: County
Date Became Current: 19790105
Date Ended Current: Not reported
Owner/Operator Address: 2500 MARYLAND AVE
Owner/Operator City,State,Zip: BALTIMORE, MD 21218
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: MIL-SPEC PAINTING INC
Legal Status: Private
Date Became Current: 19950831
Date Ended Current: Not reported
Owner/Operator Address: 1720 BELMONT AVE, STE G
Owner/Operator City,State,Zip: WINDSOR MILL, MD 21244
Owner/Operator Telephone: 410-265-1019
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: INFO@MILSPECPAINTING.COM

Owner/Operator Indicator: Operator
Owner/Operator Name: MIL-SPEC PAINTING INC
Legal Status: Private
Date Became Current: 19950831
Date Ended Current: Not reported
Owner/Operator Address: 1720 BELMONT AVE, STE G
Owner/Operator City,State,Zip: WINDSOR MILL, MD 21244
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20240216
Handler Name: MIL-SPEC PAINTING INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20010531
Handler Name: MIL SPEC PAINTING INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

MIL-SPEC PAINTING INC (Continued) **1011844006**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010531
Handler Name: MIL SPEC PAINTING INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080222
Handler Name: MIL SPEC PAINTING INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20100319
Handler Name: MIL SPEC PAINTING INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20180220
Handler Name: MIL-SPEC PAINTING INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20220208

MIL-SPEC PAINTING INC (Continued) **1011844006**

Handler Name: MIL-SPEC PAINTING INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20200226
Handler Name: MIL-SPEC PAINTING INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20220224
Handler Name: MIL-SPEC PAINTING INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 332812
NAICS Description: Metal Coating, Engraving (Except Jewelry And Silverware), And Allied Services To Manufacturers

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E MANIFEST:
Manifest Tracking Number: 020478280JJK
Last Updated Date: 20191108
Shipped Date: 20190822
Received Date: 20191028

MIL-SPEC PAINTING INC (Continued) **1011844006**

Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDR000006262
Generator Name:	Mil-Spec Painting Inc
Generator Location Street Number:	Not reported
Generator Location Street 1:	1720 BELMONT AVE
Generator Location Street 2:	Not reported
Generator Location City:	WINDSOR MILL
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1720 BELMONT AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	WINDSOR MILL
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD083377010
Designated Facility Name:	Environmental Enterprises Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	10163 CINCINNATI DAYTON RD
Designated Facility Mail City:	CINCINNATI
Designated Facility Mail Zip:	45241
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	4650 SPRING GROVE AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	CINCINNATI
Designated Facility Location Zip:	45232
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	021465170JJK
Last Updated Date:	20201207
Shipped Date:	20200929
Received Date:	20201112
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Web
Generator EPA ID:	MDR000006262
Generator Name:	Mil-Spec Painting Inc
Generator Location Street Number:	1720
Generator Location Street 1:	1720 BELMONT AVE
Generator Location Street 2:	SUITE G
Generator Location City:	WINDSOR MILL
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	1720
Generator Mail Street 1:	BELMONT AVE
Generator Mail Street 2:	UNIT G
Generator Mail City:	WINDSOR MILL
Generator Mail Zip:	21244
Generator Mail State:	MD

MIL-SPEC PAINTING INC (Continued) **1011844006**

Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD083377010
Designated Facility Name:	Environmental Enterprises Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	10163 CINCINNATI DAYTON RD
Designated Facility Mail City:	CINCINNATI
Designated Facility Mail Zip:	45241
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	4650 SPRING GROVE AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	CINCINNATI
Designated Facility Location Zip:	45232
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	014843678JJK
Last Updated Date:	20190603
Shipped Date:	20190426
Received Date:	20190503
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDR000006262
Generator Name:	Mil Spec Painting Inc
Generator Location Street Number:	Not reported
Generator Location Street 1:	1720 G BELMONT AVE
Generator Location Street 2:	Not reported
Generator Location City:	WINDSOR MILL
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1720 G BELMONT AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	WINDSOR MILL
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD066060609
Designated Facility Name:	Chemtron Corporation
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	35850 SCHNEIDER CT
Designated Facility Mail City:	AVON
Designated Facility Mail Zip:	44011
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	35850 SCHNEIDER CT
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	AVON
Designated Facility Location Zip:	44011
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N

MIL-SPEC PAINTING INC (Continued) **1011844006**

Rejection Indicator:	N
Manifest Tracking Number:	013308416JJK
Last Updated Date:	20210610
Shipped Date:	20210510
Received Date:	20210524
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDR000006262
Generator Name:	Mil Spec Painting Inc
Generator Location Street Number:	Not reported
Generator Location Street 1:	1720 G BELMONT AVE
Generator Location Street 2:	Not reported
Generator Location City:	WINDSOR MILL
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1720 G BELMONT AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	WINDSOR MILL
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD066060609
Designated Facility Name:	Chemtron Corporation
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	35850 SCHNEIDER CT
Designated Facility Mail City:	AVON
Designated Facility Mail Zip:	44011
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	35850 SCHNEIDER CT
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	AVON
Designated Facility Location Zip:	44011
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	022873956JJK
Last Updated Date:	20220112
Shipped Date:	20210914
Received Date:	20211220
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Web
Generator EPA ID:	MDR000006262
Generator Name:	Mil-Spec Painting Inc
Generator Location Street Number:	1720
Generator Location Street 1:	1720 BELMONT AVE
Generator Location Street 2:	SUITE G
Generator Location City:	WINDSOR MILL
Generator Location State:	MD
Generator Location Zip:	21244

MIL-SPEC PAINTING INC (Continued) **1011844006**

Generator Mail Street Number:	1720
Generator Mail Street 1:	BELMONT AVE
Generator Mail Street 2:	UNIT G
Generator Mail City:	WINDSOR MILL
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD083377010
Designated Facility Name:	Environmental Enterprises Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	10163 CINCINNATI DAYTON RD
Designated Facility Mail City:	CINCINNATI
Designated Facility Mail Zip:	45241
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	4650 SPRING GROVE AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	CINCINNATI
Designated Facility Location Zip:	45232
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	022873956JJK
Transporter Line Number:	1
Transporter EPA ID:	NJD054126164
Transporter Name:	Freehold Cartage, Inc.

Manifest Tracking Number:	022873956JJK
Transporter Line Number:	2
Transporter EPA ID:	OH0000000539
Transporter Name:	Midwest Environmental Transport

Waste Line:

Manifest Tracking Number:	022873956JJK
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN3264
U.S. DOT Description:	Un3264, Waste Corrosive Liquid, Acidic, Inorganic, N.O.S., (Sulfuric Acid), 8, Pgii
Non-Hazardous Waste Description:	Not reported
Number of Containers:	3
Container Type Code:	DF
Container Type Description:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	165
Quantity Unit of Measure Code:	G
Quantity Unit of Measure Description:	Gallons
Waste Quantity, in Tons:	0.6880734
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.6880734
Waste Quantity, in Kilograms:	624.1032
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	624.1032

MIL-SPEC PAINTING INC (Continued) **1011844006**

Management Method Code:	H070
Management Method Description:	CHEMICAL TREATMENT
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D002
Quantity Haz Kg:	624.1032
Quantity Haz Tons:	0.6880734
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	Not reported

NJ MANIFEST:

EPA ID:	MDR000006262
Name:	MIL-SPEC PAINTING INC
Address:	1720-G BELMONT AVE
City,State,Zip:	BALTIMORE, MD 21244
County:	Not reported
Mailing Address:	1720-G BELMONT AVE
Mailing City,State,Zip:	BALTIMORE, MD 21244
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	RAYMOND MAHAFFEY
Comments:	Not reported
SIC Code:	Not reported
County:	MD510
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	MDR000006262
Manifest Number:	002881831SKS
Date Shipped:	10/4/2011
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported

MIL-SPEC PAINTING INC (Continued) **1011844006**

Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D005
Hand Code:	H141
Quantity:	500.00
Unit:	Pounds

EPA ID:	MDR000006262
Manifest Number:	003974625SKS
Date Shipped:	11/11/2013
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

MIL-SPEC PAINTING INC (Continued) **1011844006**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F003 D001
Hand Code:	Not reported
Quantity:	300.00
Unit:	Pounds

EPA ID:	MDR000006262
Manifest Number:	002572885SKS
Date Shipped:	4/8/2011
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported

MIL-SPEC PAINTING INC (Continued) **1011844006**

Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H141
Quantity:	700.00
Unit:	Pounds

EPA ID:	MDR000006262
Manifest Number:	002929512SKS
Date Shipped:	10/25/2011
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported

MIL-SPEC PAINTING INC (Continued) **1011844006**

Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H141
Quantity:	675.00
Unit:	Pounds

EPA ID:	MDR000006262
Manifest Number:	003193268SKS
Date Shipped:	6/15/2012
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D002 D007
Hand Code:	Not reported
Quantity:	800.00
Unit:	Pounds

MIL-SPEC PAINTING INC (Continued) **1011844006**

EPA ID:	MDR000006262
Manifest Number:	003193478SKS
Date Shipped:	7/19/2012
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	Not reported
Quantity:	350.00
Unit:	Pounds

EPA ID:	MDR000006262
Manifest Number:	003610716SKS
Date Shipped:	2/11/2013
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported

MIL-SPEC PAINTING INC (Continued) **1011844006**

Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	Not reported
Quantity:	900.00
Unit:	Pounds

Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	Not reported
Quantity:	900.00
Unit:	Pounds

EPA ID:	MDR000006262
Manifest Number:	003610716SKS
Date Shipped:	2/11/2013
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported

MIL-SPEC PAINTING INC (Continued) **1011844006**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	Not reported
Quantity:	900.00
Unit:	Pounds

Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	Not reported
Quantity:	900.00
Unit:	Pounds

EPA ID:	MDR000006262
Manifest Number:	003610812SKS
Date Shipped:	2/28/2013
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000081205
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported

MIL-SPEC PAINTING INC (Continued) **1011844006**

Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D005 D007 D008
Hand Code:	Not reported
Quantity:	600.00
Unit:	Pounds

EPA ID:	MDR000006262
Manifest Number:	002592859SKS
Date Shipped:	7/5/2011
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported

MIL-SPEC PAINTING INC (Continued) **1011844006**

Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H141
Quantity:	1,200.00
Unit:	Pounds

EPA ID:	MDR000006262
Manifest Number:	003126242SKS
Date Shipped:	3/19/2012
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported

MIL-SPEC PAINTING INC (Continued) **1011844006**

Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D007
Hand Code:	Not reported
Quantity:	700.00
Unit:	Pounds

Click this hyperlink while viewing on your computer to access
2 additional NJ MANIFEST: record(s) in the EDR Site Report.

P115 **MIL-SPEC PAINTING** **MD PFAS** **S127733508**
NE **1720 BELMONT AVE** **N/A**
1/8-1/4 **WINDSOR MILL, MD**
0.205 mi.
1080 ft. **Site 4 of 11 in cluster P**

Relative:
Lower

Actual:
405 ft.

PFAS:

Name:	MIL-SPEC PAINTING
Address:	1720 BELMONT AVE
City,State,Zip:	WINDSOR MILL, MD
Object ID:	Not reported
HW ID:	2147
Origin ID:	110037395814
Facility Type:	EnviroFacts Facilities
Last update:	Not reported
PFAS use known/confirmed:	Not reported
PFAS detected:	Not reported
Total PFAS max conc EFFLUENT (ng/L):	Not reported
Total PFAS max conc gw (ng/L):	Not reported
Total PFAS max conc sw (ng/L):	Not reported
Total PFAS max conc soil (ng/g):	Not reported
Total PFAS max conc sed (ng/g):	Not reported
PFAS detects in domestic wells:	Not reported
Sample ID:	Not reported
Sample Date:	Not reported
Media:	Not reported
Well Tag:	Not reported
Hydro Unit:	Not reported
Confinement:	Not reported
Sample Type:	Not reported
Water System:	Not reported
Population:	Not reported
HI:	Not reported
PFOS:	Not reported
PFOA:	Not reported
PF3OUdS:	Not reported
ADONA:	Not reported
PF3ONS:	Not reported

MIL-SPEC PAINTING (Continued) **S127733508**

HFPO DA:	Not reported
EtFOSAA:	Not reported
MeFOSAA:	Not reported
PFBS:	Not reported
PFDA:	Not reported
PFDOA:	Not reported
PFHpA:	Not reported
PFHxS:	Not reported
PFHxA:	Not reported
PFNA:	Not reported
PFTA:	Not reported
PFTrDA:	Not reported
PFUnDA:	Not reported
PFBA:	Not reported
PFPeA:	Not reported
PFPeS:	Not reported
PFHpS:	Not reported
X4:2 FTS	Not reported
X6:2 FTS	Not reported
PFEESA:	Not reported
PFMPA:	Not reported
PFMBA:	Not reported
NFDHA:	Not reported
X8:2 FTS	Not reported
Comments:	Not reported
Site Latitude:	Not reported
Site Longitude:	Not reported

URL:

P116 **MIL-SPEC PAINTING INC** **PFAS ECHO** **1027388808**
NE **1720 BELMONT AVE** **N/A**
1/8-1/4 **WINDSOR MILL, MD 21244**
0.205 mi.
1080 ft. **Site 5 of 11 in cluster P**

Relative: **Lower**

Actual: **405 ft.**

PFAS ECHO:

Facility ID:	110037395814
Name:	Mil-Spec Painting Inc
Address:	1720 BELMONT AVE
City,State,Zip:	WINDSOR MILL, MD 21244
Latitude:	39.31519
Longitude:	-76.74592
Count:	1
County:	BALTIMORE
Status:	Active
Region:	03
Industry:	Metal Coating

ECHO Facility Report:

Facility Percent Minority:	77.935
Facility Derived Tribes:	-
Facility Population:	3937.17
EPA Programs:	CAA; RCRA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	24005
Facility Indian Country Flag:	N

MIL-SPEC PAINTING INC (Continued) **1027388808**

Facility Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Facility Derived HUC:	02060003
Facility Derived WBD:	020600030902
Facility Derived CD113:	07
Facility Derived CB2010:	240054015071007
Facility Major Flag:	-
Facility Active Flag:	Y
Facility Inspection Count:	0
Facility Date Last Inspection:	11/21/2014
Facility Days Last Inspection:	3,774
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	Y
NPDES Flag:	N
SDWIS Flag:	N
RCRA Flag:	Y
TRI Flag:	N
GHG Flag:	N
AIR IDS:	MD0000002400502321
CAA Permit Types:	Minor Emissions
CAA NAICS:	332813
CAA SICS:	3471
NPDES IDS:	-
CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDS:	MDR000006262
RCRA Permit Types:	SQG
RCRA NAICS:	332812
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-

P117 **MIL SPEC PAINTING INC** **MD MANIFEST** **S121870832**
NE **1720 BELMONT AVE STE G** **N/A**
1/8-1/4 **BALTIMORE, MD 21244**
0.205 mi.
1080 ft. **Site 6 of 11 in cluster P**

Relative:
Lower

Actual:
405 ft.

MD MANIFEST:

EPAID:	MDR000006262
Name:	MIL SPEC PAINTING INC
Address:	1720 BELMONT AVE STE G
City,State,Zip:	BALTIMORE, MD 21244-2503
Manifest Number:	005099778SKS
Transporter 1:	SAFETY-KLEEN SYSTEMS,INC.
Transporter 2:	CLEAN HARBORS ENV.SERVICES,INC.
Generator Certifier:	TERRY HOLLER
Date Shipped Out:	01/14/2016
Destination Facility Certifier:	LAKEISHA MASON
Date Arrived at Destingation Facility:	01/28/2016
Quantity:	375
Unit:	Pounds

EPAID:	MDR000006262
Name:	MIL SPEC PAINTING INC
Address:	1720 BELMONT AVE STE G
City,State,Zip:	BALTIMORE, MD 21244-2503
Manifest Number:	005099949SKS
Transporter 1:	SAFETY-KLEEN SYSTEMS, INC.
Transporter 2:	Not reported
Generator Certifier:	ANN MAHAFFEY
Date Shipped Out:	03/18/2016
Destination Facility Certifier:	JILL OSLEY
Date Arrived at Destingation Facility:	03/29/2016
Quantity:	36
Unit:	Pounds

EPAID:	MDR000006262
Name:	MIL SPEC PAINTING INC
Address:	1720 BELMONT AVE STE G
City,State,Zip:	BALTIMORE, MD 21244-2503
Manifest Number:	005318668SKS
Transporter 1:	SAFETY-KLEEN SYSTEMS, INC.
Transporter 2:	CLEAN HARBORS ENVIRONMENTAL SERVICES
Generator Certifier:	TERRY HOLLER
Date Shipped Out:	05/10/2016
Destination Facility Certifier:	GEA JACKSON
Date Arrived at Destingation Facility:	05/25/2016
Quantity:	25
Unit:	Pounds

EPAID:	MDR000006262
Name:	MIL SPEC PAINTING INC
Address:	1720 BELMONT AVE STE G
City,State,Zip:	BALTIMORE, MD 21244-2503
Manifest Number:	006365213SKS
Transporter 1:	SAFETY KLEEN SYSTEMS INC
Transporter 2:	CLEAN HARBORS ENVL SVCS
Generator Certifier:	ROBERT PIERCE
Date Shipped Out:	11/17/2017
Destination Facility Certifier:	M RILEY

MIL SPEC PAINTING INC (Continued) **S121870832**

Date Arrived at Destingation Facility: 12/05/2017
Quantity: 15
Unit: Pounds

EPAID: MDR000006262
Name: MIL SPEC PAINTING INC
Address: 1720 BELMONT AVE STE G
City,State,Zip: BALTIMORE, MD 21244-2503
Manifest Number: 006053200SKS
Transporter 1: SAFETY-KLEEN SYSTEMS INC
Transporter 2: CLEAN HARBORS ENV SVCS
Generator Certifier: ROBERT PIERRE
Date Shipped Out: 07/27/2017
Destination Facility Certifier: ROBET KUTZER
Date Arrived at Destingation Facility: 08/15/2017
Quantity: 25
Unit: Pounds

EPAID: MDR000006262
Name: MIL SPEC PAINTING INC
Address: 1720 BELMONT AVE STE G
City,State,Zip: BALTIMORE, MD 21244-2503
Manifest Number: 006404208SKS
Transporter 1: SAFETY-KLEEN SYSTEMS INC
Transporter 2: CLEAN HARBORS ENVIRO SERVICES
Generator Certifier: R D METZ
Date Shipped Out: 10/20/2017
Destination Facility Certifier: ROBERT KURTZ
Date Arrived at Destingation Facility: 11/07/2017
Quantity: 15
Unit: Pounds

EPAID: MDR000006262
Name: MIL SPEC PAINTING INC
Address: 1720 BELMONT AVE STE G
City,State,Zip: BALTIMORE, MD 21244-2503
Manifest Number: 006059728SKS
Transporter 1: SAFETY-KLEEN SYSTEMS INC
Transporter 2: CLEAN HARBORS ENVIRO SERVICES
Generator Certifier: ROBERT PIERCE
Date Shipped Out: 08/17/2017
Destination Facility Certifier: JAI S. MOBLEY
Date Arrived at Destingation Facility: 09/05/2017
Quantity: 30
Unit: Pounds

EPAID: MDR000006262
Name: MIL SPEC PAINTING INC
Address: 1720 BELMONT AVE STE G
City,State,Zip: BALTIMORE, MD 21244-2503
Manifest Number: 006066177SKS
Transporter 1: SAFETY-KLEEN SYSTEMS INC
Transporter 2: CLEAN HARBORS ENVIRO SERVICES
Generator Certifier: R. D. METZ
Date Shipped Out: 08/31/2017
Destination Facility Certifier: ROBERT KUTZER
Date Arrived at Destingation Facility: 09/19/2017

MIL SPEC PAINTING INC (Continued) **S121870832**

Quantity:	36
Unit:	Pounds
EPAID:	MDR000006262
Name:	MIL SPEC PAINTING INC
Address:	1720 BELMONT AVE STE G
City,State,Zip:	BALTIMORE, MD 21244-2503
Manifest Number:	005964800SKS
Transporter 1:	SAFETY-KLEEN SYSTEMS INC
Transporter 2:	CLEAN HARBORS ENV SVCS INC
Generator Certifier:	ROBERT PIERRE
Date Shipped Out:	10/04/2017
Destination Facility Certifier:	CHARLEEKA THOMPSON
Date Arrived at Destingation Facility:	10/26/2017
Quantity:	350
Unit:	Pounds
EPAID:	MDR000006262
Name:	MIL SPEC PAINTING INC
Address:	1720 BELMONT AVE STE G
City,State,Zip:	BALTIMORE, MD 21244-2503
Manifest Number:	006351177SKS
Transporter 1:	SAFETY-KLEEN SYSTEMS INC
Transporter 2:	CLEAN HARBORS ENVIRO SERVICES
Generator Certifier:	ROBERT PIERSON
Date Shipped Out:	10/04/2017
Destination Facility Certifier:	M RILEY
Date Arrived at Destingation Facility:	10/17/2017
Quantity:	20
Unit:	Pounds
EPAID:	MDR000006262
Name:	MIL SPEC PAINTING INC
Address:	1720 BELMONT AVE STE G
City,State,Zip:	BALTIMORE, MD 21244-2503
Manifest Number:	005836202SKS
Transporter 1:	SAFETY-KLEEN SYSTEMS, INC.
Transporter 2:	CLEAN HARBORS ENV. SERIVICES, INC
Generator Certifier:	STACEY WERNZ
Date Shipped Out:	03/03/2017
Destination Facility Certifier:	JOHN MERTH
Date Arrived at Destingation Facility:	04/03/2017
Quantity:	350
Unit:	Pounds

Click this hyperlink while viewing on your computer to access
46 additional MD_MANIFEST: record(s) in the EDR Site Report.

P118 **MIL SPEC PAINTING INC** **E MANIFEST** **1031592640**
NE **1720 1720 BELMONT AVE STE G** **N/A**
1/8-1/4 **BALTIMORE, MD 21244**
0.205 mi.
1080 ft. **Site 7 of 11 in cluster P**

Relative:
Lower

Actual:
405 ft.

E MANIFEST:

Manifest Tracking Number:	008867973SKS
Last Updated Date:	20240129
Shipped Date:	20231207
Received Date:	20240105
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	MDR000006262
Generator Name:	Mil Spec Painting Inc
Generator Location Street Number:	1720
Generator Location Street 1:	1720 1720 BELMONT AVE STE G
Generator Location Street 2:	Not reported
Generator Location City:	BALTIMORE
Generator Location State:	MD
Generator Location Zip:	21244
Generator Mail Street Number:	1720
Generator Mail Street 1:	1720 Belmont Ave Ste G
Generator Mail Street 2:	Not reported
Generator Mail City:	Baltimore
Generator Mail Zip:	21244
Generator Mail State:	MD
Generator Contact Company Name:	MIL Spec Painting Inc
Designated Facility EPA ID:	ILD980613913
Designated Facility Name:	Safety-Kleen Systems, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	633 East 138th Street
Designated Facility Mail City:	Dolton
Designated Facility Mail Zip:	60419
Designated Facility Mail State:	IL
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	633 East 138th Street
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Dolton
Designated Facility Location Zip:	60419
Designated Facility Location State:	IL
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	008867973SKS
Transporter Line Number:	1
Transporter EPA ID:	TXR000081205
Transporter Name:	Safety-Kleen Systems, Inc.
Manifest Tracking Number:	008867973SKS
Transporter Line Number:	2
Transporter EPA ID:	MAD039322250
Transporter Name:	Clean Harbors Environmental Services, Inc.
Manifest Tracking Number:	008867973SKS

MIL SPEC PAINTING INC (Continued) **1031592640**

Transporter Line Number: 3
Transporter EPA ID: MAD039322250
Transporter Name: Clean Harbors Environmental Services, Inc.

Waste Line:
Manifest Tracking Number: 008867973SKS
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: UN1263
U.S. DOT Description: Un1263, Waste Un1263 Waste Paint Related Material, 3 Pg Ii (Erg#128)(F005,F003,D001,D018,D035 D039,D040), 3, Pg Ii
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: DM
Container Type Description: Metal drums, barrels, kegs
Waste Quantity: 10
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.005
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.005
Waste Quantity, in Kilograms: 4.53515
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 4.53515
Management Method Code: H020
Management Method Description: SOLVENTS RECOVERY
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y
Federal Waste Codes: D001, D018, D035, D039, D040, F003, F005
Quantity Haz Kg: 4.53515
Quantity Haz Tons: 0.005
Quantity Non Haz Kg: Not reported
Quantity Non Haz Tons: Not reported
State Waste Codes: Not reported

P119 **SECURITY ANNEX** **UST FINDER** **1028413385**
NE **1711 BELMONT AVENUE** **UST FINDER RELEASE** **N/A**
1/8-1/4 **BALTIMORE, MD 21207**
0.227 mi.
1196 ft. **Site 8 of 11 in cluster P**

Relative: **Lower**
Actual: **399 ft.**

UST FINDER:
Object ID: 638243
Facility ID: MD7916
Name: SECURITY ANNEX

SECURITY ANNEX (Continued) **1028413385**

Address:	1711 BELMONT AVENUE
City,State,Zip:	BALTIMORE, MD 21207
Address Match Type:	StreetAddress
Open USTs:	0
Closed USTs:	3
TOS USTs:	0
Population 1500ft:	227
Private Wells 1500ft:	2
Within 100yr Floodplain:	No
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	3
Tribe:	Not reported
Coordinate Source:	Geocode
X Coord:	-76.74732948
Y Coord:	39.3143144700001
Latitude:	39.31431447
Longitude:	-76.74732948

UST FINDER:

Object ID:	690641
Facility ID:	MD7916
Tank ID:	MD7916_3
Tank Status:	Closed
Installation Date:	1998/03/01 15:59:59+00
Removal Date:	2010/02/17 15:59:59+00
Tank Capacity:	12000
Substances:	Gasohol
Tank Wall Type:	Double
Object ID:	703285
Facility ID:	MD7916
Tank ID:	MD7916_1
Tank Status:	Closed
Installation Date:	1981/02/01 16:00:00+00
Removal Date:	1998/03/31 15:59:59+00
Tank Capacity:	10000
Substances:	Gasoline
Tank Wall Type:	Single
Object ID:	716252
Facility ID:	MD7916
Tank ID:	MD7916_2
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	1992/08/01 15:59:59+00
Tank Capacity:	550

SECURITY ANNEX (Continued) **1028413385**

Substances: Used Oil
Tank Wall Type: Single

UST FINDER RELEASE:

Object ID:	196708
Facility ID:	MD7916
Lust ID:	MD98-1962BA2
Name:	MD STATE POLICE SECURITY ANNEX
Address:	1711 BELMONT AVE
City,State,Zip:	BALTIMORE, MD 21244
Address Match Type:	StreetAddress
Reported Date:	1998/03/31 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	228
Domestic Wells within 1500ft:	2
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	3
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	Geocode
X Coord:	-76.74732948
Y Coord:	39.3143144700001
Latitude:	39.3143144699999
Longitude:	-76.74732948

P120 **MD STATE POLICE SECURITY ANNEX** **MD OCPCASES** **S110295006**
NE **1711 BELMONT AVE** **N/A**
1/8-1/4 **BALTIMORE, MD 21244**
0.227 mi.
1196 ft. **Site 9 of 11 in cluster P**

Relative: **Lower**
Actual: **399 ft.**

OCPCASES:

Name:	MD STATE POLICE SECURITY ANNEX
Address:	1711 BELMONT AVE
City,State,Zip:	BALTIMORE, MD 21244
Facility ID:	98-1962BA2
Facility Status/Code:	CLOSED/Tank Closure - Motor/Lube Oil
Date Open:	03/31/1998
Date Closed:	08/21/1998
Release:	YES

MD STATE POLICE SECURITY ANNEX (Continued) **S110295006**

Cleanup: YES
Registration Number: 7916

P121 **MD STATE POLICE ANNEX** **MD OCPCASES** **S104610609**
NE **1711 BELMONT AVE** **N/A**
1/8-1/4 **BALTIMORE, MD 21244**
0.227 mi.
1196 ft. **Site 10 of 11 in cluster P**

Relative: OCPCASES:
Lower
Actual: Name: MD STATE POLICE ANNEX
399 ft. Address: 1711 BELMONT AVE
City,State,Zip: BALTIMORE, MD 21244
Facility ID: 93-0762BA2
Facility Status/Code: CLOSED/
Date Open: 08/27/1992
Date Closed: 09/16/1994
Release: Not reported
Cleanup: Not reported
Registration Number: 7916

P122 **MD STATE POLICE SECURITY ANNEX** **MD OCPCASES** **S120841870**
NE **1711 BELMONT AVE** **N/A**
1/8-1/4 **BALTIMORE, MD 21244**
0.227 mi.
1196 ft. **Site 11 of 11 in cluster P**

Relative: OCPCASES:
Lower
Actual: Name: MD STATE POLICE SECURITY ANNEX
399 ft. Address: 1711 BELMONT AVE
City,State,Zip: BALTIMORE, MD 21244
Facility ID: 10-0438BA
Facility Status/Code: CLOSED/Tank Closure - Motor/Lube Oil
Date Open: 02/18/2010
Date Closed: 06/03/2013
Release: NO
Cleanup: NO
Registration Number: 7916

---

123 **CHADWICK CLEANERS** **MD LRP** **S118494099**
West **7137 SECURITY BOULEVARD** **N/A**
1/8-1/4 **BALTIMORE, MD 21244**
0.227 mi.
1199 ft.

Relative: MD LRP:
Higher
Actual: Name: CHADWICK CLEANERS
464 ft. Address: 7137 Security Boulevard
City,State,Zip: BALTIMORE, MD 21244
Factsheet URL: Fact Sheet Not Available.
Voluntary Cleanup Program: No
Brownfield Assesment Complete: No
NPL: No
Federal Facility: No
Alias: Not reported

CHADWICK CLEANERS (Continued) **S118494099**

Groundwater:	No
Assessment On-Going:	No
Remediation On-Going:	No
Withdrawn:	No
GW Chlorinated:	Yes
GW Petroleum:	No
GW Metals:	No
GW Pesticides:	No
GW PCB:	No
GW PAH:	No
Soil Chlorinated:	Yes
Soil Metals:	No
Soil Pesticides:	No
Soil PCB:	No
Soil PAH:	No
Soil Petroleum:	No
Sediment Chlorinated:	No
Sediment Petroleum:	No
Sediment Metals:	No
Sediment Pesticides:	No
Sediment PCB:	No
Sediment PAH:	No
SW Chlorinated:	No
SW Petroleum:	No
SW Metals:	No
SW Pesticides:	No
SW PCB:	No
SW PAH:	No
Site Assessment:	No
Tax Map Number:	Not reported
File Available:	Yes
BMI Number:	MD1265
Archived:	Yes
Table Site ID:	955
Parcel Number:	Not reported
Block:	Not reported
Lot Number:	Not reported
Tax ID:	Not reported
Det Issued:	No
Enfor congo:	No
CHS Oversig:	Yes
EPAID:	Not reported
Regulatory:	Not reported
FY Open:	2001
FY_Closed:	2006

N124 **CHADWICK SHELL #517** **MD UST** **U003753594**
WNW **7175 SECURITY BOULEVARD** **MD Financial Assurance** **N/A**
1/8-1/4 **BALTIMORE, MD 21244**
0.230 mi.
1215 ft. **Site 7 of 9 in cluster N**

Relative: **Lower**
Actual: **444 ft.**

UST:

Facility Id:	7047
Oper Name:	Not reported
Form Name:	Brian Fenwick
Form Title:	Maintenance/Compliance Coordinator
Form Date:	06/14/2005

CHADWICK SHELL #517 (Continued) **U003753594**

Owner Id: 1280

Owner:
Owner Name: SMO, Incorporated
Owner Address: 102 Centennial St
Owner City: La Plata
Owner State: MD
Owner Zip: 20646
Owner Phone: (301) 932-3600
Owner Contact: Lisa D. Kane

Tanks:
Tank ID: 1
Tank Status: Permanently Out of Use
Tank Capacity: 8000
Substance Description: Gasoline
Tank Compartment: False
Compartment Compartment: A
Date Installed: 01/01/1971
Tank Material Desc: Fiberglass Reinforced Plastic
Pipe Material Desc: Fiberglass Reinforced Plastic

Tank ID: 2
Tank Status: Permanently Out of Use
Tank Capacity: 8000
Substance Description: Gasoline
Tank Compartment: False
Compartment Compartment: A
Date Installed: 01/01/1971
Tank Material Desc: Fiberglass Reinforced Plastic
Pipe Material Desc: Fiberglass Reinforced Plastic

Tank ID: 3
Tank Status: Permanently Out of Use
Tank Capacity: 8000
Substance Description: Gasoline
Tank Compartment: False
Compartment Compartment: A
Date Installed: 01/01/1971
Tank Material Desc: Fiberglass Reinforced Plastic
Pipe Material Desc: Fiberglass Reinforced Plastic

Tank ID: 4
Tank Status: Permanently Out of Use
Tank Capacity: 1000
Substance Description: Used Oil
Tank Compartment: False
Compartment Compartment: A
Date Installed: 01/01/1986
Tank Material Desc: Fiberglass Reinforced Plastic
Pipe Material Desc: Fiberglass Reinforced Plastic

MD Financial Assurance 2:
Name: CHADWICK SHELL #517
Address: 7175 SECURITY BOULEVARD
City,State,Zip: BALTIMORE, MD 21244

CHADWICK SHELL #517 (Continued) **U003753594**

Region:	2
Facility ID:	7047
Self Insured:	False
Insurance:	True
Risk Retention Group:	False
Guarantee:	False
Surety Bonds:	False
Letter of Credit:	False
State Fund:	False
Other Finance:	False
Finacnce Comments:	Policy# PLS/CCC 6190217 Insurer: American International Specialty Lines Ins. Co. Effective 11/30/00 (dt)
FR Not Listed:	False

N125 **CHADWICK SHELL #517** **UST FINDER** **1028412764**
WNW **7175 SECURITY BOULEVARD** **UST FINDER RELEASE** **N/A**
1/8-1/4 **BALTIMORE, MD 21244**
0.230 mi.
1215 ft. **Site 8 of 9 in cluster N**

Relative: **Lower**
Actual: **444 ft.**

UST FINDER:

Object ID:	638226
Facility ID:	MD7047
Name:	CHADWICK SHELL #517
Address:	7175 SECURITY BOULEVARD
City,State,Zip:	BALTIMORE, MD 21244
Address Match Type:	PointAddress
Open USTs:	0
Closed USTs:	4
TOS USTs:	0
Population 1500ft:	1082
Private Wells 1500ft:	3
Within 100yr Floodplain:	No
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	3
Tribe:	Not reported
Coordinate Source:	Geocode
X Coord:	-76.7575346799999
Y Coord:	39.3135607200001
Latitude:	39.31356072
Longitude:	-76.75753468

UST FINDER:

Object ID:	693905
Facility ID:	MD7047
Tank ID:	MD7047_4

CHADWICK SHELL #517 (Continued) **1028412764**

Tank Status:	Closed
Installation Date:	1986/01/01 16:00:00+00
Removal Date:	2005/07/12 15:59:59+00
Tank Capacity:	1000
Substances:	Used Oil
Tank Wall Type:	Single
Object ID:	693908
Facility ID:	MD7047
Tank ID:	MD7047_1
Tank Status:	Closed
Installation Date:	1971/01/01 16:00:00+00
Removal Date:	2005/07/12 15:59:59+00
Tank Capacity:	8000
Substances:	Gasoline
Tank Wall Type:	Single
Object ID:	693909
Facility ID:	MD7047
Tank ID:	MD7047_2
Tank Status:	Closed
Installation Date:	1971/01/01 16:00:00+00
Removal Date:	2005/07/12 15:59:59+00
Tank Capacity:	8000
Substances:	Gasoline
Tank Wall Type:	Single
Object ID:	693910
Facility ID:	MD7047
Tank ID:	MD7047_3
Tank Status:	Closed
Installation Date:	1971/01/01 16:00:00+00
Removal Date:	2005/07/12 15:59:59+00
Tank Capacity:	8000
Substances:	Gasoline
Tank Wall Type:	Single

UST FINDER RELEASE:

Object ID:	196197
Facility ID:	MD7047
Lust ID:	MD06-0027BA2
Name:	CHADWICK STORE #517
Address:	7175 SECURITY BLVD
City,State,Zip:	WOODLAWN, MD 21244
Address Match Type:	StreetAddressExt
Reported Date:	2005/07/12 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	Not reported
Domestic Wells within 1500ft:	Not reported
Land Use:	Not reported
Within SPA:	Not reported
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported

CHADWICK SHELL #517 (Continued) **1028412764**

Within WHPA:	Not reported
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	Not reported
Tribe:	Not reported
EPA Region:	3
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	Geocode
X Coord:	-76.75453485
Y Coord:	39.31291559
Latitude:	39.31291559
Longitude:	-76.7545348499999

N126
WNW
1/8-1/4
0.230 mi.
1215 ft.

CHADWICK STORE #517
7175 SECURITY BLVD
WOODLAWN, MD 21244

Site 9 of 9 in cluster N

MD OCPCASES **S107176761**
N/A

Relative:
Lower

Actual:
444 ft.

OCPCASES:

Name:	CHADWICK STORE #517
Address:	7175 SECURITY BLVD
City,State,Zip:	WOODLAWN, MD 21244
Facility ID:	06-0027BA2
Facility Status/Code:	CLOSED/Tank Closure - Motor/Lube Oil
Date Open:	07/12/2005
Date Closed:	01/11/2006
Release:	YES
Cleanup:	YES
Registration Number:	7047

127
NNE
1/4-1/2
0.252 mi.
1332 ft.

DENNIS MENDOZA PROPERTY
1700 HILL DR
BALTIMORE, MD 21244

MD OCPCASES **S105509313**
N/A

Relative:
Lower

Actual:
400 ft.

OCPCASES:

Name:	DENNIS MENDOZA PROPERTY
Address:	1700 HILL DR
City,State,Zip:	BALTIMORE, MD 21244
Facility ID:	02-1388BA1
Facility Status/Code:	CLOSED/Tank Closure - Commercial Heating Oil
Date Open:	04/29/2002
Date Closed:	05/13/2004
Release:	NO
Cleanup:	NO
Registration Number:	14023

128
SSE
1/4-1/2
0.268 mi.
1413 ft.

ALIKHAN RESIDENCE
6627 JOHNNYCAKE RD
BALTIMORE, MD 21228

MD OCPCASES **S105899296**
N/A

Relative:
Lower

Actual:
404 ft.

OCPCASES:

Name:	ALIKHAN RESIDENCE
Address:	6627 JOHNNYCAKE RD
City,State,Zip:	BALTIMORE, MD 21228
Facility ID:	03-1984BA1
Facility Status/Code:	CLOSED/Dumping
Date Open:	06/17/2003
Date Closed:	04/28/2004
Release:	YES
Cleanup:	YES
Registration Number:	Not reported

Q129
SSW
1/4-1/2
0.276 mi.
1459 ft.

WESTVIEW PARK NOA
1505 N. ROLLING ROAD
WESTVIEW PARK, MD 21228

Site 1 of 2 in cluster Q

SEMS-ARCHIVE **1015731270**
MDN000306732

Relative:
Lower

Actual:
456 ft.

SEMS Archive:

Site ID:	0306732
EPA ID:	MDN000306732
Name:	WESTVIEW PARK NOA
Address:	1505 N. ROLLING ROAD
Address 2:	Not reported
City,State,Zip:	WESTVIEW PARK, MD 21228
Cong District:	07
FIPS Code:	24005
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	03
Site ID:	0306732
EPA ID:	MDN000306732
Site Name:	WESTVIEW PARK NOA
NPL:	N
FF:	N
OU:	00
Action Code:	RS
Action Name:	RV ASSESS
SEQ:	1
Start Date:	2008-09-30 04:00:00
Finish Date:	2009-10-10 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	03
Site ID:	0306732
EPA ID:	MDN000306732
Site Name:	WESTVIEW PARK NOA
NPL:	N
FF:	N
OU:	00

WESTVIEW PARK NOA (Continued) **1015731270**

Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	2011-11-22 05:00:00
Finish Date:	2012-02-20 05:00:00
Qual:	H
Current Action Lead:	EPA Perf
Region:	03
Site ID:	0306732
EPA ID:	MDN000306732
Site Name:	WESTVIEW PARK NOA
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	2011-03-30 04:00:00
Finish Date:	2011-03-30 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	03
Site ID:	0306732
EPA ID:	MDN000306732
Site Name:	WESTVIEW PARK NOA
NPL:	N
FF:	N
OU:	00
Action Code:	SI
Action Name:	SI
SEQ:	1
Start Date:	2012-02-20 05:00:00
Finish Date:	2012-12-21 05:00:00
Qual:	N
Current Action Lead:	EPA Perf
Region:	03
Site ID:	0306732
EPA ID:	MDN000306732
Site Name:	WESTVIEW PARK NOA
NPL:	N
FF:	N
OU:	00
Action Code:	VU
Action Name:	UNARCHIVE
SEQ:	1
Start Date:	2012-01-20 05:00:00
Finish Date:	2012-01-20 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse
Region:	03
Site ID:	0306732
EPA ID:	MDN000306732
Site Name:	WESTVIEW PARK NOA

WESTVIEW PARK NOA (Continued) **1015731270**

NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	2011-12-09 05:00:00
Finish Date:	2011-12-09 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse
Region:	03
Site ID:	0306732
EPA ID:	MDN000306732
Site Name:	WESTVIEW PARK NOA
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	3
Start Date:	2012-12-21 05:00:00
Finish Date:	2012-12-21 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

Q130 **WESTVIEW PARK NOA SITE** **MD LRP** **S111861895**
SSW **1505 NORTH ROLLING ROAD** **N/A**
1/4-1/2 **CATONSVILLE, MD 21228**
0.276 mi.
1459 ft. **Site 2 of 2 in cluster Q**

Relative:
Lower

Actual:
456 ft.

MD LRP:

Name:	WESTVIEW PARK NOA SITE
Address:	1505 North Rolling Road
City,State,Zip:	CATONSVILLE, MD 21228
Factsheet URL:	
Voluntary Cleanup Program:	No
Brownfield Assesment Complete:	No
NPL:	No
Federal Facility:	No
Alias:	Not reported
Groundwater:	No
Assessment On-Going:	Yes
Remediation On-Going:	No
Withdrawn:	No
GW Chlorinated:	No
GW Petroleum:	No
GW Metals:	No
GW Pesticides:	No
GW PCB:	No
GW PAH:	No
Soil Chlorinated:	No
Soil Metals:	No
Soil Pesticides:	No
Soil PCB:	No

WESTVIEW PARK NOA SITE (Continued) **S111861895**

Soil PAH:	No
Soil Petroleum:	No
Sediment Chlorinated:	No
Sediment Petroleum:	No
Sediment Metals:	No
Sediment Pesticides:	No
Sediment PCB:	No
Sediment PAH:	No
SW Chlorinated:	No
SW Petroleum:	No
SW Metals:	No
SW Pesticides:	No
SW PCB:	No
SW PAH:	No
Site Assessment:	Yes
Tax Map Number:	0094
File Available:	Yes
BMI Number:	MD0593
Archived:	No
Table Site ID:	206
Parcel Number:	0137
Block:	Not reported
Lot Number:	1
Tax ID:	Not reported
Det Issued:	No
Enfor congo:	No
CHS Oversig:	No
EPAID:	Not reported
Regulatory:	Not reported
FY Open:	Not reported
FY_Closed:	Not reported

R131 **AMOCO** **MD HIST LUST** **S101183634**
East **6698 SECURITY BOULEVARD** **N/A**
1/4-1/2 **, MD**
0.305 mi.
1611 ft. **Site 1 of 3 in cluster R**

Relative: Historical LUST:
Lower
Recover Type:	Monitoring - No active remediation. Sampling of monitoring wells only
County:	BALTIMORE
Case Number:	92-1107BA
Open/Closed:	**CLOSED**

Actual:
375 ft.

R132 **AMOCO #1221** **MD OCPCASES** **S104608241**
ENE **6698 SECURITY BLVD** **N/A**
1/4-1/2 **GWYNN OAK, MD 21207**
0.324 mi.
1709 ft. **Site 2 of 3 in cluster R**

Relative: OCPCASES:
Lower
Name:	AMOCO #1221
Address:	6698 SECURITY BLVD
City,State,Zip:	GWYNN OAK, MD 21207
Facility ID:	92-1107BA2
Facility Status/Code:	CLOSED/Well/GW Contamination - Motor/Lube Oil

Actual:
381 ft.

AMOCO #1221 (Continued) **S104608241**

Date Open:	10/31/1991
Date Closed:	09/16/1997
Release:	YES
Cleanup:	YES
Registration Number:	5552

R133 **SECURITY BP** **UST FINDER** **1028411719**
ENE **6698 SECURITY BOULEVARD** **UST FINDER RELEASE** **N/A**
1/4-1/2 **WINDSOR MILL, MD 21244**
0.324 mi.
1709 ft. **Site 3 of 3 in cluster R**

Relative: **Lower**
Actual: **381 ft.**

UST FINDER:

Object ID:	643567
Facility ID:	MD5552
Name:	SECURITY BP
Address:	6698 SECURITY BOULEVARD
City,State,Zip:	WINDSOR MILL, MD 21244
Address Match Type:	PointAddress
Open USTs:	3
Closed USTs:	6
TOS USTs:	0
Population 1500ft:	0
Private Wells 1500ft:	0
Within 100yr Floodplain:	No
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	3
Tribe:	Not reported
Coordinate Source:	Geocode
X Coord:	-76.74032116
Y Coord:	39.3121164300001
Latitude:	39.31211643
Longitude:	-76.74032116

UST FINDER:

Object ID:	706621
Facility ID:	MD5552
Tank ID:	MD5552_4
Tank Status:	Closed
Installation Date:	1985/02/01 16:00:00+00
Removal Date:	1996/09/23 15:59:59+00
Tank Capacity:	550
Substances:	Used Oil
Tank Wall Type:	Single

Object ID:	706622

SECURITY BP (Continued) **1028411719**

Facility ID:	MD5552
Tank ID:	MD5552_5
Tank Status:	Closed
Installation Date:	1985/02/01 16:00:00+00
Removal Date:	1996/09/23 15:59:59+00
Tank Capacity:	550
Substances:	Heating Oil
Tank Wall Type:	Single

Object ID:	717914
Facility ID:	MD5552
Tank ID:	MD5552_6
Tank Status:	Closed
Installation Date:	1977/11/01 16:00:00+00
Removal Date:	1991/10/30 15:59:59+00
Tank Capacity:	10000
Substances:	Gasoline
Tank Wall Type:	Single

Object ID:	717920
Facility ID:	MD5552
Tank ID:	MD5552_7
Tank Status:	Closed
Installation Date:	1969/09/01 16:00:01+00
Removal Date:	1991/10/30 15:59:59+00
Tank Capacity:	8000
Substances:	Gasoline
Tank Wall Type:	Single

Object ID:	717921
Facility ID:	MD5552
Tank ID:	MD5552_8
Tank Status:	Closed
Installation Date:	1969/09/01 16:00:01+00
Removal Date:	1991/10/30 15:59:59+00
Tank Capacity:	6000
Substances:	Gasoline
Tank Wall Type:	Single

Object ID:	717922
Facility ID:	MD5552
Tank ID:	MD5552_9
Tank Status:	Closed
Installation Date:	1969/09/01 16:00:01+00
Removal Date:	1991/10/30 15:59:59+00
Tank Capacity:	6000
Substances:	Gasoline
Tank Wall Type:	Single

Object ID:	731632
Facility ID:	MD5552
Tank ID:	MD5552_1
Tank Status:	Open
Installation Date:	1991/11/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	12000
Substances:	Gasohol

SECURITY BP (Continued) **1028411719**

Tank Wall Type:	Single
Object ID:	731633
Facility ID:	MD5552
Tank ID:	MD5552_2
Tank Status:	Open
Installation Date:	1991/11/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	12000
Substances:	Gasohol
Tank Wall Type:	Single
Object ID:	731634
Facility ID:	MD5552
Tank ID:	MD5552_3
Tank Status:	Open
Installation Date:	1991/11/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	12000
Substances:	Gasohol
Tank Wall Type:	Single

UST FINDER RELEASE:

Object ID:	195224
Facility ID:	MD5552
Lust ID:	MD92-1107BA2
Name:	AMOCO #1221
Address:	6698 SECURITY BLVD
City,State,Zip:	GWYNN OAK, MD 21207
Address Match Type:	PointAddress
Reported Date:	1991/10/31 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	0
Domestic Wells within 1500ft:	0
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	3
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	Geocode
X Coord:	-76.74032116

SECURITY BP (Continued) **1028411719**

Y Coord: 39.3121164300001
Latitude: 39.31211643
Longitude: -76.7403211599999

S134 **RAHILL PROPERTY** **MD OCPCASES** **S104597560**
NE **1720 WHITEHEAD RD** **N/A**
1/4-1/2 **BALTIMORE, MD 21207**
0.328 mi.
1733 ft. **Site 1 of 2 in cluster S**

Relative: **Lower**
Actual: **396 ft.**

OCPCASES:

Name:	RAHILL PROPERTY
Address:	1720 WHITEHEAD RD
City,State,Zip:	BALTIMORE, MD 21207
Facility ID:	99-2858BA2
Facility Status/Code:	CLOSED/B-9
Date Open:	05/27/1999
Date Closed:	10/12/1999
Release:	NO
Cleanup:	NO
Registration Number:	9870

T135 **KOREAN UNITED CHURCH OF BALTIMORE** **UST FINDER RELEASE** **1029020414**
SSW **1501 N ROLLING RD** **N/A**
1/4-1/2 **CATONSVILLE, MD 21228**
0.334 mi.
1763 ft. **Site 1 of 3 in cluster T**

Relative: **Higher**
Actual: **462 ft.**

UST FINDER RELEASE:

Object ID:	189623
Facility ID:	MD11951
Lust ID:	MD92-2214BA1
Name:	KOREAN UNITED CHURCH OF BALTIMORE
Address:	1501 N ROLLING RD
City,State,Zip:	CATONSVILLE, MD 21228
Address Match Type:	PointAddress
Reported Date:	1992/04/15 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	803
Domestic Wells within 1500ft:	6
Land Use:	Developed, Low Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	3
NFA Letter 1:	Not reported

KOREAN UNITED CHURCH OF BALTIMORE (Continued) **1029020414**

NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	Geocode
X Coord:	-76.75383728
Y Coord:	39.30271772
Latitude:	39.3027177199999
Longitude:	-76.7538372799999

T136 **NEW LIFE PRESBYTERIAN CHURCH** **UST FINDER RELEASE** **1029020415**
SSW **1501 N ROLLING RD** **N/A**
1/4-1/2 **CATONSVILLE, MD 21228**
0.334 mi.
1763 ft. **Site 2 of 3 in cluster T**

Relative:
Higher

Actual:
462 ft.

UST FINDER RELEASE:

Object ID:	189624
Facility ID:	MD11951
Lust ID:	MD16-0378BA
Name:	NEW LIFE PRESBYTERIAN CHURCH
Address:	1501 N ROLLING RD
City,State,Zip:	CATONSVILLE, MD 21228
Address Match Type:	PointAddress
Reported Date:	2016/01/06 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	803
Domestic Wells within 1500ft:	6
Land Use:	Developed, Low Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	3
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	Geocode
X Coord:	-76.75383728
Y Coord:	39.30271772
Latitude:	39.3027177199999
Longitude:	-76.7538372799999

T137 **KOREAN UNITED CHURCH** **MD OCPCASES** **1004520880**
SSW **1501 N.ROLLING RD** **US AIRS** **N/A**
1/4-1/2 **BALTIMORE, MD 21228** **FINDS**
0.334 mi. **ECHO**
1763 ft. **Site 3 of 3 in cluster T**

Relative: Higher
Actual: 462 ft.

OCPCASES:

Name:	NEW LIFE PRESBYTERIAN CHURCH
Address:	1501 N ROLLING RD
City,State,Zip:	CATONSVILLE, MD 21228
Facility ID:	16-0378BA
Facility Status/Code:	CLOSED/Tank Closure - Commercial Heating Oil
Date Open:	01/06/2016
Date Closed:	01/03/2017
Release:	YES
Cleanup:	YES
Registration Number:	11951

Name:	KOREAN UNITED CHURCH OF BALTIMORE
Address:	1501 N ROLLING RD
City,State,Zip:	CATONSVILLE, MD 21228
Facility ID:	92-2214BA1
Facility Status/Code:	CLOSED/Tank Closure - Commercial Heating Oil
Date Open:	04/15/1992
Date Closed:	12/27/2005
Release:	YES
Cleanup:	YES
Registration Number:	11951

US AIRS MINOR:

Envid:	1004520880
Region Code:	03
Programmatic ID:	AIR MD0000002400501354
Facility Registry ID:	110001773153
D and B Number:	Not reported
Primary SIC Code:	8661
NAICS Code:	813110
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	03
Programmatic ID:	AIR MD0000002400501354
Facility Registry ID:	110001773153
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1989-01-27 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

FINDS:

Registry ID:	110001773153

KOREAN UNITED CHURCH (Continued) **1004520880**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004520880
Registry ID:	110001773153

DFR URL:

Name:	KOREAN UNITED CHURCH
Address:	1501 N.Rolling Rd
City,State,Zip:	BALTIMORE, MD 21228

S138 **MAC MACHINE** **MD OCPCASES** **S104612823**
NE **1719 WHITEHEAD RD** **N/A**
1/4-1/2 **WOODLAWN, MD 21207**
0.355 mi.
1876 ft. **Site 2 of 2 in cluster S**

Relative: **Lower**
Actual: **401 ft.**

OCPCASES:

Name:	MAC MACHINE
Address:	1719 WHITEHEAD RD
City,State,Zip:	WOODLAWN, MD 21207
Facility ID:	90-0434BA2
Facility Status/Code:	CLOSED/
Date Open:	07/28/1989
Date Closed:	10/10/1989
Release:	Not reported
Cleanup:	Not reported
Registration Number:	Not reported

---

139 **RESIDENTIAL PROPERTY** **MD OCPCASES** **S104606520**
East **6666 SECURITY BLVD** **N/A**
1/4-1/2 **WOODLAWN, MD 21207**
0.362 mi.
1910 ft.

Relative: **Lower**
Actual: **361 ft.**

OCPCASES:

Name:	RESIDENTIAL PROPERTY
Address:	6666 SECURITY BLVD
City,State,Zip:	WOODLAWN, MD 21207
Facility ID:	95-1859BA2
Facility Status/Code:	CLOSED/Soil Contamination - Residential Heating Oil
Date Open:	02/14/1995
Date Closed:	02/14/1995

RESIDENTIAL PROPERTY (Continued) **S104606520**

Release: Not reported
Cleanup: Not reported
Registration Number: Not reported

U140 **BEVERAGE CAPITOL CORP** **MD OCPCASES** **S104848436**
East **1620 WHITEHEAD RD** **N/A**
1/4-1/2 **WOODLAWN, MD 21207**
0.371 mi.
1958 ft. **Site 1 of 2 in cluster U**

Relative: OCPCASES:
Lower
Name: BEVERAGE CAPITOL CORP
Actual: Address: 1620 WHITEHEAD RD
371 ft. City,State,Zip: WOODLAWN, MD 21207
Facility ID: 99-1154BA2
Facility Status/Code: CLOSED/Tank Closure - Motor/Lube Oil
Date Open: 11/05/1998
Date Closed: 03/03/1999
Release: YES
Cleanup: YES
Registration Number: 4212

U141 **BEVERAGE CAPITAL CORP.** **UST FINDER** **1028410864**
East **1620 WHITEHEAD COURT** **UST FINDER RELEASE** **N/A**
1/4-1/2 **BALTIMORE, MD 21207**
0.371 mi.
1958 ft. **Site 2 of 2 in cluster U**

Relative: UST FINDER:
Lower
Object ID: 638141
Actual: Facility ID: MD4212
371 ft. Name: BEVERAGE CAPITAL CORP.
Address: 1620 WHITEHEAD COURT
City,State,Zip: BALTIMORE, MD 21207
Address Match Type: PointAddress
Open USTs: 0
Closed USTs: 1
TOS USTs: 0
Population 1500ft: 0
Private Wells 1500ft: 0
Within 100yr Floodplain: No
Land Use: Developed, High Intensity
Within SPA: No
SPA PWS Facility ID: Not reported
SPA Water Type: Not reported
SPA Facility Type: Not reported
SPA HUC12: Not reported
Within WHPA: No
WHPA PWS Facility ID: Not reported
WHPA Water Type: Not reported
WHPA Facility Type: Not reported
WHPA HUC12: Not reported
Facility Status: Closed UST(s)
Date of Last Inspection: Not reported
EPA Region: 3
Tribe: Not reported

BEVERAGE CAPITAL CORP. (Continued) **1028410864**

Coordinate Source:	Geocode
X Coord:	-76.73870311
Y Coord:	39.3107626300001
Latitude:	39.31076263
Longitude:	-76.73870311

UST FINDER:

Object ID:	701549
Facility ID:	MD4212
Tank ID:	MD4212_1
Tank Status:	Closed
Installation Date:	1980/01/01 16:00:00+00
Removal Date:	1998/11/05 15:59:59+00
Tank Capacity:	10000
Substances:	Diesel
Tank Wall Type:	Single

UST FINDER RELEASE:

Object ID:	194255
Facility ID:	MD4212
Lust ID:	MD99-1154BA2
Name:	BEVERAGE CAPITOL CORP
Address:	1620 WHITEHEAD RD
City,State,Zip:	WOODLAWN, MD 21207
Address Match Type:	StreetAddressExt
Reported Date:	1998/11/05 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	Not reported
Domestic Wells within 1500ft:	Not reported
Land Use:	Not reported
Within SPA:	Not reported
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Not reported
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	Not reported
Tribe:	Not reported
EPA Region:	3
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	Geocode
X Coord:	-76.7405417099999
Y Coord:	39.3123987500001
Latitude:	39.31239875
Longitude:	-76.74054171

V142
WSW
1/4-1/2
0.380 mi.
2007 ft.

TOWN & COUNTRY GARDENWOOD APTS
1609 BLUFFDALE RD
WOODLAWN, MD 21244

Site 1 of 2 in cluster V

MD OCPCASES

S104604455
N/A

Relative:
Higher

Actual:
487 ft.

OCPCASES:

Name:	TOWN & COUNTRY GARDENWOOD APTS
Address:	1609 BLUFFDALE RD
City,State,Zip:	WOODLAWN, MD 21244
Facility ID:	94-2879BA2
Facility Status/Code:	CLOSED/Soil Contamination - Residential Heating Oil
Date Open:	05/02/1994
Date Closed:	05/31/1995
Release:	YES
Cleanup:	Not reported
Registration Number:	10517

Name:	TOWN & COUNTRY GARDENWOOD APTS
Address:	1609 BLUFFDALE RD
City,State,Zip:	WOODLAWN, MD 21244
Facility ID:	94-2879BA2
Facility Status/Code:	CLOSED/Soil Contamination - Residential Heating Oil
Date Open:	05/02/1994
Date Closed:	05/31/1995
Release:	YES
Cleanup:	Not reported
Registration Number:	10517

143
WNW
1/4-1/2
0.381 mi.
2011 ft.

CENTER FOR MEDICADE & MEDICARE
7500 SECURITY BLVD
WOODLAWN, MD 21244

MD OCPCASES

S107176693
N/A

Relative:
Lower

Actual:
441 ft.

OCPCASES:

Name:	CENTER FOR MEDICADE & MEDICARE
Address:	7500 SECURITY BLVD
City,State,Zip:	WOODLAWN, MD 21244
Facility ID:	05-1221BA
Facility Status/Code:	OPEN/Transfer Accident - Emergency
Date Open:	06/14/2005
Date Closed:	Not reported
Release:	YES
Cleanup:	Not reported
Registration Number:	2733

144
NNE
1/4-1/2
0.384 mi.
2027 ft.

MATTHEWS PROPERTY
6701 EDWARDS AVE
BALTIMORE, MD 21244

MD OCPCASES

S104598232
N/A

Relative:
Lower

Actual:
384 ft.

OCPCASES:

Name:	MATTHEWS PROPERTY
Address:	6701 EDWARDS AVE
City,State,Zip:	BALTIMORE, MD 21244
Facility ID:	96-0544BA2

MATTHEWS PROPERTY (Continued) **S104598232**

Facility Status/Code:	CLOSED/Dumping
Date Open:	09/19/1995
Date Closed:	09/19/1995
Release:	Not reported
Cleanup:	Not reported
Registration Number:	Not reported

V145
WSW
1/4-1/2
0.386 mi.
2039 ft.

TOWN & COUNTRY GARDEN WOOD APTS **MD OCPCASES** **S104604404**
1621 BLUFFDALE RD **N/A**
WOODLAWN, MD 21244

Site 2 of 2 in cluster V

Relative:
Higher

Actual:
487 ft.

OCPCASES:

Name:	TOWN & COUNTRY GARDEN WOOD APTS
Address:	1621 BLUFFDALE RD
City,State,Zip:	WOODLAWN, MD 21244
Facility ID:	94-2820BA2
Facility Status/Code:	CLOSED/
Date Open:	05/02/1994
Date Closed:	06/01/1995
Release:	Not reported
Cleanup:	Not reported
Registration Number:	10517

Name:	TOWN & COUNTRY GARDEN WOOD APTS
Address:	1621 BLUFFDALE RD
City,State,Zip:	WOODLAWN, MD 21244
Facility ID:	94-2820BA2
Facility Status/Code:	CLOSED/
Date Open:	05/02/1994
Date Closed:	06/01/1995
Release:	Not reported
Cleanup:	Not reported
Registration Number:	10517

W146
East
1/4-1/2
0.426 mi.
2251 ft.

FOX CHEVROLET **UST FINDER** **1028411880**
6633 SECURITY BLVD. **UST FINDER RELEASE** **N/A**
BALTIMORE, MD 21207

Site 1 of 4 in cluster W

Relative:
Lower

Actual:
350 ft.

UST FINDER:

Object ID:	638165
Facility ID:	MD5769
Name:	FOX CHEVROLET
Address:	6633 SECURITY BLVD.
City,State,Zip:	BALTIMORE, MD 21207
Address Match Type:	PointAddress
Open USTs:	0
Closed USTs:	8
TOS USTs:	0
Population 1500ft:	0
Private Wells 1500ft:	0
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity

FOX CHEVROLET (Continued) **1028411880**

Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	3
Tribe:	Not reported
Coordinate Source:	Geocode
X Coord:	-76.73777976
Y Coord:	39.3119606500001
Latitude:	39.31196065
Longitude:	-76.73777976

UST FINDER:

Object ID:	727385
Facility ID:	MD5769
Tank ID:	MD5769_5
Tank Status:	Closed
Installation Date:	1971/05/01 16:00:00+00
Removal Date:	1976/03/01 16:00:00+00
Tank Capacity:	6000
Substances:	Not Listed
Tank Wall Type:	Single

Object ID:	727386
Facility ID:	MD5769
Tank ID:	MD5769_6
Tank Status:	Closed
Installation Date:	1971/05/01 16:00:00+00
Removal Date:	1976/03/01 16:00:00+00
Tank Capacity:	6000
Substances:	Not Listed
Tank Wall Type:	Single

Object ID:	691311
Facility ID:	MD5769
Tank ID:	MD5769_8
Tank Status:	Closed
Installation Date:	1992/05/01 15:59:59+00
Removal Date:	2009/02/17 15:59:59+00
Tank Capacity:	500
Substances:	Used Oil
Tank Wall Type:	Single

Object ID:	691312
Facility ID:	MD5769
Tank ID:	MD5769_7
Tank Status:	Closed
Installation Date:	1992/05/01 15:59:59+00
Removal Date:	2009/02/17 15:59:59+00
Tank Capacity:	3000

FOX CHEVROLET (Continued) **1028411880**

Substances: Gasoline
Tank Wall Type: Single

Object ID: 714722
Facility ID: MD5769
Tank ID: MD5769_2
Tank Status: Closed
Installation Date: 1971/05/01 16:00:00+00
Removal Date: 1993/04/12 15:59:59+00
Tank Capacity: 2000
Substances: Diesel
Tank Wall Type: Single

Object ID: 717518
Facility ID: MD5769
Tank ID: MD5769_1
Tank Status: Closed
Installation Date: 1971/05/01 16:00:00+00
Removal Date: 1992/01/08 15:59:59+00
Tank Capacity: 4000
Substances: Gasoline
Tank Wall Type: Single

Object ID: 712662
Facility ID: MD5769
Tank ID: MD5769_3
Tank Status: Closed
Installation Date: 1971/05/01 16:00:00+00
Removal Date: 1994/03/07 15:59:59+00
Tank Capacity: 2000
Substances: Other
Tank Wall Type: Single

Object ID: 712663
Facility ID: MD5769
Tank ID: MD5769_4
Tank Status: Closed
Installation Date: 1971/05/01 16:00:00+00
Removal Date: 1994/03/07 15:59:59+00
Tank Capacity: 2000
Substances: Other
Tank Wall Type: Single

UST FINDER RELEASE:
Object ID: 195378
Facility ID: MD5769
Lust ID: MD92-1504BA2
Name: FOX CHEVROLET
Address: 6333 SECURITY BLVD
City,State,Zip: WOODLAWN, MD 21207
Address Match Type: StreetAddress
Reported Date: 1992/01/08 15:59:59+00
Status: No Further Action
Substance: Not reported
Population within 1500ft: 125
Domestic Wells within 1500ft: 0

FOX CHEVROLET (Continued) **1028411880**

Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	3
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	Geocode
X Coord:	-76.72840567
Y Coord:	39.31151249
Latitude:	39.3115124899999
Longitude:	-76.72840567

W147 **FOX CHEVROLET** **MD OCPCASES** **S120841849**
East **6633 SECURITY BLVD** **N/A**
1/4-1/2 **WOODLAWN, MD 21207**
0.426 mi.
2251 ft. **Site 2 of 4 in cluster W**

Relative: OCPCASES:
Lower

Name:	FOX CHEVROLET
Address:	6633 SECURITY BLVD
City,State,Zip:	WOODLAWN, MD 21207
Facility ID:	09-0496BA
Facility Status/Code:	CLOSED/Tank Closure - Motor/Lube Oil
Date Open:	02/17/2009
Date Closed:	07/06/2009
Release:	NO
Cleanup:	NO
Registration Number:	5769

Actual:
350 ft.

W148 **TCG MANAGEMENT INC** **MD OCPCASES** **S116600046**
East **6640 SECURITY BLVD** **N/A**
1/4-1/2 **WOODLAWN, MD 21207**
0.458 mi.
2417 ft. **Site 3 of 4 in cluster W**

Relative: OCPCASES:
Lower

Name:	TCG MANAGEMENT INC
Address:	6640 SECURITY BLVD
City,State,Zip:	WOODLAWN, MD 21207
Facility ID:	91-2687BA
Facility Status/Code:	CLOSED/
Date Open:	07/15/1991

Actual:
354 ft.

TCG MANAGEMENT INC (Continued) **S116600046**

Date Closed:	07/15/1991
Release:	Not reported
Cleanup:	Not reported
Registration Number:	Not reported

149
NW
1/4-1/2
0.465 mi.
2454 ft.

LITTLE SLIPPER DAY CARE INC **MD OCPCASES** **S104614372**
2112 N ROLLING RD **N/A**
WINDSOR MILL, MD 21244

Relative:
Lower

Actual:
418 ft.

OCPCASES:

Name:	LITTLE SLIPPER DAY CARE INC
Address:	2112 N ROLLING RD
City,State,Zip:	WINDSOR MILL, MD 21244
Facility ID:	90-2351BA2
Facility Status/Code:	CLOSED/
Date Open:	05/22/1990
Date Closed:	12/22/1993
Release:	Not reported
Cleanup:	Not reported
Registration Number:	Not reported

W150
East
1/4-1/2
0.465 mi.
2454 ft.

MEADOWS PARK SHOPPING CENTER **MD INST CONTROL** **S105121561**
6606-6658 SECURITY BOULEVARD **MD VCP** **N/A**
BALTIMORE, MD 21207 **MD LRP**

Site 4 of 4 in cluster W

Relative:
Lower

Actual:
353 ft.

INST CONTROL:

Name:	MEADOWS PARK SHOPPING CENTER
Address:	6606-6658 SECURITY BOULEVARD
City,State,Zip:	BALTIMORE, MD 21207
Site Alias:	Not reported
App Name:	A&E Partners, LPI
Type Name:	NFRD
Low Freq Recreational:	False
Medium Freq Recreational:	False
High Freq Recrreation:	False
Other Rest:	False
Other Rest Notes:	Not reported
Shape Length:	0
Shape Area:	0
Property Account Id:	04011600013396
Issue Date:	04/05/2002
Covenant:	False
Date Covenant Recorded:	Not reported
Residential Land Use Unrestricted:	False
Residential Land Use Restricted:	True
Recreational Land Use Unrestricted:	No
Recreational Land Use Restricted:	No
Commercial Land Use Unrestricted:	False
Commercial Land Use Restricted:	True
Industrial Land Use Unrestricted:	False
Industrial Land Use Restricted:	True
Groundwater(GW) Use Restriction?:	True

MEADOWS PARK SHOPPING CENTER (Continued) **S105121561**

GW Encountered During Excavation Rqmnts?:	False
Continued GW Remediation?:	False
Long Term Monitoring For GW?:	False
Excavation Notification Restriction?:	False
Vapor Barrier Required?:	False
Vapor System Required?:	False
Long Term Monitoring Of Indoor Air?:	False
Active Dry Cleaner Restrictions?:	False
Paving Maintenance Required?:	False
Future Construction Testing Required?:	False
Slab Maintenance Required?:	False
Excavated Material Disposal Requirement?:	False
BMI Number:	MD1199
Archive:	True
Acres:	12.51
Count Acres Toward Total:	True

VCP:

Name:	MEADOWS PARK SHOPPING CENTER
Address:	6606-6658 SECURITY BOULEVARD
City,State,Zip:	BALTIMORE, MD 21207
Application Status:	NY
Acreage:	12.51
Applicants Name:	A&E Partners, LPI
Applicants Address:	c/o Emmes Asset Management LLC; 420 Lexington Avenue, Suite 900
Applicants City:	New York
Applicants Zip:	10170
Initial RAP submitted on:	Not reported
RAP accepted on:	Not reported
Sign posted on:	Not reported
Date withdrawn:	Not reported
Application submitted on:	07/19/2001
Application accepted on:	04/05/2002
Date issued:	04/05/2002
Withdrawn:	False
VCP:	True
Public Meeting Date:	Not reported
Site Alias:	Not reported
Type Name:	NFRD
BMI Number:	MD1199
Party Status Description:	RESPONSIBLE PERSON

MD LRP:

Name:	MEADOWS PARK SHOPPING CENTER
Address:	6606-6658 Security Boulevard
City,State,Zip:	BALTIMORE, MD 21207

Factsheet URL:

Voluntary Cleanup Program:	Yes
Brownfield Assesment Complete:	No
NPL:	No
Federal Facility:	No
Alias:	Not reported
Groundwater:	No
Assessment On-Going:	No
Remediation On-Going:	No

MEADOWS PARK SHOPPING CENTER (Continued) **S105121561**

Withdrawn:	No
GW Chlorinated:	Yes
GW Petroleum:	No
GW Metals:	Yes
GW Pesticides:	No
GW PCB:	No
GW PAH:	No
Soil Chlorinated:	Yes
Soil Metals:	No
Soil Pesticides:	No
Soil PCB:	No
Soil PAH:	No
Soil Petroleum:	No
Sediment Chlorinated:	No
Sediment Petroleum:	No
Sediment Metals:	No
Sediment Pesticides:	No
Sediment PCB:	No
Sediment PAH:	No
SW Chlorinated:	No
SW Petroleum:	No
SW Metals:	No
SW Pesticides:	No
SW PCB:	No
SW PAH:	No
Site Assessment:	No
Tax Map Number:	Not reported
File Available:	No
BMI Number:	MD1199
Archived:	Yes
Table Site ID:	849
Parcel Number:	Not reported
Block:	Not reported
Lot Number:	Not reported
Tax ID:	Not reported
Det Issued:	Yes
Enfor congo:	No
CHS Oversig:	No
EPAID:	Not reported
Regulatory:	Not reported
FY Open:	2002
FY_Closed:	2002

151
East
1/4-1/2
0.495 mi.
2615 ft.

AUTONATION LOCATION ID 2763
6611 SECURITY BLVD
BALTIMORE, MD 21207

MD OCPCASES **U004272521**
MD UST **N/A**
MD Financial Assurance

Relative:
Lower

Actual:
346 ft.

OCPCASES:

Name:	AUTONATION LOCATION ID 2763
Address:	6611 SECURITY BLVD
City,State,Zip:	WOODLAWN, MD 21207
Facility ID:	17-0667BA
Facility Status/Code:	CLOSED/Tank Closure - Motor/Lube Oil
Date Open:	06/02/2017
Date Closed:	01/03/2018
Release:	NO

AUTONATION LOCATION ID 2763 (Continued) **U004272521**

Cleanup: NO
Registration Number: 20757

UST:
Facility Id: 20757
Oper Name: Not reported
Form Name: Jeffrey Shupert
Form Title: Owner's Rep
Form Date: 06/20/2017
Owner Id: 3507

Owner:
Owner Name: Fox Chevrolet, LLC
Owner Address: 200 SW 1ST AVE FL 14
Owner City: Fort Lauderdale
Owner State: FL
Owner Zip: 33301
Owner Phone: (954) 769-6156
Owner Contact: Jeffrey Shupert

Tanks:
Tank ID: 1
Tank Status: Permanently Out Of Use
Tank Capacity: Not reported
Substance Description: Used Oil
Tank Compartment: False
Compartment Compartment: A
Date Installed: Not reported
Tank Material Desc: Asphalt Coated or Bare Steel
Pipe Material Desc: Bare or Galvanized Steel

MD Financial Assurance 2:
Name: AUTONATION LOCATION ID 2763
Address: 6611 SECURITY BLVD
City,State,Zip: BALTIMORE, MD 21207
Region: 2
Facility ID: 20757
Self Insured: False
Insurance: False
Risk Retention Group: False
Guarantee: False
Surety Bonds: False
Letter of Credit: False
State Fund: False
Other Finance: False
Finacnce Comments: Not reported
FR Not Listed: False

Count: 12 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BALTIMORE	S120842340	C & P C & P TELEPHONE / WOODLAWN C	6810 DOGWOOD RD	21244	MD OCPCASES
BALTIMORE	S120842535	C & P COIN CENTER	6810 DOGWOOD RD	21244	MD OCPCASES
BALTIMORE	S120842351	C&P TELEPHONE COIN CENTER	6810 DOGWOOD RD	21244	MD OCPCASES
BALTIMORE	S105040387	VERIZON COIN CENTER	6810 DOGWOOD RD	21244	MD OCPCASES
BALTIMORE	S104607585	MONTGOMERY WARD	SECURITY SQUARE MALL	21207	MD OCPCASES
CATONSVILLE	S107544382	ROLLING ROAD CLEANERS	1128 ROLLING ROAD, NORTH	21228	MD DRYCLEANERS
CATONSVILLE	S117658842	BG&E/CNR	ROLLING RD & GEIPE RD	21228	MD OCPCASES
WOODLAWN	S104617809	PATTERSON RESIDENCE	6841 DOGWOOD RD	21207	MD OCPCASES
WOODLAWN	S105040072	HELLMAN RESIDENCE	8109 DOGWOOD RD	21207	MD OCPCASES
WOODLAWN	S104603915	RECON-WAGMAN	I-70 PARK & RIDE	21207	MD OCPCASES
WOODLAWN	1004523093	DOGWOOD CLEANERS	2331 ROLLING ROAD, NORTH	21207	US AIRS, MD DRYCLEANERS
WOODLAWN	S108472384	BG&E MEADOWS SUBSTATION	1508 SECURITY BLVD	21207	MD OCPCASES

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: EPA
Telephone: N/A
Last EDR Contact: 07/01/2025
Next Scheduled EDR Contact: 10/06/2025
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: EPA
Telephone: N/A
Last EDR Contact: 07/01/2025
Next Scheduled EDR Contact: 10/06/2025
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Lists of Federal Delisted NPL sites

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: EPA
Telephone: N/A
Last EDR Contact: 07/01/2025
Next Scheduled EDR Contact: 10/06/2025
Data Release Frequency: Quarterly

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 11/20/2024
Date Data Arrived at EDR: 12/18/2024
Date Made Active in Reports: 12/20/2024
Number of Days to Update: 2

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 06/20/2025
Next Scheduled EDR Contact: 10/06/2025
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 07/01/2025
Next Scheduled EDR Contact: 10/20/2025
Data Release Frequency: Quarterly

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 07/01/2025
Next Scheduled EDR Contact: 10/20/2025
Data Release Frequency: Quarterly

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/03/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 13

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 06/03/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

Lists of Federal RCRA TSD facilities

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: 800-438-2474
Last EDR Contact: 06/04/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

Lists of Federal RCRA generators

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: 800-438-2474
Last EDR Contact: 06/04/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: 800-438-2474
Last EDR Contact: 06/04/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: 800-438-2474
Last EDR Contact: 06/04/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 03/11/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 06/24/2025
Number of Days to Update: 83

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 04/30/2025
Next Scheduled EDR Contact: 08/18/2025
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 01/29/2025
Date Data Arrived at EDR: 02/18/2025
Date Made Active in Reports: 04/29/2025
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 05/20/2025
Next Scheduled EDR Contact: 12/02/2024
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 01/29/2025
Date Data Arrived at EDR: 02/18/2025
Date Made Active in Reports: 04/29/2025
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 05/20/2025
Next Scheduled EDR Contact: 09/01/2025
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 06/10/2025
Date Data Arrived at EDR: 06/12/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 4

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 06/12/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

Lists of state- and tribal hazardous waste facilities

SHWS: Notice of Potential Hazardous Waste Sites

State Hazardous Waste Sites. State hazardous waste site records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. Available information varies by state.

Date of Government Version: 10/01/2009
Date Data Arrived at EDR: 12/11/2009
Date Made Active in Reports: 12/14/2009
Number of Days to Update: 3

Source: Department of the Environment
Telephone: 410-537-3000
Last EDR Contact: 07/22/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Semi-Annually

Lists of state and tribal landfills and solid waste disposal facilities

SWF/LF: Permitted Solid Waste Disposal Facilities

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 03/03/2025
Date Data Arrived at EDR: 04/22/2025
Date Made Active in Reports: 07/15/2025
Number of Days to Update: 84

Source: Department of the Environment
Telephone: 410-537-3375
Last EDR Contact: 07/21/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Annually

Lists of state and tribal leaking storage tanks

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land

A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 01/07/2025
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 01/07/2025
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

OCPCASES: Oil Control Program Cases
Cases monitored by the Oil Control Program. these cases can be leaking underground storage tanks and other belowground releases, leaking aboveground storage tanks, spills and inspections.

Date of Government Version: 01/02/2025
Date Data Arrived at EDR: 02/11/2025
Date Made Active in Reports: 02/19/2025
Number of Days to Update: 8

Source: Department of Environment
Telephone: 410-537-3433
Last EDR Contact: 04/30/2025
Next Scheduled EDR Contact: 08/18/2025
Data Release Frequency: Semi-Annually

HIST LUST: Recovery Sites

In 1999, the Department of the Environment stopped adding new sites to its Recovery Sites Database. Current leaking underground storage tank information maybe found in the OCPCASES database.

Date of Government Version: 03/01/1999
Date Data Arrived at EDR: 03/22/1999
Date Made Active in Reports: 04/16/1999
Number of Days to Update: 25

Source: Department of the Environment
Telephone: 410-537-3433
Last EDR Contact: 02/19/2001
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Lists of state and tribal registered storage tanks

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 04/08/2025
Date Data Arrived at EDR: 04/23/2025
Date Made Active in Reports: 04/24/2025
Number of Days to Update: 1

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 06/24/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

UST: Registered Underground Storage Tank List

Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 04/01/2025
Date Data Arrived at EDR: 04/16/2025
Date Made Active in Reports: 07/09/2025
Number of Days to Update: 84

Source: Department of the Environment
Telephone: 410-537-3433
Last EDR Contact: 06/24/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Semi-Annually

AST: Permitted Aboveground Storage Tanks

Registered Aboveground Storage Tanks.

Date of Government Version: 04/01/2025
Date Data Arrived at EDR: 04/16/2025
Date Made Active in Reports: 07/09/2025
Number of Days to Update: 84

Source: Department of The Environment
Telephone: 410-537-3000
Last EDR Contact: 05/28/2025
Next Scheduled EDR Contact: 09/15/2025
Data Release Frequency: Semi-Annually

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 11/08/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 10/15/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 01/07/2025
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

State and tribal institutional control / engineering control registries

ENG CONTROLS: Engineering Controls Site listing
Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 11/10/2008
Date Data Arrived at EDR: 11/21/2008
Date Made Active in Reports: 12/17/2008
Number of Days to Update: 26
Source: Department of the Environment
Telephone: 410-537-3422
Last EDR Contact: 05/28/2025
Next Scheduled EDR Contact: 09/15/2025
Data Release Frequency: Varies

INST CONTROL: Voluntary Cleanup Program Applicants/Participants
Sites included in the Voluntary Cleanup Program Applicants/Participants listing that have Deed Restrictions.

Date of Government Version: 09/23/2024
Date Data Arrived at EDR: 10/04/2024
Date Made Active in Reports: 12/20/2024
Number of Days to Update: 77
Source: Department of the Environment
Telephone: 410-537-3493
Last EDR Contact: 05/28/2025
Next Scheduled EDR Contact: 09/15/2025
Data Release Frequency: Semi-Annually

Lists of state and tribal voluntary cleanup sites

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142
Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 06/10/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Varies

VCP: Voluntary Cleanup Program Applicants/Participants
The Voluntary Cleanup Program, administrated by the Dept. of the Environment, streamlines the environmental cleanup process for sites, usually industrial or commercial properties, that are contaminated, or perceived to be contaminated, by hazardous substances. Developers and lenders are provided with certain limitations on liability and participants in the program are provided certainty in the process by knowing exactly what will be required.

Date of Government Version: 09/23/2024
Date Data Arrived at EDR: 10/04/2024
Date Made Active in Reports: 12/20/2024
Number of Days to Update: 77
Source: Dept. of the Environment
Telephone: 410-537-3000
Last EDR Contact: 05/28/2025
Next Scheduled EDR Contact: 09/15/2025
Data Release Frequency: Semi-Annually

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27
Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 07/08/2021
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

Lists of state and tribal brownfield sites

BROWNFIELDS: Eligible Brownfields Properties
The Site Assessment Section of the State Superfund Division is responsible for conducting federally funded assessments of eligible brownfields properties. These assessments are undertaken to determine whether there are environmental cleanup requirements at these sites.

Date of Government Version: 12/11/2024
Date Data Arrived at EDR: 02/25/2025
Date Made Active in Reports: 05/12/2025
Number of Days to Update: 76

Source: Department of Environment
Telephone: 410-537-3000
Last EDR Contact: 05/29/2025
Next Scheduled EDR Contact: 09/08/2025
Data Release Frequency: Quarterly

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 09/09/2024
Date Data Arrived at EDR: 09/11/2024
Date Made Active in Reports: 12/06/2024
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 06/10/2025
Next Scheduled EDR Contact: 09/22/2025
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWRCY: Recycling Directory

A listing of recycling facilities.

Date of Government Version: 03/10/2025
Date Data Arrived at EDR: 03/12/2025
Date Made Active in Reports: 05/30/2025
Number of Days to Update: 79

Source: Department of the Environment
Telephone: 410-631-3314
Last EDR Contact: 06/03/2025
Next Scheduled EDR Contact: 09/22/2025
Data Release Frequency: Varies

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 07/15/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Varies

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 07/08/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 02/07/2024
Date Data Arrived at EDR: 11/13/2024
Date Made Active in Reports: 11/19/2024
Number of Days to Update: 6

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 07/17/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 12/31/2024
Date Data Arrived at EDR: 02/20/2025
Date Made Active in Reports: 04/29/2025
Number of Days to Update: 68

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 06/02/2025
Next Scheduled EDR Contact: 09/01/2025
Data Release Frequency: No Update Planned

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 12/31/2024
Date Data Arrived at EDR: 02/20/2025
Date Made Active in Reports: 04/29/2025
Number of Days to Update: 68

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 06/02/2025
Next Scheduled EDR Contact: 09/01/2025
Data Release Frequency: Quarterly

Local Lists of Registered Storage Tanks

Historical UST: Historical UST Registered Database

In 1997 the Department of the Environment sent out registration forms to all the owner's listed in the UST database. Once they got the registration forms back they entered the information into a new UST database. we call this database UST. Because not all owners returned their forms, we kept the old UST database and labeled it HIST UST so that we would not be missing any past UST records. This listing is no longer updated or maintained by the agency. It is current through November 1996.

Date of Government Version: 11/21/1996
Date Data Arrived at EDR: 09/10/1997
Date Made Active in Reports: 10/22/1997
Number of Days to Update: 42

Source: Department of Environment
Telephone: 410-537-3433
Last EDR Contact: 05/15/2000
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Local Land Records

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 07/01/2025
Next Scheduled EDR Contact: 10/06/2025
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 06/11/2025
Date Data Arrived at EDR: 06/12/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 4

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 06/12/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 07/15/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/06/2013
Number of Days to Update: 62

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: 800-438-2474
Last EDR Contact: 06/04/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 01/30/2025
Date Data Arrived at EDR: 02/11/2025
Date Made Active in Reports: 04/24/2025
Number of Days to Update: 72

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 07/23/2025
Next Scheduled EDR Contact: 08/25/2025
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 06/07/2021
Date Data Arrived at EDR: 07/13/2021
Date Made Active in Reports: 03/09/2022
Number of Days to Update: 239

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 07/07/2025
Next Scheduled EDR Contact: 10/20/2025
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 06/25/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 07/30/2021
Date Data Arrived at EDR: 02/03/2023
Date Made Active in Reports: 02/10/2023
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 05/08/2025
Next Scheduled EDR Contact: 08/18/2025
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/03/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 13

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 06/03/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA Watch List

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 04/28/2025
Next Scheduled EDR Contact: 08/11/2025
Data Release Frequency: No Update Planned

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 05/01/2025
Next Scheduled EDR Contact: 08/11/2025
Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 06/14/2022
Date Made Active in Reports: 03/24/2023
Number of Days to Update: 283

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 06/12/2025
Next Scheduled EDR Contact: 09/22/2025
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 02/11/2025
Date Made Active in Reports: 02/18/2025
Number of Days to Update: 7

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 05/15/2025
Next Scheduled EDR Contact: 08/25/2025
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 04/14/2025
Date Data Arrived at EDR: 04/15/2025
Date Made Active in Reports: 07/08/2025
Number of Days to Update: 84

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 07/14/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 04/25/2025
Date Data Arrived at EDR: 05/01/2025
Date Made Active in Reports: 05/21/2025
Number of Days to Update: 20

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 07/01/2025
Next Scheduled EDR Contact: 09/08/2025
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 04/05/2025
Date Data Arrived at EDR: 04/11/2025
Date Made Active in Reports: 07/08/2025
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 07/09/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 02/26/2025
Date Data Arrived at EDR: 03/03/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 07/01/2025
Next Scheduled EDR Contact: 08/11/2025
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 07/01/2024
Date Data Arrived at EDR: 10/02/2024
Date Made Active in Reports: 01/10/2025
Number of Days to Update: 100

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 07/02/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 06/23/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 05/07/2025
Date Data Arrived at EDR: 05/07/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 27
Source: Nuclear Regulatory Commission
Telephone: 301-415-0717
Last EDR Contact: 07/08/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 10/16/2024
Date Made Active in Reports: 01/14/2025
Number of Days to Update: 90
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 05/22/2025
Next Scheduled EDR Contact: 09/08/2025
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 05/22/2025
Next Scheduled EDR Contact: 09/08/2025
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 05/01/2025
Next Scheduled EDR Contact: 08/11/2025
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 06/17/2025
Next Scheduled EDR Contact: 10/06/2025
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 03/31/2025
Date Data Arrived at EDR: 04/22/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 86

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 07/17/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 03/31/2025
Date Data Arrived at EDR: 05/02/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 76

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 06/24/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 02/19/2025
Date Made Active in Reports: 03/07/2025
Number of Days to Update: 16

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 06/03/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 06/25/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 03/03/2023
Date Data Arrived at EDR: 03/03/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 98

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 05/01/2025
Next Scheduled EDR Contact: 08/11/2025
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 02/12/2025
Date Data Arrived at EDR: 02/12/2025
Date Made Active in Reports: 02/27/2025
Number of Days to Update: 15

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 05/15/2025
Next Scheduled EDR Contact: 08/25/2025
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 07/01/2025
Next Scheduled EDR Contact: 10/06/2025
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data
A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

MINES VIOLATIONS: MSHA Violation Assessment Data
Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 04/01/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 06/24/2025
Number of Days to Update: 83

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 07/01/2025
Next Scheduled EDR Contact: 09/01/2025
Data Release Frequency: Quarterly

US MINES: Mines Master Index File
Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 02/03/2025
Date Data Arrived at EDR: 02/18/2025
Date Made Active in Reports: 03/20/2025
Number of Days to Update: 30

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 05/20/2025
Next Scheduled EDR Contact: 09/01/2025
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing
This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 05/02/2024
Date Data Arrived at EDR: 08/20/2024
Date Made Active in Reports: 10/09/2024
Number of Days to Update: 50

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 05/20/2025
Next Scheduled EDR Contact: 09/01/2025
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing
Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 05/22/2025
Next Scheduled EDR Contact: 09/01/2025
Data Release Frequency: Varies

MINES MRDS: Mineral Resources Data System
Mineral Resources Data System

Date of Government Version: 06/04/2024
Date Data Arrived at EDR: 11/22/2024
Date Made Active in Reports: 02/18/2025
Number of Days to Update: 88

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 05/22/2025
Next Scheduled EDR Contact: 09/01/2025
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 05/28/2025
Date Data Arrived at EDR: 05/28/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 6

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 05/28/2025
Next Scheduled EDR Contact: 09/15/2025
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 04/22/2025
Date Data Arrived at EDR: 05/05/2025
Date Made Active in Reports: 05/21/2025
Number of Days to Update: 16

Source: EPA
Telephone: (215) 814-5000
Last EDR Contact: 05/05/2025
Next Scheduled EDR Contact: 09/08/2025
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 02/14/2025
Date Data Arrived at EDR: 03/11/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 84

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 07/02/2025
Next Scheduled EDR Contact: 10/20/2025
Data Release Frequency: Varies

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/21/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 82

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 05/14/2025
Next Scheduled EDR Contact: 09/01/2025
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 03/23/2025
Date Data Arrived at EDR: 03/27/2025
Date Made Active in Reports: 06/24/2025
Number of Days to Update: 89

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 06/25/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Quarterly

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 02/13/2025
Date Data Arrived at EDR: 02/13/2025
Date Made Active in Reports: 04/29/2025
Number of Days to Update: 75

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 05/13/2025
Next Scheduled EDR Contact: 08/25/2025
Data Release Frequency: Quarterly

PFAS NPL: Superfund Sites with PFAS Detections Information

EPA's Office of Land and Emergency Management and EPA Regional Offices maintain data describing what is known about site investigations, contamination, and remedial actions under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) where PFAS is present in the environment.

Date of Government Version: 03/31/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 05/05/2025
Number of Days to Update: 33

Source: Environmental Protection Agency
Telephone: 703-603-8895
Last EDR Contact: 06/26/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

PFAS FEDERAL SITES: Federal Sites PFAS Information

Several federal entities, such as the federal Superfund program, Department of Defense, National Aeronautics and Space Administration, Department of Transportation, and Department of Energy provided information for sites with known or suspected detections at federal facilities.

Date of Government Version: 03/31/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 05/05/2025
Number of Days to Update: 33

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 06/26/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

PFAS TSCA: PFAS Manufacture and Imports Information

EPA issued the Chemical Data Reporting (CDR) Rule under the Toxic Substances Control Act (TSCA) and requires chemical manufacturers and facilities that manufacture or import chemical substances to report data to EPA. EPA publishes non-confidential business information (non-CBI) and includes descriptive information about each site, corporate parent, production volume, other manufacturing information, and processing and use information.

Date of Government Version: 03/31/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 05/05/2025
Number of Days to Update: 33

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 06/26/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

PFAS TRIS: List of PFAS Added to the TRI

Section 7321 of the National Defense Authorization Act for Fiscal Year 2020 (NDAA) immediately added certain per- and polyfluoroalkyl substances (PFAS) to the list of chemicals covered by the Toxics Release Inventory (TRI) under Section 313 of the Emergency Planning and Community Right-to-Know Act (EPCRA) and provided a framework for additional PFAS to be added to TRI on an annual basis.

Date of Government Version: 03/07/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 05/05/2025
Number of Days to Update: 33

Source: Environmental Protection Agency
Telephone: 202-566-0250
Last EDR Contact: 06/26/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

PFAS RCRA MANIFEST: PFAS Transfers Identified In the RCRA Database Listing

To work around the lack of PFAS waste codes in the RCRA database, EPA developed the PFAS Transfers dataset by mining e-Manifest records containing at least one of these common PFAS keywords: PFAS, PFOA, PFOS, PERFL, AFFF, GENX, GEN-X (plus the VT waste codes). These keywords were searched for in the following text fields: Manifest handling instructions (MANIFEST_HANDLING_INSTR), Non-hazardous waste description (NON_HAZ_WASTE_DESCRIPTION), DOT printed information (DOT_PRINTED_INFORMATION), Waste line handling instructions (WASTE_LINE_HANDLING_INSTR), Waste residue comments (WASTE_RESIDUE_COMMENTS).

Date of Government Version: 03/23/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 05/05/2025
Number of Days to Update: 33

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 06/23/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

PFAS ATSDR: PFAS Contamination Site Location Listing

PFAS contamination site locations from the Department of Health & Human Services, Center for Disease Control & Prevention. ATSDR is involved at a number of PFAS-related sites, either directly or through assisting state and federal partners. As of now, most sites are related to drinking water contamination connected with PFAS production facilities or fire training areas where aqueous film-forming firefighting foam (AFFF) was regularly used.

Date of Government Version: 06/24/2020
Date Data Arrived at EDR: 03/17/2021
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 601

Source: Department of Health & Human Services
Telephone: 202-741-5770
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Varies

PFAS WQP: Ambient Environmental Sampling for PFAS

The Water Quality Portal (WQP) is a part of a modernized repository storing ambient sampling data for all environmental media and tissue samples. A wide range of federal, state, tribal and local governments, academic and non-governmental organizations and individuals submit project details and sampling results to this public repository. The information is commonly used for research and assessments of environmental quality.

Date of Government Version: 03/03/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 05/21/2025
Number of Days to Update: 49

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 06/26/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

PFAS PROJECT: NORTHEASTERN UNIVERSITY PFAS PROJECT

The PFAS Contamination Site Tracker records qualitative and quantitative data from each site in a chart, specifically examining discovery, contamination levels, government response, litigation, health impacts, media coverage, and community characteristics. All data presented in the chart were extracted from government websites, such as state health departments or the Environmental Protection Agency, and news articles.

Date of Government Version: 05/15/2024
Date Data Arrived at EDR: 03/06/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 89

Source: Social Science Environmental Health Research Institute
Telephone: N/A
Last EDR Contact: 06/05/2025
Next Scheduled EDR Contact: 09/15/2025
Data Release Frequency: Varies

PFAS NPDES: Clean Water Act Discharge Monitoring Information

Any discharger of pollutants to waters of the United States from a point source must have a National Pollutant Discharge Elimination System (NPDES) permit. The process for obtaining limits involves the regulated entity (permittee) disclosing releases in a NPDES permit application and the permitting authority (typically the state but sometimes EPA) deciding whether to require monitoring or monitoring with limits. Caveats and Limitations: Less than half of states have required PFAS monitoring for at least one of their permittees and fewer states have established PFAS effluent limits for permittees. New rulemakings have been initiated that may increase the number of facilities monitoring for PFAS in the future.

Date of Government Version: 03/24/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 05/21/2025
Number of Days to Update: 49

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 06/26/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

PFAS ECHO: Facilities in Industries that May Be Handling PFAS Listing

Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

Date of Government Version: 03/24/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 05/21/2025
Number of Days to Update: 49

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 06/26/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

PFAS ECHO FIRE TRAIN: Facilities in Industries that May Be Handling PFAS Listing

A list of fire training sites was added to the Industry Sectors dataset using a keyword search on the permitted facilitys name to identify sites where fire-fighting foam may have been used in training exercises. Additionally, you may view an example spreadsheet of the subset of fire training facility data, as well as the keywords used in selecting or deselecting a facility for the subset. as well as the keywords used in selecting or deselecting a facility for the subset. These keywords were tested to maximize accuracy in selecting facilities that may use fire-fighting foam in training exercises, however, due to the lack of a required reporting field in the data systems for designating fire training sites, this methodology may not identify all fire training sites or may potentially misidentify them.

Date of Government Version: 03/24/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 05/21/2025
Number of Days to Update: 49

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 06/23/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

PFAS PT 139 AIRPORT: All Certified Part 139 Airports PFAS Information Listing

Since July 1, 2006, all certified part 139 airports are required to have fire-fighting foam onsite that meet military specifications (MIL-F-24385) (14 CFR 139.317). To date, these military specification fire-fighting foams are fluorinated and have been historically used for training and extinguishing. The 2018 FAA Reauthorization Act has a provision stating that no later than October 2021, FAA shall not require the use of fluorinated AFFF. This provision does not prohibit the use of fluorinated AFFF at Part 139 civilian airports; it only prohibits FAA from mandating its use. The Federal Aviation Administration?s document AC 150/5210-6D - Aircraft Fire Extinguishing Agents provides guidance on Aircraft Fire Extinguishing Agents, which includes Aqueous Film Forming Foam (AFFF).

Date of Government Version: 03/24/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 05/21/2025
Number of Days to Update: 49

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 06/23/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

AQUEOUS FOAM NRC: Aqueous Foam Related Incidents Listing

The National Response Center (NRC) serves as an emergency call center that fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. The spreadsheets posted to the NRC website contain initial incident data that has not been validated or investigated by a federal/state response agency. Response center calls from 1990 to the most recent complete calendar year where there was indication of Aqueous Film Forming Foam (AFFF) usage are included in this dataset. NRC calls may reference AFFF usage in the ?Material Involved? or ?Incident Description? fields.

Date of Government Version: 03/24/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 04/29/2025
Number of Days to Update: 27

Source: Environmental Protection Agency
Telephone: 202-267-2675
Last EDR Contact: 06/26/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

PCS ENF: Enforcement data

No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 06/23/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

PCS: Permit Compliance System

PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 12/16/2016
Date Data Arrived at EDR: 01/06/2017
Date Made Active in Reports: 03/10/2017
Number of Days to Update: 63

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 06/23/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: No Update Planned

BIOSOLIDS: ICIS-NPDES Biosolids Facility Data

The data reflects compliance information about facilities in the biosolids program.

Date of Government Version: 04/13/2025
Date Data Arrived at EDR: 04/15/2025
Date Made Active in Reports: 07/08/2025
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-564-4700
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

UST FINDER RELEASE: UST Finder Releases Database

US EPA's UST Finder data is a national composite of leaking underground storage tanks. This data contains information about, and locations of, leaking underground storage tanks. Data was collected from state sources and standardized into a national profile by EPA's Office of Underground Storage Tanks, Office of Research and Development, and the Association of State and Territorial Solid Waste Management Officials.

Date of Government Version: 06/08/2023
Date Data Arrived at EDR: 10/31/2023
Date Made Active in Reports: 01/18/2024
Number of Days to Update: 79

Source: Environmental Protecton Agency
Telephone: 202-564-0394
Last EDR Contact: 05/08/2025
Next Scheduled EDR Contact: 08/18/2025
Data Release Frequency: Semi-Annually

UST FINDER: UST Finder Database

EPA developed UST Finder, a web map application containing a comprehensive, state-sourced national map of underground storage tank (UST) and leaking UST (LUST) data. It provides the attributes and locations of active and closed USTs, UST facilities, and LUST sites from states and from Tribal lands and US territories . UST Finder contains information about proximity of UST facilities and LUST sites to: surface and groundwater public drinking water protection areas; estimated number of private domestic wells and number of people living nearby; and flooding and wildfires.

Date of Government Version: 06/08/2023
Date Data Arrived at EDR: 10/04/2023
Date Made Active in Reports: 01/18/2024
Number of Days to Update: 106

Source: Environmental Protection Agency
Telephone: 202-564-0394
Last EDR Contact: 05/08/2025
Next Scheduled EDR Contact: 08/18/2025
Data Release Frequency: Varies

E MANIFEST: Hazardous Waste Electronic Manifest System

EPA established a national system for tracking hazardous waste shipments electronically. This system, known as ?e-Manifest,? will modernize the nation?s cradle-to-grave hazardous waste tracking process while saving valuable time, resources, and dollars for industry and states.

Date of Government Version: 02/17/2025
Date Data Arrived at EDR: 02/19/2025
Date Made Active in Reports: 03/14/2025
Number of Days to Update: 23

Source: Environmental Protection Agency
Telephone: 833-501-6826
Last EDR Contact: 06/04/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Varies

PFAS: PFAS Contamination Site Listing

The list includes potential sources of PFAS. This may include different manufacturing facilities, landfills, wastewater treatment plants, electroplating facilities, etc. Sites on this were identified by their NASIC codes as industries that may use or produce PFAS. This list also includes sites known to the Land Restoration.

Date of Government Version: 03/03/2025
Date Data Arrived at EDR: 03/04/2025
Date Made Active in Reports: 04/02/2025
Number of Days to Update: 29

Source: Department of the Environment
Telephone: 410-537-3529
Last EDR Contact: 05/28/2025
Next Scheduled EDR Contact: 09/15/2025
Data Release Frequency: Varies

AIRS: Permit and Facility Information Listing
A listing of permitted facilities and emissions information.

Date of Government Version: 03/26/2025
Date Data Arrived at EDR: 03/27/2025
Date Made Active in Reports: 04/04/2025
Number of Days to Update: 8

Source: Department of the Environment
Telephone: 410-537-3220
Last EDR Contact: 06/11/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Annually

ASBESTOS: Asbestos Notification Listing
Asbestos sites

Date of Government Version: 08/31/2023
Date Data Arrived at EDR: 10/06/2023
Date Made Active in Reports: 12/29/2023
Number of Days to Update: 84

Source: Department of the Environment
Telephone: 410-537-3809
Last EDR Contact: 06/10/2025
Next Scheduled EDR Contact: 09/22/2025
Data Release Frequency: Varies

COAL ASH: Coal Ash Disposal Site Listing
Coal combustion byproduct site locations.

Date of Government Version: 08/13/2010
Date Data Arrived at EDR: 01/05/2011
Date Made Active in Reports: 01/31/2011
Number of Days to Update: 26

Source: Department of the Environment
Telephone: 410-537-3507
Last EDR Contact: 06/12/2025
Next Scheduled EDR Contact: 09/22/2025
Data Release Frequency: Varies

DRYCLEANERS: Registered Drycleaning Facilities
A listing of registered drycleaning facilities.

Date of Government Version: 01/02/2025
Date Data Arrived at EDR: 01/02/2025
Date Made Active in Reports: 03/19/2025
Number of Days to Update: 76

Source: Department of the Environmental
Telephone: 410-537-3220
Last EDR Contact: 06/03/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

FIN ASSURANCE 1: Financial Assurance Information Listing
Financial Assurance information.

Date of Government Version: 11/02/2023
Date Data Arrived at EDR: 11/20/2023
Date Made Active in Reports: 02/15/2024
Number of Days to Update: 87

Source: Department of the Environment
Telephone: 410-537-3345
Last EDR Contact: 07/15/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Varies

FIN ASSURANCE 2: Financial Assurance Information Listing
A listing of financial assurance information for storage tank sites.

Date of Government Version: 04/01/2025
Date Data Arrived at EDR: 04/16/2025
Date Made Active in Reports: 07/11/2025
Number of Days to Update: 86

Source: Department of the Environment
Telephone: 410-537-3461
Last EDR Contact: 06/24/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Semi-Annually

LEAD: Lead Inspection Database
The Childhood Lead Poisoning Prevention Program data of lead inspection for the state.

Date of Government Version: 03/25/2025
Date Data Arrived at EDR: 03/26/2025
Date Made Active in Reports: 04/09/2025
Number of Days to Update: 14

Source: Department of Environment, Lead Poisoning Prevention Program
Telephone: 410-537-3000
Last EDR Contact: 06/11/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Annually

LRP: Land Restoration Program
A listing of Land Restoration Program sites. Site types included in the database are: Voluntary Cleanup Program, National Priority List, Brownfields, Site Assessment, Formerly Used Defense Site, State Master List, Non Master List, Groundwater Investigation and Federal Facility.

Date of Government Version: 12/11/2024
Date Data Arrived at EDR: 02/25/2025
Date Made Active in Reports: 05/12/2025
Number of Days to Update: 76

Source: Department of the Environment
Telephone: 410-537-3000
Last EDR Contact: 05/29/2025
Next Scheduled EDR Contact: 09/05/2025
Data Release Frequency: Quarterly

MD MANIFEST: Hazardous Waste Manifest Information Listing
Hazardous waste manifest information for the state of Maryland. Maryland regulations require the generator to submit a copy of the manifest to the Maryland Department of the Environment.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 02/11/2020
Date Made Active in Reports: 04/21/2020
Number of Days to Update: 70

Source: Department of the Environment
Telephone: 410-537-3314
Last EDR Contact: 04/30/2025
Next Scheduled EDR Contact: 08/18/2025
Data Release Frequency: Annually

NPDES: Wastewater Permit Listing
A listing of wastewater permit locations.

Date of Government Version: 02/10/2025
Date Data Arrived at EDR: 02/11/2025
Date Made Active in Reports: 04/30/2025
Number of Days to Update: 78

Source: Department of the Environment
Telephone: 410-537-3507
Last EDR Contact: 05/13/2025
Next Scheduled EDR Contact: 08/25/2025
Data Release Frequency: Semi-Annually

UIC: Underground Injection Wells Database
A listing of underground injection well locations. The UIC Program is responsible for regulating the construction, operation, permitting, and closure of injection wells that place fluids underground for storage or disposal.

Date of Government Version: 07/25/2024
Date Data Arrived at EDR: 07/30/2024
Date Made Active in Reports: 10/17/2024
Number of Days to Update: 79

Source: Department of the Environment
Telephone: 410-537-3507
Last EDR Contact: 06/05/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants
The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of the Environment in Maryland.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/03/2014
Number of Days to Update: 186

Source: Department of the Environment
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of the Environment in Maryland.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/16/2014
Number of Days to Update: 199

Source: Department of the Environment
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LUST: Recovered Government Archive Leaking Underground Storage Tank

The EDR Recovered Government Archive Leaking Underground Storage Tank database provides a list of LUST incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of the Environment in Maryland from 1995-1999..

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/03/2014
Number of Days to Update: 186

Source: Department of the Environment
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 05/04/2025
Date Data Arrived at EDR: 05/06/2025
Date Made Active in Reports: 07/21/2025
Number of Days to Update: 76

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 05/06/2025
Next Scheduled EDR Contact: 08/18/2025
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 06/23/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Annually

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 11/30/2023
Date Made Active in Reports: 12/01/2023
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 07/17/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Quarterly

PA MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 07/01/2025
Next Scheduled EDR Contact: 10/20/2025
Data Release Frequency: Annually

RI MANIFEST: Manifest information

Hazardous waste manifest information

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/18/2022
Number of Days to Update: 80

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 05/07/2025
Next Scheduled EDR Contact: 08/25/2025
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 05/28/2025
Next Scheduled EDR Contact: 09/15/2025
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association’s annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics’ primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics’ primary database on private school locations in the United States.

Daycare Centers: Child Care Providers
Source: Department of Human Resources
Telephone: 410-767-7805

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.

Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

Current USGS 7.5 Minute Topographic Map

Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

SECURITY SQUARE MALL
6901 SECURITY BOULEVARD
WINDSOR MILL, MD 21244

TARGET PROPERTY COORDINATES

Latitude (North):	39.310654 - 39° 18' 38.35''
Longitude (West):	76.750229 - 76° 45' 0.82''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	349101.0
UTM Y (Meters):	4352503.0
Elevation:	459 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	14434506 BALTIMORE WEST, MD
Version Date:	2019
West Map:	14403185 ELLICOTT CITY, MD
Version Date:	2019

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General East

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES





0 1/2 1 Miles

Target Property Elevation: 459 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
24027C0095D	FEMA FIRM Flood data

Additional Panels in search area:	FEMA Source Type
24027C0085D	FEMA FIRM Flood data
2400100378F	FEMA FIRM Flood data
2400100386F	FEMA FIRM Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
ELLICOTT CITY	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Paleozoic
System:	Mississippian
Series:	Paleozoic mafic intrusives
Code:	Pzmi *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Plutonic and Intrusive Rocks

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name:	CHROME
Soil Surface Texture:	silt loam
Hydrologic Group:	Class C - Slow infiltration rates. Soils with layers impeding downward movement of water, or soils with moderately fine or fine textures.
Soil Drainage Class:	Well drained. Soils have intermediate water holding capacity. Depth to water table is more than 6 feet.

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel:	HIGH
Depth to Bedrock Min:	> 20 inches
Depth to Bedrock Max:	> 40 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	7 inches	silt loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), silt.	Max: 2.00 Min: 0.60	Max: 7.30 Min: 6.10
2	7 inches	15 inches	clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), silt.	Max: 2.00 Min: 0.60	Max: 7.30 Min: 6.10
3	15 inches	30 inches	loam	Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	COARSE-GRAINED SOILS, Gravels, Gravels with fines, Silty Gravel	Max: 2.00 Min: 0.60	Max: 7.30 Min: 6.10
4	30 inches	34 inches	weathered bedrock	Not reported	Not reported	Max: 2.00 Min: 0.06	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: gravelly - silty clay loam
clay loam
very stony - silt loam
silty clay loam

Surficial Soil Types: gravelly - silty clay loam
clay loam
very stony - silt loam
silty clay loam

Shallow Soil Types: silty clay loam

Deeper Soil Types: gravelly - silt loam
silt loam
loam
stratified

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	MD7000000078632	0 - 1/8 Mile East
A2	MD7000000503377	1/8 - 1/4 Mile NNE
A3	MD7000000503376	1/8 - 1/4 Mile NNE
A4	MD7000000503379	1/8 - 1/4 Mile NNE
A5	MD7000000503378	1/8 - 1/4 Mile NNE
6	MD7000000479235	1/4 - 1/2 Mile East
7	MD7000000386536	1/4 - 1/2 Mile SE
B8	MD7000000461630	1/4 - 1/2 Mile SW
B9	MD7000000461631	1/4 - 1/2 Mile SW
B10	MD7000000461632	1/4 - 1/2 Mile SW
C11	MD7000000067081	1/4 - 1/2 Mile NNW
C12	MD7000000068184	1/4 - 1/2 Mile NNW
D13	MD7000000074108	1/4 - 1/2 Mile East
D14	MD7000000074107	1/4 - 1/2 Mile East
D15	MD7000000074110	1/4 - 1/2 Mile East
D16	MD7000000074109	1/4 - 1/2 Mile East
E17	MD7000000406554	1/4 - 1/2 Mile West
E18	MD7000000436306	1/4 - 1/2 Mile West
F19	MD7000000499245	1/4 - 1/2 Mile ESE
F20	MD7000000499246	1/4 - 1/2 Mile ESE

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
F21	MD7000000499247	1/4 - 1/2 Mile ESE
G22	MD7000000069955	1/2 - 1 Mile WSW
G23	MD7000000428592	1/2 - 1 Mile WSW
G24	MD7000000436196	1/2 - 1 Mile WSW
25	MD7000000341377	1/2 - 1 Mile North
26	MD7000000060652	1/2 - 1 Mile South
27	MD7000000341689	1/2 - 1 Mile SE
28	MD7000000341464	1/2 - 1 Mile East
H29	MD7000000378562	1/2 - 1 Mile ENE
H30	MD7000000461103	1/2 - 1 Mile ENE
H31	MD7000000341463	1/2 - 1 Mile ENE
H32	MD7000000341461	1/2 - 1 Mile ENE
H33	MD7000000341462	1/2 - 1 Mile ENE
H34	MD7000000461107	1/2 - 1 Mile ENE
H35	MD7000000461108	1/2 - 1 Mile ENE
H36	MD7000000461106	1/2 - 1 Mile ENE
H37	MD7000000461104	1/2 - 1 Mile ENE
H38	MD7000000461105	1/2 - 1 Mile ENE
I39	MD7000000080260	1/2 - 1 Mile ESE
I40	MD7000000080259	1/2 - 1 Mile ESE
I41	MD7000000080258	1/2 - 1 Mile ESE
I42	MD7000000386543	1/2 - 1 Mile ESE
I43	MD7000000386537	1/2 - 1 Mile ESE
I44	MD7000000386535	1/2 - 1 Mile ESE
J45	MD7000000436324	1/2 - 1 Mile West
46	MD7000000070254	1/2 - 1 Mile WSW
J47	MD7000000061049	1/2 - 1 Mile West
48	MD7000000079987	1/2 - 1 Mile NE
K49	MD7000000078915	1/2 - 1 Mile ENE
K50	MD7000000078914	1/2 - 1 Mile ENE
K51	MD7000000078913	1/2 - 1 Mile ENE
K52	MD7000000079012	1/2 - 1 Mile ENE
K53	MD7000000078917	1/2 - 1 Mile ENE
K54	MD7000000078916	1/2 - 1 Mile ENE
L55	MD7000000341688	1/2 - 1 Mile ESE
L56	MD7000000341690	1/2 - 1 Mile ESE
L57	MD7000000482237	1/2 - 1 Mile ESE
58	MD7000000406529	1/2 - 1 Mile South
M59	MD7000000340852	1/2 - 1 Mile East
M60	MD7000000340851	1/2 - 1 Mile East
M61	MD7000000436070	1/2 - 1 Mile East
M62	MD7000000340853	1/2 - 1 Mile East
N63	MD7000000079985	1/2 - 1 Mile NE
N64	MD7000000079986	1/2 - 1 Mile NE
65	MD7000000079621	1/2 - 1 Mile ESE
66	MD7000000341686	1/2 - 1 Mile SE
67	MD7000000075875	1/2 - 1 Mile NNE
O68	MD7000000074385	1/2 - 1 Mile NW
O69	MD7000000497372	1/2 - 1 Mile NW
O70	MD7000000497373	1/2 - 1 Mile NW
71	MD7000000061069	1/2 - 1 Mile ENE
72	MD7000000378071	1/2 - 1 Mile North

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
73	MD7000000074725	1/2 - 1 Mile South
74	MD7000000342785	1/2 - 1 Mile NNE
P75	MD7000000395520	1/2 - 1 Mile NE
P76	MD7000000467306	1/2 - 1 Mile NE
P77	MD7000000467307	1/2 - 1 Mile NE

PHYSICAL SETTING SOURCE MAP - 8056060.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- Indeterminate Groundwater Flow at Location
- Groundwater Flow Varies at Location
- Oil, gas or related wells

SITE NAME:	Security Square Mall	CLIENT:	EA Engineering Science & Tech.
ADDRESS:	6901 Security Boulevard Windsor Mill MD 21244	CONTACT:	Mitchell Richards
		INQUIRY #:	8056060.2s
LAT/LONG:	39.310654 / 76.750229	DATE:	July 24, 2025 2:51 pm

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

1
East
0 - 1/8 Mile
Lower

MD WELLS **MD7000000078632**

County Letter:	BA	Permit #:	BA817975
MGS ID:	Not Reported	Driller:	HUBER, MICHAEL W.
Driller #:	MWD0336	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	29	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	18-MAR-88 12.00.00.000000 AM
Completion Date:	29-SEP-87 12.00.00.000000 AM		
Total Depth (ft):	29	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Bentonie Clay
Grout Top (ft):	0	Grout Bottom (ft):	17
Casing Type:	Plastic	Casing Diameter (inches):	2
Casing Depth (ft):	19	Casing Height (ft):	+02
Screen Type:	Plastic	Top of Screen (ft):	19
Bottom of Screen (ft):	29	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	2
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	1
Level During Test (ft):	1	Test Pump Type:	Other
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

A2
NNE
1/8 - 1/4 Mile
Lower

MD WELLS **MD7000000503377**

County Letter:	BA	Permit #:	BA950504
MGS ID:	Not Reported	Driller:	ROBERT TINGLEY
Driller #:	MGD 026	Est GPM Produced:	0
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	30	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	06-JUL-05 12.00.00.000000 AM
Completion Date:	14-JUL-05 12.00.00.000000 AM		
Total Depth (ft):	30	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	6
Casing Type:	Plastic	Casing Diameter (inches):	2
Casing Depth (ft):	10	Casing Height (ft):	Not Reported
Screen Type:	Plastic	Top of Screen (ft):	10
Bottom of Screen (ft):	30	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	2
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported

Level During Test (ft):	Not Reported	Test Pump Type:	Not Reported
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Y	Date Abandoned:	07-AUG-08 12.00.00.000000 AM

A3
NNE **MD WELLS** **MD7000000503376**
1/8 - 1/4 Mile
Lower

County Letter:	BA	Permit #:	BA950503
MGS ID:	Not Reported	Driller:	ROBERT TINGLEY
Driller #:	MGD026	Est GPM Produced:	0
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	30	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	06-JUL-05 12.00.00.000000 AM
Completion Date:	14-JUL-05 12.00.00.000000 AM		
Total Depth (ft):	40	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	11
Casing Type:	Plastic	Casing Diameter (inches):	2
Casing Depth (ft):	15	Casing Height (ft):	+0
Screen Type:	Plastic	Top of Screen (ft):	15
Bottom of Screen (ft):	40	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	2
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported
Level During Test (ft):	Not Reported	Test Pump Type:	Not Reported
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Y	Date Abandoned:	07-AUG-08 12.00.00.000000 AM

A4
NNE **MD WELLS** **MD7000000503379**
1/8 - 1/4 Mile
Lower

County Letter:	BA	Permit #:	BA950506
MGS ID:	Not Reported	Driller:	ROBERT TINGLEY
Driller #:	MGD 026	Est GPM Produced:	0
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	30	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	06-JUL-05 12.00.00.000000 AM
Completion Date:	14-JUL-05 12.00.00.000000 AM		
Total Depth (ft):	35	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	6
Casing Type:	Plastic	Casing Diameter (inches):	2
Casing Depth (ft):	10	Casing Height (ft):	Not Reported
Screen Type:	Plastic	Top of Screen (ft):	10
Bottom of Screen (ft):	35	Screen 2 Type:	Not Reported

Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	2
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported
Level During Test (ft):	Not Reported	Test Pump Type:	Not Reported
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Y	Date Abandoned:	07-AUG-08 12.00.00.000000 AM

A5
NNE
1/8 - 1/4 Mile
Lower

MD WELLS **MD7000000503378**

County Letter:	BA	Permit #:	BA950505
MGS ID:	Not Reported	Driller:	ROBERT TINGLEY
Driller #:	MGD 026	Est GPM Produced:	0
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	30	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	06-JUL-05 12.00.00.000000 AM
Completion Date:	14-JUL-05 12.00.00.000000 AM		
Total Depth (ft):	35	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	6
Casing Type:	Plastic	Casing Diameter (inches):	2
Casing Depth (ft):	10	Casing Height (ft):	Not Reported
Screen Type:	Plastic	Top of Screen (ft):	10
Bottom of Screen (ft):	35	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	2
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported
Level During Test (ft):	Not Reported	Test Pump Type:	Not Reported
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Y	Date Abandoned:	07-AUG-08 12.00.00.000000 AM

6
East
1/4 - 1/2 Mile
Lower

MD WELLS **MD7000000479235**

County Letter:	BA	Permit #:	BA947641
MGS ID:	Not Reported	Driller:	STEPHEN SAUL
Driller #:	MWD 421	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	20	Drill Method:	Not Reported
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	16-SEP-03 12.00.00.000000 AM
Completion Date:	17-SEP-03 12.00.00.000000 AM		
Total Depth (ft):	20	Hydrofracture:	No

Grouted:	Not Reported	Grout Type:	Not Reported
Grout Top (ft):	Not Reported	Grout Bottom (ft):	Not Reported
Casing Type:	Not Reported	Casing Diameter (inches):	Not Reported
Casing Depth (ft):	Not Reported	Casing Height (ft):	Not Reported
Screen Type:	Not Reported	Top of Screen (ft):	Not Reported
Bottom of Screen (ft):	Not Reported	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	Not Reported
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported
Level During Test (ft):	Not Reported	Test Pump Type:	Not Reported
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

7
SE **MD WELLS** **MD7000000386536**
1/4 - 1/2 Mile
Lower

County Letter:	BA	Permit #:	BA940113
MGS ID:	Not Reported	Driller:	STEVE UNDERWOOD
Driller #:	MWD 514	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	35	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	30-MAR-94 12.00.00.000000 AM
Completion Date:	06-OCT-94 12.00.00.000000 AM		
Total Depth (ft):	35	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	Not Reported	Grout Bottom (ft):	9
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	15	Casing Height (ft):	Not Reported
Screen Type:	Plastic	Top of Screen (ft):	15
Bottom of Screen (ft):	35	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	1
Level During Test (ft):	1	Test Pump Type:	Other
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

B8
SW **MD WELLS** **MD7000000461630**
1/4 - 1/2 Mile
Higher

County Letter:	BA	Permit #:	BA945472
MGS ID:	Not Reported	Driller:	MICHAEL W HUBER
Driller #:	MWD 336	Est GPM Produced:	Not Reported

Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	20	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	20-APR-01 12.00.00.000000 AM
Completion Date:	03-MAY-01 12.00.00.000000 AM		
Total Depth (ft):	27	Hydrofracture:	No
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	Not Reported	Grout Bottom (ft):	5
Casing Type:	Plastic	Casing Diameter (inches):	2
Casing Depth (ft):	7	Casing Height (ft):	Not Reported
Screen Type:	Plastic	Top of Screen (ft):	7
Bottom of Screen (ft):	27	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	2
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported
Level During Test (ft):	Not Reported	Test Pump Type:	Not Reported
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

B9
SW
1/4 - 1/2 Mile
Higher

MD WELLS **MD7000000461631**

County Letter:	BA	Permit #:	BA945473
MGS ID:	Not Reported	Driller:	MICHAEL W HUBER
Driller #:	MWD 336	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	20	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	20-APR-01 12.00.00.000000 AM
Completion Date:	03-MAY-01 12.00.00.000000 AM		
Total Depth (ft):	17	Hydrofracture:	No
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	Not Reported	Grout Bottom (ft):	2
Casing Type:	Plastic	Casing Diameter (inches):	2
Casing Depth (ft):	2	Casing Height (ft):	Not Reported
Screen Type:	Plastic	Top of Screen (ft):	2
Bottom of Screen (ft):	17	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	Not Reported
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported
Level During Test (ft):	Not Reported	Test Pump Type:	Not Reported
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

B10
SW
1/4 - 1/2 Mile
Higher

MD WELLS **MD7000000461632**

County Letter:	BA	Permit #:	BA945474
MGS ID:	Not Reported	Driller:	MICHAEL W HUBER
Driller #:	MWD 336	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	20	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	20-APR-01 12.00.00.000000 AM
Completion Date:	03-MAY-01 12.00.00.000000 AM		
Total Depth (ft):	27	Hydrofracture:	No
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	Not Reported	Grout Bottom (ft):	5
Casing Type:	Plastic	Casing Diameter (inches):	2
Casing Depth (ft):	7	Casing Height (ft):	Not Reported
Screen Type:	Plastic	Top of Screen (ft):	7
Bottom of Screen (ft):	27	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	2
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported
Level During Test (ft):	Not Reported	Test Pump Type:	Not Reported
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

C11
NNW
1/4 - 1/2 Mile
Lower

MD WELLS **MD7000000067081**

County Letter:	BA	Permit #:	BA734732
MGS ID:	Not Reported	Driller:	DILLON, HOWARD J
Driller #:	MWD0209	Est GPM Produced:	5
Water Use:	Home or Public use	Approx Depth (ft):	125
Drill Method:	AIR-PER		
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	19-JUL-77 12.00.00.000000 AM
Completion Date:	29-AUG-77 12.00.00.000000 AM		
Total Depth (ft):	150	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	21
Casing Type:	Steel	Casing Diameter (inches):	6
Casing Depth (ft):	21	Casing Height (ft):	+02
Screen Type:	Open	Top of Screen (ft):	21
Bottom of Screen (ft):	150	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	Not Reported
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	6
Pumping Rate (gpm):	10	Level Before Test (ft):	35

Level During Test (ft):	75	Test Pump Type:	Submersible
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

C12
NNW
1/4 - 1/2 Mile
Lower

MD WELLS **MD7000000068184**

County Letter:	BA	Permit #:	BA735834
MGS ID:	Not Reported	Driller:	HARR, G EDGAR & SONS
Driller #:	MWD0120	Est GPM Produced:	15
Water Use:	Industrial, Commercial, State and Federal Gov.(required an appropriation permit)		
Approx Depth (ft):	150	Drill Method:	AIR-PER
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	BA1978G023	Issue Date:	07-JUN-78 12.00.00.000000 AM
Completion Date:	06-JUL-78 12.00.00.000000 AM		
Total Depth (ft):	125	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	21
Casing Type:	Steel	Casing Diameter (inches):	6
Casing Depth (ft):	21	Casing Height (ft):	+01
Screen Type:	Open	Top of Screen (ft):	21
Bottom of Screen (ft):	125	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	Not Reported
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	6
Pumping Rate (gpm):	2	Level Before Test (ft):	32
Level During Test (ft):	85	Test Pump Type:	Submersible
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

D13
East
1/4 - 1/2 Mile
Lower

MD WELLS **MD7000000074108**

County Letter:	BA	Permit #:	BA813460
MGS ID:	Not Reported	Driller:	D'AMIANO, ANTHONY R.
Driller #:	MWD0346	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	25	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	12-FEB-85 12.00.00.000000 AM
Completion Date:	18-FEB-85 12.00.00.000000 AM		
Total Depth (ft):	14	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Bentonie Clay
Grout Top (ft):	0	Grout Bottom (ft):	4
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	4	Casing Height (ft):	+01
Screen Type:	Plastic	Top of Screen (ft):	4
Bottom of Screen (ft):	14	Screen 2 Type:	Not Reported

Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	1
Level During Test (ft):	1	Test Pump Type:	Other
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

D14
East
1/4 - 1/2 Mile
Lower

MD WELLS **MD7000000074107**

County Letter:	BA	Permit #:	BA813459
MGS ID:	Not Reported	Driller:	D'AMIANO, ANTHONY R.
Driller #:	MWD0346	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	25	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	12-FEB-85 12.00.00.000000 AM
Completion Date:	18-FEB-85 12.00.00.000000 AM		
Total Depth (ft):	14	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Bentonie Clay
Grout Top (ft):	0	Grout Bottom (ft):	4
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	4	Casing Height (ft):	+01
Screen Type:	Plastic	Top of Screen (ft):	4
Bottom of Screen (ft):	14	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	1
Level During Test (ft):	1	Test Pump Type:	Other
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

D15
East
1/4 - 1/2 Mile
Lower

MD WELLS **MD7000000074110**

County Letter:	BA	Permit #:	BA813462
MGS ID:	Not Reported	Driller:	D'AMIANO, ANTHONY R.
Driller #:	MWD0346	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	25	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	12-FEB-85 12.00.00.000000 AM
Completion Date:	18-FEB-85 12.00.00.000000 AM		
Total Depth (ft):	14	Hydrofracture:	Not Reported

Grouted:	Yes	Grout Type:	Bentonie Clay
Grout Top (ft):	0	Grout Bottom (ft):	4
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	4	Casing Height (ft):	+01
Screen Type:	Plastic	Top of Screen (ft):	4
Bottom of Screen (ft):	14	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	1
Level During Test (ft):	1	Test Pump Type:	Other
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

D16
East
1/4 - 1/2 Mile
Lower

MD WELLS **MD7000000074109**

County Letter:	BA	Permit #:	BA813461
MGS ID:	Not Reported	Driller:	D'AMIANO, ANTHONY R.
Driller #:	MWD0346	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	25	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	12-FEB-85 12.00.00.000000 AM
Completion Date:	18-FEB-85 12.00.00.000000 AM		
Total Depth (ft):	14	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Bentonie Clay
Grout Top (ft):	0	Grout Bottom (ft):	4
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	4	Casing Height (ft):	+01
Screen Type:	Plastic	Top of Screen (ft):	4
Bottom of Screen (ft):	14	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	1
Level During Test (ft):	1	Test Pump Type:	Other
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

E17
West
1/4 - 1/2 Mile
Higher

MD WELLS **MD7000000406554**

County Letter:	BA	Permit #:	BA941110
MGS ID:	Not Reported	Driller:	DENNIS C MOORE
Driller #:	MGD 58	Est GPM Produced:	Not Reported

Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	40	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	17-JUL-95 12.00.00.000000 AM
Completion Date:	Not Reported	Total Depth (ft):	Not Reported
Hydrofracture:	Not Reported	Grouted:	Not Reported
Grout Type:	Not Reported	Grout Top (ft):	Not Reported
Grout Bottom (ft):	Not Reported	Casing Type:	Not Reported
Casing Diameter (inches):	Not Reported	Casing Depth (ft):	Not Reported
Casing Height (ft):	Not Reported	Screen Type:	Not Reported
Top of Screen (ft):	Not Reported	Bottom of Screen (ft):	Not Reported
Screen 2 Type:	Not Reported	Top Screen 2 (ft):	Not Reported
Bottom Screen 2 (ft):	Not Reported	Screen 3 Type:	Not Reported
Top Screen 3 (ft):	Not Reported	Bottom Screen 3 (ft):	Not Reported
Screen Diameter (inches):	Not Reported	Flowing Well:	Not Reported
Telescoping:	Not Reported	Log Type:	Not Reported
Hours Pumped:	Not Reported	Pumping Rate (gpm):	Not Reported
Level Before Test (ft):	Not Reported	Level During Test (ft):	Not Reported
Test Pump Type:	Not Reported	Pump Installed:	Not Reported
Install pump Type:	Not Reported	Capacity (gpm):	Not Reported
Pump Horse Power:	Not Reported	Pump Column Length (ft):	Not Reported
Closed:	Not Reported	Abandoned:	Not Reported
Date Abandoned:	Not Reported		

E18
West
1/4 - 1/2 Mile
Higher

MD WELLS **MD7000000436306**

County Letter:	BA	Permit #:	BA944538
MGS ID:	Not Reported	Driller:	MICHAEL W HUBER
Driller #:	MWD 336	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	25	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	23-AUG-00 12.00.00.000000 AM
Completion Date:	28-AUG-00 12.00.00.000000 AM		
Total Depth (ft):	25	Hydrofracture:	No
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	Not Reported	Grout Bottom (ft):	3
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	5	Casing Height (ft):	Not Reported
Screen Type:	Plastic	Top of Screen (ft):	5
Bottom of Screen (ft):	25	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported
Level During Test (ft):	Not Reported	Test Pump Type:	Other
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

F19
ESE
1/4 - 1/2 Mile
Lower

MD WELLS **MD7000000499245**

County Letter:	BA	Permit #:	BA950473
MGS ID:	Not Reported	Driller:	MIKE WILLEY
Driller #:	MGD 47	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	30	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	21-JUN-05 12.00.00.000000 AM
Completion Date:	20-JUN-05 12.00.00.000000 AM		
Total Depth (ft):	25	Hydrofracture:	No
Grouted:	Yes	Grout Type:	Bentonie Clay
Grout Top (ft):	Not Reported	Grout Bottom (ft):	8
Casing Type:	Plastic	Casing Diameter (inches):	2
Casing Depth (ft):	10	Casing Height (ft):	Not Reported
Screen Type:	Plastic	Top of Screen (ft):	10
Bottom of Screen (ft):	25	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	2
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported
Level During Test (ft):	Not Reported	Test Pump Type:	Not Reported
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Y	Date Abandoned:	17-AUG-10 12.00.00.000000 AM

F20
ESE
1/4 - 1/2 Mile
Lower

MD WELLS **MD7000000499246**

County Letter:	BA	Permit #:	BA950474
MGS ID:	Not Reported	Driller:	MIKE WILLEY
Driller #:	MGD 47	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	30	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	21-JUN-05 12.00.00.000000 AM
Completion Date:	20-JUN-05 12.00.00.000000 AM		
Total Depth (ft):	25	Hydrofracture:	No
Grouted:	Yes	Grout Type:	Bentonie Clay
Grout Top (ft):	Not Reported	Grout Bottom (ft):	8
Casing Type:	Plastic	Casing Diameter (inches):	2
Casing Depth (ft):	10	Casing Height (ft):	Not Reported
Screen Type:	Plastic	Top of Screen (ft):	10
Bottom of Screen (ft):	25	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	2
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported

Level During Test (ft):	Not Reported	Test Pump Type:	Not Reported
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Y	Date Abandoned:	17-AUG-10 12.00.00.000000 AM

F21
ESE **MD WELLS** **MD7000000499247**
1/4 - 1/2 Mile
Lower

County Letter:	BA	Permit #:	BA950475
MGS ID:	Not Reported	Driller:	MIKE WILLEY
Driller #:	MGD 47	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	30	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	21-JUN-05 12.00.00.000000 AM
Completion Date:	20-JUN-05 12.00.00.000000 AM		
Total Depth (ft):	25	Hydrofracture:	No
Grouted:	Yes	Grout Type:	Bentonie Clay
Grout Top (ft):	Not Reported	Grout Bottom (ft):	8
Casing Type:	Plastic	Casing Diameter (inches):	2
Casing Depth (ft):	10	Casing Height (ft):	Not Reported
Screen Type:	Plastic	Top of Screen (ft):	10
Bottom of Screen (ft):	25	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	2
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported
Level During Test (ft):	Not Reported	Test Pump Type:	Not Reported
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Y	Date Abandoned:	17-AUG-09 12.00.00.000000 AM

G22
WSW **MD WELLS** **MD7000000069955**
1/2 - 1 Mile
Higher

County Letter:	BA	Permit #:	BA737619
MGS ID:	Not Reported	Driller:	DILLON, HOWARD J
Driller #:	MWD0209	Est GPM Produced:	5
Water Use:	Home or Public use	Approx Depth (ft):	150
Drill Method:	AIR-PER	Replacement or Deepened:	Deepened and existing well
WAP ID:	Not Reported	Issue Date:	03-SEP-80 12.00.00.000000 AM
Completion Date:	11-SEP-80 12.00.00.000000 AM		
Total Depth (ft):	175	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	17
Casing Type:	Steel	Casing Diameter (inches):	6
Casing Depth (ft):	20	Casing Height (ft):	+02
Screen Type:	Open	Top of Screen (ft):	20
Bottom of Screen (ft):	175	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported

Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	Not Reported
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	6
Pumping Rate (gpm):	5	Level Before Test (ft):	27
Level During Test (ft):	150	Test Pump Type:	Submersible
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

G23
WSW **MD WELLS** **MD7000000428592**
1/2 - 1 Mile
Higher

County Letter:	BA	Permit #:	BA943361
MGS ID:	Not Reported	Driller:	MICHAEL W HUBER
Driller #:	MGD 46	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	75	Drill Method:	BORED
Replacement or Deepened:	Yes, this well will replace a well that will be abandoned and sealed.		
WAP ID:	Not Reported	Issue Date:	08-MAY-98 12.00.00.000000 AM
Completion Date:	01-JUN-98 12.00.00.000000 AM		
Total Depth (ft):	75	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	Not Reported	Grout Bottom (ft):	20
Casing Type:	Steel	Casing Diameter (inches):	6
Casing Depth (ft):	20	Casing Height (ft):	Not Reported
Screen Type:	Open	Top of Screen (ft):	20
Bottom of Screen (ft):	75	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	Not Reported
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	Not Reported
Level During Test (ft):	Not Reported	Test Pump Type:	Other
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

G24
WSW **MD WELLS** **MD7000000436196**
1/2 - 1 Mile
Higher

County Letter:	BA	Permit #:	BA944667
MGS ID:	Not Reported	Driller:	MICHAEL W HUBER
Driller #:	MWD 336	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	25	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	06-OCT-00 12.00.00.000000 AM
Completion Date:	09-OCT-00 12.00.00.000000 AM		
Total Depth (ft):	25	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement

Grout Top (ft):	Not Reported	Grout Bottom (ft):	3
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	5	Casing Height (ft):	Not Reported
Screen Type:	Plastic	Top of Screen (ft):	5
Bottom of Screen (ft):	25	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported
Level During Test (ft):	Not Reported	Test Pump Type:	Other
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

25
North **MD WELLS** **MD7000000341377**
1/2 - 1 Mile
Lower

County Letter:	BA	Permit #:	BA883639
MGS ID:	Not Reported	Driller:	LEROY BROWN
Driller #:	MWD0489	Est GPM Produced:	5
Water Use:	Home or Public use	Approx Depth (ft):	200
Drill Method:	AIR-PER		
Replacement or Deepened:	Yes, this well will replace a well that will be abandoned and sealed.		
WAP ID:	Not Reported	Issue Date:	03-SEP-91 12.00.00.000000 AM
Completion Date:	18-SEP-91 12.00.00.000000 AM		
Total Depth (ft):	300	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	22
Casing Type:	Steel	Casing Diameter (inches):	6
Casing Depth (ft):	22	Casing Height (ft):	+1
Screen Type:	Open	Top of Screen (ft):	22
Bottom of Screen (ft):	300	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	Not Reported
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	3
Pumping Rate (gpm):	7	Level Before Test (ft):	11
Level During Test (ft):	160	Test Pump Type:	Submersible
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

26
South **MD WELLS** **MD7000000060652**
1/2 - 1 Mile
Lower

County Letter:	BA	Permit #:	BA700073
MGS ID:	Not Reported	Driller:	DILLON, HOWARD J
Driller #:	MWD0209	Est GPM Produced:	5
Water Use:	Home or Public use	Approx Depth (ft):	100

Drill Method:	AIR-PER		
Replacement or Deepened:	This well will replace a well that will be used as a standby.		
WAP ID:	Not Reported	Issue Date:	04-AUG-69 12.00.00.000000 AM
Completion Date:	24-SEP-69 12.00.00.000000 AM		
Total Depth (ft):	100	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Not Reported
Grout Top (ft):	0	Grout Bottom (ft):	18
Casing Type:	Steel	Casing Diameter (inches):	6
Casing Depth (ft):	52	Casing Height (ft):	-02
Screen Type:	Open	Top of Screen (ft):	52
Bottom of Screen (ft):	100	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	Not Reported
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	2
Pumping Rate (gpm):	10	Level Before Test (ft):	35
Level During Test (ft):	Not Reported	Test Pump Type:	Air
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

27
SE
1/2 - 1 Mile
Lower

MD WELLS **MD7000000341689**

County Letter:	BA	Permit #:	BA920035
MGS ID:	Not Reported	Driller:	STANLEY L. COHEN
Driller #:	MWD0354	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	50	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	13-JAN-92 12.00.00.000000 AM
Completion Date:	01-FEB-92 12.00.00.000000 AM		
Total Depth (ft):	21	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	4
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	6	Casing Height (ft):	+0
Screen Type:	Plastic	Top of Screen (ft):	6
Bottom of Screen (ft):	21	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	10
Level During Test (ft):	10	Test Pump Type:	Submersible
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

28
East
1/2 - 1 Mile
Lower

MD WELLS **MD7000000341464**

County Letter:	BA	Permit #:	BA883830
MGS ID:	Not Reported	Driller:	STEVE UNDERWOOD
Driller #:	MWD0514	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	20	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	19-NOV-91 12.00.00.000000 AM
Completion Date:	05-DEC-91 12.00.00.000000 AM		
Total Depth (ft):	20	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	1
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	4	Casing Height (ft):	+1
Screen Type:	Plastic	Top of Screen (ft):	4
Bottom of Screen (ft):	20	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	1
Level During Test (ft):	1	Test Pump Type:	Other
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Successful well later abandoned
Abandoned:	Not Reported	Date Abandoned:	Not Reported

H29
ENE
1/2 - 1 Mile
Lower

MD WELLS **MD7000000378562**

County Letter:	BA	Permit #:	BA930602
MGS ID:	Not Reported	Driller:	STANLEY L COHEN
Driller #:	MGD 31	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	30	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	21-DEC-93 12.00.00.000000 AM
Completion Date:	22-DEC-93 12.00.00.000000 AM		
Total Depth (ft):	28	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	Not Reported	Grout Bottom (ft):	5
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	8	Casing Height (ft):	Not Reported
Screen Type:	Plastic	Top of Screen (ft):	8
Bottom of Screen (ft):	28	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	20

Level During Test (ft):	20	Test Pump Type:	Not Reported
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Y	Date Abandoned:	04-MAR-04 12.00.00.000000 AM

H30
ENE
1/2 - 1 Mile
Lower

MD WELLS **MD7000000461103**

County Letter:	BA	Permit #:	BA946036
MGS ID:	Not Reported	Driller:	STEPHEN SAUL
Driller #:	MGD 39	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	25	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	29-NOV-01 12.00.00.000000 AM
Completion Date:	07-DEC-01 12.00.00.000000 AM		
Total Depth (ft):	20	Hydrofracture:	No
Grouted:	Yes	Grout Type:	Bentonie Clay
Grout Top (ft):	Not Reported	Grout Bottom (ft):	3
Casing Type:	Plastic	Casing Diameter (inches):	2
Casing Depth (ft):	5	Casing Height (ft):	Not Reported
Screen Type:	Plastic	Top of Screen (ft):	5
Bottom of Screen (ft):	20	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	2
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported
Level During Test (ft):	Not Reported	Test Pump Type:	Not Reported
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

H31
ENE
1/2 - 1 Mile
Lower

MD WELLS **MD7000000341463**

County Letter:	BA	Permit #:	BA883828
MGS ID:	Not Reported	Driller:	STEVE UNDERWOOD
Driller #:	MWD0514	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	20	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	19-NOV-91 12.00.00.000000 AM
Completion Date:	05-DEC-91 12.00.00.000000 AM		
Total Depth (ft):	20	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	1
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	5	Casing Height (ft):	0
Screen Type:	Plastic	Top of Screen (ft):	5
Bottom of Screen (ft):	20	Screen 2 Type:	Not Reported

Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	1
Level During Test (ft):	1	Test Pump Type:	Other
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Successful well later abandoned
Abandoned:	Not Reported	Date Abandoned:	Not Reported

H32
ENE
1/2 - 1 Mile
Lower

MD WELLS **MD7000000341461**

County Letter:	BA	Permit #:	BA883826
MGS ID:	Not Reported	Driller:	STEVE UNDERWOOD
Driller #:	MWD0514	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	20	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	19-NOV-91 12.00.00.000000 AM
Completion Date:	06-DEC-91 12.00.00.000000 AM		
Total Depth (ft):	14	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	1
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	4	Casing Height (ft):	+1
Screen Type:	Plastic	Top of Screen (ft):	4
Bottom of Screen (ft):	14	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	1
Level During Test (ft):	1	Test Pump Type:	Other
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

H33
ENE
1/2 - 1 Mile
Lower

MD WELLS **MD7000000341462**

County Letter:	BA	Permit #:	BA883827
MGS ID:	Not Reported	Driller:	STEVE UNDERWOOD
Driller #:	MWD0514	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	20	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	19-NOV-91 12.00.00.000000 AM
Completion Date:	06-DEC-91 12.00.00.000000 AM		
Total Depth (ft):	15	Hydrofracture:	Not Reported

Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	1
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	4	Casing Height (ft):	+1
Screen Type:	Plastic	Top of Screen (ft):	4
Bottom of Screen (ft):	15	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	1
Level During Test (ft):	1	Test Pump Type:	Other
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

H34
ENE **MD WELLS** **MD7000000461107**
1/2 - 1 Mile
Lower

County Letter:	BA	Permit #:	BA946040
MGS ID:	Not Reported	Driller:	STEPHEN SAUL
Driller #:	MGD 39	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	20	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	29-NOV-01 12.00.00.000000 AM
Completion Date:	07-DEC-01 12.00.00.000000 AM		
Total Depth (ft):	21	Hydrofracture:	No
Grouted:	Yes	Grout Type:	Bentonie Clay
Grout Top (ft):	Not Reported	Grout Bottom (ft):	3
Casing Type:	Plastic	Casing Diameter (inches):	2
Casing Depth (ft):	5	Casing Height (ft):	Not Reported
Screen Type:	Plastic	Top of Screen (ft):	5
Bottom of Screen (ft):	21	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	2
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported
Level During Test (ft):	Not Reported	Test Pump Type:	Not Reported
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

H35
ENE **MD WELLS** **MD7000000461108**
1/2 - 1 Mile
Lower

County Letter:	BA	Permit #:	BA946041
MGS ID:	Not Reported	Driller:	STEPHEN SAUL
Driller #:	MGD 39	Est GPM Produced:	Not Reported

Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	45	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	29-NOV-01 12.00.00.000000 AM
Completion Date:	07-DEC-01 12.00.00.000000 AM		
Total Depth (ft):	45	Hydrofracture:	No
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	Not Reported	Grout Bottom (ft):	23
Casing Type:	Steel	Casing Diameter (inches):	6
Casing Depth (ft):	20	Casing Height (ft):	Not Reported
Screen Type:	Plastic	Top of Screen (ft):	25
Bottom of Screen (ft):	45	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	2
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported
Level During Test (ft):	Not Reported	Test Pump Type:	Not Reported
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

H36
ENE **MD WELLS** **MD7000000461106**
1/2 - 1 Mile
Lower

County Letter:	BA	Permit #:	BA946039
MGS ID:	Not Reported	Driller:	STEPHEN SAUL
Driller #:	MGD 39	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	50	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	29-NOV-01 12.00.00.000000 AM
Completion Date:	07-DEC-01 12.00.00.000000 AM		
Total Depth (ft):	50	Hydrofracture:	No
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	Not Reported	Grout Bottom (ft):	28
Casing Type:	Steel	Casing Diameter (inches):	6
Casing Depth (ft):	20	Casing Height (ft):	Not Reported
Screen Type:	Plastic	Top of Screen (ft):	30
Bottom of Screen (ft):	50	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	2
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported
Level During Test (ft):	Not Reported	Test Pump Type:	Not Reported
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

H37
ENE
1/2 - 1 Mile
Lower

MD WELLS **MD7000000461104**

County Letter:	BA	Permit #:	BA946037
MGS ID:	Not Reported	Driller:	STEPHEN SAUL
Driller #:	MGD 39	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	25	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	29-NOV-01 12.00.00.000000 AM
Completion Date:	07-DEC-01 12.00.00.000000 AM		
Total Depth (ft):	25	Hydrofracture:	No
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	Not Reported	Grout Bottom (ft):	3
Casing Type:	Plastic	Casing Diameter (inches):	2
Casing Depth (ft):	5	Casing Height (ft):	Not Reported
Screen Type:	Plastic	Top of Screen (ft):	5
Bottom of Screen (ft):	25	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	2
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported
Level During Test (ft):	Not Reported	Test Pump Type:	Not Reported
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

H38
ENE
1/2 - 1 Mile
Lower

MD WELLS **MD7000000461105**

County Letter:	BA	Permit #:	BA946038
MGS ID:	Not Reported	Driller:	STEPHEN SAUL
Driller #:	MGD 39	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	50	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	29-NOV-01 12.00.00.000000 AM
Completion Date:	07-DEC-01 12.00.00.000000 AM		
Total Depth (ft):	50	Hydrofracture:	No
Grouted:	Yes	Grout Type:	Bentonie Clay
Grout Top (ft):	Not Reported	Grout Bottom (ft):	28
Casing Type:	Plastic	Casing Diameter (inches):	2
Casing Depth (ft):	30	Casing Height (ft):	Not Reported
Screen Type:	Plastic	Top of Screen (ft):	30
Bottom of Screen (ft):	50	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	2
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported

Level During Test (ft):	Not Reported	Test Pump Type:	Not Reported
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

I39
ESE **MD WELLS** **MD7000000080260**
1/2 - 1 Mile
Lower

County Letter:	BA	Permit #:	BA880863
MGS ID:	Not Reported	Driller:	COHEN, STANLEY J.
Driller #:	MWD0354	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	30	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	23-MAR-89 12.00.00.000000 AM
Completion Date:	04-APR-89 12.00.00.000000 AM		
Total Depth (ft):	37	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	10
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	12	Casing Height (ft):	+01
Screen Type:	Plastic	Top of Screen (ft):	12
Bottom of Screen (ft):	37	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	25
Level During Test (ft):	25	Test Pump Type:	Other
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

I40
ESE **MD WELLS** **MD7000000080259**
1/2 - 1 Mile
Lower

County Letter:	BA	Permit #:	BA880862
MGS ID:	Not Reported	Driller:	COHEN, STANLEY J.
Driller #:	MWD0354	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	30	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	23-MAR-89 12.00.00.000000 AM
Completion Date:	04-APR-89 12.00.00.000000 AM		
Total Depth (ft):	33	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	6
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	8	Casing Height (ft):	+01
Screen Type:	Plastic	Top of Screen (ft):	8
Bottom of Screen (ft):	33	Screen 2 Type:	Not Reported

Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	26
Level During Test (ft):	26	Test Pump Type:	Other
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

I41
ESE
1/2 - 1 Mile
Lower

MD WELLS **MD7000000080258**

County Letter:	BA	Permit #:	BA880861
MGS ID:	Not Reported	Driller:	COHEN, STANLEY J.
Driller #:	MWD0354	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	30	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	23-MAR-89 12.00.00.000000 AM
Completion Date:	04-APR-89 12.00.00.000000 AM		
Total Depth (ft):	38	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	8
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	12	Casing Height (ft):	+01
Screen Type:	Plastic	Top of Screen (ft):	12
Bottom of Screen (ft):	38	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	24
Level During Test (ft):	24	Test Pump Type:	Other
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

I42
ESE
1/2 - 1 Mile
Lower

MD WELLS **MD7000000386543**

County Letter:	BA	Permit #:	BA940110
MGS ID:	Not Reported	Driller:	STANLEY L COHEN
Driller #:	MGD 31	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	30	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	31-MAR-94 12.00.00.000000 AM
Completion Date:	04-APR-94 12.00.00.000000 AM		
Total Depth (ft):	22	Hydrofracture:	Not Reported

Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	Not Reported	Grout Bottom (ft):	3
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	5	Casing Height (ft):	Not Reported
Screen Type:	Plastic	Top of Screen (ft):	5
Bottom of Screen (ft):	22	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported
Level During Test (ft):	Not Reported	Test Pump Type:	Not Reported
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

I43
ESE **MD WELLS** **MD7000000386537**
1/2 - 1 Mile
Lower

County Letter:	BA	Permit #:	BA940114
MGS ID:	Not Reported	Driller:	STEVE UNDERWOOD
Driller #:	MWD 514	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	35	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	30-MAR-94 12.00.00.000000 AM
Completion Date:	06-OCT-94 12.00.00.000000 AM		
Total Depth (ft):	35	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	Not Reported	Grout Bottom (ft):	10
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	15	Casing Height (ft):	Not Reported
Screen Type:	Plastic	Top of Screen (ft):	15
Bottom of Screen (ft):	35	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	1
Level During Test (ft):	1	Test Pump Type:	Other
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

I44
ESE **MD WELLS** **MD7000000386535**
1/2 - 1 Mile
Lower

County Letter:	BA	Permit #:	BA940111
MGS ID:	Not Reported	Driller:	STANLEY L COHEN
Driller #:	MGD 31	Est GPM Produced:	Not Reported

Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	30	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	31-MAR-94 12.00.00.000000 AM
Completion Date:	05-APR-94 12.00.00.000000 AM		
Total Depth (ft):	23	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	Not Reported	Grout Bottom (ft):	2
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	3	Casing Height (ft):	Not Reported
Screen Type:	Plastic	Top of Screen (ft):	3
Bottom of Screen (ft):	23	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported
Level During Test (ft):	Not Reported	Test Pump Type:	Not Reported
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

J45
West
1/2 - 1 Mile
Higher

MD WELLS **MD7000000436324**

County Letter:	BA	Permit #:	BA944537
MGS ID:	Not Reported	Driller:	MICHAEL W HUBER
Driller #:	MWD 336	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	25	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	23-AUG-00 12.00.00.000000 AM
Completion Date:	28-AUG-00 12.00.00.000000 AM		
Total Depth (ft):	25	Hydrofracture:	No
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	Not Reported	Grout Bottom (ft):	3
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	5	Casing Height (ft):	Not Reported
Screen Type:	Plastic	Top of Screen (ft):	5
Bottom of Screen (ft):	25	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported
Level During Test (ft):	Not Reported	Test Pump Type:	Other
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

46
WSW
1/2 - 1 Mile
Higher

MD WELLS **MD7000000070254**

County Letter:	BA	Permit #:	BA737945
MGS ID:	Not Reported	Driller:	EASTERDAY, GEORGE F.
Driller #:	MWD0040	Est GPM Produced:	5
Water Use:	Home or Public use	Approx Depth (ft):	150
Drill Method:	AIR-ROT		
Replacement or Deepened:	This well will replace a well that will be used as a standby.		
WAP ID:	Not Reported	Issue Date:	03-FEB-81 12.00.00.000000 AM
Completion Date:	13-MAR-81 12.00.00.000000 AM		
Total Depth (ft):	160	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	19
Casing Type:	Steel	Casing Diameter (inches):	6
Casing Depth (ft):	21	Casing Height (ft):	+02
Screen Type:	Open	Top of Screen (ft):	19
Bottom of Screen (ft):	160	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	Not Reported
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	5
Pumping Rate (gpm):	5	Level Before Test (ft):	20
Level During Test (ft):	160	Test Pump Type:	Air
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

J47
West
1/2 - 1 Mile
Higher

MD WELLS **MD7000000061049**

County Letter:	BA	Permit #:	BA700470
MGS ID:	Not Reported	Driller:	HARR, G EDGAR & SONS
Driller #:	MWD0122	Est GPM Produced:	5
Water Use:	Home or Public use	Approx Depth (ft):	150
Drill Method:	AIR-PER		
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	18-MAY-70 12.00.00.000000 AM
Completion Date:	29-MAY-70 12.00.00.000000 AM		
Total Depth (ft):	250	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Not Reported
Grout Top (ft):	0	Grout Bottom (ft):	21
Casing Type:	Steel	Casing Diameter (inches):	6
Casing Depth (ft):	21	Casing Height (ft):	+01
Screen Type:	Open	Top of Screen (ft):	21
Bottom of Screen (ft):	250	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	Not Reported
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	4
Pumping Rate (gpm):	10	Level Before Test (ft):	21

Level During Test (ft):	240	Test Pump Type:	Air
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

48
NE **MD WELLS** **MD7000000079987**
1/2 - 1 Mile
Lower

County Letter:	BA	Permit #:	BA880529
MGS ID:	Not Reported	Driller:	D'AMIANO, ANTHONY R.
Driller #:	MWD0346	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	20	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	22-DEC-88 12.00.00.000000 AM
Completion Date:	27-DEC-88 12.00.00.000000 AM		
Total Depth (ft):	19	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Bentonie Clay
Grout Top (ft):	0	Grout Bottom (ft):	6
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	6	Casing Height (ft):	+01
Screen Type:	Plastic	Top of Screen (ft):	6
Bottom of Screen (ft):	9	Screen 2 Type:	PL
Top Screen 2 (ft):	10	Bottom Screen 2 (ft):	19
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	1
Level During Test (ft):	1	Test Pump Type:	Other
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

K49
ENE **MD WELLS** **MD7000000078915**
1/2 - 1 Mile
Lower

County Letter:	BA	Permit #:	BA818257
MGS ID:	Not Reported	Driller:	D'AMIANO, ANTHONY R.
Driller #:	MWD0346	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	30	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	05-MAY-88 12.00.00.000000 AM
Completion Date:	25-MAY-88 12.00.00.000000 AM		
Total Depth (ft):	15	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Bentonie Clay
Grout Top (ft):	0	Grout Bottom (ft):	2
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	2	Casing Height (ft):	+01
Screen Type:	Plastic	Top of Screen (ft):	2
Bottom of Screen (ft):	6	Screen 2 Type:	PL

Top Screen 2 (ft):	7	Bottom Screen 2 (ft):	15
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	1
Level During Test (ft):	1	Test Pump Type:	Other
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

K50
ENE **MD WELLS** **MD7000000078914**
1/2 - 1 Mile
Lower

County Letter:	BA	Permit #:	BA818256
MGS ID:	Not Reported	Driller:	D'AMIANO, ANTHONY R.
Driller #:	MWD0346	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	30	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	05-MAY-88 12.00.00.000000 AM
Completion Date:	25-MAY-88 12.00.00.000000 AM		
Total Depth (ft):	17	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Bentonie Clay
Grout Top (ft):	0	Grout Bottom (ft):	2
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	2	Casing Height (ft):	+01
Screen Type:	Plastic	Top of Screen (ft):	2
Bottom of Screen (ft):	11	Screen 2 Type:	PL
Top Screen 2 (ft):	13	Bottom Screen 2 (ft):	17
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	1
Level During Test (ft):	1	Test Pump Type:	Other
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

K51
ENE **MD WELLS** **MD7000000078913**
1/2 - 1 Mile
Lower

County Letter:	BA	Permit #:	BA818255
MGS ID:	Not Reported	Driller:	D'AMIANO, ANTHONY R.
Driller #:	MWD0346	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	30	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	05-MAY-88 12.00.00.000000 AM
Completion Date:	25-MAY-88 12.00.00.000000 AM		
Total Depth (ft):	19	Hydrofracture:	Not Reported

Grouted:	Yes	Grout Type:	Bentonie Clay
Grout Top (ft):	0	Grout Bottom (ft):	4
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	4	Casing Height (ft):	+01
Screen Type:	Plastic	Top of Screen (ft):	4
Bottom of Screen (ft):	8	Screen 2 Type:	PL
Top Screen 2 (ft):	9	Bottom Screen 2 (ft):	19
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	1
Level During Test (ft):	1	Test Pump Type:	Other
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

K52
ENE **MD WELLS** **MD7000000079012**
1/2 - 1 Mile
Lower

County Letter:	BA	Permit #:	BA818356
MGS ID:	Not Reported	Driller:	D'AMIANO, ANTHONY R.
Driller #:	MWD0346	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	20	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	07-JUN-88 12.00.00.000000 AM
Completion Date:	25-MAY-88 12.00.00.000000 AM		
Total Depth (ft):	14	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Bentonie Clay
Grout Top (ft):	0	Grout Bottom (ft):	2
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	2	Casing Height (ft):	+01
Screen Type:	Plastic	Top of Screen (ft):	2
Bottom of Screen (ft):	11	Screen 2 Type:	PL
Top Screen 2 (ft):	12	Bottom Screen 2 (ft):	14
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	1
Level During Test (ft):	1	Test Pump Type:	Other
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

K53
ENE **MD WELLS** **MD7000000078917**
1/2 - 1 Mile
Lower

County Letter:	BA	Permit #:	BA818259
MGS ID:	Not Reported	Driller:	D'AMIANO, ANTHONY R.
Driller #:	MWD0346	Est GPM Produced:	Not Reported

Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	30	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	05-MAY-88 12.00.00.000000 AM
Completion Date:	25-MAY-88 12.00.00.000000 AM		
Total Depth (ft):	15	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Bentonie Clay
Grout Top (ft):	0	Grout Bottom (ft):	2
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	2	Casing Height (ft):	+01
Screen Type:	Plastic	Top of Screen (ft):	2
Bottom of Screen (ft):	12	Screen 2 Type:	PL
Top Screen 2 (ft):	13	Bottom Screen 2 (ft):	15
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	1
Level During Test (ft):	1	Test Pump Type:	Other
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

K54
ENE **MD WELLS** **MD7000000078916**
1/2 - 1 Mile
Lower

County Letter:	BA	Permit #:	BA818258
MGS ID:	Not Reported	Driller:	D'AMIANO, ANTHONY R.
Driller #:	MWD0346	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	30	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	05-MAY-88 12.00.00.000000 AM
Completion Date:	25-MAY-88 12.00.00.000000 AM		
Total Depth (ft):	14	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Bentonie Clay
Grout Top (ft):	0	Grout Bottom (ft):	3
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	3	Casing Height (ft):	+01
Screen Type:	Plastic	Top of Screen (ft):	3
Bottom of Screen (ft):	4	Screen 2 Type:	PL
Top Screen 2 (ft):	5	Bottom Screen 2 (ft):	14
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	1
Level During Test (ft):	1	Test Pump Type:	Other
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

L55
ESE
1/2 - 1 Mile
Lower

MD WELLS **MD7000000341688**

County Letter:	BA	Permit #:	BA920034
MGS ID:	Not Reported	Driller:	STANLEY L. COHEN
Driller #:	MWD0354	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	50	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	13-JAN-92 12.00.00.000000 AM
Completion Date:	02-FEB-92 12.00.00.000000 AM		
Total Depth (ft):	21	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	4
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	6	Casing Height (ft):	+0
Screen Type:	Plastic	Top of Screen (ft):	6
Bottom of Screen (ft):	21	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	12
Level During Test (ft):	11	Test Pump Type:	Submersible
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

L56
ESE
1/2 - 1 Mile
Lower

MD WELLS **MD7000000341690**

County Letter:	BA	Permit #:	BA920036
MGS ID:	Not Reported	Driller:	STANLEY L. COHEN
Driller #:	MWD0354	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	50	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	13-JAN-92 12.00.00.000000 AM
Completion Date:	26-JAN-92 12.00.00.000000 AM		
Total Depth (ft):	26	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	4
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	6	Casing Height (ft):	+0
Screen Type:	Plastic	Top of Screen (ft):	6
Bottom of Screen (ft):	26	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	10

Level During Test (ft):	12	Test Pump Type:	Submersible
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

L57
ESE **MD WELLS** **MD7000000482237**
1/2 - 1 Mile
Lower

County Letter:	BA	Permit #:	BA947847
MGS ID:	Not Reported	Driller:	ALLEN COMPTON
Driller #:	MSD 9	Est GPM Produced:	5
Water Use:	Home or Public use	Approx Depth (ft):	300
Drill Method:	AIR-PER		
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	28-JAN-04 12.00.00.000000 AM
Completion Date:	09-MAR-04 12.00.00.000000 AM		
Total Depth (ft):	300	Hydrofracture:	No
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	Not Reported	Grout Bottom (ft):	51
Casing Type:	Steel	Casing Diameter (inches):	6
Casing Depth (ft):	57	Casing Height (ft):	+1
Screen Type:	Open	Top of Screen (ft):	57
Bottom of Screen (ft):	300	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	Not Reported
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	3
Pumping Rate (gpm):	20	Level Before Test (ft):	9
Level During Test (ft):	12	Test Pump Type:	Submersible
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

58
South **MD WELLS** **MD7000000406529**
1/2 - 1 Mile
Lower

County Letter:	BA	Permit #:	BA941545
MGS ID:	Not Reported	Driller:	BRENARD J TAYLOR
Driller #:	MWD 430	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	20	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	26-MAR-96 12.00.00.000000 AM
Completion Date:	Not Reported	Total Depth (ft):	Not Reported
Hydrofracture:	Not Reported	Grouted:	Not Reported
Grout Type:	Not Reported	Grout Top (ft):	Not Reported
Grout Bottom (ft):	Not Reported	Casing Type:	Not Reported
Casing Diameter (inches):	Not Reported	Casing Depth (ft):	Not Reported
Casing Height (ft):	Not Reported	Screen Type:	Not Reported
Top of Screen (ft):	Not Reported	Bottom of Screen (ft):	Not Reported
Screen 2 Type:	Not Reported	Top Screen 2 (ft):	Not Reported

Bottom Screen 2 (ft):	Not Reported	Screen 3 Type:	Not Reported
Top Screen 3 (ft):	Not Reported	Bottom Screen 3 (ft):	Not Reported
Screen Diameter (inches):	Not Reported	Flowing Well:	Not Reported
Telescoping:	Not Reported	Log Type:	Not Reported
Hours Pumped:	Not Reported	Pumping Rate (gpm):	Not Reported
Level Before Test (ft):	Not Reported	Level During Test (ft):	Not Reported
Test Pump Type:	Not Reported	Pump Installed:	Not Reported
Install pump Type:	Not Reported	Capacity (gpm):	Not Reported
Pump Horse Power:	Not Reported	Pump Column Length (ft):	Not Reported
Closed:	Not Reported	Abandoned:	Not Reported
Date Abandoned:	Not Reported		

M59
East
1/2 - 1 Mile
Lower

MD WELLS **MD7000000340852**

County Letter:	BA	Permit #:	BA882864
MGS ID:	Not Reported	Driller:	IAN A VOLEM
Driller #:	MWD0492	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	12	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	11-OCT-90 12.00.00.000000 AM
Completion Date:	20-OCT-90 12.00.00.000000 AM		
Total Depth (ft):	12	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	1
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	1	Casing Height (ft):	+0
Screen Type:	Plastic	Top of Screen (ft):	1
Bottom of Screen (ft):	12	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported
Level During Test (ft):	Not Reported	Test Pump Type:	Other
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

M60
East
1/2 - 1 Mile
Lower

MD WELLS **MD7000000340851**

County Letter:	BA	Permit #:	BA882863
MGS ID:	Not Reported	Driller:	IAN A VOLEM
Driller #:	MWD0492	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	16	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	11-OCT-90 12.00.00.000000 AM
Completion Date:	12-DEC-90 12.00.00.000000 AM		
Total Depth (ft):	18	Hydrofracture:	Not Reported

Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	1
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	1	Casing Height (ft):	+0
Screen Type:	Plastic	Top of Screen (ft):	1
Bottom of Screen (ft):	18	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported
Level During Test (ft):	Not Reported	Test Pump Type:	Other
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

M61
East
1/2 - 1 Mile
Lower

MD WELLS **MD7000000436070**

County Letter:	BA	Permit #:	BA944812
MGS ID:	Not Reported	Driller:	WALTER CONNELLY
Driller #:	MGD 35	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	80	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	17-AUG-99 12.00.00.000000 AM
Completion Date:	18-AUG-99 12.00.00.000000 AM		
Total Depth (ft):	20	Hydrofracture:	No
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	Not Reported	Grout Bottom (ft):	3
Casing Type:	Plastic	Casing Diameter (inches):	2
Casing Depth (ft):	5	Casing Height (ft):	Not Reported
Screen Type:	Plastic	Top of Screen (ft):	5
Bottom of Screen (ft):	20	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	2
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	1
Level During Test (ft):	1	Test Pump Type:	Not Reported
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

M62
East
1/2 - 1 Mile
Lower

MD WELLS **MD7000000340853**

County Letter:	BA	Permit #:	BA882865
MGS ID:	Not Reported	Driller:	IAN A VOLEM
Driller #:	MWD0492	Est GPM Produced:	Not Reported

Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	12	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	11-OCT-90 12.00.00.000000 AM
Completion Date:	12-DEC-90 12.00.00.000000 AM		
Total Depth (ft):	13	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	1
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	1	Casing Height (ft):	+0
Screen Type:	Plastic	Top of Screen (ft):	1
Bottom of Screen (ft):	13	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported
Level During Test (ft):	Not Reported	Test Pump Type:	Other
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

N63
NE
1/2 - 1 Mile
Lower

MD WELLS **MD7000000079985**

County Letter:	BA	Permit #:	BA880527
MGS ID:	Not Reported	Driller:	D'AMIANO, ANTHONY R.
Driller #:	MWD0346	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	20	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	22-DEC-88 12.00.00.000000 AM
Completion Date:	27-DEC-88 12.00.00.000000 AM		
Total Depth (ft):	19	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Bentonie Clay
Grout Top (ft):	0	Grout Bottom (ft):	5
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	5	Casing Height (ft):	+01
Screen Type:	Plastic	Top of Screen (ft):	5
Bottom of Screen (ft):	9	Screen 2 Type:	PL
Top Screen 2 (ft):	11	Bottom Screen 2 (ft):	19
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	1
Level During Test (ft):	1	Test Pump Type:	Other
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

N64
NE
1/2 - 1 Mile
Lower

MD WELLS **MD7000000079986**

County Letter:	BA	Permit #:	BA880528
MGS ID:	Not Reported	Driller:	D'AMIANO, ANTHONY R.
Driller #:	MWD0346	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	20	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	22-DEC-88 12.00.00.000000 AM
Completion Date:	27-DEC-88 12.00.00.000000 AM		
Total Depth (ft):	19	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Bentonie Clay
Grout Top (ft):	0	Grout Bottom (ft):	4
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	4	Casing Height (ft):	+01
Screen Type:	Plastic	Top of Screen (ft):	4
Bottom of Screen (ft):	9	Screen 2 Type:	PL
Top Screen 2 (ft):	10	Bottom Screen 2 (ft):	19
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	1
Level During Test (ft):	1	Test Pump Type:	Other
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

65
ESE
1/2 - 1 Mile
Lower

MD WELLS **MD7000000079621**

County Letter:	BA	Permit #:	BA880160
MGS ID:	Not Reported	Driller:	KYKER, DANNA JR. II
Driller #:	MWD0256	Est GPM Produced:	5
Water Use:	Home or Public use	Approx Depth (ft):	150
Drill Method:	AIR-ROT		
Replacement or Deepened:	Yes, this well will replace a well that will be abandoned and sealed.		
WAP ID:	Not Reported	Issue Date:	14-OCT-88 12.00.00.000000 AM
Completion Date:	16-DEC-88 12.00.00.000000 AM		
Total Depth (ft):	303	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	78
Casing Type:	Steel	Casing Diameter (inches):	6
Casing Depth (ft):	80	Casing Height (ft):	+02
Screen Type:	Open	Top of Screen (ft):	80
Bottom of Screen (ft):	303	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	Not Reported
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	6
Pumping Rate (gpm):	3	Level Before Test (ft):	51

Level During Test (ft):	101	Test Pump Type:	Air
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

66
SE **MD WELLS** **MD7000000341686**
1/2 - 1 Mile
Lower

County Letter:	BA	Permit #:	BA920033
MGS ID:	Not Reported	Driller:	STANLEY L. COHEN
Driller #:	MWD0354	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	50	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	13-JAN-92 12.00.00.000000 AM
Completion Date:	25-JAN-92 12.00.00.000000 AM		
Total Depth (ft):	30	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	13
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	15	Casing Height (ft):	+0
Screen Type:	Plastic	Top of Screen (ft):	15
Bottom of Screen (ft):	30	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	17
Level During Test (ft):	16	Test Pump Type:	Submersible
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

67
NNE **MD WELLS** **MD7000000075875**
1/2 - 1 Mile
Lower

County Letter:	BA	Permit #:	BA815204
MGS ID:	Not Reported	Driller:	D'AMIANO, ANTHONY R.
Driller #:	MWD0346	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	15	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	11-JUN-86 12.00.00.000000 AM
Completion Date:	12-JUN-86 12.00.00.000000 AM		
Total Depth (ft):	13	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Bentonie Clay
Grout Top (ft):	2	Grout Bottom (ft):	13
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	5	Casing Height (ft):	+02
Screen Type:	Plastic	Top of Screen (ft):	3
Bottom of Screen (ft):	13	Screen 2 Type:	Not Reported

Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	1
Level During Test (ft):	1	Test Pump Type:	Other
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

O68
NW
1/2 - 1 Mile
Lower

MD WELLS **MD7000000074385**

County Letter:	BA	Permit #:	BA813737
MGS ID:	Not Reported	Driller:	COCHRAN, SANDY B.
Driller #:	MWD0120	Est GPM Produced:	5
Water Use:	Home or Public use	Approx Depth (ft):	200
Drill Method:	AIR-PER		
Replacement or Deepened:	This well will replace a well that will be used as a standby.		
WAP ID:	Not Reported	Issue Date:	08-MAY-85 12.00.00.000000 AM
Completion Date:	03-JUN-85 12.00.00.000000 AM		
Total Depth (ft):	300	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	42
Casing Type:	Steel	Casing Diameter (inches):	6
Casing Depth (ft):	42	Casing Height (ft):	+01
Screen Type:	Open	Top of Screen (ft):	42
Bottom of Screen (ft):	300	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	Not Reported
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	3
Pumping Rate (gpm):	20	Level Before Test (ft):	30
Level During Test (ft):	280	Test Pump Type:	Air
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

O69
NW
1/2 - 1 Mile
Lower

MD WELLS **MD7000000497372**

County Letter:	BA	Permit #:	BA950446
MGS ID:	Not Reported	Driller:	GREGORY S LYONS
Driller #:	MGD 89	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	23	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	20-JUN-05 12.00.00.000000 AM
Completion Date:	18-JUN-05 12.00.00.000000 AM		
Total Depth (ft):	23	Hydrofracture:	No

Grouted:	Yes	Grout Type:	Bentonie Clay
Grout Top (ft):	Not Reported	Grout Bottom (ft):	10
Casing Type:	Plastic	Casing Diameter (inches):	1
Casing Depth (ft):	13	Casing Height (ft):	+2
Screen Type:	Plastic	Top of Screen (ft):	13
Bottom of Screen (ft):	23	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	1
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	Not Reported
Level During Test (ft):	Not Reported	Test Pump Type:	Not Reported
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

O70
NW
1/2 - 1 Mile
Lower

MD WELLS **MD7000000497373**

County Letter:	BA	Permit #:	BA950447
MGS ID:	Not Reported	Driller:	GREGORY S LYONS
Driller #:	MGD 89	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	34	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	20-JUN-05 12.00.00.000000 AM
Completion Date:	18-JUN-05 12.00.00.000000 AM		
Total Depth (ft):	30	Hydrofracture:	No
Grouted:	Yes	Grout Type:	Bentonie Clay
Grout Top (ft):	Not Reported	Grout Bottom (ft):	8
Casing Type:	Plastic	Casing Diameter (inches):	1
Casing Depth (ft):	10	Casing Height (ft):	+2
Screen Type:	Plastic	Top of Screen (ft):	10
Bottom of Screen (ft):	30	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	1
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	Not Reported
Pumping Rate (gpm):	Not Reported	Level Before Test (ft):	25
Level During Test (ft):	Not Reported	Test Pump Type:	Not Reported
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

71
ENE
1/2 - 1 Mile
Lower

MD WELLS **MD7000000061069**

County Letter:	BA	Permit #:	BA700490
MGS ID:	Not Reported	Driller:	EASTERDAY, LOUIS F
Driller #:	MWD0042	Est GPM Produced:	5

Water Use:	Home or Public use	Approx Depth (ft):	100
Drill Method:	ROTARY		
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	01-JUN-70 12.00.00.000000 AM
Completion Date:	29-MAY-70 12.00.00.000000 AM		
Total Depth (ft):	160	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Not Reported
Grout Top (ft):	0	Grout Bottom (ft):	20
Casing Type:	Steel	Casing Diameter (inches):	6
Casing Depth (ft):	22	Casing Height (ft):	+02
Screen Type:	Open	Top of Screen (ft):	22
Bottom of Screen (ft):	160	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	Not Reported
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	50	Level Before Test (ft):	35
Level During Test (ft):	160	Test Pump Type:	Rotary
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

72
North
1/2 - 1 Mile
Lower

MD WELLS **MD7000000378071**

County Letter:	BA	Permit #:	BA930536
MGS ID:	Not Reported	Driller:	PAUL M FABISZAK
Driller #:	MWD 399	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	20	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	29-NOV-93 12.00.00.000000 AM
Completion Date:	Not Reported	Total Depth (ft):	Not Reported
Hydrofracture:	Not Reported	Grouted:	Not Reported
Grout Type:	Not Reported	Grout Top (ft):	Not Reported
Grout Bottom (ft):	Not Reported	Casing Type:	Not Reported
Casing Diameter (inches):	Not Reported	Casing Depth (ft):	Not Reported
Casing Height (ft):	Not Reported	Screen Type:	Not Reported
Top of Screen (ft):	Not Reported	Bottom of Screen (ft):	Not Reported
Screen 2 Type:	Not Reported	Top Screen 2 (ft):	Not Reported
Bottom Screen 2 (ft):	Not Reported	Screen 3 Type:	Not Reported
Top Screen 3 (ft):	Not Reported	Bottom Screen 3 (ft):	Not Reported
Screen Diameter (inches):	Not Reported	Flowing Well:	Not Reported
Telescoping:	Not Reported	Log Type:	Not Reported
Hours Pumped:	Not Reported	Pumping Rate (gpm):	Not Reported
Level Before Test (ft):	Not Reported	Level During Test (ft):	Not Reported
Test Pump Type:	Not Reported	Pump Installed:	Not Reported
Install pump Type:	Not Reported	Capacity (gpm):	Not Reported
Pump Horse Power:	Not Reported	Pump Column Length (ft):	Not Reported
Closed:	Not Reported	Abandoned:	Not Reported
Date Abandoned:	Not Reported		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

73
South
1/2 - 1 Mile
Higher

MD WELLS **MD7000000074725**

County Letter:	BA	Permit #:	BA814072
MGS ID:	Not Reported	Driller:	D'AMIANO, ANTHONY R.
Driller #:	MWD0346	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	30	Drill Method:	AIR-ROT
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	21-AUG-85 12.00.00.000000 AM
Completion Date:	21-AUG-85 12.00.00.000000 AM		
Total Depth (ft):	18	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Bentonie Clay
Grout Top (ft):	0	Grout Bottom (ft):	8
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	8	Casing Height (ft):	+01
Screen Type:	Plastic	Top of Screen (ft):	8
Bottom of Screen (ft):	18	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	1
Level During Test (ft):	1	Test Pump Type:	Other
Pump Installed:	Not Reported	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

74
NNE
1/2 - 1 Mile
Lower

MD WELLS **MD7000000342785**

County Letter:	BA	Permit #:	BA920480
MGS ID:	Not Reported	Driller:	PAUL M. FABISZAK
Driller #:	MWD0399	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	20	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	22-MAY-92 12.00.00.000000 AM
Completion Date:	04-JUN-92 12.00.00.000000 AM		
Total Depth (ft):	25	Hydrofracture:	Not Reported
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	0	Grout Bottom (ft):	4
Casing Type:	Plastic	Casing Diameter (inches):	4
Casing Depth (ft):	5	Casing Height (ft):	-1
Screen Type:	Plastic	Top of Screen (ft):	5
Bottom of Screen (ft):	25	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	4
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	1
Pumping Rate (gpm):	1	Level Before Test (ft):	1

Level During Test (ft):	1	Test Pump Type:	Other
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Y	Date Abandoned:	02-AUG-00 12.00.00.000000 AM

P75
NE
1/2 - 1 Mile
Lower

MD WELLS **MD7000000395520**

County Letter:	HO	Permit #:	HO941000
MGS ID:	Not Reported	Driller:	KEYSER-GARVER
Driller #:	MSD 95	Est GPM Produced:	5
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	350	Drill Method:	AIR-PER
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	03-DEC-96 12.00.00.000000 AM
Completion Date:	06-DEC-96 12.00.00.000000 AM		
Total Depth (ft):	404	Hydrofracture:	No
Grouted:	Yes	Grout Type:	Cement
Grout Top (ft):	Not Reported	Grout Bottom (ft):	84
Casing Type:	Steel	Casing Diameter (inches):	6
Casing Depth (ft):	84	Casing Height (ft):	+4
Screen Type:	Open	Top of Screen (ft):	80
Bottom of Screen (ft):	402	Screen 2 Type:	Not Reported
Top Screen 2 (ft):	Not Reported	Bottom Screen 2 (ft):	Not Reported
Screen 3 Type:	Not Reported	Top Screen 3 (ft):	Not Reported
Bottom Screen 3 (ft):	Not Reported	Screen Diameter (inches):	Not Reported
Flowing Well:	Not Reported	Telescoping:	Not Reported
Log Type:	Not Reported	Hours Pumped:	3
Pumping Rate (gpm):	10	Level Before Test (ft):	20
Level During Test (ft):	40	Test Pump Type:	Submersible
Pump Installed:	N	Install pump Type:	Not Reported
Capacity (gpm):	Not Reported	Pump Horse Power:	Not Reported
Pump Column Length (ft):	Not Reported	Closed:	Not Reported
Abandoned:	Not Reported	Date Abandoned:	Not Reported

P76
NE
1/2 - 1 Mile
Lower

MD WELLS **MD7000000467306**

County Letter:	BA	Permit #:	BA944507
MGS ID:	Not Reported	Driller:	BRENARD J TAYLOR
Driller #:	MWD 430	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	15	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	03-AUG-00 12.00.00.000000 AM
Completion Date:	Not Reported	Total Depth (ft):	Not Reported
Hydrofracture:	Not Reported	Grouted:	Not Reported
Grout Type:	Not Reported	Grout Top (ft):	Not Reported
Grout Bottom (ft):	Not Reported	Casing Type:	Not Reported
Casing Diameter (inches):	Not Reported	Casing Depth (ft):	Not Reported
Casing Height (ft):	Not Reported	Screen Type:	Not Reported
Top of Screen (ft):	Not Reported	Bottom of Screen (ft):	Not Reported
Screen 2 Type:	Not Reported	Top Screen 2 (ft):	Not Reported

Bottom Screen 2 (ft):	Not Reported	Screen 3 Type:	Not Reported
Top Screen 3 (ft):	Not Reported	Bottom Screen 3 (ft):	Not Reported
Screen Diameter (inches):	Not Reported	Flowing Well:	Not Reported
Telescoping:	Not Reported	Log Type:	Not Reported
Hours Pumped:	Not Reported	Pumping Rate (gpm):	Not Reported
Level Before Test (ft):	Not Reported	Level During Test (ft):	Not Reported
Test Pump Type:	Not Reported	Pump Installed:	Not Reported
Install pump Type:	Not Reported	Capacity (gpm):	Not Reported
Pump Horse Power:	Not Reported	Pump Column Length (ft):	Not Reported
Closed:	Not Reported	Abandoned:	Not Reported
Date Abandoned:	Not Reported		

P77
NE
1/2 - 1 Mile
Lower

MD WELLS **MD7000000467307**

County Letter:	BA	Permit #:	BA944508
MGS ID:	Not Reported	Driller:	BRENARD J TAYLOR
Driller #:	MWD 430	Est GPM Produced:	Not Reported
Water Use:	Test, Observation, Monitoring (may require an appropriation)		
Approx Depth (ft):	15	Drill Method:	BORED
Replacement or Deepened:	This well will not replace an existing well(new well)		
WAP ID:	Not Reported	Issue Date:	03-AUG-00 12.00.00.000000 AM
Completion Date:	Not Reported	Total Depth (ft):	Not Reported
Hydrofracture:	Not Reported	Grouted:	Not Reported
Grout Type:	Not Reported	Grout Top (ft):	Not Reported
Grout Bottom (ft):	Not Reported	Casing Type:	Not Reported
Casing Diameter (inches):	Not Reported	Casing Depth (ft):	Not Reported
Casing Height (ft):	Not Reported	Screen Type:	Not Reported
Top of Screen (ft):	Not Reported	Bottom of Screen (ft):	Not Reported
Screen 2 Type:	Not Reported	Top Screen 2 (ft):	Not Reported
Bottom Screen 2 (ft):	Not Reported	Screen 3 Type:	Not Reported
Top Screen 3 (ft):	Not Reported	Bottom Screen 3 (ft):	Not Reported
Screen Diameter (inches):	Not Reported	Flowing Well:	Not Reported
Telescoping:	Not Reported	Log Type:	Not Reported
Hours Pumped:	Not Reported	Pumping Rate (gpm):	Not Reported
Level Before Test (ft):	Not Reported	Level During Test (ft):	Not Reported
Test Pump Type:	Not Reported	Pump Installed:	Not Reported
Install pump Type:	Not Reported	Capacity (gpm):	Not Reported
Pump Horse Power:	Not Reported	Pump Column Length (ft):	Not Reported
Closed:	Not Reported	Abandoned:	Not Reported
Date Abandoned:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

EPA Region 3 Statistical Summary Readings for Zip Code: 21244

Number of sites tested: 23.

Maximum Radon Level: 34.9 pCi/L.
Minimum Radon Level: 0.1 pCi/L.

pCi/L <4	pCi/L 4-10	pCi/L 10-20	pCi/L 20-50	pCi/L 50-100	pCi/L >100
20 (86.96%)	1 (4.35%)	0 (0.00%)	2 (8.70%)	0 (0.00%)	0 (0.00%)

Federal EPA Radon Zone for BALTIMORE County: 1

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

Maryland Public Supply Wells
Source: Department of the Environment
Telephone: 410-537-3702
Water use types included are farm (livestock watering and agricultural irrigation), geo-thermal, industrial-commercial-state and federal government, municipal, test-observation-monitoring.

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Location Information
Source: Department of the Environment.
Telephone: 410-537-3557

RADON

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

EPA Region 3 Statistical Summary Readings
Source: Region 3 EPA
Telephone: 215-814-2082
Radon readings for Delaware, D.C., Maryland, Pennsylvania, Virginia and West Virginia.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

This page intentionally left blank

Appendix E

Regulatory Agency Records Documentation

From: Fire-PIA
To: Richards, Mitchell
Subject: RE: PIA Request - Security Square Mall
Date: Thursday, August 14, 2025 11:39:12 AM

The Baltimore County Fire Department is the custodian of responses to hazardous materials incidents and responses to fires. Regarding Security Square Mall, the Fire Department's records have been searched and found no records of responses to hazardous materials incidents.

Please refer to PIA tracking **#25-917** in any subsequent correspondence pertaining to this matter.

Nothing in this response is intended to indicate that any records sought from the Baltimore County Fire Department exist or to waive any privileges held by the Fire Department. You have the right under GP § 4-1B-04 to contact the Public Access Ombudsman to mediate any dispute(s) you may have with this response. If the Ombudsman is unable to resolve the matter, you may subsequently seek a resolution from the Public Information Act Compliance Board for those matters within the Compliance Board's jurisdiction. See GP §§ 4-1A-01 et seq. and 4-1B-01 et seq. Lastly, after seeking redress from the Public Access Ombudsman and then Public Information Act Compliance Board; you may then contest this response by filing a complaint for Judicial Review in Circuit Court pursuant to GP § 4-362.

Mary McInnes
Records Manager
Baltimore County Fire Department
P) 410-887-2071 F) 410-832-8513
fire-pia@baltimorecountymd.gov

From: Richards, Mitchell <mrichards@eaest.com>
Sent: Thursday, July 24, 2025 10:46 AM
To: Horacio Tablada <htablada@baltimorecountymd.gov>; Fire-PIA <fire-pia@baltimorecountymd.gov>; Elyn Garrett-Jones <egarrettjones@baltimorecountymd.gov>
Subject: PIA Request - Security Square Mall

CAUTION: This message from mrichards@eaest.com originated from a non Baltimore County Government or non BCPL email system. Hover over any links before clicking and use caution opening attachments. Do not click on any link and fill any request asking for your username and password at any time. BCG OIT will never ask for your username and password over email. Use the "Phish Alert Report" button to report.

Hello,

EA is an environmental consulting firm submitting a Public Information Act request on behalf of our client. We are conducting an environmental investigation and would like information regarding all available documents within your files regarding the environmental history of the following address:

6901 Security Blvd, Baltimore, MD 21244
(Security Square Mall)

Please use the property address on all written correspondence or responses forwarded to our office in reference to this request. Any written responses should be sent to the following address:

Mitchell Richards
EA Engineering, Science, and Technology, Inc., PBC
225 Schilling Circle, Suite 400
Hunt Valley, Maryland 21031

Please contact Mitchell Richards as soon as possible at 410-917-7317 or by email at mrichards@eaest.com with any questions or with information regarding available files. Thank you very much.

Regards,

Mitchell Richards, B.S. Chemical Engineering 2023
Engineer I

EA Engineering, Science, and Technology, PBC
225 Schilling Circle, Suite 400
Hunt Valley, MD 21031
P: 410-650-6974 | M: 410-917-7317
http://secure-web.cisco.com/1nAM0CpiWPuqRjXu-Xgpxjpe8ZQEvCbGqZPnUygXqCbfO7d09W5Oi8TaGZGPjpggtYrpXkbJAp2WkrKlxrHqM_UB2iYk3Z8E6NLCEbW5tsw9C7YzCsY7k8t3KCNSkE-Siw8yYgxJvqNngsHZhlDpXYpBBIxXY_teEkdupIVkx0qCYs-I5OikFW6WmUQNZCrn8kR04mElOVcJf0vHcEjbb5LuKfoBo87R6DujWg6E2L2vVm9oe2M_y43C5wLqdOEjfgOoJdS0rS_IoR9NzMPDMUaHTLQ6ibejx2VjLJzGIF-RpYqg1xrIZplEhCluSEWuuNKJHtnMDgqNZ0PBMpP156rrDOn-i-LLBWrPMWVdXfPG4CUACmqc_wm8sIPKgmqhTlg0YQ0NpnEG_bZRdzN8MoqnLcRW98NplXbaCH6PKuvZ8Ymc3TQYsRvuy4uX-oaFf/http%3A%2F%2Fwww.eaest.com

EA is a 100% Employee-Owned Public Benefit Corporation
IMPROVING THE QUALITY OF THE ENVIRONMENT IN WHICH WE LIVE, ONE PROJECT AT A TIME®

CONNECT WITH BALTIMORE COUNTY

www.baltimorecountymd.gov

KATHERINE A. KLAUSMEIER
County Executive

HORACIO TABLADA, *Director*
Department of Environmental Protection and Sustainability

July 24, 2025

Mitchell Richards
EA ENGINEERING
225 SCHILLING CIR
SUITE 400
HUNT VALLEY MD 21031

RE: Project ID: N/A 6901 Security Blvd

Dear Mitchell Richards:

I am writing in response to your correspondence, dated 7/24/2025, and received by us on 7/24/2025, requesting information on the above referenced site under Maryland's Public Information Act.

The Department of Environmental Protection and Sustainability (EPS) stores information in files located within seven sections listed below. We performed a database search for information in those sections that best matched your request. The boxes to the left of each section indicate which sections were searched and whether any information was present in their files. If you are interested in information from a section whose files were not searched, or would like to schedule an appointment to review the files we found in the database search, please contact the individuals indicated below.

Search	Information Present		Section	Contact
	Yes	No		
☒	☒	☐	Ground Water Management (Well and Septic Information, Ground Water Contamination Cases and UST Removals)	Evan Carrozza (410) 887-2762
☒	☐	☒	Waste Management (Landfills, Recycling Facilities)	Jerry Siewierski (410) 887-3745
☐	☐	☐	Environmental Impact Review (Streams, Wetlands, Forests, Marinas, and Chesapeake Bay Critical Areas)	Regina Esslinger (410) 887-3980

☐	☐	☐	Stormwater Management (Grading and Stormwater Management Plan Review)	Kritty Udhin (410) 887-3768
☐	☐	☐	Watershed Management (NPDES and MS4 Permit Compliance)	Rob Hirsch (410) 887-5563
☐	☐	☐	Watershed Restoration (Stream Restoration Projects and Public Stormwater Pond Maintenance)	Rob Ryan (410) 887-2904
☐	☐	☐	Watershed Monitoring (Surface and Storm Water Monitoring Data)	Kevin Brittingham (410) 887-5571
☐	☐	☐	Forest Management (Reforestation and Urban Tree Planting Programs)	Brian Lindley (410) 887-1369

Due to changes in database management, the Department can only search for specific properties. We will no longer provide vicinity/radius searches when requested.

Please note that a fee of $35.00 per hour, after the first two hours, may be assessed for the time spent searching files, and preparing and reviewing records for your inspection and copying. In addition, should you desire copies of the materials in the files, Baltimore County policy requires payment of $0.50 per page, in advance.

In order to ensure timely processing, please note our address is:
111 W. Chesapeake Avenue, Room 305
Towson, MD 21204

If you have any questions please feel free to call us at (410) 887-2762.

Sincerely,

Evan J. Carrozza, L.E.H.S.
Ground Water Management

BALTIMORE COUNTY, MARYLAND
DEPARTMENT OF ENVIRONMENTAL PROTECTION AND SUSTAINABILITY
111 W. Chesapeake Avenue, Room 305
Towson, Maryland 21204
410-887-3733

Public Information Act (PIA) Request for Information Form

DATE OF REQUEST: 8-8-2025

REQUESTER INFORMATION

Name (First, Mi, Last) Mitchell P Richards

Title Engineer

Organization EA Engineering Science and Technology Inc., PBC.

Category
☐ Attorney ☐ Citizen ☐ Interest Group
☒ Consultant ☐ Media ☐ Student ☐ Other

Street Address 225 Schilling Circle Suite 400
City Hunt Valley State MD Zip 21031 Country USA
Telephone 410-584-7000 Email Address mrichards@eaest.com

Billing address (if different than above)

Street Address _____
City _____ State _____ Zip _____ Country _____
Telephone _____ Email Address _____

PROPERTY/FACILITY FOR WHICH INFORMATION IS REQUESTED

Facility Name Security Square Mall, Baltimore County Owned Parcels

Street Address See attached SDATs for requested parcels

Subdivision _____

Tax Map 0094 Grid _____ Parcel _____ Lot # _____ Tax ID# _____

Case No.: _____

OFFICE USE ONLY

Bureau: _____
# of photocopies # _____
payment received _____
process date ____/____/____
processed by (initials) _____

Please check the EPS program from which you are seeking records.

- [X] Stormwater Management
- [X] Environmental Impact Review
- [X] Groundwater Management
- [ ] Development Coordination
- [ ] Watershed Restoration
- [ ] Watershed Management and Monitoring
- [ ] Sustainability and Forest Management
- [ ] Finance and Administration

Please specify what information is being requested:

information regarding petroleum/hazardous materials storage and/or releases of petroleum products or hazardous materials or other environmental issues

- [ ] I will pick this information up after being called and notified that it is ready.
- [ ] I wish this information to be mailed at my expense.
- [X] I wish this information to be transmitted electronically to me.

PLEASE NOTE: Please Note: This Department strives to produce responsive records promptly. If the search, preparation, and reproduction of responsive records cannot be completed within ten (10) working days, will take longer than two (2) hours of staff time, or is denied, the Department will provide a written response in accordance with the Maryland Public Information Act.

FEE INFORMATION: The first two (2) hours to search, prepare, and reproduce records is free of charge. Additional time beyond two hours is charged at Thirty-five Dollars ($35.00) per hour. Photocopies are Twenty-five Cents ($0.25) per 8.5"x11" sheet and Two Dollars ($2.00) per large format plan sheet. Fee estimates for staff time and photocopies will be provided in writing.

MARYLAND DEPARTMENT OF THE ENVIRONMENT

1800 Washington Boulevard Suite 620 • Baltimore Maryland 21230-1719
(410) 537 3442 1-800-633-6101 http // www mde state md us

B797820

LAND MANAGEMENT ADMINISTRATION
Oil Control Program

Case #
INITIAL / FOLLOW UP

Tank Removal / Abandonment

Site Name **MACY S**
Address **6901 Security Blvd Baltimore Maryland 21244**

Date **October 26 2012**
Facility ID # **6267**

1 (a) **1** Number of UST's removed (b) **0** Number of UST's abandoned in-place (c) **0** Number of UST's remaining on-site.
2 Has an en ironmental assessment been completed? ☐YES ☒NO

Tank	Product	Age (years)	Size (gallons)	Tank Construction	Perforations Tank	Perforations Piping	Piping Construction	Disposal Site
2	Diesel	13	300	Stl-p3	Yes ☐ No ☒	Yes ☐ No ☒	Sleeved Copper	Yowell Scrap
					Yes ☐ No ☐	Yes ☐ No ☐		
					Yes ☐ No ☐	Yes ☐ No ☐		
					Yes ☐ No ☐	Yes ☐ No ☐		
					Yes ☐ No ☐	Yes ☐ No ☐		
					Yes ☐ No ☐	Yes ☐ No ☐		

3 Has piping been properly abandoned? ☒YES ☐NO ☐UNKNOWN
4 Has vent risers been removed? ☒YES ☐NO
5 Has all liquid been removed from UST(s)? ☒YES ☐NO
6 Is explosion meter on site? ☒YES ☐NO
7 Ha e UST(s) been purged of explosive o combustible vapors? ☒YES ☐NO
(must confirm less than 10% LEL with explosio meter)
8 Is groundwater contaminated? ☐YES ☐NO ☒NOT DETECTABLE AT THIS TIME
9 Is soil contam nated? (f yes type f product:_____) ☐YES ☐NO ☒NOT DETECTABLE AT THIS TIME
10 Were contaminated soils removed? ☐YES ☐NO
(If YES complete *Contaminated Soil Removal F rm* If NO describe in item 18)
11 Was soil field screened? ☐YES ☐NO
Tank max. units **1 4** at **below tank** Piping max. un ts **n/** at **n/a**
12 Are domestic well(s) on site? ☐YES ☒NO
Is sampling required? (If YES, list EPA method in item 14) ☐YES ☒NO

13 **ACTIONS REQUIRED IMMEDIATELY OF THE OWNER BY THIS ADMINISTRATION**
☐STOP OPERATIONS ☐PUMP OUT LIQUIDS ☐CONTAIN AND CLEAN UP SPILL
☐OTHER. _____

14 **ACTIONS REQUIRED WITHIN 30 DAYS, OF THE OWNER BY THIS ADMINISTRATION**
☒SUBMIT ALL TANK REMOVAL/ABANDONMENT DOCUMENTATION INCLUDING **Tank Closure Report**
☐PROPERLY ABANDON PIPING IN COMPLIANCE WITH COMAR 26 10 10 02 B (2) (removed unless otherwise directed)
☐REMOVE VENT PIPE RISER (S)
☐_____ MONITORING WELL (S) REQUIRED IN PETROLEUM IMPACTED AREA (S) DESCRIBED IN ITEM 18
☐COMPLETE AN ENVIRONMENTAL ASSESSMENT IN COMPLIANCE WITH COMAR 26 10 _____(submit two cop es)
☒SUBMIT SOIL ANALYTICAL RESULTS
EPA METHOD ☒8015B GRO/DRO ☐8021 (☐BTEX ☐MTBE ☐TBA) ☐8270 (SVOC S) ☒8260 (VOC S)
☐OTHER._____
☐SUBMIT GROUNDWATER ANALYTICAL RESULTS
EPA METHOD ☐8015B GRO/DRO ☐8021 (☐BTEX ☐MTBE ☐TBA) ☐8270 (SVOC S) ☐8260 (VOC S) ☐524.2 (VOC S)
☐OTHER _____
☐SUBMIT SOIL DISPOSAL RECEIPT
☐SUBMIT TANK DISPOSAL RECEIPT

Date Octobe 26 2012
Case No
Facility No 6267

14 (continued)
☐AMEND REGISTRATION ☐Notification form provided to contact person
☐Owner/Representative informed case file may remain open until notification form is received by MDE
☐ Completed on site
☐OTHER. ____

15 Has inspector completed site sketch? ☐YES ☒NO site photographs? ☒YES ☐NO
16 Were tank(s) labeled? (If YES describe. rk 10-26-12 M) ☒YES ☐NO
17 Is follow up required by this Administration? ☒YES ☐NO

18 COMMENTS Resp nded fo th m val f one 300 gall n und rground storage tank that had contained diesel fuel Observed no sta ning of soil no odor of diesel ful and no perforations in tank. The tank was a STIP-3 tank not FRP Soil from below tank bottom was field screened with a maximum reading of 1 4 units. Excavated soil can be used as backfill Site s on city water and sewer

REQUIREMENTS

1 Submit a complete tank closure report containing

a narrative

b site sketch with location of tank and where soil samples were taken with depth of samples

c. soil analysis results.

d take two so l samples one from each end of the tank two feet below tank bottom

e analyze samples us ng EPA Methods 8015B TPH DRO/GRO and 8260 limited suite VOC s including oxygenates

Ray Kozlowski	R J Kozlowski	
Inspecto Name	Inspector Signature	
MARK Bruce		518 465 4000
Co tact Person Name (printed)	Contact Perso s S gnature	Contact Person s T lephone N
Jerome Nix		4103652089
Contractor's Name (Printed)	Contracto s S gnature	Contractor s Telephon N
Jerome P Nix	MDIC 2011 0156(T)	12 1 1 2013
Techn ian/Rem er Name (printed)	Certification Number	Expirat on Date

Modified on 03/20/04 JHC

BALTIMORE COUNTY, MARYLAND

2212

INTER-OFFICE CORRESPONDENCE

TO FILE Date May 21,1986

FROM William W. Ensor, Jr.

SUBJECT Tank Removal
6901 Security Blvd.
Sears - Security Square Mall
Reference #87264

On May 21, 1986, I inspected the tank removal at the Sears Automotive Shop, 6901 Security Blvd. Inspection revealed the Petroleum, Services, Inc. was conducting the removal of six(6) 5,000 gallon underground gasoline storage tanks.

Inspection of the removed tanks revealed no evidence of leakage on them or in the tank pits.

Close File.

typed on 5.22.86
Reviewed By

WWE/kek

2212

TANK REMOVAL/ABANDONMENT

State of Maryland
Department of the Environment
Hazardous and Solid Waste Management Administration
2500 Broening Highway, Baltimore, Maryland 21224
(301) 631-3442

Date 12-1-93

Site Name: SEARS # 1634

Site Address: 6901 SECURITY BLVD. SECURITY MALL - WOODLAWN

Facility # 1634

Case #

OPEN CLOSE
INITIAL FOLLOW-UP

1a. ✓ Tank(s) removed
1b. ____ Tank(s) abandoned in place

Has an environmental assessment been completed? YES ☐ (Go to 2) NO ☑
☐ Complete an environmental assessment within ____ days in compliance with COMAR ____

2. Has piping been properly abandoned? YES ☑ (Go to 3) NO ☐ UNKNOWN ☐
☐ Properly abandon piping within ____ days in compliance with COMAR ____

3. Has all liquid been removed from tank(s)? YES ☑ (Go to 4) NO ☐
☐ Stop operations and pump out liquid as ordered by this Administration

4. Have tank(s) been purged of explosive or combustible vapors? YES ☑ (Go to 5) NO ☐
Can operation continue safely? YES ☑ (Go to 5) NO ☐
☐ Stop operations as ordered by this Administration

5. Were perforations observed during visual inspection of tank or piping? YES ☑ NO ☐

Tank #	Type of product	Age (yrs.)	Size	Type of tank	Type of piping	System tested? (Y/N)	Date of last test?	Disposal site
1	WASTE OIL	20	550 gal.	steel	steel			BROOKLYN
								SALVAGE
								BALTO., MD.

6. Is groundwater contaminated? YES ☐ NO ☐ (Go to 7) UNKNOWN ☑
☐ Perform a site assessment and submit report to this Administration within ____ days

7. Is soil contaminated? YES ☑ NO ☐ (Go to 8)
Were contaminated soils removed? YES ☑ NO ☐
If YES: Disposal site? ____
If NO: ☐ Removal of soils not required

8. Perform specified tasks or submit additional information to this Administration within 30 days:
☑ ONE monitoring well(s) required in specified location(s)
☑ Complete a site assessment and submit report
☐ Daily inventory records ☐ Past testing info. ☐ All repair work info.
☑ Other: Copy of tank and soil Disposal receipt
☑ All documentation associated with tank removal/abandonment:
including: Analysis of groundwater report - Copy

9. Comments: Tank had two perforations on one end of tank on end seam. Other perforation found is in center of tank on bottom. Soils have strong odor of waste oil visible product in soils. Concrete pad under UST, P&D reading at each end is 64 ppm. Pipe leading from separator to UST was filled with concrete and capped. Area around pipe in concrete separator was broken out for repair. Hole in concrete around pipe was patched with concrete. Separator tank is still in use and contains oil in pervious areas during rain storms, and is washed on

10. UST notification form amended? YES ☐ NO ☐ Entire floor drain grate, sump will be in
11. Is follow-up required by this Administration? YES ☑ NO ☐ violation of Maryland Regulations.

Inspector's name (printed) and signature: RICHARD S. PEGO Area likely to be subject to notice of the State

Contact person's name (printed) and signature: [illegible]

Contractor's name (printed) and signature: Bob Donald Bob Donald

GTI is Contractor, and taken soil samples for analysis.
Donald E Heaw. is sub contractor, removed U.S.T.

Maryland
Department of the Environment

Wes Moore, Governor
Aruna Miller, Lt. Governor

Serena McIlwain, Secretary
Suzanne E. Dorsey, Deputy Secretary
Adam Ortiz, Deputy Secretary

August 22, 2025

Mitchell Richards
225 Schilling Circle Suite 400
Hunt Valley , MD 21031

RE: Tracking Number: 2025-02411
Request Received August 11, 2025
Security Square Mall

Dear Mitchell Richards :

The Maryland Department of the Environment (MDE) received your recent request for information under the Public Information Act (PIA).

Copies of your request have been circulated to all Programs likely to have records that are responsive to your request. Based upon the estimated number of staff-hours required to search for and review responsive records, the Department estimates the cost of your request to be $40.30. The actual cost of fulfilling your request will depend upon the actual amount of time spent searching for and reviewing responsive records. Files have been located in the following MDE Administration(s):
Administration, Contact, Email

Air & Radiation Administration, DANIEL DAVIS, daniel.davis@maryland.gov
-- Air Quality Permits Program -005-1629 Crash Champions LLC PTC
--Air Quality Compliance Program - Premise File 005-1871 Bob's Big Boy, 005-1978 Bull on the Beach

Land & Materials Administration, MELISSA ALLEN, missi.allen@maryland.gov
-- Oil Control Program -93-2242 (Destroyed file), 94-1624BA , 94-2145BA , 04-0455BA , 13-0249BA , 15-0515BA , 23-041BA , 5743, 6267TP, 14022, 16393REG, 21208REG, SPILL-520

Water & Science Administration, Zachary Lansing, zachary.lansing@maryland.gov
-- Compliance Program - AI# 173366: 1 complaint, 2 FIRs
-- Industrial and General Discharge Permits Program - Terminated 14GP authorization MDRCC0637

You may contact the personnel listed above with any questions regarding the files found but we ask that you use the link provided in the Findings Email to formally request the specific records needed. It is requested that you make arrangements to review available files within 30 days of receipt of this letter. After 30 days your request will be closed and it will be necessary to file a new request.

Please note that we often need up to two weeks from the time we hear from you to physically assemble the files of interest to you.

When requesting information regarding this request, please cite the tracking number referenced above. If you have any questions, please email nicole.eisenstein@maryland.gov.

Sincerely,

Nicole Eisenstein

Nicole Eisenstein
PIA Coordinator
Office of Communications

BA

PA Form - Facility Data as of 02 OCT 1989

acility ID Number: 3-001797
ate Received: 04/01/86

Ownership	Location
AY DEPARTMENT STORES T/A HECHT'	SECURITY MALL.
~~FI DRIVE ST.~~ 685 N. Glebe Rd	6901 SECURITY BLVD.
~~FOSSPORT.~~ Arlington Va	BALTIMORE
~~T. LOUIS~~, MS 63101 22203-2199	BALTIMORE., MD 21207

hone: (703) 558-1555

ype of Owner

Current	:X	State/Local Govt	:	Private/Corp	:X
Former	:	Federal Govt	:	Uncertain	:

SA Number:

o. of Tanks: 001 Facility located on Indian Land? No

ontact Manager: EUGENE NOLL, Title: DVP.MAINT.ENGINEER
hone: (703) 558-1555

s this an Amended or Subsequent Form? No

orm Certification
ame: LACY WOMACK. Title: VICE PRESIDENT.
ate Signed: 03/28/86

orm Status: COMPLETE

EPA Form - Tank Data as of 02 OCT 1989

Facility ID Number: 3-001797 Tank ID Number: 001

Status Code	
Currently In Use	X
Temporarily Out of Use	
Permanently Out of Use	
Brought Into Use After 5/8/86	
Age in Years	7
Capacity (Gallons)	250
Material of Construction	
Steel	X
Concrete	
Fiberglass Reinforced Plastic	
Unknown	
Other Material	
Internal Protection	
Cathodic Protection	
Interior Lining (e.g. epoxy)	
None	
Unknown	X
Other Int. Protection	
External Protection	
Cathodic Protection	
Painted (Asphaltic)	X
Fiberglass Reinforced Plastic	
None	
Unknown	
Other Ext. Protection	
Pipe Material	
Bare Steel	
Galvanized Steel	X
Fiberglass Reinforced Plastic	
Cathodically Protected	
Unknown	
Other Pipe Mat	
Substance Code	
Empty	
Diesel	
Kerosene	X
Gasoline	
Used Oil	
Other Substance Name	
Hazardous Substance	
CERCLA Substance Name	
CAS Number	
Mixture of Substances	
Unknown	
Additional Information For Tanks Permanently Out of Service	
Date of Last Use	
Gallons remaining	
Filled with Inert Material	

Notification for Underground Storage Tanks

FORM APPROVED
OMB NO. 2050-0049
APPROVAL EXPIRES 6-30-88

RETURN COMPLETED FORM TO

STATE USE ONLY

I.D. Number 3-00117917

Date Received 04/01/86

GENERAL INFORMATION

Notification is required by Federal law for all underground tanks that have been used to store regulated substances since January 1, 1974, that are in the ground as of May 8, 1986, or that are brought into use after May 8, 1986. The information requested is required by Section 9002 of the Resource Conservation and Recovery Act, (RCRA), as amended.

The primary purpose of this notification program is to locate and evaluate underground tanks that store or have stored petroleum or hazardous substances. It is expected that the information you provide will be based on reasonably available records, or, in the absence of such records, your knowledge, belief, or recollection.

Who Must Notify? Section 9002 of RCRA, as amended, requires that, unless exempted, owners of underground tanks that store regulated substances must notify designated State or local agencies of the existence of their tanks. Owner means—

(a) in the case of an underground storage tank in use on November 8, 1984, or brought into use after that date, any person who owns an underground storage tank used for the storage, use, or dispensing of regulated substances, and

(b) in the case of any underground storage tank in use before November 8, 1984, but no longer in use on that date, any person who owned such tank immediately before the discontinuation of its use.

What Tanks Are Included? Underground storage tank is defined as any one or combination of tanks that (1) is used to contain an accumulation of "regulated substances," and (2) whose volume (including connected underground piping) is 10% or more beneath the ground. Some examples are underground tanks storing: **1.** gasoline, used oil, or diesel fuel, and **2.** industrial solvents, pesticides, herbicides or fumigants.

What Tanks Are Excluded? Tanks removed from the ground are not subject to notification. Other tanks excluded from notification are:

1. farm or residential tanks of 1,100 gallons or less capacity used for storing motor fuel for noncommercial purposes;
2. tanks used for storing heating oil for consumptive use on the premises where stored;
3. septic tanks;
4. pipeline facilities (including gathering lines) regulated under the Natural Gas Pipeline Safety Act of 1968, or the Hazardous Liquid Pipeline Safety Act of 1979, or which is an intrastate pipeline facility regulated under State laws;
5. surface impoundments, pits, ponds, or lagoons;
6. storm water or waste water collection systems;
7. flow-through process tanks;
8. liquid traps or associated gathering lines directly related to oil or gas production and gathering operations;
9. storage tanks situated in an underground area (such as a basement, cellar, mineworking, drift, shaft, or tunnel) if the storage tank is situated upon or above the surface of the floor.

What Substances Are Covered? The notification requirements apply to underground storage tanks that contain regulated substances. This includes any substance defined as hazardous in section 101 (14) of the Comprehensive Environmental Response, Compensation and Liability Act of 1980 (CERCLA), with the exception of those substances regulated as hazardous waste under Subtitle C of RCRA. It also includes petroleum, e.g., crude oil or any fraction thereof which is liquid at standard conditions of temperature and pressure (60 degrees Fahrenheit and 14.7 pounds per square inch absolute).

Where To Notify? Completed notification forms should be sent to the address given at the top of this page.

When To Notify? 1. Owners of underground storage tanks in use or that have been taken out of operation after January 1, 1974, but still in the ground, must notify by May 8, 1986. **2.** Owners who bring underground storage tanks into use after May 8, 1986, must notify within 30 days of bringing the tanks into use.

Penalties: Any owner who knowingly fails to notify or submits false information shall be subject to a civil penalty not to exceed $10,000 for each tank for which notification is not given or for which false information is submitted.

INSTRUCTIONS

Please type or print in ink all items except "signature" in Section V. **This form must by completed for each location containing underground storage tanks.** If more than 5 tanks are owned at this location, photocopy the reverse side, and staple continuation sheets to this form.

Indicate number of continuation sheets attached: 0

I. OWNERSHIP OF TANK(S)

Owner Name (Corporation, Individual, Public Agency, or Other Entity)
May Department Stores T/A Hecht's

Street Address
611 Olive Street

County

City: St.Louis | State: Missouri | ZIP Code: 63101

Area Code | Phone Number

Type of Owner *(Mark all that apply [X])*

- ☐ Current
- ☐ Former
- ☐ State or Local Gov't
- ☐ Federal Gov't (GSA facility I.D. no. _____)
- ☒ Private or Corporate
- ☐ Ownership uncertain

II. LOCATION OF TANK(S)

(If same as Section 1, mark box here ☐)

Facility Name or Company Site Identifier, as applicable
Security Mall

Street Address or State Road, as applicable
6901 Security Blvd.

County
Baltimore County

City (nearest): Baltimore | State: Maryland | ZIP Code: 21207

Indicate number of tanks at this location: 1

Mark box here if tank(s) are located on land within an Indian reservation or on other Indian trust lands ☐

III. CONTACT PERSON AT TANK LOCATION

Name (If same as Section I, mark box here ☐)
Eugene Noll

Job Title
DVP Maintenance Engineering

Area Code: 703 | Phone Number: 558-1555

IV. TYPE OF NOTIFICATION

☐ Mark box here only if this is an amended or subsequent notification for this location.

V. CERTIFICATION (Read and sign after completing Section VI.)

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete.

Name and official title of owner or owner's authorized representative
Lacy Womack Vice President - Operations

Signature: Lacy M Womack

Date Signed: 3/28/86

CONTINUE ON REVERSE SIDE

Owner Name (from Section I) May Dept Stores Location (from Section II) Baltimore, MD Page No. 1 of 1 Pages

VI. DESCRIPTION OF UNDERGROUND STORAGE TANKS *(Complete for each tank at this location.)*

Tank Identification No. (e.g., ABC-123), or Arbitrarily Assigned Sequential Number (e.g., 1,2,3...)	Tank No. 1	Tank No.	Tank No.	Tank No.	Tank No.
1. Status of Tank *(Mark all that apply ☒)*					
Currently in Use	☒	☐	☐	☐	☐
Temporarily Out of Use	☐	☐	☐	☐	☐
Permanently Out of Use	☐	☐	☐	☐	☐
Brought into Use after 5/8/86	☐	☐	☐	☐	☐
2. Estimated Age (Years)	7yrs				
3. Estimated Total Capacity (Gallons)	250gal				
4. Material of Construction *(Mark one ☒)*					
Steel	☒	☐	☐	☐	☐
Concrete	☐	☐	☐	☐	☐
Fiberglass Reinforced Plastic	☐	☐	☐	☐	☐
Unknown	☐	☐	☐	☐	☐
Other, Please Specify					
5. Internal Protection *(Mark all that apply ☒)*					
Cathodic Protection	☐	☐	☐	☐	☐
Interior Lining (e.g., epoxy resins)	☐	☐	☐	☐	☐
None	☐	☐	☐	☐	☐
Unknown	☒	☐	☐	☐	☐
Other, Please Specify					
6. External Protection *(Mark all that apply ☒)*					
Cathodic Protection	☐	☐	☐	☐	☐
Painted (e.g., asphaltic)	☒	☐	☐	☐	☐
Fiberglass Reinforced Plastic Coated	☐	☐	☐	☐	☐
None	☐	☐	☐	☐	☐
Unknown	☐	☐	☐	☐	☐
Other, Please Specify					
7. Piping *(Mark all that apply ☒)*					
Bare Steel	☐	☐	☐	☐	☐
Galvanized Steel	☒	☐	☐	☐	☐
Fiberglass Reinforced Plastic	☐	☐	☐	☐	☐
Cathodically Protected	☐	☐	☐	☐	☐
Unknown	☐	☐	☐	☐	☐
Other, Please Specify					
8. Substance Currently or Last Stored in Greatest Quantity by Volume *(Mark all that apply ☒)*					
a. Empty	☐	☐	☐	☐	☐
b. Petroleum					
Diesel	☐	☐	☐	☐	☐
Kerosene	☒	☐	☐	☐	☐
Gasoline (including alcohol blends)	☐	☐	☐	☐	☐
Used Oil	☐	☐	☐	☐	☐
Other, Please Specify					
c. Hazardous Substance	☐	☐	☐	☐	☐
Please Indicate Name of Principal CERCLA Substance					
OR Chemical Abstract Service (CAS) No.					
Mark box ☒ if tank stores a mixture of substances	☐	☐	☐	☐	☐
d. Unknown	☐	☐	☐	☐	☐
9. Additional Information (for tanks permanently taken out of service)					
a. Estimated date last used (mo/yr)	/	/	/	/	/
b. Estimated quantity of substance remaining (gal.)					
c. Mark box ☒ if tank was filled with inert material (e.g., sand, concrete)	☐	☐	☐	☐	☐

5m 17

~~B001797~~

NOTIFICATION FOR UNDERGROUND STORAGE TANKS U0005474

Return completed form to:

Maryland Department of the Environment
Oil Control Program
2500 Broening Highway
Baltimore MD 21224

State Use Only

Facility ID Number 12267

Alt ID Number 3-001797 BA

Date Entered into Computer 5/15/97

Data Clerk's Initials JNL

Owner Contacted to Clarify Response _____

Comments _____

TYPE OF NOTIFICATION: (check one)

☐ New Facility ☒ Amended ☐ Closure

1 Number of tanks at facility
_____ Number of continuation sheets attached

I. OWNERSHIP INFORMATION:

Owner ID: 9165

Owner Name: MAY Dept Stores T/A HECHTs

Street Address: 685 N Glebe Rd

Mailing Address (if different from above): _____

Arlington Va 22203-2199
City State Zip Code

Arlington
County:

(703) 558-1554
Phone Number:

Contact Person: Gene Noll

TYPE OF OWNER: (check one)

Government	Commercial
___ Federal	✓ Corporation
___ State	___ Company
___ Local	___ Partnership
	___ Individual

Non-Commercial

___ Residential
___ Agricultural
___ Non-Profit Agency

II. LOCATION OF TANK(S)

Facility Name or Company Site Identifier as applicable: HECHT's

Street Address: 6901 Security Blvd

Mailing Address (if different from above): _____

Baltimore md 21207
City State Zip Code

Baltimore
County

Phone Number ( ) Same

Facility Operator: Same

III. TYPE OF FACILITY: (check one)

___ Federal Non-Military	___ Gas Station	___ Private Home
___ Federal Military	___ Petroleum Distributor	___ Apt. / Condo
___ Educational	___ Trucking / Transport	___ Farm / Nursery
___ Fire/Rescue/Ambulance	___ Industrial	___ Marina
___ Public Service	___ Contractor	✓ Store
___ Utilities	___ Airline	___ Office
___ Railroad	___ Auto Dealership	___ Other_____

IV. CONTACT PERSON IN CHARGE OF TANKS

Name: Gene Noll Job Title: DVP MAINT ENG

Address: 685 N. Glebe Rd Arlington Va 22203-2199 Phone Number: 703-558-1554

V. FINANCIAL RESPONSIBILITY (if applicable - see instruction sheet)

I have met the financial responsibility requirements in accordance with 40 CFR Part 280, Subpart H

N/A ☐ YES ☐ No

___ Commercial Insurance	___ Self Insurance	___ Letter of Credit
Policy # _____	___ Insurance Pool	___ Surety Bond
Insurer _____	___ Risk Retention Group	___ Other method allowed
Agent/Broker _____	___ Guarantee	(specify)_____
Phone No. _____		

VI. CERTIFICATION (to be completed by owner or owner's representative)

I certify, under penalty of law, that I have personally examined, and am familiar with, the information submitted in this and all attached documents, and that the information provided is in compliance with COMAR 26.10.03, and is true, accurate, and complete.

Name (print/type): Eugene M Noll Title (print/type): Dvp Maint Eng

Signature: Eugene M Noll Date Signed: 4-21-97

VII. DESCRIPTION OF UNDERGROUND STORAGE TANKS (complete for each tank at this facility)

Tank Identification Number	Tank No.	Tank No.	Tank No.	Tank No.	Tank No.
Alt. Tank ID Number	Tank No. 1	Tank No.	Tank No.	Tank No.	Tank No.
1. Status of Tank (Mark only one)					
Currently in Use	✓				
Temporarily Out of Use					
Permanently Out of Use					
2. Date of Installation (mo/yr)	MAY 79				
3. Total Capacity (gallons)	250				
4. Material of Construction (mark all that apply)					
Asphalt Coated or Bare Steel	✓				
Cathodically Protected Steel					
Composite (Steel w/ Fiberglass)					
Concrete					
Fiberglass Reinforced Plastic					
Polyethylene Tank Jacket					
Unknown					
Other (specify)					
Has tank been repaired?	Yes___ No___	Yes___ No___	Yes___ No___	Yes___ No___	Yes___ No___
Double-walled					
Excavation Liner					
Lined Interior					
5. Piping (material) (mark all that apply)					
Bare Steel					
Galvanized Steel	✓				
Fiberglass Reinforced Plastic					
Copper					
Flexible Plastic					
Unknown					
Other (specify)					
Cathodically Protected					
Double-walled					
Secondary Containment					

VII. DESCRIPTION OF UNDERGROUND STORAGE TANKS (complete for each tank at this facility)

Tank Identification Number	Tank No. _____	Tank No. _____	Tank No. _____	Tank No. _____	Tank No. _____
Alt. Tank ID Number	Tank No. 1	Tank No. _____	Tank No. _____	Tank No. _____	Tank No. _____
6. Piping (Type) (mark all that apply)					
Pressure					
Gravity Feed					
Suction: no valve at tank (Safe Suction)	✓				
Suction: valve at tank (U.S. Suction)					
Has piping been repaired?	Yes___ No___	Yes___ No___	Yes___ No___	Yes___ No___	Yes___ No___
7. Substance Currently or Last Stored					
Gasoline					
Diesel	✓				
Gasohol					
Kerosene					
Heating Oil					
Used Oil					
Hazardous Substance CERCLA name and/or CAS #					
Other, please specify					
Mixture of Substances Please specify					
8. Closing of Tank					
Estimated date last used (mo/day/yr)	/ /	/ /	/ /	/ /	/ /
Date tank closed (mo/day/yr)	/ /	/ /	/ /	/ /	/ /
Tank was removed from ground	Yes___ No___	Yes___ No___	Yes___ No___	Yes___ No___	Yes___ No___
Tank filled with inert material	Yes___ No___	Yes___ No___	Yes___ No___	Yes___ No___	Yes___ No___
List material used					
Change in service to non-regulated substance	Yes___ No___	Yes___ No___	Yes___ No___	Yes___ No___	Yes___ No___
9. Site Assessment Completed?	Yes___ No___	Yes___ No___	Yes___ No___	Yes___ No___	Yes___ No___

VII. DESCRIPTION OF UNDERGROUND STORAGE TANKS (complete for each tank at this facility)

Tank Identification Number	Tank No. _____	Tank No. _____	Tank No. _____	Tank No. _____	Tank No. _____
Alt. Tank ID Number	Tank No. 1	Tank No. _____	Tank No. _____	Tank No. _____	Tank No. _____

10. Release Detection (mark all that apply)	TANK	PIPING	TANK	PIPING	TANK	PIPING	TANK	PIPING	TANK	PIPING
Manual tank gauging	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐
Tank tightness testing	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐
Inventory controls	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐
Automatic tank gauging	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐
Vapor monitoring	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐
Groundwater monitoring	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐
Interstitial monitoring double-walled tank/piping	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐
Statistical Inventory Reconciliation (SIR)	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐
Automatic line leak detection	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐
Line tightness testing	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐
Other method allowed (specify)	_____	_____	_____	_____	_____	_____	_____	_____	_____	_____
11. Spill and Overfill Protection										
Overfill device installed	☐		☐		☐		☐		☐	
Spill catch basin	☐		☐		☐		☐		☐	
12. Stage I Vapor Recovery	Yes___ No_____		Yes___ No_____		Yes___ No_____		Yes___ No_____		Yes___ No_____	
13. Stage II Vapor Recovery	Yes___ No_____		Yes___ No_____		Yes___ No_____		Yes___ No_____		Yes___ No_____	

VIII. CERTIFICATION OF COMPLIANCE (complete for all new and upgraded tanks at this location)

INSTALLER CERTIFICATION

I certify that the underground storage system installed, upgraded, or repaired at this facility is in compliance with all applicable regulations.

Installer: _____ _____

Print Name Signature

MDIC- _____ _____ _____

State ID Number Date Company

BA

PA Form - Facility Data as of 02 OCT 1989

acility ID Number: 3-001797
ate Received: 04/01/86

Ownership	Location
AY DEPARTMENT STORES T/A HECHT'	SECURITY MALL.
~~FI DRIVE ST.~~ 685 N. Glebe Rd	6901 SECURITY BLVD.
~~FOSSPORT.~~ Arlington Va	BALTIMORE
~~T. LOUIS~~, MS 63101 22203-2199	BALTIMORE., MD 21207

hone: (703) 558-1555

ype of Owner

Current	:X	State/Local Govt	:	Private/Corp	:X
Former	:	Federal Govt	:	Uncertain	:

SA Number:

o. of Tanks: 001 Facility located on Indian Land? No

ontact Manager: EUGENE NOLL, Title: DVP.MAINT.ENGINEER
hone: (703) 558-1555

s this an Amended or Subsequent Form? No

orm Certification
ame: LACY WOMACK. Title: VICE PRESIDENT.
ate Signed: 03/28/86

orm Status: COMPLETE

Tri County Industries
5005 Powder Mill Road
P.O. Box 1467
Beltsville, MD 20704-1467

U.S. DOT No. 384534
Maryland License No. 16-793219
Virginia License No. 2705-012615A
Maryland Oil Operations Permit No. 95-OP-0969
EPA Identification No. MDD-981104151
Federal Identification No. 52-1340142
Phone (301) 937-8611 (800) 336-8611
Fax (301) 937-9028

BILL OF LADING/MANIFEST NO. N 13020

Generator Name: ~~Hearts~~ Hecht's

Site Address: SECURITY BLVD

Billing Address: MAY - 06 TCI JOB

Business Phone: _____ Site Phone: _____

This company certifies that the materials released to Tri County Industries, Inc. do not contain Polychlorinated Biphenyls (PCB's) and have not been mixed or blended in any amount with any other hazardous materials as defined under Federal law for legal recycling or disposal. All trucks/trailers are billed at 4 hr. minimums unless otherwise quoted.

X Kelly TCI 2-16-99

Generator/Agent (Authorized Signature) Date

MATERIAL CHARACTERIZATION *(Check all that apply)*

Gasoline _____	Kerosene _____	Water _____
Diesel _____	JP#4 _____	#2 Fuel C-1993
Lube Oil _____	JP#5 _____	#4 Fuel _____
Waste Oil _____	Jet A _____	#6 Fuel _____
Other (describe) _____		
Liquid X	Soil _____	Sludge _____

HAULER IDENTIFICATION

Company Name: TRI COUNTY INC Truck # V-140

Address: 5005 POWDER MILL RD BELTSVILLE MD

Phone: 800-336-8611

No. of drums: 250 TANK No. of gallons: 3

SCALE WEIGHTS: TOTAL: _____ TARE: _____ NET: _____

Driver: (Printed Name) CARL DOWEY II

Signature Carl Dowey II

RECEIVING FACILITY AGENT

Printed Name: Shirley Waldron

Signature: Shirley Waldron

Acceptance Authorization Number: 99612

Tri County Industries
5005 Powder Mill Road
P.O. Box 1467
Beltsville, MD 20704-1467

U.S. DOT No. 384534
Maryland License No. 16-793219
Virginia License No. 2705-012615A
Maryland Oil Operations Permit No. 95-OP-0969
EPA Identification No. MDD-981104151
Federal Identification No. 52-1340142
Phone (301) 937-8611 (800) 336-8611
Fax (301) 937-9028

BILL OF LADING/MANIFEST NO. № 39901

Generator Name: Tri Lab Heath Co.
Site Address: Heath Co. Lake Forest Mall Gaithersburg, Md
Billing Address: Tri. Lab

Business Phone: _____ Site Phone: _____

This company certifies that the materials released to Tri County Industries, Inc. do not contain Polychlorinated Biphenyls (PCB's) and have not been mixed or blended in any amount with any other hazardous materials as defined under federal law for legal recycling or disposal.

Generator/Agent Authorized Signature _____ Date 01-27-99

MATERIAL CHARACTERIZATION (*Check all that apply*)

Gasoline _____ Kerosene _____ Water _____
Diesel ✓ C-1952 JP#4 _____ #2 Fuel _____
Lube Oil _____ JP#5 _____ #4 Fuel _____
Waste Oil _____ Jet A _____ #6 Fuel _____
Other (describe) PUMPED OUT LEFT OVER Rgt. in tank 300 gal.
Liquid ✓ Soil _____ Sludge _____

HAULER IDENTIFICATION

Company Name: Tri County Industries Truck # V141
Address: 5005 Powder Mill Rd. P.O. Box 1467
Beltsville, Md. 20704-1467 Phone: 1800 336-8611
No. of drums: _____ No. of gallons: Appox 10
SCALE WEIGHTS: "TOTAL: _____ TARE: _____ NET: _____
Driver: (Printed Name) Brandon D. Jones
Signature Brandon D. Jones

RECEIVING FACILITY AGENT

Printed Name: Shawn Waldron
Signature: Shawn Waldron
Acceptance Authorization Number: 997210

May 04

INVOICE #ae000456

TEST DATE: 03/18/99

ABLE ENVIRONMENTAL INC.
P.O. BOX 318
OLNEY, MD. 20832

TANK STATUS EVALUATION REPORT

***** CUSTOMER DATA *****

TRI COUNTY INDUSTRIES
P.O. BOX 1496

BELTSVILLE, MD.
20704

CONTACT: COOKSEY, TOM
PHONE #: 301-937-8611

***** SITE DATA *****

HECHT'S
6901 SECURITY BLVD.

BALTIMORE, MD.

CONTACT: NOLL, GENE
PHONE #: 703-558-1554

***** COMMENT LINES *****

CURRENT EPA STANDARDS DICTATE
THAT FOR UNDERGROUND FUEL TANKS, THE MAXIMUM ALLOWABLE LEAK/GAIN RATE
OVER THE PERIOD OF ONE HOUR IS .10 GALLONS.

TANK #1: DIESEL FUEL 1 TYPE: RATE: .010539 G.P.H. LOSS

TANK IS TIGHT.

OPERATOR: Philip Stylos SIGNATURE: [signature] DATE: 3-18-99

******* TANK DATA ********

	TANK NO. 1	TANK NO. 2	TANK NO. 3	TANK NO. 4
TANK DIAMETER (IN)	38			
LENGTH (FT)	5.62			
VOLUME (GAL)	300			
TYPE	EG			
FUEL LEVEL (IN)	28			
FUEL TYPE	DIESEL 1			
dVOL/dy (GAL/IN)	10.82			

CALIBRATION ROD	DISTANCE
1	10.65625
2	26.95313
3	41.93750
4	56.93750
5	74.93750

******* C U S T O M E R D A T A ********

JOB NUMBER	: 000456
CUSTOMER (COMPANY NAME)	: TRI COUNTY INDUSTRIES
CUSTOMER CONTACT(LAST, FIRST)	: COOKSEY, TOM
ADDRESS - LINE 1	: P.O. BOX 1496
ADDRESS - LINE 2	:
CITY, STATE	: BELTSVILLE, MD.
ZIP CODE (XXXXX-XXXX)	: 20704
PHONE NUMBER (XXX)XXX-XXXX	: 301-937-8611

******* C O M M E N T L I N E S *******

******* S I T E D A T A ********

SITE NAME (COMPANY NAME)	: HECHT'S
SITE CONTACT(LAST, FIRST)	: NOLL, GENE
ADDRESS - LINE 1	: 6901 SECURITY BLVD.
ADDRESS - LINE 2	:
CITY, STATE	: BALTIMORE, MD.
ZIP CODE (XXXXX-XXXX)	:
PHONE NUMBER (XXX)XXX-XXXX	: 703-558-1554
GROUND WATER LEVEL (FT)	: 6
NUMBER OF TANKS	: 1
LENGTH OF PRE-TEST (MIN)	: 30
LENGTH OF TEST (MIN)	: 180

INVOICE #ae000456

TEST DATE: 03/18/99

ABLE ENVIRONMENTAL INC.
P.O. BOX 318
OLNEY, MD. 20832

TANK STATUS REPORT -- ULLAGE TEST

***** CUSTOMER DATA *****

TRI COUNTY INDUSTRIES
P.O. BOX 1496

BELTSVILLE, MD.
20704

CONTACT: COOKSEY, TOM
PHONE #: 301-937-8611

***** SITE DATA *****

HECHT'S
6901 SECURITY BLVD.

BALTIMORE, MD.

CONTACT: NOLL, GENE
PHONE #: 703-558-1554

***** COMMENT LINES *****

CURRENT EPA STANDARDS DICTATE
THAT FOR UNDERGROUND FUEL TANKS, THE MAXIMUM ALLOWABLE LEAK/GAIN RATE
OVER THE PERIOD OF ONE HOUR IS .10 GALLONS.

TANK #1: DIESEL FUEL 1 TYPE: SN: .01

TANK IS TIGHT.

OPERATOR: Philip Styles SIGNATURE: DATE: 3-18-99

******* T A N K D A T A ********

	TANK NO. 1	TANK NO. 2	TANK NO. 3	TANK NO. 4
TANK DIAMETER (IN)	38			
LENGTH (FT)	5.62			
VOLUME (GAL)	300			
TYPE	EG			
FUEL LEVEL (IN)	28			
FUEL TYPE	DIESEL 1			
dVOL/dy (GAL/IN)	10.82			

CALIBRATION ROD	DISTANCE
1	10.65625
2	26.95313
3	41.93750
4	56.93750
5	74.93750

******* C U S T O M E R D A T A ********

JOB NUMBER	: 000456
CUSTOMER (COMPANY NAME)	: TRI COUNTY INDUSTRIES
CUSTOMER CONTACT(LAST, FIRST)	: COOKSEY, TOM
ADDRESS - LINE 1	: P.O. BOX 1496
ADDRESS - LINE 2	:
CITY, STATE	: BELTSVILLE, MD.
ZIP CODE (XXXXX-XXXX)	: 20704
PHONE NUMBER (XXX)XXX-XXXX	: 301-937-8611

******* C O M M E N T L I N E S *******

******* S I T E D A T A ********

SITE NAME (COMPANY NAME)	: HECHT'S
SITE CONTACT(LAST, FIRST)	: NOLL, GENE
ADDRESS - LINE 1	: 6901 SECURITY BLVD.
ADDRESS - LINE 2	:
CITY, STATE	: BALTIMORE, MD.
ZIP CODE (XXXXX-XXXX)	:
PHONE NUMBER (XXX)XXX-XXXX	: 703-558-1554
GROUND WATER LEVEL (FT)	: 6
NUMBER OF TANKS	: 1
LENGTH OF PRE-TEST (MIN)	: 30
LENGTH OF TEST (MIN)	: 180

OFFICES:
6630 BALTIMORE NATIONAL PIKE
ROUTE 40 WEST
BALTIMORE, MARYLAND 21228
410-747-8770
800-932-9047
410-788-8723 Fax
www.phaseonline.com

PHASE SEPARATION SCIENCE, INC.

ANALYTICAL CHEMISTRY • ENVIRONMENTAL SCIENCE

CERTIFICATE OF ANALYSIS

No. 99021706 Page 1 of 1

Tri-County Industries

February 18, 1999

Project: May Company
Site Location: Security Mall
Project Number: May-06
Matrix: Soil

Date Sampled: 2/16/99
Date Received: 2/17/99

	Result	Unit	Method	PQL	Prepared	Analyzed
Sample ID: May-06 #1						
Total Petroleum Hydrocarbons Diesel Range Organics	< 10	mg/kg	EPA 8015B	10	2/17/99	2/17/99
Sample ID: May-06 #2						
Total Petroleum Hydrocarbons Diesel Range Organics	19	mg/kg	EPA 8015B	10	2/17/99	2/17/99

Reviewed By: _____
Quality Assurance Chemist

Notes/Comments:
PQL - Practical Quantitation Limit

TRI COUNTY INDUSTRIES, INC.

(301) 937-8611
1-800 336-8611
Fax # 937-9028
FID 52-1340142

5005 Powder Mill Road
P.O. Box 1467
Beltsville, MD 20704-1467

March 26, 1999

May Design & Construction Co.
611 Olive Street
St. Louis, MO 63101

Attn: Steve Sobo

Re: Certification of Disposal/Treatment of NON-HAZARDOUS PETROLEUM CONTAMINATED MATERIAL originating from – **Hechts – Security Square Mall, Security Blvd. Baltimore MD**

Dear Mr. Sobo,

Tri County Industries, Inc. received a total of 13 gallons of non-hazardous TPH contaminated material from the above referenced site on **January 27, and February 16 1999.** Receipt of these shipments of NON-HAZARDOUS PETROLEUM CONTAMINATED MATERIAL is evidenced by the attached Tri County Industries bill of lading/manifests and accepted under EPA Identification No. MDD-981104151 and Maryland Oil operations Permit No. 90-OP-0969A.

This NON-HAZARDOUS PETROLEUM CONTAMINATED MATERIAL has been accepted by Tri County Industries and has been treated and discharged through our Water Treatment Facility, under the Washington Suburban Sanitary Commission Industrial and Special Waste Permit No. 07713. In this process, all light petroleum hydrocarbons are removed from the water prior to discharge. The heavily contaminated waters, by-products from our own operations, and other materials not treatable by this facility have been separated and disposed of in the following manner:

1. Free petroleum products and petroleum sludge was generated by Tri County and accepted by Eastern Oil Company in Alexandria, Virginia for recycling.
2. Water contaminated with heavier dissolved petroleum hydrocarbons was generated by Tri County and accepted by Lancaster Oil Co. in Lancaster, PA and International Petroleum Corp. in Wilmington, Delaware for treatment and disposal.

If you have any further questions or concerns please contact us at your earliest convenience at 800-336-8611.

Sincerely,

Stephen Waldron

Stephen W. Waldron
Disposal/Project Coordinator

SWW/clm
cc: Project File/Invoice

TRI COUNTY INDUSTRIES, INC.

(301) 937-8611
1-800 336-8611
Fax # 937-9028
FID 52-1340142

5005 Powder Mill Road
P.O. Box 1467
Beltsville, MD 20704-1467

March 26, 1999

May Design and Construction Co.
611 Olive Street
St. Louis, MO 63101

Attn: Steve Sobo

RE: Certification of Tank Disposal originating from – Hechts, Security Square Mall, 6901 Security Blvd. Baltimore MD

Dear Mr. Sobo,

This is to certify that **one (1) 300** gallon steel underground storage tank was removed from the above referenced site on **February 17, 1999.** This steel tank was taken to our tank dismantling yard located in Lothian, Maryland, where it was purged and treated with No-Flash, a chemical to control flammability. The tank was then disassembled via use of our Plasma Arc Cutting Machine, and all scrap steel was taken to either Super Salvage of Washington, DC, J. Smith & Sons of Washington, DC, Montgomery Scrap Corporation in Rockville, Maryland or Prince George's Scrap, Inc., in Berwyn Maryland for recycling.

If you have any questions or concerns, please feel free to contact me.

Sincerely,

Stephen Waldron

Stephen W. Waldron
Disposal/Project Manager

SWW/clm
cc: Project File/Invoice

Fax to Jackie Ryan 410-337-3092 For

TRI COUNTY INDUSTRIES, INC.

(301) 937-8611
1-800 336-8611
Fax # 937-9028
FID 52-1340142

5005 Powder Mill Road
P.O. Box 1467
Bellsville, MD 20704-1467

LETTER OF TRANSMITTAL

To: The May Company
Attn: Steve Sobo
611 Olive Street
St. Louis, Missouri 63101-1799

Date: April 12, 1999

Phone 314-342-6770
Fax 314-342-6580

Re: ***Hecht Company***
Security Square Mall
6901 Security Blvd.
Baltimore, MD

Site Activity Report:

On December 15, 1999 we began the replacement of the existing tank. A temporary tank was installed to supply the generator while the construction work was in progress. No permit was required for this project. One inspection from the Maryland Department of the Environment was required. The inspector was satisfied with the project and no further work was required. However, he did order soil samples be tested and no contamination above regulated limits was detected. The soils did have a slight petroleum odor.

The new tank system at this site is a double-wall Stip-3 cathodicly protected tank with double-wall enviro-flex piping and total containment piping. The system has over fill, and over spill equipment, tank monitoring pipes in the tank field and electric leak detection. All excavated areas were backfilled with #8 pea stone to meet the maufacturers and state regulations. The tank and system were tightness tested and are tight.

The tank at this site was originally thought to be 500-gallons, however it turned out to be 300-gallons. If I can be of further assistance please feel free to call.

Sincerely,

Glenn D. Selzer
Tri County Industries

NOTIFICATION FOR UNDERGROUND STORAGE TANKS

Return completed form to:

Maryland Department of the Environment
Oil Control Program
2500 Broening Highway
Baltimore MD 21224

****

TYPE OF NOTIFICATION: (check one)

~~☐ New Facility~~ ~~☒ Amended~~ ☐ Closure

1 Number of tanks at facility
~~0~~ Number of continuation sheets attached

State Use Only
Facility ID Number 6-26715-A
Alt ID Number
Date Entered into Computer 6/2/99
Data Clerk's Initials TK
Owner Contacted to Clarify Response
Comments

I. OWNERSHIP INFORMATION:

Owner ID: 7665

Owner Name: HECHT DEPARTMENT STORE.
Street Address: 701 N. GLEBE ROAD
Mailing Address (if different from above):
ARLINGTON, VIRGINIA 22203
City State Zip Code
ARLINGTON County
County:
(703) 558-1554
Phone Number:
Contact Person: GENE NOLL

Amend Cert.
could not find T/R (BA) folder
mk 6/2/99

II. LOCATION OF TANK(S)

Facility Name or Company Site Identifier as applicable: HECHT DEPARTMENT STORE — SECURITY SQ MALL
Street Address: 6901 SECURITY BOULEVARD
Mailing Address (if different from above):
BALTIMORE, MARYLAND
City State
21207 Zip Code
BALTIMORE County
Phone Number: (703) 558-1554
Facility Operator: GENE NOLL

RECEIVED
MAR 29 1999
OIL CONTROL PROGRAM

MDE 231 (rev. 12/96)

III. TYPE OF FACILITY: (check one)

___ Federal Non-Military	___ Gas Station	___ Private Home
___ Federal Military	___ Petroleum Distributor	___ Apt. / Condo
___ Educational	___ Trucking / Transport	___ Farm / Nursery
___ Fire/Rescue/Ambulance	___ Industrial	___ Marina
___ Public Service	___ Contractor	X Store
___ Utilities	___ Airline	___ Office
___ Railroad	___ Auto Dealership	___ Other_____

IV. CONTACT PERSON IN CHARGE OF TANKS

Name: GENE NOLL Job Title: PROJECT MGR

Address: S/A # 1 Phone Number: (703-508-1554

V. FINANCIAL RESPONSIBILITY (if applicable - see instruction sheet)

I have met the financial responsibility requirements in accordance with 40 CFR Part 280, Subpart H

☐ YES ☐ No

___ Commercial Insurance
Policy # Insurance
Insurer_____
Agent/Broker_____
Phone No._____

___ Self Insurance
___ Insurance Pool
___ Risk Retention Group
___ Guarantee

___ Letter of Credit
___ Surety Bond
___ Other method allowed
(specify)_____

VI. CERTIFICATION (to be completed by owner or owner's representative)

I certify, under penalty of law, that I have personally examined, and am familiar with, the information submitted in this and all attached documents, and that the information provided is in compliance with COMAR 26.10.03, and is true, accurate, and complete.

Name (print/type): X Eugene M Noll Title (print/type): X Dvp Manufacturing

Signature: X Eugene M Noll Date Signed: X 3-25-99

VII. DESCRIPTION OF UNDERGROUND STORAGE TANKS (complete for each tank at this facility)

Tank Identification Number	Tank No.____	Tank No.____	Tank No.____	Tank No.____	Tank No.____
Alt. Tank ID Number	Tank No. 1	Tank No. 2	Tank No.____	Tank No.____	Tank No.____
1. Status of Tank (Mark only one)					
Currently in Use		X			
Temporarily Out of Use					
Permanently Out of Use	X				
2. Date of Installation (mo/yr)	UNKNOWN	2-17-99			
3. Total Capacity (gallons)	300	300			
4. Material of Construction (mark all that apply)					
Asphalt Coated or Bare Steel	X				
Cathodically Protected Steel					
Composite (Steel w/ Fiberglass)		X			
Concrete					
Fiberglass Reinforced Plastic					
Polyethylene Tank Jacket					
Unknown					
Other (specify)					
Has tank been repaired?	Yes___ No X	Yes___ No X	Yes___ No___	Yes___ No___	Yes___ No___
Double-walled		X			
Excavation Liner					
Lined Interior					
5. Piping (material) (mark all that apply)					
Bare Steel	X				
Galvanized Steel					
Fiberglass Reinforced Plastic					
Copper	X				
Flexible Plastic		X			
Unknown					
Other (specify)					
Cathodically Protected					
Double-walled		X			
Secondary Containment					

VII. DESCRIPTION OF UNDERGROUND STORAGE TANKS (complete for each tank at this facility)

Tank Identification Number	Tank No.____	Tank No.____	Tank No.____	Tank No.____	Tank No.____
Alt. Tank ID Number	Tank No. 1	Tank No. 8	Tank No.____	Tank No.____	Tank No.____
6. Piping (Type) (mark all that apply)					
Pressure					
Gravity Feed					
Suction: no valve at tank (Safe Suction)		X			
Suction: valve at tank (U.S. Suction)	X				
Has piping been repaired?	Yes___ No X	Yes___ No X	Yes___ No___	Yes___ No___	Yes___ No___
7. Substance Currently or Last Stored					
Gasoline					
Diesel	X	X			
Gasohol					
Kerosene					
Heating Oil					
Used Oil					
Hazardous Substance CERCLA name and/or CAS #					
Other, please specify	N/A	N/A			
Mixture of Substances Please specify					
8. Closing of Tank					
Estimated date last used (mo/day/yr)	2, 16, 99	/ /	/ /	/ /	/ /
Date tank closed (mo/day/yr)	2, 16, 99	/ /	/ /	/ /	/ /
Tank was removed from ground	Yes X No___	Yes___ No___	Yes___ No___	Yes___ No___	Yes___ No___
Tank filled with inert material	Yes___ No___	Yes___ No___	Yes___ No___	Yes___ No___	Yes___ No___
List material used					
Change in service to non-regulated substance	Yes___ No X	Yes___ No___	Yes___ No___	Yes___ No___	Yes___ No___
9. Site Assessment Completed?	Yes___ No X	Yes___ No___	Yes___ No___	Yes___ No___	Yes___ No___

VII. DESCRIPTION OF UNDERGROUND STORAGE TANKS (complete for each tank at this facility)

Tank Identification Number	Tank No _____		Tank No _____		Tank No _____		Tank No _____		Tank No _____	
Alt. Tank ID Number	Tank No 2		Tank No _____		Tank No _____		Tank No _____		Tank No _____	
10. Release Detection (mark all that apply)	TANK	PIPING	TANK	PIPING	TANK	PIPING	TANK	PIPING	TANK	PIPING
Manual tank gauging	✓									
Tank tightness testing	✓									
Inventory controls										
Automatic tank gauging										
Vapor monitoring										
Groundwater monitoring	✓									
Interstitial monitoring double-walled tank/piping										
Statistical Inventory Reconciliation (SIR)										
Automatic line leak detection										
Line tightness testing		✓								
Other method allowed (specify)										
11. Spill and Overfill Protection										
Overfill device installed	2-17-99									
Spill catch basin	2-17-99									
12. Stage I Vapor Recovery	Yes___ No___		Yes___ No___		Yes___ No___		Yes___ No___		Yes___ No___	
13. Stage II Vapor Recovery	Yes___ No___		Yes___ No___		Yes___ No___		Yes___ No___		Yes___ No___	

VIII. CERTIFICATION OF COMPLIANCE (complete for all new and upgraded tanks at this location)

INSTALLER CERTIFICATION

I certify that the underground storage system installed, upgraded, or repaired at this facility is in compliance with all applicable regulations.

Installer: Kevin Bradshaw — KEVIN BRASHEARS

Print Name — Signature

MDIC- 98-1570 — 2/28/99 — _____

State ID Number — Date — Company

TRI COUNTY INDUSTRIES, INC.
P.O. Box 1467
5005 Powder Mill Road
Beltsville, MD 20705

MDE

MARYLAND DEPARTMENT OF THE ENVIRONMENT

2500 Broening Highway • Baltimore Maryland 21224
(410) 631- 3000 • 1- 800 -633-6101 • http:// www. mde. state. md. us

Parris N. Glendening
Governor

Jane T. Nishida
Secretary

June 30, 1999

Mr. Eugene M. Noll
Hecht's Department Store
702 N. Glebe Road
Arlington, VA 22203

RE: Underground Storage Tank Registration
Facility ID #0006267
6901 Security Blvd.
Baltimore, Maryland

Dear Mr. Noll:

Per documentation received in reference to the underground storage tank at 6901 Security Boulevard, Baltimore, Maryland, enclosed you will find your amended Certificate of Registration. This replaces the Certificate of Registration dated July 20, 1998. As the owner of the listed underground storage tank systems, it is your responsibility to forward a copy of the enclosed certificate to the corresponding facilities. Each facility should display this certificate for delivery of product into their tanks. Maryland Law prohibits the delivery of product to an unregistered tank (Environment Article Section 4-411.1).

If you have any questions concerning this matter, please feel free to telephone the Office of Resource Management at (410) 631-3433.

Sincerely,

Cynthia Keller, Chief
Office of Resource Management
Oil Control Program

CK:ms
Enclosure

cc: Mr. Richard Collins

Parris N. Glendening
Governor

Jane T. Nishida
Secretary

Facility No. 0006267

Richard W. Collins, Director
Waste Management Administration

Horacio Tablada, Adminstrator
Oil Control Program

State of Maryland

Department of the Environment
Waste Management Administration

Oil Control Program
UNDERGROUND STORAGE TANK FACILITY
CERTIFICATE OF REGISTRATION

Issued: June 30, 1999

This certifies that **May Department Stores T/A Hecht's**

has duly registered its underground storage tank system(s) with the State of Maryland, Department of the Environment as required by Environment Article Section 4-411.1, *Annotated Code of Maryland* for the following location:

Facility Address:

Hecht's
6901 Security Blvd.
Baltimore, MD 21207

Cynthia F. Keller, Chief
Office of Resource Management
Oil Control Program

This certificate authorizes the use of the listed underground storage tank system(s) only in accordance with Code of Maryland Regulations (COMAR) 26.10.

The following tank(s) have been duly registered at the above facility:

TANK NUMBER	STATUS	DESCRIPTION	SUBSTANCE STORED	CLOSURE STATUS
001	Currently In Use	250 gal.	Diesel	
002	Permanently Out of Use	300 gal.	Diesel	Tank removed from ground

MAY

The May Department Stores Company

April 15, 2003

To Whom It May Concern:

Re: Financial Test of Self-Insurance for Underground Storage Tanks of The May Department Stores Company Pursuant To 40 CFR §280.95

I am the Chief Financial Officer of The May Department Stores Company, 611 Olive Street, St. Louis, Missouri 63101. This letter is in support of the use of the financial test of self-insurance to demonstrate financial responsibility for taking corrective action and compensating third parties for bodily injury and property damage caused by sudden accidental releases and non-sudden accidental releases in the amount of at least ONE MILLION DOLLARS ($1,000,000.00) per occurrence and ONE MILLION DOLLARS ($1,000,000.00) annual aggregate arising from operating underground storage tanks.

Underground storage tanks at the following facilities are assured by this financial test or a financial test under an authorized State program by this owner or operator:

See Exhibit A attached.

A financial test is also used by this owner or operator to demonstrate evidence of financial responsibility in the following amounts under other EPA regulations or state programs authorized by EPA under 40 CFR Parts 271 and 145:

EPA Regulations:	**Amount**
Closure (§§264.143 and 265.143)	$ -0-
Post-Closure Care (§§264.145 and 265.145)	$ -0-
Liability Coverage (§§264.147 and 265.147)	$ -0-
Corrective Action (§264.101(b))	$ -0-
Plugging and Abandonment (§144.63)	$ -0-
Closure	$ -0-
Post-Closure Care	$ -0-
Liability Coverage	$ -0-
Corrective Action	$ -0-
Plugging and Abandonment	$ -0-
TOTAL	$ -0-

This owner or operator has not received an adverse opinion, a disclaimer of opinion, or a "going concern" qualification from an independent auditor on its financial statements for the latest completed fiscal year.

Alternative I

1.	Amount of annual UST aggregate coverage being assured by a financial test, and/or guarantee	$ 1,000,000
2.	Amount of corrective action, closure and post-closure care costs, liability coverage, and plugging and abandonment costs covered by a financial test, and/or guarantee	$ -0-
3.	Sum of lines 1 and 2.	$ 1,000,000
4.	Total tangible assets	$10,209,000,000
5.	Total liabilities [if any of the amount reported on line 3 is included in total liabilities, you may deduct that amount from this line and add that amount to line 6]	$7,788,000,000
6.	Tangible net worth [subtract line 5 from line 4]	$2,421,000,000

		Yes	No
7.	Is line 6 at least $10 million?	X	
8.	Is line 6 at least 10 times line 3?	X	
9.	Have financial statements for the latest fiscal year been filed with the Securities and Exchange Commission?	X	
10.	Have financial statements for the latest fiscal year been filed with the Energy Information Administration?		X
11.	Have financial statements for the latest fiscal year been filed with the Rural Electrification Administration?		X
12.	Has financial information been provided to Dun and Bradstreet, and has Dun and Bradstreet provided a financial strength rating of 4A or 5A? [Answer "Yes" only if both criteria have been met.]	X	

EXHIBIT A

This financial test of self-insurance covers all petroleum underground storage tanks for which financial responsibility must be demonstrated pursuant to 40 CFR §280.90 and which are owned or operated by The May Department Stores Company in the United States. Specific site or facility information can be obtained at the Company's headquarters at 611 Olive Street, St. Louis, Missouri 63101, Attention: Mr. Steven S. Sobo, Environmental Projects Director.

I hereby certify that the wording of this letter is identical to the wording specified in 40 CFR Part 280.95(d) as such regulations were constituted on the date shown immediately below.

THE MAY DEPARTMENT STORES COMPANY

/s/

By: Thomas D. Fingleton

Thomas D. Fingleton
Chief Financial Officer
April 18, 2003

Compliance Check List

Supervisor Sign Off Reed

Inspector Jackie

Facility ID 6267

Follow Up Required: Yes [X] No [ ]

Enforcement Action: (Circle One)

Administrative Order	NOV	Report of Observations
Field Citation	NOVP	(Routine Site Inspection)
None	Written Warning	

Comments:
- UST Registered as 250 gallon 24 years
- Personnel on-site indicate tank 300 gallon 3 yrs old

Number of Oustanding Violations 6 See back of form

Due Date for Violation 30

Groundwater Usage	CP Met	Overfill	Spill	Financial Responsibility
Yes [ ] No [X]	Yes [ ] No [X]	Yes [ ] No [X]	Yes [X] No [ ]	Yes [ ] No [X]

Leak Detection on Tank

Manual Tank Gauging	[ ]	Tank Tightness Testing	[ ]	Inventory Controls	[ ]
Vapor Monitoring	[ ]	Groundwater Monitoring	[ ]	Automatic Tank Gauging	[ ]
SIR	[ ]	Interstitial Monitoring Double Walled	[ ]	Other	[ ]
None	[X]				

If SYSTEM NOT BEING USED PLEASE MARK [ ]

Leak Detection on Piping

Line Tightness Testing	[ ]	Automatic Line Leak Detection	[ ]	Other	[ ]
Vapor Monitoring	[ ]	Groundwater Monitoring	[ ]	None	[X]
SIR	[ ]	Interstitial Monitoring Double Walled	[ ]		

If SYSTEM NOT BEING USED PLEASE MARK [ ]

COMAR

Violations Listed Below Begin with "Failure to"

	Report Spill		26.10.01.03B.
	Install Vapor Recovery Stage I	NFPA 30 2-4.6.6	26.10.02.06A.
	Protect Dispenser from Vehicle Traffic - Install Ballards	NFPA 30 4-2.5	26.10.02.06A.
X	Install Drop Tube	NFPA 30 2-3.8.4	26.10.02.06A.
	Install Emergency Hose Breakaway	NFPA 30A 4-2.7	26.10.02.06B.
	Install or Secure Shear Valves	NFPA 30 A 4-3.6	26.10.02.06B.
	Provide Dispenser Emergency Power Cut-off	NFPA 30A 4-1.1	26.10.02.06B.
	Properly Identify Emergency Power Cut-off	NFPA 30A 4-1.2	26.10.02.06B.
	Provide Spill Prevention		26.10.03.03A.(1)
X	Provide Overfill Prevention		26.10.03.03A.(2)
	Properly Constuct Tank Field Monitoring Pipe		26.10.03.04B.
	Tightness Test New or Upgraded System		26.10.03.05A.
X	Provide Precision Test Records		26.10.03.05B.
	Protect Vent Pipe from Traffic		26.10.03.06H.
	Install (Flammable Liquids) Vent Pipe to 12 Feet Above Ground Surface		26.10.03.06I.
	Install (Combusitble Liquids) Vent Pipe to 3 Feet Above Ground Surface		26.10.03.06J.
	Upgrade UST Systems		26.10.03.08A.
	Upgrade Tank Systems		26.10.03.08B.
	Upgrade Piping Systems		26.10.03.08C.
X	Register UST		26.10.03.09A.C.
	Keep Catch Basins Clean & Dry		26.10.04.01B.
	Maintain Daily Inventory Records & Reconcile each 30 days		26.10.04.01E.
	Tightness Test at 15 Years Age		26.10.04.01J.
	Tightness Test at 5 Year Schedule		26.10.04.01J.(2)
	Properly Mark Fill Pipe		26.10.04.01N.
	Operate & Maintain Corrosion Protection System		26.10.04.02B.
X	Maintain Corrosion Protection Records		26.10.04.05C.(2)
	Provide Release Detection for Tanks & Piping		26.10.05.02A.
	Provide Release Detection for Tank		26.10.05.02B.
	Provide Release Detection for Piping		26.10.05.02D.
	Install Auto Line Leak Detector (Pressurize Piping) or test annually		26.10.05.02D.(2)(a)
	Test Pressurized Piping Annually		26.10.05.02D(2)(b)
	Test Suction Pipe every 2 years		26.10.05.02D.(3)
	Provide proof a single check valve is located below dispenser (suction piping)		26.10.05.02D.(3)(d)
	Provide Release Detection Records		26.10.05.06
	Report leaking system, failed tightness test or 2 consecutive in conclusive test		26.10.08.01A.
	Close a substandard that is temporarily closed more than 6 months		26.10.10.01C.
	Close a UST system that meets performance and upgrade requirements temporarily closed for 1 year		26.10.10.01D.
	Notify Department 30 Days prior to beginning UST Abandonment		26.10.10.02A.
	Perform UST Change in Service Site Assessment		26.10.10.03A.
X	Provide Proof of UST Financial Responsibility		26.10.11.01A.

26.

	Discharge, Spill From UST System		26.10.02.01A.
	Surface Discharge, Spill From AST & Housekeeping		26.10.02.02A.

ROUTINE SITE INSPECTION

Maryland Department of the Environment
Waste Management Administration
2500 Broening Highway, Baltimore, Maryland 21224
(410) 631-3442

Date: 9/11/03

Time In: _____

Time Out: _____

Site Name Hecht's (Security Square) Facility # 6267

Address 6901 Security Blvd Baltimore 21207 Case # 04-0455BA1

System owner/operator May Department Stores T/A OPEN CLOSE

Address 685 N. Glebe Rd Arlington VA 22203 INITIAL FOLLOW-UP

1. System(s) registered? YES ☑ NO ☐
   If YES, facility # is 6267.
   If NO, ☐ REGISTER SYSTEM(S) WITHIN _____ DAYS AS ORDERED BY THIS ADMINISTRATION.
2. System(s) insured? YES ☐ NO ☐ UNKNOWN ☑
3. Type of facility? Motor Fuel: ☐ Commercial ☐ Private ☐ Other: _____
   ☐ Heating Oil ☐ Transfer facility/bulk plant Emergency Generator
4. Proper inventory records? YES ☐ NO ☐
   Action taken: Gauging records not verified.

Tank #	Type of Product	Age (Yrs)	Size gallons	Type of Tank	Type of Pipe	System Tested? (Y/N)	If Yes, Test Type	Leak Detection? (Y/N)	If Yes, Type	Type of Pumps (Circle)
1	diesel	registered 24	registered 250	UNK	copper	UNK		N NA		Suction or Submerged
		per original invoice 3	sign indicates 300							Suction or Submerged
										Suction or Submerged
										Suction or Submerged
										Suction or Submerged

5. Any abandoned tanks? YES ☑ NO ☐
   How many? 1
   Were they properly abandoned? YES ☐ NO ☐ According to regs.
   If YES: Method of abandonment? _____
   If NO: ☐ PROPERLY ABANDON TANK(S) WITHIN _____ DAYS IN COMPLIANCE WITH COMAR _____
6. Proper housekeeping? YES ☑ NO ☐
   Comment: _____
7. Monitoring pipes/wells present? YES ☐ NO ☑
   If NO: ☐ CONSTRUCT MONITORING PIPES ON SITE WITHIN _____ DAYS IN COMPLIANCE WITH COMAR _____
   ☐ MONITORING PIPES NOT REQUIRED AT THIS TIME.
   If YES: How many? ___ Labelled properly? YES ☐ NO ☐ Locked? YES ☐ NO ☐ Properly constructed? YES ☐ NO ☐
   If NO to any of these, comment: _____
8. Were monitoring pipes/wells checked for presence of petroleum contamination? YES ☐ NO ☐
   Comment on method and results: _____
9. Vapor recovery system present? YES ☐ NO ☑
   Comment: _____

ROUTINE SITE INSPECTION

Case # 04-0455 BA1
FAC 6267

10. Vents: Proper location? YES ☑ NO ☐
Proper height? YES ☑ NO ☐
Protected from traffic? YES ☑ NO ☐
Protected from weather? YES ☑ NO ☐
If NO to any, requirements/comments: _____

11. Is cathodic protection present? YES ☑ NO ☐
If NO, is upgrade required? YES ☐ NO ☐
If YES, is test station present? YES ☑ NO ☐
When was it last checked? _____
Were cathodic protection records kept? YES ☐ NO ☐ UNK
☐ REQUIRE RECORDKEEPING FROM THIS POINT ON BY ORDER OF THIS ADMINISTRATION.
Comments: _____

12. Are spill catch basins installed? YES ☑ NO ☐
If NO, are they required to be installed? YES ☐ NO ☐
Comments: _____
If YES, are they properly maintained? YES ☑ NO ☐

13. Fills properly marked? YES ☐ NO ☐ UNK- tank size discrepancy
☑ PROPERLY MARK FILLS WITHIN 30 DAYS IN COMPLIANCE WITH COMAR _____.
Comments: _____

14. Overfill protection present? YES ☐ NO ☐ UNK- No alarm, No flapper valve
If NO, is upgrade required? YES ☐ NO ☐
If YES, type _____

15. Are fill drop tubes present? YES ☐ NO ☑ NOT NEEDED ☐ (2" fill riser)

16. ACTIONS REQUIRED BY THIS ADMINISTRATION: SEE NUMBER(S) _____

17. Additional comments:
Hecht's POC - Mr. George Weaver 410-6122955 fax 4106122952
A notice of violation with requirements will be faxed separately,

Inspector's name (printed) and signature: Jackie Ryan

Contact person's name (printed) and signature: FAXED TO MR. WEAVER

PHOTOS TAKEN ☐ ADDITIONAL COMMENTS PAGE ☐ SITE SKETCH ☐

[redacted]

Owner Name and Address: May Department Stores T/A Hecht's 685 N. Glebe Road, Arlington, VA 22203

[redacted]

6267	Hecht's	6901 Security Blvd.	Baltimore	21207

Tank ID	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	[redacted]	FR Met
001 Currently In Use	5/1/1979 24	Diesel 250	Asphalt Coated or Bare Steel None	Galvanized Steel None	Safe Suction	A B C D E F G H I J K L B D E F G H I J K Q	No No No No
002 Permanently Out of Use		Diesel 300	Asphalt Coated or Bare Steel None	Bare Steel None	U.S. Suction	A B C D E F G H I J K L B D E F G H I J K Q	No No No No

no open cases 33B9

04-0455BA1

Tank/Piping Release Detection Codes

A	Manual Tank Gauging	C	Inventory Control	E	Vapor Monitoring	G	Interstit. Dbl-Wall Monitor	I	SIR	K	Deferred
B	Tank/Line Tightness Testing	D	ATG/Auto Line LD	F	GW Monitoring	H	Interstit. Sec. Con. Monitor	J	Other Methods	L	Not Listed

Report Generation Date: 9/3/2003

MDE

MARYLAND DEPARTMENT OF THE ENVIRONMENT

Oil Control Program, Suite 620, 1800 Washington Boulevard, Baltimore MD 21230-1719
410-537-3442 • 410-537-3092 (fax) 1-800-633-6101, ext. 3442

Robert L. Ehrlich, Jr.
Governor

Michael S. Steele
Lt. Governor

Kendl P. Philbrick
Acting Secretary

January 5, 2004

CERTIFIED MAIL

The Corporation Trust, Inc.
300 East Baltimore Street
Baltimore MD 21202

RE: Notice of Violation NV-2004-033
Case No. 2004-0455 BA1
Hecht's (Security Square Mall)
6901 Security Boulevard
Baltimore, Maryland
Facility I.D. No. 0006267

Dear Sir or Madam:

On September 11, 2003, Inspector Jackie Ryan of the Oil Control Program conducted a compliance inspection of the underground storage tank (UST) system at the above-referenced property in Baltimore County. In April 1997, May Department Stores, t/a Hecht's, registered with the Department a 250-gallon diesel UST system, installed in 1979, as "currently in use." During the compliance inspection, Inspector Ryan determined the following:

- Site personnel indicated that the only UST system in use is 300 gallons in capacity which was installed 3 years ago;
- Proof of pollution financial responsibility insurance was not available for review;
- Precision test records were not available for review;
- The copper supply line is not sleeved or wrapped (protected from corrosion) as it enters the building;
- An approved method of overfill protection is not present; and
- A drop tube is not installed.

The aforementioned findings constitute violations of Maryland law, specifically, Code of Maryland Regulations (COMAR) 26.10.02.06A, 26.10.03.05B, 26.10.03.09C, 26.10.04.01J, 26.10.04.05C, and 26.10.11.01A. Based on these violations, the Waste Management Administration hereby informs May Department Stores, t/a Hecht's, that the following corrective actions must be performed within thirty (30) days of receipt of this Notice:

(1) Register the 300-gallon UST system with the Department using the enclosed notification form.

(2) Properly abandon the 250-gallon diesel UST by removal in compliance with COMAR 26.10.10.01-.03. Notify the Oil Control Program at least 72 hours prior to removal. A Maryland-certified UST remover or technician must close the storage system. If the 250-gallon diesel UST system has been removed, submit to the Oil Control Program a copy of the closure assessment report.

(3) Submit to the Oil Control Program documentation of tank material and copies of precision test results and cathodic protection test records.

(4) Submit to the Oil Control Program documentation from a Maryland-certified UST technician that the 300-gallon UST system, including tank and lines, are protected from corrosion.

(5) Properly mark the fill indicating capacity and product stored; and

(6) Install a drop tube in the fill pipe.

All information, data, reports or plans generated for this site must be submitted to the Oil Control Program within thirty (30) days after completion of Items 1 thru 6. Please note that all remediation activities must be approved by the Department prior to implementation, discontinuance, or temporary shutdown.

Failure to perform the advised corrective actions could result in additional enforcement proceedings from the Department, which could include the issuance of civil penalties and other legal sanctions. If you have any questions, please contact the Oil Control Program at 410-537-3442.

Sincerely,

for Thomas Walter

Thomas L. Walter, Region II Section Head
Compliance/Remediation Division
Oil Control Program

JLR/nln

Enclosure

cc: Mr. George Weaver, Hecht's
Yolande J.C. Norman
Mr. Gregory Sonberg
Mr. Jonas Jacobson

HECHT'S / strawbridge's

A DIVISION OF MAY DEPARTMENT STORES

685 NORTH GLEBE ROAD
ARLINGTON VIRGINIA 22203
FAX 703.247.2328

STORE PLANNING & DESIGN
FAX COVER SHEET

TO: Mr. Thomas L. Walter
MD Dept of Environmental
Oil Control Division
Fax 410-537-3092

FROM: Gene Noll
PHONE: 703-558-1559
DATE: 1-21-04
SUBJECT: Hecht's Security-Mall
300 gal Fuel Tank

ENCLOSED: INFO Required

The Letter of Self-Insurance was signed By May's Legal Counsel - I will Fax a Copy of Self Ensurance may Take when The CFO Returns From being out of Town

MESSAGE: To Sign The Self-Insurance Letter

cc Tom Cooksey 301-937-9028
Charles Miller MAY 314-342-3066

OF PAGES: 12

HECHT'S
strawbridge's
DIVISIONS OF THE MAY DEPARTMENT STORES COMPANY

-1999-

Executive Office

January 21, 2004

Mr. Thomas L. Walter
Compliance/Remediation Division
MD Dept. Of the Environment
Oil Control Division
Suite 620
1800 Washington Blvd.
Baltimore, MD 21224

RE: Notice of Violation NV-2004-033
Case # 2004-0455 BA-1 (Hecht's Security Square Mall)
Facility ID # 0006267

Dear Mr. Walter,

As per our phone conversation with Mr. Tom Cooksey of Tri-County, listed and enclosed is the following requested information:

1. Identification sign on wall states 300 gallon diesel fuel colors are yellow background with black letter.

   Fill cap is painted yellow.

   Test cap is white with raised letter stating "Test".

2. Tank is a 30-year warranty double wall composite type made by Highland.

3. The piping is double wall Enviro-Flex piping.

4. Hecht's, a division of May Department Stores Company, is self-insured (enclosed is a copy of the insurance information. Please note, this letter of self-insurance is not signed. The CFO for the company is out of town. A signed copy will be faxed to you next week).

5. Copy of Able Environmental Inc. Tank Status Evaluation Report (enclosed are 6 pages dated 3/18/99).

6. The tank is equipped with over fill protection and a vent whistle.

685 North Glebe Road
Arlington, Virginia 22203-2199

If more information is required other than supplied by this letter and Tri-County, please contact me at 703-558-1554 or fax 703-247-2328.

Thank you for your assistance in this matter.

Sincerely,

E. M. Noll

Eugene M. Noll
Hecht's
DVP Maintenance Engineer

cc: Tom Cooksey, Tri-County
Charles Miller, May Dept. Stores Company, Legal
John Harper, CFO/SVP Finance
Bob Finney, Energy Manager

MDE

MARYLAND DEPARTMENT OF THE ENVIRONMENT
Oil Control Program, Suite 620, 1800 Washington Blvd., Baltimore MD 21230-1719
410-537-3442 • 410-537-3092 (fax) 1-800-633-6101

Robert L. Ehrlich, Jr.
Governor

Michael S. Steele
Lt. Governor

Kendl P. Philbrick
Acting Secretary

January 28, 2004

Mr. Steven S. Sobo
Environmental Projects Director
The May Department Stores Company
611 Olive Street
St. Louis MO 63101

RE: Underground Storage Tank (UST) Facilities
Owned and Operated in Maryland

Dear Mr. Sobo:

The enclosed Notice of Violation (NV-2004-033, Case No. 2004-0455-BA1) was issued on January 5, 2004. One of the requirements in this NV was to provide to the Maryland Department of the Environment proof of financial responsibility. This information was satisfactorily provided with one exception. The letter from the Chief Financial Officer provides only a general statement in "Exhibit A" that all petroleum USTs owned by May Department Stores Company are covered by the financial test.

Please provide a list of all Maryland facilities having USTs covered by this financial test. This list shall include the name and address of each facility and the capacity and fuel type of each UST at these facilities.

If you have any questions, please contact me at 410-537-3386.

Sincerely,

Gregory E. Sonberg, Acting Administrator
Oil Control Program

GES/nln

Enclosure

cc: Yolande J.C. Norman
Mr. Jonas A. Jacobson

Maryland Department of the Environment
Waste Management Administration

1800 Washington Boulevard, Suite 620
Baltimore MD 21230-1719
(410) 537-3442

Case No.: 2004-0455 BA1

Report of Observations

Facility I.D. No.: 6267

Type of Inspection/Observation: File Update Date: January 28, 2004

Facility Name: Hecht's; 6901 Security Boulevard; Baltimore 21207

Remarks:

I spoke with Mr. Tom Cooksey of Tri-County Industries (800-336-8611) concerning the emergency generator tank at the above referenced facility. Mr. Cooksey stated that the double wall composite underground storage tank was installed in 1999 by Tri-County Industries following the removal of a 300-gallon underground storage tank. Mr. Cooksey also stated that the tank now in service is equipped with a drop tube and vent whistle. In addition, Mr. Cooksey said that the product line is flexible plastic that converts to copper at the building.

The registration file was reviewed. Two underground storage tanks are registered for the facility. A 300-gallon UST was removed on February 16, 1999 and a 300-gallon UST was installed on February 17, 1999 according to the file. A case file or tank removal form does not exist for the removal in 1999.

Documentation was received indicating that the Hecht Company is self-insured.

Observer: Jackie Ryan

MARYLAND DEPARTMENT OF THE ENVIRONMENT
1800 Washington Boulevard – Suite 620 • Baltimore MD 21230
410-537-3442 • 1-800-633-6101

Robert L. Ehrlich, Jr.
Governor

Kendl P. Philbrick
Acting Secretary

Michael S. Steele
Lt. Governor

February 18, 2004

May Department Stores
T/A Hecht's
702 N. Glebe Road
Arlington VA 22203

RE: Underground Storage Tank Registration
Facility ID #6267
6901 Security Boulevard
Baltimore, Maryland

Dear Sir or Madam:

Per documentation received in reference to the underground storage tank at 6901 Security Boulevard, Baltimore, Maryland, enclosed you will find your amended Certificate of Registration. This replaces the Certificate of Registration dated June 30, 1999. As the owner of the listed underground storage tank systems, it is your responsibility to forward a copy of the enclosed certificate to the corresponding facilities. Each facility should display this certificate for delivery of product into their tanks. Maryland Law prohibits the delivery of product to an unregistered tank (Environment Article Section 4-411.1).

If you have any questions concerning this matter, please feel free to telephone the Office of Resource Management at (410) 537-3433.

Sincerely,

Shirley Fairbank

Shirley Fairbank, Chief
Office of Resource Management
Oil Control Program

SF:ms
Enclosure

cc: Mr. Jonas Jacobson

Robert L. Ehrlich, Jr.
Governor

Kendl P. Philbrick
Acting Secretary

Jonas A. Jacobson, Director
Waste Management Administration
Greg Sonberg, Acting Administrator
Oil Control Program

Facility No. 0006267

State of Maryland

Department of the Environment
Waste Management Administration

Oil Control Program
UNDERGROUND STORAGE TANK FACILITY
CERTIFICATE OF REGISTRATION

Issued: February 18, 2004

This certifies that **May Department Stores T/A Hecht's**

has duly registered its underground storage tank system(s) with the State of Maryland, Department of the Environment as required by Environment Article Section 4-411.1, *Annotated Code of Maryland* for the following location:

Facility Address:

Hecht's
6901 Security Blvd.
Baltimore MD 21207

Shirley J. Fairbank, Chief
Office of Resource Management
Oil Control Program

This certificate authorizes the use of the listed underground storage tank system(s) only in accordance with Code of Maryland Regulations (COMAR) 26.10. **This Certificate does not confirm that the UST system(s) are being operated in full compliance with all COMAR regulations.**

The following tank(s) have been duly registered at the above facility:

TANK NUMBER	STATUS	DESCRIPTION (GALLONS)	SUBSTANCE STORED	CLOSURE STATUS
001	Permanently Out of Use	300	Diesel	Tank removed from ground
002	Currently In Use	300	Diesel	

MDE

MARYLAND DEPARTMENT OF THE ENVIRONMENT

Oil Control Program, Suite 620, 1800 Washington Boulevard, Baltimore MD 21230-1719
410-537-3442 • 410-537-3092 (fax) 1-800-633-6101, ext. 3442

Robert L. Ehrlich, Jr.
Governor

Michael S. Steele
Lt. Governor

Kendl P. Philbrick
Secretary

March 12, 2004

CERTIFIED MAIL

Mr. Eugene M. Noll
May Department Stores, t/a Hecht's
685 North Glebe Road
Arlington VA 22203-2199

RE: Notice of Violation NV-2004-033 Addendum
Case No. 2004-0455 BA1
Hecht's (Security Square Mall)
6901 Security Boulevard
Baltimore, Maryland
Facility I.D. No. 0006267

Dear Mr. Noll:

On January 28, 2004, Inspector Jackie Ryan of the Oil Control Program completed a review of Case No. 2004-0455-BA1 for the above-referenced property located in Baltimore County. On January 29, 2004, Inspector Ryan performed a follow-up visit at 6901 Security Boulevard with Mr. George Weaver of Hecht's (see enclosed inspection report). Based on the case review and site observations, Inspector Ryan determined the following:

- Tank field monitoring pipes in opposing corners could not be located;
- A cathodic protection test station exists at the underground storage tank (UST) system although the UST is registered as composite steel with flexible lines;
- Test results were not available for the cathodic protection system;
- An approved method of overfill protection is not in place;
- A drop tube is not present in the fill pipe; and
- Documentation of the site assessment at the time of closure of the 300-gallon diesel UST removed from the ground on February 16, 1999 was not available for review.

The aforementioned findings constitute violations of Maryland law, specifically, Code of Maryland Regulations (COMAR) 26.10.03.04B, 26.10.04.02D, 26.10.10.03A(2), 26.10.02.06A, and 26.10.10.03A. Based on these violations, the Waste Management Administration hereby informs May Department Stores, t/a Hecht's, that the following corrective actions must be performed:

(1) Within two (2) days of receipt of this Notice, install a method of overfill protection and a fill pipe drop tube;

(2) Within fifteen (15) days of receipt of this Notice, submit to the Oil Control Program:

a. Documentation for the connection of the cathodic protection test station;
b. The most recent corrosion test results; and
c. A copy of the closure report for the removal of the 300-gallon diesel UST on February 16, 1999.

(3) Within thirty (30) days of receipt of this Notice, locate or install two tank field monitoring pipes in accordance with COMAR 26.10.03.04B.

All information, data, reports or plans generated for this site must be submitted to the Oil Control Program within thirty (30) days of completion of the above items. All remediation activities before their implementation, discontinuance, or temporary shutdown must have prior approval of the Department.

Failure to perform the advised corrective actions could result in additional enforcement proceedings from the Department, which could include the issuance of civil penalties and other legal sanctions. If you have any questions, please contact the Oil Control Program at 410-537-3442.

Sincerely,

Thomas L. Walter, Region II Section Head
Compliance/Remediation Division
Oil Control Program

JLR/nln
Enclosure
cc: Mr. George Weaver
Yolande J.C. Norman
Mr. Gregory Sonberg
Mr. Jonas Jacobson

Maryland Department of the Environment Memorandum

To: File 2004-0455 BA1

From: Jackie Ryan

Date: January 29, 2004

Subject: Hecht's; 6901 Security Boulevard; Baltimore 21207

Remarks:

I visited the above site meeting with Mr. George Weaver of Hecht's (410-612-2955). A drop tube is not installed at the diesel UST fill. A vent whistle is not in place. No monitoring pipes were located. Documentation from Hecht's (included in the case file) indicates that the underground storage tank installed on February 17, 1999 is a Highland composite tank and piping is flexible. However, a cathodic protection test station was observed in the tank field.

A representative of MDE was not present for the removal of the 300-gallon emergency generator underground storage tank on February 16, 1999.

Jackie Ryan
Environmental Compliance Specialist

HECHT'S
A DIVISION OF THE MAY DEPARTMENT STORES COMPANY

685 North Glebe Road
Arlington, Virginia
22203-2199

March 24, 2004

Mr. Thomas L. Walter
Maryland Department of Environment
Oil Control Program - Suite 620
1800 Washington Boulevard
Baltimore, MD 21230-1719

Dear Mr. Walter,

Enclosed is a letter from Tri County, a Mr. Thomas Cooksey.

As explained in Mr. Cooksey's letter all items exists. The tank is a composite tank and cathodic protection test was performed with a 1.021 on the volt meter (see attached letter).

Also please call me if you need further information on (703) 558-1554,

Sincerely,

Gene Noll
DVP – Maintenance and Engineering

RECEIVED
MAR 26 2004
OIL CONTROL PROGRAM

Direct Dial Number

TRI
COUNTY
INDUSTRIES II, INC.

5135 Frolich Lane • Hyattsville, MD 20781

(301) 937-8611 (800) 336-8611 (301) 937-9028 fax

MARCH 23RD 2004

MR. EUGENE M. NOLL
MAY DEPARTMENT STORES
685 NORTH GLEBE ROAD
ARLINGTON, VIRGINIA 22203-2199

REF: HECHT STORE
SECURITY SQUARE MALL
6901 SECURITY BOULEVARD
BALTIMORE, MARYLAND.

DEAR MR. NOLL.

THIS LETTER IS IN REFERENCE TO YOUR NOTICE OF VIOLATION, DATED MARCH 12TH 2004, FROM THE MARYLAND DEPARTMENT OF THE ENVIRONMENT IN REGARDS TO THE ABOVE LISTED LOCATION.
ON MONDAY, MARCH 22ND, 2004, ALAN JACQUEZ, SUPERVISOR FOR TRI COUNTY INDUSTRIES, MET WITH YOUR ENGINEER, GEORGE WERNER, AT THE SECURITY MALL HECHT STORE.
THE FOLLOWING WERE OBSERVED DURING THE INVESTIGATION.

AFTER THE REMOVAL OF SOME HARDWOOD MULCH, TWO (2) MONITORING WELLS WERE FOUND ON OPPOSING CORNERS OF THE TANK FIELD.

A THREE (3) INCH VENT WINDSOCK WAS OBSERVED ON THE VENT PIPE AS REQUIRED.

THE 300 GALLON UNDERGROUND STORAGE TANK IS IN FACT A COMPOSITE TANK, HOWEVER IT IS A PRE-ENGINEERED TANK WITH ANODES ATTACHED. THE CATHODIC PROTECTION SYSTEM WAS TESTED USING A CPV-2 VOLTMETER AND A HALF CELL COPPER SULPHATE. THE READING WAS -1.021 AS INDICATED ON THE VOLTMETER. THE CATHODIC PROTECTION SYSTEM IS FOR THE TANK ONLY.

THE PIPING SYSTEM IS IN FACT FLEXIBLE PIPE MANUFACTURED BY TOTAL CONTAINMENT.

YOURS FOR A CLEANER ENVIRONMENT.

Thomas A. Coakley

THOMAS A. COAKLEY

NOTE: COLOR PHOTO'S ARE ENCLOSED FOR YOUR USE.

THE MAY DESIGN
& CONSTRUCTION
COMPANY

WRITERS DIRECT DIAL
(314) 342- 6611

April 2, 2004

RECEIVED
OIL CONTROL PROGRAM

Mr. Gregory E. Sonberg
Maryland Department of the Environment
Oil Control Program, Suite 620
1800 Washington Blvd.
Baltimore, MD 21230-1719

Dear Mr. Sonberg:

Per your request, please find attached a list of all Maryland facilities owned by The May Department Stores Company having USTs.

If you have any questions, please call me at #314-342-6611.

Thank you.

Sincerely,

Jeff D. Chi
Manager
Corporate Project Development/Environmental

/lub

Attachment

cc: Chuck Miller
Gene Noll

V:\JEFF\CORRESPONDENCE\LTR-TO-MDDeptEnviron-4-2-04.doc

HS TANK INVENTORY UPDATE

04/02/04

Location	# of Tanks	Address	Age (yrs.)	Size (gal.)	Fuel Type
Prince Georges 2606	1	3500 East/West Hwy. - Hyattsville, MD 20782	7	6,000	#2
Marlow Heights 2605	1	4101 Branch Avenue - Temple Hills, MD 20748	8	8,000	#2
Lakeforest 7823	1	701 Russell Ave. - Gaithersburg, MD 20877	17	280	D
Baltimore DC 13321	2	3000 Waterview Ave. - Baltimore, MD 21230	10 10	12,000 12,000	D D
Marley Station 1319	1	7900 South Ritchie Hwy. - Suite B - Glen Burnie, MD 21061	10	1,000	D
Owings Mills 5968	1	10300 Mill Run Circle - Owings Mill, MD 21117	11	8,000	#2
Security Square 6267	1	6901 Security Blvd. - Baltimore, MD 21244	18	290	#2
Towson 6291	1	813 Dulaney Valley Road - Towson, MD 21204	5	550	#2

Fuel Type: D = Diesel, #2, #4

SUPERVISOR CLOSURE REVIEW

Case No. 2004-0455 BAT | Date: 2/15/06

Release detected? Yes ☐ No ☒

Comment: COMPLIANCE INSPECTION

	FEDERAL (UST *Motor/Lube*/Bulk)	Code	STATE (UST *Heating Oil*/All AST)	Code	
	Color Coding	C3	Aboveground Tank Leak	A5a/A5b	
X	Compliance Inspections	C11	Dumping	A4/A4e	
	Ground Seep Investigation	B6	Open Water	A1/A1a,b,e	
	Inventory	C5	Permit Inspections	A6	
	New Installation	C1	New Installation	C2a/C2b	
	Overfill Protection	C10	Transfer Accident	A3/A3a,b,e	
	Registration	C4	Registration	C4a/C4b	
	Release Detection	C9	Vehicle Accident	A2/A2e	
	Retrofit/Repair	C7	Retrofit/Repair	C8a/C8b	
	Soil Contamination	B7	Soil Contamination	B7a/B7b	
	Surface Spill Originating from UST	B11	Surface Spill Originating from UST	B11a/B11b	
	Tank Removal/Abandonment	B8	Tank Removal/Abandonment	B9a/B9b	
	Tank Test Failure	B1	Tank Test Failure	B2a/B2b	
	Tank Truck Driver Attendance	C6	Tank Truck Driver Attendance	C6a/C6b	
	Vapor Problem	B5	Vapor Problem	B5a/B5b	
	Well/Groundwater Contamination	B3	Well/Groundwater Contamination	B4a/B4b	
	Other	B10	Other	B10a/B10b	
			Unknown Source/Surface Spill	A7	
			Unknown Source/Surface Spill-E	A7e	
			Other	A8	
			Other – Emergency	A8e	

a = Residential Heating Oil b – Commercial Heating Oil e = Emergency

Agree to close? Yes ☒ No ☐

— Residual petroleum contamination may remain on site. However, based on available data, it appears this contamination poses no threat to human health or the environment.

☒ Inspector's findings complete
☐ Site poses no risk
☒ Other

Reference/Support: SUBMITTED INFORMATION

Signature: M. T. Fuel Date: 2/15/06

Revised 05.12.05

Revised 9/26/01

Registration No. 6267

LEAK SUMMARY & TANK CLOSURE

Case No.: 04-0455 B17 Date Opened: 9/3/03 Date Closed: _____

Type of Case:

A.	Pull	____	E.	Compliance Check	1
B.	Installation	____	F.	Tank Test Failure	____
C.	Surface	____	G.	Abandonment-in-Place	____
D.	Leak Investigation	____	H.	Other	____

Spill Affected:

A.	Groundwater	____	F.	Sanitary Line	____
B.	Domestic Wells	____	G.	Utility Work or Lines	____
C.	Surface Waters	____	H.	Reached Adjoining Property	____
D.	A Building	____	I.	None/Other (Specify)	1
E.	Storm Drain	____	J.	Soils	____

Owner of System:

A.	Major Oil Company	____	F.	Private Residence	____
B.	Local Oil Company	____	G.	Apartment	____
C.	Private Owner/ Service Station	____	H.	School	____
			I.	Commercial Business	X
D.	Government Facility	____	J.	Other (Specify)	____
E.	Marina	____			

Observation wells installed? ___Yes X No No. of Wells 0

Domestic or supply well on site? ___Yes X No Impacted? ___Yes ___No ___Unknown

Has UST registration been amended? X Yes ___No

If under "Type of Case" Item B, C, or E is checked, do not fill in chart below.

Tank Capacity	Tank Type	Line Type	Age	Product	Tank Status	Leak Found
1						
2						
3						
4						
5						
6						
7						
8						
9						
10						

___ Residual petroleum contamination may remain on site. However, based on available data, it appears this contamination poses no threat to human health or the environment.

___ Release? ES ___ NC X Cleanup initiated? ES ___ NC X LUFT Code: C11

Inspected By: _____ Date: _____

Site Summary notes in Pandora Mail

CODES FOR USE ON REVERSE SIDE:

TYPE:

A) STEEL
B) FIBERGLASS
C) CATHODICALLY PROTECTED STEEL
D) OTHER
E) CLAD STEEL

AGE:

A) 1 - 5 YEARS
B) 6 - 10 YEARS
C) 11 - 15 YEARS
D) 16 - 20 YEARS
E) OVER 20 YEARS

PRODUCT:

A) GASOLINE
B) #2 OIL
C) KEROSENE
D) #4 OIL
E) #5 OIL
F) #6 OIL
G) JET FUEL
H) WASTE OIL
I) ASPHALT
J) OTHER
K) DIESEL

LEAK FOUND IN:

A) TANK
B) SUPPLY LINE
C) RETURN LINE
D) VENT LINE
E) FITTINGS
F) FILL PIPE
G) AIR POCKET
H) NONE
I) OTHER
J) FLEX CONNECTOR

STATUS:

A) IN SERVICE
B) REMOVED
C) ABANDONED IN PLACE

Facility Summary for Facility ID # 6267

Owner Name and Address: May Department Stores T/A Hecht's 685 N. Glebe Road, Arlington, VA 22203

Facility ID	Location Name	Location Street Address	Location City	Zip
6267	Hecht's	6901 Security Blvd.	Baltimore	21207

Tank ID / Status	Installed / Age (yr)	Product / Capacity	Tank Mat'l of Construction / Secondary Option	Piping Material / Secondary Option	Piping Type	Tank Release Detection / Piping Release Detection	FR Met / Over/Spill/CP
001	5/1/1979	Diesel	Asphalt Coated or Bare Steel	Galvanized Steel	Safe Suction	(A) B C D E F G H I J K ●	No
Permanently Out of Use	24	300	None	None		(B) D E F G H I J K ●	Yes No No
002	2/17/1999	Diesel	Composite (Steel w/ FRP)	Flexible Plastic	Safe Suction	● ● C D E ● G H I J K L	No
Currently In Use	05	300	Double-Walled	Double-Walled		● D E F G H I J K L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 4/6/2004

MARYLAND DEPARTMENT OF THE ENVIRONMENT

1800 Washington Boulevard • Suite 620 • Baltimore, Maryland 21230-1719
410-537-3442 • 800-633-6101 x3442 • http://www.mde.state.md.us

Waste Management Administration • Oil Control Program

NOTIFICATION FOR UNDERGROUND STORAGE TANKS

Return completed form to:

Maryland Department of the Environment
Oil Control Program
1800 Washington Boulevard, Suite 620
Baltimore MD 21230-1719

State Use Only

Facility ID Number: 6267
Alt ID Number:
Date Entered into Computer: 5/16/08
Data Clerk's Initials: mpshipe
Owner Contacted to Clarify Response:
Comments:

Type Of Notification: (check one)

☐ New Facility ☒ Amended ☐ Closure

____ Number of tanks at facility

____ Number of continuation sheets attached

I. OWNERSHIP INFORMATION:

Owner ID:

Owner Name: Macy's INC

Street Address: 7 WEST 7TH ST

CINCINNATI OHIO 45202
City State Zip Code

County: HAMILTON

Mailing Address (if different from above):

Phone Number: 513.562.6702

Contact Person: MELISSA HOFFMAN

Type Of Owner: (check one)

Government	Commercial
____ Federal	✓ Corporation
____ State	____ Company
____ Local	____ Partnership
	____ Individual

Non-Commercial

____ Residential
____ Agricultural
____ Non-Profit Agency

II. LOCATION OF TANK(S):

Facility Name or Company Site Identifier (as applicable): Macy's Security Square

Street Address: 6901 SECURITY BLVD

BALTIMORE MD 21207 Baltimore
City State Zip Code County

Mailing Address (if different from above):

Phone Number: 410.944.8040

Facility Operator: MACY'S EAST

RECEIVED
MAY 13 2008
OIL CONTROL PROGRAM

Facility ID Number: _____

III. TYPE OF FACILITY: (check one)

___ Federal Non-Military	___ Gas Station	___ Private Home
___ Federal Military	___ Petroleum Distributor	___ Apt. / Condo
___ Educational	___ Trucking/Transport	___ Farm / Nursery
___ Fire/Rescue/Ambulance	___ Industrial	___ Marina
___ Public Service	___ Contractor	___ Store
___ Utilities	___ Airline	✓ Office
___ Railroad	___ Auto Dealership	___ Other: _____

IV. CONTACT PERSON IN CHARGE OF TANKS:

Name: Melissa Hoffman Job Title: Environmental Services Coordinator

Street Address: 7 West 7th St Phone Number: 513 562 6702

Cincinnati (City) Ohio (State) 45202 (Zip) Hamilton (County)

V. FINANCIAL RESPONSIBILITY: (if applicable - see instruction sheet)

I have met the financial responsibility requirements in accordance with 40 CFR Part 280, Subpart H

☒ Yes ☐ No

Policy #: _____
Insurer: _____
Agent/Broker: _____
Phone No.: _____

___ Commercial Insurance	___ Letter of Credit
✓ Self Insurance	___ Surety Bond
___ Insurance Pool	___ Other method allowed
___ Risk Retention Group	(specify) _____
___ Guarantee	

VI. CERTIFICATION: (to be completed by owner or owner's representative)

I certify, under penalty of law, that I have personally examined, and am familiar with, the information submitted in this and all attached documents, and that the information provided is in compliance with COMAR 26.10.03, and is true, accurate, and complete.

Name (print/type): Judith Vecere

Title (print/type): Director Facility Management

Signature: Judith Vecere

Date Signed: 5/12/06

Facility ID Number: _____

VII. DESCRIPTION OF UNDERGROUND STORAGE TANKS: (complete for each tank at this facility)

Tank Identification Number	Tank No. 1	Tank No. 2	Tank No.	Tank No.	Tank No.
Alt. Tank ID Number	Tank No.	Tank No.	Tank No.	Tank No.	Tank No.
1. Status of Tank (mark only one) -Currently In Use -Temporarily Out of Use -Permanently Out of Use	X	X			
2. Date of Installation (mo/yr)	5/1979	2/1999			
3. Total Capacity (gallons)	300	300			
4. Material of Tank Construction (mark all that apply) -Asphalt Coated or Bare Steel -Cathodically Protected Steel -Composite (Steel w/ Fiberglass) -Concrete -Fiberglass Reinforced Plastic -Polyethylene Tank Jacket -Unknown -Other (specify)	X	X			
-Has tank been repaired?	YES NO	YES NO	YES NO	YES NO	YES NO
-Double-walled -Excavation Liner -Lined Interior		X			
5. Material of Piping Construction (mark all that apply) -Bare Steel -Galvanized Steel -Fiberglass Reinforced Plastic -Copper -Flexible Plastic -Unknown -Other (specify)	X	X			
-Cathodically Protected -Double-walled -Secondary Containment (specify)		X PVC			
6. Type of Piping (mark all that apply) -Pressure -Gravity Feed -Suction: no valve at tank (Safe Suction) -Suction: valve at tank (U.S. Suction)	X	X			
-Has piping been repaired?	YES NO	YES NO	YES NO	YES NO	YES NO
7. Substance Currently or Last Stored -Gasoline -Diesel	X	X			

Facility ID Number: _____

Tank Identification Number	Tank No. 1	Tank No. 2	Tank No.	Tank No.	Tank No.
Alt. Tank ID Number	Tank No.	Tank No.	Tank No.	Tank No.	Tank No.
-Gasohol -Kerosene -Heating Oil -Used Oil					
-Hazardous Substance CERCLA name and/or CAS #					
-Other (specify)					
-Mixture of Substances (specify)					
8. Closing of Tank -Estimated date last used (mo/dd/yr)					
-Date tank closed (mo/dd/yr)					
-Tank removed from ground?	YES NO	YES NO	YES NO	YES NO	YES NO
-Tank filled with inert material?	YES NO	YES NO	YES NO	YES NO	YES NO
-If yes, material used					
-Change in service to non-regulated substance?	YES NO	YES NO	YES NO	YES NO	YES NO
9. Site Assessment Completed?	YES NO	YES NO	YES NO	YES NO	YES NO
10. Release Detection (mark all that apply) -Manual Tank Gauging -Tank Tightness Testing -Inventory Controls -Automatic Tank Gauging -Vapor Monitoring -Groundwater Monitoring -Interstitial Monitoring Double-walled Tank/Piping -Statistical Inventory Reconciliation (SIR) -Automatic Line Leak Detection -Line Tightness Testing -Other Method Allowed (specify)	TANK PIPING X X X	TANK PIPING X X X X X	TANK PIPING	TANK PIPING	TANK PIPING
11. Spill and Overfill Protection -Overfill device installed -Spill catch basin	X X	X X			
12. Stage I Vapor Recovery?	YES NO	YES NO	YES NO	YES NO	YES NO
13. Stage II Vapor Recovery?	YES NO	YES NO	YES NO	YES NO	YES NO

VIII. CERTIFICATION OF COMPLIANCE: (complete for all new and upgraded tanks at this location)

Installer Certification

I certify that the underground storage system installed, upgraded, or repaired at this facility is in compliance with all applicable regulations.

Installer: _____
Print Name Signature

MDIC- _____ _____ _____
State Identification Number Date Company

F.R. Package

PERFORMANCE BOND

Date bond executed: **June 26, 2008**

Period of coverage: **6/20/2008 – 6/19/2009**

Principal: **Macy's Retail Holdings, Inc., A New York Corporation**
7 West Seventh Street
Cincinnati, OH 45202
Attn: General Counsel

Type of organization: corporation

State of incorporation (if applicable): New York

Surety(ies): **Westchester Fire Insurance Company**
436 Walnut Street
Philadelphia, PA 19106

Scope of Coverage: Taking corrective action and compensating third parties for bodily injury and property damage caused by either sudden accidental releases or nonsudden accidental releases arising from operating those storage tanks listed on Exhibit A.

Penal sums of bond: **$1,000,000.00**

Per occurrence $1 Million

Annual aggregate $1 Million

Surety's bond number: **K08182425**

Know All Persons by These Presents, that we, the Principal and Surety(ies), hereto are firmly bound to the Director of the United States Environmental Protection Agency in the above penal sums for the payment of which we bind ourselves, our heirs, executors, administrators, successors, and assigns jointly and severally; provided that, where the Surety(ies) are corporations acting as co sureties, we, the Sureties, bind ourselves in such sums jointly and severally only for the purpose of allowing a joint action or actions against any or all of us, and for all other purposes each Surety binds itself, jointly and severally with the Principal, for the payment of such sums only as is set forth opposite the name of such Surety, but if no limit of liability is indicated, the limit of liability shall be the full amount of the penal sums.

Whereas said Principal is required under Subtitle I of the Resource Conservation and Recovery Act (RCRA), as amended, to provide financial assurance for taking corrective action and/or compensating third parties for bodily injury and property damage caused by either sudden accidental releases or nonsudden accidental releases, and

SCHEDULE A

Regulated Tanks

Division	Location	Address	City, State Zip
Bloomingdale's	WHITE PLAINS	175 BLOOMINGDALE ROAD	WHITE PLAINS NY 10605
Bloomingdale's	Lenox Square	3394 Peachtree Rd. NE	Atlanta, GA 30326
HO	HANGAR-LUNKEN AIRPORT	422 WILMER AVENUE HANGAR 28	CINCINNATI OH 45226
Macy's West	Laurel Plaza	6150 Laurel Canyon Blvd.	Los Angeles, CA 91606
Macy's West	San Francisco Union Square	170 O'Farrell Street	San Francisco, CA 94102
Macy's East	JERSEY CITY (Newport Center)	200 MALL DRIVE EAST	JERSEY CITY NJ 07310
Macy's East	SOUTH PORTLAND (Maine Mall)	100 MAINE MALL ROAD	SOUTH PORTLAND ME 04106
Macy's East	SUBURBAN SQUARE	400 WEST MONTGOMERY AVENUE	ARDMORE PA 19003
Macy's East	Ballston Commons	701 N. Glebe Road	Arlington, VA 22203
Macy's East	Fair Oaks	11700 Fair Oaks Mall	Fairfax, VA 22033
Macy's East	Marley Station Mall	7900 South Ritchie Hwy, Suite	Glen Burnie, MD 21061
Macy's East	Marlow Heights S.C.	4101 Branch Avenue	Temple Hills, MD 20748
Macy's East	Metro Center	1201 G. Street NW	Washington, DC 20005
Macy's East	Owings Mill Town Center	10300 Mill Run Circle	Owings Mill, MD 21117
Macy's East	Prince Georges Plaza	3500 East West Hwy	Hyattsville, MD 20782
Macy's East	Security Square	6901 Security Blvd	Baltimore, MD 21246
Macy's East	Towson Town Center	813 Dulaney Valley Rd	Towson, MD 21204
Macy's Florida	Tyrone	6901 22nd Avenue North	St. Petersburg, FL 33710
Macy's Florida	Florida Mall	8001 South Orange Blossom Trail	Orlando, FL 32809
Macy's Florida	Wellington Green Mall	10316 Forest Hill Blvd	Wellington, FL 33414
MCCS	MCCS South	13141 34th Street, North	Clearwater, FL 33762
MLO	BAILEY - DISTR. CTR.	12629 MAHONING AVENUE	NORTH JACKSON OH 44451
MLO	Gandy Distribution Center	4130 Gandy Boulevard	Tampa, FL 33611
MLO	Miami Distribution Center	7100 NW 32nd Avenue	Miami, FL 33147
MLO	Mission Road Distribution Center	3880 N. Mission Road	Los Angeles, CA 90031
MLO	KAPOLEI	91-262 OIHANA STREET	KAPOLEI HI 96707
MSO	RIVERCHASE	2600 RIVERCHASE GALLERIA	BIRMINGHAM AL 35244
MST	MST - HEADQUARTERS	5985 STATE BRIDGE ROAD	DULUTH GA 30097
Real Estate	Fashion Place Mall	333 N. University Drive	Plantation, FL 33324
Real Estate	Chicago Distribution Center	4000 West Diversey Ave	Chicago, IL 60639

F.R. Package

PERFORMANCE BOND

Date bond executed: **June 26, 2008**

Period of coverage: **6/20/2008 – 6/19/2009**

Principal: **Macy's Retail Holdings, Inc., A New York Corporation**
7 West Seventh Street
Cincinnati, OH 45202
Attn: General Counsel

Type of organization: corporation

State of incorporation (if applicable): New York

Surety(ies): **Westchester Fire Insurance Company**
436 Walnut Street
Philadelphia, PA 19106

Scope of Coverage: Taking corrective action and compensating third parties for bodily injury and property damage caused by either sudden accidental releases or nonsudden accidental releases arising from operating those storage tanks listed on Exhibit A.

Penal sums of bond: **$1,000,000.00**

Per occurrence $1 Million

Annual aggregate $1 Million

Surety's bond number: **K08182425**

Know All Persons by These Presents, that we, the Principal and Surety(ies), hereto are firmly bound to the Director of the United States Environmental Protection Agency in the above penal sums for the payment of which we bind ourselves, our heirs, executors, administrators, successors, and assigns jointly and severally; provided that, where the Surety(ies) are corporations acting as co sureties, we, the Sureties, bind ourselves in such sums jointly and severally only for the purpose of allowing a joint action or actions against any or all of us, and for all other purposes each Surety binds itself, jointly and severally with the Principal, for the payment of such sums only as is set forth opposite the name of such Surety, but if no limit of liability is indicated, the limit of liability shall be the full amount of the penal sums.

Whereas said Principal is required under Subtitle I of the Resource Conservation and Recovery Act (RCRA), as amended, to provide financial assurance for taking corrective action and/or compensating third parties for bodily injury and property damage caused by either sudden accidental releases or nonsudden accidental releases, and

Whereas said Principal shall establish a standby trust fund as is required when a surety bond is used to provide such financial assurance;

Now, therefore, the conditions of the obligation are such that if the Principal shall faithfully take corrective action, in accordance with 40 CFR part 280, subpart F and the Director's instructions for and/or compensate injured third parties for bodily injury and property damage caused by either sudden or nonsudden or sudden and nonsudden accidental releases arising from operating

the tank(s) indentified above, or if the Principal shall provide alternate financial assurance, as specified in 40 CFR part 280, subpart H, within 120 days after the date the notice of cancellation is received by the Principal from the Surety(ies), then this obligation shall be null and void; otherwise it is to remain in full force and effect.

Such obligation does not apply to any of the following:
(a) Any obligation of Macy's Retail Holdings, Inc. under a workers' compensation, disability benefits, or unemployment compensation law or other similar law;
(b) Bodily injury to an employee of Macy's Retail Holdings, Inc. arising from, and in the course of, employment by Macy's Retail Holdings, Inc.
(c) Bodily injury or property damage arising from the ownership, maintenance, use, or entrustment to others of any aircraft, motor vehicle, or watercraft;
(d) Property damage to any property owned, rented, loaned to, in the care, custody, or control of, or occupied by Macy's Retail Holdings, Inc. that is not the direct result of a release from a petroleum underground storage tank;
(e) Bodily injury or property damage for which Macy's Retail Holdings, Inc. is obligated to pay damages by reason of the assumption of liability in a contract or agreement other than a contract or agreement entered into to meet the requirements of 40 CFR 280.93.

The Surety(ies) shall become liable on this bond obligation only when the Principal has failed to fulfill the conditions described above.

Upon notification by the Director that the Principal has failed to take corrective action, in accordance with 40 CFR part 280, subpart F and the Director's instructions and/or compensate injured third parties as guaranteed by this bond, the Surety(ies) shall either perform corrective action in accordance with 40 CFR part 280 and the Director's instructions, and/or third-party liability compensation or place funds in an amount up to the annual aggregate penal sum into the standby trust fund as directed by the Director under 40 CFR 280.108.

Upon notification by the Director that the Principal has failed to provide alternate financial assurance within 60 days after the date the notice of cancellation is received by the Principal from the Surety(ies) and that the Director has determined or suspects that a release has occurred, the Surety(ies) shall place funds in an amount not exceeding the annual aggregate penal sum into the standby trust fund as directed by the Director under 40 CFR 280.108.

The Surety(ies) hereby waive(s) notification of amendments to applicable laws, statutes, rules, and regulations and agrees that no such amendment shall in any way alleviate its (their) obligation on this bond.

The liability of the Surety(ies) shall not be discharged by any payment or succession of payments hereunder, unless and until such payment or payments shall amount in the annual aggregate to the penal sum shown on the face of the bond, but in no event shall the obligation of the Surety(ies) hereunder exceed the amount of said annual aggregate penal sum.

The Surety(ies) may cancel the bond by sending notice of cancellation by certified mail to the Principal, provided, however, that cancellation shall not occur during the 120 days beginning on the date of receipt of the notice of cancellation by the Principal, as evidenced by the return receipt.

The Principal may terminate this bond by sending written notice to the Surety(ies).

In Witness Thereof, the Principal and Surety(ies) have executed this Bond and have affixed their seals on the date set forth above. The persons whose signatures appear below hereby certify that they are authorized to execute this surety bond on behalf of the Principal and Surety(ies) and that the wording of this surety bond is identical to the wording specified in 40 CFR 280.98(b) as such regulations were constituted on the date this bond was executed.

Macy's Retail Holdings, Inc., A New York Corporation

Jack B. Cox asst. Secretary

[Name(s)] JACK B. COX
[Title(s)] ASSISTANT SECRETARY
[Corporate seal]

Westchester Fire Insurance Company
436 Walnut Street
Philadelphia, PA 19106
New York:

[Liability limit: **$1,000,000.00**

Sandra Martinez

Sandra Martinez, Attorney-in-Fact

[Corporate seal]

[For every co-surety, provide signature(s), corporate seal, and other information in the same manner as for Surety above.]

Bond premium: **$7,500.00**

Exhibit A

Regulated Tanks

Division	Location	Address	City, State Zip
Bloomingdale's	WHITE PLAINS	175 BLOOMINGDALE ROAD	WHITE PLAINS NY 10605
Bloomingdale's	Lenox Square	3394 Peachtree Rd. NE	Atlanta, GA 30326
HO	HANGAR-LUNKEN AIRPORT	422 WILMER AVENUE HANGAR 28	CINCINNATI OH 45226
Macy's West	Laurel Plaza	6150 Laurel Canyon Blvd.	Los Angeles, CA 91606
Macy's West	San Francisco Union Square	170 O'Farrell Street	San Francisco, CA 94102
Macy's East	JERSEY CITY (Newport Center)	200 MALL DRIVE EAST	JERSEY CITY NJ 07310
Macy's East	SOUTH PORTLAND (Maine Mall)	100 MAINE MALL ROAD	SOUTH PORTLAND ME 04106
Macy's East	SUBURBAN SQUARE	400 WEST MONTGOMERY AVENUE	ARDMORE PA 19003
Macy's East	Ballston Commons	701 N. Glebe Road	Arlington, VA 22203
Macy's East	Fair Oaks	11700 Fair Oaks Mall	Fairfax, VA 22033
Macy's East	Marley Station Mall	7900 South Ritchie Hwy, Suite	Glen Burnie, MD 21061
Macy's East	Marlow Heights S.C.	4101 Branch Avenue	Temple Hills, MD 20748
Macy's East	Metro Center	1201 G. Street NW	Washington, DC 20005
Macy's East	Owings Mill Town Center	10300 Mill Run Circle	Owings Mill, MD 21117
Macy's East	Prince Georges Plaza	3500 East West Hwy	Hyattsville, MD 20782
Macy's East	Security Square	6901 Security Blvd	Baltimore, MD 21246
Macy's East	Towson Town Center	813 Dulaney Valley Rd	Towson, MD 21204
Macy's Florida	Tyrone	6901 22nd Avenue North	St. Petersburg, FL 33710
Macy's Florida	Florida Mall	8001 South Orange Blossom Trail	Orlando, FL 32809
Macy's Florida	Wellington Green Mall	10316 Forest Hill Blvd	Wellington, FL 33414
MCCS	MCCS South	13141 34th Street, North	Clearwater, FL 33762
MLO	BAILEY - DISTR. CTR.	12629 MAHONING AVENUE	NORTH JACKSON OH 44451
MLO	Gandy Distribution Center	4130 Gandy Boulevard	Tampa, FL 33611
MLO	Miami Distribution Center	7100 NW 32nd Avenue	Miami, FL 33147
MLO	Mission Road Distribution Center	3880 N. Mission Road	Los Angeles, CA 90031
MLO	KAPOLEI	91-262 OIHANA STREET	KAPOLEI HI 96707
MSO	RIVERCHASE	2600 RIVERCHASE GALLERIA	BIRMINGHAM AL 35244
MST	MST - HEADQUARTERS	5985 STATE BRIDGE ROAD	DULUTH GA 30097
Real Estate	Fashion Place Mall	333 N. University Drive	Plantation, FL 33324
Real Estate	Chicago Distribution Center	4000 West Diversey Ave	Chicago, IL 60639

Power of Attorney

174016

WESTCHESTER FIRE INSURANCE COMPANY

1262079

Know all men by these presents: That WESTCHESTER FIRE INSURANCE COMPANY , a corporation of the State of New York , having its principal office in the City of Atlanta , Georgia , pursuant to the following Resolution, adopted by the Board of Directors of the said Company on December 11, 2006, to wit:

"RESOLVED, that the following authorizations relate to the execution, for and on behalf of the Company, of bonds, undertakings, recognizances, contracts and other written commitments of the Company entered into the ordinary course of business(each a "Written Commitment"):

(1) Each of the Chairman, the President and the Vice Presidents of the Company is hereby authorized to execute any Written Commitment for and on behalf of the Company, under the seal of the Company or otherwise.

(2) Each duly appointed attorney-in-fact of the Company is hereby authorized to execute any Written Commitment for and on behalf of the Company, under the seal of the Company or otherwise, to the extent that such action is authorized by the grant of powers provided for in such persons written appointment as such attorney-in-fact.

(3) Each of the Chairman, the President and the Vice Presidents of the Company is hereby authorized, for and on behalf of the Company, to appoint in writing any person the attorney-in-fact of the Company with full power and authority to execute, for and on behalf of the Company, under the seal of the Company or otherwise, such Written Commitments of the Company as may be specified in such written appointment, which specification may be by general type or class of Written Commitments or by specification of one or more particular Written Commitments.

(4) Each of the Chairman, the President and Vice Presidents of the Company is hereby authorized, for and on behalf of the Company, to delegate in writing to any other officer of the Company the authority to execute, for and on behalf of the Company, under the Company's seal or otherwise, such Written Commitments of the Company as are specified in such written delegation, which specification may be by general type or class of Written Commitments or by specification of one or more particular Written Commitments.

(5) The signature of any officer or other person executing any Written Commitment or appointment or delegation pursuant to this Resolution, and the seal of the Company, may be affixed by facsimile on such Written Commitment or written appointment or delegation.

FURTHER RESOLVED, that the foregoing Resolution shall not be deemed to be an exclusive statement of the powers and authority of officers, employees and other persons to act for and on behalf of the Company, and such Resolution shall not limit or otherwise affect the exercise of any such power or authority otherwise validly granted or vested.

FURTHER RESOLVED, that the Resolution of the Board of Directors of the Company adopted at the meeting held on November 8, 1999 relating to the authorization of certain persons to execute, for and on behalf of the Company, Written Commitments and appointments and delegations, is hereby rescinded.

Does hereby nominate, constitute and appoint CRAIG T. TAGLIAMONTE, ROBERT E. DUNCAN, GEOFFREY E. HEEKIN, THOMAS J. JOSLIN, KAREN DANIEL, LINDA ISER, KATHLEEN J. MAILES, SANDRA MARTINEZ, SUSAN J. PREJKSA, SUSAN A. WELSH, MARCIA K. CESAFSKY, JOELLEN M. MENDOZA, CHRISTOPHER P. TROHA and PATRICIA M. DOYLE all of the City of Chicago, State of Illinois , each individually if there be more than one named, its true and lawful attorney-in-fact, to make, execute, seal and deliver on its behalf, and as its act and deed any and all bonds, undertakings, recognizances, contracts and other writings in the nature thereof in penalties not exceeding Twenty Five Million Dollars ($25,000,000) and the execution of such writings in pursuance of these presents shall be as binding upon said Company, as fully and amply as if they had been duly executed and acknowledged by the regularly elected officers of the Company at its principal office.

IN WITNESS WHEREOF, the said Stephen M. Haney , Vice-President, has hereunto subscribed his name and affixed the corporate seal of the said WESTCHESTER FIRE INSURANCE COMPANY this 3rd day of June 2008 .

WESTCHESTER FIRE INSURANCE COMPANY

Stephen M. Haney , Vice President

COMMONWEALTH OF PENNSYLVANIA
COUNTY OF PHILADELPHIA ss.

On this 3rd day of June , A.D. 2008 , before me, a Notary Public of the Commonwealth of Pennsylvania in and for the County of Philadelphia came Stephen M. Haney , Vice-President of the WESTCHESTER FIRE INSURANCE COMPANY to me personally known to be the individual and officer who executed the preceding instrument, and he acknowledged that he executed the same, and that the seal affixed to the preceding instrument is the corporate seal of said Company; that the said corporate seal and his signature were duly affixed by the authority and direction of the said corporation, and that Resolution, adopted by the Board of Directors of said Company, referred to in the preceding instrument, is now in force.

IN TESTIMONY WHEREOF, I have hereunto set my hand and affixed my official seal at the City of Philadelphia the day and year first above written.

COMMONWEALTH OF PENNSYLVANIA
NOTARIAL SEAL
KAREN E. BRANDT, Notary Public
City of Philadelphia, Phila. County
My Commission Expires September 26, 2010

Notary Public

I, the undersigned Assistant Secretary of WESTCHESTER FIRE INSURANCE COMPANY , do hereby certify that the original POWER OF ATTORNEY, of which the foregoing is a substantially true and correct copy, is in full force and effect.

In witness whereof, I have hereunto subscribed my name as Assistant Secretary, and affixed the corporate seal of the Corporation, this 26th day of June 2008 .

William L. Kelly , Assistant Secretary

THIS POWER OF ATTORNEY MAY NOT BE USED TO EXECUTE ANY BOND WITH AN INCEPTION DATE AFTER June 3, 2010 .

THE BACK OF THIS DOCUMENT LISTS VARIOUS SECURITY FEATURES THAT WILL PROTECT AGAINST COPY COUNTERFEIT AND ALTERATION.

ACKNOWLEDGEMENT BY SURETY

STATE OF ILLINOIS
COUNTY OF COOK

On this 26th day of June, 2008, before me, Judi Lucky, a Notary Public, within and for said County and State, personally appeared Sandra Martinez to me personally known to be the Attorney-in-Fact of and for Westchester Fire Insurance Company and acknowledged that she executed the said instrument as the free act and deed of said Company.

IN WITNESS WHEREOF, I have hereunto set my hand and affixed my official seal, at my office in the aforesaid County, the day and year in this certificate first above written.

Notary Public in the State of Illinois
County of Cook

OFFICIAL SEAL
JUDI LUCKY
NOTARY PUBLIC - STATE OF ILLINOIS
MY COMMISSION EXPIRES
OCTOBER 07, 2010

TRUST AGREEMENT

This Trust Agreement "Agreement," entered into as of June 27, 2008, by and between Macy's Retail Holdings, Inc., a New York corporation, the "Grantor," and U.S. Bank National Association, the "Trustee."

WHEREAS, the United States Environmental Protection Agency, "EPA," an agency of the United States Government, has established certain regulations applicable to the Grantor, requiring that an owner or operator of an underground storage tank shall provide assurance that funds will be available when needed for corrective action and third-party compensation for bodily injury and property damage caused by sudden and non-sudden accidental releases arising from the operation of the storage tank. The attached Schedule A lists the number of tanks at each facility and the name(s) and address(es) of the facility(ies) where the tanks are located that are covered by the standpoint trust agreement.

WHEREAS, the Grantor has elected to establish a surety bond to provide all or part of such financial assurance for the storage tanks identified herein and is required to establish a standby trust fundable to accept payments from the instrument.

WHEREAS, the Grantor, acting through its duly authorized officers, has selected the Trustee to be the trustee under this Agreement, and the Trustee is willing to act as trustee;

NOW, THEREFORE, the Grantor and the Trustee agree as follows:

Section 1. Definitions

As used in this Agreement:

(a) The term "Grantor" means the owner or operator who enters into this Agreement and any successors or assigns of the Grantor.

(b) The term "Trustee" means the Trustee who enters into this Agreement and any successor Trustee.

Section 2. Identification of the Financial Assurance Mechanism

This Agreement pertains to the surety bond from which the standby trust fund is established to receive payments.

Section 3. Establishment of Fund

The Grantor and the Trustee hereby establish a trust fund, the "Fund," for the benefit of the EPA. The Grantor and the Trustee intend that no third party have access to the Fund except as herein provided. The Fund is established initially as a standby to receive payments and shall not consist of any property. Payments made by the provider of financial assurance pursuant to the Director of the EPA's instruction are transferred to the Trustee and are referred to as the Fund, together with all earnings and profits thereon, less any payments or distributions made by the Trustee pursuant to this Agreement. The Fund shall be held by the Trustee, IN TRUST, as

hereinafter provided. The Trustee shall not be responsible nor shall it undertake any responsibility for the amount or adequacy of, nor any duty to collect from the Grantor as provider of financial assurance, any payments necessary to discharge any liability of the Grantor established by the EPA.

Section 4. Payment for Corrective Action or Third-Party Liability Claims

The Trustee shall make payments from the Fund as the Director of the EPA shall direct, in writing, to provide for the payment of the costs of taking corrective action or compensating third parties for bodily injury and property damage caused by either sudden accidental releases or non-sudden accidental releases or accidental releases arising from operating the tanks covered by the financial assurance mechanism identified in this Agreement. The Fund may not be drawn upon to cover any of the following:

(a) Any obligation of Grantor under a workers' compensation, disability benefits, or unemployment compensation law or other similar law;

(b) Bodily injury to an employee of Grantor arising from, and in the course of employment by Grantor;

(c) Bodily injury or property damage arising from the ownership, maintenance, use, or entrustment to others of any aircraft, motor vehicle, or watercraft;

(d) Property damage to any property owned, rented, loaned to, in the care, custody, or control of, or occupied by Grantor that is not the direct result of a release from a petroleum underground storage tank;

(e) Bodily injury or property damage for which Grantor is obligated to pay damages by reason of the assumption of liability in a contract or agreement other than a contract or agreement entered into to meet the requirements of 40 CFR 280.93. The Trustee shall reimburse the Grantor, or other persons as specified by the Director of the EPA, from the Fund for corrective action expenditures and/or third-party liability claims in such amounts as the Director shall direct in writing. In addition, the Trustee shall refund to the Grantor such amounts as the Director specifies in writing. Upon refund, such funds shall no longer constitute part of the Fund as defined herein.

Section 5. Payments Comprising the Fund

Payments made to the Trustee for the Fund shall consist of cash and securities acceptable to the Trustee.

Section 6. Trustee Management

The Trustee shall invest and reinvest the principal and income of the Fund and keep the Fund invested as a single fund, without distinction between principal and income, in accordance with general investment policies and guidelines which the Grantor may communicate in writing to the Trustee from time to time, subject, however, to the provisions of this Section. In investing, reinvesting, exchanging, selling, and managing the Fund, the Trustee shall discharge his duties with respect to the trust fund solely in the interest of the beneficiaries and with the care, skill,

prudence, and diligence under the circumstances then prevailing which persons of prudence, acting in a like capacity and familiar with such matters, would use in the conduct of an enterprise of a like character and with like aims; except that:

(i) Securities or other obligations of the Grantor, or any other owner or operator of the tanks, or any of their affiliates as defined in the Investment Company Act of 1940, as amended, 15 U.S.C. 80a-2(a), shall not be acquired or held, unless they are securities or other obligations of the federal or a state government;

(ii) The Trustee is authorized to invest the Fund in time or demand deposits of the Trustee, to the extent insured by an agency of the federal or state government; and

(iii) The Trustee is authorized to hold cash awaiting investment or distribution uninvested for a reasonable time and without liability for the payment of interest thereon.

Section 7. Commingling and Investment

The Trustee is expressly authorized in its discretion:

(a) To transfer from time to time any or all of the assets of the Fund to any common, commingled, or collective trust fund created by the Trustee in which the Fund is eligible to participate, subject to all of the provisions thereof, to be commingled with the assets of other trusts participating therein; and

(b) To purchase shares in any investment company registered under the Investment Company Act of 1940, 15 U.S.C. 80a-1 et seq., including one which may be created, managed, underwritten, or to which investment advice is rendered or the shares of which are sold by the Trustee. The Trustee may vote such shares in its discretion.

Section 8. Express Powers of Trustee

Without in any way limiting the powers and discretions conferred upon the Trustee by the other provisions of this Agreement or by law, the Trustee is expressly authorized and empowered:

(a) To sell, exchange, convey, transfer, or otherwise dispose of any property held by it, by public or private sale. No person dealing with the Trustee shall be bound to see to the application of the purchase money or to inquire into the validity or expediency of any such sale or other disposition;

(b) To make, execute, acknowledge, and deliver any and all documents of transfer and conveyance and any and all other instruments that may be necessary or appropriate to carry out the powers herein granted;

(c) To register any securities held in the Fund in its own name or in the name of a nominee and to hold any security in bearer form or in book entry, or to combine certificates representing such securities with certificates of the same issue held by the Trustee in other fiduciary capacities, or to deposit or arrange for the deposit of such securities in a qualified central depository even though, when so deposited, such securities may be

merged and held in bulk in the name of the nominee of such depository with other securities deposited therein by another person, or to deposit or arrange for the deposit of any securities issued by the United States Government, or any agency or instrumentality thereof, with a Federal Reserve bank, but the books and records of the Trustee shall at all times show that all such securities are part of the Fund;

(d) To deposit any cash in the Fund in interest-bearing accounts maintained or savings certificates issued by the Trustee, in its separate corporate capacity, or in any other banking institution affiliated with the Trustee, to the extent insured by an agency of the federal or state government; and

(e) To compromise or otherwise adjust all claims in favor of or against the Fund.

Section 9. Taxes and Expenses

All taxes of any kind that may be assessed or levied against or in respect of the Fund and all brokerage commissions incurred by the Fund shall be paid from the Fund. All other expenses incurred by the Trustee in connection with the administration of this Trust, including fees for legal services rendered to the Trustee, the compensation of the Trustee to the extent not paid directly by the Grantor, and all other proper charges and disbursements of the Trustee shall be paid from the Fund.

Section 10. Advice of Counsel

The Trustee may from time to time consult with counsel, who may be counsel to the Grantor, with respect to any questions arising as to the construction of this Agreement or any action to be taken hereunder. The Trustee shall be fully protected, to the extent permitted by law, in acting upon the advice of counsel.

Section 11. Trustee Compensation

The Trustee shall be entitled to reasonable compensation for its services as agreed upon in writing from time to time with the Grantor.

Section 12. Successor Trustee

The Trustee may resign or the Grantor may replace the Trustee, but such resignation or replacement shall not be effective until the Grantor has appointed a successor trustee and this successor accepts the appointment. The successor trustee shall have the same powers and duties as those conferred upon the Trustee hereunder. Upon the successor trustee's acceptance of the appointment, the Trustee shall assign, transfer, and pay over to the successor trustee the funds and properties then constituting the Fund. If for any reason the Grantor cannot or does not act in the event of the resignation of the Trustee, the Trustee may apply to a court of competent jurisdiction for the appointment of a successor trustee or for instructions. The successor trustee shall specify the date on which it assumes administration of the trust in writing sent to the Grantor and the present Trustee by certified mail 10 days before such change becomes effective. Any expenses incurred by the Trustee as a result of any of the acts contemplated by this Section shall be paid as provided in Section 9.

Section 13. Instructions to the Trustee

All orders, requests, and instructions by the Grantor to the Trustee shall be in writing, signed by such persons as are designated in the attached Schedule B or such other designees as the Grantor may designate by amendment to Schedule B. The Trustee shall be fully protected in acting without inquiry in accordance with the Grantor's orders, requests, and instructions. All orders, requests, and instructions by the Director of the EPA to the Trustee shall be in writing, signed by the Director, and the Trustee shall act and shall be fully protected in acting in accordance with such orders, requests, and instructions. The Trustee shall have the right to assume, in the absence of written notice to the contrary, that no event constituting a change or a termination of the authority of any person to act on behalf of the Grantor or the Director hereunder has occurred. The Trustee shall have no duty to act in the absence of such orders, requests, and instructions from the Grantor and/or the Director, except as provided for herein.

Section 14. Amendment of Agreement

This Agreement may be amended by an instrument in writing executed by the Grantor and the Trustee, or by the Trustee and the Director of the EPA if the Grantor ceases to exist.

Section 15. Irrevocability and Termination

Subject to the right of the parties to amend this Agreement as provided in Section 14, this Trust shall be irrevocable and shall continue until terminated at the written direction of the Grantor and the Trustee, or by the Trustee and the Director of the EPA, if the Grantor ceases to exist. Upon termination of the Trust, all remaining trust property, less final trust administration expenses, shall be delivered to the Grantor.

Section 16. Immunity and Indemnification

The Trustee shall not incur personal liability of any nature in connection with any act or omission, made in good faith, in the administration of this Trust, or in carrying out any directions by the Grantor or the Director of the EPA issued in accordance with this Agreement. The Trustee shall be indemnified and saved harmless by the Grantor, from and against any personal liability to which the Trustee may be subjected by reason of any act or conduct in its official capacity, including all expenses reasonably incurred in its defense in the event the Grantor fails to provide such defense.

Section 17. Choice of Law

This Agreement shall be administered, construed, and enforced according to the laws of the state of Ohio, or the Comptroller of the Currency in the case of National Association banks.

Section 18. Interpretation

As used in this Agreement, words in the singular include the plural and words in the plural include the singular. The descriptive headings for each section of this Agreement shall not affect the interpretation or the legal efficacy of this Agreement.

IN WITNESS WHEREOF, the parties have caused this Agreement to be executed by their respective officers duly authorized and their corporate seals (if applicable) to be hereunto affixed and attested as of the date first above written. The parties below certify that the wording of this

Agreement is identical to the wording specified in 40 CFR 280.103(b)(1) as such regulations were constituted on the date written above.

MACY'S RETAIL HOLDINGS, INC.
a New York corporation
By: Brian M. Szames
Title: Treasurer

STATE OF OHIO }
COUNTY OF HAMILTON } SS,

On this 27th day of JUNE, 2008, before me personally came Macy's Retail Holdings, Inc. to me known, who, being by me duly sworn, did depose and say that she/he resides at [address], that she/he is [title] of [corporation], the corporation described in and which executed the above instrument; that she/he knows the seal of said corporation; that the seal affixed to such instrument is such corporate seal; that it was so affixed by order of the Board of Directors of said corporation; and that she/he signed her/his name thereto by like order.

[Name of Notary Public]

KLAUS M. ZIERMAIER, Attorney-At-Law
NOTARY PUBLIC — STATE OF OHIO
My Commission has no expiration date.
Section 147.03 R.C.

Attest:

U.S. BANK NATIONAL ASSOCIATION
By: M. Christine Poppe, Vice President

WITNESS:
[Title] Vice President

SCHEDULE A

Regulated Tanks

Division	Location	Address	City, State Zip
Bloomingdale's	WHITE PLAINS	175 BLOOMINGDALE ROAD	WHITE PLAINS NY 10605
Bloomingdale's	Lenox Square	3394 Peachtree Rd. NE	Atlanta, GA 30326
HO	HANGAR-LUNKEN AIRPORT	422 WILMER AVENUE HANGAR 28	CINCINNATI OH 45226
Macy's West	Laurel Plaza	6150 Laurel Canyon Blvd.	Los Angeles, CA 91606
Macy's West	San Francisco Union Square	170 O'Farrell Street	San Francisco, CA 94102
Macy's East	JERSEY CITY (Newport Center)	200 MALL DRIVE EAST	JERSEY CITY NJ 07310
Macy's East	SOUTH PORTLAND (Maine Mall)	100 MAINE MALL ROAD	SOUTH PORTLAND ME 04106
Macy's East	SUBURBAN SQUARE	400 WEST MONTGOMERY AVENUE	ARDMORE PA 19003
Macy's East	Ballston Commons	701 N. Glebe Road	Arlington, VA 22203
Macy's East	Fair Oaks	11700 Fair Oaks Mall	Fairfax, VA 22033
Macy's East	Marley Station Mall	7900 South Ritchie Hwy, Suite	Glen Burnie, MD 21061
Macy's East	Marlow Heights S.C.	4101 Branch Avenue	Temple Hills, MD 20748
Macy's East	Metro Center	1201 G. Street NW	Washington, DC 20005
Macy's East	Owings Mill Town Center	10300 Mill Run Circle	Owings Mill, MD 21117
Macy's East	Prince Georges Plaza	3500 East West Hwy	Hyattsville, MD 20782
Macy's East	Security Square	6901 Security Blvd	Baltimore, MD 21246
Macy's East	Towson Town Center	813 Dulaney Valley Rd	Towson, MD 21204
Macy's Florida	Tyrone	6901 22nd Avenue North	St. Petersburg, FL 33710
Macy's Florida	Florida Mall	8001 South Orange Blossom Trail	Orlando, FL 32809
Macy's Florida	Wellington Green Mall	10316 Forest Hill Blvd	Wellington, FL 33414
MCCS	MCCS South	13141 34th Street, North	Clearwater, FL 33762
MLO	BAILEY - DISTR. CTR.	12629 MAHONING AVENUE	NORTH JACKSON OH 44451
MLO	Gandy Distribution Center	4130 Gandy Boulevard	Tampa, FL 33611
MLO	Miami Distribution Center	7100 NW 32nd Avenue	Miami, FL 33147
MLO	Mission Road Distribution Center	3880 N. Mission Road	Los Angeles, CA 90031
MLO	KAPOLEI	91-262 OIHANA STREET	KAPOLEI HI 96707
MSO	RIVERCHASE	2600 RIVERCHASE GALLERIA	BIRMINGHAM AL 35244
MST	MST - HEADQUARTERS	5985 STATE BRIDGE ROAD	DULUTH GA 30097
Real Estate	Fashion Place Mall	333 N. University Drive	Plantation, FL 33324
Real Estate	Chicago Distribution Center	4000 West Diversey Ave	Chicago, IL 60639

SCHEDULE B

Elena Pfarr, Manager of Environmental Services, Macy's; or
Paul McConocha, OVP SPACE Engineering and Environmental Services, Macy's; or
Melissa Hoffman, Environmental Services Coordinator, Macy's.

ID: 520 | Add Record

WASTE MANAGEMENT ADMINISTRATION
OIL POLLUTION AND TANK MANAGEMENT

Print Record

Case No: | **INITIAL REPORT OF INCIDENT** | *Facility ID#:* 6267

CALLER:

1. Name of person Taking report: Nancy Nunn
2. Date of report: 3/30/2009
3. Time of report: 11:30 AM
4. Name of caller: John Goodwin
5. Telephone #: 410-491-6639
6. What agency or company is caller with: Ace Environmental: 410-354-8030

DETAILS OF SPILL:

7. AST or UST?
8. Date of incident: 3/30/2009
9. Time of incident:
10. Has product been released? Yes/No: No
11. Amount release:
12. Tank test failure? Yes/No: No
13. Tank failure rate:
14. **Precise location of the release or incident:**

Name: Macy's Inc.

Address: 6901 Security Blvd

City: Baltimore | State: MD | Zipcode: 21207 | County: BA

15. Nearest crossroad or other identifying mark:
16. Type of product involved: diesel
17. Quantity on board: 300-gal
18. Age of tank system: 10 yrs
19. Details of release:

Found buried copper lines during third-party inspection.

20. Has product entered water? Yes/No
21. Name of waterway:

RESPONSIBLE PARTY (RP)

22. RP's name: Macy's Inc. Dave Novak
23. RP's phone: 443-484-4529
24. RP's address:
25. Has RP taken any action to control the problem? Yes/No: No
26. If YES, what:

ACTION TAKEN:

Lead: Oil Control Program: ☑ Emergency Response: ☐ No Action Taken: ☐ Other: ☐

27. Inspector Assigned Case: Ray Kozlowski
28. Initials: GES

MARYLAND DEPARTMENT OF THE ENVIRONMENT
Oil Control Program, Suite 620, 1800 Washington Blvd., Baltimore MD 21230-1719
410-537-3442 • 410-537-3092 (fax) 1-800-633-6101

Martin O'Malley
Governor

Anthony G. Brown
Lieutenant Governor

Shari T. Wilson
Secretary

Robert M. Summers, Ph.D.
Deputy Secretary

April 9, 2009

CERTIFIED MAIL

Macys Inc.
7 West 7th Street
Cincinnati OH 45202

RE: FINAL NOTICE
NOTICE TO INSPECT
Facility I.D. No. 6267 Baltimore
Hecht's
6901 Security Blvd.
Baltimore

Dear Sir or Madam:

The Waste Management Administration's Oil Control Program issued a **Notice to Inspect** letter to have your underground storage tank (UST) system(s) at the above reference facility inspected by a Maryland Department of the Environment Certified Underground Storage System Inspector within thirty (30) days. The inspection must have been performed within sixty (60) days of notice and the inspection report submitted to the Department.

To Date, the Department has not received the required inspection report, a violation of Code of Maryland Regulation (COMAR) 26.10.03.10A. The Department hereby requires the following action:

- Within ten (10) days of receipt of this letter the Department must receive an underground storage tank inspection report completed by a Maryland Department of the Environment Certified Underground Storage System Inspector (list enclosed).

Failure to perform the required UST inspection and submit the inspection report to the Department, within the required time schedule, **will** result in additional enforcement action from this Administration, which could include the issuance of civil penalties and other legal sanctions.

Additional information and a copy of the inspection report may be obtained from MDE web page at:

http://www.mde.state.md.us/Programs/LandPrograms/Oil_Control/USThome/ustcertification_programs.asp

If you have any questions or would like to report compliance, please feel free to telephone Mr. Richard Lego, Certification Section Head at (410) 537-4189 or via Email: rlego@mde.state.md.us or the Oil Control Program at (410) 537-3442.

Sincerely,

Thomas Walter

Thomas L. Walter, Chief
Compliance Division
Oil Control Program

TLW/sd
cc: Mr. Richard D. Lego
Mr. Herbert M. Meade
Mr. Horacio Tablada

MARYLAND DEPARTMENT OF THE ENVIRONMENT
Oil Control Program, Suite 620, 1800 Washington Blvd., Baltimore MD 21230-1719
410-537-3442 • 410-537-3092 (fax) 1-800-633-6101

Martin O'Malley
Governor

Shari T. Wilson
Secretary

Anthony G. Brown
Lieutenant Governor

Robert M. Summers, Ph.D.
Deputy Secretary

January 29, 2009

CERTIFIED MAIL

Macys Inc.
7 West 7th Street
Cincinnati OH 45202

RE: NOTICE TO INSPECT
Facility I.D. No. 6267 Baltimore
Hecht's
6901 Security Blvd.
Baltimore

Dear Sir or Madam:

As the registered owner of an underground storage system located at the above referenced facility, you are hereby given **Official Notice** to have your underground petroleum storage tank system(s) inspected by a Maryland Department of the Environment (MDE) Certified Underground Storage System Inspector. This inspection must take place within thirty (30) days upon receipt of this Notice. In accordance with Code of Maryland Regulations (COMAR) 26.10.03.10A. "An underground motor fuel storage tank owner shall have each underground storage tank system inspected by a certified inspector at the frequency established in Subsection B—E of this regulation. The inspection shall verify compliance with COMAR 26.10.02—.11 on forms provided by the Department". The owner of an underground motor fuel storage tank system shall complete a certified inspection of that system at least once every three years after the initial inspection.

You will find three documents enclosed with this Notice:

A) List of Companies who employ Maryland Certified Inspectors
B) Information on "How Can I Prepare For The UST Inspection"
C) MDE Underground Storage Tank (UST) Registration Summary Printout

You must choose and contact a company who employs a Maryland Certified Inspector to inspect your facility within thirty (30) days. The cost of the inspection may vary. The MDE will not participate in the billing and collection process. Submittal of the inspection report to the Department is required within thirty (30) days of the inspection and no longer than sixty (60) days from receiving this notice. The MDE will not arbitrate nor accept disputes regarding an inspection finding as a reason for a delay in the report submittal.

The inspector will need the enclosed MDE UST Registration Summary Printout to complete the Inspection Report Form. Discuss with the Inspector **prior to** his/her arrival the 14 items in the "How Can I Prepare For The UST Inspection" information page. The inspector will need all of this information to complete the inspection. To validate the Inspection Report Form the inspector and owner/operator **must sign** page 2 and **initial** page 24 at the bottom. The Department's facility registration database will be amended to reflect the information provided in the report.

The MDE encourages you to ask to see the inspector's MDE Certified Underground Storage System Inspector card (yellow card with the State Seal in the background with an (I) in the upper right corner). You should check the expiration date to ensure the card is valid.

The owner of an underground storage tank system(s) shall have **thirty (30) days** to correct all deficiencies found during the inspection, in accordance with COMAR 26.10.02—.11 unless an alternative schedule is approved by the Department. Many minor deficiencies found (example: clean containment sumps, tighten fittings, mark fill pipes, etc.) may be corrected at the time of the inspection. Only a MDE UST Certified Technician may upgrade, repair, install or close a UST system.

After the inspection you should discuss with the Third Party Inspection Company their findings and any deficiencies found during the inspection. The Department believes it is the inspector's obligation to explain, provide a summary of the findings or review any deficiencies found during the inspection process to allow the owner/operator to understand the deficiencies so that repairs or corrections can be performed in an efficient and timely manner. Remember, it is your responsibility to maintain and operate the underground storage system(s) in compliance with Maryland laws and regulation. Being prepared will make your inspection go smoothly and limit business disruption.

For more information you may contact the Maryland Department of the Environment's Oil Control Program at (410) 537-3442 or visit our web site at:
http://www.mde.state.md.us/Programs/LandPrograms/Oil_Control/index.asp.

Failure to perform the required inspection and submit the completed Inspection Report to the Department within the required sixty (60) days may result in enforcement action from the Department that could include issuance of civil penalties and other legal sanctions. If you have any questions regarding the Third Party Inspection Program and required facility inspection, please feel free to contact Mr. Richard Lego, Certification Section Head at (410) 537-4189 or via Email: rlego@mde.state.md.us or Environmental Compliance Specialist Mr. Frederick Miller at (410) 537-3479 or via Email: fmiller@mde.state.md.us or the Oil Control Program at (410) 537-3442.

Sincerely,

Thomas L. Walter, Chief
Compliance Division
Oil Control Program

TLW/sd
Enclosures
cc: Mr. Frederick Miller
Mr. Richard Lego
Mr. Herbert M. Meade
Mr. Horacio Tablada

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece

Macys Inc.
7 West 7th Street
Cincinnati, OH 45202

COMPLETE THIS SECTION ON DELIVERY

A. Signature
X [signature] ☐ Agent ☐ Addressee

B. Received by (Printed Name) | C. Date of Delivery

D. Is delivery address different from item 1? ☐ Yes
If YES, enter delivery address below: ☐ No

CINCINNATI OH MID CITY STA FEB 2 2009 USPS

3. Service Type
☑ Certified Mail ☐ Express Mail
☐ Registered ☐ Return Receipt for Merchandise
☐ Insured Mail ☐ C.O.D.

4. Restricted Delivery? (Extra Fee) ☐ Yes

2. Article Number (Transfer from service label) 7008 1830 0000 7901 3407

PS Form 3811, February 2004 Domestic Return Receipt 102595-02-M-1540

U.S. Postal Service™ CERTIFIED MAIL™ RECEIPT
(Domestic Mail Only; No Insurance Coverage Provided)
For delivery information visit our website at www.usps.com®

Postage $
Certified Fee
Return Receipt Fee (Endorsement Required)
Restricted Delivery Fee (Endorsement Required)
Total Postage & Fees $

Postmark Here

Sent To
Street, Apt. No.; or PO Box No.
City, State, ZIP+4

PS Form 3800, August 2006 See Reverse for Instructions

7008 1830 0000 7901 3407

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

Macys Inc.
7 West 7th Street
Cincinnati OH 45202

COMPLETE THIS SECTION ON DELIVERY

A. Signature
X [signature] ☐ Agent ☐ Addressee

B. Received by (Printed Name) | C. Date of Delivery

D. Is delivery address different from item 1? ☐ Yes
If YES, enter delivery address below: ☐ No

CINCINNATI OH MID CITY STA APR 13 2009 USPS 45202

3. Service Type
☑ Certified Mail ☐ Express Mail
☐ Registered ☑ Return Receipt for Merchandise
☐ Insured Mail ☐ C.O.D.

4. Restricted Delivery? (Extra Fee) ☐ Yes

2. Article Number (Transfer from service label) 7008 1830 0000 7899 6213

PS Form 3811, August 2001 Domestic Return Receipt 102595-02-M-1540

U.S. Postal Service™ CERTIFIED MAIL™ RECEIPT
(Domestic Mail Only; No Insurance Coverage Provided)
For delivery information visit our website at www.usps.com®

Postage $
Certified Fee
Return Receipt Fee (Endorsement Required)
Restricted Delivery Fee (Endorsement Required)
Total Postage & Fees $

Postmark Here

Sent To
Street, Apt. No.; or PO Box No.
City, State, ZIP+4

PS Form 3800, August 2006 See Reverse for Instructions

7008 1830 0000 7899 6213

ID: 520 | Add Record

WASTE MANAGEMENT ADMINISTRATION
OIL POLLUTION AND TANK MANAGEMENT

Print Record

Case No: | **INITIAL REPORT OF INCIDENT** | *Facility ID#:* 6267

CALLER:

1. Name of person Taking report: Nancy Nunn
2. Date of report: 3/30/2009
3. Time of report: 11:30 AM
4. Name of caller: John Goodwin
5. Telephone #: 410-491-6639
6. What agency or company is caller with: Ace Environmental: 410-354-8030

DETAILS OF SPILL:

7. AST or UST?
8. Date of incident: 3/30/2009
9. Time of incident:
10. Has product been released? Yes/No: No
11. Amount release:
12. Tank test failure? Yes/No: No
13. Tank failure rate:
14. **Precise location of the release or incident:**

Name: Macy's Inc.

Address: 6901 Security Blvd

City: Baltimore | State: MD | Zipcode: 21207 | County: BA

15. Nearest crossroad or other identifying mark:
16. Type of product involved: diesel
17. Quantity on board: 300-gal
18. Age of tank system: 10 yrs
19. Details of release:

Found buried copper lines during third-party inspection.

20. Has product entered water? Yes/No
21. Name of waterway:

RESPONSIBLE PARTY (RP)

22. RP's name: Macy's Inc. Dave Novak
23. RP's phone: 443-484-4529
24. RP's address:
25. Has RP taken any action to control the problem? Yes/No: No
26. If YES, what:

ACTION TAKEN:

Lead: Oil Control Program: ☑ Emergency Response: ☐ No Action Taken: ☐ Other: ☐

27. Inspector Assigned Case: Ray Kozlowski
28. Initials: GES

Maryland Department of the Environment

Oil Control Program, Suite 620, 1800 Washington Blvd., Baltimore MD 21230-1719
410-537-3442 410-537-3092 (fax) 1-800-633-6101 x3442 http://www.mde.state.md.us

Underground Storage Tank System Compliance Inspection Report

Instructions: Only a person currently certified by the Maryland Department of the Environment in UST Inspection shall complete this report. Detailed instructions on how to complete this form are provided in MDE's "UST Operations Inspector Reference Handbook," which is available at: http://www.mde.state.md.us/assets/document/OilControl/USTInspector_Reference_Handbook.pdf. Use a second form for facilities with more than 5 tanks. Type or Print all information with blue or black ink.

Section 1: General Information

Facility Name: Macy's Security Square Mall
Location Address: 6901 Security Boulevard
City: Baltimore, Maryland 21207
Telephone No.: (443) 484-4529
Owner Name: Macy's Inc.
Mailing Address: 7 West 7th Street
City, State, Zip: Cincinnati, Ohio 45202
Telephone No.: (513) 652-6702
Fax No.:
E-Mail:
Operator Name: Dave Novak
Telephone No.: (443) 484-4529 Cell : (301) 672-1181
Fax No.: (443) 484-4588
E-Mail: davidnovak@macys.com

RECEIVED
APR 20 2009
OIL CONTROL PROGRAM

MDE Facility ID Number:	Date of Inspection: mm/dd/yyyy	Current UST Registration Certificate on display or available onsite?	All applicable tanks registered?	Site located in High Risk Groundwater Use Area? *	Site or neighbor supplied by a potable Well? *	Owner/Operator has provided approved documentation to demonstrate Financial Responsibility?
6267	03/30/09	[√] Yes [ ] No	[√] Yes [ ] No	[ ] Yes [√] No	[ ] Yes [√] No	[√] Yes [ ] No If yes, attach FR proof to this form.

OK mgr

Inspection Summary

Tank System ID Number as listed on MDE UST Registration Form	Section No	Tank # 002	Tank # __	Tank #	Tank # __	Tank #
Owner Tank ID # (if different)						
Fill out the following using these codes: P=Pass Inspection, PC=Pass w/corrections, F=Fail Inspection, NA= Not Applicable						
Status: (Temporarily Out of Use)	(3.)	N/A				
Containment Sump Inspection	(4a.)	N/A				
Dispenser Inspection	(4b.)	N/A				
Tank Top Inspection	(5a.)	P				
Vent Pipe Inspection	(5b.)	P				
Spill Prevention P	(6a.)	F				
Overfill Prevention F	(6b.)	~~F~~ F				
Stage I Vapor Recovery	(7a.)	N/A				
Stage II Vapor Recovery	(7b.)	N/A				
Piping Construction and Corrosion Protection P	(8.)	P				
Tank Construction and Corrosion Protection P	(8.)	P				
Tightness Testing	(9.)	P				
Facility House Keeping	(10a.)	P				
Tank Field Monitoring Pipes and Site Wells See Sec 10b	(10b.)	F				
Inventory Control	(11.)	F				
Tank Release Detection N/A	(12.)	EXEMPT				
Piping Release Detection N/A	(12.)	EXEMPT				
Inspector and Owner/Operator has signed page 2 and initialed page 24		[√] Yes [ ] No				
Addendum Form Used		[Yes [√] No				

Section 1: General Comment

§ 4-417 Environment Article, Annotated Code of Maryland

(c) ***False statements in required documents; tampering with monitoring devices.*** Any person who knowingly makes any false statement, representation, or certification in any application, record, report, plan, or other document filed or required to be maintained under this title, or by any permit, rule, regulation or order issued under this title, or who falsifies, tampers with, or knowingly renders inaccurate any monitoring device or method required to be maintained under this title or by any permit, rule, regulation, or order issued under this title, upon conviction, is subject to a fine not exceeding $10,000, or by imprisonment not exceeding six months or both.

Certified Inspector: (print): John C. Goodwin
Company: Ace Environmental Services, LLC.
Certification No.: **MDIC 2007-0117**
Expiration. Date: **April 1, 2009**
Telephone No.: (410) 354-8030 Office ~ (410) 491-6639
Facsimile No.: (410) 354-8031
E-mail address: RckRsmssn@aol.com

***"High Risk Groundwater Use Area" (HRGUA) means all areas served by individual wells. Existing UST systems installed prior to 1/26/05 in Baltimore, Carroll, Cecil, Frederick and Harford counties or New UST systems installed after 1/26/05 in Anne Arundel, Baltimore, Carroll, Cecil, Charles, Calvert, Frederick, Harford, Howard, Montgomery, and Prince George's counties.**

The MDE UST database will be updated with information listed in this inspection report and any amended facility registration form unless additional forms are required by regulation.

Certified Inspector:	**Owner/Operator or Designated Representative**
I, the Maryland Certified Inspector, have performed this UST Inspection and believe the contents of this report to be true and accurate without misrepresentation or falsification. As well, I have no financial interest with this UST Facility.	I, the Owner/Operator/Designated Representative (circle one), have read this Inspection Report and understand the condition of my UST facility, including all deficiencies, corrections, and recommendations.
Print Name: John C. Goodwin	Title: ENGINEER
Signature:	Print Name: MARK FRANCZKOWSKI
Date: 30 MAR 09	Signature:
	Date: 3-30-09

Mail REPORT To:	**Questions? Call MDE Oil Control Program at**
MDE Oil Control Program	**410-537-3442**
Suite 620	**See our web page at:**
1800 Washington Blvd.	**http://www.mde.state.md.us**
Baltimore MD 21230-1719	

MDE Use Only

Certification Section – Reviewed By Melissa Purkey

Date Reviewed 05/05/09 Pass ____ Fail ✓

Comments (4) Violations

Data Clerk's Initials sdem Date Entered 5/22/09

Section 2: Tank System Information

Fill out the tank number for each tank but only use the MDE Tank ID numbering system. Use (√) box if information is obtained from facility registration form.

Tank and Piping (MDE ID#)	(√)	**Tank # 002**	**Tank # _**	**Tank #**	**Tank #**	**Tank #**
Owner Tank ID # (if different)						
Status (I-in use or T-temp. out of use)		I				
Date of Installation (month/year)	√	02/99				
Capacity (gallons)		300				
Product (see Chat A below for code and list each compartment tank product separately)		1				
Tank Construction Material (see Chart B for code)	√	6				
Compartment Tank (Yes/No) (If Yes, list capacity of each compartment separately)		/NO		/	/	/
Double-Wall Tank (Yes/No)		YES				
Piping Type (SS) safe suction; **(US)** U.S. suction **(G)** gravity; **(P)** pressure	√	SS				
Piping Construction Material (see Chart C for code)		4				
Double-Wall Piping (Yes/No)		No				
Outer Wall Pipe Construct. Material (see Chart C for code)		N/A				
Emergency Power Generator UST (Yes/No)		YES				

Global Position Signal – Only one set of coordinates is to be collected while standing over the center of each tank field.	**Tank Field #1**		**Tank Field #2**		**Tank Field #3**	
	Latitude: **N39.18.616'**	Longitude: **W076.45.054'**	Latitude:	Longitude:	Latitude:	Longitude:
List tank MDE ID # for each tank field according to MDE Registration Form.	**2**					

Section 2: Tank System Information continued on Page 4

CHART A

CODE	PRODUCT DESCRIPTION
1	Diesel
2	Gasohol **E-10**
2a	Ethanol **E-85**
2b	Methanol
3	Gasoline
4	Hazardous Substance
5	Heating Oil # 2
5a	Heating Oil # 4
5b	Heating Oil # 5
5c	Heating Oil # 6
6	Kerosene
7	Mixture
8	Used Oil
9	Car Wash O/W Separator UST
10	Other **(Must Describe)**

CHART B

CODE	TANK MATERIAL DESCRIPTION
1	Asphalt Coated or Bare Steel
2	Cathodically Protected Steel
3	Composite (Steel w/FRP)
4	Concrete
5	Epoxy Coated Steel
6	Fiberglass Reinforced Plastic (FRP)
7	Polyethylene Tank Jacket
8	Other **(Must Describe)**

CHART C

CODE	PIPING MATERIAL DESCRIPTION
1	Bare Steel
2	Galvanized Steel
3	Fiberglass Reinforced Plastic (FRP)
4	Copper
4a	Copper-slvd. in PVC, FRP or Plastic
5	Flexible Plastic
6	No Piping
7	Other **(Must Describe)**

L

Section 2: Tank System Information (cont'd.)

Diagram: Show layout of site and all UST systems.

KEY/LEGEND (Include if applicable)

- ○ 3 gallon AST Catchment Basin
- ● Interstitial Monitoring pipe
- ○ Vent



C.

Section 3: Tank Temporarily Closed or Taken Out of Service

Fill out this section for any tank that is "temporarily closed" or "taken out of service" (empty, out of use). A complete inspection of these tanks is required. This section does not apply to a tank that is currently in use or permanently out of use.

[ ] Applicable
[√] Not Applicable

#	Answer all (P)ass, (F)ail (PC), or (NA) for each Tank	Tank #_	Tank #_	Tank #_	Tank #_	Tank #_
1	Tank contains less than 1" of product.					
2	Tank vented and fill pipe locked.					
3	Date temp. closed or taken out of service (Month/Day/Year).					
4	UST closed 3 months or more, drain and cap product lines and secure other lines, pumps, and manways (vent line open and operating).					
Temporarily Closed Tank(s) passes inspection. Questions 1,2 and 4 are (P) or (PC)						

Section 4: Containment Sump and Dispenser Inspection

[ ] Applicable
[√] Not Applicable

4.a. Containment Sump Inspection

#	Complete 1 and 8. Answer (P)ass, (PC), (F)ail or (NA) for 2 – 7 (each tank)	Tank #	Tank #_	Tank #_	Tank #	Tank #
1	(√)Equipped with containment sump dispenser-					
	tank top -					
	vent riser -					
	Stage two-condensate pod -					
	Other – Specify in comments -					
2	All containment sumps are clean and free of debris, product, and water.					
3	All manway covers and containment sump lids are properly fitted and not in contact with cap, piping, or pump.					
4	All containment sumps have no visible cracks, holes, or openings.					
5	If sump equipped with liquid sensor the sensor is properly secured and within 1" of sump bottom or meets manufacturer's specifications.					
6	If equipped with double-wall piping, test boot is open to allow product flow to sump.					
7	Containment sump has been tested within past 5 years with passing results.					
8	Enter Date of last containment sump test.					
Containment Sump passes inspection. Questions 2 – 7 are (P) or (PC)						

Note: If answer to any question is (F), explain below. List any problems noted during inspection. Note corrections.

Comments:_____

[ ] Applicable
[√] Not Applicable

Section 4: Containment Sump and Dispenser Inspection (cont'd.)

4.b. Dispenser Inspection

#	Answer (P)ass, (PC), (F)ail or (NA) for each dispenser	Disp. #	Disp.#	Disp.#	Disp #	Disp #
1	Dispenser in good condition and properly secured to pump island.					
2	Shear valve (pressure system) properly secured and shear section within ½" of top of pump island or manufacturer specifications.					
2a.	Fusible link or other thermally actuated device properly connected.					
3.	Shear valve (Stage II piping) properly secured and shear section within ½" of top of pump island by manufacturer specifications **or** with flex connector.					
4	Dispenser hose in good condition with no cuts, or holes and equipped with breakaway device.					
5	Dispenser hose properly secured and not subject to damage from vehicle traffic (hose retractor).					
6	Emergency shut-off present.					
6a.	Emergency shut-off properly identified.					
6b.	Emergency shut-off in correct location.					
7	Dispenser is not leaking product.					
8	Flex connector observed under dispenser.If in contact with soil, complete Section 8.	(Circle one) Y / N	(Circle one) Y / N	(Circle one) Y / N	(Circle one) Y / N	(Circle one) Y / N
9	**Marina** Hold open device has been removed from nozzle.					
Dispenser passes inspection. Questions 1 – 7 and 9 are (P) **or** (PC)						

Note: ***If the answer to any question is (F), explain below. List any problems noted during inspection. Note corrections.***

If more then 5 dispensers include additional copies of this page.

Comments: _____

Section 5: Tank Top Components and Vent Pipe Inspection

5.a. Tank Top Inspection

#	Complete 1-3. Answer (P)ass, (PC), (F)ail or (NA) for 1a, 1b, and 4 -7 for each tank	Tank #002	Tank #	Tank #	Tank #	Tank #
1	Storage tank equipped with ATG? If Yes, complete 1a., 1b.	(Circle one) N	(Circle one)			
1a.	ATG riser is capped and electrical connection secure with proper grommet.	N/A				
1b	ATG manway lid properly fitted and not in contact with riser or electrical wires.	N/A				
2	Flex connector present on STP? If in contact with soil complete Section 8.	(Circle one) N/A	(Circle one)	(Circle one) N/A	(Circle one) N/A	(Circle one) N/A
3	Interstice monitoring system (double wall tank) or inspection station present?	(Circle one) YES	(Circle one)	(Circle one)	(Circle one)	(Circle one)
4	Ball Float riser and other riser pipes are fitted with proper caps; manway covers are not in contact with cap or riser pipe.	~~N/A~~ P				
5	No petroleum vapors present during ATG, Ball Float, or Vent riser inspection or STP without sump.	P				
6	Note all vapor field readings if taken for ATG, Ball Float, or Vent riser, or STP without sump.	N/A				
7	**Marina.** Each pipeline has a readily accessible shut-off valve grouped at one location on shore near approach to pier or dock and marked "emergency shut-off"?	N/A				
Tank Top Components passes inspection. Questions 1a., 1b.and 4 – 7are (P) or (PC) and 3 yes **or** component not required		P				

Note: If the answer to any question is (F), explain below. List any problems noted during inspection. Note corrections.

Comments: Passed based on answer to question 5 in Sec 6a. MSD

5.b. Vent Pipe Inspection

#	Answer (P)ass, (PC), (F)ail or (NA) for each vent	Tank#002	Tank#	Tank #	Tank #	Tank #
1	Vent pipe riser is constructed of steel?	P				
2	Vent pipe is properly anchored and protected from vehicle traffic (bollards or secured to building)?	P				
3	Vent pipe is proper height (flammable liquids 12 feet above ground surface and 2 feet above any attached building). (Combustible liquids minimum 3 feet above ground surface)?	P				
4	Equipped with vent cap (flammable liquid with Stage I vapor recovery must have pressure vent cap)?	P				
Vent passes inspection. Questions 1 – 4 are (P) **or** (PC)		P				

Note: If the answer to any questions is (F), explain below. List any problems noted during inspection. Note corrections.

Comments: There is a Scully Vent Whistle installed improperly on this UST. Vent whistle is not installed directly on top of tank, a coupling was installed at grade and a riser pipe installed above it.

Section 6: Spill and Overfill

6.a. Spill Device

#	Answer (P)ass, (PC), (F)ail or (NA)	Tank #002	Tank #	Tank #	Tank #	Tank #
1	Equipped with minimum 5-gallon catch basin. (Note: Used oil and heating oil USTs installed, upgraded, or replaced after 11-4-96 requires catch basin).	F				
2	Basin clean and free of debris and water.	P				
3	Basin has no cracks or holes observed.	P				
4	No abnormalities observed in fill pipe. (No bent drop tubes, no cracks or holes observed in basin especially at connection to tank and spill device).	p				
5	Basin lid fits properly and not in contact with fill cap.	P				
6	Fill pipe marked to indicate size of tank/type of product stored or Lid contains API color symbol w/posted sign to indicate tank size and type of product within delivery driver view.	P				
7	Catch basin tested within past year with passing results in accordance with Maryland Containment System Testing Protocol.	F				
7a.	Date of last test:	NA				
8	Spill device not required: (Tank receives less than 25-gallons of petroleum per delivery or heating oil UST installed prior to 11-4-96 is not required to have a spill device). If not required indicate (P).	N/A				
Spill device passes inspection. Questions 1 – 8 are (P) or (PC)		F				

Note: If the answer to any question is (F), explain below. List any problems noted during inspection. Note corrections.

Comments: **Basin needs to be tested. Tank has a Three gallon AST type catchment basin installed, this is not considered the proper type basin for this UST.**

C

Section 6: Spill and Overfill (cont'd.)

6.b. Overfill Device

#	Complete 2 – 4. Answer (P)ass, (PC), (F)ail or (NA) for 1 and 5 – 9	Tank # 002	Tank # ___	Tank # ___	Tank # ___	Tank # ___
1	Fill drop tube required and observed.	P				
2	Overfill device present (list all present): Flapper Valve (FV), Ball Float Valve (BFV), High Level Alarm (HLA), Other Describe.	Ø NONE.				
3	Indicate delivery method–gravity (G) or pump flow (PF).	PF				
4	Owner/Operator ensures releases due to spilling or overfilling do not occur? For example, product is measured prior to each delivery to ensure enough room in tank for product and all fuel deliveries are monitored.	(Circle one) Y / N	(Circle one) Y / N	(Circle one) Y / N	(Circle one) Y / N	(Circle one) Y / N
5	Visually observed overfill device housing, documentation of installation provided, OR certification provided from a certified UST installer attesting to overfill device operability.	~~P~~ F				
6	Tank receives less than 25-gallons of petroleum per delivery or heating oil UST installed prior to 11-4-96 is not required to have an overfill device.	N/A				
7	**Drop Tube Flapper Valve** Visual observation indicated flapper valve is present, with no obstruction in the drop tube that would render the device ineffective. *	N/A				
8	**Ball Float Valve / Vent Restrictor** Compatible with UST system configuration, delivery, and use. **	N/A				
9	**Audible External high level alarm only** Visual and audible alarm present to the driver at the point of transfer.	N/A				
Overfill device passes inspection. Question 4 is yes and 1 and 5– 9 (as applicable) are (P) or (PC)		~~P~~ F				

Note: If the answer to any question is No (N) or (F), explain below. List any problems noted during inspection. Note corrections.

****A fill pipe that utilizes a flapper valve in the drop tube for overfill purposes and receives a pressure delivery product drop, shall have a specific flapper valve designed for that use.***

***** If a UST system has one or more of the following, the owner or operator of the system shall not use a ball float valve on that system: (1) a tank that receives a pumped delivery; (2) suction piping with air eliminator; (3) remote fill pipes and gauge openings; (4) an emergency generator tank; (5) coaxial drop fill adapter.***

Comments: **Tank is a 300 gallon UST and has a vent whistle as its overfill method.**

C

Section 7: Stage I and II Inspection

Note: Stage I and II vapor recovery inspections also include completing and submitting Section 7c. forms to MDE's Air and Radiation Management Administration.

[ ] Applicable
[√] Not Applicable

7.a. Stage I Vapor Recovery

#	Complete 1 & 2 Answer (P)ass, (PC), (F)ail or (NA) for 3 – 6a. for each tank	Tank #	Tank #____	Tank #____	Tank #____	Tank #____
1	Is tank equipped with vapor recovery? (Yes) / (No) or (N/A). (If Yes for any tank, complete 2 through 6a. and section 7c.). **Stage I required Statewide**					
2	Type of vapor recovery: A – Coaxial B – 2 point system					
3	Dry break vapor cap and gasket in good condition?					
4	Poppet valve in dry break moves easily and closes tight?					
5	Vapor recovery connection equipped with minimum 5-gallon catchment basin. (If installed after July 1, 1998). (If 5 is N/A complete 5a. & 5b.).					
5a.	There are no petroleum vapors or staining in soil or pea gravel around vapor recovery riser pipe.					
5b.	Note all field readings if taken.					
6	Catchment basin tested within the past year with passing results.					
6a.	Date of last test.					
Stage I Passes Inspection. Question 1 is Y or NA and Questions 3 – 6a. are (P) **or** Stage I not applicable **or** (PC)						

Comments: _____

[ ] Applicable
[√] Not Applicable

7.b. Stage II Vapor Recovery

#	Answer for each tank	Tank #____	Tank #____	Tank #____	Tank #____	Tank #____
1	Does the storage system have Stage II? Yes or No. (If Yes, complete the sections below and 7c).	(Circle one) Y / **N**	(Circle one) Y / N	(Circle one) Y / N	(Circle one) Y / N	(Circle one) Y / N
2	Type of vapor recovery: Balance System -(BS) Vacuum Assist -(VA)					
3	UST system equipped with pressure control system and continuously monitors tank pressures.	Y / N	Y / N	Y / N	Y / N	Y / N
Stage II Passes Inspection. Question 1 is (Y) complete 2 **or** Stage II not applicable						

Comments:

_____
_____
_____

Section 8: Corrosion Protection

[√] Applicable
[ ] Not Applicable

A buried metal tank and piping (including fittings, flex-connectors, etc.) must be isolated from soil and cathodically protected. Commercial Heating Oil UST systems installed after March 15, 1985 require corrosion protection.

	√ Non-Metal Construction Material										
	Answer (P)ass, (PC), (F)ail or (NA) for each tank and pipe	**Tank 2**	**Pipe —**	**Tank #_**	**Pipe —**	**Tank #**	**Pipe**	**Tank #**	**Pipe**	**Tank #**	**Pipe**
1	**Tank:** Outer wall made of non-metallic material such as fiberglass or plastic jacket or coating.	P	N/A		N/A		N/A		N/A		N/A
2	**Pipe:** Outer wall made of non-metallic material such as fiberglass or flexible plastic.	N/A	N/A	N/A		N/A		N/A		N/A	
Non-Metal Construction passes inspection. Questions 1 and 2 are (P) or (PC) **Go to Section 9**		P									

#	**Check (√) type of corrosion protection for each tank and pipe, and answer (P)ass, (PC), (F)ail or (NA) for each tank and pipe**	**Tank #**	**Pipe 2**	**Tank #___**	**Pipe —**	**Tank #**	**Pipe**	**Tank #___**	**Pipe —**	**Tank #___**	**Pipe —**
	☐ √ **Galvanic Cathodic Protection (Tank and Piping)**										
3	**Tank:** CP on (sti-P_3®) tested within past 3 years and passed test in accordance with NACE Code of Practice Standard. If supplemental anodes were installed or added, complete 3a.		N/A		N/A		N/A		N/A		N/A
3a.	UST CP tested annually.		N/A		N/A		N/A		N/A		N/A
4	**Pipe:** CP tested within past year and passed test in accordance with NACE Code of Practice Standard.	N/A	P	N/A		N/A		N/A		N/A	
5	Record of last two cathodic protection tests on file with Owner or Operator.		P								
6	Cathodic protection system failure was inspected/repaired within 60 days of test.		P								
Galvanic Cathodic Protection passes inspection. Questions 3 – 6 are (P) or (PC) or 6 (NA)			P								
	☐ **Impressed Current Cathodic Protection (Tank and Piping)**										
7	Date impressed current system installed. (M/Y).										
8	Assessment performed at 5-year intervals.										
9	System has power and is turned on.										
10	Hour meter present? If (Y) complete 11.	(Circle one) Y / N		(Circle one) Y / N		(Circle one) Y / N		(Circle one) Y / N		(Circle one) Y / N	
11	Record hours:										
12	60-day inspection log is present and properly filled out.										
13	**Tank** tested within past year and passed test in accordance with NACE Code of Practice Standard.		N/A		N/A		N/A		N/A		N/A
14	**Pipe** tested within past year and passed test in accordance with NACE Code of Practice Standard.	N/A		N/A		N/A		N/A		N/A	
15	Records available for last two Impressed Current Cathodic Protection tests.										
16	Cathodic protection system failure was inspected/repaired within 60-days of test.										
Impressed Current Cathodic Protection passes inspection. Questions 8&9 and 12–16 are (P) or (PC)											

Section 8: Corrosion Protection (cont'd.)

	Internally Lined Tank	Tank #	Pipe	Tank #	Pipe	Tank #	Pipe	Tank #	Pipe	Tank #	Pipe
17	Documentation available and tank was less than 10 years old prior to installing liner.										
18	Documentation available and internal inspection performed to determine tank is structurally sound and free of corrosion holes prior to installing impressed current cathodic protection and liner.		N/A		N/A		N/A		N/A		N/A
19	Site assessment performed before installing liner.										
20	Date liner installed (Month / Year).										
21	Date of last internal inspection. (Month / Year).										
22	Internal inspection performed within 10 years of installation and every 5 years thereafter.										
Internal Liner passes inspection. Questions 17 – 19 and 22 are (P) **or** (PC)											
Note: If the answer to any question in section 8 is (F), explain below. List any problems noted during inspection. Note corrections.											

Comments:

STOP **IF A METALLIC TANK OR PIPE HAS NO CATHODIC PROTECTION NOTIFY MDE OIL CONTROL PROGRAM AT 410-537-3442.** STOP

Section 9: Tightness Testing Inspection

9. Tightness Testing (Tanks and Piping)

Complete this section if tank and/or pipe used periodic tightness testing.

#	Answer (P)ass, (PC), (F)ail or (NA) for each tank and pipe	Tank #002	Pipe 002	Tank #	Pipe	Tank #	Pipe	Tank #	Pipe	Tank #	Pipe
1	Test method on NWGLDE. Method Name: EZY 3 Locator Plus Method Name: EZY 3 Locator Plus	P	P								
2	Last tightness test results available and passed.	P	P								
3	Tightness testing conducted within specified time frames: at installation, at 15 years, and every 5 years thereafter for tanks NOT doing inventory control; annually for pressurized piping; every 2 years for non-exempt suction piping or be monitored monthly by approved leak detection method.	P	P								
4	**High Risk Groundwater Use Area** – Helium vapor test performed within past year with passing results.**	N/A	N/A								
4a.	**Date of last test.**	04/08	04/08								
Tightness Testing passes inspection. Questions 1 – 4 are (P) or (PC)		P	P								

Note: If the answer to any question is (F), please explain below. List any problems noted during inspection. Note corrections.

* www.nwglde.org (National Work Group on Leak Detection Evaluations)

***"High Risk Groundwater Use Area" (HRGUA) means all areas served by individual wells. Existing UST systems installed prior to 1/26/05 in Baltimore, Carroll, Cecil, Frederick and Harford counties or New UST systems installed after 1/26/05 in Anne Arundel, Baltimore, Carroll, Cecil, Charles, Calvert, Frederick, Harford, Howard, Montgomery, and Prince George's counties.*

Comments:

Questions regarding Helium Testing, call MDE Oil Control Program at 410-537-3442

Section 10: House Keeping and Monitoring Pipe/Well Inspectio

[√] Applicable

10.a. Facility House Keeping

#	Answer (P)ass, (PC), (F)ail or (NA)			
1	Facility is clean with no sign of spillage or open containers of oil.	P		
2	AST's (if present) are clean and properly maintained.	P		
3	Pump island area is clean with no indication of surface spillage.	N/A		
4	Garage area (if present) is maintained with no indication of surface spillage.	N/A		
House Keeping passes inspection. Questions 1 – 4 are (P) or (PC) or (NA)		P		

Note: If the answer to any questions is (F), explain below. List any problems noted during inspection. Note corrections.

10.b. Tank Field Monitoring Pipes

#	Answer (P)ass, (PC), (F)ail or (NA)	MP-1	MP-2	MP-3	MP-4
1	Storage systems installed after March 15, 1985 have PVC monitoring pipes installed on opposing corners of the tank field.	F	F		
1a.	Gasoline storage systems installed after January 26, 2005 +>2,000-gallons or multiple tanks in a shared excavation used to fuel motor vehicles located in HRGUA* have four monitoring pipes (each corner of the tank field).	N/A	N/A		
2	Monitoring pipes are screened to within 2ft. of the surface and the remaining 2ft. being solid pipe and sealed to prevent entrance of surface runoff.	F	F		
3	Monitoring pipe has liquid-tight cap, protected from traffic with manhole cover and locked or bolted closed.	F	F		
4	Monitoring pipe cover is clearly marked "monitoring well-do not fill" or identified using API color code symbol.	F	F		
5	Monitoring pipes checked for the presence of petroleum contamination and if present complete 5a.	F	F		
5a.	Record product thickness if taken. Record field vapor reading if taken.	~~N/A~~	~~N/A~~		

Site wells for Facilities located in HRGUA*		Answer (P)ass, (PC), (F)ail or (NA)			
6	Facility or immediate neighbor on either side supplied by potable well?	(Circle one) Y (N)			
7	Three or more groundwater monitoring wells installed outside of tank excavation area.	N/A			
8	Monitoring wells have liquid-tight cap, protected from traffic with manhole cover and locked or bolted closed.	N/A			
9	Groundwater has been sampled within 180 days and sample results available?	N/A			
10	Site potable well has been sampled within 180 days.	N/A			
Monitoring Pipes and Site Wells Pass Inspection. Questions 1 – 5 and 7 – 10 are (P) or (PC) or (NA)		~~F~~ N/A	F	F	

Note: If the answer to any question is (F), explain below. List any problems noted during inspection. Note corrections.
****"High Risk Groundwater Use Area" (HRGUA) means all areas served by individual wells. Existing UST systems installed prior to 1/26/05 in Baltimore, Carroll, Cecil, Frederick and Harford counties or New UST systems installed after 1/26/05 in Anne Arundel, Baltimore, Carroll, Cecil, Charles, Calvert, Frederick, Harford, Howard, Montgomery, and Prince George's counties.***

Comments: Could not find monitoring pipes, may be buried beneath the mulch and dirt in flower bed. Tank was installed in 1999 and should have had wells installed.

• No MP.

C

Section 11: Inventory Control

[√] Applicable
[ ] Not Applicable

For metered storage systems: complete items 1 – 10.
For non-metered storage systems: complete items 3 – 6.
For tanks using Inventory Control combined with SIR: also complete Section 12d.

#	Answer (P)ass, (PC), (F)ail or (NA) for each tank	Tank # 002	Tank #	Tank #	Tank #	Tank #
1	Readings recorded each day of operation.	NA				
2	Inventory records are reviewed daily and reconciled monthly. Note: Seven consecutive days of shortage totaling 80-gallons or more must be reported to owner and investigated.	NA				
3	Appropriate calibration tank chart is used for calculating volume to nearest 1/8 inch.	F				
4	Stick readings recorded before and after each delivery.	P				
5	Gauge stick is marked so the owner is capable of determining product level to the nearest 1/8 inch and stick is in good condition and not worn.	F				
6	Stick capable of measuring full height of tank.	F				
7	Monthly water readings checked to the nearest 1/8 inch and used in calculating inventory balances.	NA				
8	Prior 12 months of inventory data available.	NA				
9	Inventory variations do not exceed 1% + 130 gallons of the metered quantity (sales).	NA				
10	Existing inventory results show no evidence of a release, and no water intrusion.	NA				
Inventory Control Passes Inspection Questions 1 – 10 are (P) or (PC) or not applicable		F				
If using Statistical Inventory Reconciliation (SIR), also complete Section 12.d.						

Note: If answer to any question is (F), explain below. List any problems noted during inspection. Note corrections.

Comments:

Not sure the tank chart being used is for tank. Chart for a two hundred and ninety gallon tank. System listed as a three hundred gallon tank. Tank stick does not read in 1/8th inch increments and is not of proper length to measure tank properly.

Section 12: Release Detection Summary

This section indicates the method or methods of release detection present. Proceed to the section identified in the last column. Emergency power generator UST systems and heating oil (on-site consumptive use) UST systems are exempt from release detection.

Tank Method: Complete for each tank	**Indicate primary (PR) method and, if applicable, secondary (S) method for each tank**					**If using as primary method, proceed to section:**
	Tank #002	**Tank #_**	**Tank #_**	**Tank #**	**Tank #**	
Automatic Tank Gauging						12.a.
Vapor Monitoring						12.b.
Interstitial Monitoring						12.c.
Statistical Inventory Reconciliation						12.d.
Groundwater Monitoring						12.e.
Manual Tank Gauging						12.f.
None needed (Explain)	**exempt**					Skip section 12

Pipe Method: Complete for each pipe run	**Indicate primary (PR) method and, if applicable, secondary (S) method for each pipe run**					**If using as primary method, proceed to section:**
	Pipe # 002	**Pipe #**	**Pipe #**	**Pipe #**	**Pipe #**	
Pressurized piping only						
Automatic line leak detector (ALLD) will detect 3-gph release, double-wall pipe with containment sump and liquid sump sensor.						12.c. and 12.h.
ALLD will detect 3-gph release, double-wall pipe with containment sump and manual interstitial monitoring.						12.c. and 12.h.
Electronic ALLD will perform 3-gph continuous test plus 0.2-gph monthly test.						12.h.
Mechanical ALLD will detect 3-gph release in conjunction with annual line tightness test.						9 and 12.h.
Other combination: (Explain in comments)						
Suction piping only						
Line tightness test every 2 years.						9
Double wall piping with containment sumps utilizing electronic or manual interstitial monitoring.						12.c.
Safe Suction.	**PR**					12.g.
None needed (Explain)	**exempt**					Skip Section 12

Comments: _____

[ ] Applicable
[√] Not Applicable

Section 12.a. Automatic Tank Gauging (Tank Only)

#	Complete 1 and 4. Answer (P)ass, (PC), or (F)ail for 2,3,5 – 10.	Tank #	Tank#	Tank #	Tank #	Tank #__
1	Console Make and Model Make: Model:					
2	Monitoring console is working.					
3	Owner's manual for console and probes is available at site.					
4	Frequency ATG performs test (D) daily, (W) weekly, or (M) monthly.					
5	Device is calibrated, operated, and maintained per manufacturer's instructions in addition to limitations listed on evaluation summary NWGLDE* list.					
6	System setup reviewed and system capable of verifying probe(s) are functioning and documenting results.					
6a.	Attach copy of print out for the last monthly ATG tank leak test to this page.					
7	Tank is filled to proper capacity and test run for proper duration of time for last 2 months per NWGLDE* list.					
8	Verification that console and probe are third party approved and on the NWGLDE* list.					
9	Monthly release detection records are available and reviewed for past 12 months.					
10	Existing release detection results reviewed shows no failure.					
ATG passes inspection. Questions 2, 3 and 5 – 10 are (P) or (PC)						

Note: If the answer to any question is (F), explain below. List any problems noted during inspection. Note corrections.
****www.nwglde.org (National Work Group on Leak Detection Evaluations).***

Comments:

[ ] Applicable
[√] Not Applicable

Section 12.b. Vapor Monitoring (Tanks and/or Piping)

#	Complete 1. Answer (P)ass, (PC), (F)ail or (NA) for 2 – 11.	Tank #___	Tank #___	Tank #___	Tank #___	Tank #___
1	Console Make and Model Make:					
	Model:					
2	Monitoring panel and/or control box is working.					
3	Verification that the Vapor Monitoring device is third-party approved and on the NWGLDE* list.					
4	Owner's manual for the Vapor Monitoring device is available at the site.					
5	The material used as backfill is sufficiently porous, such as pea gravel or sand, to readily allow diffusion of vapors from releases into the excavation zone.					
6	Vapor Monitors are designed, calibrated, and operated to detect an increase in concentration of the regulated substance, a component of the regulated substance, or a tracer compound placed in the tank system and maintained per manufacturer's instructions in addition to limitations listed on evaluation summary NWGLDE* list.					
7	Site evaluation report is on site and verifies the above information and that background contamination will not interfere with vapor monitoring. **Attach evaluation cover page.**					
8	System setup reviewed and proper settings confirmed correct. Verification all probes functioning.					
9	Vapor Monitors are checking portion of tank and piping that routinely contain product.					
10	Monthly release detection records are available for last 12 months.					
11	Existing release detection results show no evidence of a release.					
Vapor Monitoring passes inspection. Questions 2 – 11 are (P) **or** (PC)						

Note: If the answer to any question is (F), please explain below. List any problems noted during inspection. Note corrections.
*** www.nwglde.org (National Work Group on Leak Detection Evaluations).***

Comments:

[ ] Applicable
[√] Not Applicable

Section 12.c. Interstitial Monitoring (Tank and Piping)

#	Complete 1 and 3 for Electronic and Answer (P)ass, (PC), (F)ail or (NA) 2&4–10 for each Tank and Pipe	Tank #	Pipe #	Tank #___	Pipe #___	Tank #___	Pipe #___	Tank #___	Pipe #___	Tank #___	Pipe #___
1	Type of interstitial monitoring: i.e. Liquid (L), Air Space (AS), or Pressure/vacuum (PV). List each if different.										
Manual /Visual Inspection Only											
2	Interstitial space is monitored and a written log is maintained monthly.										
Electronic System Only											
3	Console make/ model Make:										
	Model:										
4	Console and sensor on NWGLDE* list										
5	Monitoring console is operational.										
6	Interstitial space monitored monthly. **										
7	Device is calibrated, operated, and maintained per manufacturer's instructions in addition to limitations listed on evaluation summary NWGLDE* list.										
Summary											
8	Monthly release detection records are available for prior 12 months with passing results.										
9	No evidence of liquid in sump or interstitial space of air filled system. **No evidence of loss or gain of brine in brine filled system.** Operation of partial vacuum or over pressure system is within manufacturer's design specifications.										
10	No visible leaks or holes in secondary containment.										
Interstitial Monitoring passes inspection. Questions 2 and 8 – 10 are (P) **for Manual** Questions 4 – 10 are (P) **or** (PC) **for Electronic**											

Note: If the answer to any question is (F), please explain below. List any problems noted during inspection. Note corrections.
Monitor interstitial space at lowest point of secondary containment for air filled or at highest point of secondary containment for Brine filled and is positioned so that other equipment will not interfere with its proper operation. ***See manufacture specifications and NWGLDE listing limitations for continual partial vacuum or overpressure interstitial monitoring.*
**www.nwglde.org (National Work Group on Leak Detection Evaluations).*

Comments: _____

[ ] Applicable
[√] Not Applicable

Section 12.d. Statistical Inventory Reconciliation

Complete this section and Section 11 (Inventory Control) if you use Statistical Inventory Reconciliation (SIR).

	Answer (P)ass, (PC), (F)ail for each tank system.	**Tank #**	**Pipe #**	**Tank #___**	**Pipe #___**	**Tank #___**	**Pipe #___**	**Tank #___**	**Pipe #___**	**Tank #___**	**Pipe #___**
1	SIR method on NWGLDE* list. Method Name: **Simmons Corporation**		NA		NA		NA		NA		NA
2	Inventory records are submitted to the SIR vendor within 5 days of the 30 day monitoring period.		NA		NA		NA		NA		NA
2a	SIR results are received by owner from vendor within 15 days of submittal of data.		NA		NA		NA		NA		NA
3	SIR results indicate sufficient amount of Data was used to perform leak check.		NA		NA		NA		NA		NA
4	Existing release detection results show no evidence of a failure for the previous 12 months.		NA		NA		NA		NA		NA
Statistical Inventory Reconciliation (SIR) Passes Inspection. Questions 1 – 4 are all (P) or (PC).			NA		NA		NA		NA		NA

Note: If the answer to any question is (F), explain below. List any problems noted during inspection. Note corrections.
****www.nwglde.org (National Work Group on Leak Detection Evaluations)***

Comments:

[ ] Applicable
[√] Not Applicable

Section 12.e. Groundwater Monitoring

#	**Answer (P)ass, (PC), (F)ail for each tank system**	**Tank #___**	**Pipe #___**	**Tank #___**	**Pipe #___**	**Tank #___**	**Pipe #___**	**Tank #___**	**Pipe #___**	**Tank #___**	**Pipe #___**
1	Groundwater at site is not more than 15 feet from ground surface during inspection.										
2	Slotted casing is properly screened across the water table to allow entry of product.										
3	Monitoring wells intercept the UST excavation zone or positioned as close as technically feasible.										
4	Regulated substance is immiscible in water and has a specific gravity of less than one.										
5	Site evaluation report on site and verifies above information and background contamination will not interfere with groundwater monitoring. **Attach evaluation cover page.**										
6	Monitoring device is capable of detecting 1/8 inch of free product and wells are monitored monthly with results recorded.										
Groundwater Monitoring passes inspection. Questions 1 – 6 are all (P) **or** (PC)											

Note: If the answer to any question is (F), please explain below. List any problems noted during inspection. Note corrections.

Comments:

[ ] Applicable
[√] Not Applicable

Section 12.f. Manual Tank Gauging (Tank Only)

#	Answer 1–5 (P)ass, (PC), (F)ail or (NA) for each Tank	Tank #	Tank #__	Tank #__	Tank #__	Tank #__
1	Tank is 550-gallons or less.					
2	Tank is 551 to 2,000-gallons. **Note**: Must be combined with tightness testing.					
3	Gauging stick is capable of measuring the full height of the tank to the nearest 1/8" in conjunction with the appropriate tank calibration chart on site.					
4	Monthly log is maintained. *					
5	Last 12 months of records show no failure.					
Manual Tank Gauging passes inspection. Questions 1 or 2 and 3–5 are (P) or (PC)						

Note: If the answer to any question is (F), explain below. List any problems noted during inspection. Note corrections.
**** See Inspector guidance book or COMAR 26.10.05.04C. for weekly and monthly variation standard.***
Comments: _____

[ ] Applicable
[√] Not Applicable

Section 12.g. Safe Suction (Suction Piping Only)

#	Answer (P)ass, (F)ail, or (PC) for each pipe	Pipe #	Pipe #	Pipe #	Pipe #	Pipe #
1	The piping slope is back to the tank and operates under atmospheric pressure or less.					
2	Confirm a single check valve is located directly under the dispensing pump.					
Safe Suction passes inspection. Questions 1 and 2 are (P) or (PC)						

Note: If the answer for 1or 2 is (F), another type of release detection must be used and inspected. Fill out the applicable section on piping release detection. List any problems noted during inspection. Note corrections.
Comments: _____

[ ] Applicable
[√] Not Applicable

Section 12.h. Automatic Line Leak Detectors (Pressurized Piping Only)

#	Complete 1 Answer questions 2 – 7 (P)ass, (F)ail or (PC)	Pipe #	Pipe #	Pipe #	Pipe #	Pipe #___
1	Mechanical or Electronic (M - Mechanical or E - Electronic)					
2	Is the equipment on the NWGLDE* list.					

Section 12: Release Detection (cont'd.)

3	All ALLDs pass an annual field operability test for detection of a 3.0-gph leak.					
4	Device is calibrated, operated, and maintained per manufacturer's instructions in addition to limitations listed on evaluation summary NWGLDE* list.					
5	Line Leak Detector shows no evidence of a visual release.					
6	Is the entire piping system covered by the ALLD (including satellite pipe if present)?					
7	For an electronic ALLD, last record of passing 3.0-gph test result for each pipe is within the previous 72 hours.					
8	Does the STP shut off when the dispensers are not pumping?					
ALLD Passes Inspection. Questions 2 – 8 are (P) or (PC)						

Note: If the answer to any question is (F), please explain below. List any problems noted during inspection. Note corrections

****www.nwglde.org (National Work Group on Leak Detection Evaluations)***

COMMENTS: _____

Section 13 Suspected Release

Answer (Y)es or (N)o for 1 and if yes answer 2

1	Do you suspect or have you detected a release during this inspection?	[ ] Yes [√] No		
2	Did you report this suspected or detected release to the Department?	[ ] Yes [ ] No	DATE:	TIME:

STOP

Report all known or suspected spills or leaks

Call Maryland Department of the Environment 410-537-3442

Or call: 1-866-633-4686 after business hours

STOP

GENERAL COMMENTS:

_____

_____

_____

Please return original report no later than thirty (30) days after inspection date.	**MDE Oil Control Program** Suite 620 1800 Washington Blvd. Baltimore, MD 21230-1719

Questions? Call MDE Oil Control Program at 410-537-3442

Internet: http://www.mde.state.md.us/Programs/LandPrograms/Oil_Control/home/index.asp.

Inspector's Initials _____

Date 30 MAR 09

Owner/Operator's Initials _____

Date _____

MARYLAND DEPARTMENT OF THE ENVIRONMENT
Waste Management Administration
Oil Control Program

MEMORANDUM

TO: Ray Kozlowski

FROM: Debbie Tinsley

THROUGH: Mike Frank

DATE: 06/19/09

Re: Facility ID No. 6267

* *

A Third Party Inspection was completed at the above referenced facility. The facility failed the compliance inspection and requires a follow-up inspection by the Oil Control Program. Please document each of the violation(s), if the owner has corrected the violation(s) note the time and date when the correction(s) were made. Your field report must be detailed and well written.

Attached are the portions of inspection report that failed and a copy of our Third Party Database inspection summary. If you need additional facility information from the inspection report please notify Sheila Dean.

Inspectors are to work with your supervisor regarding compliance activities and appropriate enforcement actions. Inspectors are to provide Sheila Dean with the information when the violations have been corrected so the third party database can be updated. The compliance information is reported to EPA and the database must be current.

MARYLAND DEPARTMENT OF THE ENVIRONMENT
Oil Control Program, Suite 620, 1800 Washington Blvd., Baltimore MD 21230-1719
410-537-3442 • 410-537-3092 (fax) 1-800-633-6101

Martin O'Malley
Governor

Anthony G. Brown
Lieutenant Governor

Shari T. Wilson
Secretary

Robert M. Summers, Ph.D.
Deputy Secretary

June 19, 2009

Macys Inc.
7 West 7th Street
Cincinnati OH 45202

RE: NOTICE TO CORRECT UST DEFICIENCIES
Facility I.D. No. 6267 Baltimore
Hecht's
6901 Security Blvd.
Baltimore

Dear Sir or Madam:

The Waste Management Administration's Oil Control Program has received and performed a technical review of the Underground Storage Tank (UST) System Inspection Report submitted for the above referenced facility. The inspection identified deficiencies in the installation, operation, testing or maintenance of the UST System(s).

As the registered owner of the underground storage tank system(s) and in accordance with COMAR 26.10.03.10C.(2) you are hereby given **Notice** that the deficiencies shall be corrected within thirty (30) days from receipt of this Notice in accordance with Code of Maryland Regulations (COMAR) 26.10.02—.11. The (UST) system(s) must be **repaired, upgraded, or replaced** only in the continuous on-site presence and under the direction of an individual who is a Maryland Department of the Environment (MDE) Certified Underground Storage Tank System Technician.

Enclosed is an Owner's Summary Form documenting the deficiencies found during the inspection. Please refer to the **failed section number** on the owner's summary form and the **tank number that failed** on the Inspection Report provided to you by the inspector. The Department must receive notification and proof from the owner attesting to the repair, upgrade, or replacement that has been completed and the date the corrections took place.

You will also find a list of MDE certified technicians enclosed with this notice. You must choose and contact a company who employs a Maryland Certified Technician and have all of the UST system deficiencies corrected at your facility within thirty (30) days. Please mail the required documentation to: Maryland Department of the Environment, Oil Control Program, 1800 Washington Blvd. Suite 620, Baltimore, MD 21230-1719, **Attn: Inspector Raymond Kozlowski**. Include the MDE Facility I.D. Number on the top right corner of all documents submitted.

Failure to perform the required UST system(s) repair, upgrade, or replacement and submit the completed documentation to the Department within the required thirty (30) days may result in enforcement action from the Department that could include issuance of civil penalties and other legal sanctions.

If you have any questions regarding UST deficiency corrective actions, please call the Case Manager listed above in this letter at (410) 537-3442.

If you have any questions that pertain to MDE Certifications and Inspection Program, please feel free to contact Environmental Compliance Specialist Mr. Frederick Miller at (410) 537-3479 or via Email: fmiller@mde.state.md.us or me at (410) 537-4189 or via Email: rlego@mde.state.md.us or the Oil Control Program at (410) 537-3442.

Sincerely,

Richard D. Lego, Section Head
Certification Section, Oil Control Program

RDL/sd
Enclosures
cc: Mr. Frederick Miller
Mr. Thomas L. Walter
Mr. Herbert M. Meade
Mr. Horacio Tablada

(866) 750-4ACE
(410) 729-4088

ACE ENVIRONMENTAL SERVICES, LLC
3512 Fairfield Road
Baltimore, Maryland 21226

(410) 729-4087
FAX

RECEIVED
AUG 24 2009
OIL CONTROL PROGRAM

August 13, 2009

Maryland Department of the Environment
Oil Control Program, Suite 620
1800 Washington Boulevard
Baltimore, Maryland 21230-1719

Attn: Ray Kozlowski
Phone: (410) 537-3442
Fax: (410) 537-3092

RE: Macy's – Security Mall
6901 Security Boulevard
Baltimore, MD
Facility ID #: 6267

On July 30, 2009, ACE Environmental Services, LLC completed the following repairs at the above referenced location.

Section 6a: Supplied and installed one (1) 5 gallon spill containment basin and conduct the required hydrostatic testing.

Section 11: Supplied the customer with the proper tank stick, tank gauging chart and inventory tracking sheet for UST gauging prior to and after fuel deliveries.

*During this work, ACE attempted to locate Tankfield Monitoring wells. No wells of any type were located. This UST is located in a raised planter area that will be difficult access with drilling equipment. The UST owner asks if your administration would consider a variance for this matter.

Enclosed with this report, please find a copy of the Spill Basin Hydrostatic Test report.

Please do not hesitate to contact me at (410) 354-8030 with any questions.

Sincerely,

Randi Barra
Managing Partner

ACE ENVIRONMENTAL

LEADERS IN CLIENT SATISFACTION

(866) 750-4ACE
(410) 729-4088
(410) 354-8030

3512 Fairfield Road
Baltimore, Maryland 21226

(410) 354-8031
FAX

CATCHMENT BASIN & SUMP TEST LOG

Client: **Macy's – Security Mall**
6901 Security Boulevard
Baltimore, Maryland

Test Date: **30 Jul 09**

Tank #: **1 / #2 Diesel**

Catchment Basin Size: **5 GAL.**

Condition: **New Steel**

Start Time: **08:45** **am** or pm

Liquid Level: **06.75** inches

Stop Time: **10:00** **am** or pm

Finish Level: **06.75** +/- inches

Basin Passed or Failed Per MDE Testing Criteria {Circle One}

Sump Size and Type: _____

Condition: _____

Start Time: _____ am or pm

Liquid Level: _____ inches

Stop Time: _____ am or pm

Finish Level: _____ +/- inches

Sump Passed or Failed Per MDE Testing Criteria {Circle One}

Tester Signature: _____

Cert. #: **MDIC ~ 2008 - 0946**

MARYLAND DEPARTMENT OF THE ENVIRONMENT
1800 Washington Avenue, Suite 620 • Baltimore Maryland 21230-1719
(410) 537-3442 • 1-800-633-6101 • http://www.mde.state.md.us

WASTE MANAGEMENT ADMINISTRATION
Oil Control Program

Report of Observations

Type of Inspection/Observations: Third Party Follow-up
Site/Facility Name: Macy's
Location: 6901 Security Blvd

Facility ID 6267
Date: 7-27-09
Case No.

Telephone: Ext.

Facility Inspection Status FAIL

Remarks:

Status	Section No.	Comments
Fail	6a.	Upgrade spill bucket to 5 gallon capacity
Fail	6a.	Test spill bucket and furnish results
Fail	6b.	Furnish documentation that overfill device (vent whistle) is operable
Fail	10b.	Furnish documentation of 2 monitoring pipes in opposing corners of tank field
Fail	10b.	Furnish documentation that monitor pipes are screened properly
Fail	10b.	Furnish documentation that monitor pipes have liquid tight caps and are locked or bolted
Fail	10b.	Furnish documentation that monitor pipe covers are properly marked
Fail	10b.	Furnish documentation that there is no petroleum product in the monitor pipes.
Fail	11	Obtain correct tank calibration chart for tank (300 gallon as registered)
Fail	11	Obtain correct gauge stick capable of measuring to 1/8 inch increments
Fail	11	Obtain gauge stick that is of correct length to measure full height of tank

MDE Inspector:
(Print) RAY KOZLOWSKI
Sign: R. J. Kozlowski

Person Interviewed:
(Print) VIA TELEPHONE CALL
Sign: _____

MARYLAND DEPARTMENT OF THE ENVIRONMENT
1800 Washington Avenue, Suite 620 • Baltimore Maryland 21230-1719
(410) 537-3442 • 1-800-633-6101 • http://www.mde.state.md.us

WASTE MANAGEMENT ADMINISTRATION
Oil Control Program

Report of Observations

Type of Inspection/Observations: Third Party Follow-up
Site/Facility Name: Macy's
Location: 6901 Security Blvd

Facility ID 6267
Date: 8/31/2009
Case No.

Telephone: Ext.

Facility Inspection Status PASS

Remarks:

Status	Section No.	Comments
Pass-F	6a.	Spill bucket replaced to 5 gallon capacity
Pass-F	6a.	Spill bucket tested and results furnished
Pass-F	6b.	Overfill device (vent whistle) is operable
Pass-F	10b.	Requested waiver granted, no monitor pipes or well to be installed at site. Tank tester must determine ground water level around tank during testing.
Pass-F	10b.	See above
Pass-F	10b.	See above
Pass-F	10b.	See above
Pass-F	10b.	See above
Pass-F	11	Correct tank calibration chart for tank (300 gallon as registered) on site
Pass-F	11	Correct gauge stick capable of measuring to 1/8 inch increments on site
Pass-F	11	gauge stick that is of correct length to measure full height of tank is on site

MDE Inspector:
(Print) RAY KOZLOWSKI
Sign: RKozlowski

Person Interviewed:
(Print) VIA FAX
Sign: _____

MESSAGE CONFIRMATION

SEP-09-2009 07:05 AM WED

FAX NUMBER : 4105373092
NAME : MDE

NAME/NUMBER : 914434844588
PAGE : 2
START TIME : SEP-09-2009 07:04AM WED
ELAPSED TIME : 00'18"
MODE : STD ECM
RESULTS : [O.K]

MARYLAND DEPARTMENT OF THE ENVIRONMENT
Oil Control Program, Suite 620, 1800 Washington Blvd., Baltimore MD 21230-1719
410-537-3442 • 410-537-3092 (fax) 1-800-633-6101, ext. 3442

Martin O'Malley
Governor

Anthony G. Brown
Lieutenant Governor

Shari T. Wilson
Secretary

Robert M. Summers, Ph.D.
Deputy Secretary

FAX COVER SHEET

TO: DAVE NOVAK

FAX NUMBER: 443-484-4588

RE: INSPECTION

FROM: RAY KOZLOWSKI

# of pages including cover: 2

Comments:

MARYLAND DEPARTMENT OF THE ENVIRONMENT
1800 Washington Avenue, Suite 620 • Baltimore Maryland 21230-1719
(410) 537-3442 • 1-800-633-6101 • http://www.mde.state.md.us

WASTE MANAGEMENT ADMINISTRATION
Oil Control Program

Report of Observations

Type of Inspection/Observations: Third Party Follow-up
Site/Facility Name: Macy's
Location: 6901 Security Blvd

Facility ID 6267
Date: 8/31/2009
Case No.

Telephone: Ext.

Facility Inspection Status PASS

Remarks:

Status	Section No.	Comments
Pass-F	6a.	Spill bucket replaced to 5 gallon capacity
Pass-F	6a.	Spill bucket tested and results furnished
Pass-F	6b.	Overfill device (vent whistle) is operable
Pass-F	10b.	Requested waiver granted, no monitor pipes or well to be installed at site. Tank tester must determine ground water level around tank during testing.
Pass-F	10b.	See above
Pass-F	10b.	See above
Pass-F	10b.	See above
Pass-F	10b.	See above
Pass-F	11	Correct tank calibration chart for tank (300 gallon as registered) on site
Pass-F	11	Correct gauge stick capable of measuring to 1/8 inch increments on site
Pass-F	11	gauge stick that is of correct length to measure full height of tank is on site
------	--------	

MDE Inspector:
(Print) Ray Kozlowski
Sign: R Kozlowski

Person Interviewed:
(Print) VIA FAX
Sign: _____

MARYLAND DEPARTMENT OF THE ENVIRONMENT
Oil Control Program, Suite 620, 1800 Washington Blvd., Baltimore MD 21230-1719
410-537-3442 • 410-537-3092 (fax) 1-800-633-6101

Martin O'Malley
Governor

Anthony G. Brown
Lieutenant Governor

Robert M. Summers, Ph.D.
Secretary

NOTICE TO INSPECT

Date: January 4, 2012

Facility I.D. No. 6267 Baltimore
Macy's Security Square Mall
6901 Security Blvd.
Baltimore

Inspection Report Due Date:
March 4. 2012

Failure to perform the required inspection and submit the completed Inspection Report to the Department by the due date may result in enforcement action from the Department that could include issuance of a delivery ban, civil penalties and other legal sanctions.

Macy's Inc.
7 West 7th Street
Cincinnati OH 45202

As the registered owner of an underground storage system located at the above facility, you are hereby given **Official Notice** to have your underground petroleum storage tank system(s) inspected by a Maryland Department of the Environment (MDE) Certified Underground Storage Tank System Inspector and submit the inspection report to the Department by the due date. In accordance with Code of Maryland Regulations (COMAR) 26.10.03.10A. "An underground motor fuel storage tank owner shall have each underground storage tank system inspected by a certified inspector at the frequency established in Subsection B—E of this regulation. The inspection shall verify compliance with COMAR 26.10.02—.11 on forms provided by the Department". The owner of an underground motor fuel storage tank system shall complete a certified inspection of that system at least once every three (3) years after the initial inspection.

You must choose and contact a company who employs a Maryland Certified Inspector to inspect your UST system(s). The cost of the inspection may vary. The MDE will not participate in the billing and collection process. Submittal of the inspection report to the Department is required by the due date in this notice. The MDE will not arbitrate nor accept disputes regarding an inspection finding as a reason for a delay in the report submittal.

As the registered owner or operator of the UST system(s), it is your responsibility to maintain your operation in compliance with Code of Maryland Regulations. Failure to perform the required inspection and submit the completed Inspection Report to the Department by the due date may result in enforcement actions from the Department that could include issuance of a delivery ban, civil penalties and other legal sanctions.

Additional important information regarding the inspection, corrective actions and UST ownership changes is available on the back of this notice. Questions regarding the Third Party Inspection Program and required facility inspection may be directed to the Oil Control Program Certification Section at (410) 537-3442.

Mail Inspection Report To:
Maryland Department of the Environment
Oil Control Program
Suite 620
1800 Washington Blvd.
Baltimore, MD 21230-1719

Important Information:

- A Summary Printout of the UST(s) registered with the Department is available on the MDE web site at: http://167.102.133.155/facilitysummary/Default.aspx

- "Owner Fact Sheet/Preparing for an UST Inspection" is available on the MDE web site at: http://www.mde.state.md.us/programs/Land/OilControl/UndergroundStorageTanks/Pages/Programs/LandPrograms/Oil_Control/usthome/ustcertification_programs.aspx
  It is recommended owners discuss with the certified inspector the required information needed to complete the inspection **prior to** the inspection date.

- A list of companies employing MDE Certified UST Inspectors is available on the MDE web site at: http://www.mde.state.md.us/programs/Land/OilControl/UndergroundStorageTanks/Pages/Programs/LandPrograms/Oil_Control/usthome/ustcertification_programs.aspx
  MDE encourages UST owners and operators to ask to see the inspector's MDE Certified Underground Storage System Inspector card (yellow card with the State Seal in the background with an (I) in the upper right corner). The card will have an expiration date and must be valid at the time of the inspection.

  MDE will not accept inspection reports when it has been determined there is a "Conflict of Interest" of COMAR 26.10.06.10 Conflict of Interest, " A. Except as provided in §B of this regulation, a certified inspector may not be: 1) The owner or operator of the tank; 2) An employee of the tank owner; or 3) A certified technician on the same installation, replacement, or upgrade activity for which the technician is a certified inspector. B. A certified inspector who is also a certified technician may correct deficiencies during a compliance inspection of the operation of an underground storage system."

- For more information you may contact the Maryland Department of the Environment's Oil Control Program at (410) 537-3442 or visit our web site at: http://www.mde.state.md.us/programs/Land/OilControl/Pages/programs/landprograms/oil_control/index.aspx

- The Department's facility registration database will be amended to reflect the information provided in the UST inspection report.

Required Corrective Actions Following an Inspection:
The owner of an underground storage tank system(s) shall have **thirty (30) days** to correct all deficiencies found during the inspection, in accordance with COMAR 26.10.02—.11 unless an alternative schedule is required or approved by the Department. Many minor deficiencies found (example: clean containment sumps, tighten fittings, mark fill pipes, etc.) may be corrected at the time of the inspection. Only an MDE UST Certified Technician may upgrade, repair, install or close a UST system. The owner must submit all documentation to MDE confirming the corrective action(s). Documents submitted must include the Facility I.D. No. in the top right corner of each document.

After the inspection, you should discuss with the Third Party Inspector their findings and any deficiencies found during the inspection. The Department believes it is the inspector's obligation to explain, provide a summary of the findings or review any deficiencies found during the inspection process to allow the owner/operator to understand the deficiencies so that repairs or corrections can be performed in an efficient and timely manner. Remember, it is your responsibility to maintain and operate the underground storage system(s) in compliance with Maryland laws and regulations. Being prepared will make your inspection go smoothly and limit business disruption.

UST Ownership Change:
Immediately notify the MDE Oil Control Program in writing of the change by providing the date the change occurred, the name, address and telephone number (if available) for the new owner and any other pertinent information confirming the change.

Maryland Department of the Environment

Oil Control Program, Suite 620, 1800 Washington Blvd., Baltimore, MD 21230-1719
410-537-3442 410-537-3092 (fax) 1-800-633-6101 x3442 http://www.mde.state.md.us

Underground Storage Tank System Compliance Inspection Report

Instructions: Only a person currently certified by the Maryland Department of the Environment in UST Inspection shall complete this report. Detailed instructions on how to complete this form are provided in MDE's "UST Operations Inspector Reference Handbook," which is available at http://www.mde.state.md.us/Programs/LandPrograms/Oil_Control/home/index.asp. Use a second form for facilities with more than 5 tanks. Type or Print all information with blue or black ink.

RECEIVED
MAR 28 2012
OIL CONTROL PROGRAM

Section 1: General Information

Facility Name:	**Macy's Security Square Mall**
Location Address:	**6901 Security Blvd**
City:	**Baltimore, MD**
Telephone No.:	
Owner Name:	**Macy's Inc.**
Mailing Address:	**7 West 7th Street**
City, State, Zip:	**Cincinnati, OH 45202**
Telephone No.:	**513-562-6702**
Fax No.:	
E-Mail:	
Operator Name:	**Robert Kozul**
Telephone No.:	**215-331-8310**
Fax No.:	
E-Mail:	

on file self insured expires 6/14/12

MDE Facility ID Number:	Date of Inspection: mm/dd/yyyy	Current UST Registration Certificate on display or available onsite?	All applicable tanks registered?	Site located in High Risk Groundwater Use Area? *	Site or neighborhood supplied by potable well? *	Owner/Operator has provided approved documentation to demonstrate Financial Responsibility?
6267	February 22, 2012	**Yes**	**Yes**	No	**No**	**Yes**
						If yes, attach FR proof to this form.

Inspection Summary

Tank System ID Number as listed on MDE UST Registration Form / Owner Tank ID # (if different)	Section No.	Tank # 2	Tank #	Tank #	Tank #	Tank #	Tank #	Tank #
Status: (Temporarily Out of Use)	(3.)	NA						
Containment Sump Inspection	(4a.)	NA						
Dispenser Inspection	(4b.)	NA						
Tank Top Inspection	(5a.)	P						
Vent Pipe Inspection	(5b.)	P						
Spill Prevention P	(6a.)	F						
Overfill Prevention P	(6b.)	P						
Stage I Vapor Recovery	(7a.)	NA						
Stage II Vapor Recovery	(7b.)	NA						
Piping Construction and Corrosion Protection F	(8.)	F						
Tank Construction and Corrosion Protection P	(8.)	P						
Tightness Testing	(9.)	F						
Facility House Keeping	(10a.)	P						
Tank Field Monitoring Pipes and Site Wells See 10b	(10b.)	F						
Inventory Control	(11.)	F						
Tank Release Detection NA	(12.)	NA						
Piping Release Detection NA	(12.)	NA						
Inspector and Owner/Operator has signed page 2 and initialed page 24							Yes	
Addendum Form Used							No	

RK

Section 1: General Comment

§ 4-417 Environment Article, Annotated Code of Maryland

(c) False statements in required documents; tampering with monitoring devices. Any person who knowingly makes any false statement, representation, or certification in any application, record, report, plan, or other document filed or required to be maintained under this title, or by any permit, rule, regulation or order issued under this title, or who falsifies, tampers with, or knowingly renders inaccurate any monitoring device or method required to be maintained under this title or by any permit, rule, regulation, or order issued under this title, upon conviction, is subject to a fine not exceeding $10,000, or by imprisonment not exceeding six months or both.

Certified Inspector: (print)	Andrew V. Cignatta
Company:	Datanet Engineering Inc
Certification No.:	MDIC-2010-0043
Expiration Date:	September 1, 2012
Telephone No.:	410-654-1800
Facsimile No.:	410-654-3711
E-mail address:	acignatta@datanetengineering.com

"'High Risk Groundwater Use Area" (HRGUA) means all areas served by individual wells. Existing UST systems installed prior to 1/26/05 in Baltimore, Carroll, Cecil, Frederick and Harford counties or New UST systems installed after 1/26/05 in Anne Arundel, Baltimore, Carroll, Cecil, Charles, Calvert, Frederick, Harford, Howard, Montgomery, and Prince George's counties.

The MDE UST database will be updated with information listed in this inspection report and any amended facility registration form unless additional forms are required by regulation.

Certified Inspector:	**Owner/Operator or Designated Representative**
I, the Maryland Certified Inspector, have performed this UST Inspection and believe the contents of this report to be true and accurate without misrepresentation or falsification. As well, I have no financial interest with this UST Facility.	I, the Owner/Operator/Designated Representative (circle one), have read this Inspection Report and understand the condition of my UST facility, including all deficiencies, corrections and recommendations.
	Title: DISTRICT FACILITY MANAGER
Print Name: Andrew Cignatta	Print Name: ROBERT L KOPPLIN
Signature:	Signature:
Date: 3-26-12	Date: 3-19-2012

Mail REPORT To:	**Questions? Call MDE Oil Control Program at**
MDE Oil Control Program	**410-537-3442**
Suite 620	**See our web page at:**
1800 Washington Blvd.	**http://www.mde.state.md.us**
Baltimore, MD 21230-1719	

MDE Use Only

Certification Section - Reviewed By

Date Reviewed 4/20/12 P ☐ F ☒

Comments (5) Violations

Data Clerk's Initials DT Date Entered 5/15/12

Section 2: Tank System Information

Fill out the tank number for each tank but only use the MDE Tank ID numbering system. Use (✓) box if information is obtained from facility registration form.

Tank and Piping (MDE ID #)	(✓)	Tank #2	Tank #	Tank #	Tank #	Tank #
Owner Tank ID # (if different)						
Status (I-in use or T-temp. out of use)		I				
Date of Installation (mm/yyyy)	√	2/17/99				
Capacity (gallons)	√	300				
Product (see Chart **A** below for code and list compartment tank product separately)		1				
Tank Construction Material (see Chart **B** for code)	√	6				
Compartment Tank (Yes/No) (If Yes, list capacity of each compartment separately)		No				
Double-Wall Tank (Yes/No)		No				
Piping Type (SS) safe suction; **(US)** U.S. suction **(G)** gravity; **(P)**-Pressure		SS				
Piping Construction Material (see Chart **C** for code)		4				
Double-Wall Piping (Yes/No)		No				
Outer Wall Pipe Construction Material (see Chart **C** for code)		NA				
Emergency Power Generator UST (Yes/No)		Yes				
	Tank Field #1		**Tank Field #2**		**Tank Field #3**	
Global Position Signal- Only one set of coordinates is to be collected while standing over the center of each tank field.	Latitude: Longitude: 39°18'36.99"N 76°45'02.85"W		Latitude: Longitude		Latitude: Longitude	
List tank MDE ID # for each tank field according to MDE Registration Form.	2					

Section 2: Tank System Information continued on Page 4

Chart A		Chart B		Chart C	
Code	**Product Description**	**Code**	**Tank Material Description**	**Code**	**Piping Material Description**
1	Diesel	1	Asphalt Coated or Bare Steel	1	Bare Steel
2	Gasohol **E-10**	2	Cathodically Protected Steel	2	Galvanized Steel
2a	Ethanol **E-85**	3	Composite (Steel w/FRP)	3	Fiberglass Reinforced Plastic(FRP)
2b	Methanol	4	Concrete	4	Copper
3	Gasoline	5	Epoxy Coated Steel	4a	Copper-slvd. in PVC, FRP or Plastic
4	Hazardous Substance	6	Fiberglass Reinforced Plastic(FRP)	5	Flexible Plastic
5	Heating Oil #2	7	Polyethylene Tank Jacket	6	No Piping
5a	Heating Oil #4	8	Other (**Must Describe**)	7	Other (**Must Describe**)
5b	Heating Oil #5				
5c	Heating Oil #6				
6	Kerosene				
7	Mixture				
8	Used Oil				
9	Car Wash O/W Separator UST				
10	Other (**Must Describe**)				

Section 2: Tank System Information (cont'd)

Diagram: Show layout of site and all UST systems.

KEY/LEGEND (Include if applicable)

(BLD) Building location
(TF) Tank Field
(T #) Tanks (including all compartments) with MDE tank ID #s
(P) Product piping
(PS) Piping sumps
(D) Dispenser
(V) Vent pipe
(•) Tank field monitoring pipe
(ESO) Emergency Shutoff Switch
⊗ Monitoring Well
(CP) Cathodic protection test station
↑ North arrow
+ Roads bordering property
(DB) Dry Break/Stage I vapor recovery
(STP Sump) Submersible Turbine Pump
(ATG Probe) Automatic Tank Gauge
(FP) Fill Pipe
(AN) Impressed current anodes



Section 3: Tank Temporarily Closed or Taken Out of Service

Fill out this section for any tank that is "temporarily closed" or "taken out of service" (empty, out of use). A complete inspection of these tanks is required. This section does not apply to a tank that is currently in use or permanently out of use.

Not Applicable

#	Answer all (P)ass, (F)ail, (PC), or (NA) for each Tank	Tank #	Tank #	Tank #	Tank #	Tank #
1	Tank contains less than 1" of product.					
2	Tank vented and fill pipe locked.					
3	Date temp. closed or taken out of service (Month/Day/Year).					
4	UST closed 3 months or more, drain and cap product lines and secure other lines, pumps, and manways (vent line open and operating).					
Temporarily Closed Tank(s) passes inspection.						
Questions 1, 2 and 4 are (P) **or** (PC)						

Section 4: Containment Sump and Dispenser Inspection

Applicable

4.a. Containment Sump Inspection

#	Complete 1 and 8. Answer (P)ass, (PC), (F)ail or (NA) for 2-7 (each tank)	Tank #	Tank #	Tank #	Tank #	Tank #
1	(✓)Equipped with containment sump dispenser -					
	tank top -					
	vent riser -					
	Stage two-condensate pod -					
	Other-Specify in comments -					
2	All containment sumps are clean and free of debris, product, and water.					
3	All manway covers and containment sump lids are properly fitted and not in contact with cap, piping, or pump.					
4	All containment sumps have no visible cracks, holes, or openings.					
5	If sump equipped with liquid sensor the sensor is properly secured and within 1" of sump bottom or manufacturer's instruction specifications.					
6	If equipped with double-wall piping, test boot is open to allow product flow to sump.					
7	Containment sump has been tested within past 5 years.					
8	Enter Date of last containment sump test.					
Containment Sump passes inspection.						
Questions 2 - 7 are (P) **or** (PC)						

Note: If answer to any question is (F), explain below. List any problems noted during inspection. Note corrections.

Comments:
The existing dispensers did not have containment sumps or liquid sensors. Rather they were older dispensers and no containment sumps. As part of an upgrade project the owner has new containment sumps installed on the primary dispenser and the sattelite dispenser. Also new dispensers are being installed to replaced the older Tokheim models.

Section 4: Containment Sump and Dispenser Inspection (cont'd)

Not Applicable

4.b. Dispenser Inspection

#	Answer (P)ass, (PC), (F)ail or (NA) for each dispenser	Disp.#	Disp.#	Disp.#	Disp.#	Disp.#
1	Dispenser in good condition and properly secured to pump island.					
2	Shear valve (pressure system) properly secured and shear section within 1/2" of top of pump island or manufactures specifications.					
2a.	Fusible link or other thermally actuated device properly connected.					
3	Shear valve (Stage II piping) properly secured and shear section within 1/2" of top of pump island by manufactures specifications or flex connector.					
4	Dispenser hose in good condition with no cuts, or holes and equipped with breakaway device.					
5	Dispenser hose properly secured and not subject to damage from vehicle traffic (hose retractor).					
6	Emergency shut-off present.					
6a.	Emergency shut-off properly identified.					
6b.	Emergency shut-off in correct location.					
7	Dispenser is not leaking product.					
8	Flex connector observed under dispenser. If in contact with soil complete Section 8.					
9	**Marina** Hold open device has been removed from nozzle.					
Dispenser passes inspection. Questions 1 - 7 and 9 are (P) **or** (PC)						

Note: If the answer to any question is (F), explain below. List any problems noted during inspection. Note corrections.

If more then 5 dispensers include additional copies of this page.

Comments:

Section 5: Tank Top Components and Vent Pipe Inspection

5.a. Tank Top Inspection

#	Complete 1- 3. Answer (P)ass, (PC), (F)ail or (NA) for 1a., 1b. and 4-7 for each tank	Tank # 2	Tank #	Tank #	Tank #	Tank #
1	Storage tank equipped with ATG? If Yes, complete 1a., 1b.	No				
1a.	ATG riser is capped and electrical connection secure with proper grommet.					
1b.	ATG manway lid properly fitted and not in contact with riser or electrical wires.					
2	Flex connector present on STP? If in contact with soil complete Section 8.	No N/A				
3	Interstice monitoring system (double wall tank) or inspection station present?	No N/A				
4	Ball Float riser and other riser pipes are fitted with proper caps; manway covers are not in contact with cap or riser pipe.	~~NA~~ P				
5	No petroleum vapors present during ATG, Ball Float, or Vent riser inspection, or STP without sump.	NA P				
6	Note all vapor field readings if taken for ATG, Ball Float, or Vent riser, or STP without sump.					
7	**Marina.** Each pipeline has a readily accessible shut-off valve grouped at one location on shore near approach to pier or dock and marked "emergency shut-off"?	NA				
Tank Top Components passes inspection. Questions 1a., 1b. and 4-7 are (P) or (PC) and 3 yes **or** component not required		P				

Note: If the answer to any question is (F), explain below. List any problems noted during inspection. Note corrections.

Comments:

5.b. Vent Pipe Inspection

#	Answer (P)ass, (PC), (F)ail or (NA) for each vent	Tank # 2	Tank #	Tank #	Tank #	Tank #
1	Vent pipe riser is constructed of steel?	P				
2	Vent pipe is properly anchored and protected from vehicle traffic (bollards or secured to building)?	P				
3	Vent pipe is proper height (flammable liquids 12 feet above ground surface and 2 feet above any attached building). (Combustible liquids minimum 3 feet above ground surface)?	P				
4	Equipped with vent cap (flammable liquid with Stage I vapor recovery must have pressure vent cap)?	P				
Vent passes inspection. Questions 1 - 4 are (P) **or** (PC)		P				

Note: If the answer to any question is (F), explain below. List any problems noted during inspection. Note corrections.

Comments:

Section 6: Spill and Overfill

6.a. Spill Device

#	Answer (P)ass, (PC), (F)ail or (NA)	Tank # 2	Tank #	Tank #	Tank #	Tank #
1	Equipped with minimum 5-gallon catch basin. (Note: Used oil and heating oil USTs installed, upgraded, or replaced after 11-4-96 require catch basin.	F ← Verify.				
2	Basin clean and free of debris and water.	P				
3	Basin has no cracks or holes observed.	P				
4	No abnormalities observed in fill pipe. (No bent drop tubes, no cracks or holes observed in basin especially at connection to tank and spill device).	NA				
5	Basin lid fits properly and not in contact with fill cap.	P				
6	Fill pipe marked to indicate size of tank/type of product stored or Lid contains API color symbol w/posted sign to indicate tank size and type of product within delivery drivers view.	P				
7	Catch basin tested within past year in accordance with Maryland Containment System Testing Protocol.	XNA				
7a.	Date of last test: (ex. mm/dd/yyyy)					
8	Spill device not required: (Tank receives less than 25-gallons of petroleum per delivery or heating oil UST installed prior to 11-4-96 is not required to have a spill device). If not required indicate (P)	NA				
Spill device passes inspection. Questions 1 - 8 are (P) **or** spill device not required **or** (PC)		F				

Note: If the answer to any question is (F), explain below. List any problems noted during inspection. Note corrections.

Comments:

The spill basin is an aboveground storage tank spill basin. There are no records for spill basin testing.

Above ground spill basins do not require test MP.

Section 6: Spill and Overfill (cont'd.)

6.b. Overfill Device

#	Complete 2 - 4. Answer (P)ass, (PC), (F)ail or (NA) for 1 and 5 - 9	Tank # 2	Tank #	Tank #	Tank #	Tank #
1	Fill drop tube required and observed	No				
2	Overfill device present (list all present): Flapper Valve (FV), Ball Float Valve (BFV), High Level Alarm (HLA), Other Describe.	HLA				
3	Indicate delivery method - gravity (G) or pump flow (PF).	PF				
4	Owner/Operator ensures releases due to spilling or overfilling do not occur? For example, product is measured prior to each delivery to ensure enough room in tank for product; all fuel deliveries are monitored.	Yes				
5	Visually observed overfill device housing, documentation of installation provided, OR certification provided from a certified UST installer attesting to overfill device operability.	XP				
6	Tank receives less than 25-gallons of petroleum per delivery. Heating oil UST installed prior to 11-4-96 is not required to have an overfill device.	NA				
7	**Drop Tube Flapper Valve** Visual observation indicated flapper valve is present, with no obstruction in the drop tube that would render the device ineffective.*	NA				
8	**Ball Float Valve/Vent Restrictor** Compatible with UST system configuration, delivery, and use. **	NA				
9	**Audible External high level alarm only** Visual and audible alarm available to the driver at the point of transfer.	NA				
Overfill device passes inspection. Questions 1 and 4 are yes and 5 - 9 (as applicable) are (P) or (PC)		XPC				

***Note:** If the answer to any question is No (N) or (F), explain below. List any problems noted during inspection. Note corrections.*

**A fill pipe that utilizes a flapper valve in the drop tube for overfill purpose and receives a pressure delivery product drop, shall have a specific flapper valve designed for that use.*

***If a UST system has one or more of the following, the owner or operator of the system shall not use a ball float valve on that system: (1) a tank that receives a pumped delivery; (2) suction piping with air eliminator; (3) remote fill pipes and gauge openings; (4) an emergency generator tank; (5) coaxial drop fill adapter.*

Comments:

The overfill valve on the tank is a vent whistle alarm installed in the vent pipe. The length of the reed in the vent whistle was not removed or examined at the time of the inspection. This should be inspected to determine if the length is accurate for 90% volume of the tank.

PC per previas. Rec dated 8/31/09 MB

Section 7: Stage I and II Inspection

Note: Stage I and II vapor recovery inspections also include completing and submitting Section 7c. forms to MDE's Air and Radiation Management Administration.

7.a. Stage I Vapor Recovery

#	Complete 1 & 2 Answer (P)ass, (PC), (F)ail or (NA) for 3 - 6a. for each tank	Tank #	Tank #	Tank #	Not Applicable Tank #	Not Applicable Tank #
1	Is tank equipped with vapor recovery? (Yes) / (No) or (NA). (If Yes for any tank, complete 2 through 6a. and section 7c.). **Stage I required Statewide**					
2	Type of vapor recovery: A - Coaxial B - 2 point system					
3	Dry break vapor cap and gasket in good condition?					
4	Poppet valve in dry break moves easily and closes tight?					
5	Vapor recovery connection equipped with minimum 5-gallon catchment basin. (NA if installed prior to July 1, 1998). (If 5 is N/A complete 5a. & 5b.).					
5a.	There are no petroleum vapors or staining in soil or pea gravel around vapor recovery riser pipe.					
5b.	Note all field readings if taken.					
6	Catchment basin tested within the past year with passing results					
6a.	Date of last test. (ex. mm/dd/yyyy)					
Stage I Passes Inspection. Question 1 is Y or NA and Questions 3 - 6a are (P) **or** Stage I not applicable **or** (PC)						

Comments:

6. The catchment basins were not tested as part of the previous testing.

7.b. Stage II Vapor Recovery

#	Answer for each tank	Tank #	Tank #	Tank #	Not Applicable Tank #	Not Applicable Tank #
1	Does the storage system have Stage II? Yes or No. (If Yes, complete the applicable sections below and 7c.					
2	Type of vapor recovery: Balance System - (BS) Vacuum Assist - (VA)					
3	UST system equipped with pressure control system and continuously monitors tank pressures.					
Stage II Passes Inspection. Question 1 is (Y) complete 2 **or** Stage II not applicable						

Comments:

Section 8: Corrosion Protection

Applicable

A buried metal tank and piping (including fittings, flex-connectors, etc.) must be isolated from soil and cathodically protected.
Commercial Heating Oil UST systems installed after March 15, 1985 require corrosion protection

	☐ Non-Metal Construction Material										
#	Answer (P)ass, (PC), (F)ail or (NA) for each tank and pipe	Tank 2	Pipe	Tank	Pipe	Tank	Pipe	Tank	Pipe	Tank	Pipe
1	**Tank:** Outer wall made of non-metallic material such as fiberglass or plastic jacket or coating.	P	N/A		N/A		N/A		N/A		N/A
2	**Pipe:** Outer wall made of non-metallic material such as fiberglass or flexible plastic.	N/A		N/A		N/A		N/A		N/A	
Non-Metal Construction passes inspection. Questions 1 and 2 are (P) **or** (PC) **Go to Section 9**		P									

#	Check (✓) type of corrosion protection for each tank and pipe, and answer (P)ass, (PC), (F)ail or (NA) for each tank and pipe	Tank	Pipe 2	Tank	Pipe	Tank	Pipe	Tank	Pipe	Tank	Pipe
	☐ Galvanic Cathodic Protection (Tank and Piping)										
3	Tank: CP on (sti-P3®) tested within past 3 years and passed test in accordance with NACE Code of Practice Standard. If supplemental anodes were installed or added, complete 3a.		N/A		N/A		N/A		N/A		N/A
3a.	UST CP tested annually.		N/A		N/A		N/A		N/A		N/A
4	Pipe: CP tested within past year and passed test in accordance with NACE Code of Practice Standard.	N/A		N/A		N/A		N/A		N/A	
5	Record of last two cathodic protection tests on file with Owner or Operator.										
6	Cathodic protection system failure was inspected/repaired within 60 days of test.										
Galvanic Cathodic Protection passes inspection. Questions 3 - 6 are (P) **or** (PC) **or** 6 (NA)			F								

	☐ Impressed Current Cathodic Protection (Tank and Piping)										
7	Date impressed current system installed. (M/Y).										
8	Assessment performed at 5-year intervals.										
9	System has power and is turned on.										
10	Hour meter present? If (Y) complete 11.										
11	Record hours:										
12	60-day inspection log is present and properly filled out.										
13	Tank: tested within past year and passed test in accordance with NACE Code of Practice Standard.										
14	Pipe: tested within past year and passed test in accordance with NACE Code of Practice Standard.										
15	Records available for last two Impressed Current Cathodic Protection tests.										
16	Cathodic protection system failure was inspected/repaired within 60 days of test.										
Impressed Current Cathodic Protection passes Inspection. Questions 8 & 9 and 12 - 16 are (P) **or** (PC)											

Section 8: Corrosion Protection (cont'd)

	Internally Lined Tank	Tank #	Pipe #	Tank #	Pipe	Tank #	Pipe	Tank #	Pipe	Tank #	Pipe
17	Documentation available and tank was less than 10 years old prior to installing liner.		N/A		N/A		N/A		N/A		N/A
18	Documentation available and internal inspection performed to determine tank is structurally sound and free of corrosion holes prior to installing impressed current cathodic protection and liner.										
19	Site assessment performed before installing liner										
20	Date liner installed (Month / Year).										
21	Date of last internal inspection. (Month / Year).										
22	Internal inspection performed within 10 years of installation and every 5 years thereafter.										
	Internal Liner passes inspection. Questions 17 -19 and 22 are (P) **or** (PC)										
	Note: If the answer to any question in section 8 is (F), explain below. List any problems noted during inspection. Note corrections.										

Comments:

Copper piping from the UST is buried without any cathodic protection. The system is required to have CP because it was installed in 1999.

STOP **IF A METALLIC TANK OR PIPE HAS NO CATHODIC PROTECTION NOTIFY MDE OIL CONTROL PROGRAM AT 410-537-3442** STOP

Section 9: Tightness Testing Inspection

Applicable

9. Tightness Testing (Tanks and Piping)

Complete this section if tank and/or pipe used periodic tightness testing.

#	Answer (P)ass, (PC), (F)ail or (NA) for each tank and pipe	Tank 2	Pipe 2	Tank	Pipe	Tank	Pipe	Tank	Pipe	Tank	Pipe
1	Test method on NWGLDE. Tank Method Name: _____ Line Method Name:	F	F								
2	Last tightness test results available and passed.	F	F								
3	Tightness testing conducted within specified time frames: at installation, at 15 years, and every 5 years thereafter for tanks NOT doing inventory control; annually for pressurized piping; every 2 years for non-exempt suction piping or be monitored monthly by approved leak detection method.	F	F								
4	**High Risk Groundwater Use Area**- Helium vapor test performed within past year with passing results.**	NA	NA								
4a.	**Date of last test.** (ex. mm/dd/yyyy)										
	Tightness Testing passes inspection. Questions 1 - 5 are (P) or (PC)	F	F								

Note: If the answer to any question is (F), please explain below. List any problems noted during inspection. Note corrections.

* www.nwglde.org **(National Work Group on Leak Detection Evaluations)**

***"High Risk Groundwater Use Area" (HRGUA) means all areas served by individual wells. Existing UST systems installed prior to 1/26/05 in Baltimore, Carroll, Cecil, Frederick and Harford counties or New UST systems installed after 1/26/05 in Anne Arundel, Baltimore, Carroll, Cecil, Charles, Calvert, Frederick, Harford, Howard, Montgomery, and Prince George's counties.*

Comments:

No testing results for the tank of piping available.

Questions regarding Helium Testing, call MDE Oil Control Program at 410-537-3442

Section 10: House Keeping and Monitoring Pipe/Well Inspection

10.a. Facility House Keeping

#	Answer (P)ass, (PC), (F)ail or (NA)	
1	Facility is clean with no sign of spillage or open containers of oil.	P
2	ASTs (if present) are clean and properly maintained.	P
3	Pump island area is clean with no indication of surface spillage.	P
4	Garage area (if present) is maintained with no indication of surface spillage.	P
House Keeping passes inspection. Questions 1 - 4 are (P) **or** (PC) **or** (NA)		P

Note: If the answer to any questions is (F), explain below. List any problems noted during inspection. Note corrections.

Applicable

10.b. Tank Field Monitoring Pipes

#	Answer (P)ass, (PC), (F)ail or (NA)	MP-1	MP-2	MP-3	MP-4
1	Storage systems installed after March 15, 1985 have PVC monitoring pipes installed on opposing corners of the tank field.	F			
1a.	Gasoline storage systems installed after January 26, 2005 +> 2,000-gallons or multiple tanks in a shared excavation used to fuel motor vehicles located in HRGUA * have four monitoring pipes (each corner of the tank field.)	NA			
2	Monitoring pipes are screened to within 2ft. of the surface and the remaining 2ft. being solid pipe and sealed to prevent entrance of surface runoff.	F			
3	Monitoring pipe has liquid-tight cap, protected from traffic with manhole cover and locked or bolted closed.	F			
4	Monitoring pipe cover is clearly marked "monitoring well-do not fill" and identified using API color code symbol.	F			
5	Monitoring pipes checked for the presence of petroleum contamination and if present complete 5a.	NA			
5a.	Record product thickness if taken. Record field vapor reading if taken.				

Site wells for Facilities located in HRGUA*		Answer (P)ass, (PC), (F)ail or (NA)				
6	Facility or immediate neighbor on either side supplied by potable well?	No				
7	Three or more groundwater monitoring wells installed outside of tank excavation area.	NA				
8	Monitoring wells have liquid-tight cap, protected from traffic with manhole cover and locked or bolted closed.	NA				
9	Groundwater has been sampled within 180 days and sample results available?	NA				
10	Site potable well has been sampled within 180 days.	NA				
Monitoring Pipes and Site Wells Pass Inspection. Questions 1 - 5 are (P) **or** (PC) **or** (NA)		NA	F			

Note: If the answer to any question is (F), explain below. List any problems noted during inspection. Note corrections. *"High Risk Groundwater Use Area" (HRGUA) means all areas served by individual wells. Existing UST systems installed prior to 1/26/05 in Baltimore, Carroll, Cecil, Frederick and Harford counties or New UST systems installed after 1/26/05 in Anne Arundel, Baltimore, Carroll, Cecil, Charles, Calvert, Frederick, Harford, Howard, Montgomery, and Prince George's counties.

Comments:

There are no tank monitoring wells around the tank field.

Per previous Rec dated 8/31/09 No MP required to be installed

Section 11: Inventory Control

Applicable

For metered storage systems: complete items 1 - 10.
For non-metered storage systems: complete items 3 - 6
For tanks using Inventory Control combined with SIR: also complete Section 12d.

#	Answer (P)ass, (PC), (F)ail or (NA) for each tank	Tank 2	Tank	Tank	Tank	Tank
1	Readings recorded each day of operation.					
2	Inventory records are reviewed daily and reconciled monthly. Note: Seven consecutive days of shortage totaling 80-gallons or more must be reported to owner and investigated.					
3	Appropriate calibration tank chart is used for calculating volume to nearest 1/8 inch.	F				
4	Stick readings recorded before and after each delivery.	P				
5	Gauge stick is marked so the owner is capable of determining product level to the nearest 1/8 inch and stick is in good condition and not worn.	P				
6	Stick capable of measuring full height of tank.	P				
7	Monthly water readings checked to the nearest 1/8 inch and used in calculating inventory balances.					
8	Prior 12 months of inventory data available.					
9	Inventory variations do not exceed 1% + 130 gallons of the metered quantity (sales).					
10	Existing inventory results show no evidence of a release, and no water intrusion.					
Inventory Control Passes Inspection		F				
Questions 1 - 10 are (P) **or** (PC) **or** not applicable						
If using Statistical Inventory Reconciliation (SIR), also complete Section 12.d.						

Note: If answer to any question is (F), explain below. List any problems noted during inspection. Note corrections.

Comments:

The tank chart is measuring in 1" increments.

Section 12: Release Detection Summary

This section indicates the method or methods of release detection present. Proceed to the section identified in the last column. Emergency power generator UST systems and heating oil (on-site consumptive use) UST systems are exempt form release detection.

Tank Method: Complete for each tank	Indicate primary (PR) method and, if applicable, secondary (S) method for each tank					If using as primary method, proceed to section:
	Tank # 2	Tank #	Tank #	Tank #	Tank #	
Automatic Tank Gauging						12.a.
Vapor Monitoring						12.b.
Interstitial Monitoring						12.c.
Statistical Inventory Reconciliation						12.d.
Groundwater Monitoring						12.e.
Manual Tank Gauging						12.f.
None needed (Explain)	Primary method					Skip section 12

Pipe Method: Complete for each pipe run	Indicate primary (PR) method and, if applicable, secondary (S) method for each pipe run					If using as primary method, proceed to section:
	Pipe # 2	Pipe #	Pipe #	Pipe #	Pipe #	
Pressurized piping only						
Automatic line leak detector (ALLD) will detect 3-gph release, double-wall pipe with containment sump and liquid sump sensor.						12.c. and 12.h.
ALLD will detect 3-gph release, double-wall pipe with containment sump and manual interstitial monitoring.						12.c. and 12.h.
Electronic ALLD will perform 3-gph continuous test plus 0.2-gph monthly test.						12.h.
Mechanical ALLD will detect 3-gph release in conjunction with annual line tightness test.						9 and 12.h.
Other combination: (Explain in comments)						
Suction piping only						
Line tightness test every 2 years.						9
Double wall piping with containment sumps utilizing electronic or manual interstitial monitoring.						12.c.
Safe Suction.	Primary method					12.g.
None needed (Explain)						Skip Section 12

Comments:

This system is a emergency generator tank and does not require tank release detection.

Not Applicable

Section 12.a. Automatic Tank Gauging (Tank Only)

#	Complete 1 and 4. Answer (P)ass, (PC), or (F)ail for 2,3,5-10.		Tank #	Tank #	Tank #	Tank # ___	Tank # ___
1	Console Make and Model	Make:					
		Model:					
2	Monitoring console is working.						
3	Owner's manual for console and probes is available at site.						
4	Frequency ATG performs test (**D**) daily, (**W**) weekly, or (**M**) monthly.						
5	Device is calibrated, operated, and maintained per manufacturer's instructions in addition to limitations listed on evaluation summary NWGLDE* list.						
6	System setup reviewed and system capable of verifying probe(s) are functioning and documenting results.						
6a.	Attach copy of print out for the last monthly ATG tank leak test to this page.						
7	Tank is filled to proper capacity and test run for proper duration of time for last 2 months per NWGLDE* list.						
8	Verification that console and probe are third party approved and on the NWGLDE* list.						
9	Monthly release detection records are available and reviewed for past 12 months.						
10	Existing release detection results reviewed shows no failure.						
ATG passes inspection. Questions 2, 3 and 5 - 10 are (P) **or** (PC)							

Note: If the answer to any question is (F), explain below. List any problems noted during inspection. Note corrections. *www.nwglde.org (National Work Group on Leak Detection Evaluations).

Comments:

Not Applicable

Section 12.b. Vapor Monitoring (Tanks and/or Piping)

#	Complete 1. Answer (P)ass, (PC), (F)ail or (NA) for 2 - 11.		Tank #	Tank #	Tank #	Tank #	Tank #	Tank #
1	Console Make and Model	Make:						
		Model:						
2	Monitoring panel and/or control box is working.							
3	Verification that the Vapor Monitoring device is third-party approved and on the NWGLDE* list							
4	Owner's manual for the Vapor Monitoring device is available at the site.							
5	The material used as backfill is sufficiently porous, such as pea gravel or sand, to readily allow diffusion of vapors from releases into the excavation zone.							
6	Vapor Monitors are designed, calibrated, and operated to detect an increase in concentration of the regulated substance, a component of the regulated substance, or a tracer compound placed in the tank system and maintained per manufacturer's instructions in addition to limitations listed on							
7	Site evaluation report is on site and verifies the above information and that background contamination will not interfere with vapor monitoring. **Attach**							
8	System setup reviewed and proper settings confirmed correct. Verification all probes functioning.							
9	Vapor monitors are checking portion of tank and piping that routinely contain							
10	Monthly release detection records are available for last 12 months.							
11	Existing release detection results show no evidence of a release.							
Vapor Monitoring passes inspection. Questions 2-11 are (P) or (PC)								

Note: If the answer to any question is (F), explain below. List any problems noted during inspection. Note corrections. *www.nwglde.org (National Work Group on Leak Detection Evaluations).

Comments:

Not Applicable

Section 12.c. Interstitial Monitoring (Tank and Piping)

#	Complete 1 and 3 for Electronic and Answer (P)ass, (PC), (F)ail or (NA) 2 & 4 - 11 for each Tank and Pipe		Tank	Pipe	Tank	Pipe	Tank	Pipe	Tank	Pipe	Tank	Pipe
1	Type of interstitial monitoring: i.e. Liquid (L), Air Space (AS), or Pressure/vacuum (PV). List each if different.											
Manual / Visual Inspection Only												
2	Interstitial space is monitored and a written log is maintained monthly.											
Electronic System Only												
3	Console Make and Model	Make:										
		Model:										
4	Console and sensor on NWGLDE* list											
5	Monitoring console is operational.											
6	Interstitial space monitored monthly. **											
7	Device is calibrated, operated, and maintained per manufacturer's instructions in addition to limitations listed on evaluation summary NWGLDE* list.											
Summary												
8	Monthly release detection records are available for prior 12 months with passing results.											
9	No evidence of liquid in sump or interstitial space of air filled system. No evidence of loss or gain of brine in brine filled system. Operation of partial vacuum or over pressure system is within manufacturer's design specifications.											
10	No visible leaks or holes in secondary containment.											
	Interstitial Monitoring passes inspection. Questions 2 and 8 - 11 are (P) **for Manual.** Questions 4 - 11 are (P) **or** (PC) **for Electronic**											

Note: If the answer to any question is (F), please explain below. List any problems noted during inspection. Note corrections. **Monitor interstitial space at lowest point of secondary containment for air filled or at highest point of secondary containment for brine filled and is positioned so that other equipment will not interfere with its proper operation. ***See manufacture specifications and NWGLDE listing limitations for continual partial vacuum or overpressure interstitial monitoring. *www.nwglde.org (National Work Group on Leak Detection Evaluations).***

Comments:

Not Applicable

Section 12.d. Statistical Inventory Reconciliation

Complete this section and Section 11 (Inventory Control) if you use Statistical Inventory Reconciliation (SIR).

#	Answer (P)ass, (PC), (F)ail or for 1 - 4 each tank	Tank	Pipe	Tank	Pipe	Tank	Pipe	Tank	Pipe	Tank	Pipe
1	SIR method on NWGLDE* list. Method Name: _____		NA		NA		NA		NA		NA
2	Inventory records are submitted to the SIR vendor within 5 days of the 30 day monitoring period.		NA		NA		NA		NA		NA
2a	SIR results are received by owner from vendor within 15 days of submittal of data.		NA		NA		NA		NA		NA
3	SIR results indicate sufficient amount of data was used to perform leak check.		NA		NA		NA		NA		NA
4	Existing release detection results show no evidence of a failure for the previous 12 months.		NA		NA		NA		NA		NA
Statistical Inventory Reconciliation (SIR) Passes Inspection. Questions 1 - 4 are all (P) **or** (PC).			NA		NA		NA		NA		NA

Note: If the answer to any question is (F), explain below. List any problems noted during inspection. Note corrections. *www.nwglde.org (National Work Group on Leak Detection Evaluations)

Comments:

Not Applicable

Section 12.e. Groundwater Monitoring

#	Answer (P)ass, (PC), (F)ail for each tank system	Tank #__	Pipe #__	Tank #__	Pipe #__	Tank #__	Pipe #__	Tank #__	Pipe #__	Tank #__	Pipe #__
1	Groundwater at site is not more than 15 feet from ground surface during inspection.										
2	Slotted casing is properly screened across the water table to allow entry of product.										
3	Monitoring wells intercept the UST excavation zone or positioned as close as technically feasible.										
4	Regulated substance is immiscible in water and has a specific gravity of less than one.										
5	Site evaluation report on site and verifies above information and background contamination will not interfere with groundwater monitoring. **Attach evaluation cover page.**										
6	Monitoring device is capable of detecting 1/8 inch of free product and wells are monitored monthly with results recorded.										
Groundwater Monitoring inspection. Questions 1 - 6 are all (P) **or** (PC)											

Note: If the answer to any question is (F), please explain below. List any problems noted during inspection. Note corrections.

Comments: _____

Not Applicable

Section 12.f. Manual Tank Gauging (Tank Only)

#	Answer 1 - 5 (P)ass, (PC), (F)ail or (NA) for each Tank	Tank	Tank	Tank	Tank	Tank
1	Tank is 550 - gallons or less.					
2	Tank is 551 to 2,000 - gallons. **Note:** Must be combined with tightness testing.					
3	Gauging stick is capable of measuring the full height of the tank to the nearest 1/8" in conjunction with the appropriate tank calibration chart on site.					
4	Monthly log is maintained. *					
5	Last 12 months of records show no failure.					
	Manual Tank Gauging passes inspection. Questions 1 **or** 2 and 3 - 5 are (P) **or** (PC)					

*Note: If the answer to any question is (F), explain below. List any problems noted during inspection. Note corrections. * See Inspector guidance book or COMAR 26.10.05.04C. for weekly and monthly variation standard.*

Comments:

Applicable

Section 12.g. Safe Suction (Suction Piping Only)

#	Answer (P)ass, (F)ail, or (PC) for each pipe.	Pipe 2	Pipe	Pipe	Pipe	Pipe
1	The piping slope is back to the tank and operates under atmospheric pressure or less.	P				
2	Confirm a single check valve is located directly under the dispensing pump.	P				
	Safe Suction passes inspection. Questions 1 and 2 are (P) **or** (PC)	P				

Note: If the answer for 1 or 2 is (F), another type of release detection must be used and inspected. Fill out the applicable section on piping release detection. List any problems noted during inspection. Note corrections.

Comments: _____

Not Applicable

Section 12.h. Automatic Line Leak Detectors (Pressurized Piping Only)

#	Complete 1 Answer questions 2 - 7 (P)ass, (F)ail or (PC)	Pipe	Pipe	Pipe	Pipe	Pipe
1	Mechanical or Electronic (**M** - Mechanical or **E** - Electronic)					
2	Is the equipment on the NWGLDE* list.					

Section 12: Release Detection (cont'd.)		Pipe	Pipe	Pipe	Pipe	Pipe
3	All ALLDs pass an annual field operability test for detection of a 3.0 - gph leak.					
4	Device is calibrated, operated, and maintained per manufacturer's instructions in addition to limitations listed on evaluation summary NWGLDE* list.					
5	Line Leak Detector shows no evidence of a visual release.					
6	Is the entire piping system covered by the ALLD (including satellite pipe if present)?					
7	For an electronic ALLD, last record of passing 3.0 - gph test result for each pipe is within the previous 72 hours.					
8	Does the STP shut off when the dispensers are not pumping.					
ALLD Passes Inspection. Questions 2 - 8 are (P) or (PC)						

***Note:** If the answer to any question is (F), please explain below. List any problems noted during inspection. Note corrections. *www.nwglde.org (National Work Group on Leak Detection Evaluations)*

Comments: _____

Section 12.i. Suspected Release Answer (Y)es or (N)o for 1 and if yes answer 2

1	Do you suspect or have you detected a release during this inspection? No		
2	Did you report this suspected or detected release to the Department?	Date:	Time:



Report all known or suspected spills or leaks
Call Maryland Department of the Environmental 410-537-3442
Or call: 1-866-633-4686 after business hours

General Comments

Please return original report no later than thirty (30) days after inspection date.	**MDE Oil Control Program** Suite 620 1800 Washington Blvd. Baltimore, MD 21230-1719

Questions? Call MDE Oil Control Program at 410-537-3442
Internet: http://www.mde.state.md.us/programs/LandPrograms/oil_control/home/index.asp

Inspector's Initials AVC
Date: 3-26-12

Owner / Operator's Initials RLF
Date: 3-19-2012

Section 1: General Comment

§ 4-417 Environment Article, Annotated Code of Maryland

(c) ***False statements in required documents; tampering with monitoring devices.*** Any person who knowingly makes any false statement, representation, or certification in any application, record, report, plan, or other document filed or required to be maintained under this title, or by any permit, rule, regulation or order issued under this title, or who falsifies, tampers with, or knowingly renders inaccurate any monitoring device or method required to be maintained under this title or by any permit, rule, regulation, or order issued under this title, upon conviction, is subject to a fine not exceeding $10,000, or by imprisonment not exceeding six months or both.

Certified Inspector: (print): John C. Goodwin
Company: Ace Environmental Services, LLC.
Certification No.: **MDIC 2007-0117**
Expiration. Date: **April 1, 2009**
Telephone No.: (410) 354-8030 Office ~ (410) 491-6639
Facsimile No.: (410) 354-8031
E-mail address: RckRsmssn@aol.com

***"High Risk Groundwater Use Area" (HRGUA) means all areas served by individual wells. Existing UST systems installed prior to 1/26/05 in Baltimore, Carroll, Cecil, Frederick and Harford counties or New UST systems installed after 1/26/05 in Anne Arundel, Baltimore, Carroll, Cecil, Charles, Calvert, Frederick, Harford, Howard, Montgomery, and Prince George's counties.**

The MDE UST database will be updated with information listed in this inspection report and any amended facility registration form unless additional forms are required by regulation.

Certified Inspector:	**Owner/Operator or Designated Representative**
I, the Maryland Certified Inspector, have performed this UST Inspection and believe the contents of this report to be true and accurate without misrepresentation or falsification. As well, I have no financial interest with this UST Facility.	I, the Owner/Operator/Designated Representative (circle one), have read this Inspection Report and understand the condition of my UST facility, including all deficiencies, corrections, and recommendations.
Print Name: John C. Goodwin	Title: ENGINEER
Signature:	Print Name: MARK FRANCZKOWSKI
Date: 30 MAR 09	Signature:
	Date: 3-30-09

Mail REPORT To:	**Questions? Call MDE Oil Control Program at**
MDE Oil Control Program	**410-537-3442**
Suite 620	**See our web page at:**
1800 Washington Blvd.	**http://www.mde.state.md.us**
Baltimore MD 21230-1719	

MDE Use Only

Certification Section – Reviewed By Melissa Purkey

Date Reviewed 05/05/09 Pass ____ Fail ✓

Comments (4) Violations

Data Clerk's Initials sdem Date Entered 5/22/09

Section 2: Tank System Information

Fill out the tank number for each tank but only use the MDE Tank ID numbering system. Use (√) box if information is obtained from facility registration form.

Tank and Piping (MDE ID#)	(√)	**Tank # 002**	**Tank # _**	**Tank #**	**Tank #**	**Tank #**
Owner Tank ID # (if different)						
Status (I-in use or T-temp. out of use)		I				
Date of Installation (month/year)	√	02/99				
Capacity (gallons)		300				
Product (see Chat A below for code and list each compartment tank product separately)		1				
Tank Construction Material (see Chart B for code)	√	6				
Compartment Tank (Yes/No) (If Yes, list capacity of each compartment separately)		/NO		/	/	/
Double-Wall Tank (Yes/No)		YES				
Piping Type (SS) safe suction; **(US)** U.S. suction **(G)** gravity; **(P)** pressure	√	SS				
Piping Construction Material (see Chart C for code)		4				
Double-Wall Piping (Yes/No)		No				
Outer Wall Pipe Construct. Material (see Chart C for code)		N/A				
Emergency Power Generator UST (Yes/No)		YES				

Global Position Signal – Only one set of coordinates is to be collected while standing over the center of each tank field.	**Tank Field #1**		**Tank Field #2**		**Tank Field #3**	
	Latitude: **N39.18.616'**	Longitude: **W076.45.054'**	Latitude:	Longitude:	Latitude:	Longitude:
List tank MDE ID # for each tank field according to MDE Registration Form.	**2**					

Section 2: Tank System Information continued on Page 4

CHART A

CODE	PRODUCT DESCRIPTION
1	Diesel
2	Gasohol **E-10**
2a	Ethanol **E-85**
2b	Methanol
3	Gasoline
4	Hazardous Substance
5	Heating Oil # 2
5a	Heating Oil # 4
5b	Heating Oil # 5
5c	Heating Oil # 6
6	Kerosene
7	Mixture
8	Used Oil
9	Car Wash O/W Separator UST
10	Other **(Must Describe)**

CHART B

CODE	TANK MATERIAL DESCRIPTION
1	Asphalt Coated or Bare Steel
2	Cathodically Protected Steel
3	Composite (Steel w/FRP)
4	Concrete
5	Epoxy Coated Steel
6	Fiberglass Reinforced Plastic (FRP)
7	Polyethylene Tank Jacket
8	Other **(Must Describe)**

CHART C

CODE	PIPING MATERIAL DESCRIPTION
1	Bare Steel
2	Galvanized Steel
3	Fiberglass Reinforced Plastic (FRP)
4	Copper
4a	Copper-slvd. in PVC, FRP or Plastic
5	Flexible Plastic
6	No Piping
7	Other **(Must Describe)**

L

Section 2: Tank System Information (cont'd.)

Diagram: Show layout of site and all UST systems.

KEY/LEGEND (Include if applicable)

- ○ 3 gallon AST Catchment Basin
- ● Interstitial Monitoring pipe
- ○ Vent



C.

Section 3: Tank Temporarily Closed or Taken Out of Service

Fill out this section for any tank that is "temporarily closed" or "taken out of service" (empty, out of use). A complete inspection of these tanks is required. This section does not apply to a tank that is currently in use or permanently out of use.

[ ] Applicable
[√] Not Applicable

#	Answer all (P)ass, (F)ail (PC), or (NA) for each Tank	Tank #_	Tank #_	Tank #_	Tank #_	Tank #_
1	Tank contains less than 1" of product.					
2	Tank vented and fill pipe locked.					
3	Date temp. closed or taken out of service (Month/Day/Year).					
4	UST closed 3 months or more, drain and cap product lines and secure other lines, pumps, and manways (vent line open and operating).					
Temporarily Closed Tank(s) passes inspection. Questions 1,2 and 4 are (P) or (PC)						

Section 4: Containment Sump and Dispenser Inspection

[ ] Applicable
[√] Not Applicable

4.a. Containment Sump Inspection

#	Complete 1 and 8. Answer (P)ass, (PC), (F)ail or (NA) for 2 – 7 (each tank)	Tank #	Tank #_	Tank #_	Tank #	Tank #
1	(√)Equipped with containment sump dispenser-					
	tank top -					
	vent riser -					
	Stage two-condensate pod -					
	Other – Specify in comments -					
2	All containment sumps are clean and free of debris, product, and water.					
3	All manway covers and containment sump lids are properly fitted and not in contact with cap, piping, or pump.					
4	All containment sumps have no visible cracks, holes, or openings.					
5	If sump equipped with liquid sensor the sensor is properly secured and within 1" of sump bottom or meets manufacturer's specifications.					
6	If equipped with double-wall piping, test boot is open to allow product flow to sump.					
7	Containment sump has been tested within past 5 years with passing results.					
8	Enter Date of last containment sump test.					
Containment Sump passes inspection. Questions 2 – 7 are (P) or (PC)						

Note: If answer to any question is (F), explain below. List any problems noted during inspection. Note corrections.

Comments:_____

Certification of Financial Responsibility

Macy's Inc. hereby certifies that it is in compliance with the requirements of subpart H of 40 CFR part 280. The financial assurance mechanism(s) used to demonstrate financial responsibility under subpart H of 40 CFR part 280 is (are) as follows:

Type of mechanism:
Self-insured, Letter from the CFO

Name of issuer:
Self- insured

Mechanism number:
280.98

Amount of coverage:
$1,000,000

RECEIVED
JUN - 4 2012
OIL CONTROL PROGRAM

Effective period:
5/15/12 – 5/15/13

This mechanism covers taking corrective action and compensating third parties for bodily injury and property damage caused by accidental releases.

[Signature of owner or operator]
Melissa Olberding

[Name of owner or operator]
Melissa Olberding

[Title]
Environmental Services Manager

[Date] 5/21/12

[Signature of witness or notary]
Tia Liddell

[Name of witness or notary]
Tia Liddell

[Date] 5/21/12

LETTER FROM THE CHIEF FINANCIAL OFFICER
280.95d

I am the Chief Financial Officer of Macy's, Inc., 7 West 7th Street, Cincinnati, Ohio 45202.

This letter is in support of the use of the "financial test of self-insurance" to demonstrate financial responsibility for taking corrective action and/or compensating third parties for bodily injury and property damage caused by sudden accidental releases and/or non sudden accidental releases in the amount of $1,000,000 per occurrence and $1,000,000 annual aggregate arising from operating underground storage tanks.

Underground storage tanks at the following facilities are assured by this financial test or a financial test under an authorized State program by this owner or operator may be found under Appendix A.

This owner/operator has not received an adverse opinion, a disclaimer of opinion, or a "going concern" qualification from an independent auditor on this financial statement for the latest completed fiscal year.

Certification of Financial Responsibility

Macy's Inc. hereby certifies that it is in compliance with the requirements of subpart H of 40 CFR part 280. The financial assurance mechanism(s) used to demonstrate financial responsibility under subpart H of 40 CFR part 280 is (are) as follows:

Financial Test of Self Insurance
$1,000,000 per occurrence/$1,000,000 annual aggregate
Effective 5/15/2012 – 5/15/2013

This mechanism covers ``taking corrective action" and/or ``compensating third parties for bodily injury and property damage caused by" either ``sudden accidental releases" or ``nonsudden accidental releases" or ``accidental releases."

(Signature)

Karen Hoguet
(Name)

Vice President, Chief Financial Officer
(Title)

5/11/12
(Date)

Mary Lou Rodenberg
(Witness or Notary)

Mary Lou Rodenberg
(Name)

5/11/12
(Date)

Martin O'Malley
Governor

Shari T. Wilson
Secretary

Horacio Tablada, Director
Waste Management Administration

Herbert M. Meade, Administrator
Oil Control Program

Facility No. 0006267

State of Maryland

Department of the Environment
Waste Management Administration

Oil Control Program
UNDERGROUND STORAGE TANK FACILITY
CERTIFICATE OF REGISTRATION

Issued: July 15, 2008

This certifies that **Macy's Inc.**

has duly registered its underground storage tank system(s) with the State of Maryland, Department of the Environment as required by Environment Article Section 4-411.1, *Annotated Code of Maryland* for the following location:

Facility Address:

Macy's Security Square
6901 Security Blvd.
Baltimore, MD 21207

Shirley J. Fairbank
Administrative Resources
Oil Control Program

This certificate authorizes the use of the listed underground storage tank system(s) only in accordance with Code of Maryland Regulations (COMAR) 26.10. **This Certificate does not confirm that the UST system(s) are being operated in full compliance with all COMAR regulations.**

The following tank(s) have been duly registered at the above facility:

TANK NUMBER	STATUS	DESCRIPTION	SUBSTANCE STORED	CLOSURE STATUS
001	Permanently Out of Use	300 gal.	Diesel	Tank removed from ground
002	Currently In Use	300 gal.	Diesel	

The liability of the Surety(ies) shall not be discharged by any payment or succession of payments hereunder, unless and until such payment or payments shall amount in the annual aggregate to the penal sum shown on the face of the bond, but in no event shall the obligation of the Surety(ies) hereunder exceed the amount of said annual aggregate penal sum.

The Surety(ies) may cancel the bond by sending notice of cancellation by certified mail to the Principal, provided, however, that cancellation shall not occur during the 120 days beginning on the date of receipt of the notice of cancellation by the Principal, as evidenced by the return receipt.

The Principal may terminate this bond by sending written notice to the Surety(ies).

In Witness Thereof, the Principal and Surety(ies) have executed this Bond and have affixed their seals on the date set forth above. The persons whose signatures appear below hereby certify that they are authorized to execute this surety bond on behalf of the Principal and Surety(ies) and that the wording of this surety bond is identical to the wording specified in 40 CFR 280.98(b) as such regulations were constituted on the date this bond was executed.

Macy's Retail Holdings, Inc., A New York Corporation

Jack B. Cox asst. Secretary

[Name(s)] JACK B. COX
[Title(s)] ASSISTANT SECRETARY
[Corporate seal]

Westchester Fire Insurance Company
436 Walnut Street
Philadelphia, PA 19106
New York:

[Liability limit: **$1,000,000.00**

Sandra Martinez

Sandra Martinez, Attorney-in-Fact

[Corporate seal]

[For every co-surety, provide signature(s), corporate seal, and other information in the same manner as for Surety above.]

Bond premium: **$7,500.00**

Exhibit A

Regulated Tanks

Division	Location	Address	City, State Zip
Bloomingdale's	WHITE PLAINS	175 BLOOMINGDALE ROAD	WHITE PLAINS NY 10605
Bloomingdale's	Lenox Square	3394 Peachtree Rd. NE	Atlanta, GA 30326
HO	HANGAR-LUNKEN AIRPORT	422 WILMER AVENUE HANGAR 28	CINCINNATI OH 45226
Macy's West	Laurel Plaza	6150 Laurel Canyon Blvd.	Los Angeles, CA 91606
Macy's West	San Francisco Union Square	170 O'Farrell Street	San Francisco, CA 94102
Macy's East	JERSEY CITY (Newport Center)	200 MALL DRIVE EAST	JERSEY CITY NJ 07310
Macy's East	SOUTH PORTLAND (Maine Mall)	100 MAINE MALL ROAD	SOUTH PORTLAND ME 04106
Macy's East	SUBURBAN SQUARE	400 WEST MONTGOMERY AVENUE	ARDMORE PA 19003
Macy's East	Ballston Commons	701 N. Glebe Road	Arlington, VA 22203
Macy's East	Fair Oaks	11700 Fair Oaks Mall	Fairfax, VA 22033
Macy's East	Marley Station Mall	7900 South Ritchie Hwy, Suite	Glen Burnie, MD 21061
Macy's East	Marlow Heights S.C.	4101 Branch Avenue	Temple Hills, MD 20748
Macy's East	Metro Center	1201 G. Street NW	Washington, DC 20005
Macy's East	Owings Mill Town Center	10300 Mill Run Circle	Owings Mill, MD 21117
Macy's East	Prince Georges Plaza	3500 East West Hwy	Hyattsville, MD 20782
Macy's East	Security Square	6901 Security Blvd	Baltimore, MD 21246
Macy's East	Towson Town Center	813 Dulaney Valley Rd	Towson, MD 21204
Macy's Florida	Tyrone	6901 22nd Avenue North	St. Petersburg, FL 33710
Macy's Florida	Florida Mall	8001 South Orange Blossom Trail	Orlando, FL 32809
Macy's Florida	Wellington Green Mall	10316 Forest Hill Blvd	Wellington, FL 33414
MCCS	MCCS South	13141 34th Street, North	Clearwater, FL 33762
MLO	BAILEY - DISTR. CTR.	12629 MAHONING AVENUE	NORTH JACKSON OH 44451
MLO	Gandy Distribution Center	4130 Gandy Boulevard	Tampa, FL 33611
MLO	Miami Distribution Center	7100 NW 32nd Avenue	Miami, FL 33147
MLO	Mission Road Distribution Center	3880 N. Mission Road	Los Angeles, CA 90031
MLO	KAPOLEI	91-262 OIHANA STREET	KAPOLEI HI 96707
MSO	RIVERCHASE	2600 RIVERCHASE GALLERIA	BIRMINGHAM AL 35244
MST	MST - HEADQUARTERS	5985 STATE BRIDGE ROAD	DULUTH GA 30097
Real Estate	Fashion Place Mall	333 N. University Drive	Plantation, FL 33324
Real Estate	Chicago Distribution Center	4000 West Diversey Ave	Chicago, IL 60639

Power of Attorney

174016

WESTCHESTER FIRE INSURANCE COMPANY

1262079

Know all men by these presents: That WESTCHESTER FIRE INSURANCE COMPANY , a corporation of the State of New York , having its principal office in the City of Atlanta , Georgia , pursuant to the following Resolution, adopted by the Board of Directors of the said Company on December 11, 2006, to wit:

"RESOLVED, that the following authorizations relate to the execution, for and on behalf of the Company, of bonds, undertakings, recognizances, contracts and other written commitments of the Company entered into the ordinary course of business(each a "Written Commitment"):

(1) Each of the Chairman, the President and the Vice Presidents of the Company is hereby authorized to execute any Written Commitment for and on behalf of the Company, under the seal of the Company or otherwise.

(2) Each duly appointed attorney-in-fact of the Company is hereby authorized to execute any Written Commitment for and on behalf of the Company, under the seal of the Company or otherwise, to the extent that such action is authorized by the grant of powers provided for in such persons written appointment as such attorney-in-fact.

(3) Each of the Chairman, the President and the Vice Presidents of the Company is hereby authorized, for and on behalf of the Company, to appoint in writing any person the attorney-in-fact of the Company with full power and authority to execute, for and on behalf of the Company, under the seal of the Company or otherwise, such Written Commitments of the Company as may be specified in such written appointment, which specification may be by general type or class of Written Commitments or by specification of one or more particular Written Commitments.

(4) Each of the Chairman, the President and Vice Presidents of the Company is hereby authorized, for and on behalf of the Company, to delegate in writing to any other officer of the Company the authority to execute, for and on behalf of the Company, under the Company's seal or otherwise, such Written Commitments of the Company as are specified in such written delegation, which specification may be by general type or class of Written Commitments or by specification of one or more particular Written Commitments.

(5) The signature of any officer or other person executing any Written Commitment or appointment or delegation pursuant to this Resolution, and the seal of the Company, may be affixed by facsimile on such Written Commitment or written appointment or delegation.

FURTHER RESOLVED, that the foregoing Resolution shall not be deemed to be an exclusive statement of the powers and authority of officers, employees and other persons to act for and on behalf of the Company, and such Resolution shall not limit or otherwise affect the exercise of any such power or authority otherwise validly granted or vested.

FURTHER RESOLVED, that the Resolution of the Board of Directors of the Company adopted at the meeting held on November 8, 1999 relating to the authorization of certain persons to execute, for and on behalf of the Company, Written Commitments and appointments and delegations, is hereby rescinded.

Does hereby nominate, constitute and appoint CRAIG T. TAGLIAMONTE, ROBERT E. DUNCAN, GEOFFREY E. HEEKIN, THOMAS J. JOSLIN, KAREN DANIEL, LINDA ISER, KATHLEEN J. MAILES, SANDRA MARTINEZ, SUSAN J. PREJKSA, SUSAN A. WELSH, MARCIA K. CESAFSKY, JOELLEN M. MENDOZA, CHRISTOPHER P. TROHA and PATRICIA M. DOYLE all of the City of Chicago, State of Illinois , each individually if there be more than one named, its true and lawful attorney-in-fact, to make, execute, seal and deliver on its behalf, and as its act and deed any and all bonds, undertakings, recognizances, contracts and other writings in the nature thereof in penalties not exceeding Twenty Five Million Dollars ($25,000,000) and the execution of such writings in pursuance of these presents shall be as binding upon said Company, as fully and amply as if they had been duly executed and acknowledged by the regularly elected officers of the Company at its principal office.

IN WITNESS WHEREOF, the said Stephen M. Haney , Vice-President, has hereunto subscribed his name and affixed the corporate seal of the said WESTCHESTER FIRE INSURANCE COMPANY this 3rd day of June 2008 .

WESTCHESTER FIRE INSURANCE COMPANY

Stephen M. Haney , Vice President

COMMONWEALTH OF PENNSYLVANIA
COUNTY OF PHILADELPHIA ss.

On this 3rd day of June , A.D. 2008 , before me, a Notary Public of the Commonwealth of Pennsylvania in and for the County of Philadelphia came Stephen M. Haney , Vice-President of the WESTCHESTER FIRE INSURANCE COMPANY to me personally known to be the individual and officer who executed the preceding instrument, and he acknowledged that he executed the same, and that the seal affixed to the preceding instrument is the corporate seal of said Company; that the said corporate seal and his signature were duly affixed by the authority and direction of the said corporation, and that Resolution, adopted by the Board of Directors of said Company, referred to in the preceding instrument, is now in force.

IN TESTIMONY WHEREOF, I have hereunto set my hand and affixed my official seal at the City of Philadelphia the day and year first above written.

COMMONWEALTH OF PENNSYLVANIA
NOTARIAL SEAL
KAREN E. BRANDT, Notary Public
City of Philadelphia, Phila. County
My Commission Expires September 26, 2010

Notary Public

I, the undersigned Assistant Secretary of WESTCHESTER FIRE INSURANCE COMPANY , do hereby certify that the original POWER OF ATTORNEY, of which the foregoing is a substantially true and correct copy, is in full force and effect.

In witness whereof, I have hereunto subscribed my name as Assistant Secretary, and affixed the corporate seal of the Corporation, this 26th day of June 2008 .

William L. Kelly , Assistant Secretary

THIS POWER OF ATTORNEY MAY NOT BE USED TO EXECUTE ANY BOND WITH AN INCEPTION DATE AFTER June 3, 2010 .

THE BACK OF THIS DOCUMENT LISTS VARIOUS SECURITY FEATURES THAT WILL PROTECT AGAINST COPY COUNTERFEIT AND ALTERATION.

ACKNOWLEDGEMENT BY SURETY

STATE OF ILLINOIS
COUNTY OF COOK

On this 26th day of June, 2008, before me, Judi Lucky, a Notary Public, within and for said County and State, personally appeared Sandra Martinez to me personally known to be the Attorney-in-Fact of and for Westchester Fire Insurance Company and acknowledged that she executed the said instrument as the free act and deed of said Company.

IN WITNESS WHEREOF, I have hereunto set my hand and affixed my official seal, at my office in the aforesaid County, the day and year in this certificate first above written.

Notary Public in the State of Illinois
County of Cook

OFFICIAL SEAL
JUDI LUCKY
NOTARY PUBLIC - STATE OF ILLINOIS
MY COMMISSION EXPIRES
OCTOBER 07, 2010

Section 3: Tank Temporarily Closed or Taken Out of Service

Fill out this section for any tank that is "temporarily closed" or "taken out of service" (empty, out of use). A complete inspection of these tanks is required. This section does not apply to a tank that is currently in use or permanently out of use.

Not Applicable

#	Answer all (P)ass, (F)ail, (PC), or (NA) for each Tank	Tank #	Tank #	Tank #	Tank #	Tank #
1	Tank contains less than 1" of product.					
2	Tank vented and fill pipe locked.					
3	Date temp. closed or taken out of service (Month/Day/Year).					
4	UST closed 3 months or more, drain and cap product lines and secure other lines, pumps, and manways (vent line open and operating).					
Temporarily Closed Tank(s) passes inspection.						
Questions 1, 2 and 4 are (P) **or** (PC)						

Section 4: Containment Sump and Dispenser Inspection

Applicable

4.a. Containment Sump Inspection

#	Complete 1 and 8. Answer (P)ass, (PC), (F)ail or (NA) for 2-7 (each tank)	Tank #	Tank #	Tank #	Tank #	Tank #
1	(✓)Equipped with containment sump dispenser -					
	tank top -					
	vent riser -					
	Stage two-condensate pod -					
	Other-Specify in comments -					
2	All containment sumps are clean and free of debris, product, and water.					
3	All manway covers and containment sump lids are properly fitted and not in contact with cap, piping, or pump.					
4	All containment sumps have no visible cracks, holes, or openings.					
5	If sump equipped with liquid sensor the sensor is properly secured and within 1" of sump bottom or manufacturer's instruction specifications.					
6	If equipped with double-wall piping, test boot is open to allow product flow to sump.					
7	Containment sump has been tested within past 5 years.					
8	Enter Date of last containment sump test.					
Containment Sump passes inspection.						
Questions 2 - 7 are (P) **or** (PC)						

Note: If answer to any question is (F), explain below. List any problems noted during inspection. Note corrections.

Comments:
The existing dispensers did not have containment sumps or liquid sensors. Rather they were older dispensers and no containment sumps. As part of an upgrade project the owner has new containment sumps installed on the primary dispenser and the sattelite dispenser. Also new dispensers are being installed to replaced the older Tokheim models.

Section 4: Containment Sump and Dispenser Inspection (cont'd)

Not Applicable

4.b. Dispenser Inspection

#	Answer (P)ass, (PC), (F)ail or (NA) for each dispenser	Disp.#	Disp.#	Disp.#	Disp.#	Disp.#
1	Dispenser in good condition and properly secured to pump island.					
2	Shear valve (pressure system) properly secured and shear section within 1/2" of top of pump island or manufactures specifications.					
2a.	Fusible link or other thermally actuated device properly connected.					
3	Shear valve (Stage II piping) properly secured and shear section within 1/2" of top of pump island by manufactures specifications or flex connector.					
4	Dispenser hose in good condition with no cuts, or holes and equipped with breakaway device.					
5	Dispenser hose properly secured and not subject to damage from vehicle traffic (hose retractor).					
6	Emergency shut-off present.					
6a.	Emergency shut-off properly identified.					
6b.	Emergency shut-off in correct location.					
7	Dispenser is not leaking product.					
8	Flex connector observed under dispenser. If in contact with soil complete Section 8.					
9	**Marina** Hold open device has been removed from nozzle.					
Dispenser passes inspection. Questions 1 - 7 and 9 are (P) **or** (PC)						

Note: If the answer to any question is (F), explain below. List any problems noted during inspection. Note corrections.

If more then 5 dispensers include additional copies of this page.

Comments:

HP ENVIRONMENTAL
INCORPORATED

RECEIVED
DEC 10 2012
OIL CONTROL PROGRAM

November 27, 2012

Mr. Ray Kozlowski
Maryland Department of the Environment
Oil Control Program
1800 Washington Boulevard
Suite 620
Baltimore, Maryland 21230

Re: Underground Storage Tank Closure Report
Macy's Security Square Center
6901 Security Boulevard
Baltimore, MD 21244

Dear Mr. Kozlowski:

HP Environmental, Inc. (HPE) has prepared this report to summarize the closure of one 300-gallon capacity underground storage tank (UST) from the referenced site. The tank was installed in approximately 1998 and had been used to store and supply diesel fuel for an on-site emergency generator.

Tank Removal

HPE was retained by Macy's to remove the UST, assess site conditions, collect post-excavation soil samples, and prepare this UST Closure Report. The location of the site is shown on Figure 1 while the more specific location of the UST is shown on Figure 2. Prior to removal of the UST, approximately 200 gallons of fuel were transferred to a recently installed aboveground storage tank (AST). The UST was cleaned and inerted prior to removal from the site by Environmental Products and Services of Vermont, Inc. (EPS) of Williston, Vermont. EPS provided for the off-site disposal of the UST at Yowell Recycling Center, in Woodbine, Maryland for recycling. Copies of the tank and fluid disposal manifests are included as Attachment 1 to this letter report.

On October 26, 2012 the UST was excavated and removed from the ground. The tank was observed to be a cathodically protected STI-P3 with sacrificial anodes on either end of the UST. The UST was visually inspected and found to be free of perforations, corrosion or deterioration. There were no visible or olfactory indications of a past release from the tank. The UST and excavation were inspected by a representative of the Maryland Department of the Environment (MDE) on October 26, 2012 and HPE received approval to remove the tank from the property for off-site disposal.

During and after removal of the UST from the excavation HPE personnel field screened selected soil samples for the presence of volatile organic compounds (VOCs) such as related to petroleum fuels. Field screening was conducted using a calibrated Minirae photoionization detector (PID) equipped with a 10.6 electron volt lamp. The PID was calibrated prior to initiation of field activities and checked periodically in accordance with the manufacturer's specifications. The PID measures relative concentrations of total VOCs in the headspace of the sealed soil sample and reports the concentration in parts per million (ppm) up to a maximum concentration of 9,999 parts per million (ppm). During this investigation, no levels of VOCs above background concentrations were encountered.

At the direction of the MDE inspector two soil samples were collected from soils located below the base of the UST. Sample locations are shown on Figure 2. The soil samples collected from the base of the excavation were containerized in pre-cleaned, 4-ounce glass jar and placed on ice for laboratory analysis. The samples were submitted to HP Environmental, Inc, of Herndon, Virginia, for analysis of total petroleum hydrocarbons, diesel-range organics (TPH-DRO) by EPA Method 8015; and volatile organic compounds (VOCs) by EPA Method 8260. Analytical data sheets and a chain of custody form are included in Attachment 2. Laboratory data reveals that no VOCs were detected above the method reporting limit for the two confirmatory soil samples collected and no TPH-DRO was detected above the method reporting limit for one of the confirmatory soil samples; the other soil sample had a result of 23 ppm.

Conclusions and Recommendations

Based on the MDE Risk Based Concentration (RBC) of 230 ppm for TPH-DRO, the positive soil sample is well below the MDE RBC criteria and does not pose a threat to human health or the environment. HPE recommends that no further action be taken and that the MDE issue a Permanent Tank Closure letter to the property owner indicating that no additional investigation or remediation is being required.

Please feel free to contact me at (703) 471-4200 should you have any questions or comments related to this UST Closure Report.

Sincerely,

KDC

Kent D. Campbell
Director of Site Assessment, Monitoring & Compliance

Attachments

cc: Ms. Melissa Olberding, Macy's (via electronic mail)
Mr. Bob Kozul, Macy's (via electronic mail)

HP ENVIRONMENTAL, INC.

104 ELDEN STREET, HERNDON, VIRGINIA 20170
TELPHONE 703 471 4200 FAX 703 471 0020

FIGURE 1
SITE LOCATION MAP

Project:
MACY'S SECURITY SQUARE MALL
6901 SECURITY BOULEVARD
BALTIMORE, MARYLAND 21244

Date:	Drawn by:	CAD File:	Scale:
11-27-12	KDC	FIGURE1	1" = 2000'



HP ENVIRONMENTAL, INC.
104 ELDEN STREET
HERNDON, VIRGINIA 20170
TELEPHONE 703 471 4200 FAX 703 471 0020

FIGURE 2
SITE SKETCH

PROJECT: MACY'S SECURITY SQUARE MALL
6901 SECURITY BOULEVARD
BALTIMORE, MARYLAND 21244

DATE:	DRAWN BY:	CAD FILE:	SCALE:
11-27-12	KDC	MACYS SEC SQ	NOT TO SCALE

1000 East Ridgeville Boulevard
Mount Airy, Maryland 21771
Office 301-831-7200
Fax 301-831-7978
Email – hhconcrete@aol.com

H & H Concrete Construction, Inc.

October 29, 2012

Certificate of Destruction / Tank Disposal Receipt

The underground storage tank or tanks that were removed from the property listed below were dismantled and properly disposed of at the listed salvage facility by H & H Concrete Construction, Inc. per all state and local regulations.

Jobsite;

Macy's
6901 Security Boulevard
Baltimore, Maryland

Tank Information;

1 – 300 gallon STIP3 Steel Tank

Salvage Facility;

Yowell Scrap

Sincerely,

Jerome P. Nix
Project Manager

Petroleum Management, Inc.

5218 Curtis Avenue ♦ Baltimore, Maryland 21226 ♦ Phone 410-354-0200 ♦ Fax 410-354-0201

MD. Oil Operations Permit No: 2009-OPT-31821
EPA Identification No: MDR-000522794
Federal ID No: 52-2014536

Bill of Lading/Manifest **№ 7247**

Generator/Shipper: Security Square Mall Opt Store		Billing Name: H H Gerrit	
Site Address: 6911 Security Blvd		Address:	
City: Baltimore	State: MD Zip:	City:	State: Zip:
Phone: (410) 365-2089	Contact: Jerry	Phone: ( )	Contact:

Purchase Order NO:

MATERIAL CHARACTERIZATION (CHECK ALL THAT APPLY):

Description:	Gallons	Description:	Gallons	Description:	Gallons
Gasoline, 3, UN1203, PGII		Hazardous Waste, Liquid, 9 NA3082, PGIII		JP#4	
#2 Fuel Oil, 3, NA1993, PGIII		Hazardous Waste, Solid, 9 NA3077, PGIII		JP#5	
#4 Fuel Oil, 3 NA1993, PGIII		Paint Thinners, 3, UN1263, PGI		Jet A	
#6 Fuel Oil, 3, NA1993, PGIII		Ethylene Glycol, 9, UN3082, PGIII		Sludge	
Diesel, 3, NA1993, PGIII		Lube Oil		Petroleum Contaminated Water	20
Flammable Liquids, NOS, 3, UN1993, PGI		Waste Oil		Other:	
Corrosive Liquids, NOS, 8, UN1760, PGII		Kerosene		Other:	
No. of Drums		No. of Tanks:		Other:	
Scale Weights (Soil): Total: (Tons)		Tare: (Tons)		Net: (Tons)	

Service Description: Pump out 500gal diesel generator tank

PLACARDS TENDERED: ☐ YES ☒ NO **EMERGENCY CONTACT (410) 760-3703**

Generator/Shipper Certification Statement

As the generator or shipper, I hereby certify that this material is properly classified and does not contain Polychlorinated Biphenyls (PCB'S). To the best of my knowledge it has not been mixed, combined or blended in any amount with any other material defined as hazardous waste under applicable law. Generator/Shipper agrees to indemnify and hold Petroleum Management, Inc. harmless for any damages arising from or in any way relating to a breach of this Certification Statement.

X Generator/Shipper Authorized Agent (Print): On behalf of MALL'S Main Office — Date of Service:

X Generator/Shipper Authorized Agent Signature:

HAULER/CARRIER INFORMATION

Co. Name: **Petroleum Management, Inc.**		Driver Name (print): Merrick Hayes	
Street: **5218 Curtis Avenue**		Driver Signature:	
City: **Baltimore**	State: **MD** Zip: **21226**	Phone: (410) 354-0200	

The above mentioned materials have been received by this facility and will be handled in accordance with all applicable rules and regulations. All quantities are subject to final verification by this facility and are indicated in far right box.

RECEIVING FACILITY ACCEPTANCE

Facility Name:

Acceptance Signature:

Phone:

Petroleum Management, Inc.
5218 Curtis Avenue
Baltimore, MD 21226

Total Quantity Received: 20

White - Original Yellow - Transporter Pink - Facility Gold - Customer

Report Number: **124684**

HP ENVIRONMENTAL
INCORPORATED

Certificate of Laboratory Analysis

Macy's
Attn: Melissa Olberding
7 West 7th St.
Cincinnati, OH 45202

Date Received: 10/29/12
Date Reported: 10/31/12
Project Location: **Security Square**

---

1. Client Sample No: **Macy's S-1** HPE Sample No.: 124684-01
Sample Matrix: Soil Date Collected: 10/26/12
Sample Location:

Test Requested: **Volatile Organic Compounds**
Preparation Method: EPA 5030 Date Prepared: 10/29/12
Analysis Method: EPA 8260 Date Analyzed: 10/29/12

Analyte	Result	Units	Reporting Limit	Qualifier
Dichlorodifluoromethane	< 5.0	ug/Kg	5.0	U
Chloromethane	< 5.0	ug/Kg	5.0	U
Vinyl chloride	< 5.0	ug/Kg	5.0	U
Bromomethane	< 5.0	ug/Kg	5.0	U
Chloroethane	< 5.0	ug/Kg	5.0	U
Trichlorofluoromethane	< 5.0	ug/Kg	5.0	U
1,1-Dichloroethene	< 5.0	ug/Kg	5.0	U
Acetone	< 5.0	ug/Kg	5.0	U
Methylene chloride	< 5.0	ug/Kg	5.0	U
Methyl-tert-butyl ether (MTBE)	< 5.0	ug/Kg	5.0	U
trans-1,2-Dichloroethene	< 5.0	ug/Kg	5.0	U
1,1-Dichloroethane	< 5.0	ug/Kg	5.0	U
2-Butanone	< 5.0	ug/Kg	5.0	U
2,2-Dichloropropane	< 5.0	ug/Kg	5.0	U
cis-1,2-Dichloroethene	< 5.0	ug/Kg	5.0	U
Bromochloromethane	< 5.0	ug/Kg	5.0	U
Chloroform	< 5.0	ug/Kg	5.0	U
1,1,1-Trichloroethane	< 5.0	ug/Kg	5.0	U
Carbon tetrachloride	< 5.0	ug/Kg	5.0	U
1,1-Dichloropropene	< 5.0	ug/Kg	5.0	U
Benzene	< 5.0	ug/Kg	5.0	U
1,2-Dichloroethane	< 5.0	ug/Kg	5.0	U
Trichloroethene	< 5.0	ug/Kg	5.0	U
1,2-Dichloropropane	< 5.0	ug/Kg	5.0	U
Dibromomethane	< 5.0	ug/Kg	5.0	U
Bromodichloromethane	< 5.0	ug/Kg	5.0	U
cis-1,3-Dichloropropene	< 5.0	ug/Kg	5.0	U
4-Methyl-2-pentanone	< 5.0	ug/Kg	5.0	U
Toluene	< 5.0	ug/Kg	5.0	U
trans-1,3-Dichloropropene	< 5.0	ug/Kg	5.0	U
1,1,2-Trichloroethane	< 5.0	ug/Kg	5.0	U
2-Hexanone	< 5.0	ug/Kg	5.0	U
Tetrachloroethene	< 5.0	ug/Kg	5.0	U
1,3-Dichloropropane	< 5.0	ug/Kg	5.0	U
Dibromochloromethane	< 5.0	ug/Kg	5.0	U
1,2-Dibromoethane	< 5.0	ug/Kg	5.0	U
Chlorobenzene	< 5.0	ug/Kg	5.0	U
1,1,1,2-Tetrachloroethane	< 5.0	ug/Kg	5.0	U
Ethylbenzene	< 5.0	ug/Kg	5.0	U
m,p-Xylene	< 5.0	ug/Kg	5.0	U
o-Xylene	< 5.0	ug/Kg	5.0	U
Styrene	< 5.0	ug/Kg	5.0	U
Bromoform	< 5.0	ug/Kg	5.0	U

Report Number: **124684**

HP ENVIRONMENTAL
INCORPORATED

Certificate of Laboratory Analysis

Macy's
Attn: Melissa Olberding
7 West 7th St.
Cincinnati, OH 45202

Date Received: 10/29/12
Date Reported: 10/31/12
Project Location: **Security Square**

Sample Results Continued --------- Client Sample No.: **Macy's S-1** Analysis: **EPA 8260**

Analyte	Result	Units	Reporting Limit	Qualifier
Isopropylbenzene	< 5.0	ug/Kg	5.0	U
Bromobenzene	< 5.0	ug/Kg	5.0	U
1,1,2,2-Tetrachloroethane	< 5.0	ug/Kg	5.0	U
1,2,3-Trichloropropane	< 5.0	ug/Kg	5.0	U
n-Propylbenzene	< 5.0	ug/Kg	5.0	U
2-Chlorotoluene	< 5.0	ug/Kg	5.0	U
4-Chlorotoluene	< 5.0	ug/Kg	5.0	U
1,3,5-Trimethylbenzene	< 5.0	ug/Kg	5.0	U
tert-Butylbenzene	< 5.0	ug/Kg	5.0	U
1,2,4-Trimethylbenzene	< 5.0	ug/Kg	5.0	U
sec-Butylbenzene	< 5.0	ug/Kg	5.0	U
1,3-Dichlorobenzene	< 5.0	ug/Kg	5.0	U
4-Isopropyltoluene	< 5.0	ug/Kg	5.0	U
1,4-Dichlorobenzene	< 5.0	ug/Kg	5.0	U
1,2-Dichlorobenzene	< 5.0	ug/Kg	5.0	U
n-Butylbenzene	< 5.0	ug/Kg	5.0	U
1,2-Dibromo-3-chloropropane	< 5.0	ug/Kg	5.0	U
1,2,4-Trichlorobenzene	< 5.0	ug/Kg	5.0	U
Hexachlorobutadiene	< 5.0	ug/Kg	5.0	U
Naphthalene	< 5.0	ug/Kg	5.0	U
1,2,3-Trichlorobenzene	< 5.0	ug/Kg	5.0	U

Test Requested: **TPH - Diesel Range Organics**
Preparation Method: EPA 3550 Date Prepared: 10/29/12
Analysis Method: EPA 8015 Date Analyzed: 10/29/12

Analyte	Result	Units	Reporting Limit	Qualifier
TPH - DRO	< 10	mg/Kg	10	U

Analyte Qualifier Codes
U = Analyte was not detected
J = Analyte detected below reporting limit (estimated value)
D = Analyte reported from a sample dilution
B = Analyte was detected in the corresponding method blank

HP ENVIRONMENTAL
INCORPORATED

Report Number: **124684**

Certificate of Laboratory Analysis

Macy's
Attn: Melissa Olberding
7 West 7th St.
Cincinnati, OH 45202

Date Received: 10/29/12
Date Reported: 10/31/12
Project Location: **Security Square**

---

2. Client Sample No: **Macy's S-2** HPE Sample No.: 124684-02
Sample Matrix: Soil Date Collected: 10/26/12
Sample Location:

Test Requested: **Volatile Organic Compounds**
Preparation Method: EPA 5030 Date Prepared: 10/29/12
Analysis Method: EPA 8260 Date Analyzed: 10/29/12

Analyte	Result	Units	Reporting Limit	Qualifier
Dichlorodifluoromethane	< 5.0	ug/Kg	5.0	U
Chloromethane	< 5.0	ug/Kg	5.0	U
Vinyl chloride	< 5.0	ug/Kg	5.0	U
Bromomethane	< 5.0	ug/Kg	5.0	U
Chloroethane	< 5.0	ug/Kg	5.0	U
Trichlorofluoromethane	< 5.0	ug/Kg	5.0	U
1,1-Dichloroethene	< 5.0	ug/Kg	5.0	U
Acetone	< 5.0	ug/Kg	5.0	U
Methylene chloride	< 5.0	ug/Kg	5.0	U
Methyl-tert-butyl ether (MTBE)	< 5.0	ug/Kg	5.0	U
trans-1,2-Dichloroethene	< 5.0	ug/Kg	5.0	U
1,1-Dichloroethane	< 5.0	ug/Kg	5.0	U
2-Butanone	< 5.0	ug/Kg	5.0	U
2,2-Dichloropropane	< 5.0	ug/Kg	5.0	U
cis-1,2-Dichloroethene	< 5.0	ug/Kg	5.0	U
Bromochloromethane	< 5.0	ug/Kg	5.0	U
Chloroform	< 5.0	ug/Kg	5.0	U
1,1,1-Trichloroethane	< 5.0	ug/Kg	5.0	U
Carbon tetrachloride	< 5.0	ug/Kg	5.0	U
1,1-Dichloropropene	< 5.0	ug/Kg	5.0	U
Benzene	< 5.0	ug/Kg	5.0	U
1,2-Dichloroethane	< 5.0	ug/Kg	5.0	U
Trichloroethene	< 5.0	ug/Kg	5.0	U
1,2-Dichloropropane	< 5.0	ug/Kg	5.0	U
Dibromomethane	< 5.0	ug/Kg	5.0	U
Bromodichloromethane	< 5.0	ug/Kg	5.0	U
cis-1,3-Dichloropropene	< 5.0	ug/Kg	5.0	U
4-Methyl-2-pentanone	< 5.0	ug/Kg	5.0	U
Toluene	< 5.0	ug/Kg	5.0	U
trans-1,3-Dichloropropene	< 5.0	ug/Kg	5.0	U
1,1,2-Trichloroethane	< 5.0	ug/Kg	5.0	U
2-Hexanone	< 5.0	ug/Kg	5.0	U
Tetrachloroethene	< 5.0	ug/Kg	5.0	U
1,3-Dichloropropane	< 5.0	ug/Kg	5.0	U
Dibromochloromethane	< 5.0	ug/Kg	5.0	U
1,2-Dibromoethane	< 5.0	ug/Kg	5.0	U
Chlorobenzene	< 5.0	ug/Kg	5.0	U
1,1,1,2-Tetrachloroethane	< 5.0	ug/Kg	5.0	U
Ethylbenzene	< 5.0	ug/Kg	5.0	U
m,p-Xylene	< 5.0	ug/Kg	5.0	U
o-Xylene	< 5.0	ug/Kg	5.0	U
Styrene	< 5.0	ug/Kg	5.0	U
Bromoform	< 5.0	ug/Kg	5.0	U

Report Number: **124684**

HP ENVIRONMENTAL
INCORPORATED

Certificate of Laboratory Analysis

Macy's
Attn: Melissa Olberding
7 West 7th St.
Cincinnati, OH 45202

Date Received: 10/29/12
Date Reported: 10/31/12
Project Location: **Security Square**

Sample Results Continued --------- Client Sample No.: **Macy's S-2** Analysis: **EPA 8260**

Analyte	Result	Units	Reporting Limit	Qualifier
Isopropylbenzene	< 5.0	ug/Kg	5.0	U
Bromobenzene	< 5.0	ug/Kg	5.0	U
1,1,2,2-Tetrachloroethane	< 5.0	ug/Kg	5.0	U
1,2,3-Trichloropropane	< 5.0	ug/Kg	5.0	U
n-Propylbenzene	< 5.0	ug/Kg	5.0	U
2-Chlorotoluene	< 5.0	ug/Kg	5.0	U
4-Chlorotoluene	< 5.0	ug/Kg	5.0	U
1,3,5-Trimethylbenzene	< 5.0	ug/Kg	5.0	U
tert-Butylbenzene	< 5.0	ug/Kg	5.0	U
1,2,4-Trimethylbenzene	< 5.0	ug/Kg	5.0	U
sec-Butylbenzene	< 5.0	ug/Kg	5.0	U
1,3-Dichlorobenzene	< 5.0	ug/Kg	5.0	U
4-Isopropyltoluene	< 5.0	ug/Kg	5.0	U
1,4-Dichlorobenzene	< 5.0	ug/Kg	5.0	U
1,2-Dichlorobenzene	< 5.0	ug/Kg	5.0	U
n-Butylbenzene	< 5.0	ug/Kg	5.0	U
1,2-Dibromo-3-chloropropane	< 5.0	ug/Kg	5.0	U
1,2,4-Trichlorobenzene	< 5.0	ug/Kg	5.0	U
Hexachlorobutadiene	< 5.0	ug/Kg	5.0	U
Naphthalene	< 5.0	ug/Kg	5.0	U
1,2,3-Trichlorobenzene	< 5.0	ug/Kg	5.0	U

Test Requested: **TPH - Diesel Range Organics**
Preparation Method: EPA 3550 Date Prepared: 10/29/12
Analysis Method: EPA 8015 Date Analyzed: 10/29/12

Analyte	Result	Units	Reporting Limit	Qualifier
TPH - DRO	**23**	mg/Kg	10	

JP 10/31/12
Approved by Date

Analyte Qualifier Codes
U = Analyte was not detected
J = Analyte detected below reporting limit (estimated value)
D = Analyte reported from a sample dilution
B = Analyte was detected in the corresponding method blank

HP ENVIRONMENTAL, INC.
104 Elden St, Herndon, VA 20170 (703) 471-4200 Fax (703) 471-0020

Environmental Sample Chain-of-Custody Record

COC Reference Number: 5031

Client: MACY'S
Address: 7 WEST 7TH ST. CINCINNATI, OH 45202
Contact: MELISSA OLBERDING
Phone: 513-562-6702
Fax:

TURN-AROUND TIME: Routine / Emergency / Rush (24-48hr)
P.O./Job Number:
SITE: SECURITY SQUARE
Sampled by: KC

	Sample ID	Sample Date	Sample Time	Comp/ Grab	Matrix	Preserv. pH	# Bottles	Tests Requested: TPH-DRO	Tests Requested: VOCs	Description/Comments
1.	MACY'S S-1	10/26/12	9:15	C	S	ICE	1	X	X	
2.	MACY'S S-2	10/26/12	9:15	C	S	ICE	1	X	X	
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										
13.										
14.										
15.										

Received Condition:
Mode of Shipment:
HPE Report Number: 124684

Relinquished By: KDC Date/Time: 10/29/12 9:15 Am
Relinquished By: Date/Time:

Received By: Date/Time:
Received By Laboratory: JP Date/Time: 10/29/12 1230

MDE

Macy's
6901 Security Blvd
Baltimore Maryland 21244
Case No. 2013-0249BA
Facility ID No. 6267

Photo # 1

- Photographer: Ray Kozlowski
- Date: October 26, 2012
- Description: Tank removed from ground

MDE

Macy's
6901 Security Blvd
Baltimore Maryland 21244
Case No. 2013-0249BA
Facility ID No. 6267

Photo # 2

- Photographer: Ray Kozlowski
- Date: October 26, 2012
- Description: Excavation where tank was buried

MARYLAND DEPARTMENT OF THE ENVIRONMENT
1800 Washington Avenue, Suite 620 • Baltimore Maryland 21230-1719
(410) 537-3442 • 1-800-633-6101 • http://www.mde.state.md.us

✓

LAND MANAGEMENT ADMINISTRATION
Oil Control Program

Report of Observations

Type of Inspection/Observations: Third Party Follow-up
Site/Facility Name: MACY's
Location: 6901 Security Blvd
Baltimore Maryland 21207
Telephone: Ext.

Facility ID 6267
Date: 10/26/2012
Case No. 2013- ~~BA~~ 0249BA

Facility Inspection Status ------

Remarks: Tank and all associated piping properly abandoned by removing from the ground

Status	Section No.	Comments
------	--------	
------	--------	
------	--------	
------	--------	
------	--------	
------	--------	
------	--------	
------	--------	
------	--------	
------	--------	
------	--------	
------	--------	

MDE Inspector:
(Print) RAY KOZLOWSKI
Sign: R. J. Kozlowski

Person Interviewed:
(Print) _____
Sign: _____

Maryland Department of the Environment

Oil Control Program, Suite 620, 1800 Washington Blvd., Baltimore, MD 21230-1719
410-537-3442 410-537-3092 (fax) 1-800-633-6101 x3442 http://www.mde.state.md.us

Underground Storage Tank System Compliance Inspection Report

Instructions: Only a person currently certified by the Maryland Department of the Environment in UST Inspection shall complete this report. Detailed instructions on how to complete this form are provided in MDE's "UST Operations Inspector Reference Handbook," which is available at http://www.mde.state.md.us/Programs/LandPrograms/Oil_Control/home/index.asp. Use a second form for facilities with more than 5 tanks. Type or Print all information with blue or black ink.

RECEIVED
MAR 28 2012
OIL CONTROL PROGRAM

Section 1: General Information

Facility Name:	**Macy's Security Square Mall**
Location Address:	**6901 Security Blvd**
City:	**Baltimore, MD**
Telephone No.:	
Owner Name:	**Macy's Inc.**
Mailing Address:	**7 West 7th Street**
City, State, Zip:	**Cincinnati, OH 45202**
Telephone No.:	**513-562-6702**
Fax No.:	
E-Mail:	
Operator Name:	**Robert Kozul**
Telephone No.:	**215-331-8310**
Fax No.:	
E-Mail:	

on file self insured expires 6/14/12

MDE Facility ID Number:	Date of Inspection: mm/dd/yyyy	Current UST Registration Certificate on display or available onsite?	All applicable tanks registered?	Site located in High Risk Groundwater Use Area? *	Site or neighborhood supplied by potable well? *	Owner/Operator has provided approved documentation to demonstrate Financial Responsibility?
6267	February 22, 2012	**Yes**	**Yes**	No	**No**	**Yes**
						If yes, attach FR proof to this form.

Inspection Summary

Tank System ID Number as listed on MDE UST Registration Form / Owner Tank ID # (if different)	Section No.	Tank # 2	Tank #	Tank #	Tank #	Tank #	Tank #	Tank #
Status: (Temporarily Out of Use)	(3.)	NA						
Containment Sump Inspection	(4a.)	NA						
Dispenser Inspection	(4b.)	NA						
Tank Top Inspection	(5a.)	P						
Vent Pipe Inspection	(5b.)	P						
Spill Prevention P	(6a.)	F						
Overfill Prevention P	(6b.)	P						
Stage I Vapor Recovery	(7a.)	NA						
Stage II Vapor Recovery	(7b.)	NA						
Piping Construction and Corrosion Protection F	(8.)	F						
Tank Construction and Corrosion Protection P	(8.)	P						
Tightness Testing	(9.)	F						
Facility House Keeping	(10a.)	P						
Tank Field Monitoring Pipes and Site Wells See 10b	(10b.)	F						
Inventory Control	(11.)	F						
Tank Release Detection NA	(12.)	NA						
Piping Release Detection NA	(12.)	NA						
Inspector and Owner/Operator has signed page 2 and initialed page 24							Yes	
Addendum Form Used							No	

RK

Section 1: General Comment

§ 4-417 Environment Article, Annotated Code of Maryland

(c) False statements in required documents; tampering with monitoring devices. Any person who knowingly makes any false statement, representation, or certification in any application, record, report, plan, or other document filed or required to be maintained under this title, or by any permit, rule, regulation or order issued under this title, or who falsifies, tampers with, or knowingly renders inaccurate any monitoring device or method required to be maintained under this title or by any permit, rule, regulation, or order issued under this title, upon conviction, is subject to a fine not exceeding $10,000, or by imprisonment not exceeding six months or both.

Certified Inspector: (print)	Andrew V. Cignatta
Company:	Datanet Engineering Inc
Certification No.:	MDIC-2010-0043
Expiration Date:	September 1, 2012
Telephone No.:	410-654-1800
Facsimile No.:	410-654-3711
E-mail address:	acignatta@datanetengineering.com

"'High Risk Groundwater Use Area" (HRGUA) means all areas served by individual wells. Existing UST systems installed prior to 1/26/05 in Baltimore, Carroll, Cecil, Frederick and Harford counties or New UST systems installed after 1/26/05 in Anne Arundel, Baltimore, Carroll, Cecil, Charles, Calvert, Frederick, Harford, Howard, Montgomery, and Prince George's counties.

The MDE UST database will be updated with information listed in this inspection report and any amended facility registration form unless additional forms are required by regulation.

Certified Inspector:	**Owner/Operator or Designated Representative**
I, the Maryland Certified Inspector, have performed this UST Inspection and believe the contents of this report to be true and accurate without misrepresentation or falsification. As well, I have no financial interest with this UST Facility.	I, the Owner/Operator/Designated Representative (circle one), have read this Inspection Report and understand the condition of my UST facility, including all deficiencies, corrections and recommendations.
	Title: DISTRICT FACILITY MANAGER
Print Name: Andrew Cignatta	Print Name: ROBERT L KOPPLIN
Signature:	Signature:
Date: 3-26-12	Date: 3-19-2012

Mail REPORT To:	**Questions? Call MDE Oil Control Program at**
MDE Oil Control Program	**410-537-3442**
Suite 620	**See our web page at:**
1800 Washington Blvd.	**http://www.mde.state.md.us**
Baltimore, MD 21230-1719	

MDE Use Only

Certification Section - Reviewed By

Date Reviewed 4/20/12 P ☐ F ☒

Comments (5) Violations

Data Clerk's Initials DT Date Entered 5/15/12

Section 2: Tank System Information

Fill out the tank number for each tank but only use the MDE Tank ID numbering system. Use (✓) box if information is obtained from facility registration form.

Tank and Piping (MDE ID #)	(✓)	Tank #2	Tank #	Tank #	Tank #	Tank #
Owner Tank ID # (if different)						
Status (I-in use or T-temp. out of use)		I				
Date of Installation (mm/yyyy)	√	2/17/99				
Capacity (gallons)	√	300				
Product (see Chart **A** below for code and list compartment tank product separately)		1				
Tank Construction Material (see Chart **B** for code)	√	6				
Compartment Tank (Yes/No) (If Yes, list capacity of each compartment separately)		No				
Double-Wall Tank (Yes/No)		No				
Piping Type (SS) safe suction; **(US)** U.S. suction **(G)** gravity; **(P)**-Pressure		SS				
Piping Construction Material (see Chart **C** for code)		4				
Double-Wall Piping (Yes/No)		No				
Outer Wall Pipe Construction Material (see Chart **C** for code)		NA				
Emergency Power Generator UST (Yes/No)		Yes				
	Tank Field #1		**Tank Field #2**		**Tank Field #3**	
Global Position Signal- Only one set of coordinates is to be collected while standing over the center of each tank field.	Latitude: Longitude: 39°18'36.99"N 76°45'02.85"W		Latitude: Longitude		Latitude: Longitude	
List tank MDE ID # for each tank field according to MDE Registration Form.	2					

Section 2: Tank System Information continued on Page 4

Chart A		Chart B		Chart C	
Code	**Product Description**	**Code**	**Tank Material Description**	**Code**	**Piping Material Description**
1	Diesel	1	Asphalt Coated or Bare Steel	1	Bare Steel
2	Gasohol **E-10**	2	Cathodically Protected Steel	2	Galvanized Steel
2a	Ethanol **E-85**	3	Composite (Steel w/FRP)	3	Fiberglass Reinforced Plastic(FRP)
2b	Methanol	4	Concrete	4	Copper
3	Gasoline	5	Epoxy Coated Steel	4a	Copper-slvd. in PVC, FRP or Plastic
4	Hazardous Substance	6	Fiberglass Reinforced Plastic(FRP)	5	Flexible Plastic
5	Heating Oil #2	7	Polyethylene Tank Jacket	6	No Piping
5a	Heating Oil #4	8	Other (**Must Describe**)	7	Other (**Must Describe**)
5b	Heating Oil #5				
5c	Heating Oil #6				
6	Kerosene				
7	Mixture				
8	Used Oil				
9	Car Wash O/W Separator UST				
10	Other (**Must Describe**)				

Section 2: Tank System Information (cont'd)

Diagram: Show layout of site and all UST systems.

KEY/LEGEND (Include if applicable)

(BLD) Building location
(TF) Tank Field
(T #) Tanks (including all compartments) with MDE tank ID #s
(P) Product piping
(PS) Piping sumps
(D) Dispenser
(V) Vent pipe
(•) Tank field monitoring pipe
(ESO) Emergency Shutoff Switch
⊗ Monitoring Well
(CP) Cathodic protection test station
↑ North arrow
+ Roads bordering property
(DB) Dry Break/Stage I vapor recovery
(STP Sump) Submersible Turbine Pump
(ATG Probe) Automatic Tank Gauge
(FP) Fill Pipe
(AN) Impressed current anodes



Notification for Underground Storage Tanks

FORM APPROVED
OMB NO. 2050-0049
APPROVAL EXPIRES 6-30-88

STATE USE ONLY

I.D. Number 3-013156

Date Received 6/20/87

GENERAL INFORMATION

Notification is required by Federal law for all underground tanks that have been used to store regulated substances since January 1, 1974, that are in the ground as of May 8, 1986, or that are brought into use after May 8, 1986. The information requested is required by Section 9002 of the Resource Conservation and Recovery Act, (RCRA), as amended.

The primary purpose of this notification program is to locate and evaluate underground tanks that store or have stored petroleum or hazardous substances. It is expected that the information you provide will be based on reasonably available records, or, in the absence of such records, your knowledge, belief, or recollection.

Who Must Notify? Section 9002 of RCRA, as amended, requires that, unless exempted, owners of underground tanks that store regulated substances must notify designated State or local agencies of the existence of their tanks. Owner means—

(a) in the case of an underground storage tank in use on November 8, 1984, or brought into use after that date, any person who owns an underground storage tank used for the storage, use, or dispensing of regulated substances, and

(b) in the case of any underground storage tank in use before November 8, 1984, but no longer in use on that date, any person who owned such tank immediately before the discontinuation of its use.

What Tanks Are Included? Underground storage tank is defined as any one or combination of tanks that (1) is used to contain an accumulation of "regulated substances," and (2) whose volume (including connected underground piping) is 10% or more beneath the ground. Some examples are underground tanks storing: **1.** gasoline, used oil, or diesel fuel, and **2.** industrial solvents, pesticides, herbicides or fumigants.

What Tanks Are Excluded? Tanks removed from the ground are not subject to notification. Other tanks excluded from notification are:

1. farm or residential tanks of 1,100 gallons or less capacity used for storing motor fuel for noncommercial purposes;
2. tanks used for storing heating oil for consumptive use on the premises where stored;
3. septic tanks;
4. pipeline facilities (including gathering lines) regulated under the Natural Gas Pipeline Safety Act of 1968, or the Hazardous Liquid Pipeline Safety Act of 1979, or which is an intrastate pipeline facility regulated under State laws;
5. surface impoundments, pits, ponds, or lagoons;
6. storm water or waste water collection systems;
7. flow-through process tanks;
8. liquid traps or associated gathering lines directly related to oil or gas production and gathering operations;
9. storage tanks situated in an underground area (such as a basement, cellar, mineworking, drift, shaft, or tunnel) if the storage tank is situated upon or above the surface of the floor.

What Substances Are Covered? The notification requirements apply to underground storage tanks that contain regulated substances. This includes any substance defined as hazardous in section 101 (14) of the Comprehensive Environmental Response, Compensation and Liability Act of 1980 (CERCLA), with the exception of those substances regulated as hazardous waste under Subtitle C of RCRA. It also includes petroleum, e.g., crude oil or any fraction thereof which is liquid at standard conditions of temperature and pressure (60 degrees Fahrenheit and 14.7 pounds per square inch absolute).

Where To Notify? Completed notification forms should be sent to the address given at the top of this page.

When To Notify? 1. Owners of underground storage tanks in use or that have been taken out of operation after January 1, 1974, but still in the ground, must notify by May 8, 1986. **2.** Owners who bring underground storage tanks into use after May 8, 1986, must notify within 30 days of bringing the tanks into use.

Penalties: Any owner who knowingly fails to notify or submits false information shall be subject to a civil penalty not to exceed $10,000 for each tank for which notification is not given or for which false information is submitted.

INSTRUCTIONS

Please type or print in ink all items except "signature" in Section V. **This form must by completed for each location containing underground storage tanks.** If more than 5 tanks are owned at this location, photocopy the reverse side, and staple continuation sheets to this form.

Indicate number of continuation sheets attached: ☐

I. OWNERSHIP OF TANK(S)

Owner Name (Corporation, Individual, Public Agency, or Other Entity)
Sears, Roebuck & Co.

Street Address
6901 Security Blvd.

County
Baltimore

City: Baltimore, Maryland | State | ZIP Code: 21207

Area Code: 301 | Phone Number: 281-2255

Type of Owner *(Mark all that apply ☒)*

- ☒ Current
- ☐ Former
- ☐ State or Local Gov't
- ☐ Federal Gov't (GSA facility I.D. no. _____)
- ☐ Private or Corporate
- ☐ Ownership uncertain

II. LOCATION OF TANK(S)

(If same as Section 1, mark box here ☐)

Facility Name or Company Site Identifier, as applicable
Security Mall

Street Address or State Road, as applicable
6901 Security Blvd.

County
Baltimore

City (nearest): Baltimore, Maryland | State | ZIP Code: 21207

Indicate number of tanks at this location: 1

Mark box here if tank(s) are located on land within an Indian reservation or on other Indian trust lands: ☐

III. CONTACT PERSON AT TANK LOCATION

Name (If same as Section I, mark box here ☐)	Job Title	Area Code	Phone Number
Douglas B. Roberts	Operating Manager	301	281-2254

IV. TYPE OF NOTIFICATION

☐ Mark box here only if this is an amended or subsequent notification for this location.

V. CERTIFICATION (Read and sign after completing Section VI.)

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete.

Name and official title of owner or owner's authorized representative	Signature	Date Signed
Douglas B. Roberts - Operating Mgr.	Douglas B. Roberts	6/17/87

CONTINUE ON REVERSE SIDE

Owner Name (from Section I) Sears, Roebuck Location (from Section II) Security Mall Page No. ____ of ____ Pages

VI. DESCRIPTION OF UNDERGROUND STORAGE TANKS *(Complete for each tank at this location.)*

Tank Identification No. (e.g., ABC-123), or Arbitrarily Assigned Sequential Number (e.g., 1,2,3...)	Tank No. #1	Tank No.	Tank No.	Tank No.	Tank No.
1. Status of Tank *(Mark all that apply ☒)*					
Currently in Use	X				
Temporarily Out of Use					
Permanently Out of Use					
Brought into Use after 5/8/86					
2. Estimated Age (Years)	15				
3. Estimated Total Capacity (Gallons)	550				
4. Material of Construction *(Mark one ☒)*					
Steel	X				
Concrete					
Fiberglass Reinforced Plastic					
Unknown					
Other, Please Specify					
5. Internal Protection *(Mark all that apply ☒)*					
Cathodic Protection					
Interior Lining (e.g., epoxy resins)					
None					
Unknown	X				
Other, Please Specify					
6. External Protection *(Mark all that apply ☒)*					
Cathodic Protection					
Painted (e.g., asphaltic)	X				
Fiberglass Reinforced Plastic Coated					
None					
Unknown					
Other, Please Specify					
7. Piping *(Mark all that apply ☒)*					
Bare Steel					
Galvanized Steel	X				
Fiberglass Reinforced Plastic					
Cathodically Protected					
Unknown					
Other, Please Specify					
8. Substance Currently or Last Stored in Greatest Quantity by Volume *(Mark all that apply ☒)*					
a. Empty					
b. Petroleum					
Diesel					
Kerosene					
Gasoline (including alcohol blends)					
Used Oil	XX				
Other, Please Specify					
c. Hazardous Substance					
Please Indicate Name of Principal CERCLA Substance					
OR					
Chemical Abstract Service (CAS) No.					
Mark box ☒ if tank stores a mixture of substances					
d. Unknown					
9. Additional Information (for tanks permanently taken out of service)					
a. Estimated date last used (mo/yr)	/	/	/	/	/
b. Estimated quantity of substance remaining (gal.)					
c. Mark box ☒ if tank was filled with inert material (e.g., sand, concrete)					

SEARS

Sears, Roebuck and Co.
6901 Security Blvd.
Baltimore, MD 21207

June 16, 1987

Science and Health Advisory Group
Office of Environmental Programs
201 West Preston Street
Baltimore, MD. 21201

Dear Sir:

The enclosed form - Notification for Underground Storage Tanks may be a duplicate , if so please disreguard .

If not in your files, please keep for your records.

Thank you,

D. B. Roberts

DBR:jhr

RECEIVED
JUN 18 1987
DIVISION OF ENVIRONMENTAL
SCIENCE AND TECHNOLOGY

GROUNDWATER TECHNOLOGY

Groundwater Technology, Inc.
15010 W. 106th Street, Lenexa, KS 66215
Tel: (913) 599-0262 Fax: (913) 599-1043

December 29, 1993

State of Maryland
Department of the Environment
Hazardous and Solid Waste Management Administration
2500 Broening Highway
Baltimore, Maryland 21224

Subject: Underground Storage Tank Removal and Closure Report
Sears Store 1634
6901 Security Boulevard
Baltimore, Maryland

To Whom It May Concern:

Enclosed is the Underground Storage Tank Removal and Closure Report submitted on behalf of Sears Merchandise Group. This report documents the removal of underground storage tanks.

Should you have any questions concerning the enclosed report, please call Sherri Clark at (404) 499-9000 or Mike Girioni at (617) 769-7602.

Sincerely,
Groundwater Technology, Inc.

David Daniels

David Daniels
Program Manager

c: Ms. Bernadine G. Palka, Sears Merchandise Group
Mr. Michael Girioni, National Operations Manager

GROUNDWATER TECHNOLOGY

Groundwater Technology, Inc.
1281 Kennestone Circle, #100, Marietta, GA 30066
Tel: (404) 499-9000

December 13, 1993

Airborne Tracker # 9880627186

Mr. Richard Lego
Maryland Department of Environment
Hazardous and Solid Waste Management Administration
2500 Broening Highway
Baltimore, MD 21224

RE: Extension Request
Sears Facility #1634
6901 Security Blvd
Baltimore, MD

Dear Mr. Lego:

As discussed in our telephone conversation of December 9, 1993, Groundwater Technology, Inc., on behalf of Sears, Roebuck and Co., is requesting a 30-day extension for the installation of a monitoring well at the above referenced facility and for the submittal of the soil disposal documentation for the above referenced facility. I have attached a copy of the **Tank Removal/Abandonment** form for your convenience.

Groundwater Technology appreciates your attention to this matter. Please feel free to call me at (404) 499-9000 if you have any questions or need additional information.

Sincerely,

GROUNDWATER TECHNOLOGY, INC.

Sherri Havert Clark

Sherri Havert Clark
Staff Hydrogeologist

Enclosure

Called 12-22-93 gave 30 day extension on phone. RDL 1444

1.0 INTRODUCTION

Sears Merchandise Group contracted Groundwater Technology to perform underground storage tank (UST) closure activities at Sears Store 1634 at 6901 Security Boulevard, Baltimore, Maryland. The site is located in an area of commercial development.

The site features included USTs as listed.

Description of Underground Storage Tanks

UST ID	Capacity (gallons)	Contents	Construction
MDE 1	550	Used oil	Steel

Groundwater Technology contracted with Donald Excavating to remove the UST and associated piping from the site. The UST was permanently removed from operation on December 1, 1993.

Groundwater Technology personnel collected soil samples for laboratory analysis in accordance with the state regulatory agency UST closure guidelines.

2.0 UNDERGROUND STORAGE TANK REMOVAL

Groundwater Technology developed a site safety plan to provide a safe working environment and to comply with Occupational Safety and Health Administration (OSHA) Regulation 29 CFR 1910.120. This plan addressed specific environmental work-site hazards and presented contingency plans for site personnel. All Groundwater Technology personnel and subcontractors working at the site reviewed the plan and followed the guidelines.

On December 1, 1993, Donald Excavating, under direct supervision by Groundwater Technology personnel, excavated and removed the UST and associated piping from the UST basin. The location of the UST is shown in the figure.

Groundwater Technology submitted a state notification form to the state agency.

Before excavation started, the UST contents were quantified. The contents of the UST and piping were pumped into drums and properly stored on site. Donald Excavating inspected the UST, and the UST was rendered inert. In addition to Groundwater Technology personnel, Rick Lego (Maryland Department of Environment) and Elaine Van Aken (Sears) were on site during the excavation.

Donald Excavating personnel removed the material covering the UST basin. Fill material from the UST basin and the vent chase was excavated. As the UST was excavated, the vent and associated piping were disconnected and removed from the UST basin. Soil excavated from the UST basin and from the areas surrounding the associated piping and vent chase was stockpiled on site. A description of the stockpiling is presented in section 5.0.

During excavation it was noted that the UST was attached to a concrete pad. The concrete pad was not removed during excavation activities. It was also noted that a skimmer line was present as a part of the used-oil tank oil/water separator configuration. The skimmer line was disconnected, grouted, and capped. Lithology within the UST basin consisted of brown/black, wet silt, some clay, coarse-to-fine sand, and trace fine gravel.

Groundwater Technology personnel inspected the UST, associated piping, and vent lines. The UST had 3 holes with slight overall pitting. The UST and associated piping were removed from the site for disposal at Brooklyn Salvage in Baltimore, Maryland. A copy of the UST disposal documentation is included in appendix A.

The film did not advance in the camera; therefore, no photographs of the UST removal activities are available.

3.0 SAMPLING, TESTING, AND ANALYSIS

Groundwater Technology personnel collected soil samples on December 1, 1993. Samples were collected from the UST basin walls for laboratory analysis. See figure for sampling locations and appendix C for laboratory reports.

Duplicate samples were collected for analysis. One sample was placed in a sealable plastic bag. This sample was field tested with a photoionization detector (PID) to measure relative concentrations of petroleum hydrocarbons. The other sample was placed in a glass container, sealed with a Teflon®-lined lid, preserved, and submitted for laboratory analysis. The samples were shipped, under chain of custody and by an overnight courier, to the analytical laboratory.

The soil samples were analyzed by GTEL Environmental Laboratories. The samples were analyzed in accordance with applicable state regulations and requirements of Sears. The analytes and the methods used are presented in appendix C.

No groundwater was found in the UST basin. Therefore, no sampling was required.

4.0 UST BACKFILL GUIDANCE STANDARDS AND ACTION LEVELS

After the samples were field tested and the results reviewed, the appropriate method for disposal and/or backfilling of the excavated material was selected. The method was selected based on a review of several site-specific criteria:

- Field testing results for fill material samples
- Field testing results for samples of native soil from the floor and/or walls
- Presence or absence of groundwater in the excavation
- Previous site assessment or remedial activities
- Planned surface completion of the excavation

5.0 EXCAVATION BACKFILL

About 25 to 35 cubic yards of fill material was removed from the UST basin and associated piping trenches and stockpiled on, and covered with, plastic on site.

Based upon the results of the procedures described in section 4.0, the excavated area was backfilled with imported fill.

6.0 FLUIDS AND SOIL DISPOSAL

The fluids/sludge removed from the UST and associated piping was pumped into drums and properly stored on site.

The stockpiled backfill material was not used to refill the excavated UST basin. Disposal options for the stockpiled backfill material are being determined.

7.0 STATE FORMS

The state of Maryland requires the submission of UST closure forms that have not been specifically referenced within the text of this report. Copies of these forms can be found in appendix D.



LEGEND

— — — — AREA OF EXCAVATION

⊗ SAMPLE LOCATION POINT

NOT TO SCALE

GROUNDWATER TECHNOLOGY
2201 Brookhollow Plaza Dr. #120
Arlington, Texas 76006
(817) 633-1466
(817) 640-4900 (Metro)
(817) 633-8523 (Fax)

REV. NO.:	DRAWING DATE: 12/22/93	ACAD FILE: 1634-TK

SOIL SAMPLE LOCATION MAP

CLIENT: SEARS MERCHANDISE GROUP			PM: SC
LOCATION: STORE #1634, BALTIMORE, MD. 6901 SECURITY BOULEVARD BALTIMORE, MD			CHECKED:
DESIGNED:	DETAILED: RHW	PROJECT NO.: 013225977	FIG. #

GROUNDWATER TECHNOLOGY

Groundwater Technology, Inc.
1281 Kennestone Circle, #100, Marietta, GA 30066 USA
Tel: (404) 499-9000

October 13, 1993

Maryland Department of the Environment
Attn: Oil Control Program
2500 Broening Hwy
Baltimore, MD 21224

AIRBORNE TRACKER # 376 744 3713

Subject: 30-day Notification of UST Removal/Closure Activities

This letter serves as notification of UST removal/closure activities to be conducted. Pertinent information regarding the work is:

Activity Type: Removal

Facility: Sears Facility 1634
6901 Security Blvd.
Baltimore, MD 21207
Baltimore County

Owner: Sears, Roebuck and Co.
Bernadine Palka
Manager of Environmental Engineering
3333 Beverly Road
Hoffman Estates, IL 60179
(708) 286-8864

Consultant: Groundwater Technology, Inc.
Attn: Sherri Clark
1281 Kennestone Circle #100
Marietta, GA 30066
(404) 499-9000

Contractor: To be determined
under negotiation

The USTs to be removed are:

Capacity	Contents
1-550 gallons	used oil
3-5,000 gallons	gasoline

The approximate date for proposed work is early to mid November 1993. The date of removal is subject to contractor selection and availability. A waiver of the 30 days is requested.

Notification completed/submitted by:

GROUNDWATER TECHNOLOGY, INC.

Sherri Clark

Sherri Clark
Staff Hydrogeologist

cc: Clay Aler
Baltimore County Fire Marshall

BALTIMORE COUNTY, MARYLAND

DEPARTMENT OF PERMITS AND LICENSES
TOWSON, MARYLAND 21204

BUILDINGS ENGINEER

BUILDING PERMIT

PERMIT #: B182085 CONTROL #: TAC-175193 DIST: 11 PREC: 08
DATE ISSUED: 11/12/93 TAX ACCOUNT #: 1800010199 CLASS: 14

PLANS: CONST 0 PLOT 0 R PLAT 0 DATA ELEC NO PLUM NO
LOCATION: 6901 SECURITY BLVD
SUBDIVISION: SECURITY SQUARE SHOPPIN

OWNERS INFORMATION
NAME: SEARS ROEBUCK & CO.
ADDR: SEARS TOWER CHICAGO, ILL. 60684

THIS PERMIT EXPIRES ONE YEAR FROM DATE OF ISSUE

TENANT:
CONTR: DONALD EXCAVATING, INC.
ENGNR:
SELLR:
WORK: REMOVE 1/ 550 GALLON UNDERGROUND WASTE OIL
UNDERGROUND STORAGE TANK. REMOVAL ONLY.
WILL COMPLY WITH NFPA 30 & COMAR 26.10.01.

BLDG. CODE: BOCA CODE
RESIDENTIAL CATEGORY: OWNERSHIP: PRIVATELY OWNED

ESTIMATED $ 3,200.00 PROPOSED USE: MALL & TANK REMOVAL
EXISTING USE: RETAIL STORE

TYPE OF IMPRV: OTHER
USE: TANK, TOWER
FOUNDATION: BASEMENT:
SEWAGE: PUBLIC EXIST WATER: PUBLIC EXIST

LOT SIZE AND SETBACKS

SIZE: 18.001 AC
FRONT STREET:
SIDE STREET:
FRONT SETB: NC
SIDE SETB: NC/NC
SIDE STR SETB:
REAR SETB: NC

PLEASE REFER TO PERMIT NUMBER WHEN MAKING INQUIRIES.

"Certificate of Storage Tank Destruction"

Donald Excavating Inc.
Rosedale, Maryland

DATE 12-1-93

The undersigned guarantees that the tank(s) listed below have been rendered "unfit for further use" in accordance with current Federal, State and Local Regulations.

Having been permanently removed from service, these tanks ARE NOT:

1. Vapor free
2. Suitable for storage of Food Liquids intended for Human or Animal consumption.
3. Suitable for Underground storage of FLAMMABLE/COMBUSTIBLE/HAZARDOUS LIQUIDS OR MATERIALS

1-550	Gallon tank	Former Contents Waste oil
_____	Gallon tank	Former Contents _____
_____	Gallon tank	Former Contents _____
_____	Gallon tank	Former Contents _____

Site Location
Name: Sear's
Address: 6901 Security Blvd
Baltimore MD.

Donald Excavating, Inc.
7831 Philadelphia Road
Rosedale, MD 21237

12/06/93 08:30 FIED COLUMBIA 0002

The film did not advance in the camera; therefore, no photographs are available.

GTEL
ENVIRONMENTAL
LABORATORIES, INC.

Southeast Region
10500 University Center Drive, Suite 160
Tampa, FL 33612
(813) 979-9092 800-933-GTEL (4835)
FAX: 813-979-6914

Project Number: GTI62SRS01
013225977
Project ID: 6901 SECURITY BLVD.,
BALTIMORE, MD
Store #: 1634
Work Order Number: F312073

December 10, 1993

Ms. Sherri Clark
Groundwater Technology, Inc.
1281 Kennestone Circle NW, Suite 100
Marietta, GA 30066

Dear Ms. Clark,

Enclosed please find the analytical results for the samples received by GTEL Environmental Laboratories, Inc. on December 3, 1993 under chain of custody record 47876.

A formal Quality Assurance/Quality Control (QA/QC) program is maintained by GTEL, which is designed to meet or exceed the EPA requirements. Analytical work for this project met QA/QC criteria unless otherwise stated in the footnotes.

GTEL is certified (approved) by the State of Florida under Certificate Number HRS#E84196 and by the State of South Carolina under Certificate Number #96025.

If you have any questions concerning this analysis or if we can be of further assistance, please call our Customer Service Representative.

Sincerely,

GTEL Environmental Laboratories, Inc.

Harold Vernon
Laboratory Director

Project Number: GTI62SRS01
013225977
Project ID: 6901 SECURITY BLVD.,
BALTIMORE, MD
Store #: 1634
Work Order Number: F312073

ANALYTICAL RESULTS

Volatile Organics in Soil
EPA Method 8240[a]

GTEL Sample Number		12073-01	12073-02	12073-03	12073-04
Client Identification		NORTH (8')	SOUTH (8')	EAST (8')	WEST (8')
Date Sampled		12-01-93	12-01-93	12-01-93	12-01-93
Date Analyzed		12-09-93	12-09-93	12-09-93	12-09-93
Dilution Multiplier[b]		1	1	2	1
Analyte	Reporting Limit, mg/kg	Concentration, mg/kg			
Chloromethane	1.2	<1.2	<1.2	<1.2	<1.2
Bromomethane	1.2	<1.2	<1.2	<1.2	<1.2
Vinyl Chloride	1.2	<1.2	<1.2	<1.2	<1.2
Chloroethane	1.2	<1.2	<1.2	<1.2	<1.2
Methylene Chloride	1.2	<1.2	<1.2	<1.2	<1.2
Acetone	2.5	<2.5	<2.5	<2.5	<2.5
Carbon Disulfide	0.6	<0.6	<0.6	<0.6	<0.6
1,1-Dichloroethene	0.6	<0.6	<0.6	<0.6	<0.6
1,1-Dichloroethane	0.6	<0.6	<0.6	<0.6	<0.6
1,2-Dichloroethene (total)[c]	0.6	<0.6	<0.6	<0.6	<0.6
Chloroform	0.6	<0.6	<0.6	<0.6	<0.6
1,2-Dichloroethane	0.6	<0.6	<0.6	<0.6	<0.6
2-Butanone	2.5	<2.5	<2.5	<2.5	<2.5
1,1,1-Trichloroethane	0.6	<0.6	<0.6	<0.6	<0.6
Carbon Tetrachloride	0.6	<0.6	<0.6	<0.6	<0.6
Vinyl Acetate	2.5	<2.5	<2.5	<2.5	<2.5
Bromodichloromethane	0.6	<0.6	<0.6	<0.6	<0.6
1,2-Dichloropropane	0.6	<0.6	<0.6	<0.6	<0.6
cis-1,3-Dichloropropene	0.6	<0.6	<0.6	<0.6	<0.6
Trichloroethene	0.6	<0.6	<0.6	<0.6	<0.6
Dibromochloromethane	0.6	<0.6	<0.6	<0.6	<0.6

Project Number: GTI62SRS01
013225977
Project ID: 6901 SECURITY BLVD., BALTIMORE, MD
Store #: 1634
Work Order Number: F312073

ANALYTICAL RESULTS

Volatile Organics in Soil
EPA Method 8240[a]

GTEL Sample Number		12073-01	12073-02	12073-03	12073-04
Client Identification		NORTH (8')	SOUTH (8')	EAST (8')	WEST (8')
Date Sampled		12-01-93	12-01-93	12-01-93	12-01-93
Date Analyzed		12-09-93	12-09-93	12-09-93	12-09-93
Dilution Multiplier[b]		1	1	2	1
Analyte	Reporting Limit, mg/kg	Concentration, mg/kg			
1,1,2-Trichloroethane	0.6	<0.6	<0.6	<0.6	<0.6
Benzene	0.6	<0.6	<0.6	<0.6	<0.6
2-Chloroethylvinyl Ether	1.2	<1.2	<1.2	<1.2	<1.2
trans-1,3-Dichloropropene	0.6	<0.6	<0.6	<0.6	<0.6
Bromoform	0.6	<0.6	<0.6	<0.6	<0.6
4-Methyl-2-pentanone	2.5	<2.5	<2.5	<2.5	<2.5
2-Hexanone	2.5	<2.5	<2.5	<2.5	<2.5
Tetrachloroethene	0.6	<0.6	<0.6	<0.6	<0.6
1,1,2,2-Tetrachloroethane	0.6	<0.6	<0.6	<0.6	<0.6
Toluene	0.6	**1.3**	<0.6	**4.1**	**1.0**
Chlorobenzene	0.6	<0.6	<0.6	<0.6	<0.6
Ethylbenzene	0.6	**0.9**	<0.6	**33**	**0.8**
Styrene	0.6	<0.6	<0.6	<0.6	<0.6
Xylenes (total)	0.6	**6.0**	**2.7**	**22**	**5.1**
1,2-Dichlorobenzene	1.2	<1.2	<1.2	<1.2	<1.2
1,3-Dichlorobenzene	1.2	<1.2	<1.2	<1.2	<1.2
1,4-Dichlorobenzene	1.2	<1.2	<1.2	<1.2	<1.2

a Test Methods for Evaluating Solid Waste, SW-846, Third Edition, Revision 0, US EPA November 1986; sample preparation by methanol extraction and heated purge and trap. This method is modified for megabore column use and additional compounds. Results are calculated on a wet weight basis.

b Dilution multiplier indicates the adjustments made for sample dilution.

c Total 1,2-dichloroethene is the sum of the cis- and trans- isomers.

Project Number: GTI62SRS01
013225977
Project ID: 6901 SECURITY BLVD.,
BALTIMORE, MD
Store #: 1634
Work Order Number: F312073

ANALYTICAL RESULTS

Total Recoverable Petroleum Hydrocarbons in Soil
by Infrared Spectrometry
EPA Method 418.1/9073[a]

GTEL Sample Number		12073-01	12073-02	12073-03	12073-04
Client Identification		NORTH (8')	SOUTH (8')	EAST (8')	WEST (8')
Date Sampled		12-01-93	12-01-93	12-01-93	12-01-93
Date Extracted		12-09-93	12-09-93	12-09-93	12-09-93
Date Analyzed		12-10-93	12-10-93	12-10-93	12-10-93
Analyte	RL, mg/kg[b]	Concentration, mg/kg			
TRPH	5.0	**2800**	**360**	**1600**	**6200**
Dilution Multiplier[c]		10	10	200	100

a Test Methods for Evaluating Solid Waste, SW-846, Third Edition; extraction by Method 3550 (Modified).
b RL = Reporting Limit.
c The Dilution Multiplier indicates the factor necessary for the adjustment of the reporting limits due to sample dilutions.

RESULTS

PERCENT SOLIDS

GTEL Sample Number	12073-01	12073-02	12073-03	12073-04	--
Client Identification	NORTH (8')	SOUTH (8')	EAST (8')	WEST (8')	--
	Percent				
Percent Solids	79.7	80.0	76.5	80.3	--

GTEL ENVIRONMENTAL LABORATORIES, INC.

MEADOWBROOK INDUSTRIAL PARK
MILFORD, NH 03055
(603) 672-4835
(800) 441-4835

CHAIN-OF-CUSTODY RECORD AND ANALYSIS REQUEST 47876

Company Name: GROUNDWATER TECHNOLOGY, INC.
Phone #: (404) 499-9000
FAX #: (404) 499-9933
Company Address: 501 KENNESTONE CIRCLE NW, SUITE 100 MARIETTA, GA 30066
Site location: 6101 SECURITY BLVD BALTIMORE, MD
Project Manager: SHERRI CLARK
Client Project ID: (#) 01322-5977
(NAME) SEARS # 1634
I attest that the proper field sampling procedures were used during the collection of these samples..
Sampler Name (Print): GLEN MCFARLAND

Field Sample ID	GTEL Lab # (Lab use only)	# Containers	Matrix: WATER	SOIL	AIR	SLUDGE	PRODUCT	OTHER	Method Preserved: HCl	HNO_3	H_2SO_4	ICE	UNPRESERVED	OTHER (SPECIFY)	Sampling: DATE 1993	TIME	BTEX/602 ☐ 8020 ☐ with MTBE ☐	BTEX/Gas Hydrocarbons PID/FID ☐ with MTBE ☐	Hydrocarbons GC/FID Gas ☐ Diesel ☐ Screen ☐	Hydrocarbon Profile (SIMDIS) ☐	Oil and Grease 413.1 ☐ 413.2 ☐ SM 503 ☐	TPH/IR 418.1 ☐ SM 503 ☐	EDB by 504 ☐ DBCP by 504 ☐	EPA 503.1 ☐ EPA 502.2 ☐	EPA 601 ☐ EPA 8010 ☐	EPA 602 ☐ EPA 8020 ☐	EPA 608 ☐ 8080 ☐ PCB only ☐	EPA 624/PPL ☐ 8240/TAL ☐ NBS (+15) ☐	EPA 625/PPL ☐ 8270/TAL ☐ NBS (+25) ☐	EPA 610 ☐ 8310 ☐	EP TOX Metals ☐ Pesticides ☐ Herbicides ☐	TCLP Metals ☐ VOA ☐ Semi-VOA ☐ Pest ☐ Herb ☐	EPA Metals - Priority Pollutant ☐ TAL ☐ RCRA ☐	CAM Metals TTLC ☐ STLC ☐	Lead 239.2 ☐ 200.7 ☐ 7420 ☐ 7421 ☐ 6010 ☐	Organic Lead ☐	Corrosivity ☐ Flash Point ☐ Reactivity ☐	VOCs by EPA 8240	TPH by EPA 418.1
NORTH (8')	01	2		X								X			12-1	1710																			1	1
SOUTH (8')	02	2		X								X			12-1	1720																			1	1
EAST (8')	03	2		X								X			12-1	1730																			1	1
WEST (8')	01	2		X								X			12-1	1740																			1	1

TAT
Priority (24 hr) ☐
Expedited (48 hr) ☐
5 Business Days ☐
Other 5 Business Days ☒
BLUE ☐ CLP ☐

Special Handling
GTEL Contact
Quote/Contract #
Confirmation #
PO #

QA / QC LEVEL
OTHER

SPECIAL DETECTION LIMITS

SPECIAL REPORTING REQUIREMENTS
FAX ☐

REMARKS

Lab Use Only Lot #
Storage Location: S2-1
Work Order # F312073

CUSTODY RECORD

	Date	Time	
Relinquished by Sampler: GMcF 12	12-2-93	1700	Received by:
Relinquished by:			Received by:
Relinquished by:	12-3-93	10:00	Received by Laboratory: Killie Voight

Waybill # FDX 413537353016

v. 7/91

GROUNDWATER TECHNOLOGY

Groundwater Technology, Inc.

District Office, 3 Edgewater Drive, Suite 301, Norwood, MA 02062
Tel: (617) 769-7602 Fax: (617) 769-7785

March 30, 1994

01322-5977
(071569)

RECEIVED
MAR 31 1994

Mr. Richard Lego
Maryland Department of Environmental
Hazardous and Solid Waste
Management Administration
2500 Broening Highway
Baltimore, Maryland 21224

Subject: Confirmation of Soil Removal
Sears Facility Number 1634
Baltimore, Maryland

Dear Mr. Lego:

Please accept this letter, and the attached Bills of Lading and Disposal Receipts as confirmation of the removal of soil at the Sears Automotive Center located at 6901 Security Boulevard in Baltimore, Maryland (the site). The soil was removed from the site and received at Soil Recycling Technologies, Inc. (SRTI) facility in Hunt Valley, Maryland on March 24, 1994, in accordance with the time extension granted to Groundwater Technology, Inc. for soil removal on January 6, 1994. A total of 41.52 tons of soil was removed and received at the SRTI facility for disposal.

Thank you for your prompt attention to this matter. If you have questions, please contact me at (617) 769-7602.

Sincerely,

GROUNDWATER TECHNOLOGY, INC.

Eileen Thayer Carey
Lead Geologist
Waste Compliance Coordinator

ETC/etc

copy:
B. Palka, Sears & Roebuck Company
M. Girioni, Groundwater Technology, Inc.
B. Kittridge, Aggregate Recycling Corporation

SEARS4.27

SOIL RECYCLING TECHNOLOGIES INC

Mailing Address:
10948 Beaver Dam Road
Suite F
Hunt Valley, MD 21030

SOIL RECYCLING TECHNOLOGIES, INC.

Site Entry Ticket/Bill of Lading

11657

Ticket No. 2

Approval No.	Carrier Name	Tag No.	Carrier Address
3977	SRTI	024 E 13 MD	10948 Beaver Dam Road Hunt Valley, MD 21030

Truck No.	Trailer No.	Driver Name (Please print)
202		Dorsey B. Fleming III

Phone: (410) 584-8081

Broker Name & Address	Broker Representative	Loading Date & Time
Groundwater Technology 3 Edgewater Drive Suite 301 Norwood, MA 02062 Phone: (617) 769-7602	Eileen Carey Print Name Sign Name	3-24-94 **Receiving Date & Time** 3-24-94 12:25

Generator	Deliver To	Weights (Tons)	
Sears, Roebuck Company #1634 6901 Security Blvd. Baltimore, Maryland 21207 Phone: ( )	Miller Asphalt Products, Inc. 2803 Dede Road Finksburg, Maryland 21048	GROSS TARE NET	30.51 11.76 18.75
I hereby certify that the below named commodity was loaded on the carrier and truck identified above. Released by: (Authorized signature) X Earl H. Blackwell	I hereby certify that the below named commodity was received on the carrier and truck identified above. Received by: (Authorized signature) X Michael Lowe	Rate Amt	

Special Instructions: **Please untarp before pulling onto scales.**

24 MAR 94

Description of Commodities TICKET	Hazard Class	Codes
Petroleum Contaminated Soil RCRA Nonhazardous/DOT Nonregulated Separated at point of origin Destined for recycling/reuse	NON HAZ **Vehicle Type** DT **Volume/Units** 14 YDS	TT - Tractor Trailer DT - Dump Truck Yd - Yards Tn - Tons Dm - Drums

SRTI Use Only

Bill to: _____ Cust. No: _____

_____ Date: _____

_____ Phone: _____ Day : _____

- Received contaminated soil from _____

_____

for recycling at Miller Asphalt Products, Inc., Finksburg, MD 21048

- Approval Number: _____ Miscellaneous Costs

- _____ Loads @ _____ Tons @ _____ /Ton

- Transportation Cost _____ Tons @ _____ /Ton

- Analytical Cost _____

WHITE-BILLING GREEN-BILLING FILE CANARY-FACILITY PINK-TRUCK GOLDENROD-GENERATOR BLUE-BROKER

SOIL RECYCLING TECHNOLOGIES INC

Mailing Address:
10948 Beaver Dam Road
Suite F
Hunt Valley, MD 21030

OIL RECYCLING TECHNOLOGIES INC.

Site Entry Ticket/Bill of Lading

11656

Ticket No. 1

Approval No.	Carrier Name	Tag No.	Carrier Address
3977	SRTI	024 E D 13	10948 Beaver Dam Road Hunt Valley, MD 21030

Truck No.	Trailer No.	Driver Name (Please print)	Phone:
202		Dorsey B. Fleming III	(410)584-8081

Broker Name & Address	Broker Representative	Loading Date & Time
Groundwater Technology 3 Edgewater Drive Suite 301 Norwood, MA 02062 Phone:(617) 769-7602	Eileen Carey Print Name Sign Name	3-24-94 Receiving Date & Time 3-24-94 930

Generator	Deliver To	Weights (Tons)	
Sears,Roebuck Company #1634 6901 Security Blvd. Baltimore, Maryland 21207 Phone:( )	Miller Asphalt Products, Inc. 2803 Dede Road Finksburg, Maryland 21048	GROSS W TARE NET	34.60 11.83 22.77
I hereby certify that the below named commodity was loaded on the carrier and truck identified above. Released by:(Authorized signature) X Earl A. Bayliss	I hereby certify that the below named commodity was received on the carrier and truck identified above. Received by:(Authorized signature) X	Rate Amt	

Special Instructions: **Please untarp before pulling onto scales.**

24 MAR 94

Description of Commodities	TICKET	Hazard Class	Codes
Petroleum Contaminated Soil RCRA Nonhazardous/DOT Nonregulated Separated at point of origin Destined for recycling/reuse		NON HAZ Vehicle Type DT Volume/Units 14 YDS	TT - Tractor Trailer DT - Dump Truck Yd - Yards Tn - Tons Dm - Drums

SRTI Use Only

Bill to: _____ Cust. No: _____

_____ Date: 3-24-94

_____ Phone: _____ Day : THURS

- Received contaminated soil from SEARS, ROEBUCK CO #1634 6901 SECURITY BLVD. BALTIMORE, MD 21207

for recycling at Miller Asphalt Products, Inc., Finksburg, MD 21048

- Approval Number: 3977

Miscellaneous Costs

- 2 Loads @ 41.52 Tons @ _____ /Ton

- Transportation Cost _____ Tons @ _____ /Ton

- Analytical Cost _____

WHITE-BILLING GREEN-BILLING FILE CANARY-FACILITY PINK-TRUCK GOLDENROD-GENERATOR BLUE-BROKER

GROUNDWATER TECHNOLOGY

Groundwater Technology, Inc.
4200 First Avenue, Suite 110, Nitro, WV 25143 USA
Tel: (304) 755-5171 Fax: (304) 755-5259

April 11, 1994

Mr. Richard D. Lego
Maryland Department of the Environment
Oil Control Program
2500 Broening Highway
Baltimore, Maryland 40601

RECEIVED
APR 27 1994
OIL CONTROL PROGRAM

Re: Sears Store #1634
Security Boulevard
Baltimore, Maryland

Dear Mr. Lego:

On behalf of Sears, Roebuck and Co. (Sears) and Groundwater Technology, Inc. (GTI), thank you for your support as Sears seeks to gain closure of sites previously containing underground storage tanks (USTs).

In the state of Maryland, Sears and GTI removed USTs from multiple locations just prior to the end of 1993. This activity was performed as a single project with tank removal reports issued to your agency for each individual site.

We recognize that for each referenced site, additional work will be required. To that end, we will be performing further site assessment activities during the months of April and May, 1994. This period has been selected as a result of weather impacts. A report summarizing the results of site assessment activities will be submitted to you by June 1994.

Our proposed additional work scope is attached for your review. The proposed work is intended to supplement, not replace, state requirements. A GTI project manager will be contacting your agency with a specific date for site work in the event a representative of your agency would like to be present.

The proposed soil assessment work plan will be conducted initially to delineate the extent of petroleum-impacted soil. A geoprobe and on-site gas chromatograph will be used to rapidly delineate the impacted area. A groundwater and soil assessment will then be conducted with a standard drill rig to collect soil samples for laboratory analysis and to install monitoring wells for subsequent groundwater sample collection and analysis.

Upon completion of all on-site activities a report, in accordance with state requirements, will be completed and submitted to your office.

To the extent possible, Sears will be seeking reimbursement for qualified activities.

If you have any questions, please contact the undersigned at (304) 755-5171. The Sears representative for this project is Bernadine Palka at (708) 286-8864.

Thank you for your assistance.

Very truly yours,
Groundwater Technology, Inc.

John A. Frankenthal
Zone Project Manager

Attachment

Copy: Bernadine Palka, Sears
Rick Salness, Groundwater Technology
Dave Daniels, Groundwater Technology

SEARS/MARYLAND\#1634\ASSMENT.LTR

SOIL ASSESSMENT WORK PLAN

APPROACH

The subject site has been identified as impacted by hydrocarbons within the soil. No groundwater was encountered and no liquid phase hydrocarbons were observed. As a result, no monitoring wells are proposed for installation at this time.

For the subject site, Groundwater Technology will perform a field survey by obtaining soil samples at multiple horizons. This will be accomplished using a GeoProbe™ style of sampling device or equivalent. Sampling will be performed sufficient to define the extent of impacted soils. Collected samples will be chemically analyzed with an on-site gas chromatograph. Should impact to groundwater be identified, additional assessments will be considered.

FIELD ACTIVITIES

The purpose of the soil assessment is to establish the baseline of subsurface conditions relative to extended impact. Before initiating work, Groundwater Technology will identify the locations of all underground utilities. A minimum number of five sample point locations will be placed by Groundwater Technology and could include the vicinity of the pipe trench, UST pad, and pump islands. A site specific work plan will be developed per conditions identified. The probe point locations will be recorded by distance and direction from existing physical structures and plotted on an existing site map.

The probe will be advanced to a maximum of 20 feet deep or until probe refusal (i.e., bedrock, cobbles or sandstone). Soil samples will be retrieved from each probe point: one above five feet and the other from a depth below five feet (to be determined by field screening in the vadose zone).

If encountered, groundwater samples will be obtained at the probe point locations. After the samples have been collected, the probe holes will be filled to the surface with a concrete/bentonite slurry so they will not provide a potential pathway for vertical fluid migration. If liquid petroleum hydrocarbon (LPH) is observed at any of the locations during this assessment, Groundwater Technology will immediately notify the appropriate regulatory agency and other assessment activities will be initiated via a separate work plan.

All samples obtained (soil and, if present, groundwater), will be collected in duplicate and immediately placed in appropriate containers. The containers will be properly labeled, and preserved as required by EPA protocol. One set of labeled containers will be placed in ice-filled coolers for transport to GTEL Environmental Laboratories for potential chemical analysis. The second set of samples will be analyzed with an on-site gas chromatograph for BTEX by EPA Method 8020/SW846 and for TPH by EPA Method 418.1.

REPORT PREPARATION

A letter report of activities and results will be submitted to the appropriate regulatory agency within 45 business days after completion of site work. The report will include:

- Description of surrounding areas contiguous to the site
- Soil assessment summary including a discussion of sample locations, a description of procedures, a discussion of physical soil sample parameters and analytical data (tabulated)
- Groundwater assessment summary including a description of procedures, a discussion of apparent groundwater levels, and laboratory analytical data (tabulated), if groundwater is encountered
- Site map and sample location drawings
- Conclusions and recommendations
- Photographic documentation
- QA/QC procedures

CONDITIONS

- A data report will be issued identifying location and screening and/or chemical analytical results for each sample.
- General comments on lithology will be provided per description of discrete interval samples obtained.
- Static water levels will not be measured.
- LPH if identified will be noted, but will not be sampled or analyzed as a part of this work scope.
- Identification of groundwater impact or separate-phase hydrocarbons will result in the execution of additional work scope inclusive of monitor well installation.
- Requisite State forms will be filled out and included as a part of the report.
- Differing state required work scopes will be performed as a part of or in addition to this work plan.

SOIL AND GROUNDWATER ASSESSMENT WORK PLAN

APPROACH

The subject site has been identified as impacted by hydrocarbons within the soil and potentially the groundwater. As a result, a site assessment will be performed in an attempt to characterize the vertical and horizontal extent of hydrocarbon impact.

For the subject site, Groundwater Technology will install two-inch diameter (minimum) monitor wells completed in a manner consistent with the requirements established for this locale. Wells will be installed and sampling performed sufficient to provide adequate characterization of subsurface conditions.

FIELD ACTIVITIES

Groundwater Technology will supervise the installation of a minimum of four soil boreholes to be completed as monitoring wells at this facility. Soil boreholes will be advanced to approximately 10 feet below the soil and groundwater interface. It is anticipated that the soil boreholes will be advanced to a maximum depth of 25 feet below grade. One of the boreholes will be located as near as possible to the suspected release source area. Two boreholes will be situated to complete a triangulation around the first well and one at an alternative location.

Soil boreholes will be drilled with a truck-mounted mobile drilling rig using hollow-stem augers. Soil samples will be collected continuously with either a split-spoon sampler or a continuous core barrel. The soil samples will be field screened with an organic vapor analyzer (OVA) or photoionization detector (PID) for petroleum hydrocarbon vapors.

Three soil samples will be obtained from each borehole for potential laboratory chemical analysis. One of these samples will be obtained from the zone for which the highest field screening results were obtained, one from the soil and groundwater interface, and one from the bottom of the borehole. The soil samples will be placed in glass jars, labeled, packed on ice, and shipped overnight to a GTEL Environmental Laboratory. Chain-of-custody documentation will accompany the samples during shipment.

Collected soil samples will be analyzed in accordance with state-specific regulations, and based on the previous contents of the removed underground storage tanks (USTs) as follows:

UST CONTENTS	CHEMICAL ANALYSES
Gasoline	BTEX (EPA Method 8020)
Diesel	BTEX (EPA Method 8020) TPH (EPA Method 418.1)
Heating Oil, Bulk Oil	TPH (EPA Method 418.1)
Used Oil	VOCs (EPA Method 8240) TPH EPA Method 418.1)

Additional soil samples will be collected from the unsaturated zone in the least-impacted borehole for analysis of bulk density, porosity, fraction organic carbon, permeability, and water content. These parameters will give indications of soil transmissivities, which may be used later to analyze hydrologic transport conditions. These analyses will be conducted by a geotechnical laboratory.

Soil cuttings will be analyzed in accordance with approved local landfill parameters to determine disposal characteristics and will be subsequently disposed in accordance with Sears and state-specific guidelines.

The boreholes will be completed as monitoring wells using two-inch-diameter (minimum), threaded, 0.020-inch slotted PVC monitoring well screen and PVC riser piper. The slotted well screen will extend above the groundwater surface to ensure detection of dissolved petroleum hydrocarbons and liquid-phase hydrocarbons (LPH), if present, during periods of fluctuating water levels. The annular space between the borehole and the well screen will be backfilled with a sand pack and capped with a bentonite seal and grout to preclude any potential surface water infiltration. The monitoring wells will be subsequently fitted with a locking cap and lock, and will be enclosed in flush-mounted traffic-bearing road boxes.

After installation, monitoring wells will be developed to remove fine-grained particles that may become emplaced in the borehole walls and filter pack during the drilling process. The removal of these fine-grained particles will aid in providing a more accurate representation of groundwater elevations in the monitoring wells. Monitoring wells will be developed by manual bailing and surging. The water removed from each monitoring well will be placed in barrels and subsequently disposed by an approved contractor.

Monitoring well gauging will be conducted with an interface probe which measures depth to groundwater and thickness of any LPH in the wells. Gauging data will subsequently be used in the construction of a groundwater elevation map.

Prior to groundwater sampling of monitoring wells, about three well volumes of water will be removed from each monitoring well to ensure that the sample taken is representative of the surrounding geologic formation. A water sample will then be extracted with a clean bailer.

Samples will be placed in glass containers, acidized, labeled, packed on ice, and shipped overnight to GTEL laboratory for analysis. Chain-of-custody documentation will accompany all samples en-route to the laboratory. Water samples will be analyzed in accordance with state-specific parameters, and based on the previous contents of the removed underground storage tanks (USTs) as follows:

UST CONTENTS	CHEMICAL ANALYSES
Gasoline	BTEX (EPA Method 8020)
Diesel	BTEX (EPA Method 8020) TPH (EPA Method 418.1)
Heating Oil, Bulk Oil	TPH (EPA Method 418.1)
Used Oil	VOCs (EPA Method 8240) TPH EPA Method 418.1)

As part of the required sensitive receptor survey, a Groundwater Technology geologist will conduct a walking survey of the area immediately adjacent to the Sears site to locate registered and unregistered water wells within a 500-foot radius. In addition, Groundwater Technology will coordinate a search of state-registered water wells within a 1/2-mile radius of the site. Data obtained from these surveys will be used to identify "at risk" wells and establish the nature and depth of groundwater in the area.

Site and vicinity surveys will be conducted by a registered professional surveyor. The site survey will identify all significant site features including UST system location, subsurface utilities, relevant building and structures, monitoring well locations and top of casing elevations and adjacent roadways. The vicinity map will portray all roadways, labeled structures, adjacent properties, and water wells within a 500-foot radius of the facility.

REPORT PREPARATION

The initial assessment report will be developed after completion of all field activities. The report will include:

- An executive summary
- A site characterization including discussions of the regional and local geology and hydrogeology, potential sensitive receptors, topographic map, site map, and site vicinity map
- A soil assessment summary including a discussion of sample locations, a description of procedures, a discussion of physical soil parameters, laboratory analytical data (tabulated), distribution map for adsorbed petroleum, descriptive boring logs, and a soil description using the Unified Soil Classification System
- A groundwater assessment summary including a description of procedures, a discussion of groundwater levels during drilling and after well development, laboratory analytical data (tabulated), groundwater elevations table, groundwater gradient map, and a distribution map for dissolved petroleum
- An account of the disposition of all soil and water generated during field activities
- Conclusions and recommendations
- Quality Assurance/Quality Control Procedures

CONDITIONS

- Requisite state forms will be filled out and included as a part of the report.

REGISTRATION #_____

UNDERGROUND LEAK SUMMARY & TANK CLOSURE

CASE # 94-1654 BH2 DATE OPENED 12-1-93 DATE CLOSED 3-28-95

FILE NAME Sears INSPECTOR'S INITIALS GTT

TYPE OF CASE:

A)	PULL	✓	E)	COMPLIANCE CHECK	
B)	INSTALLATION		F)	TANK TEST FAILURE	
C)	SURFACE		G)	ABANDONMENT IN PLACE	
D)	LEAK INVESTIGATION		H)	OTHER	

****

SPILL AFFECTED:

A)	GROUNDWATERS		F)	SANITARY LINE	
B)	DOMESTIC WELLS		G)	UTILITY WORK OR LINES	
C)	SURFACE WATERS		H)	REACHED ADJOIN. PROPERTY	
D)	A BUILDING		I)	NONE/OTHER (SPECIFY)	
E)	STORM DRAIN		J)	SOILS	✓

****

OWNER OF SYSTEM:

A)	MAJOR OIL COMPANY		F)	PRIVATE RESIDENT	
B)	LOCAL OIL COMPANY		G)	APARTMENT	
C)	PRIVATELY OWNER SERVICE STATION		H)	SCHOOL	
			(I)	COMMERCIAL BUSINESS	✓
D)	GOVERNMENT FACILITY		J)	OTHER (SPECIFY)	
E)	MARINA				

****

IF UNDER TYPE OF CASE ITEM B, C, OR E IS CHECKED, DO NOT FILL IN CHART BELOW. OBSERVATION WELLS INSTALLED? YES (NO) # OF WELLS _____

	CAPACITY OF TANK	TANK TYPE	LINE TYPE	AGE	PRODUCT	STATUS OF TANK	LEAK FOUND
1	550	A	A	E	H	S	N
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							

REVIEWED BY TRW CODES ON REVERSE SIDE

CODES FOR USE ON REVERSE SIDE

TYPE:

A) Steel
B) Fiberglass
C) Cathodically-Protected Steel
D) Other
E) Clad Steel
F) Copper

AGE:

A) 1-5 years
B) 6-10 years
C) 11-15 years
D) 16-20 years
E) Over 20 years

PRODUCT:

A) Gasoline
B) #2 Oil
C) Kerosene
D) #4 Oil
E) #5 Oil
F) #6 Oil
G) Jet Fuel
H) Waste Oil
I) Asphalt
J) Other
K) Diesel

LEAK FOUND IN:

A) Tank
B) Supply Line
C) Return Line
D) Vent Line
E) Fittings
F) Fill Pipe
G) Air Pocket
H) None
I) Other
J) Flex Connector

STATUS:

A) In Service
B) Removed
C) Abandoned-In-Place

MARYLAND DEPARTMENT OF THE ENVIRONMENT
2500 BROENING HIGHWAY
BALTIMORE, MARYLAND 21224

CONTINUATION REPORT

Case No.: 94-1624 BA2 Date: 9 FEB 21

Page:

YOUR WRITER UPON VISITING SITE AND RE-VIEWING THE ABOVE CASE FOUND NO EVIDENCE OF ANY DRUMS OR CONTAINERS ON SAID ANY GROUND. REQUEST CLOSURE OF CASE

Observer: [signature] Person Interviewed:

MDE 316 (3-94)

MARYLAND DEPARTMENT OF THE ENVIRONMENT
2500 Broening Highway ● Baltimore, Maryland 21224
(410) 631-3000

Parris N. Glendening
Governor

Jane T. Nishida
Secretary

June 2, 1995

CERTIFIED MAIL

D.B. Roberts
Sears, Roebuck & Company
6901 Security Blvd.
Baltimore MD 21207

RE: Facility I.D. #3-013156 BA
Notice of Violation NV-95-502

Dear Mr. Roberts:

On October 31, 1994 the Waste Management Administration's Oil Control Program requested an amended underground storage tank registration form be completed to show tank removed. As of this date Sears, Roebuck and Company has failed to comply.

The above-cited findings constitute a violation of Maryland Regulations, COMAR 26.10.03.03. Based on this violation, the Waste Management Administration hereby informs **Sears, Roebuck and Company** that within ten (10) days after receipt of this notice, in order to come into compliance, you must take the following corrective action:

- **Submit an amended underground storage tank registration form to show tank removed from 6901 Security Blvd.**

Failure to perform this advised corrective action could result in additional enforcement action from this Administration which could include the issuance of civil penalties and other legal sanctions.

If you have any questions regarding the reporting procedures, please contact Ms. Cynthia Keller, Section Head, Administrative Support Section at (410) 631-3433.

Sincerely,

Herbert M. Meade, Chief
Compliance/Remediation Division
Oil Control Program

HMM:CK:lc
cc: Mr. Richard Collins
Mr. Horacio Tablada
Ms. Cynthia Keller

MARYLAND DEPARTMENT OF THE ENVIRONMENT
2500 Broening Highway • Baltimore, Maryland 21224
(410) 631-3000

Parris N. Glendening
Governor

Jane T. Nishida
Secretary

June 2, 1995

CERTIFIED MAIL

D.B. Roberts
Sears, Roebuck & Company
6901 Security Blvd.
Baltimore MD 21207

RE: Facility I.D. #3-013156 BA
Notice of Violation NV-95-502

Dear Mr. Roberts:

On October 31, 1994 the Waste Management Administration's Oil Control Program requested an amended underground storage tank registration form be completed to show tank removed. As of this date Sears, Roebuck and Company has failed to comply.

The above-cited findings constitute a violation of Maryland Regulations, COMAR 26.10.03.03. Based on this violation, the Waste Management Administration hereby informs **Sears, Roebuck and Company** that within ten (10) days after receipt of this notice, in order to come into compliance, you must take the following corrective action:

- **Submit an amended underground storage tank registration form to show tank removed from 6901 Security Blvd.**

Failure to perform this advised corrective action could result in additional enforcement action from this Administration which could include the issuance of civil penalties and other legal sanctions.

If you have any questions regarding the reporting procedures, please contact Ms. Cynthia Keller, Section Head, Administrative Support Section at (410) 631-3433.

Sincerely,

Herbert M. Meade, Chief
Compliance/Remediation Division
Oil Control Program

HMM:CK:lc
cc: Mr. Richard Collins
Mr. Horacio Tablada
Ms. Cynthia Keller

FACILITY I.D. 3-013156 BA

AS A RESULT OF INFORMATION RECENTLY RECEIVED BY THE OIL CONTROL PROGRAM, YOU ARE BEING ADVISED OF THE FOLLOWING:

____ You have verified that you are no longer the owner of the underground storage tank(s). Please provide the MDE/Oil Control Program with the name and address of the new owner(s).

____ You have been identified as the owner of the property and/or the underground storage tank(s) located at _____

_____

____ You need to provide a copy of the MDE UST Removal/Abandonment Form as proof of removal or abandonment of your underground storage tank(s).

✓ You need to complete and return to the MDE/Oil Control Program an amended underground storage tank registration form (MDE Form 231 enclosed).

____ You have not fully completed the underground storage tank registration form (MDE Form 231) and it is being returned to you for completion of item(s):

_____

____ You need to remit the amount due on enclosed Invoice #_____. Please make your check payable to "MD UST UPGRADE AND REPLACEMENT FUND" and include your Federal Employer Identification Number or your Social Security Number.

____ You have now received a SECOND NOTICE of payment due on enclosed Invoice # _____. Remittance is due within 30 days.

____ You have now received a FINAL NOTICE of payment due on enclosed Invoice # _____. Remittance is due within 15 days or referral to Central Collection will occur.

____ You have been billed in error. If you still have the invoice, disregard immediately.

____ You are due a refund (allow 4-6 weeks for processing).

✓ Other: Tank was removed 12/1/93 per case 94-1624BA. An amended registration is required to update our records.

Reviewed by: CK
Date: 10/31/94

INVOICE NO. 12501

STATE OF MARYLAND
Department of the Environment

2500 BROENING HIGHWAY BALTIMORE, MARYLAND 21224

(301) 631-

William Donald Schaefer
Governor

Robert Perciasepe
Secretary

PAID

INVOICE

39.01.06.01 PROJECT 3728 FUND 03

SOURCE CODE 02.61.13

DATE July 9, 1991

3-013156 BA

Sears, Roebuck & Co.
NAME

6901 Security Blvd.
STREET ADDRESS

Baltimore MD 21207
CITY STATE ZIP

AMOUNT DUE: $ 100.00

AMOUNT PAID:

DUE DATE: August 9, 1991

YOU MUST RETURN THIS PORTION WITH CHECK

39.01.06.01 PROJECT 3728 FUND 03
SOURCE CODE 02.61.13

REF NO: 3-013156

DESCRIPTION/COMMENTS 1 used oil tank

MAKE CHECK PAYABLE TO: MD UST UPGRADE & REPLACEMENT FUND

PLEASE PRINT YOUR INVOICE NUMBER ON YOUR CHECK AND RETURN TO:

DEPARTMENT OF THE ENVIRONMENT
FISCAL SERVICES DIVISION
CASH RECEIPTS UNIT
2500 BROENING HIGHWAY
BALTIMORE, MARYLAND 21224

RETAIN THIS PORTION FOR YOUR RECORDS

INVOICE NO. 12501

MDE 218

RECYCLED PAPER

STATE OF MARYLAND
DEPARTMENT OF THE ENVIRONMENT
2500 Broening Highway Baltimore, Maryland 21224

William Donald Shaefer
Governor

Robert Perciasepe
Secretary

INVOICE

INVOICE NO. 27291

39.01. .01 PROJECT 3728 FUND 03 OBJECT ITEM DATE OCTOBER 26, 1992

SOURCE CODE 02.61.13

NAME & ADDRESS:

SEARS (SECURITY MALL)
6901 SECURITY BLVD.
BALTIMORE, MD 21207

AMOUNT DUE: 100.00

DUE DATE: NOVEMBER 26, 1992

AMOUNT PAID:

FEDERAL ID # _____ (Social Security or Employer ID #)
(Please Include the above Federal ID # if it is Blank, per State Regulations)

REFERENCE NUMBER: 3-013156 BP

DESCRIPTION/COMMENTS: 1 USED OIL TANK LOCATED AT THE ABOVE ADDRESS

FOR QUESTIONS CALL UST/LUST PROGRAM AT (410) 631-3442

MAKE CHECK PAYABLE TO: MARYLAND UST UPGRADE & REPLACEMENT FUND
MAIL TO :

DEPARTMENT OF THE ENVIRONMENT
P. O. BOX 1417
BALTIMORE, MD 21203-1417

PLEASE PRINT THE INVOICE NUMBER ON YOUR CHECK

MDE 218 PAYER COPY

STATE OF MARYLAND
DEPARTMENT OF THE ENVIRONMENT
2500 Broening Highway Baltimore, Maryland 21224

William Donald Schaefer
Governor

David A.C. Carroll
Secretary

INVOICE

PCA 13728 COMP-OBJ 5673 SUFFIX 607

INVOICE NO. 085124

39.01. PROJECT FUND OBJECT ITEM

DATE JULY 11, 1994

SOURCE CODE

NAME & ADDRESS:

SEARS
6901 SECURITY BLVD.
BALTIMORE, MD 21207

AMOUNT DUE: 100.00

DUE DATE: SEPTEMBER 1, 1994

AMOUNT PAID:

FEDERAL ID # _____ (Social Security or Employer ID #)
(Please Include the above Federal ID # if it is Blank, per State Regulations)

REFERENCE NUMBER: 3-013156 bx

DESCRIPTION/COMMENTS:

1 USED OIL TANK AT ABOVE ADDRESS
AMOUNT DUE FOR CALENDAR YEAR 1994: $100

FOR QUESTIONS CALL OIL CONTROL PROGRAM AT (410) 631-3433

MAKE CHECK PAYABLE TO: MARYLAND UST UPGRADE & REPLACEMENT FUND
MAIL TO :

DEPARTMENT OF THE ENVIRONMENT
P. O. BOX 1417
BALTIMORE, MD 21203-1417

PLEASE PRINT THE INVOICE NUMBER ON YOUR CHECK

MDE 218 PAYER COPY

MDE MARYLAND DEPARTMENT OF THE ENVIRONMENT
2500 Broening Highway • Baltimore, Maryland 21224
(410) 631-3000

William Donald Schaefer
Governor

SECOND NOTICE

David A.C. Carroll
Secretary

INVOICE NO.: 85124

PCA 13728 COMP-OBJ 5673 SUFFIX 607

DATE: SEPTEMBER 2, 1994

NAME & ADDRESS:
SEARS
6901 SECURITY BLVD.
BALTIMORE, MD 21207

AMOUNT DUE: $ 100.00

DUE DATE: OCTOBER 3, 1994

AMOUNT PAID:

FEDERAL ID#_____ (Social Security or Employer ID#)

(Please Include the above Federal ID# if it is blank, per State Regulations)

REFERENCE NUMBER: 3-013156 BA

DESCRIPTION/COMMENTS: SECOND NOTICE

1 USED OIL TANK AT ABOVE ADDRESS
AMOUNT DUE FOR CALENDER YEAR 1994: $100

DATE OF NOTICE: SEPTEMBER 2, 1994

THIS ACCOUNT IS NOW SERIOUSLY PAST DUE.
IF YOU HAVE NOT ALREADY DONE SO, REMIT
PAYMENT IMMEDIATELY.

FOR QUESTIONS, CALL THE OIL CONTROL PROGRAM AT (410) 631-3433
MAKE CHECK PAYABLE TO:

MD UPGRADE & REPLACEMENT FUND

MAIL TO:

DEPARTMENT OF THE ENVIRONMENT
P.O. BOX 1417
BALTIMORE, MD 21203-1417

PLEASE PRINT THE INVOICE NUMBER ON YOUR CHECK

MDE 218

MDE MARYLAND DEPARTMENT OF THE ENVIRONMENT
2500 Broening Highway • Baltimore, Maryland 21224
(410) 631-3000

William Donald Schaefer
Governor

FINAL NOTICE

David A.C. Carroll
Secretary

INVOICE NO.: 85124

PCA 13728 COMP-OBJ 5673 SUFFIX 607

DATE: OCTOBER 3, 1994

NAME & ADDRESS:

SEARS
6901 SECURITY BLVD.
BALTIMORE, MD 21207

AMOUNT DUE: $ 100.00

DUE DATE: OCTOBER 18, 1994

AMOUNT PAID:

FEDERAL ID#_____ (Social Security or Employer ID#)
(Please Include the above Federal ID# if it is blank, per State Regulations)

REFERENCE NUMBER: 3-013156

DESCRIPTION/COMMENTS: FINAL NOTICE

1 USED OIL TANK AT ABOVE ADDRESS
AMOUNT DUE FOR CALENDER YEAR 1994: $100

DATE OF NOTICE: OCTOBER 3, 1994

PRIOR ATTEMPTS TO RECONCILE YOUR ACCOUNT HAVE BEEN UNSUCCESSFUL.
PAYMENT IN FULL MUST BE RECEIVED NO LATER THAN 10/18/94
OR YOUR ACCOUNT WILL BE REFERRED FOR COLLECTION.

FOR QUESTIONS, CALL THE OIL CONTROL PROGRAM AT (410) 631-3433
MAKE CHECK PAYABLE TO:
MD UPGRADE & REPLACEMENT FUND

MAIL TO:
DEPARTMENT OF THE ENVIRONMENT
P.O. BOX 1417
BALTIMORE, MD 21203-1417

PLEASE PRINT THE INVOICE NUMBER ON YOUR CHECK

MDE 218

94-1624 BA
RL
open

MARYLAND DEPARTMENT OF THE ENVIRONMENT
Waste Management Administration

lwk 10/31/94

MEMORANDUM

TO: James McClafferty

FROM: Cindy Keller
Oil Control Program lwk

DATE: 10/28/94

SUBJECT: Proposed Invoice Change

==========

Payee Sears Reference #3-013156 BA

Invoice Number 85124 Referral to CCU: yes( ) no ( )

Amount Invoiced 100

Revised Amount 0

Reason for Change Tank removed 12/1/93 per case 94-1624 BA.

Requesting annul reg.

==========

Supervisory approval of proposed invoice change:

Signature [signature] Date 10/28/94

Title PA

Please type or print in ink all items except "signature" in Section V. This form must be completed for each location containing underground storage tanks. If more than 5 tanks are owned at this location, photocopy the following pages and staple continuation sheets to this form.

Indicate number of continuation sheets attached _____

FACILITY NUMBER 3-013156 BA
(State Use Only)

I. OWNERSHIP OF TANK(S)

Name: Sears, Roebuck and Co., Inc.

Street: 6901 Security Blvd

City: Baltimore State: MD Zip: 21244

Phone: 410-281-2255 County: Baltimore

TYPE OF OWNER

( ) Federal (GSA facility ID#_____)

( ) State ( ) County

( ) Municipal ( ) Public School District

(XX) Private or Corporate ( ) Volunteer Fire or Ambulance Company

( ) Current ( ) Former

( ) Other_____

II. LOCATION OF TANK(S)

Name:_____

Street:_____

City:_____State:_____Zip:_____

County:_____

Number of tanks at this location:_____

III. CONTACT PERSON AT TANK LOCATION

Name:_____

Job Title:_____

Area Code:_____Phone:_____

IV. TYPE OF NOTIFICATION

(XX) Check here only if this is an amended or subsequent notification for this location.

NOTE: NOT APPLICABLE TO HEATING OIL TANKS ON-SITE.

I have financial responsibility in accordance with Subpart I of RCRA. Please specify:

Method:_____

Insurer:_____

Policy Number:_____

V. CERTIFICATION

(Read and sign after completing Section VII.)

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete.

Name: John V. Long
(Please Print)

Title: Loss Prevention Manager

Signature: _____

Date Signed: June 05, 1995

VI. CERTIFICATION OF COMPLIANCE

(Complete for all new tanks at this location)
(All others skip to next page)

The installer has been certified by the Maryland Department of the Environment.

OATH: I certify that the information concerning installation provided is true to the best of my belief and knowledge.

Installer:_____

Date:_____

Certificate Number:MDIC-_____

Position:_____

Company:_____

Address:_____

Release Detection (Mark all that apply)

( ) Automatic tank gauging.

( ) Vapor monitoring.

( ) Groundwater monitoring.

( ) Interstitial monitoring within a secondary barrier.

( ) Interstitial monitoring within a secondary containment.

( ) Automatic line leak detectors.

( ) Line tightness testing.

( ) Another method allowed by the Maryland Department of the Environment. Please specify._____

( ) None

Corrosion Protection

( ) As specified for coated steel tanks with cathodic protection.

( ) As specified for coated steel piping with cathodic protection.

Tank Identification Number_____

VII. DESCRIPTION OF UNDERGROUND STORAGE TANKS

	Tank No. 1	Tank No. 2	Tank No. 3	Tank No. 4	Tank No. 5
1. Status of Tank (Mark all that Apply)					
Currently in Use	( )	( )	( )	( )	( )
Temporarily Out of Use	( )	( )	( )	( )	( )
Permanently Out of Use	(X)	( )	( )	( )	( )
Brought Into Use after 3/15/85	( )	( )	( )	( )	( )
2. Estimated Age (Years)	( )	( )	( )	( )	( )
3. Estimated Total Capacity (Gallons)	( )	( )	( )	( )	( )
4. Material of Construction (Mark all that Apply)					
Steel	( )	( )	( )	( )	( )
Concrete	( )	( )	( )	( )	( )
Fiberglass Reinforced Plastic	( )	( )	( )	( )	( )
Double Wall	( )	( )	( )	( )	( )
Unknown	( )	( )	( )	( )	( )
Other, Please Specify					
5. Internal Protection (Mark all that Apply)					
Interior Lining (e.g. epoxy resins)	( )	( )	( )	( )	( )
None	( )	( )	( )	( )	( )
Unknown	( )	( )	( )	( )	( )
Other, Please Specify					
6. External Protection (Mark all that Apply)					
Cathodic Protection	( )	( )	( )	( )	( )
Coated (e.g. asphaltic/epoxy)	( )	( )	( )	( )	( )
Fiberglass Reinforced Plastic Coated	( )	( )	( )	( )	( )
None	( )	( )	( )	( )	( )
Unknown	( )	( )	( )	( )	( )
Other, Please Specify					
7. Piping (Mark all that Apply)					
Bare Steel	( )	( )	( )	( )	( )
Galvanized Steel	( )	( )	( )	( )	( )
Fiberglass Reinforced Plastic	( )	( )	( )	( )	( )
Cathodically Protected	( )	( )	( )	( )	( )
Coated/Wrapped	( )	( )	( )	( )	( )
Unknown	( )	( )	( )	( )	( )
Other, Please Specify					
8. Substance Currently or Last Stored in Greatest Quantity by Volume (Mark all that Apply)					
a. Petroleum	( )	( )	( )	( )	( )
Diesel	( )	( )	( )	( )	( )
Kerosene	( )	( )	( )	( )	( )
Gasoline (including alcohol blends)	( )	( )	( )	( )	( )
Used Oil	( )	( )	( )	( )	( )
Heating Oil	( )	( )	( )	( )	( )
Other, Please Specify					
b. Hazardous Substance	( )	( )	( )	( )	( )
Please Indicate Name of Principal CERCLA Substance					
or					
Chemical Abstract Service (CAS) No.					
Mark box if tank stores a mixture of substances	( )	( )	( )	( )	( )
c. Unknown	( )	( )	( )	( )	( )
9. Additional information (for tanks permanently taken out of service) (Mark all that Apply)					
a. Estimated date last used (mo/day/yr)	12/92				
b. Estimated quantity of substance remaining (gal.)					
c. Mark box if tank was filled with inert material (e.g. sand, concrete)	( )	( )	( )	( )	( )
d. Mark box if tank was removed	(XX)	( )	( )	( )	( )

REGISTRATION #_____

UNDERGROUND LEAK SUMMARY & TANK CLOSURE

CASE # 94-164 BA2 DATE OPENED 12-1-94 DATE CLOSED 3-28-95

FILE NAME Sears INSPECTOR'S INITIALS GTT

TYPE OF CASE:

A)	PULL	✓	E)	COMPLIANCE CHECK	
B)	INSTALLATION		F)	TANK TEST FAILURE	
C)	SURFACE		G)	ABANDONMENT IN PLACE	
D)	LEAK INVESTIGATION		H)	OTHER	

****

SPILL AFFECTED:

A)	GROUNDWATERS		F)	SANITARY LINE	
B)	DOMESTIC WELLS		G)	UTILITY WORK OR LINES	
C)	SURFACE WATERS		H)	REACHED ADJOIN. PROPERTY	
D)	A BUILDING		I)	NONE/OTHER (SPECIFY)	
E)	STORM DRAIN		J)	SOILS	✓

****

OWNER OF SYSTEM:

A)	MAJOR OIL COMPANY		F)	PRIVATE RESIDENT	
B)	LOCAL OIL COMPANY		G)	APARTMENT	
C)	PRIVATELY OWNER SERVICE STATION		H)	SCHOOL	
			(I)	COMMERCIAL BUSINESS	✓
D)	GOVERNMENT FACILITY		J)	OTHER (SPECIFY)	
E)	MARINA				

****

IF UNDER TYPE OF CASE ITEM B, C, OR E IS CHECKED, DO NOT FILL IN CHART BELOW. OBSERVATION WELLS INSTALLED? YES (NO) # OF WELLS _____

	CAPACITY OF TANK	TANK TYPE	LINE TYPE	AGE	PRODUCT	STATUS OF TANK	LEAK FOUND
1	550	A	A	E	H	B	N
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							

REVIEWED BY TW CODES ON REVERSE SIDE

This page intentionally left blank

Appendix F

Historical Research Documentation

F.1 – Historical Topographic Maps
F.2 – Aerial Photographs
F.3 – Fire Insurance Maps
F.4 – Local Street Directories
F.5 – Property Tax Files

This page intentionally left blank

Appendix F.1

Historical Topographic Maps

Security Square Mall
6901 Security Boulevard
Windsor Mill, MD 21244

Inquiry Number: 8056060.4
July 23, 2025

EDR Historical Topo Map Report

with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topo Map Report

07/23/25

Site Name:

Security Square Mall
6901 Security Boulevard
Windsor Mill, MD 21244
EDR Inquiry # 8056060.4

Client Name:

EA Engineering Science & Tech.
225 Schilling Circle Suite 400
Hunt Valley, MD 21031-0000
Contact: Mitchell Richards

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by EA Engineering Science & Tech. were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:

P.O.# 075411

Project: Security Square Mall Phase I

Coordinates:

Latitude:	39.310654 39° 18' 38" North
Longitude:	-76.750229 -76° 45' 1" West
UTM Zone:	Zone 18 North
UTM X Meters:	349104.87
UTM Y Meters:	4352711.46
Elevation:	458.54' above sea level

Maps Provided:

2019	1944
2016	1943
2014	1908
1982	1904, 1906
1974	1899
1966	1894
1953	1892
1946	1890

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2025 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2019 Source Sheets



Ellicott City
2019
7.5-minute, 24000

Baltimore West
2019
7.5-minute, 24000

2016 Source Sheets



Ellicott City
2016
7.5-minute, 24000

Baltimore West
2016
7.5-minute, 24000

2014 Source Sheets



Ellicott City
2014
7.5-minute, 24000

Baltimore West
2014
7.5-minute, 24000

1982 Source Sheets



Ellicott City
1982
7.5-minute, 24000
Aerial Photo Revised 1982

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1974 Source Sheets

Ellicott City
1974
7.5-minute, 24000
Aerial Photo Revised 1974

Baltimore West
1974
7.5-minute, 24000
Aerial Photo Revised 1974

1966 Source Sheets

Ellicott City
1966
7.5-minute, 24000
Aerial Photo Revised 1966

Baltimore West
1966
7.5-minute, 24000
Aerial Photo Revised 1966

1953 Source Sheets

Baltimore West
1953
7.5-minute, 24000
Aerial Photo Revised 1943

Ellicott City
1953
7.5-minute, 24000
Aerial Photo Revised 1943

1946 Source Sheets

BALTIMORE WEST
1946
7.5-minute, 24000

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1944 Source Sheets

Ellicott City
1944
7.5-minute, 31680

Baltimore West
1944
7.5-minute, 31680
Aerial Photo Revised 1943

1943 Source Sheets

Baltimore
1943
15-minute, 62500
Aerial Photo Revised 1938

1908 Source Sheets



Patapsco
1908
30-minute, 125000

1904, 1906 Source Sheets

Baltimore
1904
15-minute, 62500

Ellicott
1906
15-minute, 62500

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1899 Source Sheets

Baltimore
1899
15-minute, 62500

1894 Source Sheets

Baltimore
1894
15-minute, 62500

Ellicott
1894
15-minute, 62500

1892 Source Sheets

Ellicott
1892
15-minute, 62500

1890 Source Sheets



ELLICOTT
1890
15-minute, 62500

Historical Topo Map

2019



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Ellicott City, 2019, 7.5-minute
E, Baltimore West, 2019, 7.5-minute

SITE NAME: Security Square Mall
ADDRESS: 6901 Security Boulevard
Windsor Mill, MD 21244
CLIENT: EA Engineering Science & Tech.

N

Historical Topo Map

2016



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Ellicott City, 2016, 7.5-minute
E, Baltimore West, 2016, 7.5-minute

SITE NAME: Security Square Mall
ADDRESS: 6901 Security Boulevard
Windsor Mill, MD 21244
CLIENT: EA Engineering Science & Tech.

N

Historical Topo Map

2014



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Ellicott City, 2014, 7.5-minute
E, Baltimore West, 2014, 7.5-minute

SITE NAME: Security Square Mall
ADDRESS: 6901 Security Boulevard
Windsor Mill, MD 21244
CLIENT: EA Engineering Science & Tech.

N

Historical Topo Map

1982



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Ellicott City, 1982, 7.5-minute

SITE NAME: Security Square Mall
ADDRESS: 6901 Security Boulevard
Windsor Mill, MD 21244
CLIENT: EA Engineering Science & Tech.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Ellicott City, 1974, 7.5-minute
E, Baltimore West, 1974, 7.5-minute

SITE NAME: Security Square Mall
ADDRESS: 6901 Security Boulevard
Windsor Mill, MD 21244
CLIENT: EA Engineering Science & Tech.

N

Historical Topo Map

1966



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Ellicott City, 1966, 7.5-minute
E, Baltimore West, 1966, 7.5-minute

SITE NAME: Security Square Mall
ADDRESS: 6901 Security Boulevard
Windsor Mill, MD 21244
CLIENT: EA Engineering Science & Tech.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Ellicott City, 1953, 7.5-minute
E, Baltimore West, 1953, 7.5-minute

SITE NAME: Security Square Mall
ADDRESS: 6901 Security Boulevard
Windsor Mill, MD 21244
CLIENT: EA Engineering Science & Tech.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

E, BALTIMORE WEST, 1946, 7.5-minute

SITE NAME: Security Square Mall
ADDRESS: 6901 Security Boulevard
Windsor Mill, MD 21244
CLIENT: EA Engineering Science & Tech.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Ellicott City, 1944, 7.5-minute
E, Baltimore West, 1944, 7.5-minute

SITE NAME: Security Square Mall
ADDRESS: 6901 Security Boulevard
Windsor Mill, MD 21244
CLIENT: EA Engineering Science & Tech.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

NE, Baltimore, 1943, 15-minute

SITE NAME: Security Square Mall
ADDRESS: 6901 Security Boulevard
Windsor Mill, MD 21244
CLIENT: EA Engineering Science & Tech.

N

Historical Topo Map

1908



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Patapsco, 1908, 30-minute

SITE NAME: Security Square Mall
ADDRESS: 6901 Security Boulevard
Windsor Mill, MD 21244
CLIENT: EA Engineering Science & Tech.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5



TP, Ellicott, 1906, 15-minute
NE, Baltimore, 1904, 15-minute

SITE NAME: Security Square Mall
ADDRESS: 6901 Security Boulevard
Windsor Mill, MD 21244
CLIENT: EA Engineering Science & Tech.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

NE, Baltimore, 1899, 15-minute

SITE NAME: Security Square Mall
ADDRESS: 6901 Security Boulevard
Windsor Mill, MD 21244
CLIENT: EA Engineering Science & Tech.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Ellicott, 1894, 15-minute
NE, Baltimore, 1894, 15-minute

SITE NAME: Security Square Mall
ADDRESS: 6901 Security Boulevard
Windsor Mill, MD 21244
CLIENT: EA Engineering Science & Tech.

N



UNMAPPED

This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Ellicott, 1892, 15-minute

SITE NAME: Security Square Mall
ADDRESS: 6901 Security Boulevard
Windsor Mill, MD 21244
CLIENT: EA Engineering Science & Tech.

N



UNMAPPED

This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, ELLICOTT, 1890, 15-minute

SITE NAME: Security Square Mall
ADDRESS: 6901 Security Boulevard
Windsor Mill, MD 21244
CLIENT: EA Engineering Science & Tech.

N

This page intentionally left blank

Appendix F.2

Aerial Photographs

Security Square Mall

6901 Security Boulevard

Windsor Mill, MD 21244

Inquiry Number: 8056060.8

July 23, 2025

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

07/23/25

Site Name:

Security Square Mall
6901 Security Boulevard
Windsor Mill, MD 21244
EDR Inquiry # 8056060.8

Client Name:

EA Engineering Science & Tech.
225 Schilling Circle Suite 400
Hunt Valley, MD 21031-0000
Contact: Mitchell Richards

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	Scale	Details	Source
2023	1"=500'	Flight Year: 2023	USDA/NAIP
2018	1"=500'	Flight Year: 2018	USDA/NAIP
2015	1"=500'	Flight Year: 2015	USDA/NAIP
2011	1"=500'	Flight Year: 2011	USDA/NAIP
2007	1"=500'	Flight Year: 2007	USDA/NAIP
1994	1"=500'	Flight Year: 1994	USGS/DOQQ
1988	1"=500'	Flight Date: April 10, 1988	NAPP
1982	1"=500'	Flight Date: December 04, 1982	NHAP
1979	1"=500'	Flight Date: June 15, 1979	USDA
1971	1"=500'	Flight Date: October 12, 1971	USDA
1964	1"=500'	Flight Date: May 16, 1964	USGS
1957	1"=500'	Flight Date: September 27, 1957	USDA
1952	1"=500'	Flight Date: August 26, 1952	USDA
1943	1"=500'	Flight Date: April 25, 1943	USDA
1938	1"=500'	Flight Date: May 11, 1938	USDA

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.

Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2025 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

INQUIRY #: 8056060.8

YEAR: 2023

= 500'

N

EDR

INQUIRY #: 8056060.8
YEAR: 2018
= 500'
N
EDR

INQUIRY #: 8056060.8
YEAR: 2015
= 500'
N
EDR

INQUIRY #: 8056060.8

YEAR: 2011

= 500'

N

EDR


INQUIRY #: 8056060.8
YEAR: 2007
= 500'
N
EDR



INQUIRY #: 8056060.8

YEAR: 1994

= 500'

N

EDR

INQUIRY #: 8056060.8
YEAR: 1988
= 500'
N
EDR

INQUIRY #: 8056060.8

YEAR: 1982

= 500'

N

EDR

INQUIRY #: 8056060.8
YEAR: 1979
= 500'
N
EDR

INQUIRY #: 8056060.8

YEAR: 1971

= 500'

N

EDR

INQUIRY #: 8056060.8

YEAR: 1964

= 500'

N

EDR


INQUIRY #: 8056060.8
YEAR: 1957
= 500'
N
EDR



INQUIRY #: 8056060.8

YEAR: 1952

= 500'

N

EDR


INQUIRY #: 8056060.8
YEAR: 1943
= 500'
N
EDR

INQUIRY #: 8056060.8
YEAR: 1938
= 500'
N
EDR

This page intentionally left blank

Appendix F.3

Fire Insurance Maps

Security Square Mall
6901 Security Boulevard
Windsor Mill, MD 21244

Inquiry Number: 8056060.3
July 23, 2025

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

07/23/25

Site Name:

Security Square Mall
6901 Security Boulevard
Windsor Mill, MD 21244
EDR Inquiry # 8056060.3

Client Name:

EA Engineering Science & Tech.
225 Schilling Circle Suite 400
Hunt Valley, MD 21031-0000
Contact: Mitchell Richards

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by EA Engineering Science & Tech. were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 91D8-499C-A49C

PO # 075411

Project Security Square Mall Phase I

UNMAPPED PROPERTY

This report certifies that the complete holdings of the Sanborn Library, LLC collection have been searched based on client supplied target property information, and fire insurance maps covering the target property were not found.

Sanborn® Library search results

Certification #: 91D8-499C-A49C

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

EA Engineering Science & Tech. (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2025 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

This page intentionally left blank

Appendix F.4

Local Street Directories

Security Square Mall
6901 Security Boulevard
Windsor Mill, MD 21244

Inquiry Number: 8056060.5
July 29, 2025

The EDR-City Directory Image Report

EDR® Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Report is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Report includes a search of available business directory data at approximately five year intervals.

RECORD SOURCES

The EDR City Directory Report accesses a variety of business directory sources, including Haines, InfoUSA, Polk, Cole, Bresser, and Stewart. Listings marked as EDR Digital Archive access Cole and InfoUSA records. The various directory sources enhance and complement each other to provide a more thorough and accurate report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer.

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. A check mark indicates where information was identified in the source and provided in this report.

Year	*Target Street*	*Cross Street*	*Source*
2022	☑	☐	EDR Digital Archive
2017	☑	☐	Cole Information
2014	☑	☐	Cole Information
2010	☑	☐	Cole Information
2005	☑	☐	Cole Information
2000	☑	☐	Cole Information
1991	☑	☐	STEWART DIRECTORIES
1986	☑	☐	STEWART DIRECTORIES
1981	☐	☐	STEWART DIRECTORIES
1976	☐	☐	STEWART DIRECTORIES
1971	☐	☐	STEWART DIRECTORIES
1966	☐	☐	STEWART DIRECTORIES
1961	☐	☐	STEWART DIRECTORIES

FINDINGS

TARGET PROPERTY STREET

6901 Security Boulevard
Windsor Mill, MD 21244

Year	*CD Image*	*Source*	

SECURITY BLVD

2022	pg A2	EDR Digital Archive	
2017	pg A9	Cole Information	
2014	pg A14	Cole Information	
2010	pg A18	Cole Information	
2005	pg A22	Cole Information	
2000	pg A26	Cole Information	
1991	pg A27	STEWART DIRECTORIES	
1991	pg A28	STEWART DIRECTORIES	
1986	pg A29	STEWART DIRECTORIES	
1986	pg A30	STEWART DIRECTORIES	
1981	-	STEWART DIRECTORIES	Street not listed in Source
1976	-	STEWART DIRECTORIES	Street not listed in Source
1971	-	STEWART DIRECTORIES	Street not listed in Source
1966	-	STEWART DIRECTORIES	Street not listed in Source
1961	-	STEWART DIRECTORIES	Street not listed in Source

FINDINGS

CROSS STREETS

No Cross Streets Identified

City Directory Images

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

SECURITY BLVD 2022

6901	A KAHN
	A7 APPAREL INC
	ADCOMM DIGITEL
	ALL THINGS BEAUTY
	ALL-STATE CAREER SCHOOL
	ANDITA SSRESESA
	ANDY AND ANJI BROWART 23
	ANTONIO ROSA
	ARVINDDR SINGH
	ASHLEI BROWN
	AT&T STORE
	ATJDECORATIONS INC
	AUNTIE ANNES PRETZELS
	AVE PLUS
	BABU JAYAGOBAL
	BARBER VISION LLC
	BARRY RUBIN
	BASKIN-ROBBINS
	BATH & BODY WORKS
	BAYIT FURNITURE
	BEAUTY LAND
	BURLINGTON STORES
	BYEONG MUN
	CAJUN CAFE
	CASHLAND AT SECURITY MALL
	CAY MONEY SERVICES
	CELL CHOICE LLC
	CHADHA UJEETHAMEED
	CHECKERS DRIVE-IN RESTAURANT
	COLD STONE CREAMERY
	COLLEEN BEAVER
	COLLEEN BEEPER
	CROSBY MICHAEL
	CYNCHIA BRYANT
	DAVID PAIK
	DEANDRA WASHINGTON
	DIMPLE PATEL
	DOLLAR BUYS 112
	ENTERPRISE RENT-A-CAR
	ESTILLO FINE SHOES & ACCESSSORIES
	FEDERAL CLEANING CONTRACTORS
	FENGQIN WANG
	FEROZ PANJWANI
	FINISH LINE
	FINISHING TOUCH
	FORTIS COLLEGE
	FORTIS INSTITUTE
	FRANK JONES
	FRIES, INC
	GAME STOP

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

SECURITY BLVD 2022 (Cont'd)

6901	GENERAL NUTRITION CENTER
	GENX CLOTHING
	GLAZER JEWELERS
	GOLD EMPORIUM INC
	GOLD VALLEY
	GOOD HEALTH CENTER INC
	GREGORY CARPENTER
	HOME FASHION
	HONEY COSMETICS
	HOPE FOR ALL PHARMACY
	HOT STUFF
	HU KIM
	IMAGEPLUS
	INFINITE JEWLERS
	JAE CHOI
	JAMES SHIN
	JAMES SINGS
	JAMIL AYOUCH
	JAY PARKS
	JAYAGOBAL BABU
	JEWELRY HUT
	JIMMY CHANG
	JIMMY JAZZ
	JOHN MEISSNER
	JOSH GORDY
	KAIZEN NAIL BOUTIQUE INC
	KAMRUN HAMID
	KAREN BETHEA
	KAUR SING
	KAY JEWELERS
	KEITH MENU DESIGN
	KIDS GO ROUND
	KIM KHAU
	KOREAN CENTRAL DAILY NEWS
	LAVAR GRANT
	LAVISH LOFT SALON
	LEATHER MAN
	LEE NAILS
	LEE NGUIN
	LILLY KENO
	LOLA ADEBANJO
	LUGGAGE N THINGS
	MACYS
	MARILYN GETER
	MARQUEE BUSINESS PROPERTIES LLC
	MARYLAND SPEEDY TAG & TITLE
	MATT DALY
	MEDIX
	METRO II MUSIC & ELECTRONICS LLC
	MICHAEL CROSBY

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

SECURITY BLVD 2022 (Cont'd)

6901	MICHAEL TIM SMITH
	MICHAELS TAILOR & DRY CLEANING INC
	MICHELLE LABRECQUE
	MIGUEL COLLYMORE
	MIKE ROZETTI
	MIKE TANNER
	MIZANS BRIDAL
	MONA WAHI
	MUHAMMAD SIDDIQUI
	NABIN GAUTAM
	NAIL TRIX & SPA
	NEW GOLDEN NAMES JEWELER
	NEWS STAND
	NITA BATRA
	NOAH KIM
	NORTH AMERICAN TRADE SCHOOL
	NORTH AMERICAN TRADE SCHOOLS
	OCEAN CITY FRIES & DOGS
	OS PLACE RESTAURANT
	PARTY CRAFTS
	PATTI SQUIRES
	PHIL GORDON
	PIERCING PAGODA
	PRETTY WOMAN
	PRIME
	PZ WIRELESS
	RACHELS FINAL
	RAINBOW
	RAINBOW SHOPS
	RAINBOW USA INC
	RAJ KAFLEY
	RAM RAJANI
	REPAIR EXPRESS INC
	RICARDO JOHNSON
	SAB LUST BOUTIQUE
	SAHIN SHAH
	SANTAZ TAYLOR
	SARKA JAPAN
	SEAN TAYLOR
	SEARS
	SEARS AUTO CENTER
	SEARS HEARING AID CENTER
	SEARS HOLDINGS CORP
	SECRET GARDEN JEWELRY & GIFT
	SECURITY BEAUTY
	SECURITY SQUARE MALL
	SET THE CAPTIVES FREE OUTREACH CENTER
	SHAMIN RANA
	SHINGAR INC
	SHOE SHOW MEGA STORE

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

SECURITY BLVD 2022 (Cont'd)

6901	SIGNATURE COLLISION CENTER LLC
	SPECIALIZED HEARING SERVICE
	SPICY CHICKEN FISH
	SPRINT
	SPRINT NEXTEL
	STEPHE NORWOOD
	STORM BOUTIQUE
	SYLVIA AFRICAN HAIR BRAIDING
	T M I BUBBLE TEA WORLD
	T-MOBILE
	TAIWO SAMAIYE
	TEPPANYAKI GRILL & SEAFOOD
	TERRY KROTH
	THE GENX CLOTHING
	THE GREAT COOKIE
	TOKYO SEAFOOD & HIBACHKI GRILL
	TOTAL WIRELESS
	TRACIE SPRIGGS
	TREASURES THE DIAMOND PLACE
	TUAN LE
	TURNING POINT
	TWINS FASHION INTERNATIONAL
	UNIK HAIR
	UNIK STYLE
	UR CITY MEDIA
	WARREN FLEMING
	WIG WAREHOUSE
	WILLIAM RODGERS
	WINDSOR FASHIONS
	WIRELESS 4 YOU
	YAKI HAIR BRAIDING
	YONGIL KIM
6910	SUNG PAIK
6970	BUTLER SHAMAI
	ENTERPRISE LEASING
	FORD SERVICE CENTER
	HARRY SINGH
	KOONS BALTIMORE PARTS
	KOONS FORD INC
	LANE QUICK
	QUICK LANE
	TODD PENDERGRAST
7000	SEALEY
	ADVANCED SOFTWARE SYSTEMS
	ALIGNED DEVELOPMENT STRATEGIES, INCORPORATED
	ALLIED TITLE & TAG SERVICES LLC
	ANTONIO HARRIS
	BECONET
	CAPITOL TAX & FINANCIAL SERVICE
	CHRISTINE DAVIS

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

SECURITY BLVD 2022 (Cont'd)

7000	CLIFTON STERLING
	DOLLIE ANDERSON
	EL SHADDAI HEALTH CARE INC
	ENAYATULLAH ZAFARZAI
	FAMILY & CHILDRENS SERVICES OF CENTRAL MARYLAND
	FARMERS INSURANCE MIRZA ASIF
	GEORGE AP
	GLOBAL SYSTEMS & STRATEGIES
	GSS INC
	GUDA ADITYA
	IRA GREENSTEIN
	JOHN II
	LATONYA BELL-JONES
	LISA MAYS
	LIVEPERSON INC
	LONG & FOSTER REAL ESTATE
	LONG & FOSTER REAL ESTATE INC
	LONG & FOSTER REALTORS
	LONG FOSTER REAL ESTATE INC
	MARK WHITFIELD
	MIDHAT SHAHAB
	MIMAR ARCHITECTS & ENGINEERS INC
	MIMAR ARCHITECTS INC
	MIMAR ARCHITECTS INC MIMARCH
	MIMAR ARCHITECTS, INC. - MIMARCH AKA
	MIMARCH ARCHITECTS
	MIRZA ASIF
	MONUMENT MORTGAGE CO
	MORTGAGE AFFILIATES INC
	MUNIR KHAN
	OCSE
	QSS
	QUALITY SOFTWARE SERVICES INC
	RAVI KAKUMANI
	ROBERT FRYER
	SILVER WELLNESS CENTER
	SOFIYA KHAN
	SPLENDTEK
	STANLEY LEVI
	TOM REED
	TRAVEL INN
	WARREN SILVER
	WORLDWIDE TRAVEL
	YULIYA MAY
7004	ACTIONET INC
	ADRIAN ILAGAN
	AMY AUSHERMAN
	CMS ENERGY
	COLLEEN ISAIAH
	JOHN WIGLE

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

SECURITY BLVD 2022 (Cont'd)

7004	MARYLAND HEALTHCARE CLINICS
	MEDICAL STAFFING NETWORK
	OPTIONS FOR SENIOR AMERICA
	PMP BOWIE
	ROB FOSTER
	SECURITAS SECURITY SERVICES USA
	WELLS FARGO ALARM
7005	A&A BEVERAGES INC
	AMERICAS BEST CONTACTS & EYEGLASSES
	CASEY SARLEY
	CHADWICK LIQUORS
	DIP PATEL
	LEE LUONG
	LOIS RACHUBA
	NAILS TODAY
	WEIS GAS N GO
	WEIS MARKETS
	WINDSOR FASHIONS
7007	MARINER FINANCE
	RITA WRIGHT
7008	ABOUTWEB
	ADESEYE O AWE
	ADESEYE O AWE DDS
	ANDRE ABDUL-RAHEEM
	ANGIE YOUNG
	CHRIS CROUSE
	DEDRIA LAMOTHE
	ELITE HOMECARE SERVICES
	ERIC N LAMB
	GLOBAL COMMERCE & INFORMATION INC
	GLOBAL COMMERCE & INFORMATION, INC.
	JUDY OLSHIN
	KELVIN B SMITH
	KELVIN B SMITH DDS
	KELVIN B. SMITH DENTAL PRACTICE
	KELVIN SMITH
	LAND HOME FINANCIAL SERVICES - BALTIMORE
	LEE A WHITEMAN DDS
	LEE WHITEMAN
	LEIDOS HOLDINGS
	MARCO MARANDA
	MEC HEALTH CARE INC
	MISTY EDWARDS
	PROFESSIONAL GROUP
	RICHARD RUSSELL
	RUCHITA BAGUL
	SCIENCE APPLICATIONS INTERNATIONAL
	SCIENCE APPLICATIONS INTERNATIONAL CORP.
	SEASONS MARYLAND MERGER SUB LLC
	SHEIDA NAKHAEI

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

SECURITY BLVD 2022 (Cont'd)

7008	SMITH K
	STANL SOLDZ
	US SECURITY ASSOCIATE INC
	VISITING NURSE ASSOCIAT
	VNA OF MARYLAND
7091	ASIA DIXON
	BRIAN VOELKER
	CHIPOTLE MEXICAN GRILL
	FEDEX
	FEDEX OFFICE PRINT & SHIP CTR
	FIVE GUYS
	FIVE GUYS BURGERS AND FRIES
	HASSAN HOLLIDAY
	JUAN DELCID
	LAS VEGAS VALLEY WATER DISTRICT
	LEROY TOLES
7100	ALONZO HOWARD
	KIRAN DEWAN
	MELL SIMMONS
	NATIONAL ACCOUNTING SERVICES
	STATE FARM A
	TEXAS AUTO TITLE AND REGISTRATION CONSULTANTS INC
	V K ENTERPRISES INC

Target Street	Cross Street	Source
✓	-	Cole Information

SECURITY BLVD 2017

6901 695 AUTO BODY SHOP
A7
ADCOMMDIGITEL
ALL THINGS BEAUTY
ANDY & ANJI BROWART 23
ASTU HAIR BRAIDING
AT&T
AT&T WIRELESS
AUNTIE ANNES
AVENUE
BANK OF AMERICA ATM
BANTYEFRU BIRHANE
BATH & BODY WORKS
BEAUTY LAND
BLACK & PRETTY LTD
BMORE FIT STUDIO
BOOST MOBILE
BOUNCES PARTY PLACE
BRAIDING HOUSE LLC
BURLINGTON COAT FACTORY
BURTS LOCKSMITH
CAJUN CAFE
CHECKERS DRIVE IN RESTAURANT
CHINAR ENTERPRISES
CINNABON
CLAIRES
CONCEPT
CRICKET AUTHORIZED AGENT
DISNEY FUN & GAMES
DOLLAR BUYS
DOWNTOWN LOCKEROOM
DR BARBER
ELECTRONIC BOUTIQUES INC
ESTILLO
FABULOUS DESIGNS
FARMERS COVE INC
FASHION ACCESSORIES
FOAM CITY
FOOTACTION USA
FORTIS INSTITUTE
GAMESTOP
GEN X
GLAM STUDIOS
GOLD EMPORIUM INC
GRAND AUTO BODY
GURU HARKRISHAN
GURU HARKRISHAN INC DBA TURNING POIN
H & H SHOPPE
HARMONY RIDGE INVESTMENT GROUP
HERTZ CAR RENTAL

Target Street	Cross Street	Source
✓	-	Cole Information

SECURITY BLVD 2017 (Cont'd)

6901	HONEY COSMETICS
	HONEYCOMB HIDEOUT
	J&J PERFUMERY
	JAYAGOBAL BABU
	JEWELRY BOX
	JEWELRY HUT
	JEWELRY REPAIR CENTER
	JIMMY JAZZ
	JOLLY ARTS LLC
	KAIZEN NAIL BOUTIQUE INC
	KAY JEWELERS
	KIDS GO ROUND
	LEATHER MAN
	LEE NAILS
	LOCHEARN GARAGE DOOR
	LOCKSMITH DAY & NIGHT
	M & K MUSIC WAREHOUSE
	MACYS
	MARQUEE BUSINESS PROPERTIES LLC
	MARYLAND SPEEDY TAG & TITLE
	MEDIX
	METRO
	METRO 2
	METROPCS
	MICHAELS TAILOR & DRY CLEANING INC
	MIRACLEEAR
	MIZANS BRIDAL SHOP
	MR BULGOGI
	MR EARLS
	MSU & ASSOCIATES
	MUNS AUTO REPAIR CENTER INC
	MUSIC WAREHOUSE
	NAIL TRIX & SPA
	NEW GOLDEN NAMES JEWELER
	NEWS STAND
	NORTH AMERICAN TRADE SCHOOLS
	OCEAN CITY FRIES & DOGS
	OLD NAVY
	ONE LOVE
	OUT LOOK
	PAYLESS SHOESOURCE
	PERFUME & EMPIRE
	PHOTO MANIA
	PHOTOCOME
	PIERCING PAGODA
	POLACK JOHNNYS SECURITY MALL
	PRETTY WOMAN CLOTHING & ACCESSORIE
	PRIME
	PRIYA ENTERPRISES
	QUIZNOS

Target Street	Cross Street	Source
✓	-	Cole Information

SECURITY BLVD 2017 (Cont'd)

6901 RAINBOW
RAVENS SPORTS WEAR LLC
RUE21
SAADIAS HOUSE OF OIL
SAB LUST BOUTIQUE
SARKA JAPAN
SASHION LA FAMA
SEARS
SEARS HOME IMPROVEMENT
SEARS OPTICAL
SECRET GARDEN JEWELRY & GIFT
SECURITY BEAUTY
SECURITY MALL
SECURITY SQUARE PIZZA LLC
SECURITY SQUARE SHOE REPAIR
SECURITY SQUARE WIRELWSS
SEOUL PLAZA
SEOUL SPA USA
SHINGAR INC
SHOE CITY
SHOE SHOW
SMALLS FORMALWEAR
SOCKS FOR LESS
SPECIALIZED HEARING SERVICES
SPEEDWAY LOCKSMITH
SPRINT
STAR FACES
STORM
SUNGLASS HUT
SUNTRUST
T M I BUBBLETEA WORLD
TELL SHELLS & ACESSORIES
TEPPANYAKI GRILL & SEAFOOD
THE ATHLETES FOOT
THE FINISHING TOUCH
THE GENX CLOTHING
THE GREAT COOKIE
THE HATTER
THE LAVISH LOFT
THE PERFECT GIFT STORE
THE SPORTS ZONE INC
TOKYO SEAFOOD BUFFET
TREASURES
TREASURES THE DIAMOND PLACE
TURNING POINT
TWINS FASHION INTERNATIONAL
UNIK STYLE
URCITY MEDIA
USA BOUTIQUE SECURITY MALL
USA DISCOUNTERS INC

Target Street	Cross Street	Source
✓	-	Cole Information

SECURITY BLVD 2017 (Cont'd)

6901	WIG WAREHOUSE
	WIRELESS 4 YOU
	WIRELESS ACCESSORIES
	YAKI HAIR BRAIDING
	ZALES JEWELERS
6968	AA CHECK CASHING SERVICE
	AA STATE CHECK CASHING
6970	COMMUNITY LOCKSMITH
	KOONS BALTIMORE FORD
6975	BENNIGANS
	WYATT LOCKSMITH
7000	ADVANCED SOFTWARE SYSTEMS
	ALLIED TITLE & TAG SERVICES LLC
	ARCH SYSTEMS
	AVARIS CONCEPTS
	BECO MANAGEMENT INC
	EL SHADDAI HEALTH CARE INC
	EPSTEIN BECKER & GREEN PC
	FAMILY & CHILDRENS SERVICES
	GRACE GAS & TRANSPORT MANAGEMENT CO
	JANUS ASSOCIATES
	M SILVER WARREN DC
	MIMARCH ARCHITECTS
	MONUMENT MORTGAGE CO
	MORTGAGE AFFILIATES INC
	OCSE
	QSS
	RESIDENTIAL LENDING
	SILVER WELLNESS CENTER
	TRIBAL TECH
	WORLDWIDE TRAVEL
7004	DR SHASTINE ABATE MD PA
	MARYLAND HEALTHCARE CLINICS
	MEDICAL STAFFING NETWORK
	PREMIER CERTIFIED HOME HEALTH
	SECURITAS SECURITY SERVICES USA
	WELLS FARGO ALARM
7005	AMERICAS BEST CONTACTS & EYEGLASSES
	CARE CLEANERS
	CATHERINES
	CHADWICK LIQUORS
	KIMCO REALTY
	NAILS TODAY
	WEIS GAS N GO
	WEIS MARKETS
7007	1ST MARINER BANK
7008	ABOUTWEB LLC
	AMERICAN BAPTIST CHURCHES
	HOME HEALTH OF ILLINOIS
	NETWORK HEALTH SERVICES

Target Street	Cross Street	Source
✓	-	Cole Information

SECURITY BLVD 2017 (Cont'd)

7008	PROGRESSIVE HORIZONS INC
	PROPERTY TITLE & ESCROW
	SEASONS HOSPICE
	SMITH KELVIN B DDS
	VNA
	WALGREENS
7091	CHIPOTLE MEXICAN GRILL
	FIVE GUYS BURGERS & FRIES
	LAS VEGAS RESTAURANT
7100	7100 SECURITY BLVD
	RENEWED MIND WORSHIP CENTER
	STATE FARM INSURANCE

Target Street	Cross Street	Source
✓	-	Cole Information

SECURITY BLVD 2014

6901	695 AUTO BODY
	A & D BUFFALO
	ACCELERATED TINT & PARTS
	ASHLEY STEWART
	AT&T WIRELESS
	ATHLETHES FOOT
	AUNTIE ANNES
	AVENUE
	BATH & BODY WORKS
	BEAUTY LAND
	BLACK & PRETTY LTD
	BMORE FIT STUDIO
	BOARDWALK FRIES
	BOGUE BOUTIQUE
	BRAIDING HOUSE LLC
	BURLINGTON STORES
	CAJUN CAFE
	CHECKERS DRIVE IN RESTAURANT
	CHINAR ENTERPRISES
	CINNABON
	CLAIRES
	DBA D
	DOLLAR BUYS
	ELECTRONIC BOUTIQUES INC
	ESTILLO FINE SHOES
	FAB LUST BOUTIQUE LLC
	FEDERAL CLEANING CONTRACTORS
	FINISH LINE
	FOOTACTION USA
	GAMESTOP
	GLAM STUDIOS
	GLAZER JEWELERS
	GNC
	GOLD VALLEY
	GURU HARKRISHAN
	GURU HARKRISHAN INC DBA TURNING POIN
	H & H SHOPPE
	HARMONY RIDGE INVESTMENT GROUP
	HONEY COSMETICS
	HONEYCOMB HIDEOUT
	J&J PERFUMERY
	JEWELRY BOX
	JEWELRY HUT
	JEWELRY REPAIR CENTER
	JIMMY JAZZ
	JOLLY ARTS
	KAIZEN NAIL BOUTIQUE INC
	KANTIPUR LLC
	KAY JEWELERS
	KIDS GO ROUND

Target Street	Cross Street	Source
✓	-	Cole Information

SECURITY BLVD 2014 (Cont'd)

6901 LAL QILA
LEATHER MAN
LEE NAILS
LOCHEARN GARAGE DOOR
LOCKSMITH DAY & NIGHT
MACYS
MARQUEE BUSINESS PROPERTIES LLC
MARYLAND SPEEDY TAG & TITLE
MEDIX
MEDIX SCHOOL WEST
MENS WEARHOUSE
METRO 2
METROPCS
MICHAELS TAILOR & DRY CLEANING INC
MIZANS BRIDAL
MONEY BOX INC
MUNS AUTO REPAIR CENTER INC
MUSIC WAREHOUSE
MY WIRELESS
NAIL TRIX & SPA
NEWS STAND
NORTH AMERICAN TRADES SCHOOL
OCEAN CITY FRIES & DOGS
OLD NAVY
ONE LOVE
OS PLACE RESTURANT
OUT LOOK
PAYLESS SHOESOURCE
PHOTO COME
PHOTO MANIA
PIERCING PAGODA
PRATIK PATEL
PRETTY WOMAN CLOTHING & ACCESSORIE
PRIME
PRIYA ENTERPRISES
QUIZNOS
RADIOSHACK
RAG CELL
RAINBOW
RAVENS SPORTS WEAR LLC
RAWAL PRAGNESH
REPAIR EXPRESS INC
ROYAL BEAUTY SALON
SAADIAS HOUSE OF OILS
SAB LUST BOUTIQUE
SARKA JAPAN
SARKU JAPAN
SASHION LA FAMA
SEARS
SEARS OPTICAL

Target Street	Cross Street	Source
✓	-	Cole Information

SECURITY BLVD 2014 (Cont'd)

6901	SECRET GARDEN JEWELRY & GIFT
	SECURITY BEAUTY
	SECURITY SQUARE MALL
	SECURITY SQUARE PIZZA LLC
	SECURITY SQUARE SHOE REPAIR
	SEOUL SPA USA
	SHINGAR INC
	SHOBAN
	SHOE CITY
	SHOE SHOW MEGA STORE
	SMALLS FORMALWEAR
	SPECIALIZED HEARING SERVICES
	SPEEDWAY LOCKSMITH
	STORM
	SUNTRUST
	SUPER KIDS UNIFORMS
	TELL SHELLS & ACESSORIES
	TEPPANYAKI GRILL & SEAFOOD
	THE FINISHING TOUCH
	THE GREAT COOKIE
	THE HATTER
	THE HOOK UP
	THE LAST PAIR
	THE SPORTS ZONE INC
	TMOBILE BALTIMORE
	TOKYO
	TOKYO SEAFOOD BUFFET
	TREASURES
	TREASURES THE DIAMOND PLACE
	UFO
	UNIK STYLE
	UR CITY MEDIA
	USA DISCOUNTERS INC
	VZW AT RADIO SHACK 2905 BALTIMORE
	WENDIS CANDIES
	WIG WAREHOUSE
	WIRELESS ACCESSORIES
	WIRELESS JUNGLE
	YANG XUEHI
	ZALES JEWELERS
	ZERO GRAVITY LLC
6968	AA CHECK CASHING SERVICE
	AA STATE CHECK CASHING
6970	KOONS BALTIMORE FORD
6975	BENNIGANS
	WYATT LOCKSMITH
7000	ALIGNED DEVELOPMENT STRATEGIES INC
	ALLIED TITLE & TAG SERVICES LLC
	ARCH SYSTEMS
	AVARIS CONCEPTS

Target Street	Cross Street	Source
✓	-	Cole Information

SECURITY BLVD 2014 (Cont'd)

7000	BECO MANAGEMENT INC
	CERTEGY
	CHITECTS INC MIMAR AR
	EL SHADDAI HEALTH CARE INC
	FAMILY & CHILDRENS SERVICES OF CENT
	GRACE GAS & TRANSPORT MANAGEMENT CO
	JANUS ASSOCIATES
	MIMARCH ARCHITECTS
	MORTGAGE AFFILIATES INC
	OCSE
	QSS
	RENSIN, JOSEPH
	RESIDENTIAL LENDING
	SILVER WARREN M DC
	SILVER WELLNESS CENTER
	TRIBAL TECH
	WORLDWIDE TRAVEL
7004	ABATE SHASTINE MDPA
	ACTIONET INC
	MARYLAND HEALTHCARE CLINIC
	PREMIER CERTIFIED HOME HEALTH
	WELLS FARGO ALARM
7005	AMERICAS BEST CONTACTS & EYEGLASSES
	CARE CLEANERS
	CATHERINES
	CHADWICK LIQUORS
	KIMCO REALTY
	NAILS TODAY
	WEIS MARKETS
7007	1ST MARINER BANK
7008	ABOUTWEB LLC
	HOME HEALTH OF ILLINOIS
	PROGRESSIVE HORIZONS INC
	SAIC
	SEASONS HOSPICE
	VNA
	WALGREENS NETWORK HEALTH SERVICES
7091	CHIPOTLE MEXICAN GRILL
	FIVE GUYS BURGERS & FRIES
	LAS VEGAS RESTAURANT
7100	STATE FARM INSURANCE

Target Street	Cross Street	Source
✓	-	Cole Information

SECURITY BLVD 2010

6900	DCM
6901	ACCELERATOR
	ASHLEY STEWART
	AT&T STORE
	ATC ELECTRONICS INC
	ATHLETHES FOOT
	AUNTIE ANNES PRETZELS
	AVENUE
	BASKINROBBINS
	BATH & BODY WORKS
	BEAUTY LAND
	BOARD WALK FRIES
	BRAIDING HOUSE LLC
	BURLINGTON COAT FACTORY
	CACTUS WILLIES
	CAJUN CAFE
	CARMELS FASHIONS
	CENTRAL SOLUTIOSN INC
	CHECKERS DRIVEIN RESTAURANT
	CHEZ LEES SALON
	CITY STYLES
	CLAIRES
	COTTON CANDY INC
	DISNEY FUN & GAMES
	DOLLAR BUYS
	DOWNTOWN LOCKEROOM
	ESTILLO FINE SHOES & ACCES
	EXPRESSIONS NA JEWELERS
	EYEBROW THREADING STATION
	FASHION AVENUE
	FEDERAL CLEANING CONTRACTORS
	FINISH LINE
	FINISHING TOUCH
	FIT FOR LIFE PERSONAL TRAINING
	FOOT LOCKER
	FOOTACTION USA
	G & G RETAIL INC
	GAMESTOP
	GLAZER JEWELERS
	GNC
	GOLD VALLEY
	GRAND AUTO BODY
	GREAT COOKIE
	GURU HARKRISHAN
	H & H SHOPPE
	HOLLAND PROPERTIES
	HONEY BISCUITS INC
	HONEY COSMETICS
	HONEYCOMB HIDE OUT
	HOOK UP

Target Street	Cross Street	Source
✓	-	Cole Information

SECURITY BLVD 2010 (Cont'd)

6901 HYATT & CO
J & J PERFUMERY INC
JEWELRY BOX
JEWELRY HUT
KAY JEWELERS
KIAZEN NAIL BOUTIQUE INC
KIDS GO ROUND
KRE8ING YOUR IDEAS
LADY FOOT LOCKER
LAST STOP CO
LEATHER MAN
LEE NAILS
LEES USA BILLIARD & CAFE
LORENES HAIR CARE
LUGGAGE N THINGS
MACYS
MARKET FRIED CHICKEN
MARYLAND CRAB CAKE CO
MBI
MEDIX SCHOOL WEST
MENS WEARHOUSE
MICHAELS TAILOR & DRY CLEANING
MODERN IMAGE INC
MUSIC WAREHOUSE
NAIL TRIX & SPA
NAOMI WIGS
NEWS STAND
NORTH AMERICAN TRADE SCHOOLS
OBESSION HAIR & WEAVE
OCEAN CITY FRIES & DOGS
OLD NAVY
PAYLESS SHOE SOURCE
PENER MENS WEAR INC
PENN OPTICAL CO LTD
PHOTOCOM
PICTURE GRAPHICS
PIERCING PAGODA
POLACK JOHNNYS SECURITY MALL
PRETTY WOMAN
PRIME JEWELERS
QUIZNOS
RADIO SHACK
RAINBOW
RED SHED INC
REPAIR EXPRESS INC
ROOTS HAIR BRAIDING
RYAN SKAI COSMETICS LLC
SARKA JAPAN
SASSY BEAUTY SALON
SEARS

Target Street	Cross Street	Source
✓	-	Cole Information

SECURITY BLVD 2010 (Cont'd)

6901	SEARS AUTO CTR
	SEARS HEARING AID CTR
	SEARS OPTICAL
	SECRET GARDEN JEWELRY & GIFTS
	SECURITY SQUARE MALL
	SECURITY SQUARE PIZZA LLC
	SECURITY SQUARE SHOE REPAIR
	SECURITY STEAK & FRIES
	SELL CRAZE
	SEOUL PLAZA
	SHAHEEN RESTAURANT INDIAN FOOD
	SHINGAR INC
	SHOBAN
	SHOE CITY
	SOFTWARE ETC
	SPECIALIZED HEARING SVC
	SPORTS ZONE INC
	SUPER KIDS
	SUPERKIDS UNIFORMS
	THINGS REMEMBERED
	TOUGH AUTHENTIC
	TREASURES
	URBAN KNOWLEDGE BOOKSTORE
	US POST OFFICE
	USA BOUTIQUE
	USA DISCOUNTERS INC
	VALUE FASHION
	VISIONS INC
	VIVANCE BRIDAL GOWNS
	WENDIS CANDIES
	WHY NOT BOUTIQUE
	WIRELESS 4 YOU
	WIRELESS JUNGLE
	X ROADS
	ZALES THE DIAMOND STORE
6950	KOONS FORD INC
6968	A A STATE INCOME TAX SVC
6970	KOONS FORD
7000	ALLIED TITLE & TAG SVC LLC
	B H FUNDING
	BECO MANAGEMENT INC
	BLUE HIPPO FUNDING LLC
	BLUEHIPPO FUNDING LLC
	BUCKANEER COMPUTER SYST & SVC
	EDISON WORLDWIDE LLC
	EL SHADDAI HEALTH CARE INC
	ELMAR ASSOCIATES
	FAMILY & CHILDRENS SVC
	FAMILY ND CHILD SVC CNTL MD
	GRACE GAS & TRANSPORT MGMT CO

Target Street	Cross Street	Source
✓	-	Cole Information

SECURITY BLVD 2010 (Cont'd)

7000	JANUS ASSOCIATE
	LONG & FOSTER REALTORS
	MIMARCH ARCHITECTS
	MONUMENT MORTGAGE
	NOP PUB OLS CREDITRUST
	OCSE
	PRO LOGIC INC
	QSS
	RESIDENTIAL LENDING
	SILVER WELLNESS CTR
	TRAVEL INN
	WORLD WIDE TRAVEL
7004	ABATE, SHASTINE
	ACTIONET INC
	EMMA FARRIE MINISTRIES
	OPTIONS CORP
	SECURITAS SECURITY SVC USA INC
	SHASTINE ABATE PA
	WELLS FARGO ALARM
7005	AMERICAS BEST CONTACTS
	CARE CLEANERS
	CATHERINES
	CHADWICK DISCOUNT
	CHADWICK LIQUORS
	M&T BANK
	MID ATLANTIC REALTY TRUST
	NAILS TODAY
	SUPER FRESH
	SUPER FRESH PHARMACY
7007	FIRST MARINER BANK
7008	ABOUT WEB LLC
	MEC HEALTH CARE INC
	MEDPROTECT LLC
	NETWORK HEALTH SVC
	RAY, BARRY M
	SMITH KELVIN B DDS
	VNA OF MARYLAND
7091	FEDEX OFFICE
	FIVE GUYS BURGERS & FRIES
	LAS VEGAS RESTAURANT
7100	ACCOUNTING & FINANCIAL MGMT
	ALONZO HOWARD INSURANCE
	FIRST COMMONWEALTH FUNDING
	NATIONAL STAFFING INC
	RENEWED MIND WORSHIP CTR
	TONNESSEN DAVID W

Target Street	Cross Street	Source
✓	-	Cole Information

SECURITY BLVD 2005

6901	A MUSK FLOWER CORP
	AFRICAN AMERICAN ART & MORE
	ATHLETES FOOT
	AUNTY ANNES
	AVENUE PLUS
	B DALTON BOOKSELLER
	BATH & BODY WORKS
	BFS RTAIL COMMERCIAL OPRTONS
	BGE HOME PRODUCTS ND SERVICES INC
	BMS INC
	BURLINGTON COAT FACTORY
	C & J CLARK RETAIL
	CARD CAGE
	CHEF CHAN
	CINGULAR WIRELESS
	CLAIRES BOUTIQUE
	COLE VISION
	COLUMBIA FURNITURE
	CONSUMER PROGRAMS
	DOLLAR BUYS
	EBONY NETWORK
	ECONOMY SHOES
	ESTILLO FINE SHOES AND ACCESSORIES
	FASHION AVENUE
	FINISH LINE CORP
	FIRESTONE MASTER CARE CAR SERVICE
	FOOT LOCKER
	FOR YOUR ENTERTAINMENT
	FRAGRANCE WORLD
	GLAZER JEWELERS
	GNC
	GOLD VALLEY
	GRAND MART
	GREAT COOKIE LTD
	HANDBAG HEAVEN
	HATTERS
	HECHTS
	HONSOO PLAZA
	HYATT AND CO
	JASON SHOES
	JC PENNEY CORP INC
	JEWELRY BOX
	KB TOYS
	KEEPING YOU IN STITCHES
	KINGDOM BOOKS & MORE
	LA BOULANGERIE BAKERY
	LEATHER MAN
	LEE NAILS
	LITTMAN JEWELERS
	LUVYAHCOM

Target Street	Cross Street	Source
✓	-	Cole Information

SECURITY BLVD 2005 (Cont'd)

6901	LUXURY BOUTIQUE
	MARYLAND KOREAN CRAFT FRNTR
	MARYLAND KOREAN CRAFT FURNITURE
	MDR INC
	METRO II
	MICHAELS TAILOR & DRY CLEANING
	MIRACLE EAR
	MISS PHO
	MISS PHO INC
	MMT FOODS INC
	MUSK FLOWER SHOP
	NAIL BAR
	NORTH AMERICAN TRADE SCHOOL
	OASIS OF ARTISTRY
	OLD NAVY
	OLIN FASHION
	PAYLESS SHOESOURCE INC
	PHOTO CO
	PHOTO MANIA
	PIERCING PAGODA
	PRETTY WOMAN
	PRIME JEWELERS
	QUIZNOS SUB
	RADIOSHACK CORP
	RAINBOW
	RAINBOW APPAREL
	RAVE
	RECORD TOWN INC
	REPAIR EXPRESS INC
	RITZ CAMERA CENTERS
	ROYAL BEAUTY SALON
	SASSY BEAUTY SALON
	SEARS
	SEARS OPTICAL
	SEARS ROEBUCK AND CO
	SECURITY SQUARE MALL
	SECURITY STEAK AND FRIES
	SHADES OF BEAUTY
	SHINGAR
	SHOE DEPOT INC
	SIN KYU B
	SOFTWARE ETC
	STERLING JEWELERS INC
	SUNCOAST MOTION PICTURE CO
	SUPER KIDS SECURITY MALL
	SUPERKIDS INC
	TACO MAKER
	THE DIESEL INSTITUTE OF AMERICA
	THINGS REMEMBERED
	TOE TOE SHOE

Target Street	Cross Street	Source
✓	-	Cole Information

SECURITY BLVD 2005 (Cont'd)

6901	UNIFORMS FOR LESS II
	USA BOUTIQUE
	VITTORIOS OF SECURITY INC
	WELCOME ENTERPRISES INC
	WENDIS CANDIES
	WIRELESS 4 U
	WOODS TAMMI
	YANG BOKSUN
	YOUNG S BRIDAL SHOP
	YOUNGS BRIDAL SHOP
	YUKI JAPANESE RESTAURANT
	ZALES JEWELERS INC
6968	STATE CHECK CASHING
6970	ENTERPRISE LEASING
	KOONS
	KOONS FORD OF BALTIMORE INC
6973	IHOP
	INTERNATIONAL HOUSE OF PANCAKES
6975	S A RESTAURANT
7000	BALTIMORE CENTRAL MD NEW HOME DIRECT
	BECO MANAGEMENT
	BLUEHIPPO FUNDING LLC
	GLOBAL SYSTEMS & STRATEGIES
	GRACE GAS & TRANSPORT MANAGEMENT CO
	HANDS OF MERCY INC
	HOT PHRASE
	L C INSURANCE
	LC INSURANCE GROUP LLC
	LONG & FOSTER REALTORS
	MIMAR ARCHITECTS INC
	N C O GROUP
	NCO PORTFOLIO MANAGEMENT INC
	RESIDENTIAL LENDING
	Z TECH CORP
7004	ALLIED FINANCIAL SERVICES INC
	AMERICAN GENERAL FINANCIAL SERVICES
	BORG WARNER SECURITY
	BORG, WARNER
	BURNS PINKERTON
	MOAMEDIA
	OPTIONS FOR SENIOR AMERICA
	PARK & ASSOCIATES ATTYS AT LAW
	PINKERTON SECURITY
	SECURITAS
7005	AMERICAS BEST CONTRACTORS & EYEGLASS
	CATHERINES PLUS SIZES
	CHADWICK LIQUORS
	CHDWCK DUSCOUNT
	SUPER FRESH
	SUPER FRESH PHARMACY # 807

Target Street	Cross Street	Source
✓	-	Cole Information

SECURITY BLVD 2005 (Cont'd)

7007	FIRST MARINER BANK
7008	GARCIA IVAN H
	OMNI EYE SPECIALISTS
	RYAN HOMES INC
	SEASONS HOSPICE
	SEASONS VNA HOSPICE INC
	SMITH K DDS
	VISITING NURSES ASSOCIATION OF MD
7100	AAA FAST KASH INC
	ALL AMERICAN DRIVING ACADEMY
	ALONZO HOWARD INSURANCE
	COLDWELL BANKER GREMPLR RLT
	KASH 2 U LEASING

Target Street	Cross Street	Source
✓	-	Cole Information

SECURITY BLVD 2000

6901	AMERICAN TIRE & SERVICE CO
	AVENUE PLUS
	BALLOON CONNECTION
	BELLE MELTON P DDS
	CHAMPS SPORTS
	DENTAL CARE CENTER IN MONTGOMERY WARD
	DOLLAR STORE
	EBTS
	ELEGANT LADY
	FIRESTONE TIRE & SERVICE CENTERS
	GLAZER JEWELERS
	HAIR CUTTERY
	HECHTS
	JCPENNEY COMPANY INCORPORATED
	KEEPING YOU IN STITCHES
	LUGGAGE N THINGS
	MINI PHOTO CRAFT
	MIRACLE EAR
	NATURALIZER SHOES
	NATURE FOOD CENTRES
	NORTH STAR BOOK STORE
	PORTRAIT WORLD
	SAM GOODY
	SCENTS FOR THE SOUL
	SECURITY STEAK AND FRIES
	SHADES OF BEAUTY 2
	SUNCOAST MOTION PICTURE COMPANY
	SUPER KIDS SECURITY MALL
	WALDIN JEWELERS
	YEAR 2000 & POKEMON COLLECTIBLES
6968	AA STATE CHECK CASHING & INCOME TAX SERVICE
	AA STATE INCOME TAX & CHECK CASHING SERVICE
	AA STATE INCOME TAX SERVICE
6970	KOONS FORD OF BALTIMORE INCORPORATED
6973	INTERNATIONAL HOUSE OF PANCAKES
6975	BENNIGANS
7000	EL SHADDAI HEALTH CARE INCORPORATED
	MONUMENT MORTGAGE CORPORATION
	TECH AID
	UNITED STATES SERVICE INDUSTRIES INCORPORATED
7005	HECHINGER
7008	BAY AREA HEALTH CARE
	CITY FEDERAL FUNDING & MORTGAGE CORPORATION
	PSI HYPNOTHERAPY CLINIC
	SMITH KELVIN B DDS
	WONG RANDALL V MD
7100	HOWARD ALONZO INSURANCE
	STATE FARM INSURANCE COMPANIES AGENTS

Target Street	Cross Street	Source
✔	-	STEWART DIRECTORIES

SECURITY BLVD 1991



SECURITY BLVD 21207 Contd
6600-44 SECURITY SHOPPING CNTR Contd

#Rite Aid Discount Pharmacies store 265-7758 83
6628 #A J Stationery 281-2504 90
6630 #Mattress Discounters ..... +944-7311 91
6633 #Chevrolet Authorized Sales & Service 265-7777 83
#Fox Chevrolet Geo The .... +621-5479 91
#Fox Chevrolet Inc 265-7777 81
#Goldberg Chas S Iwyr 298-2422 86
6634 #78 Sneaker Store ..... +944-7800 91
6636 #Plus Sizes 298-0133 90
6638 #Postal USA Inc 944-1500 90
6642 #Festival Eatery Carry Outs 944-4704 79
#The Country's Best Yogurt ..... +944-1400 91
6644 #Bell W & Co 944-2500 77
6656 #Show-Off 298-1781 83

6660 THE PROFESSIONAL BUILDING
#Allstate Courier Of Baltimore 281-2100 87
#Choice TV Rental Inc ..... +298-1770 91
#Cohen Eric Dr optometrist 944-8020 78
Harris John E 265-5551 86
#Lockhart Larry L Iwyr ..... 944-4474 --
#Minuteman Press 265-8555 85
Roth John G Dr 265-5300 87
#Support Solutions Inc ..... +944-3369 91
#Turney Peter B Iwyr ..... 944-4460 --
#Western Southern Life Ins Co West Ofc 944-8787 88
6665 #Multi Graphics Technology Center ..... +944-0076 91
6665 #AM Multigraphics 281-9200 84
6665 #Fox Automotive Telemarketing 281-2191 89

6666 FOUR SIXES BUILDING
#A Diamond Dental & Orthodonic Ofc 944-6666 84
#Blue Cross & Blue Shield Association In Chicago 298-6878 84
#Buettner & Cooper PA 298-5100 90
#Buettner Robt W atty 298-5100 79
#Cohen Flax Mgt Inc 944-8900 90
#Cohen Flax Mgt Inc 944-8900 90
#Coleman Michael S physcl therpst 298-5400 82
#Cooper William S 298-5100 84
#Diamond Dental & Orthodontic Offices 944-6666 89
#Diamond Olwyn orthodontist ..... +298-4880 91
#Executive Tax Service 265-1046 89
#Lubarsky Efim dental laboratory 944-3307 85
#Luskin's Inc 265-6400 86
Portney David N 298-5100 90
#Qureshi Bilal MD 298-4200 86
#Security Medical Walk-In Clinic 298-4200 81
#Varma Osha MD 298-4200 86
#Walden E C Jr MD 298-4200 84
6667 #Roy Rogers Family Restaurant 944-4262 90
6667 #Roy Rogers Family Restaurant Woodlawn ... 298-3116 83
6669 #Cleaners Plus 597-9580 86
6669 #Dark Room The 944-9120 86
6669 #Fairfax Savings FSB 265-1140 85
6669 #Fox Comnctns Corp ..... □298-1166 91
6669 #LaBorwit L E Dr optm 944-5000 86
6669 #Optical Enterprises 944-5000 86
6669 #Parnes Group Inc ..... □265-6555 91
6669 Simmons W A ..... □265-1355 91
6669 #Spirit Rent-A-Car ..... +265-1500 91
6669 #Spirit Rent-A-Car ..... +992-6967 91
6669 #Technomart Research Growth Assocs ..... □265-6555 91
6698 #Security Amoco 944-9191 77
6700 #Day's Inn 281-1800 88
6700 #Pargo's Spirited Foods 944-4020 86

Beltway

-- #Best Western Welcome Inn ..... +944-7400 91

6901 SECURITY SQUARE MALL
#AS Beck Shoe Store 298-3292 85
#AT&T Company Local Offices Phone Center 298-4855 90
#Admiral Auto Ins Agcy 265-7500 91
#Afterthoughts 298-7511 87
#American Eagle Outfitters 298-6446 79
#Anderson Little 281-9898 90
#Annapolis Clothing Co 944-7362 86
#Athlete's Foot The 265-1031 91
#Attractions 944-4152 87
#Au Coton 298-7559 88
#B Dalton Bookseller Baltimore 944-7733 86
#Baltimore Gas & Elec Appliances Sales 265-1000 90
#Bananas-South Philly Steaks & Fries 298-5000 90
#Bendix Uniforms Inc 944-6644 78
#Benetton Italy 298-4697 89
#Berman's 298-2415 89

SECURITY BLVD 21207 Contd
6901 SECURITY SQUARE MALL Contd

#Big Al's 298-0094 89
#Block H & R 265-1040 90
#Bob's Big Boy Family Restaurant Woodlawn ... 944-0040 90
#Budget Rent A Car Suburban Office Woodlawn 597-9200 87
#Budget Rent A Truck Suburban Office Woodlawn 597-9200 87
#Bull On The Beach ..... +265-6223 91
#Burger King Restrnt 944-3909 88
#Burger King Restrnt 298-6078 91
#Camera Shop Inc The 944-7616 84
#Card Cage ..... 944-7550 --
Caren Charles 944-5855 86
#Cargo Furniture 944-0344 86
#Casual Corner 944-2900 87
#Chandler's Shoe Str 281-1475 78
#Chess King 944-9526 84
#Chez-Chocolat 298-8442 89
#Chick N Fry ..... +265-1111 91
#Children's Place The 265-1166 83
#Corn Dog On A Stick 281-0001 89
#DOC Eyeworld 944-0088 90
#Dahne Edward G DDS 944-2166 91
#Dahne Marlene Z DDS 944-2166 91
#Docktor Pet Center 265-7100 78
#Early Learning Centre 298-4766 89
#Eduardo's Ice Cream 298-2393 91
#Electronics Boutique 298-9674 87
#Fashion Bug 944-0500 83
#Firestone MasterCare Svc Ctr Baltimore 265-6666 84
#Florsheim Shoe Shops 944-4964 78
#Foot Action USA District Office ..... +944-3013 91
#Foot Locker 944-5211 84
#Forever Beautiful 944-2636 90
#Friendly Ice Cream Shop 265-8566 84
#Fun-N-Games 265-5546 78
#Games'N'Gadgets 298-9674 87
#Gap The 944-7040 84
#General Nutrition Ctr 281-2055 89
#Gordon's Jewelers 265-6005 78
#Great Cookie 298-0370 80
#Hair Cuttery The Woodlawn 944-9767 85
#Hallmark Ultimate Expressions 265-8156 90
#Hanover Shoe Store 944-7622 78
#Happy Pals 944-2647 91
#Harper's 281-0047 90
#Hecht's Stores Security Mall 944-8040 81
#Hecht's Stores Marley Station Beauty Salon 944-0892 81
#Herald Square 265-8812 88
#Hess Shoes Store Men's 281-9749 89
#Hess Shoes Store Women's 281-9748 89
#Hess Shoes Store Stride Rite Chldrn's 281-0048 89
#His Place 281-9398 84
#Household Bank FSB Baltimore ..... +944-8282 91
#Hyatt & Co 944-1216 89
#J C Penney Co Inc 298-8100 78
#J C Penney Co Inc Security Sq Mall Catalog Tel Shopping Inquire About Order 298-8500 79
#Jean's West 944-9730 88
#Jeans West Shop 944-4212 86
#Jewelry Repair Ctr 281-9932 90
#K & K Toys 944-5536 78
#Kathrine's ..... +944-4388 91
#Kay Jewelers 265-6557 78
#Keepsake Corner Melart Jewelers 265-8300 91
#Kernels World 944-2999 90
#Kinderfoto Portrait Studio 265-7039 78
#Lady Foot Locker 281-2564 89
#Lechter's 298-7073 83
#Limited The 265-5832 80
#MT Jewerly Rpr Svc 944-8354 91
#Marianne 597-8325 78
#Marianne Plus 265-5960 88
#Marvin's Sport City 944-8343 78
#Maryland Natl Bank Br Ofc Southwest Security Square 265-5333 83
#Melart Jewelers Keepsake Corner 265-8300 78
#Montgomery Wards ..... +597-8135 91
#Montgomery Wards ..... +597-8423 91
#Mr Bulkey's 944-6722 90
#Naturalizer Shoes ..... +265-5522 91
#News Center 298-7048 89
#Oak Tree 298-2944 78
#Ocean City Fries & Dogs 944-9393 84
#Opinion Centers 597-9904 90
#Oriental Cafe 281-7716 89
#Ormond Shop Inc 944-8810 78
#Parklane Hosiery 298-9884 89
#Party Shop 265-8156 90
#Paul D P Jewelers 944-8323 81

SECURITY BLVD 21207 Contd
6901 SECURITY SQUARE MALL Contd

#Paul Harris Stores 298-8310 90
#Payless Shoesource 944-0502 90
#Penney J C Optical Department 298-2926 90
#Penney J C Co Inc Dept Stores Security Sq Mall Custom Decorating 298-8100 90
#Penney J C Dept Str Security Square Mall Styling Salon 265-5192 83
#Picture Show 298-5876 89
#Piercing Pagoda 298-9630 84
#Radio Shack-A Div Of Tandy Corp Consumer Electronics Store Baltimore 265-8144 83
#Reach For The Beach 298-2080 89
#Regal Shoe Shop ..... 265-7741 --
#Regis Hair Stylists 944-4116 84
#Rite Aid Discount Centers 298-2793 91
#Sam Goody 944-8797 85
#Sam Louie 265-6332 91
#Sbarro Restaurant 281-2996 89
#Scribbles 298-9782 89
#Topkapie 281-1791 90

SEARS ROEBUCK & CO
#Auto Batteries & Accessories 281-2228 85
#Automotive Parts 281-2292 85
#Automotive Svc Desk 281-2291 85
#Bedding & Bath Shop 281-2296 85
#Building Materials 281-2264 86
#Carpet & Floor Tiles 281-2237 85
#Catalog To Check On An Order 281-2212 83
#Central Air Condtng 281-2231 89
#Children & Youth Apparel Boys 281-2229 85
#Children & Youth Apparel Girls 281-2229 85
#Children & Youth Apparel Infants 281-2229 85
#Custom Decorator 281-2225 85
#Customer Service 281-2276 85
#Dishwashers 281-2226 85
#Draperies 281-2224 85
#Electrl & Lighting 281-2209 85
#Fencing 281-2231 90
#Financial Network Centers Allstate Insurance Cos 944-5846 85
#Freezers 281-2246 85
#Furniture 281-2201 85
#Hardware 281-2209 85
#Hearing Aids Dept 281-2281 88
#Housewares 281-2211 85
#Information 281-2255 85
#Installed Home Improvements 281-2231 90
#Kitchens 281-2231 89
#Lamps & Chinaware 281-2296 85
#Lawn & Garden Shop Gas Grills Dept 281-2271 85
#Mens Apparel Shirts & Accessories 281-2242 85
#Mens Apparel Shoes 281-2215 85
#Mens Apparel Sportswr 281-2245 85
#Mens Apparel Suits 281-2245 85
#Optical Dept 281-2280 85
#Paints 281-2230 85
#Personnel Dept 281-2256 85
#Photo & Bus Eqpt 281-2203 85
#Photo Studio 281-2282 85
#Plumbing & Heating 281-2242 85
#Ranges Dept 281-2226 85
#Refrigerators 281-2246 85
#Rent A Car Suburban Offices Woodlawn 597-9201 87
#Rent A Truck Suburban Offices Woodlawn 597-9201 87
#Sewing Machines 281-2220 85
#Sports & Recreation Equipment 281-2206 85
#Televisions Stereos & Records 281-2257 85
#Toys Dept 281-2206 85
#Vacuum Cleaners 281-2220 85
#Washers & Dryers 281-2247 85
#Window Air Condtng 281-2242 86
#Womens Apparel Bras Girdles & Lingerie 281-2218 85
#Womens Apparel Budget Shop 281-2218 85
#Womens Apparel Coats Suits & Dresses 281-2207 85
#Womens Apparel Cosmetics 281-2204 85
#Womens Apparel Hosiery 281-2218 85
#Womens Apparel Jewelry 281-2204 85
#Womens Apparel Shoes 281-2215 85
#Womens Apparel Sportswear 281-2207 85
#Womens Junior Apparel 281-2219 85

SECURITY BLVD 21207 Contd
6901 SECURITY SQUARE MALL Contd

#Security Optical Contact Lens Center 944-0088
#Security Square Mall 265-6000
#Security Square Mall maintenance ofc 265-5004
#Selvi's Jewelry Co 944-0130
#Shingar ..... +298-1224
#Simply Yogurt 298-6976
#16 Plus 944-8092
#Showcase 944-0027
#Small Stuff 944-2579
#Smalls Formal Wear 298-6410
#Soni International 281-0994
#Spencer Gifts 265-7939
#Steven-Windsor Tall & Big Man's Shop 944-4040
#Sweat Shop Inc 298-5443
#Taco Bell 597-9117
#Tandy Consumer Electronics Stores Baltimore 265-8144
#Things Remembered 944-4907
#Thom McAn Shoe Store 944-3030
#Tuerkes 298-5010
#Ups N' Down 944-4009
#Victoria's Secret 265-7813
#Video Concepts 298-0600
#Vittorio's Of Security Inc 265-7394
#Waldenbooks 944-7344
#Wall To Wall Sound & Video 298-5661
#Webster Men's Wear 265-1238
#Wild Pair 944-4217
#Wilson Suede & Leather 944-4271
#Wilson's Men's Strs 944-8878
#Woolworth F W Co 944-6090
#World Bazaar 944-4500
#World Intl Imports ..... +265-5668
#Xtras Inc 298-0236
#Zales Jewelers 265-1940
#Zepp Photo Centers 944-7616
6921 #Merry-Go-Round 597-8310
6970 #Koons Ford Car Rental & Leasing ..... +281-7556
6970 #Koons Ford Of Baltimore Inc Service Dept 281-2626
6970 #Koons Ford Of Baltimore Inc Body Shp & Estimates .. 298-1192
6970 #Koons Ford Of Balto 298-3800
6970 #Koons Ford Of Balto Parts 298-2100
6970 #Koons Ford Of Balto 621-5030
6975 #Bennigan's 944-1880

7000-08 SECURITY OFFICE PARK
7000 #All Star Nursing Svc 298-7717
#All Star Personnel Services Inc 298-6651
#All Star Personnel Services Inc 621-4009
#Associated Dispencing Service 944-2922
#Audiology Associates 944-3100
#Bergin-Kreh Associates Inc 265-8500
#Chaiyupatumpa Nibonba MD 298-4288
#Classic Health Care ..... +944-2200
#Executive Service Inc 298-7727
#Greater Baltimore Merchants Employee Credit Union 298-2777
#Javis Inc 944-7500
#Kelly Temporary Svcs ..... +298-9854
#Mercantile-Safe Deposit & Trust Co Security Blv Bnkg Ofc ... 298-4000
#Miracle Ear Center 265-1659
#NCHP Property Mgt regional ofc 281-1600
#Rolm Company 944-7500
#Security Office Park 944-7594
#Tech Aid 597-9550
7004 #A Woman's Psychology Clinic 298-8282
#Baltimore Hypnotherapy Clinic 298-8282
#Consulting Psychlgsts For Business & Govt 298-8282
#Hypertension Treatment Clinic 298-8282
#Life Management Inc ..... +298-8282
#McCabe Lee PhD 298-8282
#NCNB Consumer Credit Inc 281-7800
#NCNB Leasing Corp ..... +265-5198
#NCNB National Bank Of Maryland 298-4273
#Organizational Sciences Inst 298-8282
#PSI Biofeedback Clinic 298-8282
#PSI Hypnotherapy Clinic 298-8282
#PSI Marriage Counseling Clinic 298-8282
#Security Pacific Financial Svcs Inc 944-5090

Target Street	Cross Street	Source
✓	-	STEWART DIRECTORIES

SECURITY BLVD 1991



SECURITY BLVD 21207 Contd

7000-08 SECURITY OFFICE PARK Contd

7005 #Hechinger Co
Batimore Area Str
Security Mall 298-5200 83
7007 #Erol's Video Club
Security Square 944-7020 84
7008 #UARCO
Business Forms 298-4330 83
7009 #Kelly Temporary Svcs
Security Park 298-4490 82
7013 #Dan Howard's
Maternity Factory 298-3778 84
7015 #Household Finance
Corporation
Randallstown 298-6604 91
7019 #Geppi's Comic World
Security 298-1727 86
7019 #Geppi's Comic World
Security 298-1759 87
7023 #Dental Choice 621-4121 85
7023 #Dental Choice 298-7755 84
7023 #Egert Herbert D DDS 298-7755 88
7023 #Esrig Leslie DMD PA 298-7755 86
7023 #Fett Stephen R DDS 298-7755 86
7023 #Greenbaum M Gary DDS ... 298-7755 86
7023 #Habibi H DDS 298-7755 89
7023 #Levi Richard A DDS 298-7755 86
7023 #Marcus Robert DDS 298-7755 86
7023 #Michaelson Chas S DDS ... 298-7755 90
7023 #Riley Kenneth B DDS ..... +298-7755 91
7023 #Van Emmrick Brian DDS ... 298-7755 86
7025 #Rothschild's Clothing ..... +298-7344 91
7025 B #Southern Seafood Co ..... +265-7484 91
7025 B #Southern Seafood Mkt ..... □655-0005 91
7027 #Block H & R
Year Round Office ..... +944-6800 91
7027 #H & R Block Dist Ofc ..... +944-6800 91

Rolling Rd

7100 #Grempler Realty Inc
Baltimore Co Ofc 298-3500 81
7100 #Quality Rent-A-Car 298-4440 90

7101-71 CHADWICK MANOR SHPG CTR

#Rite Aid Discount
Pharmacies pharmacy ... 944-6400 88
#Rite Aid Discount
Pharmacies store 265-7754 90
7101 #Video Magic 265-1972 88
7105 #Meeks Valli 298-8787 90
#Shaw Harry dntst 298-8787 83
7107 #NCNB National
Bank Of Maryland
Chadwick Branch Ofc ... 298-4800 80
7117 #Super Fresh Store 265-5450 89
#Western Union
Super Fresh 265-5450 89
7129 #Chadwick Manor Barber
Shop ..... 944-5793 --
7131 #Carnelle Salon 944-9070 78
7133 #Chadwick Cleaners ..... 944-5800 --
7135 #Chadwick Discount
Liquors Inc ..... 944-1911 --
7139 #Ross Dress For Less 944-8870 87
7141 #Kaiser Permanente
Health Care Program
Woodlawn Center 281-6000 86
#Kaiser Permanente
Health Care Program
Woodlawn Center
Medical Advice After
Hours Advice
Weekend Days 339-5565 87
#Kaiser Permanente
Health Care Program
Woodlawn Center
Appts-All Centers 339-5600 86
#Kaiser Permanente
Health Care Program
Woodlawn Center
Appt Cancellation
24 Hours 339-5650 86
#Kaiser Permanente
Health Care Program
Woodlawn Center
Inf Line-24 Hour 281-6123 91
#Kaiser Permanente
Health Care Program
Woodlawn Center
Pharmacy 281-6116 91
#Kaiser Permanente
Health Care Program
Woodlawn Center
Pharmacy Refill 281-6240 89
7145 #Carvel Ice Cream Str 298-2826 79
7147 #Chadwick Manor
Laundromat 944-3480 86
7149 #Szechuan Express 298-6422 89
7153 #Rite Aid Discount
Pharmacies pharmacy ... +944-6401 91
#Rite Aid Discount
Pharmacies store ..... +298-4631 91
7165 #Pebbles Pub ..... 265-7878 --
#Pebbles' Beef & Beer ..... 265-7878 --
7171 #Maryland Natl Bank
Br Ofc Southwest
Rolling Road 944-7642 83
7175 #Chadwick Manor Shell 298-1550 85
7175 #Chadwick Service Ctr 298-1550 89

417-BUS 6-RES 38-NEW

Target Street	Cross Street	Source
✓	-	STEWART DIRECTORIES

SECURITY BLVD 1986



SECURITY BLVD 21207 Contd

6666 FOUR SIXES BUILDING Contd
6666 #Equitable Life Assurance Society Of The United States Group Dept 944-8900
#Equitable Real Estate Investment Mgt Inc +944-8900
#Executive Tax Service Of H & R Block 265-1046
#Kirby John P atty 298-5100
#Law Office-Buettner & Cooper PA 298-5100
#Lubarsky Efim dental laboratory 944-3307
#Luskin's Inc +265-6400
#Maneth Tim 944-6820
#Mordes Irvin 944-6060
#Omni Health Intl Ltd 944-6060
#Omni Hypno-Health Center 944-6060
#Qureshi Bilal MD 298-4200
#Qureshi Naeem M PA 298-4210
#Security Medical Walk-In Clinic 298-4200
#Tomy's Alteration Shp 265-1053
#Trident Travel Inc 944-6820
#Varma Osha MD +298-4200
#Walden Emerson C Jr Medical Doctor 298-4200
#Weight Control Institute-Woodlawn 944-6060
6667 #Roy Rogers Family Restaurant Woodlawn 298-3116
6669 #Capital Rehabltn Physical Therapy +298-0880
6669 #Cleaners Plus +597-9580
6669 #Dark Room The +944-9120
6669 #Esterson Samuel H physical therapist +298-0880
6669 #Fairfax Savings Assn 265-1140
6669 #LaBorwit L E Dr optm a944-5000
6669 #LaBorwit Larry E Dr optometrist a944-5000
6669 #Optical Enterprises +944-5000
6698 #Security Amoco 944-9191
6700 #Pargo's Inc +944-4020
6700 #Security Assoc +265-5525
6700 #Shoney's Motor Inn 281-1800

Beltway

-- #Filltop Inn +944-7400
-- #Knott's H A Motor Inn 944-7400
-- #Meushaw's Hilltop Inn 944-7400
-- #Meushaw's Restaurant 944-7400
-- #Meushaw's Restrnt 944-5595
6901 SECURITY SQUARE MALL
#AS Beck Shoe Store 298-3292
#Alan's Deli +944-9602
#Allstate Insurance Co Sales Ofcs-Sears Bg Security Square Mall +944-5846
#American Eagle Outfitters 298-6446
#American Natl Bldg & Loan Assn 298-6220
#Amshey Mary rl est 298-2234
#Annapolis Clothing Co 944-7362
#Athlete's Foot 265-1031
#Balloon Connection 298-3700
#Baskin Robbins 31 Ice Cream Stores 265-7333
#Beck Shoes Br 944-9821
#Bendix Uniforms Inc 944-6644
#Birnbaum Michael Dr optometry 944-0088
#Block H & R Inc Balt Co W & SW Ofc 265-5480
#Block H & R Inc Sears Locations 281-2275
#Brooks Fashions 944-3223
#C & P Telephone Co 298-7253
#Camera Shop Inc The 944-7616
#Candie's Bar 944-1640
#Card Cage 944-7550
#Card Mart The 265-8156
Caren Charles +944-5855
#Cargo Furniture 944-0344
#Carousel Snack Bar 265-6644
#Chandler's Shoe Str 944-4109
#Cheese Villa 944-9602
#Chess King 944-9526
#Children's Place The 265-1166
#Coldwell Banker Residential Rl Est Security-Sears 298-2234
#Coming Attractions 944-9742
#Connie Shoe Shop 265-8011
#County Seat Stores +265-8022
#Dalton B Bookseller Baltimore Security Square 944-7733
#Dataflow Corp 298-6565
#DeYoung Shoes 265-5522
#Dean Witter Reynolds Inc Sears Financial Network Ctr Ofcs 298-2310
#Docktor Pet Center 265-7100
#Endicott Johnson Shoes 944-1798
#Equitable Bank NA Baltimore Co Security Sq Mall Branch Ofc 265-1331
#Equitable Bank NA Baltimore Co Security Square Mall Drive-In Br Ofc 265-5333

SECURITY BLVD 21207 Contd

6901 SECURITY SQUARE MALL Contd
6901 #Fashion Bug 944-0500
#Firestone Stores Div Of Firestone Tire & Rubber Co Security Mall 265-6666
#Firestone Stores Div Of Firestone Tire & Rubber Co Baltimore Market Ofc 265-8333
#Florsheim Shoe Shops 944-4964
#Foot Locker 944-5211
#Four Seasons Travel 944-5117
#Foxmoor Casuals wmns wearg apparl 944-9529
#Friendly Ice Cream Shop 265-8566
#Fun-N-Games 265-5546
#Games 'N' Gagdets 944-0800
#Gap The 944-7040
#Gemstone Jewelery 298-6537
#General Nutrition 944-9525
#Gordon's Jewelers 265-6005
#Great Cookie 298-0370
#Hallmark Utlimate Expressions 265-8156
#Hanover Shoe Store 944-7622
#Harmony Hut 944-8797
#Harvest Hse Caftra 265-1346
#Hecht's Stores Security Mall 944-8040
#Hecht's Stores Security Mall Beauty Salon 944-0892
#Hickory Farms Of Ohio 944-3800
#His Place 265-5064
#Hong Kong Gift Shop 265-8575
#Huizinga Steven 265-6590
#Hutzler's Fur Salon +265-6444
#Hutzler's Store Security Square 281-1234
#Hyatts 944-1216
#Italian Delight 265-1175
#J & S Sales 944-2181
#J C Penney Co Inc 298-8100
#Jeans West Shop 944-4212
#Jo-Ann Fabrics 944-8606
#Jordan-Kitt's Music 944-5055
#K & K Toys 944-5536
#Karmelkorn Shoppe 944-3418
#Kay Jewelers 265-6557
#Keepsake Corner Melart Jewelers 265-8300
#Kinderfoto Portrait Studio 265-7039
#Kougl Melvin J ofc 298-7517
#Lechter's 944-8775
#Limited The 265-5832
#Loyola Fed Savings & Loan Association Hutzlers Security Br +944-1555
#MCI 265-7052
#Marianne 265-1445
#Marvin's Sport City 944-8343
#Melart Jewelers Keepsake Corner 265-8300
#Mill End Shops 265-1350
#Morrow's Nut House 265-7371
#Mother Goose Shoes 298-3200
#Motherhood 944-0142
#Oak Tree 298-2944
#Ocean City Fries 944-9393
#Ole Inc 265-5588
#Orange Julius 298-5533
#Ormond Shop Inc 944-8810
#Pants Corrals Woodlawn 265-8022
#Parklane Hosiery 298-0779
#Paul D P Jewelers 944-8323
#Penney J C Co Inc Catalog Tel Shopping 298-8500
#Penney J C Co Inc Security Sq Mall Custom Dec Service 288-5950
#Penney J C Dept Str Security Square Mall Styling Salon 265-5192
#Picture This 944-5290
#Piercing Pagoda 298-9630
#Radio Shack-A Div Of Tandy Corp Retail Stores 265-8144
#Rave 944-9521
#Regal Shoe Shop 265-7741
#Regis Hair Stylists 944-4116
#Reiner Philip Furs 265-6444
#Rite Aid Discnt Pharm store 944-8776
#Russell Stover Candies Inc 265-8785
#Sam Goody 944-8797
6901 SEARS ROEBUCK & CO
#Auto Batteries & Accessories 281-2228
#Automotive Parts 281-2292
#Automotive Svc Desk 281-2291
#Baltimore Fed Fin Baltimore County 944-8282
#Bedding & Bath Shop 281-2296
#Building Materials 281-2264
#Carpet & Floor Tiles 281-2237
#Catalog 265-1600
#Catalog To Check On An Order 281-2212
#Central Air Condtng 281-2242
#Children & Youth Apparel Boys 281-2229

BALTIMORE COUNTY WEST

Target Street	Cross Street	Source
✓	-	STEWART DIRECTORIES

SECURITY BLVD 1986

6901 SEARS ROEBUCK & CO Contd
6901 #Children & Youth Apparel Girls 281-2229
#Children & Youth Apparel Infants 281-2229
#Credit Inquiry 281-1560
#Custom Decorator 281-2225
#Customer Service 281-2276
#Dishwashers 281-2226
#Electrl & Lighting 281-2209
#Ersonnel Dept 281-2256
#Financial Center Allstate Ins Co 944-5846
#Financial Center Coldwell Banker Real Estate 298-2234
#Financial Center Dean Witter Reynolds Inc 298-2310
#Freezers 281-2246
#Furniture 281-2201
#Hardware 281-2209
#Housewares 281-2211
#Hutzler's Four Seasons Travel 944-5117
#Information 281-2255
#Kitchens 281-2296
#Lamps & Chinaware 281-2296
#Lawn & Garden Shop 281-2232
#Mens Apparel Shirts & Accessories 281-2245
#Mens Apparel Shoes 281-2215
#Mens Apparel Sportswr 281-2245
#Mens Apparel Suits 281-2245
#Optical Dept 281-2280
#Paints 281-2230
#Photo & Bus Eqpt 281-2203
#Photo Studio 281-2282
#Plumbing & Heating 281-2242
#Ranges & Gas Grills 281-2232
#Refrigerators 281-2246
#Sears Financial Network Centers Allstate Ins Co 944-5846
#Sears Financial Network Centers Coldwell Banker Real Estate 298-2234
#Sears Financial Network Centers Dean Witter Reynolds Inc 298-2310
#Security Optical 944-0088
#Security Square Cinema 1 & 2 265-6911
#Security Square Mall 265-6000
#Security Square Mall maintenance ofc 265-5004
#Selvi's Jewelry Co 944-0130
#Sewing Machines 281-2220
#Shoe Repair 281-2275
#Singer Company The 944-8777
#Singer Sewing Center 944-8777
#16 Plus Security Square Mall 944-8092
#Small Stuff 944-2579
#Spencer Gifts 265-7939
#Sports & Recreation Equipment 281-2206
#Steven-Windsor Tall & Big Man's Shop 944-4040
#Stieff-D P Paul jwlr 944-8323
#Televisions Stereos & Records 281-2257
#Things Remembered 944-2110
#Tinder Box The 265-7111
#Toys 281-2249
#Tuerkes Inc 298-5010
#Undercover 298-6198
#Uno 944-0919
#Vacuum Cleaners 281-2220
#Video Concepts 298-0600
#Waldenbooks 944-7344
#Washers & Dryers 281-2247
#Wild Pair 944-4217
#Wilson Suede & Leather 944-4271
#Wilson's Men's Strs 944-8878
#Window Air Condtng 281-2242
#Womens Apparel Bras Girdles & Lingerie 281-2218
#Womens Apparel Budget Shop 281-2218
#Womens Apparel Coats Suits & Dresses 281-2207
#Womens Apparel Cosmetics 281-2204
#Womens Apparel Hosiery 281-2215
#Womens Apparel Jewelry 281-2204
#Womens Apparel Shoes 281-2215
#Womens Apparel Sportswear 281-2207
#Womens Junior Apparel 281-2219
#Woolworth F W Co 944-6090
#World Bazaar 944-4500
#Yogurt Tree Inc shop 944-0407
#York Steak House 298-6440
#Young's Men's Stores 444-3737
#Zales Jewelers 265-1940
#Zepp Photo Centers 944-7616

6901 SEARS ROEBUCK & CO Contd
6901 #Thom Mcan Shoe Store Men's Shop 298-5945
#U S General Stores Catalogue Showrooms 597-8800
#Vittorio's Of Security Inc +265-7394
6901A#Greater Baltimore Merchants Employee Credit Union 298-2777
#Hutzler's Credit Un +298-2777
6907 #Stephens Jos rl est +298-2234
6907 #Stephens Joseph rlst +298-2234
6907 Stephens Joseph rlst +298-2234
6970 #Koons Ford Of Balto +298-3800
6970 #Koons Ford Of Balto Parts 298-2100
6970 #Koons Ford Of Balto +621-5030
7000 SECURITY OFFICE PARK
#Adia Personnel Svcs 298-6700
#Bergin-Kreh Associates Inc 265-8500
#Carozza Ross ins +265-8450
#Chaiyupatumpa Nibondh MD PA 298-3932
#Chaiyupatumpa Nibondh MD PA 298-4288
#Chaiyupatumpa & Pratumrat MD PA 298-3932
#Chaiyupatumpa & Pratumrat MD PA 298-4288
#Cleveland Hair Clinic 944-6920
#Computer Dynamics Inc 298-6934
#Executive Service Inc 298-7727
#Family Find +281-7500
#Flax Richard H ins 265-8450
#Independent Center For Insurance 265-8450
#Javis Inc 944-7500
#Jiffy Lube International Inc +298-4906
#Martin's Inc Accounting Dept 265-1300
#Mercantile-Safe Deposit & Trust Co Security Blv Bnkg Of 298-4000
#Mohawk Data Sciences Corporation 298-3888
#Paradyne Corp 298-4554
#Prime Computer Inc 298-8885
#Ranul Inc ¤298-6360
#Raychem Corp 944-5737
#Rolm Corporation +944-7500
#Saf Corp 298-0480
#Safety Council Of Maryland Inc 298-4770
#Security Office Park 944-7594
#Systems And Facilities Corp 298-0480
#Terminals Unlimited +281-1770
7005 #Hechinger Co Batimore Area Str Security Mall 298-5200
7007 #Erol's Video Club 944-7020
7008 #Advanced Technology 281-1440
7008 #Associated Consultants Corp 944-8200
7008 #Associated Family Counselors +298-8282
7008 #Baltimore Hypnotherapy Clinic +298-8282
7008 #Cohen Fisher & Assocs 298-7100
7008 #Cohen Michael W CPA 298-7100
7008 #Consulting Psychlgsts For Business & Govt 298-8282
7008 #Fast Find USA Inc ¤621-4266
7008 #Fastfind USA Inc 944-5531
7008 #Financeamerica Corp Baltimore 597-9199
7008 #Fisher Sanford R CPA 298-7100
7008 #Hindman W J & Assocs 944-0866
7008 #Hypertension Treatment Clinic +298-8282
7008 #Jiffy Lube International Inc 298-8200
7008 #Kaiser-Permanente Health Care Program +281-2190
7008 #Kelly Services Security Park 298-4490
7008 #Kelly Services Security Park +484-6275
7008 #Leaseway Transportation Corp 944-8200
7008 #McCabe Lee PhD 298-8282
7008 #Mutual Of Omaha Ins Co division ofc 298-9650
7008 #NCHP Property Mgt regional ofc 281-1600
7008 #PSI Biofeedback Clinic 298-8282
7008 #PSI Hypnotherapy Clinic 298-8282
7008 #PSI Marriage Counseling Clinic 298-8282
7008 #Psychological Science Institute 298-8282
7008 #Residential Financial Corporation 298-7010
7008 #Ryan Homes Inc 944-5882
7008 #Tech Aid Corp 597-9550
7008 #UARCO Bus Forms 298-4330
7013 #Dan Howard's Maternity Factory 298-3778
7015 #Riedel's Flowers Inc +298-8522
7019 #Geppi's Comic World Security ¤298-1727
7019 #Hair Cuttery The 944-9767

190

This page intentionally left blank

Appendix F.5

Property Tax Files

Real Property Data Search ( )
Search Result for BALTIMORE COUNTY

View Map **No Ground Rent Redemption on File** **No Ground Rent Registration on File**

Special Tax Recapture: None

Account Number: **District -** 01 **Account Identifier -** 1800010198

Owner Information

Owner Name: BALTIMORE COUNTY MARYLAND
Use: EXEMPT COMMERCIAL
Principal Residence: NO
Mailing Address: 400 WASHINGTON AVE
TOWSON MD 21204-
Deed Reference: /49786/ 00351

Location & Structure Information

Premises Address: 6901 SECURITY BLVD
BALTIMORE 21244-2412
Legal Description: 2.9549 AC
6901 SECURITY BLVD SS
SECURITY SQUARE SHOPPING CENTER

Map:	Grid:	Parcel:	Neighborhood:	Subdivision:	Section:	Block:	Lot:	Assessment Year:	Plat No:	1
0094	0006	0350	30000.04	9187			3	2024	Plat Ref:	79/ 187

Town: None

Primary Structure Built	Above Grade Living Area	Finished Basement Area	Property Land Area	County Use
	149,861 SF		2.9500 AC	01

Stories	Basement	Type	Exterior	Quality	Full/Half Bath	Garage	Last Notice of Major Improvements
		DEPARTMENT STORE / C4					

Value Information

	Base Value	Value	Phase-in Assessments	
		As of 01/01/2024	As of 07/01/2025	As of 07/01/2026
Land:	885,000	885,000		
Improvements	4,196,900	4,196,900		
Total:	5,081,900	5,081,900	5,081,900	5,081,900
Preferential Land:	0	0		

Transfer Information

Seller: MAY DEPARTMENT STORES CO	**Date:** 01/17/2025	**Price:** $6,500,000
Type: ARMS LENGTH MULTIPLE	**Deed1:** /49786/ 00351	**Deed2:**
Seller: SECURITY SQUARE ASSOCIATES	**Date:** 11/14/1979	**Price:** $25,000
Type: ARMS LENGTH IMPROVED	**Deed1:** /06102/ 00109	**Deed2:**
Seller:	**Date:**	**Price:**
Type:	**Deed1:**	**Deed2:**

Exemption Information

Partial Exempt Assessments:	Class	07/01/2025	07/01/2026
County:	680	0.00	5,081,900.00
State:	680	0.00	5,081,900.00
Municipal:	680	0.00|0.00	0.00|0.00

Special Tax Recapture: None

Homestead Application Information

Homestead Application Status: No Application

Homeowners' Tax Credit Application Information

Homeowners' Tax Credit Application Status: No Application **Date:**

Real Property Data Search ( )

Search Result for BALTIMORE COUNTY

View Map **No Ground Rent Redemption on File** **No Ground Rent Registration on File**

Special Tax Recapture: None

Account Number: **District -** 01 **Account Identifier -** 1800010199

Owner Information

Owner Name: BALTIMORE COUNTY MARYLAND **Use:** EXEMPT COMMERCIAL
Principal Residence: NO

Mailing Address: C/O REAL ESTATE COMPLAINCE
111 WEST CHESAPEAKE AVE
TOWSON MD 21204- **Deed Reference:** /47503/ 00471

Location & Structure Information

Premises Address: SECURITY BLVD
BALTIMORE 21235-0000 **Legal Description:** 18.0001 AC 784084 SQ
SECURITY SQUARE SHOPPIN

Map:	Grid:	Parcel:	Neighborhood:	Subdivision:	Section:	Block:	Lot:	Assessment Year:	Plat No:
0094	0006	0350	10000.04	0000				2025	Plat Ref: 0044/ 0105

Town: None

Primary Structure Built	Above Grade Living Area	Finished Basement Area	Property Land Area	County Use
	199,532 SF		18.0000 AC	01

Stories	Basement	Type	Exterior	Quality	Full/Half Bath	Garage	Last Notice of Major Improvements
		DEPARTMENT STORE /		C3			

Value Information

	Base Value	Value	Phase-in Assessments	
		As of 01/01/2025	As of 07/01/2024	As of 07/01/2025
Land:	5,400,000	5,400,000		
Improvements	115,000	115,000		
Total:	5,515,000	5,515,000	5,515,000	5,515,000
Preferential Land:	0	0		

Transfer Information

Seller: TF BALTIMORE MD LLC	**Date:** 11/02/2022	**Price:** $10,000,000
Type: ARMS LENGTH IMPROVED	**Deed1:** /47503/ 00471	**Deed2:**
Seller: SRC O P CORPORATION	**Date:** 04/17/2019	**Price:** $0
Type: NON-ARMS LENGTH OTHER	**Deed1:** /41324/ 00131	**Deed2:**
Seller: SEARS ROEBUCK AND COMPANY	**Date:** 03/07/2017	**Price:** $0
Type: NON-ARMS LENGTH OTHER	**Deed1:** /38710/ 00321	**Deed2:**

Exemption Information

Partial Exempt Assessments:	Class	07/01/2024	07/01/2025
County:	580	5,515,000.00	5,515,000.00
State:	580	5,515,000.00	5,515,000.00
Municipal:	580	0.00|0.00	0.00|0.00

Special Tax Recapture: None

Homestead Application Information

Homestead Application Status: No Application

Homeowners' Tax Credit Application Information

Homeowners' Tax Credit Application Status: No Application **Date:**

Give Feedback

Real Property Data Search ( )

Search Result for BALTIMORE COUNTY

View Map **No Ground Rent Redemption on File** **No Ground Rent Registration on File**

Special Tax Recapture: None

Account Number: **District -** 01 **Account Identifier -** 1700014297

Owner Information

Owner Name: BALTIMORE COUNTY MARYLAND **Use:** EXEMPT COMMERCIAL
Principal Residence: NO

Mailing Address: 400 WASHINGTON AVE
TOWSON MD 21204- **Deed Reference:** /49786/ 00351

Location & Structure Information

Premises Address: SECURITY BLVD
WINDSOR MILL 21244-

Legal Description: 1.2687 AC NS
SECURITY BLVD
NE COR BELMONT AV

Map:	Grid:	Parcel:	Neighborhood:	Subdivision:	Section:	Block:	Lot:	Assessment Year:	Plat No:
0094	0006	0355	30000.04	0000				2024	Plat Ref:

Town: None

Primary Structure Built	Above Grade Living Area	Finished Basement Area	Property Land Area	County Use
			1.2700 AC	01

Stories	Basement	Type	Exterior	Quality	Full/Half Bath	Garage	Last Notice of Major Improvements
							/

Value Information

	Base Value	Value	Phase-in Assessments	
		As of 01/01/2024	As of 07/01/2025	As of 07/01/2026
Land:	380,600	380,600		
Improvements	0	0		
Total:	380,600	380,600	380,600	380,600
Preferential Land:	0	0		

Transfer Information

Seller: ASSOCIATED DRY GOODS CORPORATION **Date:** 01/17/2025 **Price:** $6,500,000
Type: ARMS LENGTH MULTIPLE **Deed1:** /49786/ 00351 **Deed2:**

Seller: BELTWAY PROPERTI ES **Date:** 02/17/1989 **Price:** $0
Type: NON-ARMS LENGTH OTHER **Deed1:** /08107/ 00160 **Deed2:**

Seller: **Date:** **Price:**
Type: **Deed1:** **Deed2:**

Exemption Information

Partial Exempt Assessments:	Class	07/01/2025	07/01/2026
County:	680	0.00	380,600.00
State:	680	0.00	380,600.00
Municipal:	680	0.00|0.00	0.00|0.00

Special Tax Recapture: None

Homestead Application Information

Homestead Application Status: No Application

Homeowners' Tax Credit Application Information

Homeowners' Tax Credit Application Status: No Application **Date:**

Real Property Data Search ( )

Search Result for BALTIMORE COUNTY

View Map **No Ground Rent Redemption on File** **No Ground Rent Registration on File**

Special Tax Recapture: None

Account Number: **District -** 01 **Account Identifier -** 1900001398

Owner Information

Owner Name:	BALTIMORE COUNTY MARYLAND	**Use:**	EXEMPT COMMERCIAL
		Principal Residence:	NO
Mailing Address:	400 WASHINGTON AVE TOWSON MD 21204-	**Deed Reference:**	/49786/ 00351

Location & Structure Information

Premises Address:	1803 ROLLING RD WINDSOR MILL 21244-	**Legal Description:**	3.2207 AC SECURITY SQ SH CNT

Map:	Grid:	Parcel:	Neighborhood:	Subdivision:	Section:	Block:	Lot:	Assessment Year:	Plat No:
0094	0006	0351	30000.04	0000		4		2024	Plat Ref: 0047/ 0072

Town: None

Primary Structure Built	Above Grade Living Area	Finished Basement Area	Property Land Area	County Use
			3.2200 AC	01

Stories	Basement	Type	Exterior	Quality	Full/Half Bath	Garage	Last Notice of Major Improvements
							/

Value Information

	Base Value	Value	Phase-in Assessments	
		As of 01/01/2024	As of 07/01/2025	As of 07/01/2026
Land:	966,200	966,200		
Improvements	148,200	148,200		
Total:	1,114,400	1,114,400	1,114,400	1,114,400
Preferential Land:	0	0		

Transfer Information

Seller: ASSOCIATED DRY GOODS CORPORATION	**Date:** 01/17/2025	**Price:** $6,500,000
Type: ARMS LENGTH MULTIPLE	**Deed1:** /49786/ 00351	**Deed2:**
Seller: BELTWAY PROPERTI ES	**Date:** 02/17/1989	**Price:** $0
Type: NON-ARMS LENGTH OTHER	**Deed1:** /08107/ 00160	**Deed2:**
Seller:	**Date:**	**Price:**
Type:	**Deed1:**	**Deed2:**

Exemption Information

Partial Exempt Assessments:	Class	07/01/2025	07/01/2026
County:	680	0.00	1,114,400.00
State:	680	0.00	1,114,400.00
Municipal:	680	0.00|0.00	0.00|0.00

Special Tax Recapture: None

Homestead Application Information

Homestead Application Status: No Application

Homeowners' Tax Credit Application Information

Homeowners' Tax Credit Application Status: No Application **Date:**

Real Property Data Search ( )
Search Result for BALTIMORE COUNTY

View Map **No Ground Rent Redemption on File** **No Ground Rent Registration on File**

Special Tax Recapture: None

Account Number: **District -** 01 **Account Identifier -** 2500019068

Owner Information

Owner Name: BALTIMORE COUNTY MARYLAND
Use: EXEMPT COMMERCIAL
Principal Residence: NO
Mailing Address: 400 WASHINGTON AVE
TOWSON MD 21204-
Deed Reference: /49786/ 00351

Location & Structure Information

Premises Address: 6973 SECURITY BLVD
BALTIMORE 21244-0000
Legal Description: 1.552 AC PARCEL D
6973 SECURITY BLVD SS
SECURITY SQUARE SHOPPING CENTER

Map:	Grid:	Parcel:	Neighborhood:	Subdivision:	Section:	Block:	Lot:	Assessment Year:	Plat No:	
0094	0006	0350	30000.04	8114			3	2024	Plat Ref:	0080/ 0114

Town: None

Primary Structure Built	Above Grade Living Area	Finished Basement Area	Property Land Area	County Use
			1.5520 AC	01

Stories	Basement	Type	Exterior	Quality	Full/Half Bath	Garage	Last Notice of Major Improvements
							/

Value Information

	Base Value	Value	Phase-in Assessments	
		As of 01/01/2024	As of 07/01/2025	As of 07/01/2026
Land:	776,000	776,000		
Improvements	0	0		
Total:	776,000	776,000	776,000	776,000
Preferential Land:	0	0		

Transfer Information

Seller: ASSOCIATED DRY GOODS CORP	**Date:** 01/17/2025	**Price:** $6,500,000
Type: ARMS LENGTH MULTIPLE	**Deed1:** /49786/ 00351	**Deed2:**
Seller:	**Date:**	**Price:**
Type:	**Deed1:**	**Deed2:**
Seller:	**Date:**	**Price:**
Type:	**Deed1:**	**Deed2:**

Exemption Information

Partial Exempt Assessments:	Class	07/01/2025	07/01/2026
County:	680	0.00	776,000.00
State:	680	0.00	776,000.00
Municipal:	680	0.00|0.00	0.00|0.00

Special Tax Recapture: None

Homestead Application Information

Homestead Application Status: No Application

Homeowners' Tax Credit Application Information

Homeowners' Tax Credit Application Status: No Application **Date:**

Real Property Data Search ( )
Search Result for BALTIMORE COUNTY

View Map **No Ground Rent Redemption on File** **No Ground Rent Registration on File**

Special Tax Recapture: None

Account Number: **District -** 01 **Account Identifier -** 2500018334

Owner Information

Owner Name: BALTIMORE COUNTY MD
Use: EXEMPT COMMERCIAL
Principal Residence: NO

Mailing Address: ROOM 127
111 W CHESAPEAKE AVE
TOWSON MD 21204-

Deed Reference: /50261/ 00472

Location & Structure Information

Premises Address: 6901 SECURITY BLVD
BALTIMORE 21244-

Legal Description: PARCEL E - 11.409 ACS
6901 SECURITY BLVD ES
SECURITY SQUARE SHOPPING CENTER

Map:	Grid:	Parcel:	Neighborhood:	Subdivision:	Section:	Block:	Lot:	Assessment Year:	Plat No:
0094	0006	0476	30000.04	0000				2024	Plat Ref: 0080/ 0166

Town: None

Primary Structure Built	Above Grade Living Area	Finished Basement Area	Property Land Area	County Use
			11.4100 AC	01

Stories	Basement	Type	Exterior	Quality	Full/Half Bath	Garage	Last Notice of Major Improvements
			/				

Value Information

	Base Value	Value	Phase-in Assessments	
		As of 01/01/2024	As of 07/01/2025	As of 07/01/2026
Land:	1,083,900	1,083,900		
Improvements	72,500	72,500		
Total:	1,156,400	1,156,400	1,156,400	1,156,400
Preferential Land:	0	0		

Transfer Information

Seller: SECURITY WARDS LLC	**Date:** 07/02/2025	**Price:** $6,850,000
Type: ARMS LENGTH VACANT	**Deed1:** /50261/ 00472	**Deed2:**
Seller:	**Date:**	**Price:**
Type:	**Deed1:**	**Deed2:**
Seller:	**Date:**	**Price:**
Type:	**Deed1:**	**Deed2:**

Exemption Information

Partial Exempt Assessments:	Class	07/01/2025	07/01/2026
County:	680	0.00	1,156,400.00
State:	680	0.00	1,156,400.00
Municipal:	680	0.00|0.00	0.00|0.00

Special Tax Recapture: None

Homestead Application Information

Homestead Application Status: No Application

Homeowners' Tax Credit Application Information

Homeowners' Tax Credit Application Status: No Application **Date:**

Real Property Data Search ( )
Search Result for BALTIMORE COUNTY

View Map **No Ground Rent Redemption on File** **No Ground Rent Registration on File**

Special Tax Recapture: None

Account Number: **District -** 01 **Account Identifier -** 2500020705

Owner Information

Owner Name: BALTIMORE COUNTY MARYLAND
Use: COMMERCIAL CONDOMINIUM
Principal Residence: NO
Mailing Address: ROOM 127
111 W CHESAPEAKE AVE
TOWSON MD 21093-
Deed Reference: /49064/ 00283

Location & Structure Information

Premises Address: 6901 SECURITY BLVD
BALTIMORE 21244-
Legal Description: LAND UNIT 1 - 4.617 ACS
6901 SECURITY BLVD ESR
SECURITY SQUARE SHOPPING CENTER

Map:	Grid:	Parcel:	Neighborhood:	Subdivision:	Section:	Block:	Lot:	Assessment Year:	Plat No:	
0094	0006	0476	30000.04	0166				2024	Plat Ref:	080/ 0166

Town: None

Primary Structure Built	Above Grade Living Area	Finished Basement Area	Property Land Area	County Use
			4.6200 AC	14

Stories	Basement	Type	Exterior	Quality	Full/Half Bath	Garage	Last Notice of Major Improvements
			/				

Value Information

	Base Value	Value	Phase-in Assessments	
		As of 01/01/2024	As of 07/01/2025	As of 07/01/2026
Land:	438,900	438,900		
Improvements	36,400	36,400		
Total:	475,300	475,300	475,300	475,300
Preferential Land:	0	0		

Transfer Information

Seller: SECURITY WARDS LLC	**Date:** 05/28/2024	**Price:** $6,850,000
Type: ARMS LENGTH VACANT	**Deed1:** /49064/ 00283	**Deed2:**
Seller:	**Date:**	**Price:**
Type:	**Deed1:**	**Deed2:**
Seller:	**Date:**	**Price:**
Type:	**Deed1:**	**Deed2:**

Exemption Information

Partial Exempt Assessments:	Class	07/01/2025	07/01/2026
County:	000	0.00	
State:	000	0.00	
Municipal:	000	0.00|0.00	0.00|0.00

Special Tax Recapture: None

Homestead Application Information

Homestead Application Status: No Application

Homeowners' Tax Credit Application Information

Homeowners' Tax Credit Application Status: No Application **Date:**

BALTIMORE COUNTY CIRCUIT COURT (Subdivision Plats, BA) Plat Book EHK, Jr. 44, p. 105, MSA_S1236_7819. Date available 1979/06/27. Printed 08/15/2025.

Baltimore County Grid Meridian

NOTES:
EXISTING ZONING LOT 2 "BM-CT"
AREA LOT 2 BEFORE REVISION = 30.7593 Ac.
AREA OF LOT 3 = 2.952 Ac.
AREA OF LOT 2 REMAINING = 27.8058 Ac.

-COORDINATES-

Nº	NORTH	WEST	Nº	NORTH	WEST
360	3485.21	38375.07	397	3564.45	36955.66
361	3485.33	38036.25	398	3778.29	37130.55
362	3446.99	37885.53	441	5549.61	37566.39
364	3529.11	37220.41	465	5545.16	37653.87
366	4095.93	36875.35	501	5056.40	38524.25
367	4328.08	36824.25	505	4964.64	38266.78
370	4513.58	36753.31	507	3494.35	38394.19
371	4703.75	36757.72	556	5441.47	38633.93
372	4890.76	36835.25	558	5381.05	38623.55
373	5067.85	36917.36	561	5467.66	38641.01
374	5288.33	37031.47	563	5580.54	38573.56
375	5354.42	37131.02	590	5580.07	37966.07
376	5458.37	37235.78	700	5126.53	38488.30
382	5476.01	37692.47	702	5107.92	38427.34
383	5457.58	37669.36	443	5585.90	38443.56
384	5445.89	37693.62	779	2913.60	37934.52
386	5503.58	37576.76	780	3587.05	37007.18
387	5466.16	37719.74	781	4222.97	36986.01
389	5451.35	37706.23	1206	4055.21	37486.42
790	5578.50	38201.67			
865	4778.51	37804.31	813	4505.18	38612.71
790	5067.82	37548.10	842	5883.35	38110.70
809	4766.36	37029.24	840	5910.06	38089.16
810	4822.19	36997.41	841	5969.26	38016.77
811	5023.58	37219.06	844	4944.77	38262.91
1074	3081.62	38574.15	1145	3013.80	37954.10
1150	4015.65	38537.55	582	3959.01	38520.59
1190	4039.38	37964.18	1128	4108.87	37278.20
580	3523.55	38165.70	581	3853.10	37940.21
1191	4280.48	37505.01	1205	4097.05	37450.08
1072	3885.26	37784.27	578	3836.24	37516.92
579	4016.22	37276.30	677	4235.88	36981.70
822	4247.50	36843.27	1154	3985.05	37804.15
1155	3998.27	37611.15	1070	4108.89	37371.07
1156	4216.77	37316.14	1150	4158.61	37280.60
1157	4556.64	37159.16	1160	4547.54	37174.84
1158	4612.38	37114.57	1161	4643.25	37175.18
1162	4656.61	37168.36	1065	4868.52	36984.05
1108	4878.56	37004.55	1110	4851.88	36957.57
1157	3820.09	37077.25	1164	4961.31	37344.75
1068	5075.77	37350.80	1100	5045.84	37482.50
			1166	5060.56	37465.00
1101	5451.26	37610.50	1067	5081.63	37529.64
1066	4806.84	37641.18	1167	4738.77	37769.21
1168*	4728.17	37763.58	1142	4844.51	38005.28
1144	4601.06	37959.24	1050	4572.05	38082.76
1051	4534.56	38063.04	1141	4505.35	38208.13
1143	4518.63	38215.17	1065	4453.75	38505.25
1219	4040.47	37453.74	1219	4546.87	37147.95
1214	4009.57	37437.30	1220	4560.03	37173.79
1215	4211.85	37318.65	1221	4602.11	37119.80
1216	4191.42	37278.55	1222	4632.98	37180.90
1217	4220.76	37314.11	1223	4650.80	37171.31
1238	4229.64	37381.93	1209	4908.92	37552.30
1210	4939.78	37940.18			

-NOTES-

1. Highway and Highway Widening slope drainage and Utility Easements shown hereon are reserved unto the developer and are hereby offered for dedication to Baltimore County, Maryland. The developer his personal representatives and assigns shall convey said areas by deed to Baltimore County, Md. at no cost.
2. Streets and/or roads shown hereon and mention thereof in deeds are for purposes of description only the same are not intended to be dedicated to public use. The fee simple title to the beds thereof is expressly reserved in the grantor of the deed to which this plat is attached their heirs and assigns.

REVISED PLAT 1
SECURITY SQUARE SHOPPING CENTER

ELECTION DISTRICT Nº 1
SCALE: 1" = 100'

BALTIMORE COUNTY, MD.
MARCH 6, 1979

EHK JR 44 FOLIO 105

Clerk

NONE DHL

REASON FOR REVISION:
SUBDIVIDED LOT 2 TO CREATE LOT 3. SEE AREA REVISIONS.
DEAD RUN SANITARY SEWER AREA

"CURVES"

From	To	Δ	R	L	T	Chord
364	362	30° 00' 00"	1382.09'	723.66'	370.33	S 69° 21' 54" W 715.42'
443	441	10° 00' 01"	4518.66'	788.81'	395.41	S 87° 21' 36" E 787.81'
563	561	66° 26' 37"	120.00'	139.16'	78.69	S 80° 51' 39" W 131.49'
536	558	25° 38' 21"	141.00'	63.10	32.09	S 15° 10' 52" E 62.57'
700	702	30° 00' 00"	45.00'	70.65	45.00	S 73° 00' 00" E 63.64'

COORDINATES (Cont'd)

Nº	North	West	Nº	North	West
1196	3884.84	37746.44	1590	3781.4.37	4789.40
1197	4073.31	37388.22			
1207	3845.04	38261.28	1592	3831.215	4797.38
1208	4029.96	38221.41	1593	3812.44	4926.60
1226	5004.87	37459.55	1594	3809.2.00	4992.72
1227	5085.36	37516.18	1595	3792.8.63	5003.94
1228	4458.35	38221.37	600	3799.8.34	5337.52
1235	4516.61	38230.76	1596	3823.31.10	4967.92
1230	4616.65	37958.88	1597	3826.1.62	4925.31
1231	4698.15	38020.94	1598	3824.3.32	4958.54

APPROVED: BALTIMORE COUNTY PLANNING BOARD	
6/21/79 DATE	Norman E. Gerber ACTING DIRECTOR
APPROVED:	
6/23/79 DATE	Dennis F. Rasmussen DEPUTY STATE & COUNTY HEALTH OFFICER
6/19/79 DATE	Edsel W. Diver COUNTY ROADS ENGINEER

NOTE:
STREETS and/or ROADS shown hereon and mention thereof in deeds are for purposes of description only and the same are not intended to be dedicated to public use the fee simple title to the beds thereof is expressly reserved in the grantors of the deed to which this plat is attached their heirs and assigns.

NOTE:
COORDINATES and BEARINGS shown on this plat are referred to the system of coordinates established in The Baltimore County Metropolitan District and are based on the following traverse stations:

x 8069	W 33497.30	N 3356.17
x 8070	W 33364.87	N 2960.00

OWNERS CERTIFICATE:
The requirements of Section 3-108A Article 21 of the Annotated Code of Maryland, as far as they relate to the preparation of this plat have been complied with.
SECURITY SQUARE ASSOCIATES
Arthur D. Wolfcale Jr. 5-4-79
ARTHUR D. WOLFCALE, JR.
MANAGING PARTNER

SURVEYORS CERTIFICATE:
I, Ronald W. Broyles a Registered Land Surveyor of the State of Maryland do hereby certify that the land shown hereon has been laid out, and the plat thereof prepared in accordance with the provisions of the law relating to the subdivision of land known as House Bill 459 Chapter 1016 of the Acts of 1945 and subsequent amendatory acts.
Ronald W. Broyles
REGISTERED LAND SURVEYOR Nº 3980 DATE

KIDDE CONSULTANTS, INC.
1020 CROMWELL BRIDGE ROAD
BALTIMORE, MARYLAND 21204

COMPUTED: HGW DRAWN: WB CHECKED: MCA J.O. *6021A0

P60200

MSA S5W 1236-7819 44-105

BALTIMORE COUNTY CIRCUIT COURT (Subdivision Plats, BA) Plat Book OTG 35, p. 142, MSA_S1236_9004. Date available 1972/09/06. Printed 08/15/2025.

Baltimore County
Grid Meridian

CURVES

FROM	TO	Δ	R	L	T	CHORD
401	541	02° 15' 26"	756.04'	29.90'	14.96'	N 19° 50' 13" E. 29.90'
540	539	46° 42' 58"	950.00'	552.65'	294.27'	N. 05° 30' 12" W. 535.15'
538	531	13° 52' 08"	2235.83'	541.17'	271.91'	N. 23° 04' 38" W. 539.85'
529	450	13° 30' 33"	2,350.83'	890.33'	921.64'	S. 84° 35' 22" E. 637.97'
589	561	46° 24' 51"	120.00'	139.16'	76.59'	S 30° 51' 39" W. 131.49'
550	552	22° 30' 21"	141.00'	63.10'	32.09	S. 15° 10' 50" E. 62.57'
700	702	90° 00' 00"	45.00'	70.69'	45.00	S. 73° 00' 00" E. 63.64
550	400	08° 25' 27"	3960.86'	378.42	186.89	N 67° 06' 27" W 378.29'

~COORDINATES~

№	NORTH	WEST	№	NORTH	WEST
160	5446.27	39160.15	539	4438.36	38930.38
358	3893.71	38801.96	540	3904.82	38886.56
400	3738.78	38945.91	541	3822.57	38914.41
401	3794.45	39024.55	556	5441.47	38630.93
427	5309.44	39134.04	558	5381.05	38623.55
450	5576.17	38675.51	561	5467.66	38641.01
501	6056.40	38582.25	563	5580.54	38573.56
505	4564.64	38288.76	819	4505.19	38312.71
507	3434.35	38304.19	818	4429.11	38600.89
509	5636.27	39314.04	817	4189.29	38642.44
530	3838.78	39390.16	820	3976.78	38802.46
531	5137.53	39267.95	700	5126.53	38488.20
533	6463.01	39346.65	702	5107.92	38427.34
534	5258.60	39363.30	944	4438.87	38563.14
535	4849.88	39056.35			
537	3840.47	38902.78	789	5558.34	39384.54
538	3893.25	38918.77	791	5579.50	38501.87
770	6333.62	39014.98	790	5617.66	39325.51
535	3867.17	38960.80	1285	4210.57	38581.30
536	5062.62	38846.52	1077	4300.60	38534.58
552	5080.01	38520.50	1078	4524.78	38731.52
1280	5025.55	38120.70	1076	4282.78	38874.71
1162	5045.76	38250.36	1063	4430.86	38517.52
1074	5081.82	38974.18	1064	4470.82	38444.28
1160	4178.15	38980.78	1065	4483.78	38505.25
1285	6209.51	38548.36	1141	4505.85	38208.13
1170	4168.84	38940.57	1148	4518.68	38215.17
325	4500.47	38847.05	787	5405.85	38341.57
192	5582.42	38867.36			



Q.T.G. 35 FOLIO 142

Filed for record
Date SEP 6 1972
Test:
Clerk

PLAT 2
SECURITY SQUARE
SHOPPING CENTER

ELECTION DISTRICT № 1
SCALE: 1" = 100'

BALTIMORE COUNTY, MD.
OCT. 30, 1970
REV. JUNE 24, 1971
REVISED: JANUARY 27, 1972

W. & S. Completed 17107 GC
Final Plat Completed
Planning
Engineering MWS 7-25-72
Street Name(s)
Misc. No.

APPROVED, BALTIMORE COUNTY PLANNING BOARD
7/25/72 DATE — Albert V. Quinsky ACTING DIRECTOR

APPROVED:
8/2/72 DATE — Donald J. Roop, M.D. DEPUTY STATE & COUNTY HEALTH OFFICER

8/1/72 DATE — Thomas H. Bowing COUNTY ROADS ENGINEER

NOTE: STREETS and/or ROADS, and Utility Easements shown hereon and mention thereof in deeds are for purposes of description only, and the same are not intended to be dedicated to public use; the fee simple title to the beds thereof is expressly reserved in the grantors of the deed to which this plat is attached, their heirs and assigns.

NOTE: COORDINATES and BEARINGS shown on this plat are referred to the system of coordinates established in The Baltimore County Metropolitan District and are based on the following traverse stations:

× 8060 W 33497.50 N 3350.17
× 8070 W 33564.87 N 2960.08

OWNERS CERTIFICATE:

The requirements of Section 72-B, Article 17 of the Annotated Code of Maryland, (Flack 1947 Supplement) as far as they relate to the preparation of this plat have been complied with.

H-K SECURITY SQUARE INC.
BY _____ DATE

SECURITY SQUARE ASSOCIATES
BY Arthur D Wolfgale MANAGING 6-28-72
ARTHUR D. WOLFGALE PARTNER DATE

SURVEYORS CERTIFICATE:

I, JOHN C. CHILDS SR., a Registered Land Surveyor of the State of Maryland, do hereby certify that the land shown hereon has been laid out, and the plat thereof prepared in accordance with the provisions of the law relating to the subdivision of land known as House Bill #459, Chapter 1016 of the Acts of 1945 and subsequent amendatory acts.

John C. Childs Sr. 12-1-70
REGISTERED LAND SURVEYOR, No. 3622 DATE

MATZ, CHILDS & ASSOCIATES
1020 CROMWELL BRIDGE RD
BALTIMORE MD. 21204

COMPUTED: H.G.W. DRAWN: W.B. CHECKED: M.C.

MSA S54 1236-9004

This page intentionally left blank

Appendix G

Resumes

Jim Hulbert, CHMM
Project Manager

Mr. Hulbert has more than 30 years of experience in a wide range of environmental projects. His area of expertise includes real estate due diligence, Brownfield redevelopment, remedial action design and waterfront consulting. His experience also includes performing and managing Phase I and Phase II environmental assessments, remedial design, and implementation, performing and managing hazardous material surveys, managing teams of environmental professionals, and due diligence real estate consulting.

Qualifications

Education
B.S.; Salisbury University; Environmental Science; 1988

Registration/Certification
Certified Hazardous Material Manager (CHMM)

Specialized Training
OSHA 40-Hour Health and Safety Training for Hazardous Waste Site Work; 1989
Asbestos Building Inspector Certification
Lead-Based Paint Inspector Certification
Mold Remediation Supervisor Training; 2002

Professional Affiliations/Appointments
American Society for Testing and Materials 1500 Sub-Committee Member
Certified Hazardous Materials Manager – Institute of Hazardous Material Management; 2007

Experience
Years with EA: 25 Total Years: 33

Professional Experience

Due Diligence—Director of Operations for an environmental due diligence firm that performed over 30,000 Phase I environmental site assessments in a span of 8 years, along with other environmental assessments including Phase II environmental site assessments and indoor air quality studies. Environmental assessments were performed on various industrial, commercial, and residential property types, as well as farmland and undeveloped properties. Project Manager for the completion of more than 900 environmental site assessments associated with the liquidation of Confederated Life Insurance Company assets. Duties included contract negotiation, scope development, subcontractor selection and management, review team management, client service, and technical support. The project also included the completion of more than 50 Phase II subsurface investigations and the presentation of results to potential investors.

Brownfields Redevelopment—Project experience includes managing Brownfield redevelopment projects from initial investigation through site cleanup and reuse. Work has included developing planning documents, coordinating with state and federal Brownfield Programs, managing site assessments and Human Health Risk Assessments, evaluating remedial alternatives, designing remedial actions and working with the development team to integrate remedial actions into the final site designs. All projects have been partially or completely funded through U.S. Environmental Protection Agency Grant programs. Experience includes writing Site Specific Cleanup Grant applications and managing those grants as well as managing Community Block Assessment Grants. Extensive experience working through the Maryland Department of the Environment – Voluntary Clean-up Program (MDE-VCP) as well as the MDE- Controlled Hazardous Substances Program (CHS).

Waterfront Redevelopment – Project experience includes managing Baltimore waterfront projects completed for the Maryland Department of Transportation Maryland Port Administration Projects including the Dundalk Marine Terminal (DMT) hexavalent chromium management evaluation, Masonville Environmental Education Center environmental clean-up and redevelopment, Cox Creek Former Copper Refinery clean-up and redevelopment and Hawkins Point Landfill groundwater management and permitting support. Waterfront projects completed for private developer clients include the West Covington Park remedial design and clean-up, Westport environmental engineering/permitting support, and Under Armour - Port Covington remedial design and redevelopment. Areas of technical expertise include integration of remedial design and natural shoreline features including fringe wetlands, armored riparian shoreline stabilization, and design of tidal and non-tidal wetland green shorelines.

Mitchell P. Richards
Engineer

Mr. Richards is an engineer in the environmental consulting industry. He is knowledgeable in the areas of media sampling, well construction and development, well operations and maintenance, and environmental site assessment and remediation.

Education
B.S./Chemical Engineering/2023 (University of Maryland, Baltimore County)

Specialized Training
OSHA 40-Hour Hazardous Waste Operations and Emergency Response Training; 2023
CPR, First Aid, and AED Training; 2023

Experience
Years with EA: 2 Total Years: 2

Professional Experience

***Well Construction, Development, O&M*—**Provided oversight of the construction and installation of several wells to be used for groundwater monitoring. Recorded timestamped notes on the progress of the installation to ensure quality and safety. Oversees a continuing groundwater recovery effort, performing routine inspections on equipment, collecting water quality samples, and assisting with quarterly pump removal and cleaning efforts.

***Environmental Media Sampling*—**Provided oversight of fieldwork activities involving sampling and sample custody of groundwater, surface water, soil/sediment, and air. Recorded water quality parameters and performed air monitoring when necessary. Monitored site health and safety and managed all aspects of site equipment usage and maintenance.

***Environmental Site Assessment*—**Performed on-site reconnaissance as part of Phase I Environmental Site Assessment efforts, taking photographs and notes on potential objects and areas of concern while adhering to safety standards. Used online environmental research databases to compile information and develop reports for multiple properties undergoing phase I environmental site assessment.

EA Project Experience

Phase I Environmental Site Assessments, Baltimore, Maryland; Engineer— Assisted in site assessment efforts at a series of properties in the Irvington neighborhood of Baltimore City. Collected photographs and notes during site reconnaissance and utilized environmental research databases to characterize environmental concerns at the properties. Efforts were incorporated in the Phase I environmental site assessment submitted to EA client.
Project Date: October 2024

Price Landfill, Pleasantville, New Jersey; Engineer—Performed low-flow groundwater sampling from monitoring wells to monitor the extent of volatile organic compounds (VOCs) and other landfill-related contaminants in the vicinity of Price Landfill Superfund Site in Pleasantville, New Jersey. Utilized U.S. Environmental Protection Agency (EPA) methods for collecting environmental samples and utilized Scribe labelling methods.
Project Date: November 2023

Worcester County Central Landfill Groundwater Sampling, Snow Hill, Maryland; Worcester County Central Landfill Facility; Engineer—Performed low-flow groundwater sampling and surface water sampling to assess the levels of VOCs, semivolatile organic compounds (SVOCs), polycyclic aromatic hydrocarbons, polychlorinated biphenyls, pesticides, metals, and acids/corrosives present. Provided management of sampling equipment and sample custody.
Project Date: August–September 2023

Worcester County Closed Landfill Groundwater Sampling, Snow Hill, Maryland; Berlin, Pokomoke, and Snow Hill Landfill Facilities; Engineer—Performed low-flow groundwater sampling and surface water sampling to assess the levels of VOCs, SVOCs, polycyclic aromatic hydrocarbons, polychlorinated biphenyls, pesticides, metals, and acids/corrosives present. Provided management of sampling equipment and sample custody.
Project Date: August–September 2023

This page intentionally left blank